




SHEET 3

LINDA VISTA DRIVE

RANCHO SANTA FE ROAD

SHEET 2

SHEET 2

WOODWARD STREET

VINEYARD ROAD


BORDEN ROAD

TWIN OAKS VALLEY ROAD

HWY 78

MISSION ROAD



CITY OF SAN MARCOS
ROAD REPAIR LOCATIONS
SHEET 1 OF 3



Michael Baker
INTERNATIONAL




5050 AVENIDA ENCINAS, SUITE 260
CARLSBAD, CA 92008
Phone: (760) 603-6252
MBAKERINTL.COM

EAST VINEYARD



RICHMAR NEIGHBORHOOD

ADDITIVE BID ITEMS




LEGEND

-  TYPE 1/TYPE 3 LATEX MOD
-  TYPE 2 LATEX MOD


CITY OF SAN MARCOS
ROAD REPAIR LOCATIONS
RICHMAR NEIGHBORHOOD & EAST VINEYARD
SHEET 2 OF 3

Michael Baker
INTERNATIONAL
5050 AVENIDA ENCINAS, SUITE 260
CARLSBAD, CA 92008
Phone: (760) 603-6252
MBAKERINTL.COM



LEGEND

- TYPE 1/TYPE 3 LATX MOD
- WEEKEND WORK REQUIRED



CITY OF SAN MARCOS
ROAD REPAIR LOCATIONS
WEST CITY
SHEET 3 OF 3

Michael Baker
INTERNATIONAL
 5050 AVENIDA ENCINAS, SUITE 260
 CARLSBAD, CA 92008
 Phone: (760) 603-6252
 MBAKERINTL.COM