ATTACHMENT D

ENVIRONMENTAL IMPACT REPORT

APPENDIX J

PHASE 1 ESA

Prepared for:

Ambient Communities
179 Calle Magdalena, #201
Encinitas, California 92024

PHASE 1 ENVIRONMENTAL SITE ASSESSMENT

Vacant Property
Northeast Side of Capalina Road
APN 219-115-33-00
San Marcos, San Diego County, California 92069

Prepared by:

The Phase One Group
324 South Diamond Bar Boulevard, #130
Diamond Bar, California 91765
323.364.2530
info@thephaseonegroup.com

Issued on March 28, 2022
Project Number: 22-015

TABLE OF CONTENTS

1.0 EXECUTIVE SUMMARY 1
1.1 FINDINGS 1
1.2 CONCLUSIONS 2
1.3 RECOMMENDATIONS 2
2.0 INTRODUCTION 3
2.1 PURPOSE 3
2.2 SCOPE OF WORK 3
2.3 REPORT RELIANCE 4
2.4 LIMITATIONS 4
2.5 LIMITING CONDITIONS 5
3.0 PROPERTY DESCRIPTION 6
3.1 PROPERTY LOCATION AND DESCRIPTION 6
3.1.1 Type of Property 6
3.1.2 Improvements 6
3.1.3 Current Property Use 6
4.0 USER PROVIDED INFORMATION 7
4.1 TITLE RECORDS 7
4.2 ENVIRONMENTAL LIENS OR ACTIVITY USE LIMITATIONS 7
4.3 SPECIALIZED KNOWLEDGE 7
4.4 COMMONLY KNOWN OR REASONABLY ASCERTAINABLE INFORMATION 7
4.5 VALUATION REDUCTION FOR ENVIRONMENTAL ISSUES 7
4.6 OWNER, PROPERTY MANAGER AND OCCUPANT INFORMATION 8
4.7 PRIOR REPORTS 8
4.8 REASON FOR PERFORMING PHASE 1 ESA 8
5.0 RECORDS REVIEW 9
5.1 GENERAL PUBLIC RECORDS 9
5.1.1 Physical Setting Sources 9
5.1.1.1 Topography 9
5.1.1.2 Geology/Soils 9
5.1.1.3 Hydrology 9
5.1.2 Historical Use Information 10
5.1.2.1 Prior Uses of Property 10
5.1.2.2 Recorded Land Title Records 10
5.1.2.3 Chain of Title 10
5.1.2.4 Aerial Photographs 11
5.1.2.5 Fire Insurance Maps 15
5.1.2.6 Historical City Directories 15
5.1.2.7 Building Permit Records 15
5.1.2.8 Planning Records 15
5.1.2.9 Other Maps 15
5.1.3 Properties and Areas Surrounding the Property 16
5.1.3.1 Current Uses of Adjoining Properties 16
5.1.3.2 Past Uses 16
5.1.3.3 Current Use of Surrounding Areas 16
5.2 ENVIRONMENTAL RECORDS REVIEWS 16
5.2.1 Mapped Database Records Search 16
5.2.2 Vapor Encroachment Screening 21
5.2.3 Local Regulatory Review 21
5.2.3.1 Fire Department 21
5.2.3.2 Health Department 22
5.2.3.3 Air Quality Management District 22

5.2.3.4 California Regional Water Quality Control Board 22
5.2.3.5 Department of Toxic Substances Control 22
5.2.3.6 Assessor's Office 22
6.0 RECONNAISSANCE AND INTERVIEWS 24
6.1 PROPERTY CHARACTERISTICS 24
6.1.1 Topography 24
6.1.2 Potable Water Supply 24
6.1.3 Solid Waste Disposal 24
6.1.4 Sewage Discharge and Disposal 25
6.1.5 Surface Water Drainage 25
6.1.6 Source of Heating and Cooling 25
6.1.7 Wells and Cisterns 25
6.1.8 Current Occupants 25
6.2 POTENTIAL ENVIRONMENTAL HAZARDS 25
6.2.1 Hazardous Materials and Petroleum Products 25
6.2.2 Labeled Drums and Containers 25
6.2.3 Unlabeled Containers and Drums 25
6.2.4 Disposal Locations 26
6.2.5 Evidence of Releases 26
6.2.6 Stressed Vegetation/Stained Soils 26
6.2.7 Strong, Pungent or Noxious Odors 26
6.2.8 Polychlorinated Biphenyl's (PCBs) 26
6.2.9 Sumps, Drywells, Catchbasins or Clarifiers 26
6.2.10 Pits, Ponds or Lagoons 26
6.2.11 Groundwater Wells 26
6.2.12 Oil Wells/Pipelines 27
6.2.13 Imported Fill 27
6.2.14 On-Site ASTs and USTs 27
6.2.15 Radiological Hazards 27
6.2.16 Additional Hazard Observations 27
6.2.17 Asbestos 27
6.2.18 Lead-Based Paint 27
6.2.19 Radon 28
6.2.20 Water Intrusion and Mold Growth 28
6.3 INTERVIEWS 28
6.3.1 Property 28
6.3.2 Surrounding Area 28
6.3.3 Regulatory Agency Officials 29
6.4 ADDITIONAL SERVICES 29
7.0 CONCLUSIONS AND RECOMMENDATIONS 30
7.1 Conclusions 30
7.2 Recommendations 30
8.0 CONSULTANT INFORMATION 31
8.1 SIGNATURE PAGE 31

FIGURES

Figure 1 Site Topographic Map
Figure 2 Site Location Map
Figure 3 Site Plan

APPENDICES

Appendix A	Site Photographs
Appendix B	Aerial Photographs
Appendix C	Environmental Database Report
Appendix D	Other Pertinent Data
Appendix E	Qualifications

1.0 EXECUTIVE SUMMARY

1.1 FINDINGS

The Phase One Group has performed a Phase 1 Environmental Site Assessment (Phase 1 ESA) in general accordance with the scope and limitations of ASTM Practice E1527-13 of the Vacant Property located at the northeast side of Capalina Road, APN 219-115-33-00 (unaddressed), in the City of San Marcos, San Diego County, California 92069 (the "subject property"). The Phase 1 Environmental Site Assessment is designed to provide Ambient Communities with an assessment concerning environmental conditions as they exist at the subject property. Any exceptions to or deletions from this scope of work are described in the report.

The site inspection was performed by Mark E. Smith, Environmental Professional, a representative of The Phase One Group, on March 23, 2022. The subject property is located at the northeast side of Capalina Road, APN 219-115-33-00 (unaddressed), in the City of San Marcos, San Diego County, California 92069.

The subject property is located on the northeast side of Capalina Road, approximately 450 feet southeast of the intersection of Capalina Road and North Rancho Santa Fe Road. West Mission Road borders the northeast side of the subject property. The subject property consists of one parcel of land totaling approximately 2.51-acres in size, identified by the San Diego County Assessor as Assessor's Parcel Number (APN) 219-115-33-00. The subject property is vacant rough-graded land covered with weeds and a couple of palm trees. The perimeter of the subject property is surrounded by a chain-link fence with a gate on the southwest side of the subject property along Capalina Road. No structures were observed on-site. Several small piles of what appeared to be construction debris in the form of large rocks were observed along the northwestern portion of the subject property. At the time of The Phase One Group's site visit, the subject property was unoccupied. No evidence of the use of reportable quantities of hazardous materials and petroleum products or the generation of hazardous waste was observed on the subject property during the site visit.

Based on a review of historical sources, the subject property appeared to be vacant pastureland from prior to 1939 until approximately 1974, when the northwestern perimeter of the subject property appeared to be vacant, rough-graded land. By 1980, the subject property appeared to be vacant, rough-graded land with what appeared to be an area graded for use as a vehicle parking area on the southeastern portion of the subject property. By 1996, the subject property appeared to be vacant, weed-abated land, and by 2005, a vehicle parking area appears to be located on the southeastern perimeter of the subject property. By 2012, the vehicle parking area was removed and the subject property appeared to be vacant, weed-abated land.

The subject property is not listed in the Envirosite Corporation (Envirosite) environmental database report.

The subject property is located within a mixed commercial/retail and residential area of the City of San Marcos. The vicinity of the subject property can be described as to the northeast; a multi-tenant commercial/retail building (1605 West Mission Road) and a medical office building (1560 Capalina Road) to the southeast; Capalina Road, followed by El Dorado Mobil Home Park (1515 Capalina Road) and The Movement Church (1609 Capalina Road) to the southwest; and the remnants of a multi-tenant commercial/retail shopping center (225-245 North Rancho Santa Fe Road) to the northwest.

The adjacent property to the southeast, 1560 Capalina Road, is listed as a CalEPA Site and HAZMAT San Diego County site on the Envirosite environmental database report. However, based on the current regulatory statuses of the adjacent properties, the adjacent properties are not expected to represent a significant environmental concern to the subject property.

1.2 CONCLUSIONS

The Phase One Group has performed a Phase 1 Environmental Site Assessment in conformance with the scope and limitations of ASTM Standard E1527-13 of the Vacant Property located at the northeast side of Capalina Road, APN 219-115-33-00 (unaddressed), in the City of San Marcos, San Diego County, California 92069 (the "subject property"). Any exceptions to or deletions from this practice are described in Section 2.0 of this report. This assessment has revealed no evidence of recognized environmental conditions (RECs), historical recognized environmental conditions (HRECs), controlled recognized environmental conditions (CRECs) or environmental issues in connection with the subject property.

1.3 RECOMMENDATIONS

As a result of this assessment, The Phase One Group does not recommend further investigation of the subject property at this time.

This summary is not to be used alone. This report must be read in its entirety.

2.0 INTRODUCTION

2.1 PURPOSE

The purpose of this Phase 1 Environmental Site Assessment (Phase 1 ESA) is to identify existing or potential Recognized Environmental Conditions (as defined by ASTM Standard E1527-13) affecting the subject property that: 1) constitute or result in a material violation or a potential material violation of any applicable environmental law; 2) impose any material constraints on the operation of the subject property or require a material change in the use thereof; 3) require clean-up, remedial action or other response with respect to Hazardous Substances or Petroleum Products on or affecting the subject property under any applicable environmental law; 4) may affect the value of the subject property; and 5) may require specific actions to be performed with regard to such conditions and circumstances. The information contained in the Phase 1 ESA report will be used by Client to: 1) evaluate its legal and financial liabilities for transactions related to foreclosure, purchase, sale, loan origination, loan workout or seller financing; 2) evaluate the subject property's overall development potential, the associated market value and the impact of applicable laws that restrict financial and other types of assistance for the future development of the subject property; and/or 3) determine whether specific actions are required to be performed prior to the foreclosure, purchase, sale, loan origination, loan workout or seller financing of the subject property.

This Phase 1 ESA was performed to permit the User to satisfy one of the requirements to qualify for the innocent landowner, contiguous property owner, or bona fide prospective purchaser limitations on scope of Comprehensive Environmental Response, Compensation and Liability Act (CERCLA) (42 U.S.C. §9601) liability (hereinafter, the "landowner liability protections," or "LLPs"). ASTM Standard E1527-13 constitutes "all appropriate inquiry into the previous ownership and uses of the property consistent with good commercial or customary practice" as defined at 42 U.S.C. §9601(35)(B).

2.2 SCOPE OF WORK

The scope of work for this Phase 1 ESA is in general accordance with the requirements of ASTM Standard E1527-13. This assessment included: 1) a property and adjacent site reconnaissance; 2) interviews with key personnel; 3) a review of historical sources; 4) a review of environmental regulatory agency records; and 5) a review of an environmental regulatory database report provided by a third-party vendor. The Phase One Group contacted local agencies, such as environmental health departments, fire departments and building departments, in order to determine any current and/or former hazardous substances usage, storage and/or releases of hazardous substances on the subject property. Additionally, The Phase One Group researched information on the presence of Activity and Use Limitations (AULs) at these agencies. As defined by ASTM E1527-13, AULs are the legal or physical restrictions or limitations on the use of, or access to, a site or facility: 1) to reduce or eliminate potential exposure to

hazardous substances or petroleum products in the soil or groundwater on the subject property; or 2) to prevent activities that could interfere with the effectiveness of a response action, in order to ensure maintenance of a condition of no significant risk to public health or the environment. These legal or physical restrictions, which may include institutional and/or engineering controls (IC/ECs), are intended to prevent adverse impacts to individuals or populations that may be exposed to hazardous substances and petroleum products in the soil or groundwater on the property.

If requested by Client, this Phase 1 ESA report may also include the identification, discussion of, and/or limited sampling of asbestos-containing materials (ACMs), lead-based paint (LBP), mold and/or radon.

2.3 REPORT RELIANCE

This assessment was performed at the request of Ambient Communities utilizing methods and procedures consistent with good commercial or customary practices designed to conform to acceptable industry standards. This report may be distributed to and relied upon by Ambient Communities, its successors and assigns and Conduit to be assigned by Ambient Communities, its successors and assigns with respect to a loan upon the project, together with any rating agency or issuer or purchaser of any security collateralized or otherwise backed up by such loan. The independent conclusions The Phase One Group's best professional judgment based on the conditions that existed and the information and data available to us during the course of this assignment. Factual information regarding operations, conditions, and test data provided by Ambient Communities, owner, or its representative has been assumed to be correct and complete.

2.4 LIMITATIONS

The information presented in this Phase 1 ESA report is based on the agreed upon scope of work as noted above. The Phase One Group makes no warranties or guarantees as to the accuracy or completeness of information obtained from information provided or compiled by others. It is possible that information exists beyond the scope of this investigation. Also, changes in subject property use may have occurred sometime in the past due to variations in rainfall, temperature, water usage, economic, agricultural or other factors. Limited site specific information was made available to The Phase One Group about the subject property. Additional information that was not found or available to The Phase One Group at the time of writing the report, may result in a modification of the conclusions and recommendations presented. This report is not a legal opinion. The services performed by The Phase One Group have been conducted in a manner consistent with the level of care ordinarily exercised by members of our profession currently practicing under similar conditions. No other warranty, expressed or implied, is made.

The Phase One Group notes that all surficial environmental assessments are inherently limited in the sense that conclusions are drawn and recommendations developed from information obtained from limited research and site evaluation. Subsurface conditions were not field investigated as part of this study and may differ from the conditions

implied by the surficial observations. Additionally, the passage of time may result in a change in the environmental characteristics at this site and surrounding properties.

The Phase One Group notes that no investigation can absolutely rule out the existence of any hazardous materials at a given site. This assessment has been based upon prior site history and observable conditions and activities. Existing hazardous materials and contaminants can escape detection using these methods.

The work performed in conjunction with this assessment and the data developed are intended as a description of available information at the dates and location given. This report does not warrant against future operations or conditions, nor does it warrant against operations or conditions present of a type or at a location not investigated. In addition, this report is not intended as a regulatory agency compliance/safety audit or for the purpose of ensuring that all applicable permits and/or operating procedures are current and/or appropriate.

The Phase One Group recommends that any periodic review of any property should include an update of information on environmental conditions in the area. The Phase One Group notes that no soils, groundwater, or potable water testing for the presence of hazardous substances was performed for this assessment.

2.5 LIMITING CONDITIONS

The findings and conclusions contain all of the limitations inherent in these methodologies that are referred to in ASTM E1527-13.

Specific limitations and exceptions to this Phase 1 ESA are more specifically set forth below:

- Interviews with past owners, operators and occupants were not reasonably ascertainable and thus constitute a data gap. Based on information obtained from other historical sources (as discussed in Section 5.1.2), this data gap is not expected to alter the findings of this investigation.

- The Phase One Group requested information relative to deed restrictions and environmental liens, and a pre-survey questionnaire from the Report User. This information was not provided at the time of the assessment.

- The Phase One Group performed the site inspection without the benefit of a key site manager and was unaccompanied. Based on the size and nature of use of the subject property (vacant land), this limited method of inspection is not expected to alter the overall findings of this assessment.

3.0 PROPERTY DESCRIPTION

3.1 PROPERTY LOCATION AND DESCRIPTION

3.1.1 Type of Property

The subject property is located on the northeast side of Capalina Road, approximately 450 feet southeast of the intersection of Capalina Road and North Rancho Santa Fe Road. West Mission Road borders the northeast side of the subject property. The subject property consists of one parcel of land totaling approximately 2.51-acres in size, identified by the San Diego County Assessor as Assessor's Parcel Number (APN) 219-115-33-00. The subject property is vacant, rough-graded land covered with weeds and a couple of palm trees. The perimeter of the subject property is surrounded by a chain-link fence with a gate on the southwest side of the subject property along Capalina Road. No structures were observed on-site. Several small piles of what appeared to be construction debris in the form of large rocks were observed along the northwestern portion of the subject property. At the time of The Phase One Group's site visit, the subject property was unoccupied. No evidence of the use of reportable quantities of hazardous materials and petroleum products or the generation of hazardous waste was observed on the subject property during the site visit.

3.1.2 Improvements

The subject property is vacant rough-graded land covered with weeds and a couple of palm trees. The perimeter of the subject property is surrounded by a chain-link fence with a gate on the southwest side of the subject property along Capalina Road. No structures were observed on-site. Several small piles of what appeared to be construction debris in the form of large rocks were observed along the northwestern portion of the subject property.

3.1.3 Current Property Use

At the time of The Phase One Group's site visit, the subject property was unoccupied. No evidence of the use of reportable quantities of hazardous materials and petroleum products or the generation of hazardous waste was observed on the subject property during the site visit.

4.0 USER PROVIDED INFORMATION

Pursuant to ASTM E1527-13, The Phase One Group requested the following site information from Ambient Communities (User of this report).

4.1 TITLE RECORDS

The Phase One Group requested title records from the User; however, title records were not available and were not provided to The Phase One Group for review.

4.2 ENVIRONMENTAL LIENS OR ACTIVITY USE LIMITATIONS

The Phase One Group requested information from the User regarding knowledge of environmental liens, activity and use limitations for the subject property. The User, Ambient Communities, was not aware of any environmental liens associated with the subject property. In addition, Kevin Fortuna, property owner representative, was not aware of any environmental liens associated with the subject property.

4.3 SPECIALIZED KNOWLEDGE

The Phase One Group inquired with the site contact regarding any specialized knowledge of environmental conditions associated with the subject property. The User, Ambient Communities, was not aware of any environmental conditions associated with the subject property. In addition, Kevin Fortuna, property owner representative, was not aware of any environmental conditions associated with the subject property.

4.4 COMMONLY KNOWN OR REASONABLY ASCERTAINABLE INFORMATION

The Phase One Group inquired with the User regarding commonly known or reasonably ascertainable information associated with the subject property. The User, Ambient Communities, was unaware of commonly known or reasonably ascertainable information within the local community about the subject property that is material to recognized environmental conditions in connection with the subject property. In addition, Kevin Fortuna, property owner representative, was unaware of commonly known or reasonably ascertainable information within the local community about the subject property that is material to recognized environmental conditions in connection with the subject property.

4.5 VALUATION REDUCTION FOR ENVIRONMENTAL ISSUES

The Phase One Group inquired with the site contact regarding any knowledge of reductions in property value due to environmental issues. The User, Ambient Communities, was not aware of any valuation reductions associated with the subject property. In addition, Kevin Fortuna, property owner representative, was not aware of any valuation reductions associated with the subject property.

4.6 OWNER, PROPERTY MANAGER AND OCCUPANT INFORMATION

According to the San Diego County Assessor, the current subject property owner is identified as Saba Family Trust 07-24-18, who has owned the subject property since August 2, 2019. Kevin Fortuna, property owner representative, was interviewed and provided property specific information. At the time of The Phase One Group's site visit, the subject property was unoccupied. No evidence of the use of reportable quantities of hazardous materials and petroleum products or the generation of hazardous waste was observed on the subject property during the site visit.

4.7 PRIOR REPORTS

No prior reports issued for the subject property by others were provided to The Phase One Group for review.

4.8 REASON FOR PERFORMING PHASE 1 ESA

The Phase One Group understands that the findings of this study will be used by Ambient Communities for environmental due diligence purposes.

5.0 RECORDS REVIEW

5.1 GENERAL PUBLIC RECORDS

5.1.1 Physical Setting Sources

5.1.1.1 Topography

The United States Geological Survey (USGS), San Marcos, California Quadrangle 7.5-minute series topographic map was reviewed for this ESA. This map was published by the Geological Survey in 1983. According to the contour lines on the topographic map, the subject property is located approximately 583 feet above Mean Sea Level (msl). The contour lines in the area of the subject property slopes gently to the east. The subject property is depicted on the map as undeveloped.

5.1.1.2 Geology/Soils

The subject property is situated in an area underlain by undifferentiated alluvium and slope wash. The alluvium consists of poorly consolidated stream deposits of silt, sand, and cobble-sized particles derived from bedrock sources east of the subject property. The deposits mix with Holocene slope wash that commonly mantles the lower valley slopes throughout much of coastal San Diego County. The slope wash deposits are poorly consolidated surficial materials derived from nearby sources of soil and decomposed bedrock. The slope wash is deposited along the flanks of the lower valley slopes by interaction of gravity and water.

Based on information obtained from the USDA Natural Resources Conservation Service Web Soil Survey online database, the subject property is mapped as Diablo clay, 2 to 9 percent slopes (DaC), Diablo clay, 9 to 15 percent slopes, warm MAAT (DaD), and Las Flores loamy fine sand, 2 to 9 percent slopes (LeC). The Diablo series soils are formed from residuum weathered from calcareous shale, are well drained and have a moderate available water supply. The Las Flores series soils are formed from residuum weathered from siliceous calcareous sandstone, are moderately well drained and have a very low available water supply.

5.1.1.3 Hydrology

According to California's Groundwater: Bulletin 118, published by the State of California Department of Water Resources, the subject property is located in the Hydrologic Region South Coast, San Marcos Valley Groundwater Basin. This groundwater basin underlies San Marcos Valley in northwestern San Diego County. The basin is bounded by semi-permeable marine and nonmarine deposits, and impermeable granitic and metamorphic rocks. San Marcos Creek

drains this valley southwestward into Lake San Marcos. Average annual precipitation ranges from 11 to 15 inches.

The nearest surface water in the vicinity of the subject property is Lake San Marcos, located approximately 1.75-miles south-southwest of the subject property. No settling ponds, lagoons, surface impoundments, wetlands or natural catch basins were observed at the subject property during this assessment.

According to available information, a public water system operated by the Vallecitos Water District serves the subject property vicinity. According to a representative of the Vallecitos Water District, shallow groundwater beneath the subject property is not utilized for domestic purposes. The source of public water for the Vallecitos Water District is water purchased from the San Diego County Water Authority (SDCWA).

According to environmental documentation posted on the State Water Resources Control Board, GeoTracker website (http://geotracker.swrcb.ca.gov), the depth and direction of groundwater in the vicinity of the subject property is approximately 14 feet below ground surface (bgs) and inferred to flow toward the east.

5.1.2 Historical Use Information

5.1.2.1 Prior Uses of Property

Based on a review of historical sources, the subject property appeared to be vacant pastureland from prior to 1939 until approximately 1974, when the northwestern perimeter of the subject property appeared to be vacant, rough-graded land. By 1980, the subject property appeared to be vacant, rough-graded land with what appeared to be an area graded for use as a vehicle parking area on the southeastern portion of the subject property. By 1996, the subject property appeared to be vacant, weed-abated land, and by 2002, a vehicle parking area appears to be located on the southeastern perimeter of the subject property. By 2012, the vehicle parking area was removed and the subject property appeared to be vacant, weed-abated land.

5.1.2.2 Recorded Land Title Records

Environmental liens recorded against the subject property were not reported to The Phase One Group.

5.1.2.3 Chain of Title

A 50-year chain-of-title was not requested for this study. Historical use of the subject property was researched using other standard historical sources.

5.1.2.4 Aerial Photographs

Available aerial photographs dated 1939, 1947, 1953, 1963, 1971, 1974, 1979, 1980, 1985, 1989, 1994, 1996, 2001, 2005, 2009, 2010, 2012, 2014, 2016 and 2020 from Envirosite Corporation (Envirosite) were reviewed for this Phase 1 ESA. The photographs are discussed below.

Date: **1939**
Source: **USDA**
Description: The 1939 aerial photograph shows the subject property as vacant pastureland. The adjacent property to the northeast across West Mission Road and a railroad track appears to be vacant pastureland. The adjacent property to the southeast appears to be vacant pastureland. The adjacent property to the southwest across Capalina Road appears to be vacant pastureland. The adjacent property to the northwest appears to be vacant pastureland.

Date: **1947**
Source: **USDA**
Description: The 1947 aerial photograph showed no changes to the subject property or the adjoining properties as compared to the 1939 aerial photograph.

Date: **1953**
Source: **USDA**
Description: The 1953 aerial photograph showed no changes to the subject property or the adjoining properties as compared to the 1947 aerial photograph.

Date: **1963**
Source: **USDA**
Description: The 1963 aerial photograph shows the subject property as vacant pastureland. The adjacent property to the northeast across West Mission Road and a railroad track appears to be vacant pastureland. The adjacent property to the southeast appears to be vacant pastureland. The adjacent property to the southwest across Capalina Road appears to be developed with the existing mobile home park and vacant pastureland. The adjacent property to the northwest appears to be vacant pastureland.

Date: **1971**
Source: **USGS**
Description: The 1971 aerial photograph showed no changes to the subject property or the adjoining properties as compared to the 1963 aerial photograph.

Date: 1974
Source: USDA
Description: The 1974 aerial photograph shows the northwestern portion of the subject property as vacant, rough-graded land, and the remainder of the subject property as vacant pastureland. The adjacent property to the northeast across West Mission Road and a railroad track appears to be vacant pastureland. The adjacent property to the southeast appears to be developed with the existing multi-tenant commercial/retail building and the existing medical office building. The adjacent property to the southwest across Capalina Road appears to be developed with the existing mobile home park and vacant pastureland. The adjacent property to the northwest appears to be developed with a multi-tenant commercial/retail shopping center.

Date: 1979
Source: USGS
Description: The 1979 aerial photograph showed no changes to the subject property or the adjoining properties as compared to the 1974 aerial photograph.

Date: 1980
Source: USGS
Description: The 1980 aerial photograph shows the subject property as vacant, rough-graded land with what appears to be an area graded for use as a vehicle parking area on the southeastern portion of the subject property. The adjacent property to the northeast across West Mission Road and a railroad track appears to be vacant pastureland. The adjacent property to the southeast appears to be developed with the existing multi-tenant commercial/retail building and the existing medical office building. The adjacent property to the southwest across Capalina Road appears to be developed with the existing mobile home park and vacant land. The adjacent property to the northwest appears to be developed with a multi-tenant commercial/retail shopping center.

Date: 1985
Source: NHAP
Description: The 1985 aerial photograph showed no changes to the subject property or the adjoining properties as compared to the 1980 aerial photograph.

Date: 1989
Source: NAPP
Description: The 1989 aerial photograph showed no changes to the subject property or the adjoining properties as compared to the 1985 aerial photograph.

Date: 1994
Source: DOQ
Description: The 1994 aerial photograph shows the subject property as vacant, rough-graded land with what appears to be an area graded for use as a vehicle parking area on the southeastern portion of the subject property. The adjacent property to the northeast across West Mission Road, a railroad track and the Inland Rail Trail appears to be vacant land. The adjacent property to the southeast appears to be developed with the existing multi-tenant commercial/retail building and the existing medical office building. The adjacent property to the southwest across Capalina Road appears to be developed with the existing mobile home park and the existing church. The adjacent property to the northwest appears to be developed with a multi-tenant commercial/retail shopping center.

Date: 1996
Source: DOQ
Description: The 1996 aerial photograph shows the subject property as vacant, weed-abated land. The adjacent property to the northeast across West Mission Road, a railroad track and the Inland Rail Trail appears to be vacant land. The adjacent property to the southeast appears to be developed with the existing multi-tenant commercial/retail building and the existing medical office building. The adjacent property to the southwest across Capalina Road appears to be developed with the existing mobile home park and the existing church. The adjacent property to the northwest appears to be developed with a multi-tenant commercial/retail shopping center.

Date: 2001
Source: USDA
Description: The 2001 aerial photograph showed no changes to the subject property or the adjoining properties as compared to the 1996 aerial photograph.

Date: 2005
Source: NAIP
Description: The 2005 aerial photograph shows the subject property as vacant, weed-abated land with a vehicle parking area on the southeastern perimeter of the subject property. The adjacent property to the northeast across West Mission Road, a railroad track and the Inland Rail Trail appears to be vacant land. The adjacent property to the southeast appears to be developed with the existing multi-tenant commercial/retail building and the existing medical office building. The adjacent property to the southwest across Capalina Road appears to be developed with the existing mobile home park and the existing church. The adjacent property to the northwest

appears to be developed with a multi-tenant commercial/retail shopping center.

Date: **2009**
Source: **NAIP**
Description: The 2009 aerial photograph showed no changes to the subject property or the adjoining properties as compared to the 2005 aerial photograph.

Date: **2010**
Source: **NAIP**
Description: The 2010 aerial photograph showed no changes to the subject property or the adjoining properties as compared to the 2009 aerial photograph.

Date: **2012**
Source: **NAIP**
Description: The 2012 aerial photograph shows the subject property as vacant, weed-abated land. The adjacent property to the northeast across West Mission Road, a railroad track and the Inland Rail Trail appears to be vacant land. The adjacent property to the southeast appears to be developed with the existing multi-tenant commercial/retail building and the existing medical office building. The adjacent property to the southwest across Capalina Road appears to be developed with the existing mobile home park and the existing church. The adjacent property to the northwest appears to be developed with a multi-tenant commercial/retail shopping center.

Date: **2014**
Source: **NAIP**
Description: The 2014 aerial photograph showed no changes to the subject property or the adjoining properties as compared to the 2012 aerial photograph.

Date: **2016**
Source: **NAIP**
Description: The 2016 aerial photograph showed no changes to the subject property or the adjoining properties as compared to the 2014 aerial photograph.

Date: **2020**
Source: **NAIP**
Description: The 2020 aerial photograph showed no changes to the subject property or the adjoining properties as compared to the 2016 aerial photograph.

A copy of the reviewed historical aerial photographs is included in the appendix.

5.1.2.5 Fire Insurance Maps

Sanborn fire insurance maps were originally created in the late 1800s and early 1900s for assessing fire insurance liability in urbanized areas of the United States. These maps include detailed town and building information.

The Phase One Group reviewed Sanborn fire insurance maps available on-line from The Seattle Public Library's collection on March 23, 2022. Sanborn map coverage was not available for the subject property.

5.1.2.6 Historical City Directories

Historical city directories were not readily available at the time of the assessment. The historical use of the subject property was researched through other standard historical sources.

5.1.2.7 Building Permit Records

The Phase One Group contacted the City of San Marcos Development Services Department for building information on the subject property. No building permit records were found for the subject property.

5.1.2.8 Planning Records

The Phase One Group obtained information from the City of San Marcos Development Services Department for information on the subject property in order to identify Activity Use Limitations (AULs) associated with the subject property. According to records reviewed, the subject property is zoned MU-3 – Mixed-Use 3 – for mixed-use.

5.1.2.9 Other Maps

The Phase One Group performed a review of the Flood Insurance Rate Map, published by the Federal Emergency Management Agency. According to Community Panel Number 06073C 0789H, dated May 16, 2012, the subject property appears to be located in Zone X, defined as an area of minimal flood hazard.

The Phase One Group researched the State of California Department of Conservation, Division of Oil, Gas and Geothermal Resources (DOGGR), DOGGR Online Mapping System (http://maps.conservation.ca.gov/doms) for information regarding oil and gas development. According to the DOGGR Online Mapping System, no oil or gas wells are located on or adjacent to the subject property.

5.1.3 Properties and Areas Surrounding the Property

5.1.3.1 Current Uses of Adjoining Properties

The current use of adjoining properties was observed from the subject property as follows:

Northeast	West Mission Road, followed by the North San Diego County Transit Sprinter Hybrid Rail railroad track, Indian Rail Trail, and vacant land (no address identified)
Southeast	Multi-tenant commercial/retail building (1605 West Mission Road) and a medical office building (1560 Capalina Road)
Southwest	Capalina Road, followed by El Dorado Mobil Home Park (1515 Capalina Road) and The Movement Church (1609 Capalina Road)
Northwest	Remnants of a multi-tenant commercial/retail shopping center (225-245 North Rancho Santa Fe Road)

5.1.3.2 Past Uses

Based on a review of the historical aerial photographs, the adjacent properties were historically vacant pastureland prior to the development of the current improvements.

5.1.3.3 Current Use of Surrounding Areas

The subject property is located in a mixed commercial/retail and residential area of the City of San Marcos. None of the adjacent properties are expected to have posed an environmental concern to the subject property.

5.2 ENVIRONMENTAL RECORDS REVIEWS

5.2.1 Mapped Database Records Search

Information from standard federal and state environmental record sources is provided through Envirosite Corporation (Envirosite). Data from governmental agency lists are updated and integrated into one database, which is updated as these data are released. This integrated database also contains postal service data in order to enhance address matching. Records from one government source are compared to records from another to clarify any address ambiguities. The demographic and geographic information available provides assistance in identifying and managing risk. The accuracy of the geocoded locations is approximately +/- 300 feet. Based on the review of the unmappable sites, none of these sites are within the prescribed search radii.

The subject property is not listed in the Envirosite Corporation (Envirosite) environmental database report.

The adjacent property to the southeast, 1560 Capalina Road, is listed as a CalEPA Site and HAZMAT San Diego County site on the Envirosite environmental database report. However, based on the current regulatory statuses of the adjacent properties, the adjacent properties are not expected to represent a significant environmental concern to the subject property.

Federal NPL

The National Priorities List (NPL) is the Environmental Protection Agency (EPA) database of uncontrolled or abandoned hazardous waste sites identified for priority remedial actions under the Superfund Program.

No NPL sites are located within one mile of the subject property.

Federal CERCLIS List

The Comprehensive Environmental Response, Compensation and Liability Information System (CERCLIS) list is a compilation of sites that the EPA has investigated or is currently investigating for a release or threatened release of hazardous substances.

No CERCLIS sites are listed within one-half mile of the subject property.

Federal CERCLIS NFRAP Sites List

The CERCLIS No Further Remedial Action Planned (NFRAP) List is a compilation of sites that the EPA has investigated, and has determined that the facility does not pose a threat to human health or the environment, under the CERCLA framework.

One CERCLIS NFRAP site is listed within one-half mile of the subject property. However, based on the relative distance, regulatory status, and/or inferred direction of groundwater flow, the listed site is not expected to represent a significant environmental concern.

Federal Resource Conservation and Recovery Act (RCRA) CORRACTS TSD Facilities List

The EPA Resource Conservation and Recovery Act (RCRA) Program identifies and tracks hazardous waste from the point of generation to the point of disposal. The RCRA Treatment, Storage and Disposal (TSD) database is a compilation by the EPA of reporting facilities that treat, store or dispose of hazardous waste. The Corrective Action Sites (CORRACTS) database is the EPA's list of treatment storage or disposal facilities subject to corrective action under RCRA.

One RCRA CORRACTS TSD site is listed within one mile of the subject property. However, based on the relative distance, regulatory status, and/or inferred direction of

groundwater flow, the listed site is not expected to represent a significant environmental concern.

Federal Resource Conservation and Recovery Act (RCRA) Non-CORRACTS TSD Facilities List

The RCRA TSD database is a compilation by the EPA of reporting facilities that treat, store or dispose of hazardous waste.

No RCRA TSD sites are listed within one-half mile of the subject property.

Federal RCRA Generator List

The RCRA program identifies and tracks hazardous waste from the point of generation to the point of disposal. The RCRA Generators database is a compilation by the EPA of reporting facilities that generate hazardous waste.

No RCRA Generator facilities are listed on the subject property or adjacent to the subject property.

Federal Institutional Controls/Engineering Controls (IC/EC)

The Federal IC/EC database is designed to assist the EPA in collecting, tracking, and updating information, as well as reporting on the major activities and accomplishments of the various Brownfield grant programs. The IC/EC sites are superfund sites that have either engineering or an institutional control in place. The data includes the control and the media contaminated.

No Federal IC/EC sites were found within one-half mile of the subject property.

Federal Emergency Response Notification System (ERNS)

The Emergency Response Notification System (ERNS) is a national database used to collect information or reported release of oil or hazardous substances.

No ERNS sites were listed on the subject property or on the adjacent properties.

Tribal Lands

The Tribal Lands database consists of areas with boundaries established by treaty, statute, and/or executive or court order, recognized by the Federal Government as territory in which American Indian tribes have primary governmental authority. The Indian Lands of the United States map layer shows areas of 640 acres or more, administered by the Bureau of Indian Affairs. Included are Federally-administered lands within a reservation which may or may not be considered part of the reservation.

No Tribal Land sites were found within one-mile of the subject property.

State/Tribal Sites

The State of California Environmental Protection Agency, Department Toxic Substances Control (DTSC) maintains a State Priority List (SPL) of sites considered to be actually or potentially contaminated and a State CERCLIS-equivalent list (SCL) (ENVIROSTOR) of sites under investigation that could be actually or potentially contaminated and presenting a possible threat to human health and the environment.

No SPL sites and a total of five SCL (ENVIROSTOR) sites are listed within one-mile of the subject property. However, based on the relative distance, regulatory status, and/or inferred direction of groundwater flow, the listed sites are not expected to represent a significant environmental concern.

Solid Waste/Landfill Facilities (SWLF)

A database of Solid Waste/Landfill Facilities (SWF/LF) is prepared by California Integrated Waste Management Board.

One SWF/LF facility is listed within one-half mile of the subject property. However, based on the relative distance, regulatory status, and/or inferred direction of groundwater flow, the listed site is not expected to represent a significant environmental concern.

State/Tribal Leaking Underground Storage Tank List (LUST)

The California Regional Water Quality Control Board compiles lists of all leaks of hazardous substances from underground storage tanks, identified as Leaking Underground Storage Tank (LUST) facilities.

A total of 10 LUST facilities are identified within one-half mile of the subject property. However, based on the relative distance, regulatory status, and/or inferred direction of groundwater flow, the listed sites are not expected to represent a significant environmental concern.

State/Tribal Underground Storage Tank/Aboveground Storage Tank List (UST/AST)

The California Regional Water Quality Control Board compiles a list of underground storage tank (UST) and aboveground storage tank (AST) locations.

No UST or AST facilities are listed on the subject property or on the adjacent properties.

State/Tribal VCP Sites

The California Department of Toxic Substances Control compiles a list of Voluntary Cleanup Program (VCP) sites. This list contains low threat level properties with either confirmed or unconfirmed releases and the project proponents have request that DTSC

oversee investigation and/or cleanup activities and have agreed to provide coverage for DTSC's costs.

No State/Tribal VCP sites were found within one-half mile of the subject property.

State/Tribal Brownfields Sites

The California Department of Toxic Substances Control has developed an electronic database system with information about sites that are known to be contaminated with hazardous substances as well as information on uncharacterized properties where further studies may reveal problems. The Site Mitigation and Brownfields Reuse Program Database (SMBRPD), also known as CalSites, is used primarily by DTSC's staff as an informational tool to evaluate and track activities at properties that may have been affected by the release of hazardous substances.

No State/Tribal Brownfields sites were found within one-half mile of the subject property.

SLIC Sites

The Spills, Leaks, Investigations and Cleanup (SLIC) program, managed by the California Regional Water Quality Control Board, is designed to protect and restore water quality from spills, leaks and similar discharges. This list includes sites that have recorded spills, leaks, investigations, and cleanups.

A total of five SLIC sites are listed within one-half mile of the subject property. However, based on the relative distance, regulatory status, and/or inferred direction of groundwater flow, the listed sites are not expected to represent a significant environmental concern.

DRYCLEANERS Sites

The California EPA maintains a list of registered dry cleaning facilities.

Two DRYCLEANERS sites are listed within one-fourth mile of the subject property. However, based on the relative distance, regulatory status, and/or inferred direction of groundwater flow, the listed sites are not expected to represent a significant environmental concern.

HAZMAT San Diego County Sites

The HAZMAT San Diego County listing is a list of hazardous material permitted facilities in San Diego County.

The subject property is not listed as a HAZMAT San Diego County site. One adjoining property is listed as a HAZMAT San Diego County site and are discussed below:

- Capalina Clinic, at 1560 Capalina Road, is located adjacent to the southeast side of the subject property. According to the environmental database report, this site is

identified as a "United Program Facility Permit" site. No violations are reported. Based on the current regulatory status, this site is not expected to represent a significant environmental concern to the subject property.

CalEPA Sites

CalEPA regulated sites (CalEPA Sites) are sites from the Certified United Program Agencies (CUPA).

The subject property is not listed as a CalEPA Site. One adjoining property is listed as a CalEPA Sites and is discussed below:

- Capalina Clinic, at 1560 Capalina Road, is located adjacent to the southeast side of the subject property. According to the environmental database report, this tenant is listed as a "Chemical Storage Facility" site. No violations are reported. Based on the current regulatory status, this site is not expected to represent a significant environmental concern to the subject property

Unmappable Listings

A total of 10 unmappable listings are identified in the regulatory database report. However, based on the relative distance, regulatory status, and/or inferred direction of groundwater flow, the listed sites are not expected to represent a significant environmental concern.

5.2.2 Vapor Encroachment Screening

ASTM defines a vapor encroachment condition (VEC) as the presence or likely presence of vapors from chemicals of concern (COC) in the subsurface of a property caused by the release of vapors on or near the subject property. As a "Tier 1" vapor encroachment screening, The Phase One Group reviewed information obtained during the Phase I ESA, including the environmental database, visual observations of adjacent and nearby properties, geology, groundwater depth and flow direction, interviews of knowledgeable persons, and known sources of contamination in the nearby vicinity to evaluate the likelihood of a VEC in connection with the subject property. This information indicates there are no known active sources of contamination within 500 feet of the subject property, or large quantity generators of waste containing potential COC within 200 feet. Based on the results of this Tier 1 screening, it appears reasonable to conclude that a VEC can be ruled out for the subject property.

5.2.3 Local Regulatory Review

5.2.3.1 Fire Department

Records from the City of San Marcos Fire Department were requested for evidence indicating the presence of underground storage tanks (USTs) and for the use of hazardous materials.

No records were on-file for the subject property.

5.2.3.2 Health Department

Records from the San Diego County Department of Environmental Health (SDCDEH) were requested for evidence indicating the presence of underground storage tanks (USTs) and for the use of hazardous materials.

No records were on-file for the subject property.

5.2.3.3 Air Quality Management District

The Phase One Group researched the San Diego Air Pollution Control District (SDAPCD) records via the San Diego County website (www.sandiegocounty.gov) for information regarding any Permits to Operate (PTO), Notices of Violation (NOV), or Notices to Comply (NTC) records for the subject property related to air emission equipment, which may include dry cleaning machines and underground storage tanks.

No PTOs, NOVs, NTCs or the presence of AULs were on-file for the subject property with the SDAPCD.

5.2.3.4 California Regional Water Quality Control Board

The Phase One Group researched the California Regional Water Quality Control Board (CRWQCB) online database (GeoTracker) for information regarding any releases to the subsurface which may have impacted or threatened a body of water.

No records regarding a release or the presence of AULs on the subject property were on-file with the CRWQCB.

5.2.3.5 Department of Toxic Substances Control

The Phase One Group researched the Department of Toxic Substances Control (DTSC) online database (EnviroStor) for the subject property. These records may contain evidence indicating current and/or historical hazardous materials usage, storage or releases.

No records regarding a release or the presence of AULs on the subject property were on file with the DTSC.

5.2.3.6 Assessor's Office

According to the San Diego County Assessor, the subject property consists of one parcel of land totaling approximately 2.510-acres in size, identified by the San Diego County Assessor as Assessor's Parcel Number (APN) 219-115-33-00. The

current subject property owner is identified as Saba Family Trust 07-24-18, who has owned the subject property since August 2, 2019.

A copy of the reviewed records is included in the appendix.

6.0 RECONNAISSANCE AND INTERVIEWS

The subject property was inspected by Mark E. Smith, Environmental Professional, a representative of The Phase One Group, on March 23, 2022. The weather at the time of the site visit was sunny and approximately 80 degrees Fahrenheit. At the time of The Phase One Group's site visit, the subject property was unoccupied. No evidence of the use of reportable quantities of hazardous materials and petroleum products or the generation of hazardous waste was observed on the subject property during the site visit.

6.1 PROPERTY CHARACTERISTICS

6.1.1 Topography

The United States Geological Survey (USGS), San Marcos, California Quadrangle 7.5-minute series topographic map was reviewed for this ESA. This map was published by the Geological Survey in 1983. According to the contour lines on the topographic map, the subject property is located approximately 583 feet above Mean Sea Level (msl). The contour lines in the area of the subject property slopes gently to the east. The subject property is depicted on the map as undeveloped.

6.1.2 Potable Water Supply

According to available information, a public water system operated by the Vallecitos Water District serves the subject property vicinity. According to a representative of the Vallecitos Water District, shallow groundwater beneath the subject property is not utilized for domestic purposes. The source of public water for the Vallecitos Water District is water purchased from the San Diego County Water Authority (SDCWA). According to the Vallecitos Water District 2020 Water Quality Report, water supplied to the subject property is in compliance with all State and Federal regulations pertaining to drinking water standards, including lead and copper. Water sampling was not conducted to verify water quality.

6.1.3 Solid Waste Disposal

The subject property was unoccupied and no buildings were observed on-site at the time of The Phase One Group's site visit. No evidence of solid waste disposal collection service was observed on-site. No evidence of the use of reportable quantities of hazardous materials and petroleum products or the generation of hazardous waste was observed on the subject property during the site visit.

During The Phase One Group's site visit, several small piles of what appeared to be construction debris in the form of large rocks were observed along the northwestern portion of the subject property. The observed piles of construction debris are not expected to represent a significant environmental concern to the subject property.

6.1.4 Sewage Discharge and Disposal

The subject property area is serviced by the City of San Marcos. No evidence of on-site septic tanks or septic systems was noted.

6.1.5 Surface Water Drainage

Surface water drainage from the subject property is via sheet flow throughout the subject property to curb and gutter systems along the surrounding streets.

6.1.6 Source of Heating and Cooling

The subject property was unoccupied and no structures were observed on-site at the time of The Phase One Group's site visit. No evidence of heating or cooling equipment was observed on-site.

6.1.7 Wells and Cisterns

No evidence of wells or cisterns was observed on the subject property.

6.1.8 Current Occupants

At the time of The Phase One Group's site visit, the subject property was unoccupied. No evidence of the use of reportable quantities of hazardous materials and petroleum products or the generation of hazardous waste was observed on the subject property during the site visit.

6.2 POTENTIAL ENVIRONMENTAL HAZARDS

6.2.1 Hazardous Materials and Petroleum Products

The on-site reconnaissance addressed hazardous materials and petroleum products utilized on the subject property. No evidence of the use of reportable quantities of hazardous materials and petroleum products was observed at the subject property. No indication of potential hazardous material disposal was noted during the site visit.

6.2.2 Labeled Drums and Containers

The on-site reconnaissance addressed labeled drums and containers located on the subject property. No evidence of drums and containers of hazardous materials or hazardous waste were observed at the subject property.

6.2.3 Unlabeled Containers and Drums

The on-site reconnaissance addressed unlabeled containers located on the subject property. No evidence of unlabeled containers or drums was observed at the subject property.

6.2.4 Disposal Locations

The on-site reconnaissance addressed unlabeled containers located on the subject property. No evidence of unlabeled containers or drums was observed at the subject property.

6.2.5 Evidence of Releases

No evidence of a release or spill was observed at the subject property.

6.2.6 Stressed Vegetation/Stained Soils

No evidence of stressed vegetation or stained soils was observed at the subject property.

6.2.7 Strong, Pungent or Noxious Odors

No evidence of strong, pungent or noxious odors was identified at the subject property.

6.2.8 Polychlorinated Biphenyl's (PCBs)

Older transformers and other electrical equipment could contain PCBs at a level that subjects them to regulation by the U.S. EPA. PCBs in electrical equipment are controlled by United States Environmental Protection Agency regulations 40 CFR, Part 761. Under the regulations, there are three categories into which electrical equipment can be classified: 1) Less than 50 parts per million (ppm) of PCBs – "Non-PCB;" 2) 50 ppm-500 ppm – "PCB-Contaminated;" and, 3) Greater than 500 ppm – "PCB-Containing." The manufacture, process, or distribution in commerce or use of any PCB in any manner other than in a totally enclosed manner was prohibited after January 1, 1977.

The on-site reconnaissance addressed indoor and outdoor transformers that may contain PCBs. No evidence of on-site transformers was observed at the subject property.

No additional potential PCB-containing equipment (oil-filled switches, hoists, lifts, dock levelers, hydraulic elevators, etc.) was observed on the subject property.

6.2.9 Sumps, Drywells, Catchbasins or Clarifiers

No evidence of sumps, drywells, catchbasins or clarifiers was found on the subject property.

6.2.10 Pits, Ponds or Lagoons

No evidence of pits, ponds or lagoons was observed at the subject property.

6.2.11 Groundwater Wells

No evidence of groundwater wells was observed or reported at the subject property.

6.2.12 Oil Wells/Pipelines

No evidence of oil wells or pipelines was observed or reported at the subject property.

6.2.13 Imported Fill

No information related to the use of imported fill material was identified in records for the subject property.

6.2.14 On-Site ASTs and USTs

No evidence of aboveground storage tanks (ASTs) or underground storage tanks (USTs) was identified on-site during the site visit.

6.2.15 Radiological Hazards

No evidence of radiological substances or equipment was stored on the subject property.

6.2.16 Additional Hazard Observations

No additional hazards were observed on the subject property.

6.2.17 Asbestos

Asbestos is the name given to a number of naturally occurring, fibrous silicate minerals mined for their useful properties such as thermal insulation, chemical and thermal stability, and high tensile strength. The Occupational Safety and Health Administration (OSHA) regulation 29 CFR 1926.1101 requires certain construction materials to be presumed to contain asbestos, for purposes of this regulation. All thermal system insulation (TSI), surfacing material, and asphalt/vinyl flooring that are present in a building constructed prior to 1981 and have not been appropriately tested are "presumed asbestos-containing material" (PACM).

The subject property was unoccupied and no structures were observed on-site at the time of The Phase One Group's site visit. As such, an asbestos evaluation was not performed.

6.2.18 Lead-Based Paint

Lead is a highly toxic metal that affects virtually every system of the body. LBP is defined as any paint, varnish, stain, or other applied coating that has 1 mg/cm2 (or 5,000 ug/g or 0.5% by weight) or more of lead. Congress passed the Residential Lead-Based Paint Hazard Reduction Act of 1992, also known as "Title X", to protect families from exposure to lead from paint, dust, and soil. Under Section 1017 of Title X, intact LBP on most walls and ceilings is not considered a "hazard," although the condition of the paint should be monitored and maintained to ensure that it does not become deteriorated. Further, Section 1018 of this law directed the Housing and Urban Development (HUD) and the US EPA to require the disclosure of known information on LBP and LBP hazards before the sale or lease of most housing built before 1978.

The subject property was unoccupied and no structures were observed on-site at the time of The Phase One Group's site visit. As such, a lead-based paint evaluation was not performed.

6.2.19 Radon

Radon is a colorless, odorless, naturally occurring, radioactive, inert and gaseous element formed by radioactive decay of radium (Ra) atoms. The USEPA has prepared a map to assist National, State, and local organizations to target their resources and to implement radon-resistant building codes. The map divides the country into three Radon Zones; Zone 1 being those areas with the average predicted indoor radon concentration in residential dwellings exceeding the US EPA Action Limit of 4.0 picoCuries per Liter (pCi/L). It is important to note that the EPA has found homes with elevated levels of radon in all three zones, and the US EPA recommends site-specific testing in order to determine radon levels at a specific location. However, the map does give a valuable indication of the propensity of radon gas accumulation in structures.

Radon sampling was not conducted as part of this assessment. Review of the US EPA Map of Radon Zones places the subject property in Zone 3, where average predicted radon levels are less than 2.0 pCi/L.

Based upon the radon zone classification, radon is not considered to be a significant environmental concern.

6.2.20 Water Intrusion and Mold Growth

The Phase One Group performed a limited visual inspection for the conspicuous presence of mold in the subject property buildings. The Phase One Group inspected the accessible interior areas of the subject property building, including walls and ceilings, common mechanical/electrical closets, areas under sinks and around windows and exterior doors for the presence of conspicuous mold or observed water intrusion or accumulation.

The subject property was unoccupied and no structures were observed on-site at the time of The Phase One Group's site visit. As such, a mold evaluation was not performed.

6.3 INTERVIEWS

Interviews were conducted with the following individuals. Findings from these interviews are discussed in the appropriate sections in this report.

6.3.1 Property

- Kevin Fortuna, property owner representative, 949.291.6493

6.3.2 Surrounding Area

- N/A

6.3.3 Regulatory Agency Officials

- City of San Marcos Development Services Department
- City of San Marcos Fire Department
- San Diego County Assessor
- San Diego County Department of Environmental Health (SDCDEH)
- San Diego Air Pollution Control District (SDAPCD)
- Department of Toxic Substances Control (DTSC)
- California Regional Water Quality Control Board (CRWQCB)
- South Coast Air Quality Management District (SCAQMD)
- State of California Department of Conservation, Division of Oil, Gas and Geothermal Resources (DOGGR), DOGGR Online Mapping System

6.4 ADDITIONAL SERVICES

No additional services were performed with this scope of work.

7.0 CONCLUSIONS AND RECOMMENDATIONS

7.1 CONCLUSIONS

The Phase One Group has performed a Phase 1 Environmental Site Assessment in conformance with the scope and limitations of ASTM Standard E1527-13 of the Vacant Property located at the northeast side of Capalina Road, APN 219-115-33-00 (unaddressed), in the City of San Marcos, San Diego County, California 92069 (the "subject property"). Any exceptions to or deletions from this practice are described in Section 2.0 of this report. This assessment has revealed no evidence of recognized environmental conditions (RECs), historical recognized environmental conditions (HRECs), controlled recognized environmental conditions (CRECs) or environmental issues in connection with the subject property.

7.2 RECOMMENDATIONS

As a result of this assessment, The Phase One Group does not recommend further investigation of the subject property at this time.

This summary is not to be used alone. This report must be read in its entirety.

8.0 CONSULTANT INFORMATION

8.1 SIGNATURE PAGE

By signing below, The Phase One Group declares that, to the best of our professional knowledge and belief, we meet the definition of Environmental Professional as defined in §312.10 of 40 CFR §312. The Phase One Group has the specific qualifications based on education, training, and experience to assess a property of the nature, history, and setting of the subject property. The Phase One Group has developed and performed the all appropriate inquiries in conformance with the standards and practices set forth in 40 CFR Part 312.



Mark E. Smith, Environmental Professional
President
The Phase One Group LLC

FIGURES

Site Topographic Map
Site Location Map
Site Plan



SITE TOPOGRAPHIC MAP

DRAWING NOT TO SCALE

Source: USGS 7.5-Minute Topographic Map, San Marcos, CA Quadrangle 1983

N↑

The Phase One Group

Site: Vacant Property
Northeast Side of Capalina Road
APN 219-115-33-00
San Marcos, California 92069

Project No.: 22-015



SITE LOCATION MAP

DRAWING NOT TO SCALE

Source: Google Maps

N↑

The Phase One Group

Site: Vacant Property
Northeast Side of Capalina Road
APN 219-115-33-00
San Marcos, California 92069

Project No.: 22-015

SITE PLAN

DRAWING NOT TO SCALE

Source: Google Earth

N↑

The Phase One Group

Site:	Vacant Property Northeast Side of Capalina Road APN 219-115-33-00 San Marcos, California 92069
Project No.:	22-015

APPENDIX A

Site Photographs

Photograph Number 1: View of southwest side of subject property along Capalina Road, facing east.

Photograph Number 2: View of southwest side of subject property along Capalina Road, facing north.

Photograph Number 3: View of southwest side of subject property along Capalina Road, facing northeast.

Photograph Number 4: View of southwest side of subject property along Capalina Road, facing east-northeast.

Photograph Number 5: View of southwest side of subject property along Capalina Road, facing north-northwest.

Photograph Number 6: View of northeast side of subject property along West Mission Road, facing east.

Photograph Number 7: View of northeast side of subject property along West Mission Road, facing south.

Photograph Number 8: View of northeast side of subject property along West Mission Road, facing southwest.

Photograph Number 9: View of northeast side of subject property along West Mission Road, facing west-southwest.

Photograph Number 10: View of northeast side of subject property along West Mission Road, facing south-southeast.

Photograph Number 11: View of western portion of subject property along Capalina Road, facing northeast.

Photograph Number 12: View of western portion of subject property, facing east.

Photograph Number 13: View of southern portion of subject property, facing north-northeast.

Photograph Number 14: View of southeastern portion of subject property, facing northwest.

Photograph Number 15: View southern portion of subject property, facing southwest.

Photograph Number 16: View of eastern portion of subject property, facing southwest.

Photograph Number 17: View of eastern portion of subject property, facing west-northwest.

Photograph Number 18: View of northwestern portion of subject property, facing south.

Photograph Number 19: View of northern portion of subject property and a small pile of construction debris in the form of large rocks, facing south.

Photograph Number 20: View of the northwestern portion of the subject property and a small pile of construction debris in the form of large rocks, facing northwest.

Photograph Number 21: View of northwestern portion of subject property and small pile of construction debris in the form of large rocks, facing north-northwest.

Photograph Number 22: View of northwestern portion of subject property, facing southwest.

Photograph Number 23: View of adjacent property to the northeast across West Mission Road, facing north.

Photograph Number 24: View of adjacent property to the northeast across West Mission Road, facing northeast.

Photograph Number 25: View of adjacent property to the northeast across West Mission Road, facing east-northeast.

Photograph Number 26: View of adjacent property to the southeast along West Mission Road, facing south.

Photograph Number 27: View of adjacent property to the southeast along Capalina Road, facing east.

Photograph Number 28: View of adjacent property to the southwest across Capalina Road, facing south.

Photograph Number 29: View of adjacent property to the southwest across Capalina Road, facing southwest.

Photograph Number 30: View of adjacent property to the northwest along Capalina Road, facing north.

Photograph Number 31: View of adjacent property to the northwest along West Mission Road, facing west.

Photograph Number 32: View of adjacent property to the northwest along Capalina Road, facing southwest.

APPENDIX B

Aerial Photographs

FLIGHT YEAR:
1939

N
W E
S

Scale: 1" = 500'



AERIAL PHOTOGRAPH

Date:	1939
Photo ID No.	USDA

N↑

The Phase One Group

Site:	Vacant Property Northeast Side of Capalina Road APN 219-115-33-00 San Marcos, California 92069
Project No.:	22-015

FLIGHT YEAR:
1947

N
W E
S

Scale: 1" = 500'



AERIAL PHOTOGRAPH

Date: 1947
Photo ID No. USDA

N↑

The Phase One Group

Site: Vacant Property
Northeast Side of Capalina Road
APN 219-115-33-00
San Marcos, California 92069

Project No.: 22-015

FLIGHT YEAR:
1953

N
W E
S

Scale: 1" = 500'



AERIAL PHOTOGRAPH

Date:	1953
Photo ID No.	USDA

N↑

The Phase One Group

Site:	Vacant Property Northeast Side of Capalina Road APN 219-115-33-00 San Marcos, California 92069
Project No.:	22-015

FLIGHT YEAR:
1963

N
W E
S

Scale: 1" = 500'



AERIAL PHOTOGRAPH

Date:	1963
Photo ID No.	USDA

N↑

The Phase One Group

Site:	Vacant Property Northeast Side of Capalina Road APN 219-115-33-00 San Marcos, California 92069
Project No.:	22-015

FLIGHT YEAR:
1971

N
W E
S

Scale: 1" = 1,000'



AERIAL PHOTOGRAPH

Date: 1971
Photo ID No. USGS

N↑

The Phase One Group

Site: Vacant Property
Northeast Side of Capalina Road
APN 219-115-33-00
San Marcos, California 92069

Project No.: 22-015

FLIGHT YEAR:
1974

N
W E
S

Scale: 1" = 500'



AERIAL PHOTOGRAPH

Date: 1974
Photo ID No. USDA

N↑

The Phase One Group

Site: Vacant Property
Northeast Side of Capalina Road
APN 219-115-33-00
San Marcos, California 92069

Project No.: 22-015

FLIGHT YEAR:
1979

N
W E
S

Scale: 1" = 1,000'

AERIAL PHOTOGRAPH

Date: 1979
Photo ID No. USGS

N↑

The Phase One Group

Site: Vacant Property
Northeast Side of Capalina Road
APN 219-115-33-00
San Marcos, California 92069

Project No.: 22-015

FLIGHT YEAR:
1980

N
W E
S

Scale: 1" = 500'



AERIAL PHOTOGRAPH

Date: 1980
Photo ID No. USGS

N↑

The Phase One Group

Site: Vacant Property
Northeast Side of Capalina Road
APN 219-115-33-00
San Marcos, California 92069

Project No.: 22-015

FLIGHT YEAR:
1985

N
W E
S

Scale: 1" = 1,000'

AERIAL PHOTOGRAPH

Date: 1985
Photo ID No. NHAP

N↑

The Phase One Group

Site: Vacant Property
Northeast Side of Capalina Road
APN 219-115-33-00
San Marcos, California 92069

Project No.: 22-015

FLIGHT YEAR:
1989

N
W E
S

Scale: 1" = 1,000'

AERIAL PHOTOGRAPH

Date: 1989
Photo ID No. NAPP

N↑

The Phase One Group

Site: Vacant Property
Northeast Side of Capalina Road
APN 219-115-33-00
San Marcos, California 92069

Project No.: 22-015

FLIGHT YEAR:
1994

N
W E
S

Scale: 1" = 500'



AERIAL PHOTOGRAPH

Date:	1994
Photo ID No.	DOQ

N↑

The Phase One Group

Site:	Vacant Property Northeast Side of Capalina Road APN 219-115-33-00 San Marcos, California 92069
Project No.:	22-015

FLIGHT YEAR:
1996

N
W E
S

Scale: 1" = 500'

AERIAL PHOTOGRAPH

Date: 1996
Photo ID No. DOQ

N↑

The Phase One Group

Site: Vacant Property
Northeast Side of Capalina Road
APN 219-115-33-00
San Marcos, California 92069

Project No.: 22-015

FLIGHT YEAR:
2001

N
W E
S

Scale: 1" = 500'

AERIAL PHOTOGRAPH

Date:	2001
Photo ID No.	USDA

N↑

The Phase One Group

Site:	Vacant Property Northeast Side of Capalina Road APN 219-115-33-00 San Marcos, California 92069
Project No.:	22-015

FLIGHT YEAR:
2005

N
W E
S

Scale: 1" = 500'



AERIAL PHOTOGRAPH

Date: 2005
Photo ID No. NAIP

N↑

The Phase One Group

Site: Vacant Property
Northeast Side of Capalina Road
APN 219-115-33-00
San Marcos, California 92069

Project No.: 22-015

FLIGHT YEAR:
2009

N
W E
S

Scale: 1" = 500'

AERIAL PHOTOGRAPH

Date:	2009
Photo ID No.	NAIP

N↑

The Phase One Group

Site:	Vacant Property Northeast Side of Capalina Road APN 219-115-33-00 San Marcos, California 92069
Project No.:	22-015

FLIGHT YEAR:
2010

N
W E
S

Scale: 1" = 500'

AERIAL PHOTOGRAPH

Date:	2010
Photo ID No.	NAIP

N↑

The Phase One Group

Site:	Vacant Property Northeast Side of Capalina Road APN 219-115-33-00 San Marcos, California 92069
Project No.:	22-015

FLIGHT YEAR:
2012

N
W E
S

Scale: 1" = 500'

AERIAL PHOTOGRAPH

Date: 2012
Photo ID No. NAIP

N↑

The Phase One Group

Site: Vacant Property
Northeast Side of Capalina Road
APN 219-115-33-00
San Marcos, California 92069

Project No.: 22-015

FLIGHT YEAR:
2014

N
W E
S

Scale: 1" = 500'

AERIAL PHOTOGRAPH

Date:	2014
Photo ID No.	NAIP

N↑

The Phase One Group

Site:	Vacant Property Northeast Side of Capalina Road APN 219-115-33-00 San Marcos, California 92069
Project No.:	22-015

FLIGHT YEAR:
2016

N
W E
S

Scale: 1" = 500'

AERIAL PHOTOGRAPH

Date:	2016
Photo ID No.	NAIP

N↑

The Phase One Group

Site:	Vacant Property Northeast Side of Capalina Road APN 219-115-33-00 San Marcos, California 92069
Project No.:	22-015

FLIGHT YEAR:
2020

N
W E
S

Scale: 1" = 500'

AERIAL PHOTOGRAPH

Date: 2020
Photo ID No. NAIP

N↑

The Phase One Group

Site: Vacant Property
Northeast Side of Capalina Road
APN 219-115-33-00
San Marcos, California 92069

Project No.: 22-015

APPENDIX C

Environmental Database Report

Government Records Report | 2022

Order Number: 69131

Report Generated: 03/21/2022

Project Name: Vacant Property

Project Number: 22-015

Vacant Property
Northeast Side of Capalina Rd.
San Marcos, CA 92069

2 Corporate Drive
Suite 450
Shelton, CT 06484
Toll Free: 866-211-2028
www.envirositecorp.com

Table of Contents

2022

Section	Page
Executive Summary	1
Executive Summary by Distance	2
Executive Summary by Database	6
Property Proximity Map	38
Area Map	39
Map Findings Summary	40
Map Findings	52
Unmappable Summary	835
Environmental Records Searched	836
Geological Landscape Section	873
Geological Landscape Section Soil Map	876
Geological Landscape Section Summary	877
Geological Findings Map	891
Geological Landscape Section Map Findings	892
Geological Landscape Section Map Findings Radon	894
Geological Landscape Records Searched	895

Disclaimer - Copyright and Trademark Notice

All information contained in this report are based on data available from various public, government and other sources and are based upon the best data available from those sources. The information available in this report may be available from other sources and is not exclusive or the exclusive property of Envirosite Corporation.

NO WARRANTY EXPRESSED OR IMPLIED, IS MADE IN CONNECTION WITH THIS REPORT, INCLUDING WITHOUT LIMITATION, MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE. ALL RISK IS ASSUMED BY USER AND Envirosite assumes no liability for faulty or inaccurate information. The Reports may utilize a variety of public and other sources reasonably available to Envirosite. Envirosite cannot, and does not assure, warrant, guarantee or assume any liability for the correctness, comprehensiveness, timeliness or completeness of any of such information, nor is the information in any Report to be construed as legal advice with respect to environmental risks associated with any property. Envirosite shall not be liable to anyone for any claims, causes of action, suits, damages, losses, costs and expenses (including, without limitation, attorneys' fees and costs) arising out of or caused by this report regardless of the acts, errors or omissions, or negligence of Envirosite. Any damages shall be limited to the purchase price of the report.

Purchaser of the report accepts the report "As Is". The report is intended only to provide information only and should not be considered as providing any legal advice, prediction, forecast, or fact as to the environmental risk for any specific property. Reports are proprietary to Envirosite, and contain copyrighted material and trademarks of Envirosite. All other trademarks used herein are the property of their respective owners. All rights of Envirosite as to the Reports are reserved.

Envirosite Corporation has conducted a search of all reasonably ascertainable records in accordance with EPA's AAI (40 CFR Part 312) requirements and the ASTM E-1527-21 Environmental Site Assessments standard.

SUBJECT PROPERTY INFORMATION:

ADDRESS:

Vacant Property
Northeast Side of Capalina Rd.
San Marcos, CA 92069

COORDINATES:

Latitude (North):	33.151670 - 33°9'6"
Longitude (West):	-117.195125 - -117°11'42.5"
Universal Transverse Mercator:	Zone 11N
UTM X (Meters):	481803.45
UTM Y (Meters):	3668118.20

ELEVATION:

Elevation:	587 ft. above sea level

USGS TOPOGRAPHIC MAP ASSOCIATED WITH SUBJECT PROPERTY:

Subject Property Map: 33117-B2 San Marcos, CA
Most Recent Revision: 2018

MAP ID	SITE NAME	ADDRESS	DATABASE(S)	RELATIVE ELEVATION	DIRECTION / DISTANCE
1	TREK BICYCLE SUPERSTORE | MTC CY...	1617 CAPALINA RD STE B | ...	ECHO, FRS, HAZNET - CA, HWG - CA, RCRA_N...	Higher	SW / 0.009 mi., 50 ft.
A2	CAPALINA CLINIC | SAN DIEGO HEALT...	1560 CAPALINA RD	CALEPA SITES - CA, FRS, HAZMAT_SAN DIEGO...	Lower	SSE / 0.012 mi., 64 ft.
B3	THOMAS PAYNE CHIROPRACTIC	317 RANCHO SANTA FE	HAZNET - CA, HWG - CA	Higher	NNW / 0.027 mi., 141 ft.
B4	MINUTEMAN PRESS | DR NOVIKOFF &...	277 S RANCHO SANTA FE RD...	HAZMAT_SAN DIEGO COUNTY - CA	Higher	NNW / 0.036 mi., 191 ft.
A5	ALOHA PRINTING	1551 W MISSION RD STE C	HAZNET - CA, HWG - CA	Lower	ESE / 0.048 mi., 252 ft.
B6	WISE CHIROPRACTIC	245 N. RANCHO SANTA FE RD...	HAZNET - CA, HWG - CA	Higher	NW / 0.050 mi., 262 ft.
A7	ALOHA PRINTING	1551 W MISSION RD	HAZMAT_SAN DIEGO COUNTY - CA	Lower	ESE / 0.050 mi., 266 ft.
B8	RANDALL LEADS DDS | RANDALL J LE...	235 N RANCHO SANTA FE RD...	HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - ...	Higher	NW / 0.056 mi., 297 ft.
C9	THE JUMPING TURTLE BAR & GRILL	1660 CAPALINA RD	HAZNET - CA, HWG - CA	Higher	W / 0.058 mi., 309 ft.
B10	SHERIDAN CHIROPRACTIC	225 N RANCHO SANTA FE RD	FRS, HAZMAT_SAN DIEGO COUNTY - CA	Higher	NW / 0.061 mi., 324 ft.
A11	7-ELEVEN # 21142 | BHANDAL ENTER...	1531 W MISSION RD STE G |...	FRS, HAZMAT_SAN DIEGO COUNTY - CA	Lower	ESE / 0.065 mi., 346 ft.
A12	7-ELEVEN STORE #21142 | BHANDAL...	1531 W MISSION RD STE G	CALEPA SITES - CA	Lower	ESE / 0.065 mi., 346 ft.
C13	JACK IN THE BOX #71	1655 CAPALINA RD	CALEPA SITES - CA	Higher	W / 0.069 mi., 364 ft.
C14	CHIEF AUTO PARTS, #29979	195 S RANCHO SANTE FE RD	HAZNET - CA, HWG - CA	Higher	W / 0.088 mi., 464 ft.
C15	AUTOZONE #5723	195 RANCHO SANTA FE RD | ...	CALEPA SITES - CA, HAZMAT_SAN DIEGO COU...	Higher	W / 0.094 mi., 498 ft.
D16	1X MILLERS OUTPOST	155 RANCHO SANTA FE	HAZNET - CA, HWG - CA	Higher	W / 0.097 mi., 515 ft.
C17	TEXACO XPRESS LUBE #623	218 S SANTA FE RD	HAZNET - CA, HWG - CA	Higher	WNW / 0.101 mi., 535...
D18	WESTERN DENTAL SERVICES INC	169 S RANCHO SANTA FE RD	ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA	Higher	W / 0.102 mi., 537 ft.
C19	JIFFY LUBE #1967 | TEAM CAR CARE ...	218 S RANCHO SANTA FE RD...	AST - CA, CALEPA SITES - CA, CIWQS - CA, EC...	Higher	WNW / 0.102 mi., 539...
D20	99 Cents Only Stores #307	155 S RANCHO SANTA FE RD...	CALEPA SITES - CA, FRS, HAZMAT_SAN DIEGO...	Higher	W / 0.104 mi., 550 ft.
C21	CIRCLE K STORES DC 36 #2969 | 787349	202 S RANCHO SANTA FE RD	CALEPA SITES - CA, CASE LIST_SAN DIEGO CO...	Higher	W / 0.106 mi., 559 ft.
D22	SAN MARCOS VETERINARY CLINIC	145 S RANCHO SANTA FE RD	CALEPA SITES - CA, FRS, HAZMAT_SAN DIEGO...	Higher	W / 0.106 mi., 561 ft.
C23	POBRAN CHIROPRACTIC	174 S RANCHO SANTA FE RD	CALEPA SITES - CA, FRS	Higher	W / 0.108 mi., 573 ft.
C24	SAN MARCOS DENTAL CENTER	162 S RANCHO SANTA FE RD	CALEPA SITES - CA, FRS	Higher	W / 0.108 mi., 573 ft.
C25	RANCHO SANTA FE EXXON | GSE San...	112 N RANCHO SANTA FE RD	FID UST - CA, FRS, HAZMAT_SAN DIEGO COUN...	Higher	W / 0.109 mi., 577 ft.
C26	PALM SPRINGS OIL CO (CHEVRON) | A...	110 S RANCHO SANTA FE RD...	CALEPA SITES - CA, CASE LIST_SAN DIEGO CO...	Higher	W / 0.109 mi., 577 ft.
C27	SIERRRA PRINT AND DESIGN INC | AL...	100 N RANCHO SANTA FE RD...	CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, ...	Higher	W / 0.110 mi., 584 ft.
C28	RANCHO SANTA FE EXXON | COASTAL...	112 N RANCHO SANTA FE RD...	CALEPA SITES - CA, CASE LIST_SAN DIEGO CO...	Higher	W / 0.116 mi., 615 ft.
E29	TAMMY TRUAX	3542 DE LEONE RD	ECHO, FRS, HWG - CA, MANIFEST EPA, RCRA_...	Higher	NW / 0.118 mi., 622 ft.
D30	GLENN YOUNG ARCO #6200 | SAN M...	125 N RANCHO SANTA FE RD	CALEPA SITES - CA, CASE LIST_SAN DIEGO CO...	Higher	WSW / 0.118 mi., 624 ft.
F31	TRI CITY COMPETITION SERVICE	1338 N PACIFIC	HAZNET - CA, HWG - CA	Lower	ESE / 0.118 mi., 625 ft.
D32	ARCO PRODUCTS COMPANY | ARCO #...	125 NORTH RANCHO SANTE FE...	CALEPA SITES - CA, CIWQS 2 - CA, FRS, HAZNE...	Higher	WSW / 0.119 mi., 627 ft.
F33	CREATIVE PAINTING & WALL COVERIN...	185 N PACIFIC ST	CIWQS - CA, HAZNET - CA, HWG - CA	Lower	ESE / 0.120 mi., 632 ft.
F34	LOREAL USA INC | 1X FRITO LAY INC	215 PACIFIC ST UNIT 103 |...	HAZNET - CA, HWG - CA	Lower	ESE / 0.124 mi., 657 ft.
E35	MINDY LANDRY	3556 DE LEONE RD.	HAZNET - CA, HWG - CA	Higher	WNW / 0.124 mi., 657...
D36	CONTINENTAL CLEANERS	109 S RANCHO SANTA FE RD	DRYCLEANERS - CA, HAZNET - CA, HWG - CA	Higher	WSW / 0.125 mi., 659 ft.
D37	FIVE STAR TEXACO SERVICE CNTR | R...	105 RANCHO SANTA FE RD | ...	BRS, CALEPA SITES - CA, CASE LIST_SAN DIEG...	Higher	WSW / 0.126 mi., 668 ft.
G38	HELENE NICKEL	406 CONCHA LN	HAZNET - CA, HWG - CA	Higher	NNE / 0.128 mi., 675 ft.

MAP ID	SITE NAME	ADDRESS	DATABASE(S)	RELATIVE ELEVATION	DIRECTION / DISTANCE
39	1X DUPLICATE PARTS COMPANY | DUP...	168 PACIFIC ST | 168 S PA...	HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - ...	Lower	SE / 0.130 mi., 685 ft.
F40	EAGLE SAFE CORP	320 SO PACIFIC	HAZNET - CA, HWG - CA	Lower	E / 0.131 mi., 690 ft.
D41	BRADLEY PARK OLD LINDA VSTA LF | ...	RANCHO SANTA FE & LINDA V...	CALEPA SITES - CA, CASE LIST_SAN DIEGO CO...	Higher	WSW / 0.134 mi., 706 ft.
F42	GENERAL ELECTRONIC DEVICES | PAC...	320 S PACIFIC ST | 320 PA...	HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - ...	Lower	ESE / 0.135 mi., 715 ft.
F43	RYKO SOLUTIONS	330 S PACIFIC ST, A	HAZMAT_SAN DIEGO COUNTY - CA	Lower	E / 0.137 mi., 725 ft.
C44	GARRET KAYE	3570 DE LONE ROAD	ECHO, FRS, HAZNET - CA, HWG - CA, MANIFES...	Higher	WNW / 0.139 mi., 736...
F45	FREE BUILDING SUPPLY	330 PACIFIC #D	HAZNET - CA, HWG - CA	Lower	E / 0.142 mi., 752 ft.
F46	HydroPlant Hydroseeding, Inc. | MOBI...	356 S PACIFIC ST	CALEPA SITES - CA, FRS	Lower	E / 0.144 mi., 760 ft.
F47	SAN MARCOS AUTO TRUCK REPAIR	382 SOUTH PACIFIC ST.	HAZNET - CA, HWG - CA	Lower	E / 0.152 mi., 801 ft.
E48	CHIP UYU	3532 HOLLENCREST RD	HAZNET - CA, HWG - CA	Higher	NW / 0.157 mi., 830 ft.
F49	PEACOCK CLEANERS | SUNNY FRESH ...	1450 W MISSION RD | 1450 ...	CALEPA SITES - CA, DRYCLEANERS_SAN DIEG...	Lower	ESE / 0.160 mi., 846 ft.
H50	SO CAL COUNTERWORKS | EHIINC	120 NORTH PACIFIC ST#D8	CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, I...	Lower	S / 0.164 mi., 865 ft.
H51	BEST AUTO BODY	120 N PACIFIC ST BLDG B-3	HAZNET - CA, HWG - CA	Lower	S / 0.165 mi., 869 ft.
52	METAL SURGE	16115 RANCHO SANTA FE	HAZNET - CA, HWG - CA	Lower	WSW / 0.171 mi., 906 ft.
G53	GERLAND, KEITH	1634 SADDLEHORN DRIVE	HAZNET - CA, HWG - CA	Higher	NNE / 0.173 mi., 914 ft.
H54	VECCHIO MONDO IMPORTS | TRANSMI...	120 N PACIFIC ST H2 | 120...	CIWQS - CA, ECHO, FRS, HAZNET - CA, HWG - ...	Lower	S / 0.173 mi., 914 ft.
55	SAN MARCOS ANIMAL MEDICAL CENT...	100 N RANCHO SANTA FE RD...	HAZNET - CA, HWG - CA, SCHOOLS PUBLIC	Higher	W / 0.173 mi., 916 ft.
I56	UNICAP MOLD CO	140 N PACIFIC ST STE K	HAZNET - CA, HWG - CA	Lower	SSE / 0.177 mi., 933 ft.
I57	STONE ELEMENT | SCD FABRICATION	143 N PACIFIC ST #K | 143...	CIWQS - CA, HAZMAT_SAN DIEGO COUNTY - CA	Lower	SSE / 0.177 mi., 934 ft.
E58	ERNESTO RAYMUNDO	3520 HOLLENCREST RD	ECHO, FRS, HAZNET - CA, HWG - CA, MANIFES...	Higher	NW / 0.179 mi., 945 ft.
I59	BENCHMARK LANDSCAPE SERVICES I...	145 N PACIFIC ST	CALEPA SITES - CA, DEBRIS EPA SWRCY, ECHO...	Lower	SSE / 0.181 mi., 956 ft.
I60	MEL'S AUTO REPAIR, LLC | K & D MAC...	139 NORTH PACIFIC STE A1 ...	CALEPA SITES - CA, ECHO, FRS, HAZMAT_SAN...	Lower	SSE / 0.182 mi., 960 ft.
I61	J J & S ASBESTOS REMOVAL , INC., DB...	141 N PACIFIC ST STE D | ...	CIWQS - CA, HAZNET - CA, HWG - CA, HWT - CA	Lower	SSE / 0.182 mi., 962 ft.
I62	NEILL WORKS LLC DBA MEL'S AUTO R...	139 N PACIFIC ST | 139 N ...	CALEPA SITES - CA, ECHO, FRS, HWG - CA	Lower	SSE / 0.183 mi., 967 ft.
I63	ARENDSE MOTORSPORTS | BULTER M...	137 N PACIFIC ST | 137 N ...	HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - ...	Lower	SSE / 0.183 mi., 968 ft.
I64	AVISTA TECHNOLOGIES | TRI-CITY CO...	133 N PACIFIC ST	HAZMAT_SAN DIEGO COUNTY - CA	Lower	SSE / 0.184 mi., 974 ft.
I65	ANTUAN KASSABRY EUROPEAN WOO...	137 PACIFIC ST	HAZMAT_SAN DIEGO COUNTY - CA	Lower	SSE / 0.184 mi., 974 ft.
F66	PEACOCK CLEANERS	1450 MISSION RD | 1450 MI...	DRYCLEANERS - CA, ECHO, FRS, HAZNET - CA,...	Lower	ESE / 0.186 mi., 985 ft.
I67	ADVANCED ENGINEERING SOLUTIONS...	135 N PACIFIC ST	HAZMAT_SAN DIEGO COUNTY - CA	Lower	SSE / 0.187 mi., 987 ft.
68	SCOTT SAALFELD	441 SILVER SPUR WAY	HAZNET - CA, HWG - CA	Lower	ENE / 0.188 mi., 995 ft.
I69	NEILL WORKS LLC DBA MEL'S AUTO R...	139 N PACIFIC ST | 139 N ...	ECHO, HAZNET - CA, HWG - CA, RCRA_NONGEN	Lower	SSE / 0.192 mi., 1015 ft.
J70	MELLES GRIOT | MELLES GRIOT SAN ...	435 S PACIFIC ST	ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA...	Lower	E / 0.194 mi., 1025 ft.
J71	SOUTHERN CALIFORNIA FLEET SERVI...	437 S PACIFIC ST | 437 SO...	HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - ...	Lower	E / 0.196 mi., 1034 ft.
K72	MATTESON PRINT INC	1665 S RANCHO SANTA FE SU...	HAZNET - CA, HWG - CA	Higher	WSW / 0.197 mi., 1042...
I73	Sunrise Spa Covers Manufacturing | A...	120 N PACIFIC ST | 120 NO...	CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, ...	Lower	SSE / 0.201 mi., 1061 ft.
I74	MOTOTECH DIVISION OF JADAT INC | ...	120 N PACIFIC AVE #D6 | 1...	HAZNET - CA, HWG - CA	Lower	SSE / 0.201 mi., 1063 ft.
L75	LUIS RODRIGUEZ	3518 CAPALINA ROAD	HAZNET - CA, HWG - CA	Higher	WNW / 0.203 mi., 107...
I76	Old World Wood | PIONEER INDUSTRI...	120 N PACIFIC ST STE D4 |...	CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, ...	Lower	SSE / 0.203 mi., 1075 ft.

MAP ID	SITE NAME	ADDRESS	DATABASE(S)	RELATIVE ELEVATION	DIRECTION / DISTANCE
M77	DEMON FABRICATION, INC	169 BALBOA ST	HAZMAT_SAN DIEGO COUNTY - CA	Lower	SE / 0.206 mi., 1086 ft.
M78	TECHNOGRAPHICS CO	181 BALBOA STREET	ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA...	Lower	SE / 0.208 mi., 1099 ft.
K79	CHEVRON	110 RANCHO SANTE FE RD	CALEPA SITES - CA, ECHO, FRS	Higher	WSW / 0.210 mi., 1110...
E80	JOSE LOPEZ	3514 BARRANCA ROAD	ECHO, FRS, HWG - CA, RCRA_NONGEN	Higher	NW / 0.211 mi., 1113 ft.
M81	PACIFIC YACHT TOWERS | HENRY MAC...	165 BALBOA ST	FRS, HAZMAT_SAN DIEGO COUNTY - CA	Lower	SE / 0.211 mi., 1113 ft.
M82	CONCOURS CLASSICS | XREFURB CENTER	155 BALBOA SUITE D-2 | 15...	ECHO, FRS, HAZNET - CA, HWG - CA, RCRA_SQG	Lower	SE / 0.211 mi., 1115 ft.
M83	HENRY MACHINE INC	165 BALBOA ST UNIT C-11	HAZNET - CA, HWG - CA	Lower	SE / 0.211 mi., 1115 ft.
84	AUTO ELECTRIC | ROMA MARBLE | BA...	3110 S SANTA FE | 3110 SO...	HAZNET - CA, HWG - CA	Lower	NNW / 0.216 mi., 1140...
K85	APRO LLC DBA UNITED PACIFIC 0659 ...	112 S RANCHO SANTA FE RD	CALEPA SITES - CA, ECHO, EPA UST, FID UST -...	Higher	WSW / 0.218 mi., 1150...
86	PEACOCK CLEANERS	1450 MISSION RD W #S	CALEPA SITES - CA, FRS	Lower	ESE / 0.219 mi., 1158 ft.
K87	COUNTY OF SAN DIEGO PUBLIC WORKS	1660 DESCANSO AV	HAZNET - CA, HWG - CA	Lower	SW / 0.220 mi., 1162 ft.
M88	BUTLER MACHINING AND DESIGN IN...	155 BALBOA ST D4 | 155 BA...	CALEPA SITES - CA, CIWQS - CA, DOCKET, ECH...	Lower	SE / 0.220 mi., 1163 ft.
M89	1X BALBOA NAVAL HOSPITAL	BUILDING 121	HAZNET - CA, HWG - CA	Lower	SE / 0.223 mi., 1179 ft.
K90	SAN DIEGO CO DPW DIV II	1600 DESCANSO AVE	HAZNET - CA, HWG - CA	Lower	SW / 0.224 mi., 1184 ft.
I91	BARREL SERVICE CO | BARREL SERVI...	105 S PACIFIC ST | 105 SO...	FRS, HAZNET - CA, HWG - CA, MANIFEST EPA,...	Lower	SSE / 0.229 mi., 1207 ft.
J92	JOHN PERRY	412 PALMAC ST	HAZNET - CA, HWG - CA	Lower	E / 0.229 mi., 1210 ft.
K93	GSE SAN MARCOS 851632 | EXXON #1041	112 S RANCHO SANTA FE | 1...	CALEPA SITES - CA, ECHO, FRS, HAZNET - CA,...	Lower	WSW / 0.230 mi., 1215...
M94	HIGH TECH EDM | 1X MISSION INDUST...	175 BALBOA ST STE A4 | 17...	CALEPA SITES - CA, CIWQS - CA, HAZNET - CA,...	Lower	SE / 0.231 mi., 1220 ft.
M95	ALLSTAR GRAPHICS & SCREEN PRINT...	165 BALBOA ST C-13 | 165 ...	HAZNET - CA, HWG - CA	Lower	SE / 0.234 mi., 1238 ft.
J96	MR. GEISER	441 PALMAC	HAZNET - CA, HWG - CA	Lower	E / 0.235 mi., 1244 ft.
L97	SCHIEBERT, JENNIFER | JENNIFER SCH...	3502 CAPALINA ROAD	ECHO, FRS, HWG - CA, RCRA_NONGEN	Higher	WNW / 0.239 mi., 126...
L98	JAVIER LUCAS | JIMMY HARRIS	3522 BADILLO ROAD	HAZNET - CA, HWG - CA	Higher	WNW / 0.240 mi., 126...
K99	RANCHO SANTE FE GAS | RANCHO SA...	105 RANCHO SANTA FE ROAD	CALEPA SITES - CA, ECHO, FRS	Lower	SW / 0.245 mi., 1294 ft.
100	GIANNA JIMENEZ	3501 HOLLENCREST ROAD'	HAZNET - CA, HWG - CA	Lower	NW / 0.247 mi., 1306 ft.
J101	DEAN TILTON	431 N PACIFIC ST SUITE D	HAZNET - CA, HWG - CA	Lower	E / 0.248 mi., 1309 ft.
M102	PACIFIC METAL PRODUCTS | 1X ROOT...	155 BALBOA ST UNIT D13 | ...	CIWQS - CA, HAZNET - CA, HWG - CA, RFR - CA	Lower	SE / 0.250 mi., 1320 ft.
K103	FORMER CONTINENTAL CLEANERS | R...	109 SOUTH RANCHO SANTA FE...	CALEPA SITES - CA, CASE LIST_SAN DIEGO CO...	Lower	SW / 0.262 mi., 1384 ft.
104	N R	33.179126, -117.200551	FIRE AREAS - CA	N/R	ENE / 0.274 mi., 1447 ft.
105	SAN MARCOS HDQTRS DIVISION II | C...	1579 OSAGE ST	CALEPA SITES - CA, CASE LIST_SAN DIEGO CO...	Lower	SSW / 0.294 mi., 1551...
N106	PIONEER MILLS | 1X PIONEER MILLS	1329 W MISSION RD | 1329 ...	CALEPA SITES - CA, CASE LIST_SAN DIEGO CO...	Lower	ESE / 0.369 mi., 1948 ft.
O107	EDCO WASTE & RECYCLING SERVICE ...	224 S LAS POSAS RD | 224 ...	CASE LIST_SAN DIEGO COUNTY - CA, CHMIRS ...	Lower	SE / 0.392 mi., 2069 ft.
108	AUTOZONE #5723	195 RANCHO SANTA FE RD	ECHO, FRS, SWRCY - CA	Higher	SW / 0.419 mi., 2213 ft.
O109	TORREY CHEMICAL CO | GR ENTERPRI...	217 LAS POSAS RD	CERCLIS NFRAP, ENVIROSTOR - CA, FRS, FTTS...	Lower	SE / 0.419 mi., 2213 ft.
N110	LAS POSAS VENTURE, INC | SAN MAR...	1290 W MISSION RD	BRS, CALEPA SITES - CA, CASE LIST_SAN DIEG...	Lower	ESE / 0.421 mi., 2223 ft.
111	BAJA PACIFIC | TIAGO INC | SINGH GR...	1308 DECANSO AVE | 1308 D...	ECHO, FRS, HAULERS - CA, HAZMAT_SAN DIE...	Lower	SE / 0.426 mi., 2248 ft.
112	GOURMET LIQUOR 100944 | EZ SERV...	2966 S SANTA FE AVE	CALEPA SITES - CA, CASE LIST_SAN DIEGO CO...	Lower	NW / 0.445 mi., 2349 ft.
O113	COCA COLA ENTERPISES	LAS POSAS ARMORLITE | NON...	CALEPA SITES - CA, CASE LIST_SAN DIEGO CO...	Lower	SE / 0.452 mi., 2387 ft.
114	CITY SAN MARCOS BUILDING & SAFET...	120 LAS POSAS RD | 120 N ...	HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - ...	Lower	SSE / 0.486 mi., 2566 ft.

MAP ID	SITE NAME	ADDRESS	DATABASE(S)	RELATIVE ELEVATION	DIRECTION / DISTANCE
115	RANCHO SANTA LUNA SCHOOL | RAN...	SANTA LUNA HILLS	CALEPA SITES - CA, ENVIROSTOR - CA, SCH - CA	Higher	NNW / 0.544 mi., 2875...
116	N R	33.686331, -116.858686	HIGH FIRE - CA	N/R	N / 0.702 mi., 3708 ft.
117	SIGNET ARMORLITE INC | ARMORLITE...	1001 ARMORLITE DR	AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN...	Lower	ESE / 0.746 mi., 3940 ft.
118	NAPP SYSTEMS * | NAPP SYSTEMS, IN...	360 PACIFIC ST S | 360 S....	CALEPA SITES - CA, CASE LIST_SAN DIEGO CO...	Lower	SSW / 0.796 mi., 4201...
119	N R	33.190584, -117.21929	HIGH FIRE - CA	N/R	NW / 0.845 mi., 4461 ft.
120	N R	33.202447, -117.208458	HIGH FIRE - CA	N/R	NNW / 0.963 mi., 5086...
121	HUES METAL FINISHING INC | RMP ME...	977 LINDA VISTA DR	CALEPA SITES - CA, ENVIROSTOR - CA, FRS, H...	Lower	SE / 0.964 mi., 5088 ft.

SUBJECT PROPERTY SEARCH RESULTS:

The subject property was not listed in any of the databases searched by Envirosite Corporation.

SEARCH RESULTS:

FEDERAL, STATE, AND TRIBAL REGISTERED STORAGE TANK LISTS

EPA UST: Facilities listed in the EPA UST Finder database **3 SITES FOUND WITHIN .25 MILE**

EQUAL/HIGHER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
D30	*GLENN YOUNG ARCO #6200 | SAN MARCOS AMPM | RANCHO SANTA FE ARCO*	*125 N RANCHO SANTA FE RD*	*WSW / 0.118 mi., 624 ft.*	*172*
D37	*FIVE STAR TEXACO SERVICE CNTR | RANCHO SANTE FE GAS | RANCHO SANTA FE GAS*	*105 RANCHO SANTA FE RD | 105 S RANCHO SANTA FE RD | 105 RANCHO SANTA FE RD SAP #120462*	*WSW / 0.126 mi., 668 ft.*	*218*
K85	*APRO LLC DBA UNITED PACIFIC 0659 | UNITED PACIFIC 0659 | GSE San Marcos 851632*	*112 S RANCHO SANTA FE RD*	*WSW / 0.218 mi., 1150 ft.*	*532*

AST - CA: Listing of tank facilities that are subject to the California Aboveground Petroleum Storage Act **1 SITE FOUND WITHIN .25 MILE**

EQUAL/HIGHER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
C19	*JIFFY LUBE #1967 | TEAM CAR CARE WEST LLC DBA JIFFY LUBE | CASEY'S CAR WASH*	*218 S RANCHO SANTA FE RD | 218 SOUTH RANCHO SANTA FE ROAD | LOT SOUTH OF 218 S RANCHO SANTA FE RD*	*WNW / 0.102 mi., 539 ft.*	*83*

FID UST - CA: The State Water Resource Control Board's Facility Inventory Database underground storage tank locations listing **5 SITES FOUND WITHIN .25 MILE**

EQUAL/HIGHER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
C25	*RANCHO SANTA FE EXXON | GSE San Marcos 851632 | G&M OIL #171*	*112 N RANCHO SANTA FE RD*	*W / 0.109 mi., 577 ft.*	*119*
C26	*PALM SPRINGS OIL CO (CHEVRON) | APRO LLC DBA UNITED PACIFIC 0658 | 1X CHEVRON USA INC #9-3496*	*110 S RANCHO SANTA FE RD | 110 RANCHO SANTA FE RD*	*W / 0.109 mi., 577 ft.*	*122*
D30	*GLENN YOUNG ARCO #6200 | SAN MARCOS AMPM | RANCHO SANTA FE ARCO*	*125 N RANCHO SANTA FE RD*	*WSW / 0.118 mi., 624 ft.*	*172*
D37	*FIVE STAR TEXACO SERVICE CNTR | RANCHO SANTE FE GAS | RANCHO SANTA FE GAS*	*105 RANCHO SANTA FE RD | 105 S RANCHO SANTA FE RD | 105 RANCHO SANTA FE RD SAP #120462*	*WSW / 0.126 mi., 668 ft.*	*218*
K85	*APRO LLC DBA UNITED PACIFIC 0659 | UNITED PACIFIC 0659 | GSE San Marcos 851632*	*112 S RANCHO SANTA FE RD*	*WSW / 0.218 mi., 1150 ft.*	*532*

FEDERAL, STATE, AND TRIBAL REGISTERED STORAGE TANK LISTS *(cont.)*

HIST AST - CA: Historical listing of tank facilities that are subject to the California Aboveground Petroleum Storage Act **1 SITE FOUND WITHIN .25 MILE**

EQUAL/HIGHER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
C19	*JIFFY LUBE #1967 | TEAM CAR CARE WEST LLC DBA JIFFY LUBE | CASEY'S CAR WASH*	*218 S RANCHO SANTA FE RD | 218 SOUTH RANCHO SANTA FE ROAD | LOT SOUTH OF 218 S RANCHO SANTA FE RD*	*WNW / 0.102 mi., 539 ft.*	*83*

UST - CA: Listing of active underground storage tank facilities **5 SITES FOUND WITHIN .25 MILE**

EQUAL/HIGHER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
C25	*RANCHO SANTA FE EXXON | GSE San Marcos 851632 | G&M OIL #171*	*112 N RANCHO SANTA FE RD*	*W / 0.109 mi., 577 ft.*	*119*
C26	*PALM SPRINGS OIL CO (CHEVRON) | APRO LLC DBA UNITED PACIFIC 0658 | 1X CHEVRON USA INC #9-3496*	*110 S RANCHO SANTA FE RD | 110 RANCHO SANTA FE RD*	*W / 0.109 mi., 577 ft.*	*122*
D30	*GLENN YOUNG ARCO #6200 | SAN MARCOS AMPM | RANCHO SANTA FE ARCO*	*125 N RANCHO SANTA FE RD*	*WSW / 0.118 mi., 624 ft.*	*172*
D37	*FIVE STAR TEXACO SERVICE CNTR | RANCHO SANTE FE GAS | RANCHO SANTA FE GAS*	*105 RANCHO SANTA FE RD | 105 S RANCHO SANTA FE RD | 105 RANCHO SANTA FE RD SAP #120462*	*WSW / 0.126 mi., 668 ft.*	*218*
K85	*APRO LLC DBA UNITED PACIFIC 0659 | UNITED PACIFIC 0659 | GSE San Marcos 851632*	*112 S RANCHO SANTA FE RD*	*WSW / 0.218 mi., 1150 ft.*	*532*

FEDERAL CERCLIS LIST

CERCLIS NFRAP: The CERCLIS sites with No Further Remedial Action Planned from the CERCLIS program database. The Environmental Protection Agency decommissioned the CERCLIS data in 2014. The last update was November 12, 2013. **1 SITE FOUND WITHIN .5 MILE**

LOWER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
O109	*TORREY CHEMICAL CO | GR ENTERPRISE INC*	*217 LAS POSAS RD*	*SE / 0.419 mi., 2213 ft.*	*676*
	- ID: CAD982360430	Status: NFRAP-Site does not qualify for the NPL based on existing information	Date: 1991-03-19	

SEMS_8R_ARCHIVED SITES: The Archived Site Inventory displays site and location information at sites archived from SEMS. An archived site is one at which EPA has determined that assessment has been completed and no further remedial action is planned under the Superfund program at this time. **1 SITE FOUND WITHIN .5 MILE**

LOWER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
O109	*TORREY CHEMICAL CO | GR ENTERPRISE INC*	*217 LAS POSAS RD*	*SE / 0.419 mi., 2213 ft.*	*676*
	- ID: 0902600	Status: NFRAP-Site does not qualify for the NPL based on existing information	Date: N/A	

FEDERAL RCRA CORRACTS FACILITIES LIST

CORRACTS: List of facilities where Resource Conservation and Recovery Act Corrective Action Program used to investigate and remediate hazardous releases **1 SITE FOUND WITHIN 1 MILE**

LOWER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
117	*SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE*	*1001 ARMORLITE DR*	*ESE / 0.746 mi., 3940 ft.*	*744*

- ID: CAD008362634	Status: N/A	Date: N/A
- ID: ENTIRE FACILITY	Status: REMEDY CONSTRUCTION-REMEDY CONSTRUCTED	Date: 2018-06-11
- ID: ENTIRE FACILITY	Status: RELEASE TO GW CONTROLLED DETERMINATION-YES, APPLICABLE AS OF THIS DATE	Date: 2018-06-11
- ID: ENTIRE FACILITY	Status: HUMAN EXPOSURES CONTROLLED DETERMINATION-YES, APPLICABLE AS OF THIS DATE	Date: 1997-12-15
- ID: N/R	Status: RELEASE TO GW CONTROLLED DETERMINATION-FACILITY DOES NOT MEET DEFINITION	Date: 1997-12-15

There are an additional 11 status records, see site details.

FEDERAL, STATE, AND TRIBAL LEAKING STORAGE TANK LISTS

EPA LUST: Releases listed in the EPA UST Finder database **10 SITES FOUND WITHIN .5 MILE**

EQUAL/HIGHER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
C21	*CIRCLE K STORES DC 36 #2969 | 787349*	*202 S RANCHO SANTA FE RD*	*W / 0.106 mi., 559 ft.*	*107*
C26	*PALM SPRINGS OIL CO (CHEVRON) | APRO LLC DBA UNITED PACIFIC 0658 | 1X CHEVRON USA INC #9-3496*	*110 S RANCHO SANTA FE RD | 110 RANCHO SANTA FE RD*	*W / 0.109 mi., 577 ft.*	*122*
C28	*RANCHO SANTA FE EXXON | COASTAL TRANSPORT CO | GSE San Marcos 851632*	*112 N RANCHO SANTA FE RD | 112 RANCHO SANTA FE DR*	*W / 0.116 mi., 615 ft.*	*147*
D30	*GLENN YOUNG ARCO #6200 | SAN MARCOS AMPM | RANCHO SANTA FE ARCO*	*125 N RANCHO SANTA FE RD*	*WSW / 0.118 mi., 624 ft.*	*172*
D37	*FIVE STAR TEXACO SERVICE CNTR | RANCHO SANTE FE GAS | RANCHO SANTA FE GAS*	*105 RANCHO SANTA FE RD | 105 S RANCHO SANTA FE RD | 105 RANCHO SANTA FE RD SAP #120462*	*WSW / 0.126 mi., 668 ft.*	*218*

LOWER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
105	*SAN MARCOS HDQTRS/DIVISION II | COUNTY OF SAN DIEGO DPW DIV II | DPW DIV II HEADQUARTERS*	*1579 OSAGE ST*	*SSW / 0.294 mi., 1551 ft.*	*623*
N106	*PIONEER MILLS | 1X PIONEER MILLS*	*1329 W MISSION RD | 1329 WEST MISSION ROAD*	*ESE / 0.369 mi., 1948 ft.*	*646*

FEDERAL, STATE, AND TRIBAL LEAKING STORAGE TANK LISTS *(cont.)*

EPA LUST: Releases listed in the EPA UST Finder database **10 SITES FOUND WITHIN .5 MILE**

LOWER ELEVATION *(cont.)*

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
O107	*EDCO WASTE & RECYCLING SERVICE | 1X SOLID WASTE SVC | EDCO CONSTRUCTION DEMOLOTION INERT RECYCLING FACILITY*	*224 S LAS POSAS RD | 224 LAS POSAS ROAD*	*SE / 0.392 mi., 2069 ft.*	*652*
N110	*LAS POSAS VENTURE, INC | SAN MARCOS GAS | EXXONMOBIL OIL CORPORATION #12452*	*1290 W MISSION RD*	*ESE / 0.421 mi., 2223 ft.*	*681*
112	*GOURMET LIQUOR 100944 | EZ SERVE 100944 | RESTRUCTURE PETROLEUM MARKETING SRVS*	*2966 S SANTA FE AVE*	*NW / 0.445 mi., 2349 ft.*	*720*

LUST REG 9 - CA: Leaking underground storage tanks in Region 9: San Diego Imperial Riverside counties. **10 SITES FOUND WITHIN .5 MILE**

EQUAL/HIGHER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
C21	*CIRCLE K STORES DC 36 #2969 | 787349*	*202 S RANCHO SANTA FE RD*	*W / 0.106 mi., 559 ft.*	*107*
	- ID: T0607399218	Status: Completed - Case Closed	Date: 2019-06-13	
C26	*PALM SPRINGS OIL CO (CHEVRON) | APRO LLC DBA UNITED PACIFIC 0658 | 1X CHEVRON USA INC #9-3496*	*110 S RANCHO SANTA FE RD | 110 RANCHO SANTA FE RD*	*W / 0.109 mi., 577 ft.*	*122*
	- ID: T0607303122	Status: Completed - Case Closed	Date: 2019-11-07	
C28	*RANCHO SANTA FE EXXON | COASTAL TRANSPORT CO | GSE San Marcos 851632*	*112 N RANCHO SANTA FE RD | 112 RANCHO SANTA FE DR*	*W / 0.116 mi., 615 ft.*	*147*
	- ID: T0607302478 - ID: T0619784179	Status: Completed - Case Closed Status: Open - Verification Monitoring	Date: 2021-12-07 Date: 2021-04-23	
D30	*GLENN YOUNG ARCO #6200 | SAN MARCOS AMPM | RANCHO SANTA FE ARCO*	*125 N RANCHO SANTA FE RD*	*WSW / 0.118 mi., 624 ft.*	*172*
	- ID: T0607300398 - ID: T0607301273	Status: Completed - Case Closed Status: Completed - Case Closed	Date: 1991-06-20 Date: 2018-05-16	
D37	*FIVE STAR TEXACO SERVICE CNTR | RANCHO SANTE FE GAS | RANCHO SANTA FE GAS*	*105 RANCHO SANTA FE RD | 105 S RANCHO SANTA FE RD | 105 RANCHO SANTA FE RD SAP #120462*	*WSW / 0.126 mi., 668 ft.*	*218*
	- ID: T0607302827 - ID: T0607301309	Status: Completed - Case Closed Status: Completed - Case Closed	Date: 1988-08-25 Date: 2019-11-07	

LOWER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
105	*SAN MARCOS HDQTRS/DIVISION II | COUNTY OF SAN DIEGO DPW DIV II | DPW DIV II HEADQUARTERS*	*1579 OSAGE ST*	*SSW / 0.294 mi., 1551 ft.*	*623*
	- ID: T0607302697	Status: Completed - Case Closed	Date: 2011-07-06	

FEDERAL, STATE, AND TRIBAL LEAKING STORAGE TANK LISTS *(cont.)*

LUST REG 9 - CA: Leaking underground storage tanks in Region 9: San Diego Imperial Riverside counties. **10 SITES FOUND WITHIN .5 MILE**

LOWER ELEVATION *(cont.)*

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
	- ID: T0607302282	Status: Completed - Case Closed	Date: 2004-11-23	
N106	*PIONEER MILLS | 1X PIONEER MILLS*	*1329 W MISSION RD | 1329 WEST MISSION ROAD*	*ESE / 0.369 mi., 1948 ft.*	*646*
	- ID: T0607300032	Status: Completed - Case Closed	Date: 1993-02-12	
O107	*EDCO WASTE & RECYCLING SERVICE | 1X SOLID WASTE SVC | EDCO CONSTRUCTION DEMOLOTION INERT RECYCLING FACILITY*	*224 S LAS POSAS RD | 224 LAS POSAS ROAD*	*SE / 0.392 mi., 2069 ft.*	*652*
	- ID: T0607301051	Status: Completed - Case Closed	Date: 1998-02-11	
	- ID: T0607302493	Status: Completed - Case Closed	Date: 2009-01-21	
	- ID: T0607300258	Status: Completed - Case Closed	Date: 1998-02-11	
N110	*LAS POSAS VENTURE, INC | SAN MARCOS GAS | EXXONMOBIL OIL CORPORATION #12452*	*1290 W MISSION RD*	*ESE / 0.421 mi., 2223 ft.*	*681*
	- ID: T0607383730	Status: Completed - Case Closed	Date: 2013-07-15	
112	*GOURMET LIQUOR 100944 | EZ SERVE 100944 | RESTRUCTURE PETROLEUM MARKETING SRVS*	*2966 S SANTA FE AVE*	*NW / 0.445 mi., 2349 ft.*	*720*
	- ID: T0607300358	Status: Completed - Case Closed	Date: 2017-11-01	

SLIC REG 9 - CA: List of Region 9 sites from GeoTracker Site Cleanup Program (formerly known as SLIC) database that is no longer in current agency list. **5 SITES FOUND WITHIN .5 MILE**

EQUAL/HIGHER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
D30	*GLENN YOUNG ARCO #6200 | SAN MARCOS AMPM | RANCHO SANTA FE ARCO*	*125 N RANCHO SANTA FE RD*	*WSW / 0.118 mi., 624 ft.*	*172*
	- ID: T0608153478	Status: Completed - Case Closed	Date: 1991-07-12	
	- ID: T0608148767	Status: Completed - Case Closed	Date: 1991-08-06	
D37	*FIVE STAR TEXACO SERVICE CNTR | RANCHO SANTE FE GAS | RANCHO SANTA FE GAS*	*105 RANCHO SANTA FE RD | 105 S RANCHO SANTA FE RD | 105 RANCHO SANTA FE RD SAP #120462*	*WSW / 0.126 mi., 668 ft.*	*218*
	- ID: T0608107669	Status: Completed - Case Closed	Date: 1993-11-04	

LOWER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
K103	*FORMER CONTINENTAL CLEANERS | RESOURCE ENVIRONMENTAL LLC TEXACO STATION | CONTINENTAL CLEANERS*	*109 SOUTH RANCHO SANTA FE ROAD | 105 S RANCHO SANTA FE RD | 109 S RANCHO SANTA FE RD*	*SW / 0.262 mi., 1384 ft.*	*610*
	- ID: T10000005844	Status: Completed - Case Closed	Date: 2018-06-20	

FEDERAL, STATE, AND TRIBAL LEAKING STORAGE TANK LISTS *(cont.)*

SLIC REG 9 - CA: List of Region 9 sites from GeoTracker Site Cleanup Program (formerly known as SLIC) database that is no longer in current agency list. **5 SITES FOUND WITHIN .5 MILE**

LOWER ELEVATION *(cont.)*

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
O107	*EDCO WASTE & RECYCLING SERVICE | 1X SOLID WASTE SVC | EDCO CONSTRUCTION DEMOLOTION INERT RECYCLING FACILITY*	*224 S LAS POSAS RD | 224 LAS POSAS ROAD*	*SE / 0.392 mi., 2069 ft.*	*652*
	- ID: T0608184522	Status: Completed - Case Closed	Date: 1992-09-16	
O113	*COCA COLA ENTERPISES*	*LAS POSAS/ARMORLITE | NONE LAS POSAS/ARMORLITE*	*SE / 0.452 mi., 2387 ft.*	*732*
	- ID: T0608184290	Status: Completed - Case Closed	Date: 1997-07-31	

FEDERAL RCRA GENERATORS LIST

RCRA_NONGEN: Resource Conservation and Recovery Act listing of licensed non-generators **19 SITES FOUND WITHIN .25 MILE**

EQUAL/HIGHER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
1	*TREK BICYCLE SUPERSTORE | MTC CYCLE SPORTS INC DBA TREK BICYCLE SUPERSTORE*	*1617 CAPALINA RD STE B | 1617 CAPALINA RD UNIT B*	*SW / 0.009 mi., 50 ft.*	*52*
	- ID: CAL000377346	Status: No Violation/Inspections	Date: N/A	
C15	*AUTOZONE #5723*	*195 RANCHO SANTA FE RD | 195 S RANCHO SANTA FE RD*	*W / 0.094 mi., 498 ft.*	*70*
	- ID: CAL000148027	Status: No Violation/Inspections	Date: N/A	
C19	*JIFFY LUBE #1967 | TEAM CAR CARE WEST LLC DBA JIFFY LUBE | CASEY'S CAR WASH*	*218 S RANCHO SANTA FE RD | 218 SOUTH RANCHO SANTA FE ROAD | LOT SOUTH OF 218 S RANCHO SANTA FE RD*	*WNW / 0.102 mi., 539 ft.*	*83*
	- ID: CAL000438389	Status: No Violation/Inspections	Date: N/A	
C26	*PALM SPRINGS OIL CO (CHEVRON) | APRO LLC DBA UNITED PACIFIC 0658 | 1X CHEVRON USA INC #9-3496*	*110 S RANCHO SANTA FE RD | 110 RANCHO SANTA FE RD*	*W / 0.109 mi., 577 ft.*	*122*
	- ID: CAL000453927	Status: No Violation/Inspections	Date: N/A	
E29	*TAMMY TRUAX*	*3542 DE LEONE RD*	*NW / 0.118 mi., 622 ft.*	*162*
	- ID: CAC003130195 - ID: CAC003117122	Status: No Violation/Inspections Status: No Violation/Inspections	Date: N/A Date: N/A	
D30	*GLENN YOUNG ARCO #6200 | SAN MARCOS AMPM | RANCHO SANTA FE ARCO*	*125 N RANCHO SANTA FE RD*	*WSW / 0.118 mi., 624 ft.*	*172*
	- ID: CAL000388657	Status: No Violation/Inspections	Date: N/A	
D37	*FIVE STAR TEXACO SERVICE CNTR | RANCHO SANTE FE GAS | RANCHO SANTA FE GAS*	*105 RANCHO SANTA FE RD | 105 S RANCHO SANTA FE RD | 105 RANCHO SANTA FE RD SAP #120462*	*WSW / 0.126 mi., 668 ft.*	*218*
	- ID: CAL000287229	Status: No Violation/Inspections	Date: N/A	
C44	*GARRET KAYE*	*3570 DE LONE ROAD*	*WNW / 0.139 mi., 736 ft.*	*277*
	- ID: CAC003084864	Status: No Violation/Inspections	Date: N/A	

FEDERAL RCRA GENERATORS LIST *(cont.)*

RCRA_NONGEN: Resource Conservation and Recovery Act listing of licensed non-generators **19 SITES FOUND WITHIN .25 MILE**

EQUAL/HIGHER ELEVATION *(cont.)*

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
E58	*ERNESTO RAYMUNDO*	*3520 HOLLENCREST RD*	*NW / 0.179 mi., 945 ft.*	*349*
	- ID: CAC003107027	Status: No Violation/Inspections	Date: N/A	
E80	*JOSE LOPEZ*	*3514 BARRANCA ROAD*	*NW / 0.211 mi., 1113 ft.*	*518*
	- ID: CAC003150884	Status: No Violation/Inspections	Date: N/A	
K85	*APRO LLC DBA UNITED PACIFIC 0659 | UNITED PACIFIC 0659 | GSE San Marcos 851632*	*112 S RANCHO SANTA FE RD*	*WSW / 0.218 mi., 1150 ft.*	*532*
	- ID: CAL000453913	Status: No Violation/Inspections	Date: N/A	
L97	*SCHIEBERT, JENNIFER | JENNIFER SCHIEBERT*	*3502 CAPALINA ROAD*	*WNW / 0.239 mi., 1264 ft.*	*590*
	- ID: CAC003141889	Status: No Violation/Inspections	Date: N/A	
	- ID: CAC003143545	Status: No Violation/Inspections	Date: N/A	

LOWER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
H54	*VECCHIO MONDO IMPORTS | TRANSMISSION DEPOT | OLD FASHIONED WOODWORKING*	*120 N PACIFIC ST H2 | 120 N PACIFIC ST STE L11 | 120 N PACIFIC ST*	*S / 0.173 mi., 914 ft.*	*308*
	- ID: CAL000301230	Status: No Violation/Inspections	Date: N/A	
	- ID: CAL000338198	Status: No Violation/Inspections	Date: N/A	
I59	*BENCHMARK LANDSCAPE SERVICES INC 1/1/07 | Benchmark Landscape - San Marcos | BENCHMARK LANSCAPE INC*	*145 N PACIFIC ST*	*SSE / 0.181 mi., 956 ft.*	*355*
	- ID: CAL000319551	Status: No Violation/Inspections	Date: N/A	
I60	*MEL'S AUTO REPAIR, LLC | K & D MACHINE | MEL'S AUTO REPAIRNA LLC*	*139 NORTH PACIFIC STE A1 | 139 N PACIFIC ST | 139 N PACIFIC ST, SUITE B*	*SSE / 0.182 mi., 960 ft.*	*366*
	- ID: CAL000063269	Status: No Violation/Inspections	Date: N/A	
F66	*PEACOCK CLEANERS*	*1450 MISSION RD | 1450 MISSION RD STE S | 1450 Mision Road West #S*	*ESE / 0.186 mi., 985 ft.*	*386*
	- ID: CAL000334565	Status: No Violation/Inspections	Date: N/A	
I69	*NEILL WORKS LLC DBA MEL'S AUTO REPAIR | MONY'S AUTO REPAIR | MANNING MOTOR SPORT PERFORMANCE*	*139 N PACIFIC ST | 139 N PACIFIC ST #A | 139 NORTH PACIFIC ST #D*	*SSE / 0.192 mi., 1015 ft.*	*394*
	- ID: CAL000464025	Status: No Violation/Inspections	Date: N/A	
M78	*TECHNOGRAPHICS CO*	*181 BALBOA STREET*	*SE / 0.208 mi., 1099 ft.*	*510*
	- ID: CAL000091925	Status: No Violation/Inspections	Date: N/A	
K93	*GSE SAN MARCOS 851632 | EXXON #1041*	*112 S RANCHO SANTA FE | 112 RANCHO SANTA FE RD | 112 South Rancho Santa Fe*	*WSW / 0.230 mi., 1215 ft.*	*575*
	- ID: CAL000422807	Status: No Violation/Inspections	Date: N/A	

FEDERAL RCRA GENERATORS LIST *(cont.)*

RCRA_SQG: Resource Conservation and Recovery Act listing of licensed small quantity generators **5 SITES FOUND WITHIN .25 MILE**

LOWER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
J70	*MELLES GRIOT | MELLES GRIOT SAN MARCOS CO*	*435 S PACIFIC ST*	*E / 0.194 mi., 1025 ft.*	*401*
	- ID: CAD121712988	Status: Generators - General	Date: Violation 1992-05-12 - Achieved Compliance 1997-05-12	
I73	*Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros*	*120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2*	*SSE / 0.201 mi., 1061 ft.*	*410*
	- ID: CAR000067124 - ID: CAD121704688	Status: No Violation/Inspections Status: No Violation/Inspections	Date: N/A Date: N/A	
I76	*Old World Wood | PIONEER INDUSTRIAL PARK | BEST AUTO BODY AND FRAME*	*120 N PACIFIC ST STE D4 | 120 N PACIFIC STE G3 | 120 N PACIFIC*	*SSE / 0.203 mi., 1075 ft.*	*481*
	- ID: CAD982431512 - ID: CAP000048090	Status: No Violation/Inspections Status: No Violation/Inspections	Date: N/A Date: N/A	
M82	*CONCOURS CLASSICS | XREFURB CENTER*	*155 BALBOA SUITE D-2 | 155 BALBOA DR | 155 BALBOA DR STE D13*	*SE / 0.211 mi., 1115 ft.*	*523*
	- ID: CAD980891386	Status: No Violation/Inspections	Date: N/A	
I91	*BARREL SERVICE CO | BARREL SERVICE COMPANY - 203419*	*105 S PACIFIC ST | 105 SOUTH PACIFIC ST*	*SSE / 0.229 mi., 1207 ft.*	*567*
	- ID: CAD981453467	Status: No Violation/Inspections	Date: N/A	

STATE- AND TRIBAL - EQUIVALENT CERCLIS

ENVIROSTOR - CA: Department of Toxic Substances Controls **5 SITES FOUND WITHIN 1 MILE**

EQUAL/HIGHER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
115	*RANCHO SANTA LUNA SCHOOL | RANCHO SANTA LUNA SC*	*SANTA LUNA HILLS*	*NNW / 0.544 mi., 2875 ft.*	*741*
	- ID: 37010030	Status: No Action Required	Date: Cleanup Date 2002-05-25	

LOWER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
O109	*TORREY CHEMICAL CO | GR ENTERPRISE INC*	*217 LAS POSAS RD*	*SE / 0.419 mi., 2213 ft.*	*676*
	- ID: 37510137	Status: Refer: Other Agency	Date: Cleanup Date 1995-08-21	
117	*SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE*	*1001 ARMORLITE DR*	*ESE / 0.746 mi., 3940 ft.*	*744*
	- ID: 80001570	Status: Refer: RWQCB	Date: Cleanup Date 2012-08-29	

STATE- AND TRIBAL - EQUIVALENT CERCLIS *(cont.)*

ENVIROSTOR - CA: Department of Toxic Substances Controls **5 SITES FOUND WITHIN 1 MILE**

LOWER ELEVATION *(cont.)*

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
118	*NAPP SYSTEMS * | NAPP SYSTEMS, INC. | MACDERMID PRINTING SOLUTIONS*	*360 PACIFIC ST S | 360 S. PACIFIC STREET | 360 SOUTH PACIFIC STREET*	*SSW / 0.796 mi., 4201 ft.*	*822*
	- ID: 71002510	Status: Inactive - Needs Evaluation	Date: Cleanup Date N/R	
121	*HUES METAL FINISHING INC | RMP METAL FINISHING*	*977 LINDA VISTA DR*	*SE / 0.964 mi., 5088 ft.*	*830*
	- ID: 71002362	Status: Inactive - Needs Evaluation	Date: Cleanup Date N/R	

STATE AND TRIBAL LANDFILL AND/OR SOLID WASTE DISPOSAL SITE LISTS

SWF/LF - CA: Solid Waste Information System's facility listing of solid waste facilities and landfills **1 SITE FOUND WITHIN .5 MILE**

LOWER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
I59	*BENCHMARK LANDSCAPE SERVICES INC 1/1/07 | Benchmark Landscape - San Marcos | BENCHMARK LANSCAPE INC*	*145 N PACIFIC ST*	*SSE / 0.181 mi., 956 ft.*	*355*
	- ID: SWIS Number 37-AA-0986	Status: Notification	Date: Permit Date N/R	
	- ID: N/R	Status: Operational Status Active	Date: N/R	

STATE RCRA GENERATORS LIST

HWG - CA: Hazardous waste generator listing **73 SITES FOUND WITHIN .25 MILE**

EQUAL/HIGHER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
1	*TREK BICYCLE SUPERSTORE | MTC CYCLE SPORTS INC DBA TREK BICYCLE SUPERSTORE*	*1617 CAPALINA RD STE B | 1617 CAPALINA RD UNIT B*	*SW / 0.009 mi., 50 ft.*	*52*
B3	*THOMAS PAYNE CHIROPRACTIC*	*317 RANCHO SANTA FE*	*NNW / 0.027 mi., 141 ft.*	*59*
B6	*WISE CHIROPRACTIC*	*245 N. RANCHO SANTA FE RD 204*	*NW / 0.050 mi., 262 ft.*	*62*
B8	*RANDALL LEADS DDS | RANDALL J LEADS DDS | RONALD PARK, MD*	*235 N RANCHO SANTA FE RD | 235 N RANCHO SANTA FE RD STE 206*	*NW / 0.056 mi., 297 ft.*	*63*
C9	*THE JUMPING TURTLE BAR & GRILL*	*1660 CAPALINA RD*	*W / 0.058 mi., 309 ft.*	*64*
C14	*CHIEF AUTO PARTS, #29979*	*195 S RANCHO SANTE FE RD*	*W / 0.088 mi., 464 ft.*	*69*
C15	*AUTOZONE #5723*	*195 RANCHO SANTA FE RD | 195 S RANCHO SANTA FE RD*	*W / 0.094 mi., 498 ft.*	*70*
D16	*1X MILLERS OUTPOST*	*155 RANCHO SANTA FE*	*W / 0.097 mi., 515 ft.*	*77*
C17	*TEXACO XPRESS LUBE #623*	*218 S SANTA FE RD*	*WNW / 0.101 mi., 535 ft.*	*78*
C19	*JIFFY LUBE #1967 | TEAM CAR CARE WEST LLC DBA JIFFY LUBE | CASEY'S CAR WASH*	*218 S RANCHO SANTA FE RD | 218 SOUTH RANCHO SANTA FE ROAD | LOT SOUTH OF 218 S RANCHO SANTA FE RD*	*WNW / 0.102 mi., 539 ft.*	*83*
C26	*PALM SPRINGS OIL CO (CHEVRON) | APRO LLC DBA UNITED PACIFIC 0658 | 1X CHEVRON USA INC #9-3496*	*110 S RANCHO SANTA FE RD | 110 RANCHO SANTA FE RD*	*W / 0.109 mi., 577 ft.*	*122*

STATE RCRA GENERATORS LIST *(cont.)*

HWG - CA: Hazardous waste generator listing **73 SITES FOUND WITHIN .25 MILE**

EQUAL/HIGHER ELEVATION *(cont.)*

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
C28	RANCHO SANTA FE EXXON | COASTAL TRANSPORT CO | GSE San Marcos 851632	112 N RANCHO SANTA FE RD | 112 RANCHO SANTA FE DR	W / 0.116 mi., 615 ft.	147
E29	TAMMY TRUAX	3542 DE LEONE RD	NW / 0.118 mi., 622 ft.	162
D30	GLENN YOUNG ARCO #6200 | SAN MARCOS AMPM | RANCHO SANTA FE ARCO	125 N RANCHO SANTA FE RD	WSW / 0.118 mi., 624 ft.	172
D32	ARCO PRODUCTS COMPANY | ARCO #6200 | ARCO Facility No. 6200 125 North Rancho Santa Fe Road	125 NORTH RANCHO SANTE FE | 125 RANCHO SANTA FE RD N | 125 North Rancho Santa Fe Road	WSW / 0.119 mi., 627 ft.	208
E35	MINDY LANDRY	3556 DE LEONE RD.	WNW / 0.124 mi., 657 ft.	215
D36	CONTINENTAL CLEANERS	109 S RANCHO SANTA FE RD	WSW / 0.125 mi., 659 ft.	216
D37	FIVE STAR TEXACO SERVICE CNTR | RANCHO SANTE FE GAS | RANCHO SANTA FE GAS	105 RANCHO SANTA FE RD | 105 S RANCHO SANTA FE RD | 105 RANCHO SANTA FE RD SAP #120462	WSW / 0.126 mi., 668 ft.	218
G38	HELENE NICKEL	406 CONCHA LN	NNE / 0.128 mi., 675 ft.	247
C44	GARRET KAYE	3570 DE LONE ROAD	WNW / 0.139 mi., 736 ft.	277
E48	CHIP UYU	3532 HOLLENCREST RD	NW / 0.157 mi., 830 ft.	287
G53	GERLAND, KEITH	1634 SADDLEHORN DRIVE	NNE / 0.173 mi., 914 ft.	306
55	SAN MARCOS ANIMAL MEDICAL CENTER | SIENNA PRINT & DESIGN INC DBA ALPHAGRAPHICS 554 | THE NORTH COUNTY EMERGENCY ANIMAL CLINIC	100 N RANCHO SANTA FE RD | 100 N RANCHO SANTA FE RD STE 127 | 100 N RANCHO SANTA FE RD, 133	W / 0.173 mi., 916 ft.	344
E58	ERNESTO RAYMUNDO	3520 HOLLENCREST RD	NW / 0.179 mi., 945 ft.	349
K72	MATTESON PRINT INC	1665 S RANCHO SANTA FE SUITE-	WSW / 0.197 mi., 1042 ft.	409
L75	LUIS RODRIGUEZ	3518 CAPALINA ROAD	WNW / 0.203 mi., 1073 ft.	479
E80	JOSE LOPEZ	3514 BARRANCA ROAD	NW / 0.211 mi., 1113 ft.	518
K85	APRO LLC DBA UNITED PACIFIC 0659 | UNITED PACIFIC 0659 | GSE San Marcos 851632	112 S RANCHO SANTA FE RD	WSW / 0.218 mi., 1150 ft.	532
L97	SCHIEBERT, JENNIFER | JENNIFER SCHIEBERT	3502 CAPALINA ROAD	WNW / 0.239 mi., 1264 ft.	590
L98	JAVIER LUCAS | JIMMY HARRIS	3522 BADILLO ROAD	WNW / 0.240 mi., 1268 ft.	598

LOWER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
A5	ALOHA PRINTING	1551 W MISSION RD STE C	ESE / 0.048 mi., 252 ft.	61
F31	TRI CITY COMPETITION SERVICE	1338 N PACIFIC	ESE / 0.118 mi., 625 ft.	207
F33	CREATIVE PAINTING & WALL COVERING | PFT STORAGE INC | STOREM SELF STORAGE	185 N PACIFIC ST	ESE / 0.120 mi., 632 ft.	212
F34	LOREAL USA INC | 1X FRITO LAY INC	215 PACIFIC ST UNIT 103 | 235 SOUTH PACIFIC	ESE / 0.124 mi., 657 ft.	214
39	1X DUPLICATE PARTS COMPANY | DUPLICATE PARTS COMPANY	168 PACIFIC ST | 168 S PACIFIC ST	SE / 0.130 mi., 685 ft.	249
F40	EAGLE SAFE CORP	320 SO PACIFIC	E / 0.131 mi., 690 ft.	251
F42	GENERAL ELECTRONIC DEVICES | PACIFIC AUTO RESTORATION | AM GRAPHICS AND PRINTING	320 S PACIFIC ST | 320 PACIFIC ST	ESE / 0.135 mi., 715 ft.	273
F45	FREE BUILDING SUPPLY	330 PACIFIC #D	E / 0.142 mi., 752 ft.	283

STATE RCRA GENERATORS LIST *(cont.)*

HWG - CA: Hazardous waste generator listing **73 SITES FOUND WITHIN .25 MILE**

LOWER ELEVATION *(cont.)*

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
F47	SAN MARCOS AUTO TRUCK REPAIR	382 SOUTH PACIFIC ST.	E / 0.152 mi., 801 ft.	286
F49	PEACOCK CLEANERS | SUNNY FRESH & PEACOCK CLEANERS | HAPPY CHANGS	1450 W MISSION RD | 1450 W MISSION RD STE S | 1450 W Mission Rd #S	ESE / 0.160 mi., 846 ft.	288
H51	BEST AUTO BODY	120 N PACIFIC ST BLDG B-3	S / 0.165 mi., 869 ft.	305
52	METAL SURGE	16115 RANCHO SANTA FE	WSW / 0.171 mi., 906 ft.	305
H54	VECCHIO MONDO IMPORTS | TRANSMISSION DEPOT | OLD FASHIONED WOODWORKING	120 N PACIFIC ST H2 | 120 N PACIFIC ST STE L11 | 120 N PACIFIC ST	S / 0.173 mi., 914 ft.	308
I56	UNICAP MOLD CO	140 N PACIFIC ST STE K	SSE / 0.177 mi., 933 ft.	347
I59	BENCHMARK LANDSCAPE SERVICES INC 1/1/07 | Benchmark Landscape - San Marcos | BENCHMARK LANSCAPE INC	145 N PACIFIC ST	SSE / 0.181 mi., 956 ft.	355
I60	MEL'S AUTO REPAIR, LLC | K & D MACHINE | MEL'S AUTO REPAIRNA LLC	139 NORTH PACIFIC STE A1 | 139 N PACIFIC ST | 139 N PACIFIC ST, SUITE B	SSE / 0.182 mi., 960 ft.	366
I61	J J & S ASBESTOS REMOVAL , INC., DBA: J J & S CONSTRUCTION | NORTH COUNTY HYDRAULICS | JJ&S CONSTRUCTION	141 N PACIFIC ST STE D | 141 NORTH PACIFIC STREET, SUITE D | 143 N PACIFIC ST # K	SSE / 0.182 mi., 962 ft.	374
I62	NEILL WORKS LLC DBA MEL'S AUTO REPAIR | KB MOTORSPORTS INC | MEL'S AUTO REPAIR	139 N PACIFIC ST | 139 N PACIFIC ST STE A | 139 N PACIFIC ST STE A-1	SSE / 0.183 mi., 967 ft.	377
I63	ARENDSE MOTORSPORTS | BULTER MACHINING & DESIGN INC | REBEL FABRICATION	137 N PACIFIC ST | 137 N PACIFIC ST STE E	SSE / 0.183 mi., 968 ft.	383
F66	PEACOCK CLEANERS	1450 MISSION RD | 1450 MISSION RD STE S | 1450 Mision Road West #S	ESE / 0.186 mi., 985 ft.	386
68	SCOTT SAALFELD	441 SILVER SPUR WAY	ENE / 0.188 mi., 995 ft.	392
I69	NEILL WORKS LLC DBA MEL'S AUTO REPAIR | MONY'S AUTO REPAIR | MANNING MOTOR SPORT PERFORMANCE	139 N PACIFIC ST | 139 N PACIFIC ST #A | 139 NORTH PACIFIC ST #D	SSE / 0.192 mi., 1015 ft.	394
J70	MELLES GRIOT | MELLES GRIOT SAN MARCOS CO	435 S PACIFIC ST	E / 0.194 mi., 1025 ft.	401
J71	SOUTHERN CALIFORNIA FLEET SERVICES | SOUTHERN CALIFORNIA FLEET SER	437 S PACIFIC ST | 437 SOUTH PACIFIC ST	E / 0.196 mi., 1034 ft.	407
I73	Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros	120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2	SSE / 0.201 mi., 1061 ft.	410
I74	MOTOTECH DIVISION OF JADAT INC | PACIFIC BODY & PAINT | EXTREME RACING MOTORSPORTS INC	120 N PACIFIC AVE #D6 | 120 N PACIFIC ST BLDG E3 | 120 N PACIFIC ST STE E-2	SSE / 0.201 mi., 1063 ft.	473
I76	Old World Wood | PIONEER INDUSTRIAL PARK | BEST AUTO BODY AND FRAME	120 N PACIFIC ST STE D4 | 120 N PACIFIC STE G3 | 120 N PACIFIC	SSE / 0.203 mi., 1075 ft.	481
M78	TECHNOGRAPHICS CO	181 BALBOA STREET	SE / 0.208 mi., 1099 ft.	510
M82	CONCOURS CLASSICS | XREFURB CENTER	155 BALBOA SUITE D-2 | 155 BALBOA DR | 155 BALBOA DR STE D13	SE / 0.211 mi., 1115 ft.	523

STATE RCRA GENERATORS LIST *(cont.)*

HWG - CA: Hazardous waste generator listing **73 SITES FOUND WITHIN .25 MILE**

LOWER ELEVATION *(cont.)*

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
M83	HENRY MACHINE INC	165 BALBOA ST UNIT C-11	SE / 0.211 mi., 1115 ft.	529
84	AUTO ELECTRIC | ROMA MARBLE | BATZS CAR CARE CENTER	3110 S SANTA FE | 3110 SOUTH SANTA FE	NNW / 0.216 mi., 1140 ft.	529
K87	COUNTY OF SAN DIEGO PUBLIC WORKS	1660 DESCANSO AV	SW / 0.220 mi., 1162 ft.	547
M89	1X BALBOA NAVAL HOSPITAL	BUILDING 121	SE / 0.223 mi., 1179 ft.	564
K90	SAN DIEGO CO DPW DIV II	1600 DESCANSO AVE	SW / 0.224 mi., 1184 ft.	565
I91	BARREL SERVICE CO | BARREL SERVICE COMPANY - 203419	105 S PACIFIC ST | 105 SOUTH PACIFIC ST	SSE / 0.229 mi., 1207 ft.	567
J92	JOHN PERRY	412 PALMAC ST	E / 0.229 mi., 1210 ft.	574
K93	GSE SAN MARCOS 851632 | EXXON #1041	112 S RANCHO SANTA FE | 112 RANCHO SANTA FE RD | 112 South Rancho Santa Fe	WSW / 0.230 mi., 1215 ft.	575
M94	HIGH TECH EDM | 1X MISSION INDUSTRIAL SQUARE	175 BALBOA ST STE A4 | 175 N BALBOA ST	SE / 0.231 mi., 1220 ft.	583
M95	ALLSTAR GRAPHICS & SCREEN PRINTING | JRL STREET ROD | C & G EARLY FORD PARTS	165 BALBOA ST C-13 | 165 BALBOA ST C-5 | 165 BALBOA ST C11	SE / 0.234 mi., 1238 ft.	585
J96	MR. GEISER	441 PALMAC	E / 0.235 mi., 1244 ft.	589
100	GIANNA JIMENEZ	3501 HOLLENCREST ROAD'	NW / 0.247 mi., 1306 ft.	606
J101	DEAN TILTON	431 N PACIFIC ST SUITE D	E / 0.248 mi., 1309 ft.	607
M102	PACIFIC METAL PRODUCTS | 1X ROOT TRUCKING CO INC	155 BALBOA ST UNIT D13 | 155 N BALBOA ST	SE / 0.250 mi., 1320 ft.	608

LOCAL LISTS OF HAZARDOUS WASTE / CONTAMINATED SITES

CASE LIST_SAN DIEGO COUNTY - CA: San Diego county listing of hazardous chemical releases **13 SITES FOUND WITHIN .5 MILE**

EQUAL/HIGHER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
C21	CIRCLE K STORES DC 36 #2969 | 787349	202 S RANCHO SANTA FE RD	W / 0.106 mi., 559 ft.	107
	- ID: T0607399218	Status: Completed - Case Closed	Date: 2019-06-13	
C26	PALM SPRINGS OIL CO (CHEVRON) | APRO LLC DBA UNITED PACIFIC 0658 | 1X CHEVRON USA INC #9-3496	110 S RANCHO SANTA FE RD | 110 RANCHO SANTA FE RD	W / 0.109 mi., 577 ft.	122
	- ID: T0607303122	Status: Completed - Case Closed	Date: 2019-11-07	
C28	RANCHO SANTA FE EXXON | COASTAL TRANSPORT CO | GSE San Marcos 851632	112 N RANCHO SANTA FE RD | 112 RANCHO SANTA FE DR	W / 0.116 mi., 615 ft.	147
	- ID: T0607302478 - ID: T0619784179	Status: Completed - Case Closed Status: Open - Verification Monitoring	Date: 2021-12-07 Date: 2021-04-23	
D30	GLENN YOUNG ARCO #6200 | SAN MARCOS AMPM | RANCHO SANTA FE ARCO	125 N RANCHO SANTA FE RD	WSW / 0.118 mi., 624 ft.	172
	- ID: T0608153478 - ID: T0607300398 - ID: T0607301273 - ID: T0608148767	Status: Completed - Case Closed Status: Completed - Case Closed Status: Completed - Case Closed Status: Completed - Case Closed	Date: 1991-07-12 Date: 1991-06-20 Date: 2018-05-16 Date: 1991-08-06	

LOCAL LISTS OF HAZARDOUS WASTE / CONTAMINATED SITES *(cont.)*

CASE LIST_SAN DIEGO COUNTY - CA: San Diego county listing of hazardous chemical releases **13 SITES FOUND WITHIN .5 MILE**

EQUAL/HIGHER ELEVATION *(cont.)*

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
D37	*FIVE STAR TEXACO SERVICE CNTR | RANCHO SANTE FE GAS | RANCHO SANTA FE GAS*	*105 RANCHO SANTA FE RD | 105 S RANCHO SANTA FE RD | 105 RANCHO SANTA FE RD SAP #120462*	*WSW / 0.126 mi., 668 ft.*	*218*
	- ID: T0607302827	Status: Completed - Case Closed	Date: 1988-08-25	
	- ID: T0607301309	Status: Completed - Case Closed	Date: 2019-11-07	
	- ID: T0608107669	Status: Completed - Case Closed	Date: 1993-11-04	
D41	*BRADLEY PARK OLD LINDA VSTA LF | SD CO OF PUB WKS SAN MARCOS I LANDFILL | BRADLEY PARK - OLD LINDA VSTA LANDFILL (SAN MARCOS I LANDFILL)*	*RANCHO SANTA FE & LINDA VISTA | RANCHO SANTE FE RD/LINDA VISTA | RANCHO SANTA FE/LINDA VISTA RD*	*WSW / 0.134 mi., 706 ft.*	*253*
	- ID: L10006943141	Status: Open - Closed/with Monitoring	Date: 2015-06-30	

LOWER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
K103	*FORMER CONTINENTAL CLEANERS | RESOURCE ENVIRONMENTAL LLC TEXACO STATION | CONTINENTAL CLEANERS*	*109 SOUTH RANCHO SANTA FE ROAD | 105 S RANCHO SANTA FE RD | 109 S RANCHO SANTA FE RD*	*SW / 0.262 mi., 1384 ft.*	*610*
	- ID: T10000005844	Status: Completed - Case Closed	Date: 2018-06-20	
105	*SAN MARCOS HDQTRS/DIVISION II | COUNTY OF SAN DIEGO DPW DIV II | DPW DIV II HEADQUARTERS*	*1579 OSAGE ST*	*SSW / 0.294 mi., 1551 ft.*	*623*
	- ID: T0607302697	Status: Completed - Case Closed	Date: 2011-07-06	
	- ID: T0607302282	Status: Completed - Case Closed	Date: 2004-11-23	
N106	*PIONEER MILLS | 1X PIONEER MILLS*	*1329 W MISSION RD | 1329 WEST MISSION ROAD*	*ESE / 0.369 mi., 1948 ft.*	*646*
	- ID: T0607300032	Status: Completed - Case Closed	Date: 1993-02-12	
O107	*EDCO WASTE & RECYCLING SERVICE | 1X SOLID WASTE SVC | EDCO CONSTRUCTION DEMOLOTION INERT RECYCLING FACILITY*	*224 S LAS POSAS RD | 224 LAS POSAS ROAD*	*SE / 0.392 mi., 2069 ft.*	*652*
	- ID: T0608184522	Status: Completed - Case Closed	Date: 1992-09-16	
	- ID: T0607301051	Status: Completed - Case Closed	Date: 1998-02-11	
	- ID: T0607302493	Status: Completed - Case Closed	Date: 2009-01-21	
	- ID: T0607300258	Status: Completed - Case Closed	Date: 1998-02-11	
N110	*LAS POSAS VENTURE, INC | SAN MARCOS GAS | EXXONMOBIL OIL CORPORATION #12452*	*1290 W MISSION RD*	*ESE / 0.421 mi., 2223 ft.*	*681*
	- ID: T0607383730	Status: Completed - Case Closed	Date: 2013-07-15	

LOCAL LISTS OF HAZARDOUS WASTE / CONTAMINATED SITES *(cont.)*

CASE LIST_SAN DIEGO COUNTY - CA: San Diego county listing of hazardous chemical releases **13 SITES FOUND WITHIN .5 MILE**

LOWER ELEVATION *(cont.)*

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
112	*GOURMET LIQUOR 100944 | EZ SERVE 100944 | RESTRUCTURE PETROLEUM MARKETING SRVS*	*2966 S SANTA FE AVE*	*NW / 0.445 mi., 2349 ft.*	*720*
	- ID: T0607300358	Status: Completed - Case Closed	Date: 2017-11-01	
O113	*COCA COLA ENTERPISES*	*LAS POSAS/ARMORLITE | NONE LAS POSAS/ARMORLITE*	*SE / 0.452 mi., 2387 ft.*	*732*
	- ID: T0608184290	Status: Completed - Case Closed	Date: 1997-07-31	

LOCAL LISTS OF LANDFILL / SOLID WASTE DISPOSAL SITES

HAULERS - CA: Waste Tire Manifest Program Hauler Registration listing **1 SITE FOUND WITHIN .5 MILE**

LOWER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
111	*BAJA PACIFIC | TIAGO INC | SINGH GROUP INC DBA BAJA PACIFIC*	*1308 DECANSO AVE | 1308 DESCANSO AVE*	*SE / 0.426 mi., 2248 ft.*	*713*

LF_SAN DIEGO COUNTY - CA: San Diego county landfill listing **2 SITES FOUND WITHIN .5 MILE**

LOWER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
I59	*BENCHMARK LANDSCAPE SERVICES INC 1/1/07 | Benchmark Landscape - San Marcos | BENCHMARK LANSCAPE INC*	*145 N PACIFIC ST*	*SSE / 0.181 mi., 956 ft.*	*355*
O107	*EDCO WASTE & RECYCLING SERVICE | 1X SOLID WASTE SVC | EDCO CONSTRUCTION DEMOLOTION INERT RECYCLING FACILITY*	*224 S LAS POSAS RD | 224 LAS POSAS ROAD*	*SE / 0.392 mi., 2069 ft.*	*652*

SWRCY - CA: Listing of facilities which perform recycled material processing activities **2 SITES FOUND WITHIN .5 MILE**

EQUAL/HIGHER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
C19	*JIFFY LUBE #1967 | TEAM CAR CARE WEST LLC DBA JIFFY LUBE | CASEY'S CAR WASH*	*218 S RANCHO SANTA FE RD | 218 SOUTH RANCHO SANTA FE ROAD | LOT SOUTH OF 218 S RANCHO SANTA FE RD*	*WNW / 0.102 mi., 539 ft.*	*83*
108	*AUTOZONE #5723*	*195 RANCHO SANTA FE RD*	*SW / 0.419 mi., 2213 ft.*	*673*

OTHER ASCERTAINABLE RECORDS

DEBRIS EPA SWRCY: EPA list of facilities for the safe recovery, recycling, and disposal of disaster debris. **2 SITES FOUND WITHIN .5 MILE**

LOWER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
I59	*BENCHMARK LANDSCAPE SERVICES INC 1/1/07 | Benchmark Landscape - San Marcos | BENCHMARK LANSCAPE INC*	*145 N PACIFIC ST*	*SSE / 0.181 mi., 956 ft.*	*355*

OTHER ASCERTAINABLE RECORDS *(cont.)*

DEBRIS EPA SWRCY: EPA list of facilities for the safe recovery, recycling, and disposal of disaster debris. **2 SITES FOUND WITHIN .5 MILE**

LOWER ELEVATION *(cont.)*

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
O107	EDCO WASTE & RECYCLING SERVICE | 1X SOLID WASTE SVC | EDCO CONSTRUCTION DEMOLOTION INERT RECYCLING FACILITY	224 S LAS POSAS RD | 224 LAS POSAS ROAD	SE / 0.392 mi., 2069 ft.	652

MANIFEST EPA: EPA Hazardous Waste Electronic Manifest System (e-Manifest) **13 SITES FOUND WITHIN .25 MILE**

EQUAL/HIGHER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
C15	AUTOZONE #5723	195 RANCHO SANTA FE RD | 195 S RANCHO SANTA FE RD	W / 0.094 mi., 498 ft.	70
C19	JIFFY LUBE #1967 | TEAM CAR CARE WEST LLC DBA JIFFY LUBE | CASEY'S CAR WASH	218 S RANCHO SANTA FE RD | 218 SOUTH RANCHO SANTA FE ROAD | LOT SOUTH OF 218 S RANCHO SANTA FE RD	WNW / 0.102 mi., 539 ft.	83
C26	PALM SPRINGS OIL CO (CHEVRON) | APRO LLC DBA UNITED PACIFIC 0658 | 1X CHEVRON USA INC #9-3496	110 S RANCHO SANTA FE RD | 110 RANCHO SANTA FE RD	W / 0.109 mi., 577 ft.	122
E29	TAMMY TRUAX	3542 DE LEONE RD	NW / 0.118 mi., 622 ft.	162
D30	GLENN YOUNG ARCO #6200 | SAN MARCOS AMPM | RANCHO SANTA FE ARCO	125 N RANCHO SANTA FE RD	WSW / 0.118 mi., 624 ft.	172
D37	FIVE STAR TEXACO SERVICE CNTR | RANCHO SANTE FE GAS | RANCHO SANTA FE GAS	105 RANCHO SANTA FE RD | 105 S RANCHO SANTA FE RD | 105 RANCHO SANTA FE RD SAP #120462	WSW / 0.126 mi., 668 ft.	218
C44	GARRET KAYE	3570 DE LONE ROAD	WNW / 0.139 mi., 736 ft.	277
E58	ERNESTO RAYMUNDO	3520 HOLLENCREST RD	NW / 0.179 mi., 945 ft.	349
K85	APRO LLC DBA UNITED PACIFIC 0659 | UNITED PACIFIC 0659 | GSE San Marcos 851632	112 S RANCHO SANTA FE RD	WSW / 0.218 mi., 1150 ft.	532

LOWER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
F49	PEACOCK CLEANERS | SUNNY FRESH & PEACOCK CLEANERS | HAPPY CHANGS	1450 W MISSION RD | 1450 W MISSION RD STE S | 1450 W Mission Rd #S	ESE / 0.160 mi., 846 ft.	288
I60	MEL'S AUTO REPAIR, LLC | K & D MACHINE | MEL'S AUTO REPAIRNA LLC	139 NORTH PACIFIC STE A1 | 139 N PACIFIC ST | 139 N PACIFIC ST, SUITE B	SSE / 0.182 mi., 960 ft.	366
I91	BARREL SERVICE CO | BARREL SERVICE COMPANY - 203419	105 S PACIFIC ST | 105 SOUTH PACIFIC ST	SSE / 0.229 mi., 1207 ft.	567
K93	GSE SAN MARCOS 851632 | EXXON #1041	112 S RANCHO SANTA FE | 112 RANCHO SANTA FE RD | 112 South Rancho Santa Fe	WSW / 0.230 mi., 1215 ft.	575

OTHER ASCERTAINABLE RECORDS *(cont.)*

RMP: Facilities producing/handling/ process/ distribute/ store specific chemicals report plans required by the Clean Air Act **1 SITE FOUND WITHIN .5 MILE**

LOWER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
114	*CITY SAN MARCOS BUILDING & SAFETY | CCC POOL SERVICES, INC.*	*120 LAS POSAS RD | 120 N LAS POSAS RD*	*SSE / 0.486 mi., 2566 ft.*	*736*

CALEPA SITES - CA: CalEPA Regulated Sites from the Certified Unified Program Agencies (CUPA). **32 SITES FOUND WITHIN .25 MILE**

EQUAL/HIGHER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
C13	JACK IN THE BOX #71	1655 CAPALINA RD	W / 0.069 mi., 364 ft.	*68*
C15	*AUTOZONE #5723*	*195 RANCHO SANTA FE RD | 195 S RANCHO SANTA FE RD*	*W / 0.094 mi., 498 ft.*	*70*
C19	*JIFFY LUBE #1967 | TEAM CAR CARE WEST LLC DBA JIFFY LUBE | CASEY'S CAR WASH*	*218 S RANCHO SANTA FE RD | 218 SOUTH RANCHO SANTA FE ROAD | LOT SOUTH OF 218 S RANCHO SANTA FE RD*	*WNW / 0.102 mi., 539 ft.*	*83*
D20	*99 Cents Only Stores #307*	*155 S RANCHO SANTA FE RD | 155 SNA RANCHO SANTA FE RD*	*W / 0.104 mi., 550 ft.*	*105*
C21	*CIRCLE K STORES DC 36 #2969 | 787349*	*202 S RANCHO SANTA FE RD*	*W / 0.106 mi., 559 ft.*	*107*
D22	*SAN MARCOS VETERINARY CLINIC*	*145 S RANCHO SANTA FE RD*	*W / 0.106 mi., 561 ft.*	*116*
C23	*POBRAN CHIROPRACTIC*	*174 S RANCHO SANTA FE RD*	*W / 0.108 mi., 573 ft.*	*118*
C24	*SAN MARCOS DENTAL CENTER*	*162 S RANCHO SANTA FE RD*	*W / 0.108 mi., 573 ft.*	*118*
C26	*PALM SPRINGS OIL CO (CHEVRON) | APRO LLC DBA UNITED PACIFIC 0658 | 1X CHEVRON USA INC #9-3496*	*110 S RANCHO SANTA FE RD | 110 RANCHO SANTA FE RD*	*W / 0.109 mi., 577 ft.*	*122*
C27	*SIERRRA PRINT AND DESIGN INC | ALTA VISTA DENTAL | TOREY PRESTERA MD*	*100 N RANCHO SANTA FE RD | 100 N RANCHO SANTA FE RD #127 | 100 N RANCHO SANTA FE RD STE 123*	*W / 0.110 mi., 584 ft.*	*140*
C28	*RANCHO SANTA FE EXXON | COASTAL TRANSPORT CO | GSE San Marcos 851632*	*112 N RANCHO SANTA FE RD | 112 RANCHO SANTA FE DR*	*W / 0.116 mi., 615 ft.*	*147*
D30	*GLENN YOUNG ARCO #6200 | SAN MARCOS AMPM | RANCHO SANTA FE ARCO*	*125 N RANCHO SANTA FE RD*	*WSW / 0.118 mi., 624 ft.*	*172*
D32	*ARCO PRODUCTS COMPANY | ARCO #6200 | ARCO Facility No. 6200 125 North Rancho Santa Fe Road*	*125 NORTH RANCHO SANTE FE | 125 RANCHO SANTA FE RD N | 125 North Rancho Santa Fe Road*	*WSW / 0.119 mi., 627 ft.*	*208*
D37	*FIVE STAR TEXACO SERVICE CNTR | RANCHO SANTE FE GAS | RANCHO SANTA FE GAS*	*105 RANCHO SANTA FE RD | 105 S RANCHO SANTA FE RD | 105 RANCHO SANTA FE RD SAP #120462*	*WSW / 0.126 mi., 668 ft.*	*218*
D41	*BRADLEY PARK OLD LINDA VSTA LF | SD CO OF PUB WKS SAN MARCOS I LANDFILL | BRADLEY PARK - OLD LINDA VSTA LANDFILL (SAN MARCOS I LANDFILL)*	*RANCHO SANTA FE & LINDA VISTA | RANCHO SANTE FE RD/LINDA VISTA | RANCHO SANTA FE/LINDA VISTA RD*	*WSW / 0.134 mi., 706 ft.*	*253*
K79	*CHEVRON*	*110 RANCHO SANTE FE RD*	*WSW / 0.210 mi., 1110 ft.*	*515*
K85	*APRO LLC DBA UNITED PACIFIC 0659 | UNITED PACIFIC 0659 | GSE San Marcos 851632*	*112 S RANCHO SANTA FE RD*	*WSW / 0.218 mi., 1150 ft.*	*532*

OTHER ASCERTAINABLE RECORDS *(cont.)*

CALEPA SITES - CA: CalEPA Regulated Sites from the Certified Unified Program Agencies (CUPA). **32 SITES FOUND WITHIN .25 MILE**

LOWER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
A2	*CAPALINA CLINIC | SAN DIEGO HEALTH ALLIANCE*	*1560 CAPALINA RD*	*SSE / 0.012 mi., 64 ft.*	*57*
A12	7-ELEVEN STORE #21142 | BHANDAL ENTERPRISES INC DBA: 7-ELEVEN #21142	1531 W MISSION RD STE G	ESE / 0.065 mi., 346 ft.	*68*
F46	*HydroPlant Hydroseeding, Inc. | MOBILEWELD, INC. | HYDRO-PLANTNA INC*	*356 S PACIFIC ST*	*E / 0.144 mi., 760 ft.*	*284*
F49	*PEACOCK CLEANERS | SUNNY FRESH & PEACOCK CLEANERS | HAPPY CHANGS*	*1450 W MISSION RD | 1450 W MISSION RD STE S | 1450 W Mission Rd #S*	*ESE / 0.160 mi., 846 ft.*	*288*
H50	*SO CAL COUNTERWORKS | EHIINC*	*120 NORTH PACIFIC ST#D8*	*S / 0.164 mi., 865 ft.*	*294*
I59	*BENCHMARK LANDSCAPE SERVICES INC 1/1/07 | Benchmark Landscape - San Marcos | BENCHMARK LANSCAPE INC*	*145 N PACIFIC ST*	*SSE / 0.181 mi., 956 ft.*	*355*
I60	*MEL'S AUTO REPAIR, LLC | K & D MACHINE | MEL'S AUTO REPAIRNA LLC*	*139 NORTH PACIFIC STE A1 | 139 N PACIFIC ST | 139 N PACIFIC ST, SUITE B*	*SSE / 0.182 mi., 960 ft.*	*366*
I62	*NEILL WORKS LLC DBA MEL'S AUTO REPAIR | KB MOTORSPORTS INC | MEL'S AUTO REPAIR*	*139 N PACIFIC ST | 139 N PACIFIC ST STE A | 139 N PACIFIC ST STE A-1*	*SSE / 0.183 mi., 967 ft.*	*377*
I73	*Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros*	*120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2*	*SSE / 0.201 mi., 1061 ft.*	*410*
I76	*Old World Wood | PIONEER INDUSTRIAL PARK | BEST AUTO BODY AND FRAME*	*120 N PACIFIC ST STE D4 | 120 N PACIFIC STE G3 | 120 N PACIFIC*	*SSE / 0.203 mi., 1075 ft.*	*481*
86	*PEACOCK CLEANERS*	*1450 MISSION RD W #S*	*ESE / 0.219 mi., 1158 ft.*	*547*
M88	*BUTLER MACHINING AND DESIGN INCORPORATED | PACIFIC METAL PRODUCTS | ANVIL DESIGNS*	*155 BALBOA ST D4 | 155 BALBOA ST UNIT D13 | 155 BALBOA ST*	*SE / 0.220 mi., 1163 ft.*	*549*
K93	*GSE SAN MARCOS 851632 | EXXON #1041*	*112 S RANCHO SANTA FE | 112 RANCHO SANTA FE RD | 112 South Rancho Santa Fe*	*WSW / 0.230 mi., 1215 ft.*	*575*
M94	*HIGH TECH EDM | 1X MISSION INDUSTRIAL SQUARE*	*175 BALBOA ST STE A4 | 175 N BALBOA ST*	*SE / 0.231 mi., 1220 ft.*	*583*
K99	*RANCHO SANTE FE GAS | RANCHO SANTA FE GAS*	*105 RANCHO SANTA FE ROAD*	*SW / 0.245 mi., 1294 ft.*	*600*

DRYCLEANERS - CA: Listing of drycleaning facilities **2 SITES FOUND WITHIN .25 MILE**

EQUAL/HIGHER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
D36	*CONTINENTAL CLEANERS*	*109 S RANCHO SANTA FE RD*	*WSW / 0.125 mi., 659 ft.*	*216*

LOWER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
F66	*PEACOCK CLEANERS*	*1450 MISSION RD | 1450 MISSION RD STE S | 1450 Mision Road West #S*	*ESE / 0.186 mi., 985 ft.*	*386*

OTHER ASCERTAINABLE RECORDS *(cont.)*

DRYCLEANERS_SAN DIEGO COUNTY - CA: Listing of drycleaning facilities in San Diego County **1 SITE FOUND WITHIN .25 MILE**

LOWER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
F49	*PEACOCK CLEANERS | SUNNY FRESH & PEACOCK CLEANERS | HAPPY CHANGS*	*1450 W MISSION RD | 1450 W MISSION RD STE S | 1450 W Mission Rd #S*	*ESE / 0.160 mi., 846 ft.*	*288*
	- ID: N/R	Status: Active	Date: N/R	
	- ID: APCD2007-PTO-910396	Status: Active	Date: N/R	

FIRE AREAS - CA: The multi-agency statewide database of fire perimeters. **1 SITE FOUND WITHIN 1 MILE**

EQUAL/HIGHER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
104	N/R	33.179126, -117.200551	ENE / 0.274 mi., 1447 ft.	*622*

HAZMAT_SAN DIEGO COUNTY - CA: San Diego county listing of hazardous material permitted facilities **35 SITES FOUND WITHIN .25 MILE**

EQUAL/HIGHER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
B4	MINUTEMAN PRESS | DR NOVIKOFF & ASSOCIATES	277 S RANCHO SANTA FE RD | 277 S RANCHO SANTA FE RD, SUITE J	NNW / 0.036 mi., 191 ft.	*60*
	- ID: DEH2002-HUPFP-153400	Status: Permit Renewed	Date: 2002-05-04	
	- ID: DEH2002-HUPFP-200201	Status: Completed	Date: 2002-07-11	
B8	*RANDALL LEADS DDS | RANDALL J LEADS DDS | RONALD PARK, MD*	*235 N RANCHO SANTA FE RD | 235 N RANCHO SANTA FE RD STE 206*	*NW / 0.056 mi., 297 ft.*	*63*
	- ID: DEH2002-HUPFP-153348	Status: Completed	Date: 2002-05-04	
	- ID: DEH2005-HUPFP-205083	Status: Expired	Date: 2005-03-24	
B10	*SHERIDAN CHIROPRACTIC*	*225 N RANCHO SANTA FE RD*	*NW / 0.061 mi., 324 ft.*	*65*
	- ID: DEH2003-HUPFP-202503	Status: Expired	Date: 2003-09-25	
C15	*AUTOZONE #5723*	*195 RANCHO SANTA FE RD | 195 S RANCHO SANTA FE RD*	*W / 0.094 mi., 498 ft.*	*70*
	- ID: DEH2002-HUPFP-136426	Status: Permit Renewed	Date: 2002-05-04	
D18	*WESTERN DENTAL SERVICES INC*	*169 S RANCHO SANTA FE RD*	*W / 0.102 mi., 537 ft.*	*79*
	- ID: DEH2011-HUPFP-215763	Status: Permit Renewed	Date: 2011-11-21	
C19	*JIFFY LUBE #1967 | TEAM CAR CARE WEST LLC DBA JIFFY LUBE | CASEY'S CAR WASH*	*218 S RANCHO SANTA FE RD | 218 SOUTH RANCHO SANTA FE ROAD | LOT SOUTH OF 218 S RANCHO SANTA FE RD*	*WNW / 0.102 mi., 539 ft.*	*83*
	- ID: DEH2004-HUPFP-203570	Status: Permit Renewed	Date: 2004-06-02	
D20	*99 Cents Only Stores #307*	*155 S RANCHO SANTA FE RD | 155 SNA RANCHO SANTA FE RD*	*W / 0.104 mi., 550 ft.*	*105*
	- ID: DEH2012-HUPFP-216180	Status: Permit Renewed	Date: 2012-03-13	
D22	*SAN MARCOS VETERINARY CLINIC*	*145 S RANCHO SANTA FE RD*	*W / 0.106 mi., 561 ft.*	*116*
	- ID: DEH2012-HUPFP-217323	Status: Application In-Review	Date: 2012-11-15	

OTHER ASCERTAINABLE RECORDS *(cont.)*

HAZMAT_SAN DIEGO COUNTY - CA: San Diego county listing of hazardous material permitted facilities **35 SITES FOUND WITHIN .25 MILE**

EQUAL/HIGHER ELEVATION *(cont.)*

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
C25	*RANCHO SANTA FE EXXON | GSE San Marcos 851632 | G&M OIL #171*	*112 N RANCHO SANTA FE RD*	*W / 0.109 mi., 577 ft.*	*119*
	- ID: DEH2009-HUPFP-210458	Status: Completed	Date: 2009-03-06	
	- ID: DEH2012-HUPFP-217308	Status: Permit Renewed	Date: 2012-11-13	
C26	*PALM SPRINGS OIL CO (CHEVRON) | APRO LLC DBA UNITED PACIFIC 0658 | 1X CHEVRON USA INC #9-3496*	*110 S RANCHO SANTA FE RD | 110 RANCHO SANTA FE RD*	*W / 0.109 mi., 577 ft.*	*122*
	- ID: DEH2002-HUPFP-113261	Status: Permit Renewed	Date: 2002-05-04	
C27	*SIERRRA PRINT AND DESIGN INC | ALTA VISTA DENTAL | TOREY PRESTERA MD*	*100 N RANCHO SANTA FE RD | 100 N RANCHO SANTA FE RD #127 | 100 N RANCHO SANTA FE RD STE 123*	*W / 0.110 mi., 584 ft.*	*140*
	- ID: DEH2003-HUPFP-202443	Status: Completed	Date: 2003-09-12	
	- ID: DEH2008-HUPFP-209826	Status: Permit Renewed	Date: 2008-10-23	
	- ID: DEH2011-HUPFP-215736	Status: Completed	Date: 2011-11-10	
	- ID: DEH2010-HUPFP-212730	Status: Completed	Date: 2010-09-03	
	- ID: DEH2004-HUPFP-203151	Status: Completed	Date: 2004-02-25	
	There are an additional 4 status records, see site details.			
D30	*GLENN YOUNG ARCO #6200 | SAN MARCOS AMPM | RANCHO SANTA FE ARCO*	*125 N RANCHO SANTA FE RD*	*WSW / 0.118 mi., 624 ft.*	*172*
	- ID: DEH2002-HUPFP-105181	Status: Permit Renewed	Date: 2002-05-04	
D37	*FIVE STAR TEXACO SERVICE CNTR | RANCHO SANTE FE GAS | RANCHO SANTA FE GAS*	*105 RANCHO SANTA FE RD | 105 S RANCHO SANTA FE RD | 105 RANCHO SANTA FE RD SAP #120462*	*WSW / 0.126 mi., 668 ft.*	*218*
	- ID: DEH2002-HUPFP-105804	Status: Completed	Date: 2002-05-04	
	- ID: DEH2002-HUPFP-133765	Status: Completed	Date: 2002-05-04	
	- ID: DEH2003-HUPFP-202180	Status: Permit Renewed	Date: 2003-07-25	

LOWER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
A2	*CAPALINA CLINIC | SAN DIEGO HEALTH ALLIANCE*	*1560 CAPALINA RD*	*SSE / 0.012 mi., 64 ft.*	*57*
	- ID: DEH2004-HUPFP-204404	Status: Permit Renewed	Date: 2004-11-16	
	- ID: DEH2003-HUPFP-201643	Status: Completed	Date: 2003-04-10	
	- ID: DEH2002-HUPFP-154377	Status: Completed	Date: 2002-05-04	
A7	ALOHA PRINTING	1551 W MISSION RD	ESE / 0.050 mi., 266 ft.	*62*
	- ID: DEH2002-HUPFP-104149	Status: Completed	Date: 2002-05-04	
A11	*7-ELEVEN # 21142 | BHANDAL ENTERPRISES INC DBA: 7-ELEVEN #21142*	*1531 W MISSION RD STE G | 1531 W MISSION RD, G, SAN MARCOS CA 920691255*	*ESE / 0.065 mi., 346 ft.*	*66*
	- ID: DEH2018-HUPFP-004273	Status: Pending Inspection	Date: 2018-03-15	

OTHER ASCERTAINABLE RECORDS *(cont.)*

HAZMAT_SAN DIEGO COUNTY - CA: San Diego county listing of hazardous material permitted facilities **35 SITES FOUND WITHIN .25 MILE**

LOWER ELEVATION *(cont.)*

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
39	*1X DUPLICATE PARTS COMPANY | DUPLICATE PARTS COMPANY*	*168 PACIFIC ST | 168 S PACIFIC ST*	*SE / 0.130 mi., 685 ft.*	*249*
	- ID: DEH2002-HUPFP-104190	Status: Completed	Date: 2002-05-04	
F42	*GENERAL ELECTRONIC DEVICES | PACIFIC AUTO RESTORATION | AM GRAPHICS AND PRINTING*	*320 S PACIFIC ST | 320 PACIFIC ST*	*ESE / 0.135 mi., 715 ft.*	*273*
	- ID: DEH2002-HUPFP-108671 - ID: DEH2003-HUPFP-201509	Status: Completed Status: Completed	Date: 2002-05-04 Date: 2003-03-12	
F43	RYKO SOLUTIONS	330 S PACIFIC ST, A	E / 0.137 mi., 725 ft.	*276*
	- ID: DEH2011-HUPFP-215890	Status: Permit Renewed	Date: 2011-12-20	
F49	*PEACOCK CLEANERS | SUNNY FRESH & PEACOCK CLEANERS | HAPPY CHANGS*	*1450 W MISSION RD | 1450 W MISSION RD STE S | 1450 W Mission Rd #S*	*ESE / 0.160 mi., 846 ft.*	*288*
	- ID: DEH2008-HUPFP-209330	Status: Permit Renewed	Date: 2008-05-16	
I57	*STONE ELEMENT | SCD FABRICATION*	*143 N PACIFIC ST #K | 143 S PACIFIC ST*	*SSE / 0.177 mi., 934 ft.*	*348*
	- ID: DEH2011-HUPFP-213476	Status: Completed	Date: 2011-01-12	
I59	*BENCHMARK LANDSCAPE SERVICES INC 1/1/07 | Benchmark Landscape - San Marcos | BENCHMARK LANSCAPE INC*	*145 N PACIFIC ST*	*SSE / 0.181 mi., 956 ft.*	*355*
	- ID: DEH2007-HUPFP-208337	Status: Permit Renewed	Date: 2007-07-19	
I60	*MEL'S AUTO REPAIR, LLC | K & D MACHINE | MEL'S AUTO REPAIRNA LLC*	*139 NORTH PACIFIC STE A1 | 139 N PACIFIC ST | 139 N PACIFIC ST, SUITE B*	*SSE / 0.182 mi., 960 ft.*	*366*
	- ID: DEH2011-HUPFP-213699 - ID: DEH2012-HUPFP-216339 - ID: DEH2012-HUPFP-216956	Status: Completed Status: Permit Suspended Status: Permit Renewed	Date: 2011-02-07 Date: 2012-04-18 Date: 2012-08-23	
I63	*ARENDSE MOTORSPORTS | BULTER MACHINING & DESIGN INC | REBEL FABRICATION*	*137 N PACIFIC ST | 137 N PACIFIC ST STE E*	*SSE / 0.183 mi., 968 ft.*	*383*
	- ID: DEH2005-HUPFP-205032 - ID: DEH2003-HUPFP-201513 - ID: DEH2011-HUPFP-213581	Status: Completed Status: Completed Status: Completed	Date: 2005-03-14 Date: 2003-03-12 Date: 2011-01-21	
I64	AVISTA TECHNOLOGIES | TRI-CITY COMPETITION	133 N PACIFIC ST	SSE / 0.184 mi., 974 ft.	*384*
	- ID: DEH2002-HUPFP-105738 - ID: DEH2002-HUPFP-128907	Status: Completed Status: Completed	Date: 2002-05-04 Date: 2002-05-04	
I65	ANTUAN KASSABRY EUROPEAN WOODWORKS	137 PACIFIC ST	SSE / 0.184 mi., 974 ft.	*385*
	- ID: DEH2010-HUPFP-212450	Status: Completed	Date: 2010-08-03	

OTHER ASCERTAINABLE RECORDS *(cont.)*

HAZMAT_SAN DIEGO COUNTY - CA: San Diego county listing of hazardous material permitted facilities **35 SITES FOUND WITHIN .25 MILE**

LOWER ELEVATION *(cont.)*

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
I67	ADVANCED ENGINEERING SOLUTIONS | METAL ARTS | TOM MAXWELL ENTERPRISES	135 N PACIFIC ST	SSE / 0.187 mi., 987 ft.	*392*
	- ID: DEH2008-HUPFP-209569	Status: Completed	Date: 2008-07-30	
	- ID: DEH2002-HUPFP-128908	Status: Completed	Date: 2002-05-04	
	- ID: DEH2002-HUPFP-137039	Status: Completed	Date: 2002-05-04	
J70	*MELLES GRIOT | MELLES GRIOT SAN MARCOS CO*	*435 S PACIFIC ST*	*E / 0.194 mi., 1025 ft.*	*401*
	- ID: DEH2002-HUPFP-108130	Status: Completed	Date: 2002-05-04	
J71	*SOUTHERN CALIFORNIA FLEET SERVICES | SOUTHERN CALIFORNIA FLEET SER*	*437 S PACIFIC ST | 437 SOUTH PACIFIC ST*	*E / 0.196 mi., 1034 ft.*	*407*
	- ID: DEH2002-HUPFP-132976	Status: Completed	Date: 2002-05-04	
I73	*Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros*	*120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2*	*SSE / 0.201 mi., 1061 ft.*	*410*
	- ID: DEH2002-HUPFP-200325	Status: Completed	Date: 2002-07-22	
	- ID: DEH2002-HUPFP-135665	Status: Completed	Date: 2002-05-04	
	- ID: DEH2002-HUPFP-116173	Status: Completed	Date: 2002-05-04	
	- ID: DEH2002-HUPFP-131158	Status: Completed	Date: 2002-05-04	
	- ID: DEH2010-HUPFP-212474	Status: Completed	Date: 2010-08-04	
	There are an additional 24 status records, see site details.			
I76	*Old World Wood | PIONEER INDUSTRIAL PARK | BEST AUTO BODY AND FRAME*	*120 N PACIFIC ST STE D4 | 120 N PACIFIC STE G3 | 120 N PACIFIC*	*SSE / 0.203 mi., 1075 ft.*	*481*
	- ID: DEH2002-HUPFP-135935	Status: Completed	Date: 2002-05-04	
M77	DEMON FABRICATION, INC	169 BALBOA ST	SE / 0.206 mi., 1086 ft.	*510*
	- ID: DEH2008-HUPFP-209645	Status: Permit Suspended	Date: 2008-08-25	
M78	*TECHNOGRAPHICS CO*	*181 BALBOA STREET*	*SE / 0.208 mi., 1099 ft.*	*510*
	- ID: DEH2002-HUPFP-133191	Status: Completed	Date: 2002-05-04	
M81	*PACIFIC YACHT TOWERS | HENRY MACHINE, INC.*	*165 BALBOA ST*	*SE / 0.211 mi., 1113 ft.*	*521*
	- ID: DEH2002-HUPFP-139433	Status: Completed	Date: 2002-05-04	
	- ID: DEH2005-HUPFP-204666	Status: Permit Renewed	Date: 2005-01-10	
M88	*BUTLER MACHINING AND DESIGN INCORPORATED | PACIFIC METAL PRODUCTS | ANVIL DESIGNS*	*155 BALBOA ST D4 | 155 BALBOA ST UNIT D13 | 155 BALBOA ST*	*SE / 0.220 mi., 1163 ft.*	*549*
	- ID: DEH2002-HUPFP-126032	Status: Completed	Date: 2002-05-04	
	- ID: DEH2020-HUPFP-005866	Status: Pending Inspection	Date: 2020-05-27	

OTHER ASCERTAINABLE RECORDS *(cont.)*

HAZNET - CA: Listing of hazardous waste manifests from when hazardous waste is transported from generators to permitted recycling treatment storage or disposal facilities by registered hazardous waste transporters **69 SITES FOUND WITHIN .25 MILE**

EQUAL/HIGHER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
1	*TREK BICYCLE SUPERSTORE | MTC CYCLE SPORTS INC DBA TREK BICYCLE SUPERSTORE*	*1617 CAPALINA RD STE B | 1617 CAPALINA RD UNIT B*	*SW / 0.009 mi., 50 ft.*	*52*
B3	*THOMAS PAYNE CHIROPRACTIC*	*317 RANCHO SANTA FE*	*NNW / 0.027 mi., 141 ft.*	*59*
B6	*WISE CHIROPRACTIC*	*245 N. RANCHO SANTA FE RD 204*	*NW / 0.050 mi., 262 ft.*	*62*
B8	*RANDALL LEADS DDS | RANDALL J LEADS DDS | RONALD PARK, MD*	*235 N RANCHO SANTA FE RD | 235 N RANCHO SANTA FE RD STE 206*	*NW / 0.056 mi., 297 ft.*	*63*
C9	*THE JUMPING TURTLE BAR & GRILL*	*1660 CAPALINA RD*	*W / 0.058 mi., 309 ft.*	*64*
C14	*CHIEF AUTO PARTS, #29979*	*195 S RANCHO SANTE FE RD*	*W / 0.088 mi., 464 ft.*	*69*
C15	*AUTOZONE #5723*	*195 RANCHO SANTA FE RD | 195 S RANCHO SANTA FE RD*	*W / 0.094 mi., 498 ft.*	*70*
D16	*1X MILLERS OUTPOST*	*155 RANCHO SANTA FE*	*W / 0.097 mi., 515 ft.*	*77*
C17	*TEXACO XPRESS LUBE #623*	*218 S SANTA FE RD*	*WNW / 0.101 mi., 535 ft.*	*78*
C19	*JIFFY LUBE #1967 | TEAM CAR CARE WEST LLC DBA JIFFY LUBE | CASEY'S CAR WASH*	*218 S RANCHO SANTA FE RD | 218 SOUTH RANCHO SANTA FE ROAD | LOT SOUTH OF 218 S RANCHO SANTA FE RD*	*WNW / 0.102 mi., 539 ft.*	*83*
C26	*PALM SPRINGS OIL CO (CHEVRON) | APRO LLC DBA UNITED PACIFIC 0658 | 1X CHEVRON USA INC #9-3496*	*110 S RANCHO SANTA FE RD | 110 RANCHO SANTA FE RD*	*W / 0.109 mi., 577 ft.*	*122*
C28	*RANCHO SANTA FE EXXON | COASTAL TRANSPORT CO | GSE San Marcos 851632*	*112 N RANCHO SANTA FE RD | 112 RANCHO SANTA FE DR*	*W / 0.116 mi., 615 ft.*	*147*
D30	*GLENN YOUNG ARCO #6200 | SAN MARCOS AMPM | RANCHO SANTA FE ARCO*	*125 N RANCHO SANTA FE RD*	*WSW / 0.118 mi., 624 ft.*	*172*
D32	*ARCO PRODUCTS COMPANY | ARCO #6200 | ARCO Facility No. 6200 125 North Rancho Santa Fe Road*	*125 NORTH RANCHO SANTE FE | 125 RANCHO SANTA FE RD N | 125 North Rancho Santa Fe Road*	*WSW / 0.119 mi., 627 ft.*	*208*
E35	*MINDY LANDRY*	*3556 DE LEONE RD.*	*WNW / 0.124 mi., 657 ft.*	*215*
D36	*CONTINENTAL CLEANERS*	*109 S RANCHO SANTA FE RD*	*WSW / 0.125 mi., 659 ft.*	*216*
D37	*FIVE STAR TEXACO SERVICE CNTR | RANCHO SANTE FE GAS | RANCHO SANTA FE GAS*	*105 RANCHO SANTA FE RD | 105 S RANCHO SANTA FE RD | 105 RANCHO SANTA FE RD SAP #120462*	*WSW / 0.126 mi., 668 ft.*	*218*
G38	*HELENE NICKEL*	*406 CONCHA LN*	*NNE / 0.128 mi., 675 ft.*	*247*
C44	*GARRET KAYE*	*3570 DE LONE ROAD*	*WNW / 0.139 mi., 736 ft.*	*277*
E48	*CHIP UYU*	*3532 HOLLENCREST RD*	*NW / 0.157 mi., 830 ft.*	*287*
G53	*GERLAND, KEITH*	*1634 SADDLEHORN DRIVE*	*NNE / 0.173 mi., 914 ft.*	*306*
55	*SAN MARCOS ANIMAL MEDICAL CENTER | SIENNA PRINT & DESIGN INC DBA ALPHAGRAPHICS 554 | THE NORTH COUNTY EMERGENCY ANIMAL CLINIC*	*100 N RANCHO SANTA FE RD | 100 N RANCHO SANTA FE RD STE 127 | 100 N RANCHO SANTA FE RD, 133*	*W / 0.173 mi., 916 ft.*	*344*
E58	*ERNESTO RAYMUNDO*	*3520 HOLLENCREST RD*	*NW / 0.179 mi., 945 ft.*	*349*
K72	*MATTESON PRINT INC*	*1665 S RANCHO SANTA FE SUITE-*	*WSW / 0.197 mi., 1042 ft.*	*409*
L75	*LUIS RODRIGUEZ*	*3518 CAPALINA ROAD*	*WNW / 0.203 mi., 1073 ft.*	*479*
K85	*APRO LLC DBA UNITED PACIFIC 0659 | UNITED PACIFIC 0659 | GSE San Marcos 851632*	*112 S RANCHO SANTA FE RD*	*WSW / 0.218 mi., 1150 ft.*	*532*

OTHER ASCERTAINABLE RECORDS *(cont.)*

HAZNET - CA: Listing of hazardous waste manifests from when hazardous waste is transported from generators to permitted recycling treatment storage or disposal facilities by registered hazardous waste transporters **69 SITES FOUND WITHIN .25 MILE**

EQUAL/HIGHER ELEVATION *(cont.)*

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
L98	JAVIER LUCAS | JIMMY HARRIS	3522 BADILLO ROAD	WNW / 0.240 mi., 1268 ft.	598

LOWER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
A5	ALOHA PRINTING	1551 W MISSION RD STE C	ESE / 0.048 mi., 252 ft.	61
F31	TRI CITY COMPETITION SERVICE	1338 N PACIFIC	ESE / 0.118 mi., 625 ft.	207
F33	CREATIVE PAINTING & WALL COVERING | PFT STORAGE INC | STOREM SELF STORAGE	185 N PACIFIC ST	ESE / 0.120 mi., 632 ft.	212
F34	LOREAL USA INC | 1X FRITO LAY INC	215 PACIFIC ST UNIT 103 | 235 SOUTH PACIFIC	ESE / 0.124 mi., 657 ft.	214
39	1X DUPLICATE PARTS COMPANY | DUPLICATE PARTS COMPANY	168 PACIFIC ST | 168 S PACIFIC ST	SE / 0.130 mi., 685 ft.	249
F40	EAGLE SAFE CORP	320 SO PACIFIC	E / 0.131 mi., 690 ft.	251
F42	GENERAL ELECTRONIC DEVICES | PACIFIC AUTO RESTORATION | AM GRAPHICS AND PRINTING	320 S PACIFIC ST | 320 PACIFIC ST	ESE / 0.135 mi., 715 ft.	273
F45	FREE BUILDING SUPPLY	330 PACIFIC #D	E / 0.142 mi., 752 ft.	283
F47	SAN MARCOS AUTO TRUCK REPAIR	382 SOUTH PACIFIC ST.	E / 0.152 mi., 801 ft.	286
F49	PEACOCK CLEANERS | SUNNY FRESH & PEACOCK CLEANERS | HAPPY CHANGS	1450 W MISSION RD | 1450 W MISSION RD STE S | 1450 W Mission Rd #S	ESE / 0.160 mi., 846 ft.	288
H51	BEST AUTO BODY	120 N PACIFIC ST BLDG B-3	S / 0.165 mi., 869 ft.	305
52	METAL SURGE	16115 RANCHO SANTA FE	WSW / 0.171 mi., 906 ft.	305
H54	VECCHIO MONDO IMPORTS | TRANSMISSION DEPOT | OLD FASHIONED WOODWORKING	120 N PACIFIC ST H2 | 120 N PACIFIC ST STE L11 | 120 N PACIFIC ST	S / 0.173 mi., 914 ft.	308
I56	UNICAP MOLD CO	140 N PACIFIC ST STE K	SSE / 0.177 mi., 933 ft.	347
I59	BENCHMARK LANDSCAPE SERVICES INC 1/1/07 | Benchmark Landscape - San Marcos | BENCHMARK LANSCAPE INC	145 N PACIFIC ST	SSE / 0.181 mi., 956 ft.	355
I60	MEL'S AUTO REPAIR, LLC | K & D MACHINE | MEL'S AUTO REPAIRNA LLC	139 NORTH PACIFIC STE A1 | 139 N PACIFIC ST | 139 N PACIFIC ST, SUITE B	SSE / 0.182 mi., 960 ft.	366
I61	J J & S ASBESTOS REMOVAL , INC., DBA: J J & S CONSTRUCTION | NORTH COUNTY HYDRAULICS | JJ&S CONSTRUCTION	141 N PACIFIC ST STE D | 141 NORTH PACIFIC STREET, SUITE D | 143 N PACIFIC ST # K	SSE / 0.182 mi., 962 ft.	374
I63	ARENDSE MOTORSPORTS | BULTER MACHINING & DESIGN INC | REBEL FABRICATION	137 N PACIFIC ST | 137 N PACIFIC ST STE E	SSE / 0.183 mi., 968 ft.	383
F66	PEACOCK CLEANERS	1450 MISSION RD | 1450 MISSION RD STE S | 1450 Mision Road West #S	ESE / 0.186 mi., 985 ft.	386
68	SCOTT SAALFELD	441 SILVER SPUR WAY	ENE / 0.188 mi., 995 ft.	392
I69	NEILL WORKS LLC DBA MEL'S AUTO REPAIR | MONY'S AUTO REPAIR | MANNING MOTOR SPORT PERFORMANCE	139 N PACIFIC ST | 139 N PACIFIC ST #A | 139 NORTH PACIFIC ST #D	SSE / 0.192 mi., 1015 ft.	394

OTHER ASCERTAINABLE RECORDS *(cont.)*

HAZNET - CA: Listing of hazardous waste manifests from when hazardous waste is transported from generators to permitted recycling treatment storage or disposal facilities by registered hazardous waste transporters **69 SITES FOUND WITHIN .25 MILE**

LOWER ELEVATION *(cont.)*

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
J70	*MELLES GRIOT | MELLES GRIOT SAN MARCOS CO*	*435 S PACIFIC ST*	*E / 0.194 mi., 1025 ft.*	*401*
J71	*SOUTHERN CALIFORNIA FLEET SERVICES | SOUTHERN CALIFORNIA FLEET SER*	*437 S PACIFIC ST | 437 SOUTH PACIFIC ST*	*E / 0.196 mi., 1034 ft.*	*407*
I73	*Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros*	*120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2*	*SSE / 0.201 mi., 1061 ft.*	*410*
I74	*MOTOTECH DIVISION OF JADAT INC | PACIFIC BODY & PAINT | EXTREME RACING MOTORSPORTS INC*	*120 N PACIFIC AVE #D6 | 120 N PACIFIC ST BLDG E3 | 120 N PACIFIC ST STE E-2*	*SSE / 0.201 mi., 1063 ft.*	*473*
I76	*Old World Wood | PIONEER INDUSTRIAL PARK | BEST AUTO BODY AND FRAME*	*120 N PACIFIC ST STE D4 | 120 N PACIFIC STE G3 | 120 N PACIFIC*	*SSE / 0.203 mi., 1075 ft.*	*481*
M78	*TECHNOGRAPHICS CO*	*181 BALBOA STREET*	*SE / 0.208 mi., 1099 ft.*	*510*
M82	*CONCOURS CLASSICS | XREFURB CENTER*	*155 BALBOA SUITE D-2 | 155 BALBOA DR | 155 BALBOA DR STE D13*	*SE / 0.211 mi., 1115 ft.*	*523*
M83	*HENRY MACHINE INC*	*165 BALBOA ST UNIT C-11*	*SE / 0.211 mi., 1115 ft.*	*529*
84	*AUTO ELECTRIC | ROMA MARBLE | BATZS CAR CARE CENTER*	*3110 S SANTA FE | 3110 SOUTH SANTA FE*	*NNW / 0.216 mi., 1140 ft.*	*529*
K87	*COUNTY OF SAN DIEGO PUBLIC WORKS*	*1660 DESCANSO AV*	*SW / 0.220 mi., 1162 ft.*	*547*
M89	*1X BALBOA NAVAL HOSPITAL*	*BUILDING 121*	*SE / 0.223 mi., 1179 ft.*	*564*
K90	*SAN DIEGO CO DPW DIV II*	*1600 DESCANSO AVE*	*SW / 0.224 mi., 1184 ft.*	*565*
I91	*BARREL SERVICE CO | BARREL SERVICE COMPANY - 203419*	*105 S PACIFIC ST | 105 SOUTH PACIFIC ST*	*SSE / 0.229 mi., 1207 ft.*	*567*
J92	*JOHN PERRY*	*412 PALMAC ST*	*E / 0.229 mi., 1210 ft.*	*574*
K93	*GSE SAN MARCOS 851632 | EXXON #1041*	*112 S RANCHO SANTA FE | 112 RANCHO SANTA FE RD | 112 South Rancho Santa Fe*	*WSW / 0.230 mi., 1215 ft.*	*575*
M94	*HIGH TECH EDM | 1X MISSION INDUSTRIAL SQUARE*	*175 BALBOA ST STE A4 | 175 N BALBOA ST*	*SE / 0.231 mi., 1220 ft.*	*583*
M95	*ALLSTAR GRAPHICS & SCREEN PRINTING | JRL STREET ROD | C & G EARLY FORD PARTS*	*165 BALBOA ST C-13 | 165 BALBOA ST C-5 | 165 BALBOA ST C11*	*SE / 0.234 mi., 1238 ft.*	*585*
J96	*MR. GEISER*	*441 PALMAC*	*E / 0.235 mi., 1244 ft.*	*589*
100	*GIANNA JIMENEZ*	*3501 HOLLENCREST ROAD'*	*NW / 0.247 mi., 1306 ft.*	*606*
J101	*DEAN TILTON*	*431 N PACIFIC ST SUITE D*	*E / 0.248 mi., 1309 ft.*	*607*
M102	*PACIFIC METAL PRODUCTS | 1X ROOT TRUCKING CO INC*	*155 BALBOA ST UNIT D13 | 155 N BALBOA ST*	*SE / 0.250 mi., 1320 ft.*	*608*

HIGH FIRE - CA: Fire hazard severity zones mapped as areas of significant fire hazards on the basis of fuels terrain weather and other factors **3 SITES FOUND WITHIN 1 MILE**

EQUAL/HIGHER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
116	N/R	33.686331, -116.858686	N / 0.702 mi., 3708 ft.	*744*
119	N/R	33.190584, -117.21929	NW / 0.845 mi., 4461 ft.	*830*
120	N/R	33.202447, -117.208458	NNW / 0.963 mi., 5086 ft.	*830*

OTHER ASCERTAINABLE RECORDS *(cont.)*

HIST CORTESE - CA: The historical compliance document used in providing information about the location of hazardous material release sites utilized by the state local agencies and developers **1 SITE FOUND WITHIN .5 MILE**

LOWER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
O109	*TORREY CHEMICAL CO | GR ENTERPRISE INC*	*217 LAS POSAS RD*	*SE / 0.419 mi., 2213 ft.*	*676*
	- ID: 37510137	Status: REFER: OTHER AGENCY	Date: 1995-08-21	

HIST HAZNET - CA: List of hazardous waste manifests from when hazardous waste is transported from generators to permitted recycling treatment storage or disposal facilities by registered hazardous waste transporters that are no longer in current agency list. **2 SITES FOUND WITHIN .25 MILE**

EQUAL/HIGHER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
C26	*PALM SPRINGS OIL CO (CHEVRON) | APRO LLC DBA UNITED PACIFIC 0658 | 1X CHEVRON USA INC #9-3496*	*110 S RANCHO SANTA FE RD | 110 RANCHO SANTA FE RD*	*W / 0.109 mi., 577 ft.*	*122*

LOWER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
39	*1X DUPLICATE PARTS COMPANY | DUPLICATE PARTS COMPANY*	*168 PACIFIC ST | 168 S PACIFIC ST*	*SE / 0.130 mi., 685 ft.*	*249*

HIST LDS - CA: List of areas of land on or in which hazardous waste is placed or the largest area in which there is significant likelihood of mixing hazardous waste constituents in the same area that are no longer in current agency list. **1 SITE FOUND WITHIN .5 MILE**

EQUAL/HIGHER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
D41	*BRADLEY PARK OLD LINDA VSTA LF | SD CO OF PUB WKS SAN MARCOS I LANDFILL | BRADLEY PARK - OLD LINDA VSTA LANDFILL (SAN MARCOS I LANDFILL)*	*RANCHO SANTA FE & LINDA VISTA | RANCHO SANTE FE RD/LINDA VISTA | RANCHO SANTA FE/LINDA VISTA RD*	*WSW / 0.134 mi., 706 ft.*	*253*
	- ID: L10006943141	Status: OPEN - VERIFICATION MONITORING	Date: N/A	

HWP - CA: Facility listing of the Department of Toxic Substance Control's hazardous waste transporters and corrective action **1 SITE FOUND WITHIN 1 MILE**

LOWER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
117	*SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE*	*1001 ARMORLITE DR*	*ESE / 0.746 mi., 3940 ft.*	*744*

HWT - CA: Listing of registered hazardous waste transporters **1 SITE FOUND WITHIN .25 MILE**

LOWER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
I61	*J J & S ASBESTOS REMOVAL , INC., DBA: J J & S CONSTRUCTION | NORTH COUNTY HYDRAULICS | JJ&S CONSTRUCTION*	*141 N PACIFIC ST STE D | 141 NORTH PACIFIC STREET, SUITE D | 143 N PACIFIC ST # K*	*SSE / 0.182 mi., 962 ft.*	*374*

OTHER ASCERTAINABLE RECORDS *(cont.)*

LDS - CA: List of Land Disposal Cleanup Sites from Geotracker **1 SITE FOUND WITHIN .5 MILE**

EQUAL/HIGHER ELEVATION

MAP ID	SITE NAME	SITE ADDRESS	DIRECTION/DISTANCE	PAGE
D41	*BRADLEY PARK OLD LINDA VSTA LF | SD CO OF PUB WKS SAN MARCOS I LANDFILL | BRADLEY PARK - OLD LINDA VSTA LANDFILL (SAN MARCOS I LANDFILL)*	*RANCHO SANTA FE & LINDA VISTA | RANCHO SANTE FE RD/LINDA VISTA | RANCHO SANTA FE/LINDA VISTA RD*	*WSW / 0.134 mi., 706 ft.*	*253*
	- ID: L10006943141	Status: Open - Closed/with Monitoring	Date: 2015-06-30	

Following sites were unable to be mapped.

SITE NAME:	ADDRESS, CITY, ZIP:	DATABASE(S):
2174 Vons A Safeway Company	671 S RANCHO SANTA FE RD SAN MARCO...	HAZMAT_SAN DIEGO COUNTY - CA
5 M MAINTENANCE SERVICES	1404 DESCANSO AVE SAN MARCOS CA 92...	HAZMAT_SAN DIEGO COUNTY - CA
COLINAS CONTRACTORS	1990 S SANTA FE AVE SUITE A VISTA...	HAZMAT_SAN DIEGO COUNTY - CA
COUNTY OF SAN DIEGO - VECTOR CONTROL	126 PACIFIC ST	HAZMAT_SAN DIEGO COUNTY - CA
Gregory Canyon Landfill	State Route 76 SW of Pala Indian R...	LF_SAN DIEGO COUNTY - CA
Jacumba Burnsite II	Jacumba Street SW of Lake Jacumba	LF_SAN DIEGO COUNTY - CA
Javier Mobile and Auto Repair	2514 S SANTA FE AVE SUITE E5 VIST...	HAZMAT_SAN DIEGO COUNTY - CA
Luna's Auto Shop	1828 S SANTA FE AVE VISTA CA 92083	HAZMAT_SAN DIEGO COUNTY - CA
MEADOWLARK WASTE WATER REC FAC | ...	2310 RANCHO SANTA FE..., SAN MARCOS...	HAZNET - CA, HWG - CA
PARK REVOCABLE FAMILY TRUST	225 235 245 N RANC..., SAN MARCOS 92069	ECHO, FRS, HWG - CA, RCRA_NONGEN

DATABASE(S) WITH NO MAPPED SITES:

FEDERAL RCRA NON-CORRACTS TSD FACILITIES LIST

ARCHIVED RCRA TSDF	Archived Resource Conservation and Recovery Act: Treatment Storage and Disposal Facilities
RCRA_TSDF	Resource Conservation and Recovery Act: Treatment Storage and Disposal Facilities

FEDERAL, STATE, AND TRIBAL REGISTERED STORAGE TANK LISTS

AST PBS	ASTs at Bulk Petroleum Terminals
FEMA UST	FEMA Underground Storage Tanks
HIST INDIAN UST R6	Historical Underground Storage Tanks on Indian Land in EPA Region 6
HIST INDIAN UST R7	Historical Underground Storage Tanks on Indian Land in EPA Region 7
INDIAN UST R1	Underground Storage Tanks on Indian Land in EPA Region 1
INDIAN UST R10	Underground Storage Tanks on Indian Land in EPA Region 10
INDIAN UST R2	Underground Storage Tanks on Indian Land in EPA Region 2
INDIAN UST R4	Underground Storage Tanks on Indian Land in EPA Region 4
INDIAN UST R5	Underground Storage Tanks on Indian Land in EPA Region 5
INDIAN UST R6	Underground Storage Tanks on Indian Land in EPA Region 6
INDIAN UST R7	Underground Storage Tanks on Indian Land in EPA Region 7
INDIAN UST R8	Underground Storage Tanks on Indian Land in EPA Region 8
INDIAN UST R9	Underground Storage Tanks on Indian Land in EPA Region 9
AST_KERN COUNTY - CA	Kern County Aboveground Storage Tanks Facilites
AST_ORANGE COUNTY - CA	Orange County Aboveground Storage Tanks
AST_PLACER COUNTY - CA	Placer County Aboveground Storage Tanks
AST_YOLO COUNTY - CA	Yolo County Above Ground Storage Tanks
CLOSED UST_VENTURA COUNTY - CA	Ventura County Closed Underground Storage Tanks
HIST UST - CA	Historical Underground Storage Tanks
HIST UST_EL SEGUNDO CITY - CA	Historical City of El Segundo Underground Storage Tanks

FEDERAL, STATE, AND TRIBAL REGISTERED STORAGE TANK LISTS *(cont.)*

HIST UST_KERN COUNTY - CA	Historical Kern County Underground Storage Tanks
HIST UST_SUTTER COUNTY - CA	Historical Sutter County Underground Storage Tank List
TANKS_CONTRA COSTA COUNTY - CA	Contra Costa County Aboveground Storage Tanks
UST_ALAMEDA COUNTY - CA	Alameda County Underground Storage Tanks
UST_CITY OF LONG BEACH - CA	City of Long Beach Underground Storage Tanks
UST_CITY OF TORRANCE - CA	City of Torrance Underground Storage Tanks
UST_EL SEGUNDO CITY - CA	City of El Segundo Underground Storage Tanks
UST_KERN COUNTY - CA	Kern County Underground Storage Tanks
UST_MARIN COUNTY - CA	Marin County Underground Storage Tanks
UST_MENDOCINO COUNTY - CA	Mendocino County Underground Storage Tanks
UST_NAPA COUNTY - CA	Underground storage tank sites located in Napa county.
UST_ORANGE COUNTY - CA	Orange County Underground Storage Tanks
UST_PLACER COUNTY - CA	Placer County Underground Storage Tanks
UST_RIVERSIDE COUNTY - CA	Riverside County Underground Storage Tanks
UST_SAN FRANCISCO COUNTY - CA	San Francisco County Underground Storage Tanks
UST_SAN JOAQUIN COUNTY - CA	San Joaquin County Underground Storage Tanks
UST_SOLANO COUNTY - CA	Solano County Underground Storage Tanks
UST_SUTTER COUNTY - CA	Sutter County Underground Storage Tanks
UST_YOLO COUNTY - CA	Yolo County Underground Storage Tanks

FEDERAL CERCLIS LIST

CERCLIS-HIST	Comprehensive Environmental Response Compensation and Liability Act
EPA SAA	EPA Superfund Alternative Approach
FEDERAL FACILITY	Federal Facility sites
SEMS_8R_ACTIVE SITES	Sites on SEMS Active Site Inventory

FEDERAL RCRA CORRACTS FACILITIES LIST

HIST CORRACTS 2	Historical Hazardous Waste Corrective Action

FEDERAL DELISTED NPL SITE LIST

DELISTED NPL	Delisted National Priority List
DELISTED PROPOSED NPL	Delisted proposed National Priority List
SEMS_DELETED NPL	Sites Deleted from National Priorities List

FEDERAL LANDFILL AND/OR SOLID WASTE DISPOSAL SITE LISTS

EPA LF MOP	EPA Landfill Methane Outreach Project Database

FEDERAL, STATE, AND TRIBAL LEAKING STORAGE TANK LISTS

HIST INDIAN LUST R4	Historical Leaking Underground Storage Tanks on Indian Land in EPA Region 4
HIST INDIAN LUST R8	Historical Leaking Underground Storage Tanks on Indian Land in EPA Region 8
INDIAN LUST R1	Leaking Underground Storage Tanks on Indian Land in EPA Region 1
INDIAN LUST R10	Leaking Underground Storage Tanks on Indian Land in EPA Region 10
INDIAN LUST R2	Leaking Underground Storage Tanks on Indian Land in EPA Region 2
INDIAN LUST R4	Leaking Underground Storage Tanks on Indian Land in EPA Region 4
INDIAN LUST R5	Leaking Underground Storage Tanks on Indian Land in EPA Region 5
INDIAN LUST R6	Leaking Underground Storage Tanks on Indian Land in EPA Region 6
INDIAN LUST R7	Leaking Underground Storage Tanks on Indian Land in EPA Region 7
INDIAN LUST R8	Leaking Underground Storage Tanks on Indian Land in EPA Region 8
INDIAN LUST R9	Leaking Underground Storage Tanks on Indian Land in EPA Region 9
HIST LUST_SONOMA COUNTY - CA	Historical Sonoma County Leaking Underground Storage Tanks
LUFT_ALAMEDA COUNTY - CA	Alameda County Leaking Underground Fuel Tanks
LUST ORANGE COUNTY - CA	Orange County Leaking Underground Storage Tanks
LUST REG 1 - CA	Region 1 Leaking Underground Storage Tanks
LUST REG 2 - CA	Region 2 Leaking Underground Storage Tanks
LUST REG 3 - CA	Region 3 Leaking Underground Storage Tanks
LUST REG 4 - CA	Region 4 Leaking Underground Storage Tanks
LUST REG 5 - CA	Region 5 Leaking Underground Storage Tanks

FEDERAL, STATE, AND TRIBAL LEAKING STORAGE TANK LISTS *(cont.)*

LUST REG 6 - CA	Region 6 Leaking Underground Storage Tanks
LUST REG 7 - CA	Region 7 Leaking Underground Storage Tanks
LUST REG 8 - CA	Region 8 Leaking Underground Storage Tanks
LUST_HAZMAT_YOLO COUNTY - CA	Yolo County Leaking Underground Storage tanks
LUST_KERN COUNTY - CA	Kern County leaking underground tank sites
LUST_RIVERSIDE COUNTY - CA	Riverside County Leaking Underground Storage Tanks
LUST_SAN FRANCISCO COUNTY - CA	listing of leaking underground storage tanks
LUST_SAN MATEO COUNTY - CA	San Mateo County Leaking Underground Storage Tanks
LUST_SOLANO COUNTY - CA	Solano County Leaking Underground Storage Tanks
LUST_SONOMA COUNTY - CA	Sonoma County Leaking Underground Storage Tanks
LUST_SUTTER COUNTY - CA	Sutter County Leaking Underground Storage Tanks
LUST_VENTURA COUNTY - CA	Ventura County Leaking Underground Storage Tanks
SLIC REG 1 - CA	Spills Leaks Investigation & Cleanup Program
SLIC REG 2 - CA	Spills Leaks Investigation & Cleanup Program
SLIC REG 3 - CA	Spills Leaks Investigation & Cleanup Program
SLIC REG 4 - CA	Spills Leaks Investigation & Cleanup Program
SLIC REG 5 - CA	Spills Leaks Investigation & Cleanup Program
SLIC REG 6 - CA	Spills Leaks Investigation & Cleanup Program
SLIC REG 7 - CA	Spills Leaks Investigation & Cleanup Program
SLIC REG 8 - CA	Spills Leaks Investigation & Cleanup Program
SLIC_ALAMEDA COUNTY - CA	Alameda County Spills Leaks Investigation & Cleanup

FEDERAL ERNS LIST

ERNS	Emergency Response Notification System

FEDERAL INSTITUTIONAL CONTROLS / ENGINEERING CONTROLS REGISTRIES

FED E C	Engineering Controls
FED I C	Institutional Controls
RCRA IC_EC	RCRA sites with Institutional and Engineering Controls

FEDERAL RCRA GENERATORS LIST

HIST RCRA_CESQG	Historical Resource Conservation and Recovery Act_Conditionally Exempt Small Quantity Generators
HIST RCRA_LQG	Historical Resource Conservation and Recovery Act_ Large Quantity Generators
HIST RCRA_NONGEN	Historical Resource Conservation and Recovery Act_Non Generators
HIST RCRA_SQG	Historical Resource Conservation and Recovery Act_Small Quantity Generators
RCRA_LQG	Resource Conservation and Recovery Act_ Large Quantity Generators
RCRA_VSQG	Resource Conservation and Recovery Act_Very Small Quantity Generator

FEDERAL NPL SITE LIST

NPL	National Priority List
NPL EPA R1 GIS	GIS for EPA Region 1 NPL
NPL EPA R3 GIS	GIS for EPA Region 3 NPL
NPL EPA R6 GIS	GIS for EPA Region 6 NPL
NPL EPA R8 GIS	GIS for EPA Region 8 NPL
NPL EPA R9 GIS	GIS for EPA Region 9 NPL
PART NPL	Part National Priority List
PROPOSED NPL	Proposed National Priority List
SEMS_FINAL NPL	Sites included on the Final National Priorities List
SEMS_PROPOSED NPL	Sites Proposed to be Added to the National Priorities List

STATE- AND TRIBAL - EQUIVALENT CERCLIS

HIST TOXIC PITS - CA	Historical Toxic Pits Cleanup Act
OIL & GAS CLEANUP - CA	SWRCB Oil & Gas Cleanup Sites
SWRCB CLEANUP - CA	SWRCB Cleanup Program
SWRCB NON_CASE - CA	SWRCB Non-Case Sites
TOXIC PITS - CA	Toxic Pits Cleanup Act

STATE- AND TRIBAL - EQUIVALENT NPL

HIST RESPONSE - CA	Historical State Response Sites
RESPONSE - CA	State Response Sites

STATE AND TRIBAL LANDFILL AND/OR SOLID WASTE DISPOSAL SITE LISTS

HIST SWF/LF - CA	Historical Solid Waste Information System

STATE RCRA GENERATORS LIST

HWG_YOLO COUNTY - CA	State Hazardous Waste Generators

STATE AND TRIBAL BROWNFIELD SITES

TRIBAL BROWNFIELDS	Tribal Brownfields

STATE AND TRIBAL VOLUNTARY CLEANUP SITES

VCP - CA	Voluntary Cleanup Program sites

LOCAL BROWNFIELD LISTS

BROWNFIELDS-ACRES	EPA ACRES Brownfields
FED BROWNFIELDS	Federal Brownfields

LOCAL LISTS OF HAZARDOUS WASTE / CONTAMINATED SITES

FED CDL	DOJ Clandestine Drug Labs
US HIST CDL	Historical Clandestine Drug Labs
CALARP_KERN COUNTY - CA	HazMat Chemical Facility List
CDL - CA	Meth and Clandestine Drug Labs
CORRECTIVE ACTION_RIVERSIDE COUNTY - CA	Riverside County Corrective Action Sites
CS_NAPA COUNTY - CA	Contaminated Sites
CS_PLACER COUNTY - CA	Placer County Cleanup Sites
SCH - CA	School Property Evaluation Program
SITE LIST_CONTRA COSTA COUNTY - CA	Contra Costa County Sites List
TOXIC SITE_SACRAMENTO COUNTY - CA	Sacramento County Toxic Site Cleanup list

RECORDS OF EMERGENCY RELEASE REPORTS

HMIRS (DOT)	Hazardous Materials Information Reporting Systems
CHMIRS - CA	California Hazardous Material Incident Report System
HIST CHMIRS - CA	California Hazardous Material Incident Report System
INDUSTRIAL CLEANUP_ORANGE COUNTY - CA	Petroleum and non-petroleum industrial spills
SML_LOS ANGELES COUNTY - CA	Los Angeles County Emergency Response session spills

LOCAL LAND RECORDS

LIENS 2	CERCLA Lien Information
DEED - CA	Deeds
HIST LIENS - CA	Historical Liens
LIENS - CA	Liens

LOCAL LISTS OF LANDFILL / SOLID WASTE DISPOSAL SITES

HIST INDIAN ODI R8	Historical Open Dump Inventory
INDIAN ODI R8	Open Dump Inventory
ODI	Open Dump Inventory
TRIBAL ODI	Indian Open Dump Inventory Sites
SWF_LOS ANGELES COUNTY - CA	Los Angeles County solid waste facilities

OTHER ASCERTAINABLE RECORDS

AFS	Air Facility Systems
ALT FUELING	Alternative Fueling Stations
BRS	Biennial Reporting Systems
CDC HAZDAT	Hazardous Substance Release and Health Effects Information
COAL ASH DOE	Coal Ash: Department of Energy
COAL ASH EPA	Coal Ash: Environmental Protection Agency
COAL GAS	Coal Gas Plants

OTHER ASCERTAINABLE RECORDS *(cont.)*

COLLEGES	COLLEGES
COLLEGES 2	COLLEGES 2
CONSENT (DECREES)	Superfund Consent Decree
CORRECTIVE ACTIONS_2020	Wastes - Hazardous Waste - Corrective Action
DEBRIS EPA LF	EPA Disaster Debris Landfill Sites
DOD	Department of Defense
DOT OPS	Department of Transportation Office of Pipeline Safety
ECHO	EPA Enforcement and Compliance History Online
ENOI	Electronic Notice of Intent
EPA FUELS	EPA Fuels Registration, Reporting, and Compliance List
EPA OSC	EPA On-Site Coordinator
EPA WATCH	EPA Watch List
FA HWF	Financial Assurance for Hazardous Waste Facilities
FEDLAND	Federal Lands
FRS	Facility Index Systems
FTTS	FIFRA/TSCA Tracking System
FTTS INSP	FIFRA/TSCA Tracking System: Inspections
FUDS	Formerly Used Defense Sites
HIST AFS	Historical Air Facility Systems
HIST AFS 2	Historical Air Facility Systems
HIST DOD	Department of Defense historical sites
HIST LEAD_SMELTER	Historical Lead Smelter Sites
HIST MLTS	Historical Material Licensing Tracking Systems
HIST PCB TRANS	Historical Polychlorinated Biphenyl (PCB) Facilities
HIST PCS ENF	Historical Enforced Permit Compliance Facilities
HIST PCS FACILITY	Historical Permit Compliance Facilities
HIST SSTS	Historical Section 7 Tracking Systems
HOSPITALS	HOSPITALS
HWC DOCKET	Hazardous Waste Compliance Docket
ICIS	Integrated Compliance Information System
INACTIVE PCS	Inactive Permit Compliance Facilities
INDIAN RESERVATION	American Indian Lands
LUCIS	Land Use Control Information Systems
LUCIS 2	Land Use Control Information Systems 2
MINE OPERATIONS	Mines list from USGS
MINES	Mines
MINES USGS	Mines list from USGS
MLTS	Material Licensing Tracking Systems
NPL AOC	Areas related to NPL remediation sites
NPL LIENS	National Priority List Liens
NURSING HOMES	NURSING HOMES
OSHA	Occupational Safety & Health Administration
PADS	PCB Activity Database Systems
PCB TRANSFORMER	Polychlorinated Biphenyl (PCB) Waste
PCS ENF	Enforced Permit Compliance Facilities
PCS FACILITY	Permit Compliance Facilities
PFAS NPL	PFAS NPL Sites
PFAS TRIS	PFAS TRIS Sites
PFAS UCMR3	PFAS UCMR Samples
RAATS	RCRA Administrative Action Tracking Systems
RADINFO	Radiation Information Systems
ROD	Record of Decision
SCHOOLS PRIVATE	SCHOOLS PRIVATE
SCHOOLS PUBLIC	SCHOOLS PUBLIC
SCRD DRYCLEANERS	SCRD Drycleaners
SEMS_SMELTER	Sites on SEMS Potential Smelter Activity
SSTS	Section 7 Tracking Systems
STORMWATER	Storm Water Permits

OTHER ASCERTAINABLE RECORDS *(cont.)*

TOSCA-PLANT	Toxic Substance Control Act: Plants
TRIS	Toxic Release Inventory Systems
UMTRA	Uranium Mill Tailing Sites
VAPOR	EPA Vapor Intrusion
AOC_SAN GABRIEL VALLEY - CA	San Gabriel Valley Superfund
BOND EXPENDITURE PLAN - CA	Bond Expenditure Plan
BP HW OUT_VENTURA COUNTY - CA	Ventura County Business Plan Hazardous Waste Producers and Operating Underground Tanks
BUSINESS INVENTORY_SAN MATEO COUNTY - CA	San Mateo County List of Underground Storage Tanks, Hazardous Materials, Business Plans, and Hazardous Waste Generators
CIWQS - CA	California Integrated Water Quality System
CIWQS 2 - CA	California Integrated Water Quality System
CORTESE - CA	The Hazardous Waste and Substances Sites List
CUPA_BUTTE COUNTY - CA	Butte County Certified Unified Program Agency
CUPA_FRESNO COUNTY - CA	Fresno County Certified Unified Program Agency
CUPA_PLACER COUNTY - CA	CUPA County Certified Unified Program Agency
DAYCARE - CA	Daycares
DRYCLEANERS_AMADOR COUNTY - CA	Amador County Drycleaners
DRYCLEANERS_ANTELOPE VALLEY - CA	Antelope Valley Drycleaners
DRYCLEANERS_BAY AREA - CA	Bay Area Drycleaners
DRYCLEANERS_BUTTE COUNTY - CA	Butte County Drycleaners
DRYCLEANERS_CALAVERAS COUNTY - CA	Calaveras County Drycleaners
DRYCLEANERS_COLUSA COUNTY - CA	Colusa County Drycleaners
DRYCLEANERS_EASTERN KERN COUNTY - CA	Eastern Kern County Drycleaners
DRYCLEANERS_EL DORADO COUNTY - CA	El Dorado County Drycleaners
DRYCLEANERS_FEATHER RIVER - CA	Feather River Drycleaners
DRYCLEANERS_GLENN COUNTY - CA	Glenn County Drycleaners
DRYCLEANERS_GREAT BASIN UNIFIED - CA	Great Basin Unified Drycleaners
DRYCLEANERS_IMPERIAL COUNTY - CA	Imperial County Drycleaners
DRYCLEANERS_LAKE COUNTY - CA	Lake County Drycleaners
DRYCLEANERS_LASSEN COUNTY - CA	Lassen County Drycleaners
DRYCLEANERS_MENDOCINO COUNTY - CA	Mendocino County Drycleaners
DRYCLEANERS_MOJAVE DESERT - CA	Mojave Desert Drycleaners
DRYCLEANERS_MONTEREY BAY - CA	Monterey Bay Drycleaners
DRYCLEANERS_NORTH COAST UNIFIED - CA	North Coast Unified Drycleaners
DRYCLEANERS_NORTHERN SIERRA - CA	Northern Sierra Drycleaners
DRYCLEANERS_NORTHERN SONOMA COUNTY - CA	Northern Sonoma County Drycleaners
DRYCLEANERS_PLACER COUNTY - CA	Placer County Drycleaners
DRYCLEANERS_SACRAMENTO COUNTY - CA	Sacramento County Drycleaners
DRYCLEANERS_SAN JOAQUIN VALLEY - CA	San Joaquin Valley Drycleaners
DRYCLEANERS_SAN LUIS OBISPO - CA	San Luis Obispo Drycleaners
DRYCLEANERS_SANTA BARBARA COUNTY - CA	Santa Barbara Drycleaners
DRYCLEANERS_SHASTA COUNTY - CA	Shasta County Drycleaner
DRYCLEANERS_SISKIYOU COUNTY - CA	Siskiyou County Drycleaners
DRYCLEANERS_SOUTH COAST - CA	South Coast Drycleaners
DRYCLEANERS_TEHAMA COUNTY - CA	Tehama County Drycleaners
DRYCLEANERS_TUOLUMNE COUNTY - CA	Tuolumne County Drycleaners
DRYCLEANERS_VENTURA COUNTY - CA	Ventura County Drycleaners
DRYCLEANERS_YOLO-SOLANO COUNTIES - CA	Yolo and Solano Counties Drycleaners
EMI - CA	Emissions Inventory Data
FA - CA	Financial Assurance
FA 2 - CA	Financial Assurance for Solid Waste Facilities
GCC_SANTA CLARA VALLEY - CA	Santa Clara Valley Groundwater Contamination Cleanups
HAZMAT INCIDENT_CONTRA COSTA COUNTY - CA	Contra Costa County Hazardous Materials Incident list

OTHER ASCERTAINABLE RECORDS *(cont.)*

HAZMAT_CITY OF SAN JOSE - CA	City of San Jose Hazardous Material Facilities
HAZMAT_SACRAMENTO COUNTY - CA	Sacramento County Master Hazardous Materials Facility list
HAZMAT_SAN BERNARDINO COUNTY - CA	San Bernardino County Hazardous Material Permits
HAZMAT_SANTA CLARA COUNTY - CA	Santa Clara County Hazardous Material Facilities
HAZWASTE_ORANGE COUNTY - CA	Orange County hazardous waste facilities
HIST HMS_LOS ANGELES COUNTY - CA	Historical Los Angeles County Street Number List
HIST HWP - CA	Historical EnviroStor Permitted Facilities
HIST MCS - CA	Historical Military Cleanup Sites
HIST NFA - CA	Historical No Further Action Sites
HMS_LOS ANGELES COUNTY - CA	Los Angeles County Street Number List
HWM COMMERCIAL FACILITIES - CA	Hazardous Waste Management Commercial Facilities
LOP_SANTA CLARA COUNTY - CA	Santa Clara County Local Oversight Program
MCS - CA	Military Cleanup Sites
MWMP - CA	Medical Waste Management Program
MWMP 2 - CA	Medical Waste Management Program
NFA - CA	No Further Action Sites
NFE - CA	Unconfirmed contaminated properties
NPDES - CA	State Wastewater and NPDES Permits
PERCHLORATE 2 - CA	Perchlorate contaminted sites
PFAS - CA	PFAS Site Listing
PFAS DOD - CA	PFAS Site Listing
PFAS GAMA - CA	PFAS GAMA Well Sampling
PROPOSITION 65 - CA	Proposition 65 Records
RFR - CA	Regulated Facility Report
SITES INVENTORY_VENTURA COUNTY - CA	Ventura County Inventory of Closed Illegal Abandoned and Inactive Sites
SMU_SANTA BARBARA COUNTY - CA	Site Mitigation Unit Sites
SWAT - CA	SWAT Reports Summary Data
VCCP_VENTURA COUNTY - CA	Ventura County County Cleanup Program
WDS - CA	Waste Discharge System
WILDLANDS - CA	Preserves List
WIP - CA	Well Investigation Program

OTHER

SEISMIC - CA	Seismic Hazards Zonation Program

SUBJECT NAME: Vacant Property
ADDRESS: Northeast Side of Capalina Rd., San Marcos, C...
LAT/LONG: 33.151670 / -117.195125

PREPARED FOR: The Phase One Group
ORDER #: 69131
REPORT DATE: March 21, 2022



- Subject Property
- CDC HAZDAT (No Data)
- Federal Lands (No Data)
- Fire Hazard Zone
- NWI
- Equal/Higher Elevation
- Department of Defense (No Data)
- FEMA FloodZone 100 (No Data)
- Historical DOD (No Data)
- Seismic (No Data)
- Lower Elevation
- DFIRM Floodzone 100
- FEMA FloodZone 500 (No Data)
- Indian Reservation (No Data)
- Area Of Concern (No Data)
- DFIRM Floodzone 500
- Fire Areas
- National Priority List (No Data)

SUBJECT NAME: Vacant Property
ADDRESS: Northeast Side of Capalina Rd., San Marcos, C...
LAT/LONG: 33.151670 / -117.195125

PREPARED FOR: The Phase One Group
ORDER #: 69131
REPORT DATE: March 21, 2022



- Subject Property
- CDC HAZDAT (No Data)
- Federal Lands (No Data)
- Fire Hazard Zone
- NWI
- Equal/Higher Elevation
- Department of Defense (No Data)
- FEMA FloodZone 100 (No Data)
- Historical DOD (No Data)
- Seismic (No Data)
- Lower Elevation
- DFIRM Floodzone 100
- FEMA FloodZone 500 (No Data)
- Indian Reservation (No Data)
- Area Of Concern (No Data)
- DFIRM Floodzone 500
- Fire Areas
- National Priority List (No Data)

DATABASE	SUBJECT PROPERTY	SEARCH DISTANCE (MILES)	<1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	>1	TOTAL MAPPED
FEDERAL RCRA NON-CORRACTS TSD FACILITIES LIST								
ARCHIVED RCRA TSDF		0.500	0	0	0	--	--	0
RCRA_TSDF		0.500	0	0	0	--	--	0
FEDERAL, STATE, AND TRIBAL REGISTERED STORAGE TANK LISTS								
AST PBS		0.250	0	0	--	--	--	0
EPA UST		0.250	1	2	--	--	--	3
FEMA UST		0.250	0	0	--	--	--	0
HIST INDIAN UST R6		0.250	0	0	--	--	--	0
HIST INDIAN UST R7		0.250	0	0	--	--	--	0
INDIAN UST R1		0.250	0	0	--	--	--	0
INDIAN UST R10		0.250	0	0	--	--	--	0
INDIAN UST R2		0.250	0	0	--	--	--	0
INDIAN UST R4		0.250	0	0	--	--	--	0
INDIAN UST R5		0.250	0	0	--	--	--	0
INDIAN UST R6		0.250	0	0	--	--	--	0
INDIAN UST R7		0.250	0	0	--	--	--	0
INDIAN UST R8		0.250	0	0	--	--	--	0
INDIAN UST R9		0.250	0	0	--	--	--	0
AST - CA		0.250	1	0	--	--	--	1
AST_KERN COUNTY - CA		0.250	0	0	--	--	--	0
AST_ORANGE COUNTY - CA		0.250	0	0	--	--	--	0
AST_PLACER COUNTY - CA		0.250	0	0	--	--	--	0
AST_YOLO COUNTY - CA		0.250	0	0	--	--	--	0
CLOSED UST_VENTURA COUNTY - CA		0.250	0	0	--	--	--	0
FID UST - CA		0.250	3	2	--	--	--	5
HIST AST - CA		0.250	1	0	--	--	--	1
HIST UST - CA		0.250	0	0	--	--	--	0
HIST UST_EL SEGUNDO CITY - CA		0.250	0	0	--	--	--	0
HIST UST_KERN COUNTY - CA		0.250	0	0	--	--	--	0
HIST UST_SUTTER COUNTY - CA		0.250	0	0	--	--	--	0
TANKS_CONTRA COSTA COUNTY - CA		0.250	0	0	--	--	--	0
UST - CA		0.250	3	2	--	--	--	5
UST_ALAMEDA COUNTY - CA		0.250	0	0	--	--	--	0
UST_CITY OF LONG BEACH - CA		0.250	0	0	--	--	--	0
UST_CITY OF TORRANCE - CA		0.250	0	0	--	--	--	0
UST_EL SEGUNDO CITY - CA		0.250	0	0	--	--	--	0

DATABASE	SUBJECT PROPERTY	SEARCH DISTANCE (MILES)	<1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	>1	TOTAL MAPPED
FEDERAL, STATE, AND TRIBAL REGISTERED STORAGE TANK LISTS *(cont.)*								
UST_KERN COUNTY - CA		0.250	0	0	--	--	--	0
UST_MARIN COUNTY - CA		0.250	0	0	--	--	--	0
UST_MENDOCINO COUNTY - CA		0.250	0	0	--	--	--	0
UST_NAPA COUNTY - CA		0.250	0	0	--	--	--	0
UST_ORANGE COUNTY - CA		0.250	0	0	--	--	--	0
UST_PLACER COUNTY - CA		0.250	0	0	--	--	--	0
UST_RIVERSIDE COUNTY - CA		0.250	0	0	--	--	--	0
UST_SAN FRANCISCO COUNTY - CA		0.250	0	0	--	--	--	0
UST_SAN JOAQUIN COUNTY - CA		0.250	0	0	--	--	--	0
UST_SOLANO COUNTY - CA		0.250	0	0	--	--	--	0
UST_SUTTER COUNTY - CA		0.250	0	0	--	--	--	0
UST_YOLO COUNTY - CA		0.250	0	0	--	--	--	0
FEDERAL CERCLIS LIST								
CERCLIS NFRAP		0.500	0	0	1	--	--	1
CERCLIS-HIST		0.500	0	0	0	--	--	0
EPA SAA		0.500	0	0	0	--	--	0
FEDERAL FACILITY		1.000	0	0	0	0	--	0
SEMS_8R_ACTIVE SITES		0.500	0	0	0	--	--	0
SEMS_8R_ARCHIVED SITES		0.500	0	0	1	--	--	1
FEDERAL RCRA CORRACTS FACILITIES LIST								
CORRACTS		1.000	0	0	0	1	--	1
HIST CORRACTS 2		1.000	0	0	0	0	--	0
FEDERAL DELISTED NPL SITE LIST								
DELISTED NPL		1.000	0	0	0	0	--	0
DELISTED PROPOSED NPL		1.000	0	0	0	0	--	0
SEMS_DELETED NPL		1.000	0	0	0	0	--	0
FEDERAL LANDFILL AND/OR SOLID WASTE DISPOSAL SITE LISTS								
EPA LF MOP		0.500	0	0	0	--	--	0
FEDERAL, STATE, AND TRIBAL LEAKING STORAGE TANK LISTS								
EPA LUST		0.500	4	1	5	--	--	10
HIST INDIAN LUST R4		0.500	0	0	0	--	--	0
HIST INDIAN LUST R8		0.500	0	0	0	--	--	0
INDIAN LUST R1		0.500	0	0	0	--	--	0

DATABASE	SUBJECT PROPERTY	SEARCH DISTANCE (MILES)	<1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	>1	TOTAL MAPPED
FEDERAL, STATE, AND TRIBAL LEAKING STORAGE TANK LISTS *(cont.)*								
INDIAN LUST R10		0.500	0	0	0	--	--	0
INDIAN LUST R2		0.500	0	0	0	--	--	0
INDIAN LUST R4		0.500	0	0	0	--	--	0
INDIAN LUST R5		0.500	0	0	0	--	--	0
INDIAN LUST R6		0.500	0	0	0	--	--	0
INDIAN LUST R7		0.500	0	0	0	--	--	0
INDIAN LUST R8		0.500	0	0	0	--	--	0
INDIAN LUST R9		0.500	0	0	0	--	--	0
HIST LUST_SONOMA COUNTY - CA		0.500	0	0	0	--	--	0
LUFT_ALAMEDA COUNTY - CA		0.500	0	0	0	--	--	0
LUST ORANGE COUNTY - CA		0.500	0	0	0	--	--	0
LUST REG 1 - CA		0.500	0	0	0	--	--	0
LUST REG 2 - CA		0.500	0	0	0	--	--	0
LUST REG 3 - CA		0.500	0	0	0	--	--	0
LUST REG 4 - CA		0.500	0	0	0	--	--	0
LUST REG 5 - CA		0.500	0	0	0	--	--	0
LUST REG 6 - CA		0.500	0	0	0	--	--	0
LUST REG 7 - CA		0.500	0	0	0	--	--	0
LUST REG 8 - CA		0.500	0	0	0	--	--	0
LUST REG 9 - CA		0.500	4	1	5	--	--	10
LUST_HAZMAT_YOLO COUNTY - CA		0.500	0	0	0	--	--	0
LUST_KERN COUNTY - CA		0.500	0	0	0	--	--	0
LUST_RIVERSIDE COUNTY - CA		0.500	0	0	0	--	--	0
LUST_SAN FRANCISCO COUNTY - CA		0.500	0	0	0	--	--	0
LUST_SAN MATEO COUNTY - CA		0.500	0	0	0	--	--	0
LUST_SOLANO COUNTY - CA		0.500	0	0	0	--	--	0
LUST_SONOMA COUNTY - CA		0.500	0	0	0	--	--	0
LUST_SUTTER COUNTY - CA		0.500	0	0	0	--	--	0
LUST_VENTURA COUNTY - CA		0.500	0	0	0	--	--	0
SLIC REG 1 - CA		0.500	0	0	0	--	--	0
SLIC REG 2 - CA		0.500	0	0	0	--	--	0
SLIC REG 3 - CA		0.500	0	0	0	--	--	0
SLIC REG 4 - CA		0.500	0	0	0	--	--	0
SLIC REG 5 - CA		0.500	0	0	0	--	--	0
SLIC REG 6 - CA		0.500	0	0	0	--	--	0

DATABASE	SUBJECT PROPERTY	SEARCH DISTANCE (MILES)	<1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	>1	TOTAL MAPPED
FEDERAL, STATE, AND TRIBAL LEAKING STORAGE TANK LISTS *(cont.)*								
SLIC REG 7 - CA		0.500	0	0	0	--	--	0
SLIC REG 8 - CA		0.500	0	0	0	--	--	0
SLIC REG 9 - CA		0.500	1	1	3	--	--	5
SLIC_ALAMEDA COUNTY - CA		0.500	0	0	0	--	--	0
FEDERAL ERNS LIST								
ERNS		SP	0	--	--	--	--	0
FEDERAL INSTITUTIONAL CONTROLS / ENGINEERING CONTROLS REGISTRIES								
FED E C		0.500	0	0	0	--	--	0
FED I C		0.500	0	0	0	--	--	0
RCRA IC_EC		0.250	0	0	--	--	--	0
FEDERAL RCRA GENERATORS LIST								
HIST RCRA_CESQG		0.250	0	0	--	--	--	0
HIST RCRA_LQG		0.250	0	0	--	--	--	0
HIST RCRA_NONGEN		0.250	0	0	--	--	--	0
HIST RCRA_SQG		0.250	0	0	--	--	--	0
RCRA_LQG		0.250	0	0	--	--	--	0
RCRA_NONGEN		0.250	6	13	--	--	--	19
RCRA_SQG		0.250	0	5	--	--	--	5
RCRA_VSQG		0.250	0	0	--	--	--	0
FEDERAL NPL SITE LIST								
NPL		1.000	0	0	0	0	--	0
NPL EPA R1 GIS		1.000	0	0	0	0	--	0
NPL EPA R3 GIS		1.000	0	0	0	0	--	0
NPL EPA R6 GIS		1.000	0	0	0	0	--	0
NPL EPA R8 GIS		1.000	0	0	0	0	--	0
NPL EPA R9 GIS		1.000	0	0	0	0	--	0
PART NPL		1.000	0	0	0	0	--	0
PROPOSED NPL		1.000	0	0	0	0	--	0
SEMS_FINAL NPL		1.000	0	0	0	0	--	0
SEMS_PROPOSED NPL		1.000	0	0	0	0	--	0
STATE- AND TRIBAL - EQUIVALENT CERCLIS								
ENVIROSTOR - CA		1.000	0	0	1	4	--	5
HIST TOXIC PITS - CA		1.000	0	0	0	0	--	0
OIL & GAS CLEANUP - CA		0.500	0	0	0	--	--	0

DATABASE	SUBJECT PROPERTY	SEARCH DISTANCE (MILES)	<1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	>1	TOTAL MAPPED
STATE- AND TRIBAL - EQUIVALENT CERCLIS *(cont.)*								
SWRCB CLEANUP - CA		0.500	0	0	0	--	--	0
SWRCB NON_CASE - CA		0.500	0	0	0	--	--	0
TOXIC PITS - CA		1.000	0	0	0	0	--	0
STATE- AND TRIBAL - EQUIVALENT NPL								
HIST RESPONSE - CA		1.000	0	0	0	0	--	0
RESPONSE - CA		1.000	0	0	0	0	--	0
STATE AND TRIBAL LANDFILL AND/OR SOLID WASTE DISPOSAL SITE LISTS								
HIST SWF/LF - CA		0.500	0	0	0	--	--	0
SWF/LF - CA		0.500	0	1	0	--	--	1
STATE RCRA GENERATORS LIST								
HWG - CA		0.250	20	53	--	--	--	73
HWG_YOLO COUNTY - CA		0.250	0	0	--	--	--	0
STATE AND TRIBAL BROWNFIELD SITES								
TRIBAL BROWNFIELDS		0.500	0	0	0	--	--	0
STATE AND TRIBAL VOLUNTARY CLEANUP SITES								
VCP - CA		0.500	0	0	0	--	--	0
LOCAL BROWNFIELD LISTS								
BROWNFIELDS-ACRES		0.500	0	0	0	--	--	0
FED BROWNFIELDS		0.500	0	0	0	--	--	0
LOCAL LISTS OF HAZARDOUS WASTE / CONTAMINATED SITES								
FED CDL		SP	0	--	--	--	--	0
US HIST CDL		SP	0	--	--	--	--	0
CALARP_KERN COUNTY - CA		0.250	0	0	--	--	--	0
CASE LIST_SAN DIEGO COUNTY - CA		0.500	4	2	7	--	--	13
CDL - CA		SP	0	--	--	--	--	0
CORRECTIVE ACTION_RIVERSIDE COUNTY - CA		1.000	0	0	0	0	--	0
CS_NAPA COUNTY - CA		0.500	0	0	0	--	--	0
CS_PLACER COUNTY - CA		1.000	0	0	0	0	--	0
SCH - CA		0.250	0	0	--	--	--	0
SITE LIST_CONTRA COSTA COUNTY - CA		0.250	0	0	--	--	--	0

DATABASE	SUBJECT PROPERTY	SEARCH DISTANCE (MILES)	<1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	>1	TOTAL MAPPED
LOCAL LISTS OF HAZARDOUS WASTE / CONTAMINATED SITES *(cont.)*								
TOXIC SITE_SACRAMENTO COUNTY - CA		1.000	0	0	0	0	--	0
RECORDS OF EMERGENCY RELEASE REPORTS								
HMIRS (DOT)		SP	0	--	--	--	--	0
CHMIRS - CA		SP	0	--	--	--	--	0
HIST CHMIRS - CA		SP	0	--	--	--	--	0
INDUSTRIAL CLEANUP_ORANGE COUNTY - CA		0.125	0	--	--	--	--	0
SML_LOS ANGELES COUNTY - CA		0.125	0	--	--	--	--	0
LOCAL LAND RECORDS								
LIENS 2		SP	0	--	--	--	--	0
DEED - CA		0.500	0	0	0	--	--	0
HIST LIENS - CA		SP	0	--	--	--	--	0
LIENS - CA		SP	0	--	--	--	--	0
LOCAL LISTS OF LANDFILL / SOLID WASTE DISPOSAL SITES								
HIST INDIAN ODI R8		0.500	0	0	0	--	--	0
INDIAN ODI R8		0.500	0	0	0	--	--	0
ODI		0.500	0	0	0	--	--	0
TRIBAL ODI		0.500	0	0	0	--	--	0
HAULERS - CA		0.500	0	0	1	--	--	1
LF_SAN DIEGO COUNTY - CA		0.500	0	1	1	--	--	2
SWF_LOS ANGELES COUNTY - CA		0.500	0	0	0	--	--	0
SWRCY - CA		0.500	1	0	1	--	--	2
OTHER ASCERTAINABLE RECORDS								
AFS		SP	0	--	--	--	--	0
ALT FUELING		0.250	0	0	--	--	--	0
BRS		SP	0	--	--	--	--	0
CDC HAZDAT		1.000	0	0	0	0	--	0
COAL ASH DOE		0.500	0	0	0	--	--	0
COAL ASH EPA		0.500	0	0	0	--	--	0
COAL GAS		1.000	0	0	0	0	--	0
COLLEGES		SP	0	--	--	--	--	0
COLLEGES 2		SP	0	--	--	--	--	0
CONSENT (DECREES)		1.000	0	0	0	0	--	0
CORRECTIVE ACTIONS_2020		0.500	0	0	0	--	--	0

DATABASE	SUBJECT PROPERTY	SEARCH DISTANCE (MILES)	<1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	>1	TOTAL MAPPED
OTHER ASCERTAINABLE RECORDS *(cont.)*								
DEBRIS EPA LF		0.500	0	0	0	--	--	0
DEBRIS EPA SWRCY		0.500	0	1	1	--	--	2
DOD		1.000	0	0	0	0	--	0
DOT OPS		SP	0	--	--	--	--	0
ECHO		SP	0	--	--	--	--	0
ENOI		SP	0	--	--	--	--	0
EPA FUELS		SP	0	--	--	--	--	0
EPA OSC		0.125	0	--	--	--	--	0
EPA WATCH		SP	0	--	--	--	--	0
FA HWF		SP	0	--	--	--	--	0
FEDLAND		1.000	0	0	0	0	--	0
FRS		SP	0	--	--	--	--	0
FTTS		SP	0	--	--	--	--	0
FTTS INSP		SP	0	--	--	--	--	0
FUDS		1.000	0	0	0	0	--	0
HIST AFS		SP	0	--	--	--	--	0
HIST AFS 2		SP	0	--	--	--	--	0
HIST DOD		1.000	0	0	0	0	--	0
HIST LEAD_SMELTER		SP	0	--	--	--	--	0
HIST MLTS		SP	0	--	--	--	--	0
HIST PCB TRANS		SP	0	--	--	--	--	0
HIST PCS ENF		SP	0	--	--	--	--	0
HIST PCS FACILITY		SP	0	--	--	--	--	0
HIST SSTS		SP	0	--	--	--	--	0
HOSPITALS		SP	0	--	--	--	--	0
HWC DOCKET		SP	0	--	--	--	--	0
ICIS		SP	0	--	--	--	--	0
INACTIVE PCS		SP	0	--	--	--	--	0
INDIAN RESERVATION		1.000	0	0	0	0	--	0
LUCIS		0.500	0	0	0	--	--	0
LUCIS 2		0.500	0	0	0	--	--	0
MANIFEST EPA		0.250	5	8	--	--	--	13
MINE OPERATIONS		0.250	0	0	--	--	--	0
MINES		0.250	0	0	--	--	--	0
MINES USGS		0.250	0	0	--	--	--	0
MLTS		SP	0	--	--	--	--	0

DATABASE	SUBJECT PROPERTY	SEARCH DISTANCE (MILES)	<1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	>1	TOTAL MAPPED
OTHER ASCERTAINABLE RECORDS *(cont.)*								
NPL AOC		1.000	0	0	0	0	--	0
NPL LIENS		SP	0	--	--	--	--	0
NURSING HOMES		SP	0	--	--	--	--	0
OSHA		SP	0	--	--	--	--	0
PADS		SP	0	--	--	--	--	0
PCB TRANSFORMER		SP	0	--	--	--	--	0
PCS ENF		SP	0	--	--	--	--	0
PCS FACILITY		SP	0	--	--	--	--	0
PFAS NPL		0.500	0	0	0	--	--	0
PFAS TRIS		0.500	0	0	0	--	--	0
PFAS UCMR3		0.500	0	0	0	--	--	0
RAATS		SP	0	--	--	--	--	0
RADINFO		SP	0	--	--	--	--	0
RMP		0.500	0	0	1	--	--	1
ROD		1.000	0	0	0	0	--	0
SCHOOLS PRIVATE		SP	0	--	--	--	--	0
SCHOOLS PUBLIC		SP	0	--	--	--	--	0
SCRD DRYCLEANERS		0.250	0	0	--	--	--	0
SEMS_SMELTER		SP	0	--	--	--	--	0
SSTS		SP	0	--	--	--	--	0
STORMWATER		SP	0	--	--	--	--	0
TOSCA-PLANT		SP	0	--	--	--	--	0
TRIS		SP	0	--	--	--	--	0
UMTRA		0.500	0	0	0	--	--	0
VAPOR		0.500	0	0	0	--	--	0
AOC_SAN GABRIEL VALLEY - CA		1.000	0	0	0	0	--	0
BOND EXPENDITURE PLAN - CA		1.000	0	0	0	0	--	0
BP HW OUT_VENTURA COUNTY - CA		0.250	0	0	--	--	--	0
BUSINESS INVENTORY_SAN MATEO COUNTY - CA		0.250	0	0	--	--	--	0
CALEPA SITES - CA		0.250	15	17	--	--	--	32
CIWQS - CA		SP	0	--	--	--	--	0
CIWQS 2 - CA		SP	0	--	--	--	--	0
CORTESE - CA		0.500	0	0	0	--	--	0
CUPA_BUTTE COUNTY - CA		0.250	0	0	--	--	--	0
CUPA_FRESNO COUNTY - CA		0.250	0	0	--	--	--	0

DATABASE	SUBJECT PROPERTY	SEARCH DISTANCE (MILES)	<1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	>1	TOTAL MAPPED
OTHER ASCERTAINABLE RECORDS *(cont.)*								
CUPA_PLACER COUNTY - CA		0.250	0	0	--	--	--	0
DAYCARE - CA		SP	0	--	--	--	--	0
DRYCLEANERS - CA		0.250	0	2	--	--	--	2
DRYCLEANERS_AMADOR COUNTY - CA		0.250	0	0	--	--	--	0
DRYCLEANERS_ANTELOPE VALLEY - CA		0.250	0	0	--	--	--	0
DRYCLEANERS_BAY AREA - CA		0.250	0	0	--	--	--	0
DRYCLEANERS_BUTTE COUNTY - CA		0.250	0	0	--	--	--	0
DRYCLEANERS_CALAVERAS COUNTY - CA		0.250	0	0	--	--	--	0
DRYCLEANERS_COLUSA COUNTY - CA		0.250	0	0	--	--	--	0
DRYCLEANERS_EASTERN KERN COUNTY - CA		0.250	0	0	--	--	--	0
DRYCLEANERS_EL DORADO COUNTY - CA		0.250	0	0	--	--	--	0
DRYCLEANERS_FEATHER RIVER - CA		0.250	0	0	--	--	--	0
DRYCLEANERS_GLENN COUNTY - CA		0.250	0	0	--	--	--	0
DRYCLEANERS_GREAT BASIN UNIFIED - CA		0.250	0	0	--	--	--	0
DRYCLEANERS_IMPERIAL COUNTY - CA		0.250	0	0	--	--	--	0
DRYCLEANERS_LAKE COUNTY - CA		0.250	0	0	--	--	--	0
DRYCLEANERS_LASSEN COUNTY - CA		0.250	0	0	--	--	--	0
DRYCLEANERS_MENDOCINO COUNTY - CA		0.250	0	0	--	--	--	0
DRYCLEANERS_MOJAVE DESERT - CA		0.250	0	0	--	--	--	0
DRYCLEANERS_MONTEREY BAY - CA		0.250	0	0	--	--	--	0
DRYCLEANERS_NORTH COAST UNIFIED - CA		0.250	0	0	--	--	--	0
DRYCLEANERS_NORTHERN SIERRA - CA		0.250	0	0	--	--	--	0
DRYCLEANERS_NORTHERN SONOMA COUNTY - CA		0.250	0	0	--	--	--	0
DRYCLEANERS_PLACER COUNTY - CA		0.250	0	0	--	--	--	0

DATABASE	SUBJECT PROPERTY	SEARCH DISTANCE (MILES)	<1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	>1	TOTAL MAPPED
OTHER ASCERTAINABLE RECORDS *(cont.)*								
DRYCLEANERS_SACRAMENTO COUNTY - CA		0.250	0	0	--	--	--	0
DRYCLEANERS_SAN DIEGO COUNTY - CA		0.250	0	1	--	--	--	1
DRYCLEANERS_SAN JOAQUIN VALLEY - CA		0.250	0	0	--	--	--	0
DRYCLEANERS_SAN LUIS OBISPO - CA		0.250	0	0	--	--	--	0
DRYCLEANERS_SANTA BARBARA COUNTY - CA		0.250	0	0	--	--	--	0
DRYCLEANERS_SHASTA COUNTY - CA		0.250	0	0	--	--	--	0
DRYCLEANERS_SISKIYOU COUNTY - CA		0.250	0	0	--	--	--	0
DRYCLEANERS_SOUTH COAST - CA		0.250	0	0	--	--	--	0
DRYCLEANERS_TEHAMA COUNTY - CA		0.250	0	0	--	--	--	0
DRYCLEANERS_TUOLUMNE COUNTY - CA		0.250	0	0	--	--	--	0
DRYCLEANERS_VENTURA COUNTY - CA		0.250	0	0	--	--	--	0
DRYCLEANERS_YOLO-SOLANO COUNTIES - CA		0.250	0	0	--	--	--	0
EMI - CA		SP	0	--	--	--	--	0
FA - CA		SP	0	--	--	--	--	0
FA 2 - CA		SP	0	--	--	--	--	0
FIRE AREAS - CA		1.000	0	0	1	0	--	1
GCC_SANTA CLARA VALLEY - CA		0.500	0	0	0	--	--	0
HAZMAT INCIDENT_CONTRA COSTA COUNTY - CA		0.250	0	0	--	--	--	0
HAZMAT_CITY OF SAN JOSE - CA		0.250	0	0	--	--	--	0
HAZMAT_SACRAMENTO COUNTY - CA		0.250	0	0	--	--	--	0
HAZMAT_SAN BERNARDINO COUNTY - CA		0.250	0	0	--	--	--	0
HAZMAT_SAN DIEGO COUNTY - CA		0.250	15	20	--	--	--	35
HAZMAT_SANTA CLARA COUNTY - CA		0.250	0	0	--	--	--	0
HAZNET - CA		0.250	19	50	--	--	--	69
HAZWASTE_ORANGE COUNTY - CA		0.500	0	0	0	--	--	0

DATABASE	SUBJECT PROPERTY	SEARCH DISTANCE (MILES)	<1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	>1	TOTAL MAPPED
OTHER ASCERTAINABLE RECORDS *(cont.)*								
HIGH FIRE - CA		1.000	0	0	0	3	--	3
HIST CORTESE - CA		0.500	0	0	1	--	--	1
HIST HAZNET - CA		0.250	1	1	--	--	--	2
HIST HMS_LOS ANGELES COUNTY - CA		0.250	0	0	--	--	--	0
HIST HWP - CA		1.000	0	0	0	0	--	0
HIST LDS - CA		0.500	0	1	0	--	--	1
HIST MCS - CA		1.000	0	0	0	0	--	0
HIST NFA - CA		0.500	0	0	0	--	--	0
HMS_LOS ANGELES COUNTY - CA		0.250	0	0	--	--	--	0
HWM COMMERCIAL FACILITIES - CA		0.250	0	0	--	--	--	0
HWP - CA		1.000	0	0	0	1	--	1
HWT - CA		0.250	0	1	--	--	--	1
LDS - CA		0.500	0	1	0	--	--	1
LOP_SANTA CLARA COUNTY - CA		0.500	0	0	0	--	--	0
MCS - CA		1.000	0	0	0	0	--	0
MWMP - CA		0.250	0	0	--	--	--	0
MWMP 2 - CA		0.250	0	0	--	--	--	0
NFA - CA		0.500	0	0	0	--	--	0
NFE - CA		0.500	0	0	0	--	--	0
NPDES - CA		SP	0	--	--	--	--	0
PERCHLORATE 2 - CA		0.500	0	0	0	--	--	0
PFAS - CA		0.500	0	0	0	--	--	0
PFAS DOD - CA		0.500	0	0	0	--	--	0
PFAS GAMA - CA		0.500	0	0	0	--	--	0
PROPOSITION 65 - CA		1.000	0	0	0	0	--	0
RFR - CA		SP	0	--	--	--	--	0
SITES INVENTORY_VENTURA COUNTY - CA		1.000	0	0	0	0	--	0
SMU_SANTA BARBARA COUNTY - CA		1.000	0	0	0	0	--	0
SWAT - CA		SP	0	--	--	--	--	0
VCCP_VENTURA COUNTY - CA		0.500	0	0	0	--	--	0
WDS - CA		SP	0	--	--	--	--	0
WILDLANDS - CA		1.000	0	0	0	0	--	0
WIP - CA		0.250	0	0	--	--	--	0

DATABASE	SUBJECT PROPERTY	SEARCH DISTANCE (MILES)	<1/8	1/8 - 1/4	1/4 - 1/2	1/2 - 1	>1	TOTAL MAPPED
OTHER								
SEISMIC - CA		1.000	0	0	0	0	--	0

Map Id: 1
Direction: SW
Distance: 0.009 mi., 50 ft.
Elevation: 598 ft.
Relative: Higher

Site Name :	TREK BICYCLE SUPERSTORE | MTC CYCLE SPORTS INC DBA TREK BICYCLE SUPERSTORE 1617 CAPALINA RD STE B | 1617 CAPALINA RD UNIT B SAN MARCOS, CA 92069
Database(s) :	[ECHO, FRS, HAZNET - CA, HWG - CA, RCRA_NONGEN]

Envirosite ID: 1039123
EPA ID: CAL000392315

ECHO

Facility Name :	TREK BICYCLE SUPERSTORE
Facility Address :	1617 CAPALINA RD STE B, SAN MARCOS, CA 92069
County :	SAN DIEGO
Last Inspection Date :	N/R
Registry ID :	110070480110
FIPS Code :	N/R
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	_____
Collection Method :	Zip Code Centroid
Reference Point :	N/R
Accuracy Meters :	10000
Derived Tribes :	N/R
Derived HUC :	N/R
Derived WBD :	N/R
Derived STCTY FIPS :	N/R
Derived Zip :	N/R
Derived CD113 :	N/R
Derived CB2010 :	N/R
MYRTK Universe :	NNN
NPDES IDs :	N/R
CWA Permit Types :	N/R
CWA Compliance Tracking :	N/R
CWA NAICS :	N/R
CWA SICS :	N/R
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	N/R
CWA Current Compliance Status :	N/R
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	N/R
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R

Map Id: 1
Direction: SW
Distance: 0.009 mi., 50 ft.
Elevation: 598 ft.
Relative: Higher

Site Name : TREK BICYCLE SUPERSTORE | MTC CYCLE SPORTS INC DBA TREK BICYCLE SUPERSTORE
1617 CAPALINA RD STE B | 1617 CAPALINA RD UNIT B
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HAZNET - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 1039123
EPA ID: CAL000392315

ECHO ***(cont.)***

DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	N/R
Facility NAICS :	45111 - Sporting Goods Stores
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	N/R
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	N
SDWIS Flag :	N
RCRA Flag :	Y
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	Y
NAA Flag :	N
Latitude :	33.194075
Longitude :	-117.16177
Last Date in Agency List :	2022-01-17

FRS

Facility Name :	TREK BICYCLE SUPERSTORE
Facility Address :	1617 CAPALINA RD STE B, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Registry ID :	110070480110
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Source Description

Map Id: 1
Direction: SW
Distance: 0.009 mi., 50 ft.
Elevation: 598 ft.
Relative: Higher

Site Name : TREK BICYCLE SUPERSTORE | MTC CYCLE SPORTS INC DBA TREK BICYCLE SUPERSTORE
1617 CAPALINA RD STE B | 1617 CAPALINA RD UNIT B
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HAZNET - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 1039123
EPA ID: CAL000392315

FRS ***(cont.)***

Source Description :

RCRAInfo is EPA's comprehensive information system that supports the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984 through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA. RCRAInfo also supports generation of the National Hazardous Waste Biennial Report. All generators and treatment, storage, and disposal facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years to support creation of the Biennial Report.

FRS Environmental Interest

Source and System ID :	RCRAINFO - CAL000377346

HAZNET - CA

Facility Name :	MTC CYCLE SPORTS INC DBA TREK BICYCLE SUPERSTORE
Facility Address :	1617 CAPALINA RD UNIT B, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000392315
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	14677 VIA BETTONA STE 110-231, SAN DIEGO, CA 921274809
Latitude :	33.14945700
Longitude :	-117.19635750
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Facility Name :	TREK BICYCLE SUPERSTORE
Facility Address :	1617 CAPALINA RD STE B, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000377346
Active :	Active
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R

Map Id: 1
Direction: SW
Distance: 0.009 mi., 50 ft.
Elevation: 598 ft.
Relative: Higher

Site Name : TREK BICYCLE SUPERSTORE | MTC CYCLE SPORTS INC DBA TREK BICYCLE SUPERSTORE
1617 CAPALINA RD STE B | 1617 CAPALINA RD UNIT B
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HAZNET - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 1039123
EPA ID: CAL000392315

HAZNET - CA ***(cont.)***

Facility Mailing Address :	4240 KEARNY MESA RD, SAN DIEGO, CA 921110000
Latitude :	33.14945700
Longitude :	-117.19635750
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	2016: 214 - Unspecified solvent mixture, 0.108 tons to CAD008252405

HWG - CA

Facility Name :	MTC CYCLE SPORTS INC DBA TREK BICYCLE SUPERSTORE
Facility Address :	1617 CAPALINA RD UNIT B, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAL000392315
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	14677 VIA BETTONA STE 110-231, SAN DIEGO, CA 921274809
Owner Name :	MTC CYCLE SPORTS INC
Owner Address :	14677 VIA BETTONA STE 110-231, SAN DIEGO, CA 921274809
Operator Name :	MIKE OLSON
Operator Address :	14677 VIA BETTONA STE 110-231, SAN DIEGO, CA 92127
Latitude :	33.149457
Longitude :	-117.196358

Facility Name :	TREK BICYCLE SUPERSTORE
Facility Address :	1617 CAPALINA RD STE B, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAL000377346
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	4240 KEARNY MESA RD, SAN DIEGO, CA 921110000
Owner Name :	MIKE OLSON
Owner Address :	4240 KEARNY MESA RD, SAN DIEGO, CA 92111
Operator Name :	MIKE WILLARD
Operator Address :	4240 KEARNY MESA RD, SAN DIEGO, CA 92111
Latitude :	33.149457
Longitude :	-117.196358

Map Id: 1
Direction: SW
Distance: 0.009 mi., 50 ft.
Elevation: 598 ft.
Relative: Higher

Site Name : TREK BICYCLE SUPERSTORE | MTC CYCLE SPORTS INC DBA TREK BICYCLE SUPERSTORE
1617 CAPALINA RD STE B | 1617 CAPALINA RD UNIT B
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HAZNET - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 1039123
EPA ID: CAL000392315

RCRA_NONGEN

Facility Name :	TREK BICYCLE SUPERSTORE
Facility Address :	1617 CAPALINA RD STE B, SAN MARCOS, CA 92069
County :	SAN DIEGO
Date Form Received by Agency :	2012-08-16
EPA ID :	CAL000377346
Mailing Address :	1617 CAPALINA RD STE B, SAN MARCOS, CA 92069
Contact :	MIKE WILLARD
Contact Address :	4240 KEARNY MESA RD, SAN DIEGO, CA 92111
Contact Country :	N/R
Contact Telephone :	858-974-8735
Contact Email :	MWILLARD@TREKSD.COM
EPA Region :	09
Land Type :	Not Reported
Source Type :	Implementer
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2022-01-26

Owner/Operator Summary

Owner/Operator Name :	MIKE OLSON
Owner/Operator Address :	4240 KEARNY MESA RD, SAN DIEGO, CA 92111
Owner/Operator Country :	N/R
Owner/Operator Telephone :	589-749-8735
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Owner/Operator Name :	MIKE WILLARD
Owner/Operator Address :	4240 KEARNY MESA RD, SAN DIEGO, CA 92111
Owner/Operator Country :	N/R
Owner/Operator Telephone :	858-974-8735
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N
Recycler of Hazardous Waste :	N

Map Id: 1
Direction: SW
Distance: 0.009 mi., 50 ft.
Elevation: 598 ft.
Relative: Higher

Site Name : TREK BICYCLE SUPERSTORE | MTC CYCLE SPORTS INC DBA TREK BICYCLE SUPERSTORE
1617 CAPALINA RD STE B | 1617 CAPALINA RD UNIT B
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HAZNET - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 1039123
EPA ID: CAL000392315

RCRA_NONGEN ***(cont.)***

Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Notices of Violations Summary

Regulation Violated :	N

Map Id: A2
Direction: SSE
Distance: 0.012 mi., 64 ft.
Elevation: 585 ft.
Relative: Lower

Site Name : CAPALINA CLINIC | SAN DIEGO HEALTH ALLIANCE
1560 CAPALINA RD
SAN MARCOS, CA 92069

Database(s) : [CALEPA SITES - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA]

Envirosite ID: 639679
EPA ID: N/R

CALEPA SITES - CA

Facility Name :	CAPALINA CLINIC
Facility Address :	1560 CAPALINA RD, SAN MARCOS, 92069
Site ID :	102848
EI ID :	10376131
EI Description :	Chemical Storage Facilities
Latitude :	33.151161
Longitude :	-117.194588
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07

FRS

Facility Name :	CAPALINA CLINIC
Facility Address :	1560 CAPALINA RD, SAN MARCOS, CA 92069
County :	SAN DIEGO

Map Id: A2
Direction: SSE
Distance: 0.012 mi., 64 ft.
Elevation: 585 ft.
Relative: Lower

Site Name : CAPALINA CLINIC | SAN DIEGO HEALTH ALLIANCE
1560 CAPALINA RD
SAN MARCOS, CA 92069

Database(s) : [CALEPA SITES - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA] ***(cont.)***

Envirosite ID: 639679
EPA ID: N/R

FRS ***(cont.)***

Site Details

Registry ID :	110065706212
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Source Description

Source Description :

The California Environmental Protection Agency (CalEPA) has recently implemented a new data warehouse system (nSite). This data warehouse combines and merges facility and site information from five different systems managed within CalEPA. The five systems are: California Environmental Reporting System (CERS), EnviroStor, GeoTracker, California Integrated Water Quality System (CIWQS), and Toxic Release Inventory (TRI).

FRS Environmental Interest

Source and System ID :	CA-ENVIROVIEW - 102848

HAZMAT_SAN DIEGO COUNTY - CA

Facility Name :	CAPALINA CLINIC
Facility Address :	1560 CAPALINA RD, SAN MARCOS, CA 92069
Date :	2004-11-16
Record ID :	DEH2004-HUPFP-204404
Record Type :	Unified Program Facility Permit
Status :	Permit Renewed
Action :	Pay Fees Due
Short Notes :	N/R
Last Date in Agency List :	2015-11-23

Facility Name :	SAN DIEGO HEALTH ALLIANCE
Facility Address :	1560 CAPALINA RD, SAN MARCOS, CA 92069
Date :	2003-04-10
Record ID :	DEH2003-HUPFP-201643
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23

Date :	2002-05-04
Record ID :	DEH2002-HUPFP-154377
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R

Map Id: A2
Direction: SSE
Distance: 0.012 mi., 64 ft.
Elevation: 585 ft.
Relative: Lower

Site Name : CAPALINA CLINIC | SAN DIEGO HEALTH ALLIANCE
1560 CAPALINA RD
SAN MARCOS, CA 92069

Database(s) : [CALEPA SITES - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA] ***(cont.)***

Envirosite ID: 639679
EPA ID: N/R

HAZMAT_SAN DIEGO COUNTY - CA ***(cont.)***

Short Notes :	N/R
Last Date in Agency List :	2015-11-23

Map Id: B3
Direction: NNW
Distance: 0.027 mi., 141 ft.
Elevation: 590 ft.
Relative: Higher

Site Name : THOMAS PAYNE CHIROPRACTIC
317 RANCHO SANTA FE
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 41129021
EPA ID: CAL000160818

HAZNET - CA

Facility Name :	THOMAS PAYNE CHIROPRACTIC
Facility Address :	317 RANCHO SANTA FE, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000160818
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	317 S RANCHO SANTA FE RD, SAN MARCOS, CA 920690000
Latitude :	33.15291529
Longitude :	-117.19548422
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HWG - CA

Facility Name :	THOMAS PAYNE CHIROPRACTIC
Facility Address :	317 RANCHO SANTA FE, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAL000160818
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	317 S RANCHO SANTA FE RD, SAN MARCOS, CA 920690000
Owner Name :	THOMAS PAYNE
Owner Address :	317 S RANCHO SANTA FE RD, SAN MARCOS, CA
Operator Name :	THOMAS J. PAYNE
Operator Address :	INACTIVE PER VQ99 - BMI, SAN MARCOS, CA
Latitude :	33.142581

Map Id: B3
Direction: NNW
Distance: 0.027 mi., 141 ft.
Elevation: 590 ft.
Relative: Higher

Site Name : THOMAS PAYNE CHIROPRACTIC
317 RANCHO SANTA FE
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 41129021
EPA ID: CAL000160818

HWG - CA ***(cont.)***

Longitude : -117.202091

Map Id: B4
Direction: NNW
Distance: 0.036 mi., 191 ft.
Elevation: 592 ft.
Relative: Higher

Site Name : MINUTEMAN PRESS | DR NOVIKOFF & ASSOCIATES
277 S RANCHO SANTA FE RD | 277 S RANCHO SANTA FE RD, SUITE J
SAN MARCOS, CA 92069

Database(s) : [HAZMAT_SAN DIEGO COUNTY - CA]

Envirosite ID: 637200
EPA ID: N/R

HAZMAT_SAN DIEGO COUNTY - CA

Facility Name : DR NOVIKOFF & ASSOCIATES
Facility Address : 277 S RANCHO SANTA FE RD, SUITE J, SAN MARCOS, CA 92069

Date : 2002-05-04
Record ID : DEH2002-HUPFP-153400
Record Type : Unified Program Facility Permit
Status : Permit Renewed
Action : Pay Fees Due
Short Notes : N/R
Last Date in Agency List : 2015-11-23

Facility Name : MINUTEMAN PRESS
Facility Address : 277 S RANCHO SANTA FE RD, SAN MARCOS, CA 92069

Date : 2002-07-11
Record ID : DEH2002-HUPFP-200201
Record Type : Unified Program Facility Permit
Status : Completed
Action : N/R
Short Notes : N/R
Last Date in Agency List : 2015-11-23

Map Id: A5
Direction: ESE
Distance: 0.048 mi., 252 ft.
Elevation: 578 ft.
Relative: Lower

Site Name : ALOHA PRINTING
1551 W MISSION RD STE C
SAN MARCOS, CA 92096

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 838860
EPA ID: CAL000098155

HAZNET - CA

Facility Name :	ALOHA PRINTING
Facility Address :	1551 W MISSION RD STE C, SAN MARCOS, CA 92096
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000098155
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	1551 W MISSION RD STE C, SAN MARCOS, CA 920690000
Latitude :	33.15127626
Longitude :	-117.19378127
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	1993: 792 - Liquids with pH <= 2 with metals, 0.0625 tons to CAT080010101

HWG - CA

Facility Name :	ALOHA PRINTING
Facility Address :	1551 W MISSION RD STE C, SAN MARCOS, CA 92096
County :	SAN DIEGO

EPA ID :	CAL000098155
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	1551 W MISSION RD STE C, SAN MARCOS, CA 920690000
Owner Name :	BURROLA RUBEN
Owner Address :	N/A
Operator Name :	UNDELIVERABLE FEE FORM 4-94
Operator Address :	N/A
Latitude :	32.772006
Longitude :	-117.251139

Map Id: B6
Direction: NW
Distance: 0.050 mi., 262 ft.
Elevation: 604 ft.
Relative: Higher

Site Name : WISE CHIROPRACTIC
245 N. RANCHO SANTA FE RD 204
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 41087617
EPA ID: CAL921125689

HAZNET - CA

Facility Name :	WISE CHIROPRACTIC
Facility Address :	245 N. RANCHO SANTA FE RD 204, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL921125689
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	245 N. RANCHO SANTA FE RD 204, SAN MARCOS, CA 920690000
Latitude :	33.15258241
Longitude :	-117.19621427
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HWG - CA

Facility Name :	WISE CHIROPRACTIC
Facility Address :	245 N. RANCHO SANTA FE RD 204, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAL921125689
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	245 N. RANCHO SANTA FE RD 204, SAN MARCOS, CA 920690000
Owner Name :	JACK P. WISE
Owner Address :	245 N. RANCHO SANTA FE RD 204, SAN MARCOS, CA 920690000
Operator Name :	DEACT NON-DELIV. PER 95 FEES -
Operator Address :	P.H., N/A
Latitude :	33.152484
Longitude :	-117.196553

Map Id: A7
Direction: ESE
Distance: 0.050 mi., 266 ft.
Elevation: 578 ft.
Relative: Lower

Site Name : ALOHA PRINTING
1551 W MISSION RD
SAN MARCOS, CA 92069

Database(s) : [HAZMAT_SAN DIEGO COUNTY - CA]

Envirosite ID: 640673
EPA ID: N/R

HAZMAT_SAN DIEGO COUNTY - CA

Facility Name :	ALOHA PRINTING
Facility Address :	1551 W MISSION RD, SAN MARCOS, CA 92069

Map Id: A7
Direction: ESE
Distance: 0.050 mi., 266 ft.
Elevation: 578 ft.
Relative: Lower

Site Name : ALOHA PRINTING
1551 W MISSION RD
SAN MARCOS, CA 92069

Database(s) : [HAZMAT_SAN DIEGO COUNTY - CA] ***(cont.)***

Envirosite ID: 640673
EPA ID: N/R

HAZMAT_SAN DIEGO COUNTY - CA ***(cont.)***

Date :	2002-05-04
Record ID :	DEH2002-HUPFP-104149
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23

Map Id: B8
Direction: NW
Distance: 0.056 mi., 297 ft.
Elevation: 603 ft.
Relative: Higher

Site Name : RANDALL LEADS DDS | RANDALL J LEADS DDS | RONALD PARK, MD
235 N RANCHO SANTA FE RD | 235 N RANCHO SANTA FE RD STE 206
SAN MARCOS, CA 92069

Database(s) : [HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA]

Envirosite ID: 638561
EPA ID: N/R

HAZMAT_SAN DIEGO COUNTY - CA

Facility Name :	RANDALL J LEADS DDS
Facility Address :	235 N RANCHO SANTA FE RD, SAN MARCOS, CA 92069

Date :	2002-05-04
Record ID :	DEH2002-HUPFP-153348
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23

Facility Name :	RONALD PARK, MD
Facility Address :	235 N RANCHO SANTA FE RD, SAN MARCOS, CA 92069

Date :	2005-03-24
Record ID :	DEH2005-HUPFP-205083
Record Type :	Unified Program Facility Permit
Status :	Expired
Action :	Pay Fees Due
Short Notes :	N/R
Last Date in Agency List :	2015-11-23

HAZNET - CA

Facility Name :	RANDALL LEADS DDS
Facility Address :	235 N RANCHO SANTA FE RD STE 206, SAN MARCOS, CA 92069
County :	SAN DIEGO

Map Id: B8
Direction: NW
Distance: 0.056 mi., 297 ft.
Elevation: 603 ft.
Relative: Higher

Site Name : RANDALL LEADS DDS | RANDALL J LEADS DDS | RONALD PARK, MD
235 N RANCHO SANTA FE RD | 235 N RANCHO SANTA FE RD STE 206
SAN MARCOS, CA 92069

Database(s) : [HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 638561
EPA ID: N/R

HAZNET - CA ***(cont.)***

Site Details

Generator EPA ID :	CAL000140421
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	235 N RANCHO SANTA FE RD STE 206, SAN MARCOS, CA 920690000
Latitude :	33.15255692
Longitude :	-117.19626965
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HWG - CA

Facility Name :	RANDALL LEADS DDS
Facility Address :	235 N RANCHO SANTA FE RD STE 206, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAL000140421
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	235 N RANCHO SANTA FE RD STE 206, SAN MARCOS, CA 920690000
Owner Name :	RANDALL LEADS DDS
Owner Address :	235 N RANCHO SANTA FE RD STE 206, SAN MARCOS, CA 920690000
Operator Name :	RANDALL LEADS-OWNER
Operator Address :	235 N RANCHO SANTA FE RD STE 206, SAN MARCOS, CA 920690000
Latitude :	33.152378
Longitude :	-117.196779

Map Id: C9
Direction: W
Distance: 0.058 mi., 309 ft.
Elevation: 611 ft.
Relative: Higher

Site Name : THE JUMPING TURTLE BAR & GRILL
1660 CAPALINA RD
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 41131775
EPA ID: CAL000283012

HAZNET - CA

Facility Name :	THE JUMPING TURTLE BAR & GRILL
Facility Address :	1660 CAPALINA RD, SAN MARCOS, CA 92069
County :	SAN DIEGO

Map Id: C9
Direction: W
Distance: 0.058 mi., 309 ft.
Elevation: 611 ft.
Relative: Higher

Site Name : THE JUMPING TURTLE BAR & GRILL
1660 CAPALINA RD
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 41131775
EPA ID: CAL000283012

HAZNET - CA ***(cont.)***

Site Details

Generator EPA ID :	CAL000283012
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	1660 CAPALINA RD, SAN MARCOS, CA 92069
Latitude :	33.15162770
Longitude :	-117.19663145
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HWG - CA

Facility Name :	THE JUMPING TURTLE BAR & GRILL
Facility Address :	1660 CAPALINA RD, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAL000283012
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	1660 CAPALINA RD, SAN MARCOS, CA 92069
Owner Name :	BREEN ENTERPRISES, INC.
Owner Address :	1660 CAPALINA RD, SAN MARCOS, CA 92069
Operator Name :	MATT HALL
Operator Address :	1660 CAPALINA RD, SAN MARCOS, CA 92069
Latitude :	33.151564
Longitude :	-117.196646

Map Id: B10
Direction: NW
Distance: 0.061 mi., 324 ft.
Elevation: 607 ft.
Relative: Higher

Site Name : SHERIDAN CHIROPRACTIC
225 N RANCHO SANTA FE RD
SAN MARCOS, CA 92069

Database(s) : [FRS, HAZMAT_SAN DIEGO COUNTY - CA]

Envirosite ID: 639979
EPA ID: N/R

FRS

Facility Name :	SHERIDAN CHIROPRACTIC
Facility Address :	225 N RANCHO SANTA FE RD, SAN MARCOS, CA 92069
County :	SAN DIEGO

Map Id: B10
Direction: NW
Distance: 0.061 mi., 324 ft.
Elevation: 607 ft.
Relative: Higher

Site Name : SHERIDAN CHIROPRACTIC
225 N RANCHO SANTA FE RD
SAN MARCOS, CA 92069

Database(s) : [FRS, HAZMAT_SAN DIEGO COUNTY - CA] ***(cont.)***

Envirosite ID: 639979
EPA ID: N/R

FRS ***(cont.)***

Site Details

Registry ID :	110066399150
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Source Description

Source Description :

The California Environmental Protection Agency (CalEPA) has recently implemented a new data warehouse system (nSite). This data warehouse combines and merges facility and site information from five different systems managed within CalEPA. The five systems are: California Environmental Reporting System (CERS), EnviroStor, GeoTracker, California Integrated Water Quality System (CIWQS), and Toxic Release Inventory (TRI).

FRS Environmental Interest

Source and System ID :	CA-ENVIROVIEW - 153092

HAZMAT_SAN DIEGO COUNTY - CA

Facility Name :	SHERIDAN CHIROPRACTIC
Facility Address :	225 N RANCHO SANTA FE RD, SAN MARCOS, CA 92069
Date :	2003-09-25
Record ID :	DEH2003-HUPFP-202503
Record Type :	Unified Program Facility Permit
Status :	Expired
Action :	Pay Fees Due
Short Notes :	N/R
Last Date in Agency List :	2015-11-23

Map Id: A11
Direction: ESE
Distance: 0.065 mi., 346 ft.
Elevation: 577 ft.
Relative: Lower

Site Name : 7-ELEVEN # 21142 | BHANDAL ENTERPRISES INC DBA: 7-ELEVEN #21142
1531 W MISSION RD STE G | 1531 W MISSION RD, G, SAN MARCOS CA 920691255
SAN MARCOS, CA 92069

Database(s) : [FRS, HAZMAT_SAN DIEGO COUNTY - CA]

Envirosite ID: 40680356
EPA ID: N/R

FRS

Facility Name :	7-ELEVEN # 21142
Facility Address :	1531 W MISSION RD STE G, SAN MARCOS, CA 92069

Map Id: A11
Direction: ESE
Distance: 0.065 mi., 346 ft.
Elevation: 577 ft.
Relative: Lower

Site Name : 7-ELEVEN # 21142 | BHANDAL ENTERPRISES INC DBA: 7-ELEVEN #21142
1531 W MISSION RD STE G | 1531 W MISSION RD, G, SAN MARCOS CA 920691255
SAN MARCOS, CA 92069

Database(s) : [FRS, HAZMAT_SAN DIEGO COUNTY - CA] ***(cont.)***

Envirosite ID: 40680356
EPA ID: N/R

FRS ***(cont.)***

County : SAN DIEGO

Site Details
Registry ID : 110066493556
FRS Facility URL : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-02-17

Source Description

Source Description :

The California Environmental Protection Agency (CalEPA) has recently implemented a new data warehouse system (nSite). This data warehouse combines and merges facility and site information from five different systems managed within CalEPA. The five systems are: California Environmental Reporting System (CERS), EnviroStor, GeoTracker, California Integrated Water Quality System (CIWQS), and Toxic Release Inventory (TRI).

FRS Environmental Interest
Source and System ID : CA-ENVIROVIEW - 87524

HAZMAT_SAN DIEGO COUNTY - CA

Facility Name : BHANDAL ENTERPRISES INC DBA: 7-ELEVEN #21142
Facility Address : 1531 W MISSION RD, G, SAN MARCOS CA 920691255

Date : 2018-03-15
Record ID : DEH2018-HUPFP-004273
Record Type : Unified Program Facility Permit
Status : Pending Inspection
Action : N/R
Short Notes : N/R
Last Date in Agency List : 2018-04-24

Map Id: A12
Direction: ESE
Distance: 0.065 mi., 346 ft.
Elevation: 577 ft.
Relative: Lower

Site Name : 7-ELEVEN STORE #21142 | BHANDAL ENTERPRISES INC DBA: 7-ELEVEN #21142
1531 W MISSION RD STE G
SAN MARCOS, CA 92069

Database(s) : [CALEPA SITES - CA]

Envirosite ID: 863740
EPA ID: N/R

CALEPA SITES - CA

Facility Name :	7-ELEVEN STORE #21142
Facility Address :	1531 W MISSION RD STE G, SAN MARCOS, 92069
Site ID :	561609
EI ID :	10464676
EI Description :	Chemical Storage Facilities
Latitude :	33.150950
Longitude :	-117.193950
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07
Facility Name :	BHANDAL ENTERPRISES INC DBA: 7-ELEVEN #21142
Facility Address :	1531 W MISSION RD STE G, SAN MARCOS, 92069
Site ID :	87524
EI ID :	10464676
EI Description :	Chemical Storage Facilities
Latitude :	33.150950
Longitude :	-117.193950
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2019-07-24

Map Id: C13
Direction: W
Distance: 0.069 mi., 364 ft.
Elevation: 615 ft.
Relative: Higher

Site Name : JACK IN THE BOX #71
1655 CAPALINA RD
SAN MARCOS, CA 92069

Database(s) : [CALEPA SITES - CA]

Envirosite ID: 1124970
EPA ID: N/R

CALEPA SITES - CA

Facility Name :	JACK IN THE BOX #71
Facility Address :	1655 CAPALINA RD, SAN MARCOS, 92069
Site ID :	443318
EI ID :	10772407
EI Description :	Chemical Storage Facilities
Latitude :	33.151400
Longitude :	-117.197090
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07

Map Id: C14
Direction: W
Distance: 0.088 mi., 464 ft.
Elevation: 621 ft.
Relative: Higher

Site Name : CHIEF AUTO PARTS, #29979
195 S RANCHO SANTE FE RD
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 41054052
EPA ID: CAL000163428

HAZNET - CA

Facility Name :	CHIEF AUTO PARTS, #29979
Facility Address :	195 S RANCHO SANTE FE RD, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000163428
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	123 SO FRONT ST, MEMPHIS, TN 381036216
Latitude :	33.14625945
Longitude :	-117.20010571
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HWG - CA

Facility Name :	CHIEF AUTO PARTS, #29979
Facility Address :	195 S RANCHO SANTE FE RD, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAL000163428
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	123 SO FRONT ST, MEMPHIS, TN 381036216
Owner Name :	CHIEF AUTO PARTS INC.
Owner Address :	5400 LBJ FREEWAY STE 200, DALLAS, TX 752406216
Operator Name :	MARY M MAHON
Operator Address :	INACTIVE PER VQ99 - BMI, DALLAS, TX 752406216
Latitude :	33.146189
Longitude :	-117.200273

Map Id: C15
Direction: W
Distance: 0.094 mi., 498 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : AUTOZONE #5723
195 RANCHO SANTA FE RD | 195 S RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN]

Envirosite ID: 437663
EPA ID: CAL000148027

CALEPA SITES - CA

Facility Name :	AUTOZONE #5723
Facility Address :	195 S RANCHO SANTA FE RD, SAN MARCOS, 92069
Site ID :	96582
EI ID :	10140023
EI Description :	Hazardous Waste Generator
Latitude :	33.146220
Longitude :	-117.199660
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07

Site ID :	96582
EI ID :	10140023
EI Description :	Chemical Storage Facilities
Latitude :	33.146220
Longitude :	-117.199660
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07

HAZMAT_SAN DIEGO COUNTY - CA

Facility Name :	AutoZone #5723
Facility Address :	195 S RANCHO SANTA FE RD, SAN MARCOS, CA 92069
Date :	2002-05-04
Record ID :	DEH2002-HUPFP-136426
Record Type :	Unified Program Facility Permit
Status :	Permit Renewed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23

HAZNET - CA

Facility Name :	AUTOZONE #5723
Facility Address :	195 RANCHO SANTA FE RD, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000148027
Active :	Active
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	DEPT 8190, 123 SOUTH FRONT STREET, MEMPHIS, TN 38103
Latitude :	33.15169345

Map Id: C15
Direction: W
Distance: 0.094 mi., 498 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : AUTOZONE #5723
195 RANCHO SANTA FE RD | 195 S RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 437663
EPA ID: CAL000148027

HAZNET - CA ***(cont.)***

Longitude :	-117.19736239
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

State Waste :

2019: 223 - Unspecified oil-containing waste, 0.03500 tons to NED981723513
2018: 181 - Other inorganic solid waste, 0.00550 tons to CAD008364432
2018: 352 - Other organic solids, 0.14000 tons to CAD044429835
2018: 214 - Unspecified solvent mixture, 0.00100 tons to NVD980895338
2017: 223 - Unspecified oil-containing waste, 0.03 tons to NED981723513
2017: 352 - Other organic solids, 0.375 tons to CAD044429835
2017: 214 - Unspecified solvent mixture, 0.0035 tons to CAD008364432
2017: 181 - Other inorganic solid waste, 0.0045 tons to CAD008364432
2017: 331 - Off-specification, aged or surplus organics, 0.0005 tons to CAD008364432
2016: 214 - Unspecified solvent mixture, 0.0105 tons to CAD008364432
2016: 223 - Unspecified oil-containing waste, 0.2025 tons to NED981723513
2016: 352 - Other organic solids, 0.3875 tons to CAD044429835
2016: 181 - Other inorganic solid waste, 0.033 tons to CAD008364432
2016: 331 - Off-specification, aged or surplus organics, 0.0095 tons to CAD008364432
2016: 122 - Alkaline solution without metals pH >= 12.5, 0.0085 tons to CAD008364432
2015: 214 - Unspecified solvent mixture, 0.0255 tons to CAD008364432
2015: 331 - Off-specification, aged or surplus organics, 0.0725 tons to CAD008364432
2015: 331 - Off-specification, aged or surplus organics, 0.1065 tons to CAD008364432
2015: 352 - Other organic solids, 0.5 tons to CAD044429835
2014: 331 - Off-specification, aged or surplus organics, 0.015 tons to CAD008364432
2014: 791 - Liquids with pH <= 2, 0.0025 tons to CAD008364432
2014: 331 - Off-specification, aged or surplus organics, 0.023 tons to CAD008364432
2014: 214 - Unspecified solvent mixture, 0.0468 tons to CAD008364432
2014: 352 - Other organic solids, 0.1 tons to CAD044429835
2013: 352 - Other organic solids, 0.05 tons to CAD044429835
2013: 331 - Off-specification, aged or surplus organics, 0.0205 tons to CAD008364432
2013: 223 - Unspecified oil-containing waste, 0.02 tons to CAD008364432
2013: 343 - Unspecified organic liquid mixture, 0.0145 tons to CAD008364432
2012: 352 - Other organic solids, 0.675 tons to NVT330010000

Map Id: C15
Direction: W
Distance: 0.094 mi., 498 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : AUTOZONE #5723
195 RANCHO SANTA FE RD | 195 S RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 437663
EPA ID: CAL000148027

HAZNET - CA ***(cont.)***

2012: 343 - Unspecified organic liquid mixture, 0.0145 tons to CAD008364432

HWG - CA

Facility Name :	AUTOZONE #5723
Facility Address :	195 RANCHO SANTA FE RD, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAL000148027
Status :	Active
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	DEPT 8190, 123 SOUTH FRONT STREET, MEMPHIS, TN 38103
Owner Name :	AUTOZONE INC
Owner Address :	123 SOUTH FRONT ST, MEMPHIS, TN 381033607
Operator Name :	BRYAN BLAIR
Operator Address :	DEPT 8190, 123 SOUTH FRONT STREET, MEMPHIS, TN 38103
Latitude :	33.151755
Longitude :	-117.197406

MANIFEST EPA

Manifest Details

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Manifest Number :	022736092JJK
Shipped Date :	2021-06-23
Updated Date :	2021-07-23
Received Date :	2021-07-02
Status :	Signed
Generator ID :	CAL000148027
Generator Name :	AUTOZONE #5723
Generator Address :	195 RANCHO SANTA FE RD, SAN MARCOS, CA 92069
Generator Mailing :	DEPT 8190, 123 S FRONT ST, MEMPHIS, TN 38103-3607
Generator Contact :	N/R
Destination ID :	CAD008252405
Destination Name :	PACIFIC RESOURCE RECOVERY SERVICES INC
Destination Mailing :	3150 EAST PICO BLVD CA90023 CA037US 3150, LOS ANGELES, CA 90023
Destination Address :	3150 EAST PICO BLVD, LOS ANGELES, CA 90023-0000
Destination Contact :	N/R
Submission Type :	DataImage5Copy
Origin Type :	Web
Manifest Residue :	N
Rejection :	N
Last Date in Agency List :	2022-01-14

Map Id: C15
Direction: W
Distance: 0.094 mi., 498 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : AUTOZONE #5723
195 RANCHO SANTA FE RD | 195 S RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 437663
EPA ID: CAL000148027

MANIFEST EPA ***(cont.)***

Waste Details

Waste Line Number :	1
Is DOT Hazardous :	Y
DOT ID Number :	UN1203
DOT Information :	UN1203, WASTE GASOLINE, 3, PGII
Non Waste Description :	N/R
Quantity :	4 Gallons
Quantity Tons, Acute, Non-Acute :	0.016680567, 0, 0.016680567
Quantity Kg, Acute, Non-Acute :	0, 15.129775
Management Method :	H061 - FUEL BLENDING
Is EPA Waste :	Y
Federal Code :	D001, D018
State Code :	CA - 343

Manifest Details

Manifest Number :	022736015JJK
Shipped Date :	2021-06-17
Updated Date :	2021-07-13
Received Date :	2021-06-24
Status :	Signed
Generator ID :	CAL000148027
Generator Name :	AUTOZONE #5723
Generator Address :	195 RANCHO SANTA FE RD, SAN MARCOS, CA 92069
Generator Mailing :	DEPT 8190, 123 S FRONT ST, MEMPHIS, TN 38103
Generator Contact :	N/R
Destination ID :	AZR000521146
Destination Name :	YUMA YES 2 WASTE TRANSFER STATION
Destination Mailing :	2621 GREEN RIVER RD STE 105, CORONA, CA 92882
Destination Address :	6500 S US HIGHWAY 95, YUMA, AZ 85365
Destination Contact :	N/R
Submission Type :	DataImage5Copy
Origin Type :	Service
Manifest Residue :	N
Rejection :	N
Last Date in Agency List :	2022-01-14

Waste Details

Waste Line Number :	1
Is DOT Hazardous :	N
DOT ID Number :	N/R
DOT Information :	N/R
Non Waste Description :	NON-RCRA HAZARDOUS WASTE, SOLID (OILY DEBRIS)
Quantity :	100 Pounds
Quantity Tons, Acute, Non-Acute :	0.05, 0, 0.05
Quantity Kg, Acute, Non-Acute :	0, 45.3515
Management Method :	H141 - STORAGE, BULKING AND/OR TRANSFER OFF SITE
Is EPA Waste :	N
Federal Code :	N/R
State Code :	CA - 352

Map Id: C15
Direction: W
Distance: 0.094 mi., 498 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : AUTOZONE #5723
195 RANCHO SANTA FE RD | 195 S RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 437663
EPA ID: CAL000148027

MANIFEST EPA ***(cont.)***

Manifest Details

Manifest Number :	022498073JJK
Shipped Date :	2021-04-01
Updated Date :	2021-05-17
Received Date :	2021-04-16
Status :	Signed
Generator ID :	CAL000148027
Generator Name :	AUTOZONE #5723
Generator Address :	195 RANCHO SANTA FE RD, SAN MARCOS, CA 92069
Generator Mailing :	DEPT 8190, 123 S FRONT ST, MEMPHIS, TN 38103
Generator Contact :	N/R
Destination ID :	AZR000521146
Destination Name :	YUMA YES 2 WASTE TRANSFER STATION
Destination Mailing :	2621 GREEN RIVER RD STE 105, CORONA, CA 92882
Destination Address :	6500 S US HIGHWAY 95, YUMA, AZ 85365
Destination Contact :	N/R
Submission Type :	DataImage5Copy
Origin Type :	Service
Manifest Residue :	N
Rejection :	N
Last Date in Agency List :	2022-01-14

Waste Details

Waste Line Number :	1
Is DOT Hazardous :	N
DOT ID Number :	N/R
DOT Information :	N/R
Non Waste Description :	NON-RCRA HAZARDOUS WASTE, SOLID (OILY DEBRIS)
Quantity :	160 Pounds
Quantity Tons, Acute, Non-Acute :	0.08, 0, 0.08
Quantity Kg, Acute, Non-Acute :	0, 72.5624
Management Method :	H141 - STORAGE, BULKING AND/OR TRANSFER OFF SITE
Is EPA Waste :	N
Federal Code :	N/R
State Code :	CA - 352

Manifest Details

Manifest Number :	022493656JJK
Shipped Date :	2021-01-14
Updated Date :	2021-02-19
Received Date :	2021-01-20
Status :	Signed
Generator ID :	CAL000148027
Generator Name :	AUTOZONE #5723
Generator Address :	195 RANCHO SANTA FE RD, SAN MARCOS, CA 92069
Generator Mailing :	DEPT 8190, 123 S FRONT ST, MEMPHIS, TN 38103-3607
Generator Contact :	N/R
Destination ID :	AZR000521146
Destination Name :	YUMA YES 2 WASTE TRANSFER STATION
Destination Mailing :	2621 GREEN RIVER RD STE 105, CORONA, CA 92882

Map Id: C15
Direction: W
Distance: 0.094 mi., 498 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : AUTOZONE #5723
195 RANCHO SANTA FE RD | 195 S RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 437663
EPA ID: CAL000148027

MANIFEST EPA ***(cont.)***

Destination Address :	6500 S US HIGHWAY 95, YUMA, AZ 85365
Destination Contact :	N/R
Submission Type :	DataImage5Copy
Origin Type :	Service
Manifest Residue :	N
Rejection :	N
Last Date in Agency List :	2022-01-14

Waste Details

Waste Line Number :	1
Is DOT Hazardous :	N
DOT ID Number :	N/R
DOT Information :	N/R
Non Waste Description :	NON-RCRA HAZARDOUS WASTE, SOLID (OILY DEBRIS)
Quantity :	150 Pounds
Quantity Tons, Acute, Non-Acute :	0.075, 0, 0.075
Quantity Kg, Acute, Non-Acute :	0, 68.02725
Management Method :	H141 - STORAGE, BULKING AND/OR TRANSFER OFF SITE
Is EPA Waste :	N
Federal Code :	N/R
State Code :	CA - 352

Manifest Details

Manifest Number :	022490234JJK
Shipped Date :	2020-12-04
Updated Date :	2021-01-19
Received Date :	2020-12-14
Status :	Signed
Generator ID :	CAL000148027
Generator Name :	AUTOZONE #5723
Generator Address :	195 RANCHO SANTA FE RD, SAN MARCOS, CA 92069
Generator Mailing :	DEPT 8190, 123 S FRONT ST, MEMPHIS, TN 38103-3607
Generator Contact :	N/R
Destination ID :	AZR000521146
Destination Name :	YUMA YES 2 WASTE TRANSFER STATION
Destination Mailing :	2621 GREEN RIVER RD STE 105, CORONA, CA 92882
Destination Address :	6500 S US HIGHWAY 95, YUMA, AZ 85365
Destination Contact :	N/R
Submission Type :	DataImage5Copy
Origin Type :	Service
Manifest Residue :	N
Rejection :	N
Last Date in Agency List :	2022-01-14

Waste Details

Waste Line Number :	1
Is DOT Hazardous :	N
DOT ID Number :	N/R

Map Id: C15
Direction: W
Distance: 0.094 mi., 498 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : AUTOZONE #5723
195 RANCHO SANTA FE RD | 195 S RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 437663
EPA ID: CAL000148027

MANIFEST EPA ***(cont.)***

DOT Information :	N/R
Non Waste Description :	Non-RCRA Hazardous Waste, solid (oily debris)
Quantity :	150 Pounds
Quantity Tons, Acute, Non-Acute :	0.075, 0, 0.075
Quantity Kg, Acute, Non-Acute :	0, 68.02725
Management Method :	H141 - STORAGE, BULKING AND/OR TRANSFER OFF SITE
Is EPA Waste :	N
Federal Code :	N/R
State Code :	CA - 352

RCRA_NONGEN

Facility Name :	AUTOZONE #5723
Facility Address :	195 RANCHO SANTA FE RD, SAN MARCOS, CA 92069-0000
County :	SAN DIEGO
Date Form Received by Agency :	1999-01-08
EPA ID :	CAL000148027
Mailing Address :	DEPT 8190, 123 S FRONT ST, MEMPHIS, TN 38103-3607
Contact :	BRYAN BLAIR
Contact Address :	DEPT 8190, 123 SOUTH FRONT STREET, MEMPHIS, TN 38103
Contact Country :	N/R
Contact Telephone :	901-495-7217
Contact Email :	BRYAN.BLAIR@AUTOZONE.COM
EPA Region :	09
Land Type :	Not Reported
Source Type :	Implementer
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2022-01-26

Owner/Operator Summary

Owner/Operator Name :	AUTO ZONE CORPORTATION
Owner/Operator Address :	123 S FRONT ST, MEMPHIS, TN 38103-3607
Owner/Operator Country :	N/R
Owner/Operator Telephone :	901-495-6500
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R
Owner/Operator Name :	BRYAN BLAIR
Owner/Operator Address :	DEPT 8190, 123 SOUTH FRONT STREET, MEMPHIS, TN 38103
Owner/Operator Country :	N/R
Owner/Operator Telephone :	901-495-7217
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type

Map Id: C15
Direction: W
Distance: 0.094 mi., 498 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : AUTOZONE #5723
195 RANCHO SANTA FE RD | 195 S RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 437663
EPA ID: CAL000148027

RCRA_NONGEN ***(cont.)***

Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Notices of Violations Summary

Regulation Violated :	N

Map Id: D16
Direction: W
Distance: 0.097 mi., 515 ft.
Elevation: 622 ft.
Relative: Higher

Site Name : 1X MILLERS OUTPOST
155 RANCHO SANTA FE
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 41112051
EPA ID: CAC000301473

HAZNET - CA

Facility Name :	1X MILLERS OUTPOST
Facility Address :	155 RANCHO SANTA FE, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAC000301473
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY

Map Id: D16
Direction: W
Distance: 0.097 mi., 515 ft.
Elevation: 622 ft.
Relative: Higher

Site Name : 1X MILLERS OUTPOST
155 RANCHO SANTA FE
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 41112051
EPA ID: CAC000301473

HAZNET - CA ***(cont.)***

Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	--, ONTARIO, CA 917610000
Latitude :	33.15130929
Longitude :	-117.19756769
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HWG - CA

Facility Name :	1X MILLERS OUTPOST
Facility Address :	155 RANCHO SANTA FE, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAC000301473
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	ONTARIO, CA 917610000
Owner Name :	AMCENA CORPORATION
Owner Address :	N/A
Operator Name :	REGINA CROMWELL, PURCH. AGENT
Operator Address :	N/A
Latitude :	33.1513
Longitude :	-117.197687

Map Id: C17
Direction: WNW
Distance: 0.101 mi., 535 ft.
Elevation: 622 ft.
Relative: Higher

Site Name : TEXACO XPRESS LUBE #623
218 S SANTA FE RD
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 596738
EPA ID: CAL000127716

HAZNET - CA

Facility Name :	TEXACO XPRESS LUBE #623
Facility Address :	218 S SANTA FE RD, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000127716
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	138 ESCONDIDO AVE STE 203, VISTA, CA 920846044

Map Id: C17
Direction: WNW
Distance: 0.101 mi., 535 ft.
Elevation: 622 ft.
Relative: Higher

Site Name : TEXACO XPRESS LUBE #623
218 S SANTA FE RD
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 596738
EPA ID: CAL000127716

HAZNET - CA ***(cont.)***

Latitude :	33.15355087
Longitude :	-117.19579473
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :
1998: 135 - Unspecified aqueous solution, 2.184 tons to CAT080013352
1997: 135 - Unspecified aqueous solution, 3.024 tons to CAT080013352
1995: 135 - Unspecified aqueous solution, 3.024 tons to CAT080013352

HWG - CA

Facility Name :	TEXACO XPRESS LUBE #623
Facility Address :	218 S SANTA FE RD, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAL000127716
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	138 ESCONDIDO AVE STE 203, VISTA, CA 920846044
Owner Name :	COASTAL LUBES INC
Owner Address :	138 ESCONDIDO AVE STE 203, VISTA, CA 920846044
Operator Name :	ROBERT TAYLOR MGR
Operator Address :	INACTIVE PER VQ99 - BMI, SAN MARCOS, CA 920696044
Latitude :	33.161782
Longitude :	-117.205087

Map Id: D18
Direction: W
Distance: 0.102 mi., 537 ft.
Elevation: 623 ft.
Relative: Higher

Site Name : WESTERN DENTAL SERVICES INC
169 S RANCHO SANTA FE RD
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA]

Envirosite ID: 279214
EPA ID: N/R

ECHO

Facility Name :	WESTERN DENTAL SERVICES INC
Facility Address :	169 S RANCHO SANTA FE RD, SAN MARCOS, CA 92069
County :	SAN DIEGO
Last Inspection Date :	N/R
Registry ID :	110058253303
FIPS Code :	06073
EPA Region :	09
Inspection Count :	0

Map Id: D18
Direction: W
Distance: 0.102 mi., 537 ft.
Elevation: 623 ft.
Relative: Higher

Site Name : WESTERN DENTAL SERVICES INC
169 S RANCHO SANTA FE RD
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA] ***(cont.)***

Envirosite ID: 279214
EPA ID: N/R

ECHO ***(cont.)***

Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	_____
Collection Method :	ADDRESS MATCHING-HOUSE NUMBER
Reference Point :	CENTER OF A FACILITY OR STATION
Accuracy Meters :	30

Derived Tribes :

San Pasqual Band of Diegueno Mission Indians of California - 12.7 mile(s), Pala Band of Mission Indians - 13.5 mile (s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 14.3 mile(s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 16.5 mile(s), Pauma Band of Luiseno Mission Indians of the Pauma & Yuima Reservation, California - 17.2 mile(s), La Jolla Band of Luiseno Indians, California - 17.4 mile(s), Pechanga Band of Luiseno Mission Indians of the Pechanga Reservation, California - 20.7 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 22.6 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 23 mile(s), Mesa Grande Band of Diegueno Mission Indians of the Mesa Grande Reservation, California - 23.5 mile(s)

Derived HUC :	18070303
Derived WBD :	180703030503
Derived STCTY FIPS :	06073
Derived Zip :	92078
Derived CD113 :	50
Derived CB2010 :	060730200291006
MYRTK Universe :	NNN
NPDES IDs :	N/R
CWA Permit Types :	N/R
CWA Compliance Tracking :	N/R
CWA NAICS :	N/R
CWA SICS :	N/R
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	N/R
CWA Current Compliance Status :	N/R
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	N/R
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.

Map Id: D18
Direction: W
Distance: 0.102 mi., 537 ft.
Elevation: 623 ft.
Relative: Higher

Site Name : WESTERN DENTAL SERVICES INC
169 S RANCHO SANTA FE RD
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA] ***(cont.)***

Envirosite ID: 279214
EPA ID: N/R

ECHO ***(cont.)***

Facility SIC :	N/R
Facility NAICS :	56299 - All Other Waste Management Services
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	Y
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	N
SDWIS Flag :	N
RCRA Flag :	Y
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	Y
NAA Flag :	Y
Latitude :	33.14659
Longitude :	-117.19935
Last Date in Agency List :	2022-01-17

FRS

Facility Name :	WESTERN DENTAL SERVICES INC
Facility Address :	169 S RANCHO SANTA FE RD, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Registry ID :	110058253303
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Source Description

Source Description : The California Environmental Reporting System (CERS) is a statewide web-based user and information exchange system to support over 140,000 regulated businesses and over 130 local agencies in electronically collecting and reporting significant hazardous materials, hazardous waste and compliance and enforcement data as mandated by California law. Under oversight by Cal/EPA, certified local governing agencies (Unified Program Agencies - UPAs) consolidate, coordinate and provide consistent regulatory activities for six state and federal environmental programs.

Map Id: D18
Direction: W
Distance: 0.102 mi., 537 ft.
Elevation: 623 ft.
Relative: Higher

Site Name : WESTERN DENTAL SERVICES INC
169 S RANCHO SANTA FE RD
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA] ***(cont.)***

Envirosite ID: 279214
EPA ID: N/R

FRS ***(cont.)***

The California Environmental Protection Agency (CalEPA) has recently implemented a new data warehouse system (nSite). This data warehouse combines and merges facility and site information from five different systems managed within CalEPA. The five systems are: California Environmental Reporting System (CERS), EnviroStor, GeoTracker, California Integrated Water Quality System (CIWQS), and Toxic Release Inventory (TRI).

Source Description :

RCRAInfo is EPA's comprehensive information system that supports the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984 through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA. RCRAInfo also supports generation of the National Hazardous Waste Biennial Report. All generators and treatment, storage, and disposal facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years to support creation of the Biennial Report.

FRS Environmental Interest

Source and System ID :	CA-CERS - 10376590 CA-ENVIROVIEW - 171272 RCRAINFO - CAL000371968

HAZMAT_SAN DIEGO COUNTY - CA

Facility Name :	WESTERN DENTAL SERVICES, INC
Facility Address :	169 S RANCHO SANTA FE RD, SAN MARCOS, CA 92069
Date :	2011-11-21
Record ID :	DEH2011-HUPFP-215763
Record Type :	Unified Program Facility Permit
Status :	Permit Renewed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23

Map Id: C19
Direction: WNW
Distance: 0.102 mi., 539 ft.
Elevation: 622 ft.
Relative: Higher

Site Name : JIFFY LUBE #1967 | TEAM CAR CARE WEST LLC DBA JIFFY LUBE | CASEY'S CAR WASH
218 S RANCHO SANTA FE RD | 218 SOUTH RANCHO SANTA FE ROAD | LOT SOUTH OF 218 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA

Database(s) : [AST - CA, CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AST - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN, SWRCY - CA]

Envirosite ID: 461082
EPA ID: CAL000329923

AST - CA

Facility Name :	JIFFY LUBE #1967
Facility Address :	218 S RANCHO SANTA FE RD, SAN MARCOS, CA 92069
County :	San Diego County
Site ID :	126059
Facility Identifer :	37-000-203570
EPA Identifier :	CAL000438389
Facility Explorer ID :	126059
Dun and Bradsheet Number :	834872400
Regulatory Programs :	Hazardous Waste Generator, Chemical Storage Facilities, Aboveground Petroleum Storage
SIC :	7549 Automotive services, n.e.c.
NAICS :	811191 Automotive Oil Change and Lubrication Shops
Latitude :	33.145530
Longitude :	-117.201210
Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-12-22

Violations

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Violation Date :	2018-11-02
Citation :	HSC 6.5 Multiple - California Health and Safety Code, Chapter 6.5, Section(s) Multiple
Description :	Hazardous Waste Generator Program - Administration/Documentation - General
Notes :	Returned to compliance on 12/18/2018. Inspection Sequence ID: 6092820;Violation:HMD0131 Unified Program Facility Permit not obtained &/or maintained for the generation of hazardous waste. SDCC 68.905
Division :	San Diego County Department of Env Health
Program :	HW
Source :	CERS

Map Id: C19
Direction: WNW
Distance: 0.102 mi., 539 ft.
Elevation: 622 ft.
Relative: Higher

Site Name : JIFFY LUBE #1967 | TEAM CAR CARE WEST LLC DBA JIFFY LUBE | CASEY'S CAR WASH
218 S RANCHO SANTA FE RD | 218 SOUTH RANCHO SANTA FE ROAD | LOT SOUTH OF 218 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA

Database(s) : [AST - CA, CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AST - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN, SWRCY - CA] ***(cont.)***

Envirosite ID: 461082
EPA ID: CAL000329923

AST - CA ***(cont.)***

Violation Date : 2018-11-02

Citation : HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)

Description : Failure to complete and electronically submit a business plan when storing/handling a hazardous material at or above reportable quantities.

Notes : Returned to compliance on 03/23/2019. Inspection Sequence ID:6092820
Division : San Diego County Department of Env Health
Program : HMRRP
Source : CERS

Violation Date : 2018-11-02

Citation : HSC 6.95 Multiple - California Health and Safety Code, Chapter 6.95, Section(s) Multiple

Description : Business Plan Program - Administration/Documentation - General

Notes : Returned to compliance on 12/18/2018. Inspection Sequence ID: 6092820;Violation:HMD1001 Unified Program Facility permit not obtained for hazardous materials. SDCC 68.905; 68.906, 68.907

Division : San Diego County Department of Env Health
Program : HMRRP
Source : CERS

Violation Date : 2018-11-02

Citation : 22 CCR 15 66265.192(a) - California Code of Regulations, Title 22, Chapter 15, Section(s) 66265.192(a)

Description :

Failure to obtain and maintain a written assessment reviewed and certified by an independent, qualified, professional engineer prior to placing the tank system in service. The written assessment shall state that, the new hazardous waste tank system has sufficient structural integrity, is acceptable for the transferring, storing and treating of hazardous waste, and that the tanks and containment system including the foundation, structural support, seams, connections, and pressure controls (if applicable) are suitably designed to meet the regulation.

Notes : Returned to compliance on 03/29/2019. Inspection Sequence ID:6092820
Division : San Diego County Department of Env Health
Program : HW

Map Id: C19
Direction: WNW
Distance: 0.102 mi., 539 ft.
Elevation: 622 ft.
Relative: Higher

Site Name : JIFFY LUBE #1967 | TEAM CAR CARE WEST LLC DBA JIFFY LUBE | CASEY'S CAR WASH
218 S RANCHO SANTA FE RD | 218 SOUTH RANCHO SANTA FE ROAD | LOT SOUTH OF 218 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA

Database(s) : [AST - CA, CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AST - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN, SWRCY - CA] ***(cont.)***

Envirosite ID: 461082
EPA ID: CAL000329923

AST - CA ***(cont.)***

Source :	CERS
Violation Date :	2017-02-21
Citation :	HSC 6.95 25508(a)(1) - California Health and Safety Code, Chapter 6.95, Section(s) 25508(a)(1)
Description :	Failure to complete and electronically submit a site map with all required content.
Notes :	Returned to compliance on 03/07/2017.
Division :	San Diego County Department of Env Health
Program :	HMRRP
Source :	CERS

Enforcements

Enforcement Action Date :	N/R
Type :	N/R
Description :	N/R
Notes :	N/R
Division :	N/R
Program :	N/R
Source :	N/R

Chemicals

Chemical Name :	ETHYLENE GLYCOL
CAS Number :	107-21-1
Hazard Type(s) :	-
Max Daily Amount / Unit :	120-599 Gallons
Average Daily Amount / Unit :	120-599 Gallons
Days Onsite :	365
Physical State(s) :	Liquid, Pure

Chemical Name :	Gear Lube
CAS Number :	N/R
Hazard Type(s) :	-
Max Daily Amount / Unit :	120-599 Gallons
Average Daily Amount / Unit :	60-119 Gallons
Days Onsite :	365
Physical State(s) :	Liquid, Pure

Map Id: C19
Direction: WNW
Distance: 0.102 mi., 539 ft.
Elevation: 622 ft.
Relative: Higher

Site Name : JIFFY LUBE #1967 | TEAM CAR CARE WEST LLC DBA JIFFY LUBE | CASEY'S CAR WASH
218 S RANCHO SANTA FE RD | 218 SOUTH RANCHO SANTA FE ROAD | LOT SOUTH OF 218 S RANCHO SANTA FE RD SAN MARCOS | San Marcos, CA

Database(s) : [AST - CA, CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AST - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN, SWRCY - CA] ***(cont.)***

Envirosite ID: 461082
EPA ID: CAL000329923

AST - CA ***(cont.)***

Chemical Name : Metal Oil Filters
CAS Number : N/R
Hazard Type(s) : -
Max Daily Amount / Unit : 60-119 Gallons
Average Daily Amount / Unit : 12-59 Gallons
Days Onsite : 0
Physical State(s) : Solid

Chemical Name : New Motor Oil
CAS Number : 8002-05-9
Hazard Type(s) : -
Max Daily Amount / Unit : 1200-2999 Gallons
Average Daily Amount / Unit : 1200-2999 Gallons
Days Onsite : 365
Physical State(s) : Liquid, Pure

Chemical Name : Non-Metal Oil Filiters
CAS Number : N/R
Hazard Type(s) : -
Max Daily Amount / Unit : 100-499 Pounds
Average Daily Amount / Unit : 0-99 Pounds
Days Onsite : 365
Physical State(s) : Solid

Chemical Name : Oily Debris
CAS Number : N/R
Hazard Type(s) : -
Max Daily Amount / Unit : 0-99 Pounds
Average Daily Amount / Unit : 0-99 Pounds
Days Onsite : 365
Physical State(s) : Solid

Chemical Name : Oily Water
CAS Number : N/R
Hazard Type(s) : -
Max Daily Amount / Unit : 120-599 Gallons
Average Daily Amount / Unit : 120-599 Gallons
Days Onsite : 365
Physical State(s) : Liquid

Chemical Name : TRUE BLUE WINDSHIELD WASHER FLUID
CAS Number : 1336-21-6
Hazard Type(s) : -

Map Id: C19
Direction: WNW
Distance: 0.102 mi., 539 ft.
Elevation: 622 ft.
Relative: Higher

Site Name : JIFFY LUBE #1967 | TEAM CAR CARE WEST LLC DBA JIFFY LUBE | CASEY'S CAR WASH
218 S RANCHO SANTA FE RD | 218 SOUTH RANCHO SANTA FE ROAD | LOT SOUTH OF 218 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA

Database(s) : [AST - CA, CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AST - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN, SWRCY - CA] ***(cont.)***

Envirosite ID: 461082
EPA ID: CAL000329923

AST - CA ***(cont.)***

Max Daily Amount / Unit :	12-59 Gallons
Average Daily Amount / Unit :	12-59 Gallons
Days Onsite :	365
Physical State(s) :	Liquid, Pure

Chemical Name :	Transmission Fluid
CAS Number :	N/R
Hazard Type(s) :	-
Max Daily Amount / Unit :	120-599 Gallons
Average Daily Amount / Unit :	60-119 Gallons
Days Onsite :	365
Physical State(s) :	Liquid, Mix

Chemical Name :	WASTE 135 UNSPECIFIED AQUEOUS SOL'N
CAS Number :	N/R
Hazard Type(s) :	-
Max Daily Amount / Unit :	120-599 Gallons
Average Daily Amount / Unit :	0-11 Gallons
Days Onsite :	365
Physical State(s) :	Liquid

CALEPA SITES - CA

Facility Name :	JIFFY LUBE #1967
Facility Address :	218 S RANCHO SANTA FE RD, SAN MARCOS, 92069

Site ID :	126059
EI ID :	10376089
EI Description :	Aboveground Petroleum Storage
Latitude :	33.145530
Longitude :	-117.201210
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07

Site ID :	126059
EI ID :	10376089
EI Description :	Chemical Storage Facilities
Latitude :	33.145530
Longitude :	-117.201210
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07

Map Id: C19
Direction: WNW
Distance: 0.102 mi., 539 ft.
Elevation: 622 ft.
Relative: Higher

Site Name : JIFFY LUBE #1967 | TEAM CAR CARE WEST LLC DBA JIFFY LUBE | CASEY'S CAR WASH
218 S RANCHO SANTA FE RD | 218 SOUTH RANCHO SANTA FE ROAD | LOT SOUTH OF 218 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA

Database(s) : [AST - CA, CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AST - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN, SWRCY - CA] ***(cont.)***

Envirosite ID: 461082
EPA ID: CAL000329923

CALEPA SITES - CA ***(cont.)***

Site ID :	126059
EI ID :	10376089
EI Description :	Hazardous Waste Generator
Latitude :	33.145530
Longitude :	-117.201210
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07

CIWQS - CA

Facility Name :	SAN CLEMENTE AUTO
Facility Address :	LOT SOUTH OF 218 S RANCHO SANTA FE RD, SAN MARCOS, CA 92069
County :	SAN DIEGO
Place ID :	S626008
Agency Name :	BILL & JOE LAUER
Last Date in Agency List :	2021-12-30

ECHO

Facility Name :	TEAM CAR CARE WEST LLC DBA JIFFY LUBE
Facility Address :	218 S RANCHO SANTA FE RD, SAN MARCOS, CA 92069
County :	SAN DIEGO
Last Inspection Date :	N/R
Registry ID :	110070486565
FIPS Code :	N/R
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	_____
Collection Method :	Zip Code Centroid
Reference Point :	N/R
Accuracy Meters :	10000
Derived Tribes :	N/R

Map Id: C19
Direction: WNW
Distance: 0.102 mi., 539 ft.
Elevation: 622 ft.
Relative: Higher

Site Name : JIFFY LUBE #1967 | TEAM CAR CARE WEST LLC DBA JIFFY LUBE | CASEY'S CAR WASH
218 S RANCHO SANTA FE RD | 218 SOUTH RANCHO SANTA FE ROAD | LOT SOUTH OF 218 S RANCHO SANTA FE RD SAN MARCOS | San Marcos, CA

Database(s) : [AST - CA, CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AST - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN, SWRCY - CA] ***(cont.)***

Envirosite ID: 461082
EPA ID: CAL000329923

ECHO ***(cont.)***

Derived HUC :	N/R
Derived WBD :	N/R
Derived STCTY FIPS :	N/R
Derived Zip :	N/R
Derived CD113 :	N/R
Derived CB2010 :	N/R
MYRTK Universe :	NNN
NPDES IDs :	N/R
CWA Permit Types :	N/R
CWA Compliance Tracking :	N/R
CWA NAICS :	N/R
CWA SICS :	N/R
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	N/R
CWA Current Compliance Status :	N/R
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	N/R
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	N/R
Facility NAICS :	811198 - All Other Automotive Repair and Maintenance
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	N/R
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	N
SDWIS Flag :	N
RCRA Flag :	Y
TRI Flag :	N

Map Id: C19
Direction: WNW
Distance: 0.102 mi., 539 ft.
Elevation: 622 ft.
Relative: Higher

Site Name : JIFFY LUBE #1967 | TEAM CAR CARE WEST LLC DBA JIFFY LUBE | CASEY'S CAR WASH
218 S RANCHO SANTA FE RD | 218 SOUTH RANCHO SANTA FE ROAD | LOT SOUTH OF 218 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA

Database(s) : [AST - CA, CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AST - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN, SWRCY - CA] ***(cont.)***

Envirosite ID: 461082
EPA ID: CAL000329923

ECHO ***(cont.)***

GHG Flag :	N
Major Flag :	N/R
Active Flag :	Y
NAA Flag :	N
Latitude :	33.194075
Longitude :	-117.16177
Last Date in Agency List :	2022-01-17

FRS

Facility Name :	JIFFY LUBE #1967
Facility Address :	218 S RANCHO SANTA FE RD, SAN MARCOS, CA 92078-
County :	SAN DIEGO

Site Details

Registry ID :	110033212672
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Source Description

Source Description :

The California Environmental Reporting System (CERS) is a statewide web-based user and information exchange system to support over 140,000 regulated businesses and over 130 local agencies in electronically collecting and reporting significant hazardous materials, hazardous waste and compliance and enforcement data as mandated by California law. Under oversight by Cal/EPA, certified local governing agencies (Unified Program Agencies - UPAs) consolidate, coordinate and provide consistent regulatory activities for six state and federal environmental programs.
The California Environmental Protection Agency (CalEPA) has recently implemented a new data warehouse system (nSite). This data warehouse combines and merges facility and site information from five different systems managed within CalEPA. The five systems are: California Environmental Reporting System (CERS), EnviroStor, GeoTracker, California Integrated Water Quality System (CIWQS), and Toxic Release Inventory (TRI).
The UORS is managed by the California Waste Management Board (CIWMB). The CIWMB helps communities establish and promote convenient collection opportunities for used oil and used oil filters.

Map Id: C19
Direction: WNW
Distance: 0.102 mi., 539 ft.
Elevation: 622 ft.
Relative: Higher

Site Name : JIFFY LUBE #1967 | TEAM CAR CARE WEST LLC DBA JIFFY LUBE | CASEY'S CAR WASH
218 S RANCHO SANTA FE RD | 218 SOUTH RANCHO SANTA FE ROAD | LOT SOUTH OF 218 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA

Database(s) : [AST - CA, CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AST - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN, SWRCY - CA] ***(cont.)***

Envirosite ID: 461082
EPA ID: CAL000329923

FRS ***(cont.)***

FRS Environmental Interest
Source and System ID : CA-CERS - 10376089
CA-ENVIROVIEW - 126059
CERTIFICATION APPLICATION - 37-C-06604

Facility Name : TEAM CAR CARE WEST LLC DBA JIFFY LUBE
Facility Address : 218 S RANCHO SANTA FE RD, SAN MARCOS, CA 92069-2302
County : SAN DIEGO

Site Details
Registry ID : 110070486565
FRS Facility URL : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-02-17

Source Description

Source Description :

RCRAInfo is EPA's comprehensive information system that supports the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984 through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA. RCRAInfo also supports generation of the National Hazardous Waste Biennial Report. All generators and treatment, storage, and disposal facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years to support creation of the Biennial Report.

FRS Environmental Interest
Source and System ID : RCRAINFO - CAL000438389

HAZMAT_SAN DIEGO COUNTY - CA

Facility Name : JIFFY LUBE #1967
Facility Address : 218 S RANCHO SANTA FE RD, SAN MARCOS, CA 92069

Date : 2004-06-02
Record ID : DEH2004-HUPFP-203570
Record Type : Unified Program Facility Permit
Status : Permit Renewed
Action : N/R
Short Notes : N/R

Map Id: C19
Direction: WNW
Distance: 0.102 mi., 539 ft.
Elevation: 622 ft.
Relative: Higher

Site Name : JIFFY LUBE #1967 | TEAM CAR CARE WEST LLC DBA JIFFY LUBE | CASEY'S CAR WASH
218 S RANCHO SANTA FE RD | 218 SOUTH RANCHO SANTA FE ROAD | LOT SOUTH OF 218 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA

Database(s) : [AST - CA, CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AST - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN, SWRCY - CA] ***(cont.)***

Envirosite ID: 461082
EPA ID: CAL000329923

HAZMAT_SAN DIEGO COUNTY - CA ***(cont.)***

Last Date in Agency List : 2015-11-23

HAZNET - CA

Facility Name : CASEY'S CAR WASH
Facility Address : 218 S RANCHO SANTA FE RD, SAN MARCOS, CA 92078
County : SAN DIEGO

Site Details
Generator EPA ID : CAL000329923
Active : Inactive
Category : STATE
Facility Types : N/R
Type : PERMANENT
Contact Name : N/R
Contact Phone : N/R
Facility Mailing Address : 218 S RANCHO SANTA FE RD, SAN MARCOS, CA 920782302
Latitude : 33.14526794
Longitude : -117.20089422
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2021-07-08

Waste Generator Details
State Waste : 2008: 222 - Oil/water separation sludge, 10.008 tons to CAT080013352

Facility Name : GREASE MONKEY
Facility Address : 218 S RANCHO SANTA FE ROAD, SAN MARCOS, CA 92069
County : SAN DIEGO

Site Details
Generator EPA ID : CAL000035909
Active : Inactive
Category : STATE
Facility Types : N/R
Type : PERMANENT
Contact Name : N/R
Contact Phone : N/R
Facility Mailing Address : 218 S RANCHO SANTA FE ROAD, SAN MARCOS, CA 920690000
Latitude : 33.14526794
Longitude : -117.20089422
Agency Hyperlink : Click here for hyperlink provided by the agency.

Map Id: C19
Direction: WNW
Distance: 0.102 mi., 539 ft.
Elevation: 622 ft.
Relative: Higher

Site Name : JIFFY LUBE #1967 | TEAM CAR CARE WEST LLC DBA JIFFY LUBE | CASEY'S CAR WASH
218 S RANCHO SANTA FE RD | 218 SOUTH RANCHO SANTA FE ROAD | LOT SOUTH OF 218 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA

Database(s) : [AST - CA, CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AST - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN, SWRCY - CA] ***(cont.)***

Envirosite ID: 461082
EPA ID: CAL000329923

HAZNET - CA ***(cont.)***

Last Date in Agency List : 2021-07-08

Facility Name : GREASE MONKEY OF SAN MARCOS
Facility Address : 218 SOUTH RANCHO SANTA FE ROAD, SAN MARCOS, CA 92069
County : SAN DIEGO

Site Details
Generator EPA ID : CAL912244799
Active : Inactive
Category : STATE
Facility Types : N/R
Type : PERMANENT
Contact Name : N/R
Contact Phone : N/R
Facility Mailing Address : 218 SOUTH RANCHO SANTA FE ROAD, SAN MARCOS, CA 920690000
Latitude : 33.14556000
Longitude : -117.20119950
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2021-07-08

Waste Generator Details
State Waste : 1994: 221 - Waste oil and mixed oil, 7.6 tons to CAT080013352

Facility Name : JIFFY LUBE #1967
Facility Address : 218 S RANCHO SANTA FE RD, SAN MARCOS, CA 92078
County : SAN DIEGO

Site Details
Generator EPA ID : CAL000181260
Active : Inactive
Category : STATE
Facility Types : N/R
Type : PERMANENT
Contact Name : N/R
Contact Phone : N/R
Facility Mailing Address : 15 VISTA SOLE, DANA POINT, CA 92629
Latitude : 33.14526794
Longitude : -117.20089422
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2021-07-08

Map Id: C19
Direction: WNW
Distance: 0.102 mi., 539 ft.
Elevation: 622 ft.
Relative: Higher

Site Name : JIFFY LUBE #1967 | TEAM CAR CARE WEST LLC DBA JIFFY LUBE | CASEY'S CAR WASH
218 S RANCHO SANTA FE RD | 218 SOUTH RANCHO SANTA FE ROAD | LOT SOUTH OF 218 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA

Database(s) : [AST - CA, CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AST - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN, SWRCY - CA] ***(cont.)***

Envirosite ID: 461082
EPA ID: CAL000329923

HAZNET - CA ***(cont.)***

Waste Generator Details
State Waste :
2005: 221 - Waste oil and mixed oil, 9.12 tons to CAD981696420
2004: 352 - Other organic solids, 0.1 tons to CAD008252405
2003: 352 - Other organic solids, 0.1 tons to CAD980884183
2003: 352 - Other organic solids, 0.05 tons to CAD008252405
2000: 134 - Aqueous solution with total organic residues less than 10 percent, 3.843 tons to CAD981696420
1999: 134 - Aqueous solution with total organic residues less than 10 percent, 1.806 tons to CAD981696420
1998: 134 - Aqueous solution with total organic residues less than 10 percent, 1.092 tons to CAD981696420

Site Details

Generator EPA ID :	CAL000282877
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	105 DECKER CT STE 900, IRVING, TX 750620000
Latitude :	33.14526794
Longitude :	-117.20089422
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details
State Waste :
2018: 352 - Other organic solids, 0.02000 tons to AZR000515924
2018: 352 - Other organic solids, 0.20000 tons to CAD097030993
2017: 352 - Other organic solids, 0.1075 tons to AZR000515924
2017: 222 - Oil/water separation sludge, 10.008 tons to CAT080013352
2017: 223 - Unspecified oil-containing waste, 10.0497 tons to CAT080013352
2017: 352 - Other organic solids, 0.3 tons to CAD097030993
2016: 352 - Other organic solids, 0.04 tons to AZR000515924
2016: 352 - Other organic solids, 0.0505 tons to CAD097030993
2015: 352 - Other organic solids, 0.075 tons to CAD097030993
2014: 352 - Other organic solids, 0.0625 tons to CAD097030993
2011: 222 - Oil/water separation sludge, 1.56375 tons to CAT080013352
2010: 222 - Oil/water separation sludge, 2.502 tons to CAT080013352
2010: 223 - Unspecified oil-containing waste, 4.35765 tons to CAT080013352
2008: 135 - Unspecified aqueous solution, 0.924 tons to CAT080013352
2007: 222 - Oil/water separation sludge, 7.506 tons to CAT080013352

Map Id: C19
Direction: WNW
Distance: 0.102 mi., 539 ft.
Elevation: 622 ft.
Relative: Higher

Site Name : JIFFY LUBE #1967 | TEAM CAR CARE WEST LLC DBA JIFFY LUBE | CASEY'S CAR WASH
218 S RANCHO SANTA FE RD | 218 SOUTH RANCHO SANTA FE ROAD | LOT SOUTH OF 218 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA

Database(s) : [AST - CA, CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AST - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN, SWRCY - CA] ***(cont.)***

Envirosite ID: 461082
EPA ID: CAL000329923

HAZNET - CA ***(cont.)***

2006: 222 - Oil/water separation sludge, 9.591 tons to CAT080013352
2005: 221 - Waste oil and mixed oil, 9.5 tons to CAD981696420
2005: 223 - Unspecified oil-containing waste, 6.255 tons to CAD981696420

Facility Name : TEAM CAR CARE WEST LLC DBA JIFFY LUBE
Facility Address : 218 S RANCHO SANTA FE RD, SAN MARCOS, CA 92069
County : SAN DIEGO

Site Details
Generator EPA ID : CAL000438389
Active : Active
Category : STATE
Facility Types : N/R
Type : PERMANENT
Contact Name : N/R
Contact Phone : N/R
Facility Mailing Address : 105 DECKER CT STE 900, IRVING, TX 750620000
Latitude : 33.14556000
Longitude : -117.20119950
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2021-07-08

Waste Generator Details
State Waste :
2019: 223 - Unspecified oil-containing waste, 0.15750 tons to CAD044429835
2019: 352 - Other organic solids, 0.06250 tons to CAD044429835
2018: 352 - Other organic solids, 0.10000 tons to CAD097030993
2018: 223 - Unspecified oil-containing waste, 0.07500 tons to CAD044429835

HIST AST - CA

Facility Name : JIFFY LUBE #1967
Facility Address : 218 S RANCHO SANTA FE RD, SAN MARCOS, CA 92069
County : San Diego

Site Details
CERS ID : 10376089
Facility ID : 37-000-203570
EPA ID : CAL000282877

Map Id: C19
Direction: WNW
Distance: 0.102 mi., 539 ft.
Elevation: 622 ft.
Relative: Higher

Site Name : JIFFY LUBE #1967 | TEAM CAR CARE WEST LLC DBA JIFFY LUBE | CASEY'S CAR WASH
218 S RANCHO SANTA FE RD | 218 SOUTH RANCHO SANTA FE ROAD | LOT SOUTH OF 218 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA

Database(s) : [AST - CA, CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AST - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN, SWRCY - CA] ***(cont.)***

Envirosite ID: 461082
EPA ID: CAL000329923

HIST AST - CA ***(cont.)***

Business Name :	Heartland Group
Phone :	760-727-9785
Fax :	N/R
Mailing Address :	105 DECKER CT #900, IRVING, TX 75062
Owner Name :	Heartland Automotive Services, Inc. II
Owner Phone :	9728127900
Owner Mailing Address :	105 DECKER CT 900, IRVING, TX 75062
Property Owner Name :	SOUTHERN CALIFORNIA LUBE CENTER
Property Owner Phone :	9728127900
Property Owner Mailing Address :	105 DECKER CT 900, IRVING, TX 75062
Operator Name :	HEARTLAND AUTOMOTIVE SVCS II INC
Operator Phone :	9728127900
CUPA :	N/R
Total Gallons :	N/R
Facility Latitude Measure :	33.14553
Facility Longitude Measure :	-117.20121
Last Date in Agency List :	2018-01-31

HWG - CA

Facility Name :	CASEY'S CAR WASH
Facility Address :	218 S RANCHO SANTA FE RD, SAN MARCOS, CA 92078
County :	SAN DIEGO
EPA ID :	CAL000329923
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	218 S RANCHO SANTA FE RD, SAN MARCOS, CA 920782302
Owner Name :	MCCREERY & HOFFMAN CORP LLC
Owner Address :	455 E 5TH AVE, ESCONDIDO, CA 920254310
Operator Name :	JAME MCCREERY
Operator Address :	455 E 5TH AVE, ESCONDIDO, CA 920254310
Latitude :	33.14542
Longitude :	-117.200739
Facility Name :	GREASE MONKEY
Facility Address :	218 S RANCHO SANTA FE ROAD, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAL000035909
Status :	Inactive
Category :	STATE
Type :	PERMANENT

Map Id: C19
Direction: WNW
Distance: 0.102 mi., 539 ft.
Elevation: 622 ft.
Relative: Higher

Site Name : JIFFY LUBE #1967 | TEAM CAR CARE WEST LLC DBA JIFFY LUBE | CASEY'S CAR WASH
218 S RANCHO SANTA FE RD | 218 SOUTH RANCHO SANTA FE ROAD | LOT SOUTH OF 218 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA

Database(s) : [AST - CA, CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AST - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN, SWRCY - CA] ***(cont.)***

Envirosite ID: 461082
EPA ID: CAL000329923

HWG - CA ***(cont.)***

Facility Type :	N/R
Mailing Address :	218 S RANCHO SANTA FE ROAD, SAN MARCOS, CA 920690000
Owner Name :	LUBRECHAUN OF ESCONDI
Owner Address :	N/A
Operator Name :	INACTIVE PER SURVEY 1/95 HN
Operator Address :	N/A
Latitude :	33.145421
Longitude :	-117.200658

Facility Name :	GREASE MONKEY OF SAN MARCOS
Facility Address :	218 SOUTH RANCHO SANTA FE ROAD, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAL912244799
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	218 SOUTH RANCHO SANTA FE ROAD, SAN MARCOS, CA 920690000
Owner Name :	DICK W. MCCAULEY
Owner Address :	98-1827C KAAHUMANU, ALEA, HA 697010000
Operator Name :	INACTIVE PER SURVEY 1/95 HN
Operator Address :	N/A
Latitude :	33.145421
Longitude :	-117.200658

Facility Name :	JIFFY LUBE #1967
Facility Address :	218 S RANCHO SANTA FE RD, SAN MARCOS, CA 92078
County :	SAN DIEGO

EPA ID :	CAL000282877
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	105 DECKER CT STE 900, IRVING, TX 750620000
Owner Name :	HEARTLAND AUTOMOTIVE SVCS INC
Owner Address :	105 DECKER CT STE 900, IRVING, TX 750620000
Operator Name :	JAMES WILLIS
Operator Address :	105 DECKER COURT SUITE 900, IRVING, TX 75062
Latitude :	33.145459
Longitude :	-117.200849

Map Id: C19
Direction: WNW
Distance: 0.102 mi., 539 ft.
Elevation: 622 ft.
Relative: Higher

Site Name : JIFFY LUBE #1967 | TEAM CAR CARE WEST LLC DBA JIFFY LUBE | CASEY'S CAR WASH
218 S RANCHO SANTA FE RD | 218 SOUTH RANCHO SANTA FE ROAD | LOT SOUTH OF 218 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA

Database(s) : [AST - CA, CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AST - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN, SWRCY - CA] ***(cont.)***

Envirosite ID: 461082
EPA ID: CAL000329923

HWG - CA ***(cont.)***

EPA ID :	CAL000181260
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	15 VISTA SOLE, DANA POINT, CA 92629
Owner Name :	RICHARD & LINDA HYNAN
Owner Address :	5790 MIRAMAR RD - STE 211, SAN DIEGO, CA 921210000
Operator Name :	LYNDA HYNAN
Operator Address :	15 VISTA SOLE, DANA POINT, CA 92629
Latitude :	33.14542
Longitude :	-117.200739

Facility Name :	TEAM CAR CARE WEST LLC DBA JIFFY LUBE
Facility Address :	218 S RANCHO SANTA FE RD, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAL000438389
Status :	Active
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	105 DECKER CT STE 900, IRVING, TX 750620000
Owner Name :	TEAM CAR CARE W LLC DBA JIFFY LUBE
Owner Address :	105 DECKER CT STE 900, IRVING, TX 750620000
Operator Name :	LILLIAN NICHOLSON
Operator Address :	105 DECKER COURT SUITE 900, IRVING, TX 75062
Latitude :	33.14556
Longitude :	-117.2012

MANIFEST EPA

Manifest Details

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Manifest Number :	008052991SKS
Shipped Date :	2021-07-01
Updated Date :	2021-08-17
Received Date :	2021-07-21
Status :	Signed
Generator ID :	CAL000438389
Generator Name :	Team Car Care Jiffy Lube 1967
Generator Address :	218 S RANCHO SANTA FE RD, SAN MARCOS, CA 92069

Map Id: C19
Direction: WNW
Distance: 0.102 mi., 539 ft.
Elevation: 622 ft.
Relative: Higher

Site Name : JIFFY LUBE #1967 | TEAM CAR CARE WEST LLC DBA JIFFY LUBE | CASEY'S CAR WASH
218 S RANCHO SANTA FE RD | 218 SOUTH RANCHO SANTA FE ROAD | LOT SOUTH OF 218 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA

Database(s) : [AST - CA, CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AST - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN, SWRCY - CA] ***(cont.)***

Envirosite ID: 461082
EPA ID: CAL000329923

MANIFEST EPA ***(cont.)***

Generator Mailing :	218 S RANCHO SANTA FE RD, San Marcos, CA 92069
Generator Contact :	Team Car Care Jiffy Lube 1967
Destination ID :	UTD991301748
Destination Name :	Clean Harbors Grassy Mountain LLC
Destination Mailing :	PO Box 22750, Salt Lake City, UT 84122
Destination Address :	3 Miles East 7 Miles North of Knolls Exit 41 off I-80, Grantsville, UT 84029
Destination Contact :	N/R
Submission Type :	DataImage5Copy
Origin Type :	Service
Manifest Residue :	N
Rejection :	N
Last Date in Agency List :	2022-01-14

Waste Details

Waste Line Number :	1
Is DOT Hazardous :	N
DOT ID Number :	N/R
DOT Information :	N/R
Non Waste Description :	NONE, NON-RCRA HAZARDOUS WASTE, SOLID) USED OIL FILTERS CONTAINING USED OI (DRAINED AND UNDRAINED OIL FILTERS), N/A, NONE
Quantity :	100 Pounds
Quantity Tons, Acute, Non-Acute :	0.05, 0, 0.05
Quantity Kg, Acute, Non-Acute :	0, 45.3515
Management Method :	H132 - LANDFILL (WITH PRIOR TREATMENT AND/OR STABILIZATION)
Is EPA Waste :	N
Federal Code :	N/R
State Code :	CA - 223

Manifest Details

Manifest Number :	007623044SKS
Shipped Date :	2021-05-18
Updated Date :	2021-06-22
Received Date :	2021-05-24
Status :	Signed
Generator ID :	CAL000438389
Generator Name :	Team Car Care Jiffy Lube 1967
Generator Address :	218 S RANCHO SANTA FE RD, SAN MARCOS, CA 92069
Generator Mailing :	218 S RANCHO SANTA FE RD, San Marcos, CA 92069
Generator Contact :	Team Car Care Jiffy Lube 1967
Destination ID :	UTD991301748
Destination Name :	Clean Harbors Grassy Mountain LLC

Map Id: C19
Direction: WNW
Distance: 0.102 mi., 539 ft.
Elevation: 622 ft.
Relative: Higher

Site Name : JIFFY LUBE #1967 | TEAM CAR CARE WEST LLC DBA JIFFY LUBE | CASEY'S CAR WASH
218 S RANCHO SANTA FE RD | 218 SOUTH RANCHO SANTA FE ROAD | LOT SOUTH OF 218 S RANCHO SANTA FE RD SAN MARCOS | San Marcos, CA

Database(s) : [AST - CA, CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AST - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN, SWRCY - CA] ***(cont.)***

Envirosite ID: 461082
EPA ID: CAL000329923

MANIFEST EPA ***(cont.)***

Destination Mailing :	PO Box 22750, Salt Lake City, UT 84122
Destination Address :	3 Miles East 7 Miles North of Knolls Exit 41 off I-80, Grantsville, UT 84029
Destination Contact :	N/R
Submission Type :	DataImage5Copy
Origin Type :	Service
Manifest Residue :	N
Rejection :	N
Last Date in Agency List :	2022-01-14

Waste Details

Waste Line Number :	2
Is DOT Hazardous :	N
DOT ID Number :	N/R
DOT Information :	N/R
Non Waste Description :	NONE, NON-RCRA HAZARDOUS WASTE, SOLID, N/A, NONE
Quantity :	50 Pounds
Quantity Tons, Acute, Non-Acute :	0.025, 0, 0.025
Quantity Kg, Acute, Non-Acute :	0, 22.67575
Management Method :	H132 - LANDFILL (WITH PRIOR TREATMENT AND/OR STABILIZATION)
Is EPA Waste :	N
Federal Code :	N/R
State Code :	CA - 352

Manifest Details

Manifest Number :	007623368SKS
Shipped Date :	2021-05-07
Updated Date :	2021-06-16
Received Date :	2021-05-17
Status :	Signed
Generator ID :	CAL000438389
Generator Name :	Team Car Care Jiffy Lube 1967
Generator Address :	218 S RANCHO SANTA FE RD, SAN MARCOS, CA 92069
Generator Mailing :	218 S RANCHO SANTA FE RD, San Marcos, CA 92069
Generator Contact :	Team Car Care Jiffy Lube 1967
Destination ID :	UTD991301748
Destination Name :	Clean Harbors Grassy Mountain LLC
Destination Mailing :	PO Box 22750, Salt Lake City, UT 84122
Destination Address :	3 Miles East 7 Miles North of Knolls Exit 41 off I-80, Grantsville, UT 84029
Destination Contact :	N/R
Submission Type :	DataImage5Copy
Origin Type :	Service
Manifest Residue :	N
Rejection :	N
Last Date in Agency List :	2022-01-14

Map Id: C19
Direction: WNW
Distance: 0.102 mi., 539 ft.
Elevation: 622 ft.
Relative: Higher

Site Name : JIFFY LUBE #1967 | TEAM CAR CARE WEST LLC DBA JIFFY LUBE | CASEY'S CAR WASH
218 S RANCHO SANTA FE RD | 218 SOUTH RANCHO SANTA FE ROAD | LOT SOUTH OF 218 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA

Database(s) : [AST - CA, CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AST - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN, SWRCY - CA] ***(cont.)***

Envirosite ID: 461082
EPA ID: CAL000329923

MANIFEST EPA ***(cont.)***

Waste Details

Waste Line Number :	1
Is DOT Hazardous :	N
DOT ID Number :	N/R
DOT Information :	N/R
Non Waste Description :	NONE, NON-RCRA HAZARDOUS WASTE, SOLID) USED OIL FILTERS CONTAINING USED OI (DRAINED AND UNDRAINED OIL FILTERS), N/A, NONE
Quantity :	150 Pounds
Quantity Tons, Acute, Non-Acute :	0.075, 0, 0.075
Quantity Kg, Acute, Non-Acute :	0, 68.02725
Management Method :	H132 - LANDFILL (WITH PRIOR TREATMENT AND/OR STABILIZATION)
Is EPA Waste :	N
Federal Code :	N/R
State Code :	CA - 223

Manifest Details

Manifest Number :	007582920SKS
Shipped Date :	2021-03-24
Updated Date :	2021-05-07
Received Date :	2021-04-12
Status :	Signed
Generator ID :	CAL000438389
Generator Name :	Team Car Care Jiffy Lube 1967
Generator Address :	218 S RANCHO SANTA FE RD, SAN MARCOS, CA 92069
Generator Mailing :	218 S RANCHO SANTA FE RD, San Marcos, CA 92069
Generator Contact :	Team Car Care Jiffy Lube 1967
Destination ID :	UTD991301748
Destination Name :	Clean Harbors Grassy Mountain LLC
Destination Mailing :	PO Box 22750, Salt Lake City, UT 84122
Destination Address :	3 Miles East 7 Miles North of Knolls Exit 41 off I-80, Grantsville, UT 84029
Destination Contact :	N/R
Submission Type :	DataImage5Copy
Origin Type :	Service
Manifest Residue :	N
Rejection :	N
Last Date in Agency List :	2022-01-14

Waste Details

Waste Line Number :	1
Is DOT Hazardous :	N
DOT ID Number :	N/R

Map Id: C19
Direction: WNW
Distance: 0.102 mi., 539 ft.
Elevation: 622 ft.
Relative: Higher

Site Name : JIFFY LUBE #1967 | TEAM CAR CARE WEST LLC DBA JIFFY LUBE | CASEY'S CAR WASH
218 S RANCHO SANTA FE RD | 218 SOUTH RANCHO SANTA FE ROAD | LOT SOUTH OF 218 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA

Database(s) : [AST - CA, CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AST - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN, SWRCY - CA] ***(cont.)***

Envirosite ID: 461082
EPA ID: CAL000329923

MANIFEST EPA ***(cont.)***

DOT Information :	N/R
Non Waste Description :	NONE, NON-RCRA HAZARDOUS WASTE, SOLID) USED OIL FILTERS CONTAINING USED OI (DRAINED AND UNDRAINED OIL FILTERS), N/A, NONE
Quantity :	150 Pounds
Quantity Tons, Acute, Non-Acute :	0.075, 0, 0.075
Quantity Kg, Acute, Non-Acute :	0, 68.02725
Management Method :	H132 - LANDFILL (WITH PRIOR TREATMENT AND/OR STABILIZATION)
Is EPA Waste :	N
Federal Code :	N/R
State Code :	CA - 223

Manifest Details

Manifest Number :	007790028SKS
Shipped Date :	2021-01-21
Updated Date :	2021-03-02
Received Date :	2021-02-01
Status :	Signed
Generator ID :	CAL000438389
Generator Name :	Team Car Care Jiffy Lube 1967
Generator Address :	218 S RANCHO SANTA FE RD, SAN MARCOS, CA 92069
Generator Mailing :	218 S RANCHO SANTA FE RD, San Marcos, CA 92069
Generator Contact :	Team Car Care Jiffy Lube 1967
Destination ID :	UTD991301748
Destination Name :	Clean Harbors Grassy Mountain LLC
Destination Mailing :	PO Box 22750, Salt Lake City, UT 84122
Destination Address :	3 Miles East 7 Miles North of Knolls Exit 41 off I-80, Grantsville, UT 84029
Destination Contact :	N/R
Submission Type :	DataImage5Copy
Origin Type :	Service
Manifest Residue :	N
Rejection :	N
Last Date in Agency List :	2022-01-14

Waste Details

Waste Line Number :	1
Is DOT Hazardous :	N
DOT ID Number :	N/R
DOT Information :	N/R

Map Id: C19
Direction: WNW
Distance: 0.102 mi., 539 ft.
Elevation: 622 ft.
Relative: Higher

Site Name : JIFFY LUBE #1967 | TEAM CAR CARE WEST LLC DBA JIFFY LUBE | CASEY'S CAR WASH
218 S RANCHO SANTA FE RD | 218 SOUTH RANCHO SANTA FE ROAD | LOT SOUTH OF 218 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA

Database(s) : [AST - CA, CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AST - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN, SWRCY - CA] ***(cont.)***

Envirosite ID: 461082
EPA ID: CAL000329923

MANIFEST EPA ***(cont.)***

Non Waste Description :	NONE, NON-RCRA HAZARDOUS WASTE, SOLID) USED OIL FILTERS CONTAINING USED OI (DRAINED AND UNDRAINED OIL FILTERS), N/A, NONE
Quantity :	300 Pounds
Quantity Tons, Acute, Non-Acute :	0.15, 0, 0.15
Quantity Kg, Acute, Non-Acute :	0, 136.0545
Management Method :	H132 - LANDFILL (WITH PRIOR TREATMENT AND/OR STABILIZATION)
Is EPA Waste :	N
Federal Code :	N/R
State Code :	CA - 223

RCRA_NONGEN

Facility Name :	TEAM CAR CARE WEST LLC DBA JIFFY LUBE
Facility Address :	218 S RANCHO SANTA FE RD, SAN MARCOS, CA 92069-2302
County :	SAN DIEGO
Date Form Received by Agency :	2018-08-15
EPA ID :	CAL000438389
Mailing Address :	105 DECKER CT STE 900, IRVING, TX 75062-0000
Contact :	JAMES WILLIS
Contact Address :	105 DECKER COURT SUITE 900, IRVING, TX 75062
Contact Country :	N/R
Contact Telephone :	972-812-7935
Contact Email :	JAMES.WILLIS@JIFFYWORLD.COM
EPA Region :	09
Land Type :	Not Reported
Source Type :	Implementer
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2022-01-26

Owner/Operator Summary

Owner/Operator Name :	JAMES WILLIS
Owner/Operator Address :	105 DECKER COURT SUITE 900, IRVING, TX 75062
Owner/Operator Country :	N/R
Owner/Operator Telephone :	972-812-7935
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Map Id: C19
Direction: WNW
Distance: 0.102 mi., 539 ft.
Elevation: 622 ft.
Relative: Higher

Site Name : JIFFY LUBE #1967 | TEAM CAR CARE WEST LLC DBA JIFFY LUBE | CASEY'S CAR WASH
218 S RANCHO SANTA FE RD | 218 SOUTH RANCHO SANTA FE ROAD | LOT SOUTH OF 218 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA

Database(s) : [AST - CA, CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AST - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN, SWRCY - CA] ***(cont.)***

Envirosite ID: 461082
EPA ID: CAL000329923

RCRA_NONGEN ***(cont.)***

Owner/Operator Name :	TEAM CAR CARE W LLC DBA JIFFY LUBE
Owner/Operator Address :	105 DECKER CT STE 900, IRVING, TX 75062-0000
Owner/Operator Country :	N/R
Owner/Operator Telephone :	972-812-7900
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Notices of Violations Summary

Regulation Violated :	N

SWRCY - CA

Facility Name :	Jiffy Lube #1967
Facility Address :	218 S. Rancho Santa Fe Road, San Marcos, 92069
County :	N/R

Site Details

ID Number :	N/R
Activity Categories :	N/R
Activities :	N/R
Phone Number :	(760) 598-5823

Map Id: C19
Direction: WNW
Distance: 0.102 mi., 539 ft.
Elevation: 622 ft.
Relative: Higher

Site Name : JIFFY LUBE #1967 | TEAM CAR CARE WEST LLC DBA JIFFY LUBE | CASEY'S CAR WASH
218 S RANCHO SANTA FE RD | 218 SOUTH RANCHO SANTA FE ROAD | LOT SOUTH OF 218 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA

Database(s) : [AST - CA, CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AST - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN, SWRCY - CA] ***(cont.)***

Envirosite ID: 461082
EPA ID: CAL000329923

SWRCY - CA ***(cont.)***

Type :	UsedOil
Last Date in Agency List :	2022-02-16

Map Id: D20
Direction: W
Distance: 0.104 mi., 550 ft.
Elevation: 624 ft.
Relative: Higher

Site Name : 99 Cents Only Stores #307
155 S RANCHO SANTA FE RD | 155 SNA RANCHO SANTA FE RD
SAN MARCOS, CA 92069

Database(s) : [CALEPA SITES - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA]

Envirosite ID: 279088
EPA ID: N/R

CALEPA SITES - CA

Facility Name :	99 CENTS ONLY STORES #307
Facility Address :	155 S, RANCHO SANTA FE RD, SAN MARCOS, 92069
Site ID :	1789
EI ID :	10376629
EI Description :	Chemical Storage Facilities
Latitude :	33.146990
Longitude :	-117.198820
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07
Site ID :	1789
EI ID :	10376629
EI Description :	Hazardous Waste Generator
Latitude :	33.146990
Longitude :	-117.198820
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07

FRS

Facility Name :	99 CENTS ONLY STORES #307
Facility Address :	155 SNA RANCHO SANTA FE RD, SAN MARCOS, CA 92069
County :	SAN DIEGO

Map Id: D20
Direction: W
Distance: 0.104 mi., 550 ft.
Elevation: 624 ft.
Relative: Higher

Site Name : 99 Cents Only Stores #307
155 S RANCHO SANTA FE RD | 155 SNA RANCHO SANTA FE RD
SAN MARCOS, CA 92069

Database(s) : [CALEPA SITES - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA] ***(cont.)***

Envirosite ID: 279088
EPA ID: N/R

FRS ***(cont.)***

Site Details
Registry ID : 110066461402
FRS Facility URL : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-02-17

Source Description

Source Description :

The California Environmental Protection Agency (CalEPA) has recently implemented a new data warehouse system (nSite). This data warehouse combines and merges facility and site information from five different systems managed within CalEPA. The five systems are: California Environmental Reporting System (CERS), EnviroStor, GeoTracker, California Integrated Water Quality System (CIWQS), and Toxic Release Inventory (TRI).

FRS Environmental Interest
Source and System ID : CA-ENVIROVIEW - 1789

Facility Name : 99 CENTS ONLY STORES #307
Facility Address : 155 S, RANCHO SANTA FE RD, SAN MARCOS, CA 92069
County : SAN DIEGO

Site Details
Registry ID : 110055736413
FRS Facility URL : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2019-08-12

Source Description

Source Description :

The California Environmental Reporting System (CERS) is a statewide web-based user and information exchange system to support over 140,000 regulated businesses and over 130 local agencies in electronically collecting and reporting significant hazardous materials, hazardous waste and compliance and enforcement data as mandated by California law. Under oversight by Cal/EPA, certified local governing agencies (Unified Program Agencies - UPAs) consolidate, coordinate and provide consistent regulatory activities for six state and federal environmental programs.

FRS Environmental Interest
Source and System ID : CA-CERS - 10376629

HAZMAT_SAN DIEGO COUNTY - CA

Facility Name : 99 Cents Only Stores #307

Map Id: D20
Direction: W
Distance: 0.104 mi., 550 ft.
Elevation: 624 ft.
Relative: Higher

Site Name : 99 Cents Only Stores #307
155 S RANCHO SANTA FE RD | 155 SNA RANCHO SANTA FE RD
SAN MARCOS, CA 92069

Database(s) : [CALEPA SITES - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA] ***(cont.)***

Envirosite ID: 279088
EPA ID: N/R

HAZMAT_SAN DIEGO COUNTY - CA ***(cont.)***

Facility Address :	155 S RANCHO SANTA FE RD, SAN MARCOS, CA 92069
Date :	2012-03-13
Record ID :	DEH2012-HUPFP-216180
Record Type :	Unified Program Facility Permit
Status :	Permit Renewed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23

Map Id: C21
Direction: W
Distance: 0.106 mi., 559 ft.
Elevation: 624 ft.
Relative: Higher

Site Name : CIRCLE K STORES DC 36 #2969 | 787349
202 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, EPA LUST, FRS, LUST REG 9 - CA, RFR - CA]

Envirosite ID: 342579
EPA ID: N/R

CALEPA SITES - CA

Facility Name :	CIRCLE K STORES DC 36 #2969
Facility Address :	202 S RANCHO SANTA FE RD, SAN MARCOS, 920692302
Site ID :	193117
EI ID :	T0607399218
EI Description :	Leaking Underground Storage Tank Cleanup Site
Latitude :	33.145975
Longitude :	-117.200539
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07

CASE LIST_SAN DIEGO COUNTY - CA

Facility Name :	CIRCLE K STORES DC 36 #2969
Facility Address :	202 S RANCHO SANTA FE RD, SAN MARCOS, CA 920692302
County :	San Diego

Site Details

Status Date :	2019-06-13
Status :	Completed - Case Closed
Begin Date :	1999-12-08
Global ID :	T0607399218

Map Id: C21
Direction: W
Distance: 0.106 mi., 559 ft.
Elevation: 624 ft.
Relative: Higher

Site Name : CIRCLE K STORES DC 36 #2969 | 787349
202 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, EPA LUST, FRS, LUST REG 9 - CA, RFR - CA] ***(cont.)***

Envirosite ID: 342579
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Site History :

The Site is located on the southwestern corner of the intersection of South Rancho Santa Fe Road and Grand Avenue in San Marcos, California. The Site was a former gasoline station but is currently occupied by a convenience store. In December 1999, two 10,000-gallon USTs and associated dispenser island and product lines were removed from the site. Liquid-phase hydrocarbons (LPH) and groundwater were observed in the UST cavity at approximately 10 feet below ground surface (bgs). Approximately 175 gallons of LPH and groundwater were removed from the excavation. Soil samples collected beneath the dispenser and stockpiles contained maximum concentrations of total petroleum hydrocarbons as gasoline (TPHg), benzene, and methyl tert-butyl ether (MTBE) of 2,800 milligrams per kilogram (mg/kg), 17 mg/kg, and 140 mg/kg, respectively. Based on observations in the field, Unauthorized Release Case H04763-001 was opened. On March 14 and 15, 2011, six temporary soil gas probes (SGP-1 through SGP-6) were installed. In March and April 2011, soil gas samples were collected from soil gas probes SGP-1 through SGP-6. The highest contaminant concentrations were detected in the March 30, 2011 sample collected from SGP-5. TPHg and BTEX were detected at concentrations of up to 4,200 parts per million by volume (ppmv), 0.18 ppmv, 1.3 ppmv, 1.7 ppmv, and 6.0 ppmv, respectively. MTBE was also detected, at concentrations of up to 2.0 ppmv, while naphthalene was not detected in any of the soil gas samples. URS utilized the soil vapor analytical data to complete SAM Level 1 Vapor Risk Assessment models for the analyzed constituents. The risk models indicated that there is no significant health risk to occupants in the commercial building present on the western portion of the property. DEH concurred with this conclusion in a letter dated July 7, 2011. Between September 12 and 14, 2012, DPE wells DPE-3 through DPE-5 and injection wells IP-2 through IP-4 and IP-8 were installed. The injection wells were subsequently utilized for an injection feasibility test; the results of which suggested the injection of liquid-phase oxidants into the subsurface beneath the site is not feasible. In July and August 2015, approximately 2,858 tons of petroleum hydrocarbon-impacted soil centered in the area of the former UST basin were excavated. The excavated area was approximately 51 feet by 33.5 feet and extended to a depth of approximately 27 feet bgs. The clean backfill was amended with 1,560 pounds of ORC Advanced« that was mixed in the backfill material emplaced at a depth of 10 to 20 feet bgs. Following excavation activities in the former UST basin, confirmation sampling indicated that residual soil contamination still exists in the former UST basin at depths greater than 27 feet bgs. Based on concentrations greater than 100 mg/kg, the amount of hydrocarbon impacted soil for the entire Site is conservatively estimated at approximately 3,775 pounds. As requested by the DEH, periodic removal of liquid phase hydrocarbons (LPH) in well MW-7, including the installation of a passive skimmer, commenced in April 2016. Due to the rapidly declining LPH thicknesses in well MW-7, the skimmer was removed on September 23, 2016. Monthly monitoring of LPH thicknesses in well MW-7 were performed through January 2017. LPH is no longer present in well MW-7. Based on the trend analysis data, the well with the longest estimated time to reach the benzene MCL is 84 years and the well with the longest estimated time to reach the MTBE MCL is 12 years to reach the primary MCL of 13 parts per billion (ppb) and 13 years to reach the secondary MCL of 5 ppb. Remediation by Natural Attenuation (RNA) is currently active in remediating hydrocarbons present at the Site. The Site poses no significant risk to human health and meets the requirements of the Low-Threat UST Case Closure Policy. The case was evaluated under the StateÆs Low-Threat Underground Storage Tank Case Closure Policy (the Policy). Current and historical soil and groundwater data indicate that the secondary source has been adequately removed and a stable to decreasing plume remains. DEH concurs that the case qualifies for a low-risk closure designation. Public notification was completed per the Policy. All monitoring wells associated with the case were destroyed under permit DEH2019-LMWP-003881. The closure of the case is based on the current use of the property as a store and active service station. ANY CONTAMINATED SOIL EXCAVATED AS PART OF SUBSURFACE CONSTRUCTION WORK MUST BE MANAGED IN ACCORDANCE WITH THE LEGAL REQUIREMENTS AT THAT TIME.

RB Case Number :	9UT4013
Potential Media Affected :	Aquifer used for drinking water supply
Potential Contaminants of Concern :	Gasoline
Local Agency :	SAN DIEGO COUNTY LOP
Local Case Number :	H04763-001
Lead Agency :	SAN DIEGO COUNTY LOP
File Location :	Local Agency
CUF Case :	NO
Caseworker :	JC
Case Type :	LUST Cleanup Site

Map Id: C21
Direction: W
Distance: 0.106 mi., 559 ft.
Elevation: 624 ft.
Relative: Higher

Site Name : CIRCLE K STORES DC 36 #2969 | 787349
202 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, EPA LUST, FRS, LUST REG 9 - CA, RFR - CA] ***(cont.)***

Envirosite ID: 342579
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

How Discovered :	N/R
How Discovered Description :	N/R
Stop Method :	Close and Remove Tank
Stop Description :	CLOSE AND REMOVE TANK
Calwater Watershed Name :	Carlsbad - San Marcos - Richland (904.52)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)
Disadvantaged Community :	N/R
Latitude :	33.145975
Longitude :	-117.200539
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-09

Contacts Summary

Global ID :	T0607399218
Contact Name :	JAMES CLAY
Contact Type :	Local Agency Caseworker
Organization Name :	SAN DIEGO COUNTY LOP
Address :	P.O. Box 129261
City :	San Diego
Phone Number :	N/R
Email :	james.clay@sdcounty.ca.gov

Regulatory Activities

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Date :	2019-06-06
Global ID :	T0607399218
Action Type :	ENFORCEMENT
Action :	Closure/No Further Action Letter

Date :	2019-01-11
Global ID :	T0607399218
Action Type :	RESPONSE
Action :	Monitoring Report - Quarterly

Date :	2019-01-08
Global ID :	T0607399218
Action Type :	ENFORCEMENT
Action :	Email Correspondence

Date :	2018-12-18
Global ID :	T0607399218
Action Type :	ENFORCEMENT
Action :	Email Correspondence

Map Id: C21
Direction: W
Distance: 0.106 mi., 559 ft.
Elevation: 624 ft.
Relative: Higher

Site Name : CIRCLE K STORES DC 36 #2969 | 787349
202 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, EPA LUST, FRS, LUST REG 9 - CA, RFR - CA] ***(cont.)***

Envirosite ID: 342579
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Date : 2018-12-14
Global ID : T0607399218
Action Type : ENFORCEMENT
Action : Email Correspondence

Date : 2018-10-29
Global ID : T0607399218
Action Type : ENFORCEMENT
Action : Technical Correspondence / Assistance / Other

Date : 2018-10-22
Global ID : T0607399218
Action Type : RESPONSE
Action : Request for Closure - Regulator Responded

Date : 2018-06-07
Global ID : T0607399218
Action Type : ENFORCEMENT
Action : Technical Correspondence / Assistance / Other

Date : 2018-05-30
Global ID : T0607399218
Action Type : RESPONSE
Action : Monitoring Report - Quarterly - Regulator Responded

Date : 2018-04-04
Global ID : T0607399218
Action Type : RESPONSE
Action : Monitoring Report - Quarterly

Status History

Status Date : 2019-06-13
Global ID : T0607399218
Status : Completed - Case Closed

Status Date : 2019-06-06
Global ID : T0607399218
Status : Completed - Case Closed

Status Date : 2000-05-02
Global ID : T0607399218
Status : Open - Remediation

Status Date : 1999-12-08
Global ID : T0607399218

Map Id: C21
Direction: W
Distance: 0.106 mi., 559 ft.
Elevation: 624 ft.
Relative: Higher

Site Name : CIRCLE K STORES DC 36 #2969 | 787349
202 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, EPA LUST, FRS, LUST REG 9 - CA, RFR - CA] ***(cont.)***

Envirosite ID: 342579
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Status :	Open - Case Begin Date

EPA LUST

Facility Name :	CIRCLE K STORES DC 36 #2969
Facility Address :	202 S RANCHO SANTA FE RD, SAN MARCOS, California 920692302
County :	N/R
Facility ID :	N/R
LUST ID :	CAT0607399218
Reported Date :	N/R
Status :	No Further Action
Substance :	N/R
Closed With Residual Contamination (Tribal Only):	N/R
NFA_Letter (Tribal Only) :	N/R
Tribe (Tribal Only) :	N/R
EPA Region :	9
Estimated Population within 1500ft :	1288
Estimated Private Domestic Wells within 1500ft:	0
Within Source Water Protection Area (SPA):	No
SPA Public Water System and Facility ID:	N/R
SPA Water Type :	N/R
SPA Facility Type :	N/R
SPA HUC12 :	N/R
Within Groundwater Wellhead Protection Area (WHPA):	No
WHPA Public Water System and Facility ID:	N/R
WHPA Water Type :	N/R
WHPA Facility Type :	N/R
WHPA HUC12 :	N/R
Within Estimated 100-year Floodplain:	No
Latitude :	33.145809999999898
Longitude :	-117.200590000000005
Last Date in Agency List :	2022-01-04

FRS

Facility Name :	787349
Facility Address :	202 S RANCHO SANTA FE RD., SAN MARCOS, CA 92069
County :	SAN DIEGO COUNTY

Site Details

Registry ID :	110066723745
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Map Id: C21
Direction: W
Distance: 0.106 mi., 559 ft.
Elevation: 624 ft.
Relative: Higher

Site Name : CIRCLE K STORES DC 36 #2969 | 787349
202 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, EPA LUST, FRS, LUST REG 9 - CA, RFR - CA] ***(cont.)***

Envirosite ID: 342579
EPA ID: N/R

FRS ***(cont.)***

Source Description

Source Description :

The California Environmental Protection Agency (CalEPA) has recently implemented a new data warehouse system (nSite). This data warehouse combines and merges facility and site information from five different systems managed within CalEPA. The five systems are: California Environmental Reporting System (CERS), EnviroStor, GeoTracker, California Integrated Water Quality System (CIWQS), and Toxic Release Inventory (TRI).

FRS Environmental Interest

Source and System ID :	CA-ENVIROVIEW - 355276
Facility Name :	CIRCLE K STORES DC 36 #2969
Facility Address :	202 S RANCHO SANTA FE RD, SAN MARCOS, CA 920692302
County :	SAN DIEGO

Site Details

Registry ID :	110065835546
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Source Description

Source Description :

The California Environmental Protection Agency (CalEPA) has recently implemented a new data warehouse system (nSite). This data warehouse combines and merges facility and site information from five different systems managed within CalEPA. The five systems are: California Environmental Reporting System (CERS), EnviroStor, GeoTracker, California Integrated Water Quality System (CIWQS), and Toxic Release Inventory (TRI).

FRS Environmental Interest

Source and System ID :	CA-ENVIROVIEW - 193117

LUST REG 9 - CA

Facility Name :	CIRCLE K STORES DC 36 #2969
Facility Address :	202 S RANCHO SANTA FE RD, SAN MARCOS, CA 920692302
County :	San Diego

Site Details

Status Date :	2019-06-13
Status :	Completed - Case Closed
Begin Date :	1999-12-08

Map Id: C21
Direction: W
Distance: 0.106 mi., 559 ft.
Elevation: 624 ft.
Relative: Higher

Site Name : CIRCLE K STORES DC 36 #2969 | 787349
202 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, EPA LUST, FRS, LUST REG 9 - CA, RFR - CA] ***(cont.)***

Envirosite ID: 342579
EPA ID: N/R

LUST REG 9 - CA ***(cont.)***

Global ID : T0607399218
Region : REGION 9

Site History :

The Site is located on the southwestern corner of the intersection of South Rancho Santa Fe Road and Grand Avenue in San Marcos, California. The Site was a former gasoline station but is currently occupied by a convenience store. In December 1999, two 10,000-gallon USTs and associated dispenser island and product lines were removed from the site. Liquid-phase hydrocarbons (LPH) and groundwater were observed in the UST cavity at approximately 10 feet below ground surface (bgs). Approximately 175 gallons of LPH and groundwater were removed from the excavation. Soil samples collected beneath the dispenser and stockpiles contained maximum concentrations of total petroleum hydrocarbons as gasoline (TPHg), benzene, and methyl tert-butyl ether (MTBE) of 2,800 milligrams per kilogram (mg/kg), 17 mg/kg, and 140 mg/kg, respectively. Based on observations in the field, Unauthorized Release Case H04763-001 was opened. On March 14 and 15, 2011, six temporary soil gas probes (SGP-1 through SGP-6) were installed. In March and April 2011, soil gas samples were collected from soil gas probes SGP-1 through SGP-6. The highest contaminant concentrations were detected in the March 30, 2011 sample collected from SGP-5. TPHg and BTEX were detected at concentrations of up to 4,200 parts per million by volume (ppmv), 0.18 ppmv, 1.3 ppmv, 1.7 ppmv, and 6.0 ppmv, respectively. MTBE was also detected, at concentrations of up to 2.0 ppmv, while naphthalene was not detected in any of the soil gas samples. URS utilized the soil vapor analytical data to complete SAM Level 1 Vapor Risk Assessment models for the analyzed constituents. The risk models indicated that there is no significant health risk to occupants in the commercial building present on the western portion of the property. DEH concurred with this conclusion in a letter dated July 7, 2011. Between September 12 and 14, 2012, DPE wells DPE-3 through DPE-5 and injection wells IP-2 through IP-4 and IP-8 were installed. The injection wells were subsequently utilized for an injection feasibility test; the results of which suggested the injection of liquid-phase oxidants into the subsurface beneath the site is not feasible. In July and August 2015, approximately 2,858 tons of petroleum hydrocarbon-impacted soil centered in the area of the former UST basin were excavated. The excavated area was approximately 51 feet by 33.5 feet and extended to a depth of approximately 27 feet bgs. The clean backfill was amended with 1,560 pounds of ORC Advanced« that was mixed in the backfill material emplaced at a depth of 10 to 20 feet bgs. Following excavation activities in the former UST basin, confirmation sampling indicated that residual soil contamination still exists in the former UST basin at depths greater than 27 feet bgs. Based on concentrations greater than 100 mg/kg, the amount of hydrocarbon impacted soil for the entire Site is conservatively estimated at approximately 3,775 pounds. As requested by the DEH, periodic removal of liquid phase hydrocarbons (LPH) in well MW-7, including the installation of a passive skimmer, commenced in April 2016. Due to the rapidly declining LPH thicknesses in well MW-7, the skimmer was removed on September 23, 2016. Monthly monitoring of LPH thicknesses in well MW-7 were performed through January 2017. LPH is no longer present in well MW-7. Based on the trend analysis data, the well with the longest estimated time to reach the benzene MCL is 84 years and the well with the longest estimated time to reach the MTBE MCL is 12 years to reach the primary MCL of 13 parts per billion (ppb) and 13 years to reach the secondary MCL of 5 ppb. Remediation by Natural Attenuation (RNA) is currently active in remediating hydrocarbons present at the Site. The Site poses no significant risk to human health and meets the requirements of the Low-Threat UST Case Closure Policy. The case was evaluated under the StateÆs Low-Threat Underground Storage Tank Case Closure Policy (the Policy). Current and historical soil and groundwater data indicate that the secondary source has been adequately removed and a stable to decreasing plume remains. DEH concurs that the case qualifies for a low-risk closure designation. Public notification was completed per the Policy. All monitoring wells associated with the case were destroyed under permit DEH2019-LMWP-003881. The closure of the case is based on the current use of the property as a store and active service station. ANY CONTAMINATED SOIL EXCAVATED AS PART OF SUBSURFACE CONSTRUCTION WORK MUST BE MANAGED IN ACCORDANCE WITH THE LEGAL REQUIREMENTS AT THAT TIME.

RB Case Number : 9UT4013
Potential Media Affected : Aquifer used for drinking water supply
Potential Contaminants of Concern : Gasoline
Local Agency : SAN DIEGO COUNTY LOP
Local Case Number : H04763-001
Lead Agency : SAN DIEGO COUNTY LOP
File Location : Local Agency

Map Id: C21
Direction: W
Distance: 0.106 mi., 559 ft.
Elevation: 624 ft.
Relative: Higher

Site Name : CIRCLE K STORES DC 36 #2969 | 787349
202 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, EPA LUST, FRS, LUST REG 9 - CA, RFR - CA] ***(cont.)***

Envirosite ID: 342579
EPA ID: N/R

LUST REG 9 - CA ***(cont.)***

CUF Case :	NO
Caseworker :	JC
Case Type :	LUST Cleanup Site
How Discovered :	N/R
How Discovered Description :	N/R
Stop Method :	Close and Remove Tank
Stop Description :	CLOSE AND REMOVE TANK
Calwater Watershed Name :	Carlsbad - San Marcos - Richland (904.52)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)
Disadvantaged Community :	N/R
Latitude :	33.145975
Longitude :	-117.200539
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-11

Contacts Summary

Global ID :	T0607399218
Contact Name :	JAMES CLAY
Contact Type :	Local Agency Caseworker
Organization Name :	SAN DIEGO COUNTY LOP
Address :	P.O. Box 129261
City :	San Diego
Phone Number :	N/R
Email :	james.clay@sdcounty.ca.gov

Regulatory Activities

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Date :	2019-06-06
Global ID :	T0607399218
Action Type :	ENFORCEMENT
Action :	Closure/No Further Action Letter

Date :	2019-01-11
Global ID :	T0607399218
Action Type :	RESPONSE
Action :	Monitoring Report - Quarterly

Date :	2019-01-08
Global ID :	T0607399218
Action Type :	ENFORCEMENT
Action :	Email Correspondence

Date :	2018-12-18
Global ID :	T0607399218

Map Id: C21
Direction: W
Distance: 0.106 mi., 559 ft.
Elevation: 624 ft.
Relative: Higher

Site Name : CIRCLE K STORES DC 36 #2969 | 787349
202 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, EPA LUST, FRS, LUST REG 9 - CA, RFR - CA] ***(cont.)***

Envirosite ID: 342579
EPA ID: N/R

LUST REG 9 - CA ***(cont.)***

Action Type : ENFORCEMENT
Action : Email Correspondence

Date : 2018-12-14
Global ID : T0607399218
Action Type : ENFORCEMENT
Action : Email Correspondence

Date : 2018-10-29
Global ID : T0607399218
Action Type : ENFORCEMENT
Action : Technical Correspondence / Assistance / Other

Date : 2018-10-22
Global ID : T0607399218
Action Type : RESPONSE
Action : Request for Closure - Regulator Responded

Date : 2018-06-07
Global ID : T0607399218
Action Type : ENFORCEMENT
Action : Technical Correspondence / Assistance / Other

Date : 2018-05-30
Global ID : T0607399218
Action Type : RESPONSE
Action : Monitoring Report - Quarterly - Regulator Responded

Date : 2018-04-04
Global ID : T0607399218
Action Type : RESPONSE
Action : Monitoring Report - Quarterly

Status History
Status Date : 2019-06-13
Global ID : T0607399218
Status : Completed - Case Closed

Status Date : 2019-06-06
Global ID : T0607399218
Status : Completed - Case Closed

Status Date : 2000-05-02
Global ID : T0607399218
Status : Open - Remediation

Map Id: C21
Direction: W
Distance: 0.106 mi., 559 ft.
Elevation: 624 ft.
Relative: Higher

Site Name : CIRCLE K STORES DC 36 #2969 | 787349
202 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, EPA LUST, FRS, LUST REG 9 - CA, RFR - CA] ***(cont.)***

Envirosite ID: 342579
EPA ID: N/R

LUST REG 9 - CA ***(cont.)***

Status Date :	1999-12-08
Global ID :	T0607399218
Status :	Open - Case Begin Date

RFR - CA

Facility Name :	787349
Facility Address :	202 S Rancho Santa Fe Rd., San Marcos, CA 92069
County :	San Diego
Effective Date :	2015-06-19
Adoption Date :	2015-06-19
Termination Date :	N/R
Expiration/Review Date :	2016-06-20
NPDES Number :	N/R
Order Number :	N/R
WDID :	9 000002865
SIC/NAICS :	N/R
Program :	UST
Regulatory Measure Status :	Active
Regulatory Measure Type :	Enrollee - WDR
Place/Project Type :	Groundwater Cleanup Site
Region :	9
Design Flow :	N/R
Major/Minor :	N/R
Complexity :	C
TTWQ :	3
Number of Enforcement Actions within Five Years:	N/R
Number of Violations within Five Years:	N/R
Agency :	Phillips 66 Company Rodeo
Agency Address :	1380 San Pablo Avenue, Rodeo, CA 94572
Latitude :	N/R
Longitude :	N/R
Last Date in Agency List :	2015-09-26

Map Id: D22
Direction: W
Distance: 0.106 mi., 561 ft.
Elevation: 623 ft.
Relative: Higher

Site Name : SAN MARCOS VETERINARY CLINIC
145 S RANCHO SANTA FE RD
SAN MARCOS, CA 92069

Database(s) : [CALEPA SITES - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA]

Envirosite ID: 278758
EPA ID: N/R

CALEPA SITES - CA

Facility Name :	SAN MARCOS VETERINARY CLINIC
Facility Address :	145 S RANCHO SANTA FE RD, SAN MARCOS, 92069

Map Id: D22
Direction: W
Distance: 0.106 mi., 561 ft.
Elevation: 623 ft.
Relative: Higher

Site Name : SAN MARCOS VETERINARY CLINIC
145 S RANCHO SANTA FE RD
SAN MARCOS, CA 92069

Database(s) : [CALEPA SITES - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA] ***(cont.)***

Envirosite ID: 278758
EPA ID: N/R

CALEPA SITES - CA ***(cont.)***

Site ID :	64700
EI ID :	10376719
EI Description :	Chemical Storage Facilities
Latitude :	33.147820
Longitude :	-117.199320
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07

FRS

Facility Name :	SAN MARCOS VETERINARY CLINIC
Facility Address :	145 S RANCHO SANTA FE RD, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Registry ID :	110065300711
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Source Description

Source Description :

The California Environmental Protection Agency (CalEPA) has recently implemented a new data warehouse system (nSite). This data warehouse combines and merges facility and site information from five different systems managed within CalEPA. The five systems are: California Environmental Reporting System (CERS), EnviroStor, GeoTracker, California Integrated Water Quality System (CIWQS), and Toxic Release Inventory (TRI).

FRS Environmental Interest

Source and System ID :	CA-ENVIROVIEW - 64700

HAZMAT_SAN DIEGO COUNTY - CA

Facility Name :	SAN MARCOS VETERINARY CLINIC
Facility Address :	145 S RANCHO SANTA FE RD, SAN MARCOS, CA 92069
Date :	2012-11-15
Record ID :	DEH2012-HUPFP-217323
Record Type :	Unified Program Facility Permit
Status :	Application In-Review
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23

Map Id: C23
Direction: W
Distance: 0.108 mi., 573 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : POBRAN CHIROPRACTIC
174 S RANCHO SANTA FE RD
SAN MARCOS, CA 92069

Database(s) : [CALEPA SITES - CA, FRS]

Envirosite ID: 1049166
EPA ID: N/R

CALEPA SITES - CA

Facility Name : POBRAN CHIROPRACTIC
Facility Address : 174 S RANCHO SANTA FE RD, SAN MARCOS, 92069

Site ID : 58042
EI ID : 10375843
EI Description : Hazardous Waste Generator
Latitude : 33.146490
Longitude : -117.200270
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-01-07

FRS

Facility Name : POBRAN CHIROPRACTIC
Facility Address : 174 S RANCHO SANTA FE RD, SAN MARCOS, CA 92069
County : SAN DIEGO

Site Details

Registry ID : 110065353673
FRS Facility URL : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-02-17

Source Description

Source Description :

The California Environmental Protection Agency (CalEPA) has recently implemented a new data warehouse system (nSite). This data warehouse combines and merges facility and site information from five different systems managed within CalEPA. The five systems are: California Environmental Reporting System (CERS), EnviroStor, GeoTracker, California Integrated Water Quality System (CIWQS), and Toxic Release Inventory (TRI).

FRS Environmental Interest

Source and System ID : CA-ENVIROVIEW - 58042

Map Id: C24
Direction: W
Distance: 0.108 mi., 573 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : SAN MARCOS DENTAL CENTER
162 S RANCHO SANTA FE RD
SAN MARCOS, CA 92069

Database(s) : [CALEPA SITES - CA, FRS]

Envirosite ID: 1048282
EPA ID: N/R

CALEPA SITES - CA

Facility Name : SAN MARCOS DENTAL CENTER
Facility Address : 162 S RANCHO SANTA FE RD, SAN MARCOS, 92069

Map Id: C24
Direction: W
Distance: 0.108 mi., 573 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : SAN MARCOS DENTAL CENTER
162 S RANCHO SANTA FE RD
SAN MARCOS, CA 92069

Database(s) : [CALEPA SITES - CA, FRS] ***(cont.)***

Envirosite ID: 1048282
EPA ID: N/R

CALEPA SITES - CA ***(cont.)***

Site ID :	150655
EI ID :	10376002
EI Description :	Chemical Storage Facilities
Latitude :	33.146830
Longitude :	-117.200100
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07

FRS

Facility Name :	SAN MARCOS DENTAL CENTER
Facility Address :	162 S RANCHO SANTA FE RD, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Registry ID :	110066202120
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Source Description

Source Description :

The California Environmental Protection Agency (CalEPA) has recently implemented a new data warehouse system (nSite). This data warehouse combines and merges facility and site information from five different systems managed within CalEPA. The five systems are: California Environmental Reporting System (CERS), EnviroStor, GeoTracker, California Integrated Water Quality System (CIWQS), and Toxic Release Inventory (TRI).

FRS Environmental Interest

Source and System ID :	CA-ENVIROVIEW - 150655

Map Id: C25
Direction: W
Distance: 0.109 mi., 577 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : RANCHO SANTA FE EXXON | GSE San Marcos 851632 | G&M OIL #171
112 N RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, UST - CA]

Envirosite ID: 258269
EPA ID: N/R

FID UST - CA

Facility Name :	GSE San Marcos 851632
Facility Address :	112 N RANCHO SANTA FE RD, SAN MARCOS, 92069
County :	San Diego

Map Id: C25
Direction: W
Distance: 0.109 mi., 577 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : RANCHO SANTA FE EXXON | GSE San Marcos 851632 | G&M OIL #171
112 N RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, UST - CA] ***(cont.)***

Envirosite ID: 258269
EPA ID: N/R

FID UST - CA ***(cont.)***

Facility ID :	37-000-217308
CERSID :	10376716
Permitting Agency :	San Diego County Department of Environmental Health
Latitude :	N/R
Longitude :	N/R
Last Date in Agency List :	2019-09-16
Facility Name :	RANCHO SANTA FE EXXON
Facility Address :	112 N RANCHO SANTA FE RD, SAN MARCOS, 92069
County :	San Diego
Facility ID :	H03229
CERSID :	N/R
Permitting Agency :	SAN DIEGO COUNTY
Latitude :	33.15094
Longitude :	-117.19797
Last Date in Agency List :	2018-05-14

FRS

Facility Name :	RANCHO SANTA FE EXXON
Facility Address :	112 N RANCHO SANTA FE RD, SAN MARCOS, CA 920691218
County :	SAN DIEGO

Site Details

Registry ID :	110065089371
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Source Description

Source Description :

The California Environmental Protection Agency (CalEPA) has recently implemented a new data warehouse system (nSite). This data warehouse combines and merges facility and site information from five different systems managed within CalEPA. The five systems are: California Environmental Reporting System (CERS), EnviroStor, GeoTracker, California Integrated Water Quality System (CIWQS), and Toxic Release Inventory (TRI).

FRS Environmental Interest

Source and System ID :	CA-ENVIROVIEW - 214650 CA-ENVIROVIEW - 218725

HAZMAT_SAN DIEGO COUNTY - CA

Facility Name :	G&M OIL #171
Facility Address :	112 N RANCHO SANTA FE RD, SAN MARCOS, CA 92069

Map Id: C25
Direction: W
Distance: 0.109 mi., 577 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : RANCHO SANTA FE EXXON | GSE San Marcos 851632 | G&M OIL #171
112 N RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, UST - CA] ***(cont.)***

Envirosite ID: 258269
EPA ID: N/R

HAZMAT_SAN DIEGO COUNTY - CA ***(cont.)***

Date :	2009-03-06
Record ID :	DEH2009-HUPFP-210458
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	Pay Fees Due
Short Notes :	N/R
Last Date in Agency List :	2015-11-23
Facility Name :	RANCHO SANTA FE 76
Facility Address :	112 N RANCHO SANTA FE RD, SAN MARCOS, CA 92069
Date :	2012-11-13
Record ID :	DEH2012-HUPFP-217308
Record Type :	Unified Program Facility Permit
Status :	Permit Renewed
Action :	Pay Fees Due
Short Notes :	N/R
Last Date in Agency List :	2015-11-23

UST - CA

Facility Name :	GSE San Marcos 851632
Facility Address :	112 N RANCHO SANTA FE RD, SAN MARCOS, 92069
County :	San Diego
Facility ID :	37-000-217308
CERS ID :	10376716
Permitting Agency :	San Diego County Department of Environmental Health
Latitude :	N/R
Longitude :	N/R
Last Date in Agency List :	2019-09-04
Facility Name :	RANCHO SANTA FE EXXON
Facility Address :	112 N RANCHO SANTA FE RD, SAN MARCOS, 92069
County :	San Diego
Facility ID :	H03229
CERS ID :	N/R
Permitting Agency :	SAN DIEGO COUNTY
Latitude :	33.15094
Longitude :	-117.19797
Last Date in Agency List :	2017-01-13

Map Id: C26
Direction: W
Distance: 0.109 mi., 577 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : PALM SPRINGS OIL CO (CHEVRON) | APRO LLC DBA UNITED PACIFIC 0658 | 1X CHEVRON USA INC #9-3496
110 S RANCHO SANTA FE RD | 110 RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, UST - CA]

Envirosite ID: 258087
EPA ID: N/R

CALEPA SITES - CA

Facility Name :	PALM SPRINGS OIL CO (CHEVRON)
Facility Address :	110 S RANCHO SANTA FE RD, SAN MARCOS, 920692502
Site ID :	247568
EI ID :	T0607303122
EI Description :	Leaking Underground Storage Tank Cleanup Site
Latitude :	33.148811
Longitude :	-117.199372
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07

CASE LIST_SAN DIEGO COUNTY - CA

Facility Name :	PALM SPRINGS OIL CO (CHEVRON)
Facility Address :	110 S RANCHO SANTA FE RD, SAN MARCOS, CA 920692502
County :	San Diego

Site Details

Status Date :	2019-11-07
Status :	Completed - Case Closed
Begin Date :	1987-12-04
Global ID :	T0607303122
Site History :	This case was opened after receiving the results of soil and groundwater data collected after the removal of the underground storage tanks on November 2, 1987. Petroleum hydrocarbons were detected in soil and groundwater samples collected from the tank excavation. Please see Environmental Data Tab for additional information.
RB Case Number :	9UT878
Potential Media Affected :	Aquifer used for drinking water supply
Potential Contaminants of Concern :	Gasoline
Local Agency :	N/R
Local Case Number :	N/R
Lead Agency :	SAN DIEGO RWQCB (REGION 9)
File Location :	Regional Board
CUF Case :	YES
Caseworker :	LT
Case Type :	LUST Cleanup Site
How Discovered :	UST System Modification
How Discovered Description :	N/R
Stop Method :	Close and Replace Tank
Stop Description :	CLOSE AND REPLACE TANK
Calwater Watershed Name :	Carlsbad - San Marcos - Richland (904.52)

Map Id: C26
Direction: W
Distance: 0.109 mi., 577 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : PALM SPRINGS OIL CO (CHEVRON) | APRO LLC DBA UNITED PACIFIC 0658 | 1X CHEVRON USA INC #9-3496
110 S RANCHO SANTA FE RD | 110 RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 258087
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

DWR Groundwater Subbasin Name :	San Marcos Area (9-032)
Disadvantaged Community :	N/R
Latitude :	33.148811
Longitude :	-117.199372
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-09

Contacts Summary

Global ID :	T0607303122
Contact Name :	LALITHA THOTAKURA
Contact Type :	Regional Board Caseworker
Organization Name :	SAN DIEGO RWQCB (REGION 9)
Address :	2375 NORTHSIDE DRIVE, SUITE 100
City :	SAN DIEGO
Phone Number :	6195213002
Email :	lalitha.thotakura@waterboards.ca.gov

Regulatory Activities

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Date :	2019-11-07
Global ID :	T0607303122
Action Type :	ENFORCEMENT
Action :	Closure/No Further Action Letter

Date :	2019-06-28
Global ID :	T0607303122
Action Type :	RESPONSE
Action :	Well Destruction Report

Date :	2019-01-18
Global ID :	T0607303122
Action Type :	ENFORCEMENT
Action :	Staff Letter

Date :	2018-11-05
Global ID :	T0607303122

Map Id: C26
Direction: W
Distance: 0.109 mi., 577 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : PALM SPRINGS OIL CO (CHEVRON) | APRO LLC DBA UNITED PACIFIC 0658 | 1X CHEVRON USA INC #9-3496
110 S RANCHO SANTA FE RD | 110 RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 258087
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Action Type : ENFORCEMENT
Action : Notification - Public Notice of Case Closure

Date : 2018-10-03
Global ID : T0607303122
Action Type : ENFORCEMENT
Action : Notification - Preclosure

Date : 2018-08-03
Global ID : T0607303122
Action Type : RESPONSE
Action : Technical Memos

Date : 2018-07-30
Global ID : T0607303122
Action Type : RESPONSE
Action : Monitoring Report - Semi-Annually

Date : 2018-01-24
Global ID : T0607303122
Action Type : RESPONSE
Action : Monitoring Report - Semi-Annually

Date : 2017-10-11
Global ID : T0607303122
Action Type : RESPONSE
Action : Correspondence

Date : 2017-08-18
Global ID : T0607303122
Action Type : ENFORCEMENT
Action : Clean Up Fund - Case Closure Review Summary Report (RSR)

Status History
Status Date : 2019-11-07
Global ID : T0607303122
Status : Completed - Case Closed

Map Id: C26
Direction: W
Distance: 0.109 mi., 577 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : PALM SPRINGS OIL CO (CHEVRON) | APRO LLC DBA UNITED PACIFIC 0658 | 1X CHEVRON USA INC #9-3496
110 S RANCHO SANTA FE RD | 110 RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 258087
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Status Date :	1987-12-04
Global ID :	T0607303122
Status :	Open - Remediation
Status Date :	1987-12-04
Global ID :	T0607303122
Status :	Open - Case Begin Date

ECHO

Facility Name :	APRO LLC DBA UNITED PACIFIC 0658
Facility Address :	110 S RANCHO SANTA FE RD, SAN MARCOS, CA 92069
County :	SAN DIEGO
Last Inspection Date :	N/R
Registry ID :	110070800354
FIPS Code :	N/R
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	_____
Collection Method :	Zip Code Centroid
Reference Point :	N/R
Accuracy Meters :	10000
Derived Tribes :	N/R
Derived HUC :	N/R
Derived WBD :	N/R
Derived STCTY FIPS :	N/R
Derived Zip :	N/R
Derived CD113 :	N/R
Derived CB2010 :	N/R
MYRTK Universe :	NNN
NPDES IDs :	N/R
CWA Permit Types :	N/R

Map Id: C26
Direction: W
Distance: 0.109 mi., 577 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : PALM SPRINGS OIL CO (CHEVRON) | APRO LLC DBA UNITED PACIFIC 0658 | 1X CHEVRON USA INC #9-3496
110 S RANCHO SANTA FE RD | 110 RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 258087
EPA ID: N/R

ECHO ***(cont.)***

CWA Compliance Tracking :	N/R
CWA NAICS :	N/R
CWA SICS :	N/R
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	N/R
CWA Current Compliance Status :	N/R
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	N/R
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	N/R
Facility NAICS :	447190 - Other Gasoline Stations
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	N/R
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	N
SDWIS Flag :	N
RCRA Flag :	Y
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	N/R
NAA Flag :	N
Latitude :	33.194075
Longitude :	-117.16177
Last Date in Agency List :	2022-01-17

Map Id: C26
Direction: W
Distance: 0.109 mi., 577 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : PALM SPRINGS OIL CO (CHEVRON) | APRO LLC DBA UNITED PACIFIC 0658 | 1X CHEVRON USA INC #9-3496
110 S RANCHO SANTA FE RD | 110 RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 258087
EPA ID: N/R

EPA LUST

Facility Name :	PALM SPRINGS OIL CO (CHEVRON)
Facility Address :	110 S RANCHO SANTA FE RD, SAN MARCOS, California 920692502
County :	N/R
Facility ID :	N/R
LUST ID :	CAT0607303122
Reported Date :	N/R
Status :	No Further Action
Substance :	N/R
Closed With Residual Contamination (Tribal Only):	N/R
NFA_Letter (Tribal Only) :	N/R
Tribe (Tribal Only) :	N/R
EPA Region :	9
Estimated Population within 1500ft :	1488
Estimated Private Domestic Wells within 1500ft:	0
Within Source Water Protection Area (SPA):	No
SPA Public Water System and Facility ID:	N/R
SPA Water Type :	N/R
SPA Facility Type :	N/R
SPA HUC12 :	N/R
Within Groundwater Wellhead Protection Area (WHPA):	No
WHPA Public Water System and Facility ID:	N/R
WHPA Water Type :	N/R
WHPA Facility Type :	N/R
WHPA HUC12 :	N/R
Within Estimated 100-year Floodplain:	No
Latitude :	33.148710000000001
Longitude :	-117.199129999999002
Last Date in Agency List :	2022-01-04

FID UST - CA

Facility Name :	PALM SPRINGS OIL CO (CHEVRON)
Facility Address :	110 S RANCHO SANTA FE RD, SAN MARCOS, 92069
County :	San Diego
Facility ID :	H13261
CERSID :	N/R
Permitting Agency :	SAN DIEGO COUNTY
Latitude :	33.15092

Map Id: C26
Direction: W
Distance: 0.109 mi., 577 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : PALM SPRINGS OIL CO (CHEVRON) | APRO LLC DBA UNITED PACIFIC 0658 | 1X CHEVRON USA INC #9-3496
110 S RANCHO SANTA FE RD | 110 RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 258087
EPA ID: N/R

FID UST - CA ***(cont.)***

Longitude : -117.19798
Last Date in Agency List : 2018-05-14

FRS

Facility Name : APRO LLC DBA UNITED PACIFIC 0658
Facility Address : 110 S RANCHO SANTA FE RD, SAN MARCOS, CA 92069
County : SAN DIEGO

Site Details
Registry ID : 110070800354
FRS Facility URL : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-02-17

Source Description

Source Description :

RCRAInfo is EPA's comprehensive information system that supports the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984 through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA. RCRAInfo also supports generation of the National Hazardous Waste Biennial Report. All generators and treatment, storage, and disposal facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years to support creation of the Biennial Report.

FRS Environmental Interest
Source and System ID : RCRAINFO - CAL000453927

Facility Name : CHEVRON
Facility Address : 110 RANCHO SANTA FE RD, SAN MARCOS, CA 92069
County : SAN DIEGO

Site Details
Registry ID : 110040964588
FRS Facility URL : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2014-03-25

Map Id: C26
Direction: W
Distance: 0.109 mi., 577 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : PALM SPRINGS OIL CO (CHEVRON) | APRO LLC DBA UNITED PACIFIC 0658 | 1X CHEVRON USA INC #9-3496
110 S RANCHO SANTA FE RD | 110 RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 258087
EPA ID: N/R

FRS ***(cont.)***

Source Description

Source Description :

The Emission Inventory System (EIS) maintains an inventory of large stationary sources and voluntarily-reported smaller sources of air point pollution emitters. It contains information about facility sites and their physical location, emission units, emission processes, release points, control approaches, and regulations. Facility inventory data are kept separate from the emissions data and have stable identifiers to improve continuity from year to year and to help identify duplicate or missing facilities.

FRS Environmental Interest

Source and System ID :	EIS - 1252411
Facility Name :	PALM SPRINGS OIL CO (CHEVRON)
Facility Address :	110 S RANCHO SANTA FE RD, SAN MARCOS, CA 920692502
County :	SAN DIEGO

Site Details

Registry ID :	110064963794
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Source Description

Source Description :

The California Environmental Protection Agency (CalEPA) has recently implemented a new data warehouse system (nSite). This data warehouse combines and merges facility and site information from five different systems managed within CalEPA. The five systems are: California Environmental Reporting System (CERS), EnviroStor, GeoTracker, California Integrated Water Quality System (CIWQS), and Toxic Release Inventory (TRI).

FRS Environmental Interest

Source and System ID :	CA-ENVIROVIEW - 247568 CA-ENVIROVIEW - 55139

Map Id: C26
Direction: W
Distance: 0.109 mi., 577 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : PALM SPRINGS OIL CO (CHEVRON) | APRO LLC DBA UNITED PACIFIC 0658 | 1X CHEVRON USA INC #9-3496
110 S RANCHO SANTA FE RD | 110 RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 258087
EPA ID: N/R

HAZMAT_SAN DIEGO COUNTY - CA

Facility Name : PALM SPRINGS OIL CO (CHEVRON)
Facility Address : 110 S RANCHO SANTA FE RD, SAN MARCOS, CA 92069

Date : 2002-05-04
Record ID : DEH2002-HUPFP-113261
Record Type : Unified Program Facility Permit
Status : Permit Renewed
Action : N/R
Short Notes : N/R
Last Date in Agency List : 2015-11-23

HAZNET - CA

Facility Name : 1X CHEVRON USA INC #9-3496
Facility Address : 110 RANCHO SANTA FE RD, SAN MARCOS, CA 92069
County : SAN DIEGO

Site Details
Generator EPA ID : CAC000039503
Active : Inactive
Category : STATE
Facility Types : N/R
Type : TEMPORARY
Contact Name : N/R
Contact Phone : N/R
Facility Mailing Address : PO BOX 2833, LA HABRA, CA 906320000
Latitude : 33.15170219
Longitude : -117.19767969
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2021-07-08

Facility Name : APRO LLC DBA UNITED PACIFIC 0658
Facility Address : 110 S RANCHO SANTA FE RD, SAN MARCOS, CA 92069
County : SAN DIEGO

Site Details
Generator EPA ID : CAL000453927
Active : Active
Category : STATE
Facility Types : N/R
Type : PERMANENT

Map Id: C26
Direction: W
Distance: 0.109 mi., 577 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : PALM SPRINGS OIL CO (CHEVRON) | APRO LLC DBA UNITED PACIFIC 0658 | 1X CHEVRON USA INC #9-3496
110 S RANCHO SANTA FE RD | 110 RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 258087
EPA ID: N/R

HAZNET - CA ***(cont.)***

Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	4130 COVER ST, LONG BEACH, CA 90808
Latitude :	33.14880900
Longitude :	-117.19941300
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Facility Name :	PALM SPRINGS OIL CO
Facility Address :	110 RANCHO SANTA FE RD, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAC001171536
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	3410 E FOOTHILL BLVD, PASADENA, CA 911070000
Latitude :	33.15170219
Longitude :	-117.19767969
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	1998: 241 - Tank bottom waste, 9.3825 tons to CAT080013352

Site Details

Generator EPA ID :	CAC002312513
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	155 S PALM CANYON #B22, PALM SPRINGS, CA 922620000
Latitude :	33.15170219
Longitude :	-117.19767969

Map Id: C26
Direction: W
Distance: 0.109 mi., 577 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : PALM SPRINGS OIL CO (CHEVRON) | APRO LLC DBA UNITED PACIFIC 0658 | 1X CHEVRON USA INC #9-3496
110 S RANCHO SANTA FE RD | 110 RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 258087
EPA ID: N/R

HAZNET - CA ***(cont.)***

Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	2002: 343 - Unspecified organic liquid mixture, 0.187 tons to CAD982444481

HIST HAZNET - CA

Facility Name :	1X CHEVRON USA INC #9-3496
Facility Address :	110 RANCHO SANTA FE RD, SAN MARCOS, 92069
ID Number :	CAC000039503
Last Date in Agency List :	2014-11-17

HWG - CA

Facility Name :	1X CHEVRON USA INC #9-3496
Facility Address :	110 RANCHO SANTA FE RD, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAC000039503
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	PO BOX 2833, LA HABRA, CA 906320000
Owner Name :	N/R
Owner Address :	N/A
Operator Name :	JIM HAYNES, MKTG ASSISTANT
Operator Address :	N/A
Latitude :	33.150764
Longitude :	-117.197946
Facility Name :	APRO LLC DBA UNITED PACIFIC 0658
Facility Address :	110 S RANCHO SANTA FE RD, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAL000453927
Status :	Active
Category :	STATE

Map Id: C26
Direction: W
Distance: 0.109 mi., 577 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : PALM SPRINGS OIL CO (CHEVRON) | APRO LLC DBA UNITED PACIFIC 0658 | 1X CHEVRON USA INC #9-3496
110 S RANCHO SANTA FE RD | 110 RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 258087
EPA ID: N/R

HWG - CA ***(cont.)***

Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	4130 COVER ST, LONG BEACH, CA 90808
Owner Name :	APRO LLC DBA UNITED PACIFIC
Owner Address :	4130 COVER ST, LONG BEACH, CA 90808
Operator Name :	UMANGDEEP SINGH
Operator Address :	4130COVER ST, LONG BEACH, CA 90808
Latitude :	33.148809
Longitude :	-117.199413

Facility Name :	PALM SPRINGS OIL CO
Facility Address :	110 RANCHO SANTA FE RD, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAC001171536
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	3410 E FOOTHILL BLVD, PASADENA, CA 911070000
Owner Name :	PALM SPRINGS OIL COMPANY INC
Owner Address :	110 RANCHO SANTA FE RD, SAN MARCOS, CA 920690000
Operator Name :	STREVEN ANENBERG/CHIEF EXEC OF
Operator Address :	110 RANCHO SANTA FE RD, SAN MARCOS, CA 920690000
Latitude :	33.150764
Longitude :	-117.197946

EPA ID :	CAC002312513
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	155 S PALM CANYON #B22, PALM SPRINGS, CA 922620000
Owner Name :	PALM SPRINGS OIL COMPANY INC
Owner Address :	155 S PALM CANYON #B22, PALM SPRINGS, CA 922620000
Operator Name :	CAROL PINEDA-OFFICE MGR
Operator Address :	155 S PALM CANYON #B22, PALM SPRINGS, CA 922620000
Latitude :	33.150764
Longitude :	-117.197946

LUST REG 9 - CA

Facility Name :	PALM SPRINGS OIL CO (CHEVRON)
Facility Address :	110 S RANCHO SANTA FE RD, SAN MARCOS, CA 920692502

Map Id: C26
Direction: W
Distance: 0.109 mi., 577 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : PALM SPRINGS OIL CO (CHEVRON) | APRO LLC DBA UNITED PACIFIC 0658 | 1X CHEVRON USA INC #9-3496
110 S RANCHO SANTA FE RD | 110 RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 258087
EPA ID: N/R

LUST REG 9 - CA ***(cont.)***

County :	San Diego

Site Details

Status Date :	2019-11-07
Status :	Completed - Case Closed
Begin Date :	1987-12-04
Global ID :	T0607303122
Region :	REGION 9
Site History :	This case was opened after receiving the results of soil and groundwater data collected after the removal of the underground storage tanks on November 2, 1987. Petroleum hydrocarbons were detected in soil and groundwater samples collected from the tank excavation. Please see Environmental Data Tab for additional information.
RB Case Number :	9UT878
Potential Media Affected :	Aquifer used for drinking water supply
Potential Contaminants of Concern :	Gasoline
Local Agency :	N/R
Local Case Number :	N/R
Lead Agency :	SAN DIEGO RWQCB (REGION 9)
File Location :	Regional Board
CUF Case :	YES
Caseworker :	LT
Case Type :	LUST Cleanup Site
How Discovered :	UST System Modification
How Discovered Description :	N/R
Stop Method :	Close and Replace Tank
Stop Description :	CLOSE AND REPLACE TANK
Calwater Watershed Name :	Carlsbad - San Marcos - Richland (904.52)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)
Disadvantaged Community :	N/R
Latitude :	33.148811
Longitude :	-117.199372
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-11

Contacts Summary

Global ID :	T0607303122
Contact Name :	LALITHA THOTAKURA
Contact Type :	Regional Board Caseworker
Organization Name :	SAN DIEGO RWQCB (REGION 9)
Address :	2375 NORTHSIDE DRIVE, SUITE 100

Map Id: C26
Direction: W
Distance: 0.109 mi., 577 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : PALM SPRINGS OIL CO (CHEVRON) | APRO LLC DBA UNITED PACIFIC 0658 | 1X CHEVRON USA INC #9-3496
110 S RANCHO SANTA FE RD | 110 RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 258087
EPA ID: N/R

LUST REG 9 - CA ***(cont.)***

City :	SAN DIEGO
Phone Number :	6195213002
Email :	lalitha.thotakura@waterboards.ca.gov

Regulatory Activities

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Date :	2019-11-07
Global ID :	T0607303122
Action Type :	ENFORCEMENT
Action :	Closure/No Further Action Letter

Date :	2019-06-28
Global ID :	T0607303122
Action Type :	RESPONSE
Action :	Well Destruction Report

Date :	2019-01-18
Global ID :	T0607303122
Action Type :	ENFORCEMENT
Action :	Staff Letter

Date :	2018-11-05
Global ID :	T0607303122
Action Type :	ENFORCEMENT
Action :	Notification - Public Notice of Case Closure

Date :	2018-10-03
Global ID :	T0607303122
Action Type :	ENFORCEMENT
Action :	Notification - Preclosure

Date :	2018-08-03
Global ID :	T0607303122
Action Type :	RESPONSE
Action :	Technical Memos

Map Id: C26
Direction: W
Distance: 0.109 mi., 577 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : PALM SPRINGS OIL CO (CHEVRON) | APRO LLC DBA UNITED PACIFIC 0658 | 1X CHEVRON USA INC #9-3496
110 S RANCHO SANTA FE RD | 110 RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 258087
EPA ID: N/R

LUST REG 9 - CA ***(cont.)***

Date : 2018-07-30
Global ID : T0607303122
Action Type : RESPONSE
Action : Monitoring Report - Semi-Annually

Date : 2018-01-24
Global ID : T0607303122
Action Type : RESPONSE
Action : Monitoring Report - Semi-Annually

Date : 2017-10-11
Global ID : T0607303122
Action Type : RESPONSE
Action : Correspondence

Date : 2017-08-18
Global ID : T0607303122
Action Type : ENFORCEMENT
Action : Clean Up Fund - Case Closure Review Summary Report (RSR)

Status History

Status Date : 2019-11-07
Global ID : T0607303122
Status : Completed - Case Closed

Status Date : 1987-12-04
Global ID : T0607303122
Status : Open - Remediation

Status Date : 1987-12-04
Global ID : T0607303122
Status : Open - Case Begin Date

MANIFEST EPA

Manifest Details

Manifest Number : 023393039JJK
Shipped Date : 2021-07-12
Updated Date : 2021-08-17
Received Date : 2021-07-22

Map Id: C26
Direction: W
Distance: 0.109 mi., 577 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : PALM SPRINGS OIL CO (CHEVRON) | APRO LLC DBA UNITED PACIFIC 0658 | 1X CHEVRON USA INC #9-3496
110 S RANCHO SANTA FE RD | 110 RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 258087
EPA ID: N/R

MANIFEST EPA ***(cont.)***

Status :	Signed
Generator ID :	CAL000453927
Generator Name :	APRO LLC DBA UNITED PACIFIC 0658
Generator Address :	110 S RANCHO SANTA FE RD, SAN MARCOS, CA 92069
Generator Mailing :	4130 COVER ST, LONG BEACH, CA 90808
Generator Contact :	N/R
Destination ID :	CAD028409019
Destination Name :	CROSBY & OVERTON
Destination Mailing :	1630 W. 17TH STREET CA90813 CA037US 1630, LONG BEACH, CA 90813
Destination Address :	1630 W. 17TH STREET, LONG BEACH, CA 90813-0000
Destination Contact :	N/R
Submission Type :	DataImage5Copy
Origin Type :	Web
Manifest Residue :	N
Rejection :	N
Last Date in Agency List :	2022-01-14

Waste Details

Waste Line Number :	1
Is DOT Hazardous :	N
DOT ID Number :	N/R
DOT Information :	N/R
Non Waste Description :	NON RCRA HAZARDOUS WASTE SOLID
Quantity :	100 Pounds
Quantity Tons, Acute, Non-Acute :	0.05, 0, 0.05
Quantity Kg, Acute, Non-Acute :	0, 45.3515
Management Method :	H141 - STORAGE, BULKING AND/OR TRANSFER OFF SITE
Is EPA Waste :	N
Federal Code :	N/R
State Code :	CA - 352

Manifest Details

Manifest Number :	023393049JJK
Shipped Date :	2021-07-12
Updated Date :	2021-08-16
Received Date :	2021-07-22
Status :	Signed
Generator ID :	CAL000453927
Generator Name :	UNITED PACIFIC CO
Generator Address :	110 S RANCHO SANTA FE RD, SAN MARCOS, CA 92069
Generator Mailing :	4130 COVER ST, LONG BEACH, CA 90808
Generator Contact :	N/R
Destination ID :	CAD028409019

Map Id: C26
Direction: W
Distance: 0.109 mi., 577 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : PALM SPRINGS OIL CO (CHEVRON) | APRO LLC DBA UNITED PACIFIC 0658 | 1X CHEVRON USA INC #9-3496
110 S RANCHO SANTA FE RD | 110 RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 258087
EPA ID: N/R

MANIFEST EPA ***(cont.)***

Destination Name :	CROSBY & OVERTON
Destination Mailing :	1630 W. 17TH STREET CA90813 CA037US 1630, LONG BEACH, CA 90813
Destination Address :	1630 W. 17TH STREET, LONG BEACH, CA 90813-0000
Destination Contact :	N/R
Submission Type :	DataImage5Copy
Origin Type :	Web
Manifest Residue :	N
Rejection :	N
Last Date in Agency List :	2022-01-14

Waste Details

Waste Line Number :	1
Is DOT Hazardous :	N
DOT ID Number :	N/R
DOT Information :	N/R
Non Waste Description :	NON RCRA HAZARDOUS WASTE LIQUID
Quantity :	20 Gallons
Quantity Tons, Acute, Non-Acute :	0.083402835, 0, 0.083402835
Quantity Kg, Acute, Non-Acute :	0, 75.64887
Management Method :	H135 - DISCHARGE TO SEWER/POTW OR NPDES
Is EPA Waste :	N
Federal Code :	N/R
State Code :	CA - 241

RCRA_NONGEN

Facility Name :	APRO LLC DBA UNITED PACIFIC 0658
Facility Address :	110 S RANCHO SANTA FE RD, SAN MARCOS, CA 92069
County :	SAN DIEGO
Date Form Received by Agency :	2020-03-25
EPA ID :	CAL000453927
Mailing Address :	4130 COVER ST, LONG BEACH, CA 90808
Contact :	TOM ROBINS
Contact Address :	4130 COVER ST, LONG BEACH, CA 90808
Contact Country :	US
Contact Telephone :	310-323-3992
Contact Email :	TOM.ROBINS@UNITEDPACIFIC.COM
EPA Region :	09
Land Type :	Private
Source Type :	Implementer
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2022-01-26

Map Id: C26
Direction: W
Distance: 0.109 mi., 577 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : PALM SPRINGS OIL CO (CHEVRON) | APRO LLC DBA UNITED PACIFIC 0658 | 1X CHEVRON USA INC #9-3496
110 S RANCHO SANTA FE RD | 110 RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 258087
EPA ID: N/R

RCRA_NONGEN ***(cont.)***

Owner/Operator Summary

Owner/Operator Name :	APRO LLC DBA UNITED PACIFIC
Owner/Operator Address :	4130 COVER ST, LONG BEACH, CA 90808
Owner/Operator Country :	US
Owner/Operator Telephone :	310-323-3992
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Private
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Owner/Operator Name :	APRO LLC DBA UNITED PACIFIC
Owner/Operator Address :	4130 COVER ST, LONG BEACH, CA 90808
Owner/Operator Country :	US
Owner/Operator Telephone :	310-323-3992
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Private
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N/R
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Map Id: C26
Direction: W
Distance: 0.109 mi., 577 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : PALM SPRINGS OIL CO (CHEVRON) | APRO LLC DBA UNITED PACIFIC 0658 | 1X CHEVRON USA INC #9-3496
110 S RANCHO SANTA FE RD | 110 RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 258087
EPA ID: N/R

RCRA_NONGEN ***(cont.)***

Notices of Violations Summary
Regulation Violated : N

UST - CA

Facility Name : PALM SPRINGS OIL CO (CHEVRON)
Facility Address : 110 S RANCHO SANTA FE RD, SAN MARCOS, 92069
County : San Diego

Facility ID : H13261
CERS ID : N/R
Permitting Agency : SAN DIEGO COUNTY
Latitude : 33.15092
Longitude : -117.19798
Last Date in Agency List : 2017-01-13

Map Id: C27
Direction: W
Distance: 0.110 mi., 584 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : SIERRRA PRINT AND DESIGN INC | ALTA VISTA DENTAL | TOREY PRESTERA MD
100 N RANCHO SANTA FE RD | 100 N RANCHO SANTA FE RD #127 | 100 N RANCHO SANTA FE RD STE 123
SAN MARCOS, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, ICIS]

Envirosite ID: 279225
EPA ID: N/R

CALEPA SITES - CA

Facility Name : ALTA VISTA DENTAL
Facility Address : 100 N RANCHO SANTA FE RD STE 123, SAN MARCOS, 92069

Site ID : 4742
EI ID : 10376314
EI Description : Chemical Storage Facilities
Latitude : 33.151730
Longitude : -117.198770
Agency Hyperlink : Click here for hyperlink provided by the agency.

Map Id: C27
Direction: W
Distance: 0.110 mi., 584 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : SIERRRA PRINT AND DESIGN INC | ALTA VISTA DENTAL | TOREY PRESTERA MD
100 N RANCHO SANTA FE RD | 100 N RANCHO SANTA FE RD #127 | 100 N RANCHO SANTA FE RD STE 123
SAN MARCOS, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, ICIS] ***(cont.)***

Envirosite ID: 279225
EPA ID: N/R

CALEPA SITES - CA ***(cont.)***

Last Date in Agency List : 2022-01-07

Facility Name : SAN MARCOS ANIMAL MEDICAL CENTER
Facility Address : 100 N RANCHO SANTA FE RD STE 133, SAN MARCOS, 92069

Site ID : 374982
EI ID : 10376557
EI Description : Chemical Storage Facilities
Latitude : 33.151730
Longitude : -117.198770
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2019-07-24

Facility Name : TOREY PRESTERA MD
Facility Address : 100 N RANCHO SANTA FE RD STE 126, SAN MARCOS, 92069

Site ID : 362159
EI ID : 10376038
EI Description : Chemical Storage Facilities
Latitude : 33.151730
Longitude : -117.198770
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-01-07

CIWQS - CA

Facility Name : SIERRRA PRINT AND DESIGN INC
Facility Address : 100 N RANCHO SANTA FE RD #127, SAN MARCOS, CA 92069
County : SAN DIEGO

Place ID : S808174
Agency Name : SIERRRA PRINT AND DESIGN INC
Last Date in Agency List : 2021-12-30

ECHO

Facility Name : SIERRRA PRINT AND DESIGN INC
Facility Address : 100 N RANCHO SANTA FE RD #127, SAN MARCOS, CA 92069
County : SAN DIEGO COUNTY

Last Inspection Date : N/R
Registry ID : 110070085001
FIPS Code : N/R
EPA Region : 09
Inspection Count : 0

Map Id: C27
Direction: W
Distance: 0.110 mi., 584 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : SIERRRA PRINT AND DESIGN INC | ALTA VISTA DENTAL | TOREY PRESTERA MD
100 N RANCHO SANTA FE RD | 100 N RANCHO SANTA FE RD #127 | 100 N RANCHO SANTA FE RD STE 123
SAN MARCOS, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, ICIS] ***(cont.)***

Envirosite ID: 279225
EPA ID: N/R

ECHO ***(cont.)***

Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	N/R
Three-Year Compliance Status :	N/R
Collection Method :	Zip Code Centroid
Reference Point :	N/R
Accuracy Meters :	10000
Derived Tribes :	N/R
Derived HUC :	N/R
Derived WBD :	N/R
Derived STCTY FIPS :	N/R
Derived Zip :	N/R
Derived CD113 :	N/R
Derived CB2010 :	N/R
MYRTK Universe :	NNN
NPDES IDs :	CAW412468
CWA Permit Types :	Minor
CWA Compliance Tracking :	N/R
CWA NAICS :	N/R
CWA SICS :	N/R
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	0
CWA Current Compliance Status :	Not Applicable
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	N/R
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	N/R
Facility NAICS :	N/R
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R

Map Id: C27
Direction: W
Distance: 0.110 mi., 584 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : SIERRRA PRINT AND DESIGN INC | ALTA VISTA DENTAL | TOREY PRESTERA MD
100 N RANCHO SANTA FE RD | 100 N RANCHO SANTA FE RD #127 | 100 N RANCHO SANTA FE RD STE 123
SAN MARCOS, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, ICIS] ***(cont.)***

Envirosite ID: 279225
EPA ID: N/R

ECHO ***(cont.)***

Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	N/R
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	Y
SDWIS Flag :	N
RCRA Flag :	N
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	N/R
NAA Flag :	N
Latitude :	33.194075
Longitude :	-117.16177
Last Date in Agency List :	2022-01-17

FRS

Facility Name :	ALTA VISTA DENTAL
Facility Address :	100 N RANCHO SANTA FE RD STE 123, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Registry ID :	110065262600
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Source Description

Source Description :

The California Environmental Protection Agency (CalEPA) has recently implemented a new data warehouse system (nSite). This data warehouse combines and merges facility and site information from five different systems managed within CalEPA. The five systems are: California Environmental Reporting System (CERS), EnviroStor, GeoTracker, California Integrated Water Quality System (CIWQS), and Toxic Release Inventory (TRI).

FRS Environmental Interest

Source and System ID :	CA-ENVIROVIEW - 4742

Map Id: C27
Direction: W
Distance: 0.110 mi., 584 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : SIERRRA PRINT AND DESIGN INC | ALTA VISTA DENTAL | TOREY PRESTERA MD
100 N RANCHO SANTA FE RD | 100 N RANCHO SANTA FE RD #127 | 100 N RANCHO SANTA FE RD STE 123
SAN MARCOS, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, ICIS] ***(cont.)***

Envirosite ID: 279225
EPA ID: N/R

FRS ***(cont.)***

Facility Name : SIERRRA PRINT AND DESIGN INC
Facility Address : 100 N RANCHO SANTA FE RD #127, SAN MARCOS, CA 92069
County : SAN DIEGO COUNTY

Site Details
Registry ID : 110070085001
FRS Facility URL : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-02-17

Source Description

Source Description :

The NPDES module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

FRS Environmental Interest
Source and System ID : ICIS - CAW412468

HAZMAT_SAN DIEGO COUNTY - CA

Facility Name : ALPHA GRAPHICS 554
Facility Address : 100 N RANCHO SANTA FE RD, CA

Date : 2003-09-12
Record ID : DEH2003-HUPFP-202443
Record Type : Unified Program Facility Permit
Status : Completed
Action : N/R
Short Notes : N/R
Last Date in Agency List : 2015-11-23

Facility Name : ALTA VISTA DENTAL
Facility Address : 100 N RANCHO SANTA FE RD, SUITE 123, SAN MARCOS, CA 92069

Date : 2008-10-23
Record ID : DEH2008-HUPFP-209826
Record Type : Unified Program Facility Permit
Status : Permit Renewed

Map Id: C27
Direction: W
Distance: 0.110 mi., 584 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : SIERRRA PRINT AND DESIGN INC | ALTA VISTA DENTAL | TOREY PRESTERA MD
100 N RANCHO SANTA FE RD | 100 N RANCHO SANTA FE RD #127 | 100 N RANCHO SANTA FE RD STE 123
SAN MARCOS, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, ICIS] ***(cont.)***

Envirosite ID: 279225
EPA ID: N/R

HAZMAT_SAN DIEGO COUNTY - CA ***(cont.)***

Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23
Facility Name :	AT&T MOBILITY
Facility Address :	100 N RANCHO SANTA FE RD, SAN MARCOS, CA 92069
Date :	2011-11-10
Record ID :	DEH2011-HUPFP-215736
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23
Facility Name :	BAYSHORE PREP
Facility Address :	100 N RANCHO SANTA FE RD, SAN MARCOS, CA 92069
Date :	2010-09-03
Record ID :	DEH2010-HUPFP-212730
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23
Facility Name :	CALIFORNIA VETERINARY SPEC
Facility Address :	100 N RANCHO SANTA FE RD, CA
Date :	2004-02-25
Record ID :	DEH2004-HUPFP-203151
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23
Date :	2002-05-04
Record ID :	DEH2002-HUPFP-137154
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23

Map Id: C27
Direction: W
Distance: 0.110 mi., 584 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : SIERRRA PRINT AND DESIGN INC | ALTA VISTA DENTAL | TOREY PRESTERA MD
100 N RANCHO SANTA FE RD | 100 N RANCHO SANTA FE RD #127 | 100 N RANCHO SANTA FE RD STE 123
SAN MARCOS, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, ICIS] ***(cont.)***

Envirosite ID: 279225
EPA ID: N/R

HAZMAT_SAN DIEGO COUNTY - CA ***(cont.)***

Facility Name : FAMILY DENTAL PRACTICE OF SAN MARCOS
Facility Address : 100 N RANCHO SANTA FE RD, CA

Date : 2003-10-01
Record ID : DEH2003-HUPFP-202527
Record Type : Unified Program Facility Permit
Status : Completed
Action : N/R
Short Notes : N/R
Last Date in Agency List : 2015-11-23

Facility Name : SAN MARCOS ANIMAL MEDICAL CENTER
Facility Address : 100 N RANCHO SANTA FE RD, SUITE 133, SAN MARCOS, CA 92069

Date : 2011-07-20
Record ID : DEH2011-HUPFP-215312
Record Type : Unified Program Facility Permit
Status : Expired
Action : Pay Fees Due
Short Notes : N/R
Last Date in Agency List : 2015-11-23

Facility Name : TOREY PRESTERA MD
Facility Address : 100 N RANCHO SANTA FE RD, SUITE 126, SAN MARCOS, CA 92069

Date : 2003-02-06
Record ID : DEH2003-HUPFP-201336
Record Type : Unified Program Facility Permit
Status : Expired
Action : Pay Fees Due
Short Notes : N/R
Last Date in Agency List : 2015-11-23

ICIS

Facility Name : SIERRRA PRINT AND DESIGN INC
Facility Address : 100 N RANCHO SANTA FE RD #127, SAN MARCOS, CA 92069

Site Details
NPDES ID : CAW412468
ICIS Facility Interest ID : 3600737416
Facility UIN : 110070085001
Facility Type Code : N/R
Impaired Waters : N/R

Map Id: C27
Direction: W
Distance: 0.110 mi., 584 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : SIERRRA PRINT AND DESIGN INC | ALTA VISTA DENTAL | TOREY PRESTERA MD
100 N RANCHO SANTA FE RD | 100 N RANCHO SANTA FE RD #127 | 100 N RANCHO SANTA FE RD STE 123
SAN MARCOS, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, ICIS] ***(cont.)***

Envirosite ID: 279225
EPA ID: N/R

ICIS ***(cont.)***

Latitude :	N/R
Longitude :	N/R
Last Date in Agency List :	2022-01-12

Map Id: C28
Direction: W
Distance: 0.116 mi., 615 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : RANCHO SANTA FE EXXON | COASTAL TRANSPORT CO | GSE San Marcos 851632
112 N RANCHO SANTA FE RD | 112 RANCHO SANTA FE DR
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, EPA LUST, HAZNET - CA, HWG - CA, LUST REG 9 - CA]

Envirosite ID: 41123805
EPA ID: N/R

CALEPA SITES - CA

Facility Name :	GSE San Marcos 851632
Facility Address :	112 N RANCHO SANTA FE RD, SAN MARCOS, 92069
Site ID :	60393
EI ID :	10376716
EI Description :	Chemical Storage Facilities
Latitude :	33.150982
Longitude :	-117.198012
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2019-07-24
Site ID :	60393
EI ID :	10376716
EI Description :	Hazardous Waste Generator
Latitude :	33.150982
Longitude :	-117.198012
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2019-07-24
Site ID :	60393
EI ID :	10376716
EI Description :	Underground Storage Tank
Latitude :	33.150982
Longitude :	-117.198012
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2019-07-24

Map Id: C28
Direction: W
Distance: 0.116 mi., 615 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : RANCHO SANTA FE EXXON | COASTAL TRANSPORT CO | GSE San Marcos 851632
112 N RANCHO SANTA FE RD | 112 RANCHO SANTA FE DR
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, EPA LUST, HAZNET - CA, HWG - CA, LUST REG 9 - CA] ***(cont.)***

Envirosite ID: 41123805
EPA ID: N/R

CALEPA SITES - CA ***(cont.)***

Facility Name :	RANCHO SANTA FE EXXON
Facility Address :	112 N RANCHO SANTA FE RD, SAN MARCOS, 920691218
Site ID :	218725
EI ID :	T0607302478
EI Description :	Leaking Underground Storage Tank Cleanup Site
Latitude :	33.149556
Longitude :	-117.199069
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07
Facility Name :	RANCHO SANTA FE EXXON
Facility Address :	112 N.RANCHO SANTA FE RD, SAN MARCOS, 92069-121
Site ID :	214650
EI ID :	T0619784179
EI Description :	Leaking Underground Storage Tank Cleanup Site
Latitude :	33.149612
Longitude :	-117.198827
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07

CASE LIST_SAN DIEGO COUNTY - CA

Facility Name :	RANCHO SANTA FE EXXON
Facility Address :	112 N RANCHO SANTA FE RD, SAN MARCOS, CA 920691218
County :	San Diego

Site Details

Status Date :	2021-12-07
Status :	Completed - Case Closed
Begin Date :	1998-08-20
Global ID :	T0607302478

Site History :

Gasoline contaminated soil was discovered during a Phase II Environmental Assessment conducted in 1998. Thirteen soil borings were drilled and soil samples were collected as part of the Phase II investigation. Total petroleum hydrocarbons as gasoline (TPHg)were detected at 1,000 mg/kg and BTEX and MTBE were also detected in soil samples. Groundwater monitoring wells were installed in 2000. TPHg, BTex and MTBE at 1,000 ug/l were detected in groundwater samples. See Environmental Data Tab for additional information.

RB Case Number :	9UT3709
Potential Media Affected :	Aquifer used for drinking water supply
Potential Contaminants of Concern :	Gasoline
Local Agency :	SAN DIEGO COUNTY LOP
Local Case Number :	N/R

Map Id: C28
Direction: W
Distance: 0.116 mi., 615 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : RANCHO SANTA FE EXXON | COASTAL TRANSPORT CO | GSE San Marcos 851632
112 N RANCHO SANTA FE RD | 112 RANCHO SANTA FE DR
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, EPA LUST, HAZNET - CA, HWG - CA, LUST REG 9 - CA] ***(cont.)***

Envirosite ID: 41123805
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Lead Agency :	SAN DIEGO RWQCB (REGION 9)
File Location :	Regional Board
CUF Case :	NO
Caseworker :	LT
Case Type :	LUST Cleanup Site
How Discovered :	UST System Modification
How Discovered Description :	N/R
Stop Method :	Other Means
Stop Description :	OTHER MEANS
Calwater Watershed Name :	Carlsbad - Agua Hedionda - Buena (904.32)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)
Disadvantaged Community :	N/R
Latitude :	33.149556
Longitude :	-117.19907
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-09

Contacts Summary

Global ID :	T0607302478
Contact Name :	LALITHA THOTAKURA
Contact Type :	Regional Board Caseworker
Organization Name :	SAN DIEGO RWQCB (REGION 9)
Address :	2375 NORTHSIDE DRIVE, SUITE 100
City :	SAN DIEGO
Phone Number :	6195213002
Email :	lalitha.thotakura@waterboards.ca.gov

Global ID :	T0607302478
Contact Name :	CAROL FENNER
Contact Type :	Local Agency Caseworker
Organization Name :	SAN DIEGO COUNTY LOP
Address :	P.O. Box 129261
City :	San Diego
Phone Number :	N/R
Email :	carol.fenner@sdcounty.ca.gov

Regulatory Activities

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Date :	2021-12-06
Global ID :	T0607302478
Action Type :	ENFORCEMENT
Action :	Closure/No Further Action Letter

Map Id: C28
Direction: W
Distance: 0.116 mi., 615 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : RANCHO SANTA FE EXXON | COASTAL TRANSPORT CO | GSE San Marcos 851632
112 N RANCHO SANTA FE RD | 112 RANCHO SANTA FE DR
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, EPA LUST, HAZNET - CA, HWG - CA, LUST REG 9 - CA] ***(cont.)***

Envirosite ID: 41123805
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Date :	2021-05-14
Global ID :	T0607302478
Action Type :	RESPONSE
Action :	Well Destruction Report
Date :	2021-04-06
Global ID :	T0607302478
Action Type :	ENFORCEMENT
Action :	Email Correspondence
Date :	2021-02-24
Global ID :	T0607302478
Action Type :	ENFORCEMENT
Action :	Clean Up Fund - Case Closure Review Summary Report (RSR)
Date :	2021-01-04
Global ID :	T0607302478
Action Type :	RESPONSE
Action :	Soil Vapor Intrusion Investigation Report
Date :	2020-12-21
Global ID :	T0607302478
Action Type :	ENFORCEMENT
Action :	Other Report
Date :	2020-10-19
Global ID :	T0607302478
Action Type :	ENFORCEMENT
Action :	Other Report
Date :	2020-10-06
Global ID :	T0607302478
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other
Date :	2020-09-29
Global ID :	T0607302478
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other
Date :	2020-08-26
Global ID :	T0607302478
Action Type :	RESPONSE
Action :	Soil Vapor Intrusion Investigation Report - Regulator Responded

Map Id: C28
Direction: W
Distance: 0.116 mi., 615 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : RANCHO SANTA FE EXXON | COASTAL TRANSPORT CO | GSE San Marcos 851632
112 N RANCHO SANTA FE RD | 112 RANCHO SANTA FE DR
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, EPA LUST, HAZNET - CA, HWG - CA, LUST REG 9 - CA] ***(cont.)***

Envirosite ID: 41123805
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Status History

Status Date :	2021-12-07
Global ID :	T0607302478
Status :	Completed - Case Closed
Status Date :	2018-11-05
Global ID :	T0607302478
Status :	Open - Eligible for Closure
Status Date :	2000-11-17
Global ID :	T0607302478
Status :	Open - Remediation
Status Date :	1998-08-20
Global ID :	T0607302478
Status :	Open - Case Begin Date
Facility Name :	RANCHO SANTA FE EXXON
Facility Address :	112 N.RANCHO SANTA FE RD, SAN MARCOS, CA 92069-121
County :	San Diego

Site Details

Status Date :	2021-04-23
Status :	Open - Verification Monitoring
Begin Date :	2007-03-20
Global ID :	T0619784179
Site History :	An older single walled underground storage tank was thought to have been ruptured during fuel delivery and approximately 6,000 gallons of diesel fuel were released to the subsurface on March 20, 2007. See Environmental Data Tab for additional information. This case is under consideration for either to combine it with case # T0607302478 (H03229-001) or handle it seperately.
RB Case Number :	N/R
Potential Media Affected :	Aquifer used for drinking water supply
Potential Contaminants of Concern :	Diesel
Local Agency :	N/R
Local Case Number :	N/R
Lead Agency :	SAN DIEGO RWQCB (REGION 9)
File Location :	Regional Board
CUF Case :	YES
Caseworker :	LT
Case Type :	LUST Cleanup Site
How Discovered :	Automatic Tank Gauging, Inventory Control
How Discovered Description :	ALARMS FROM ATG

Map Id: C28
Direction: W
Distance: 0.116 mi., 615 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : RANCHO SANTA FE EXXON | COASTAL TRANSPORT CO | GSE San Marcos 851632
112 N RANCHO SANTA FE RD | 112 RANCHO SANTA FE DR
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, EPA LUST, HAZNET - CA, HWG - CA, LUST REG 9 - CA] ***(cont.)***

Envirosite ID: 41123805
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Stop Method :	Remove Contents
Stop Description :	REMOVE CONTENTS - VACUUM EXTRACTION
Calwater Watershed Name :	Carlsbad - Agua Hedionda - Buena (904.32)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)
Disadvantaged Community :	N/R
Latitude :	33.149612
Longitude :	-117.198827
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-09

Contacts Summary

Global ID :	T0619784179
Contact Name :	LALITHA THOTAKURA
Contact Type :	Regional Board Caseworker
Organization Name :	SAN DIEGO RWQCB (REGION 9)
Address :	2375 NORTHSIDE DRIVE, SUITE 100
City :	SAN DIEGO
Phone Number :	6195213002
Email :	lalitha.thotakura@waterboards.ca.gov

Regulatory Activities

Date :	2021-11-05
Global ID :	T0619784179
Action Type :	RESPONSE
Action :	Monitoring Report - Quarterly
Date :	2021-06-09
Global ID :	T0619784179
Action Type :	ENFORCEMENT
Action :	Email Correspondence
Date :	2021-04-27
Global ID :	T0619784179
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other
Date :	2021-04-23
Global ID :	T0619784179
Action Type :	ENFORCEMENT
Action :	Clean Up Fund - Case Closure Review Summary Report (RSR)
Date :	2021-03-02
Global ID :	T0619784179
Action Type :	RESPONSE

Map Id: C28
Direction: W
Distance: 0.116 mi., 615 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : RANCHO SANTA FE EXXON | COASTAL TRANSPORT CO | GSE San Marcos 851632
112 N RANCHO SANTA FE RD | 112 RANCHO SANTA FE DR
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, EPA LUST, HAZNET - CA, HWG - CA, LUST REG 9 - CA] ***(cont.)***

Envirosite ID: 41123805
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Action : Site Investigation Workplan - Regulator Responded

Date : 2020-09-15
Global ID : T0619784179
Action Type : ENFORCEMENT
Action : Email Correspondence

Date : 2020-07-20
Global ID : T0619784179
Action Type : RESPONSE
Action : Other Workplan - Regulator Responded

Date : 2019-12-02
Global ID : T0619784179
Action Type : ENFORCEMENT
Action : Staff Letter

Date : 2019-10-04
Global ID : T0619784179
Action Type : RESPONSE
Action : Request for Closure - Regulator Responded

Date : 2019-04-10
Global ID : T0619784179
Action Type : RESPONSE
Action : Monitoring Report - Quarterly

Status History

Status Date : 2021-04-23
Global ID : T0619784179
Status : Open - Verification Monitoring

Status Date : 2017-07-10
Global ID : T0619784179
Status : Open - Remediation

Status Date : 2007-03-20
Global ID : T0619784179
Status : Open - Case Begin Date

Status Date : 2007-03-20
Global ID : T0619784179

Map Id: C28
Direction: W
Distance: 0.116 mi., 615 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : RANCHO SANTA FE EXXON | COASTAL TRANSPORT CO | GSE San Marcos 851632
112 N RANCHO SANTA FE RD | 112 RANCHO SANTA FE DR
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, EPA LUST, HAZNET - CA, HWG - CA, LUST REG 9 - CA] ***(cont.)***

Envirosite ID: 41123805
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Status :	Open - Site Assessment

EPA LUST

Facility Name :	RANCHO SANTA FE EXXON
Facility Address :	112 N RANCHO SANTA FE RD, SAN MARCOS, California 920691218
County :	N/R
Facility ID :	N/R
LUST ID :	CAT0607302478
Reported Date :	N/R
Status :	Open
Substance :	N/R
Closed With Residual Contamination (Tribal Only):	N/R
NFA_Letter (Tribal Only) :	N/R
Tribe (Tribal Only) :	N/R
EPA Region :	9
Estimated Population within 1500ft :	2562
Estimated Private Domestic Wells within 1500ft:	0
Within Source Water Protection Area (SPA):	No
SPA Public Water System and Facility ID:	N/R
SPA Water Type :	N/R
SPA Facility Type :	N/R
SPA HUC12 :	N/R
Within Groundwater Wellhead Protection Area (WHPA):	No
WHPA Public Water System and Facility ID:	N/R
WHPA Water Type :	N/R
WHPA Facility Type :	N/R
WHPA HUC12 :	N/R
Within Estimated 100-year Floodplain:	No
Latitude :	33.151699999999899
Longitude :	-117.197680000000005
Last Date in Agency List :	2022-01-04
Facility Name :	RANCHO SANTA FE EXXON
Facility Address :	112 N.RANCHO SANTA FE RD, SAN MARCOS, California
County :	N/R
Facility ID :	N/R
LUST ID :	CAT0619784179
Reported Date :	N/R
Status :	Open
Substance :	N/R
Closed With Residual Contamination (Tribal Only):	N/R

Map Id: C28
Direction: W
Distance: 0.116 mi., 615 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : RANCHO SANTA FE EXXON | COASTAL TRANSPORT CO | GSE San Marcos 851632
112 N RANCHO SANTA FE RD | 112 RANCHO SANTA FE DR
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, EPA LUST, HAZNET - CA, HWG - CA, LUST REG 9 - CA] ***(cont.)***

Envirosite ID: 41123805
EPA ID: N/R

EPA LUST ***(cont.)***

NFA_Letter (Tribal Only) :	N/R
Tribe (Tribal Only) :	N/R
EPA Region :	9
Estimated Population within 1500ft :	2562
Estimated Private Domestic Wells within 1500ft:	0
Within Source Water Protection Area (SPA):	No
SPA Public Water System and Facility ID:	N/R
SPA Water Type :	N/R
SPA Facility Type :	N/R
SPA HUC12 :	N/R
Within Groundwater Wellhead Protection Area (WHPA):	No
WHPA Public Water System and Facility ID:	N/R
WHPA Water Type :	N/R
WHPA Facility Type :	N/R
WHPA HUC12 :	N/R
Within Estimated 100-year Floodplain:	No
Latitude :	33.151699999999899
Longitude :	-117.197680000000005
Last Date in Agency List :	2022-01-04

HAZNET - CA

Facility Name :	COASTAL TRANSPORT CO
Facility Address :	112 RANCHO SANTA FE DR, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAC002271081
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	9950 SAN DIEGO MISSION RD, SAN DIEGO, CA 921080000
Latitude :	33.15170540
Longitude :	-117.19767822
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HWG - CA

Facility Name :	COASTAL TRANSPORT CO
Facility Address :	112 RANCHO SANTA FE DR, SAN MARCOS, CA 92069
County :	SAN DIEGO

Map Id: C28
Direction: W
Distance: 0.116 mi., 615 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : RANCHO SANTA FE EXXON | COASTAL TRANSPORT CO | GSE San Marcos 851632
112 N RANCHO SANTA FE RD | 112 RANCHO SANTA FE DR
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, EPA LUST, HAZNET - CA, HWG - CA, LUST REG 9 - CA] ***(cont.)***

Envirosite ID: 41123805
EPA ID: N/R

HWG - CA ***(cont.)***

EPA ID :	CAC002271081
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	9950 SAN DIEGO MISSION RD, SAN DIEGO, CA 921080000
Owner Name :	COASTAL TRANSPORT CO
Owner Address :	9950 SAN DIEGO MISSION RD, SAN DIEGO, CA 921080000
Operator Name :	MATT PORTTERUS/FOSS ENV
Operator Address :	N/A
Latitude :	33.150789
Longitude :	-117.197934

LUST REG 9 - CA

Facility Name :	RANCHO SANTA FE EXXON
Facility Address :	112 N RANCHO SANTA FE RD, SAN MARCOS, CA 920691218
County :	San Diego

Site Details

Status Date :	2021-12-07
Status :	Completed - Case Closed
Begin Date :	1998-08-20
Global ID :	T0607302478
Region :	REGION 9

Site History :

Gasoline contaminated soil was discovered during a Phase II Environmental Assessment conducted in 1998. Thirteen soil borings were drilled and soil samples were collected as part of the Phase II investigation. Total petroleum hydrocarbons as gasoline (TPHg)were detected at 1,000 mg/kg and BTEX and MTBE were also detected in soil samples. Groundwater monitoring wells were installed in 2000. TPHg, BTex and MTBE at 1,000 ug/l were detected in groundwater samples. See Environmental Data Tab for additional information.

RB Case Number :	9UT3709
Potential Media Affected :	Aquifer used for drinking water supply
Potential Contaminants of Concern :	Gasoline
Local Agency :	SAN DIEGO COUNTY LOP
Local Case Number :	N/R
Lead Agency :	SAN DIEGO RWQCB (REGION 9)
File Location :	Regional Board
CUF Case :	NO
Caseworker :	LT
Case Type :	LUST Cleanup Site
How Discovered :	UST System Modification
How Discovered Description :	N/R
Stop Method :	Other Means
Stop Description :	OTHER MEANS
Calwater Watershed Name :	Carlsbad - Agua Hedionda - Buena (904.32)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)

Map Id: C28
Direction: W
Distance: 0.116 mi., 615 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : RANCHO SANTA FE EXXON | COASTAL TRANSPORT CO | GSE San Marcos 851632
112 N RANCHO SANTA FE RD | 112 RANCHO SANTA FE DR
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, EPA LUST, HAZNET - CA, HWG - CA, LUST REG 9 - CA] ***(cont.)***

Envirosite ID: 41123805
EPA ID: N/R

LUST REG 9 - CA ***(cont.)***

Disadvantaged Community :	N/R
Latitude :	33.149556
Longitude :	-117.19907
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-11

Contacts Summary

Global ID :	T0607302478
Contact Name :	LALITHA THOTAKURA
Contact Type :	Regional Board Caseworker
Organization Name :	SAN DIEGO RWQCB (REGION 9)
Address :	2375 NORTHSIDE DRIVE, SUITE 100
City :	SAN DIEGO
Phone Number :	6195213002
Email :	lalitha.thotakura@waterboards.ca.gov

Global ID :	T0607302478
Contact Name :	CAROL FENNER
Contact Type :	Local Agency Caseworker
Organization Name :	SAN DIEGO COUNTY LOP
Address :	P.O. Box 129261
City :	San Diego
Phone Number :	N/R
Email :	carol.fenner@sdcounty.ca.gov

Regulatory Activities

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Date :	2021-12-06
Global ID :	T0607302478
Action Type :	ENFORCEMENT
Action :	Closure/No Further Action Letter

Date :	2021-05-14
Global ID :	T0607302478
Action Type :	RESPONSE
Action :	Well Destruction Report

Date :	2021-04-06
Global ID :	T0607302478
Action Type :	ENFORCEMENT
Action :	Email Correspondence

Map Id: C28
Direction: W
Distance: 0.116 mi., 615 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : RANCHO SANTA FE EXXON | COASTAL TRANSPORT CO | GSE San Marcos 851632
112 N RANCHO SANTA FE RD | 112 RANCHO SANTA FE DR
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, EPA LUST, HAZNET - CA, HWG - CA, LUST REG 9 - CA] ***(cont.)***

Envirosite ID: 41123805
EPA ID: N/R

LUST REG 9 - CA ***(cont.)***

Date : 2021-02-24
Global ID : T0607302478
Action Type : ENFORCEMENT
Action : Clean Up Fund - Case Closure Review Summary Report (RSR)

Date : 2021-01-04
Global ID : T0607302478
Action Type : RESPONSE
Action : Soil Vapor Intrusion Investigation Report

Date : 2020-12-21
Global ID : T0607302478
Action Type : ENFORCEMENT
Action : Other Report

Date : 2020-10-19
Global ID : T0607302478
Action Type : ENFORCEMENT
Action : Other Report

Date : 2020-10-06
Global ID : T0607302478
Action Type : ENFORCEMENT
Action : Technical Correspondence / Assistance / Other

Date : 2020-09-29
Global ID : T0607302478
Action Type : ENFORCEMENT
Action : Technical Correspondence / Assistance / Other

Date : 2020-08-26
Global ID : T0607302478
Action Type : RESPONSE
Action : Soil Vapor Intrusion Investigation Report - Regulator Responded

Status History

Status Date : 2021-12-07
Global ID : T0607302478
Status : Completed - Case Closed

Status Date : 2018-11-05
Global ID : T0607302478
Status : Open - Eligible for Closure

Map Id: C28
Direction: W
Distance: 0.116 mi., 615 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : RANCHO SANTA FE EXXON | COASTAL TRANSPORT CO | GSE San Marcos 851632
112 N RANCHO SANTA FE RD | 112 RANCHO SANTA FE DR
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, EPA LUST, HAZNET - CA, HWG - CA, LUST REG 9 - CA] ***(cont.)***

Envirosite ID: 41123805
EPA ID: N/R

LUST REG 9 - CA ***(cont.)***

Status Date :	2000-11-17
Global ID :	T0607302478
Status :	Open - Remediation
Status Date :	1998-08-20
Global ID :	T0607302478
Status :	Open - Case Begin Date
Facility Name :	RANCHO SANTA FE EXXON
Facility Address :	112 N.RANCHO SANTA FE RD, SAN MARCOS, CA 92069-121
County :	San Diego

Site Details

Status Date :	2021-04-23
Status :	Open - Verification Monitoring
Begin Date :	2007-03-20
Global ID :	T0619784179
Region :	REGION 9
Site History :	An older single walled underground storage tank was thought to have been ruptured during fuel delivery and approximately 6,000 gallons of diesel fuel were released to the subsurface on March 20, 2007. See Environmental Data Tab for additional information. This case is under consideration for either to combine it with case # T0607302478 (H03229-001) or handle it seperately.
RB Case Number :	N/R
Potential Media Affected :	Aquifer used for drinking water supply
Potential Contaminants of Concern :	Diesel
Local Agency :	N/R
Local Case Number :	N/R
Lead Agency :	SAN DIEGO RWQCB (REGION 9)
File Location :	Regional Board
CUF Case :	YES
Caseworker :	LT
Case Type :	LUST Cleanup Site
How Discovered :	Automatic Tank Gauging, Inventory Control
How Discovered Description :	ALARMS FROM ATG
Stop Method :	Remove Contents
Stop Description :	REMOVE CONTENTS - VACUUM EXTRACTION
Calwater Watershed Name :	Carlsbad - Agua Hedionda - Buena (904.32)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)
Disadvantaged Community :	N/R
Latitude :	33.149612
Longitude :	-117.198827
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-11

Map Id: C28
Direction: W
Distance: 0.116 mi., 615 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : RANCHO SANTA FE EXXON | COASTAL TRANSPORT CO | GSE San Marcos 851632
112 N RANCHO SANTA FE RD | 112 RANCHO SANTA FE DR
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, EPA LUST, HAZNET - CA, HWG - CA, LUST REG 9 - CA] ***(cont.)***

Envirosite ID: 41123805
EPA ID: N/R

LUST REG 9 - CA ***(cont.)***

Contacts Summary

Global ID :	T0619784179
Contact Name :	LALITHA THOTAKURA
Contact Type :	Regional Board Caseworker
Organization Name :	SAN DIEGO RWQCB (REGION 9)
Address :	2375 NORTHSIDE DRIVE, SUITE 100
City :	SAN DIEGO
Phone Number :	6195213002
Email :	lalitha.thotakura@waterboards.ca.gov

Regulatory Activities

Date :	2021-11-05
Global ID :	T0619784179
Action Type :	RESPONSE
Action :	Monitoring Report - Quarterly
Date :	2021-06-09
Global ID :	T0619784179
Action Type :	ENFORCEMENT
Action :	Email Correspondence
Date :	2021-04-27
Global ID :	T0619784179
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other
Date :	2021-04-23
Global ID :	T0619784179
Action Type :	ENFORCEMENT
Action :	Clean Up Fund - Case Closure Review Summary Report (RSR)
Date :	2021-03-02
Global ID :	T0619784179
Action Type :	RESPONSE
Action :	Site Investigation Workplan - Regulator Responded
Date :	2020-09-15
Global ID :	T0619784179
Action Type :	ENFORCEMENT
Action :	Email Correspondence
Date :	2020-07-20
Global ID :	T0619784179
Action Type :	RESPONSE

Map Id: C28
Direction: W
Distance: 0.116 mi., 615 ft.
Elevation: 625 ft.
Relative: Higher

Site Name : RANCHO SANTA FE EXXON | COASTAL TRANSPORT CO | GSE San Marcos 851632
112 N RANCHO SANTA FE RD | 112 RANCHO SANTA FE DR
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, EPA LUST, HAZNET - CA, HWG - CA, LUST REG 9 - CA] ***(cont.)***

Envirosite ID: 41123805
EPA ID: N/R

LUST REG 9 - CA ***(cont.)***

Action : Other Workplan - Regulator Responded

Date : 2019-12-02
Global ID : T0619784179
Action Type : ENFORCEMENT
Action : Staff Letter

Date : 2019-10-04
Global ID : T0619784179
Action Type : RESPONSE
Action : Request for Closure - Regulator Responded

Date : 2019-04-10
Global ID : T0619784179
Action Type : RESPONSE
Action : Monitoring Report - Quarterly

Status History

Status Date : 2021-04-23
Global ID : T0619784179
Status : Open - Verification Monitoring

Status Date : 2017-07-10
Global ID : T0619784179
Status : Open - Remediation

Status Date : 2007-03-20
Global ID : T0619784179
Status : Open - Case Begin Date

Status Date : 2007-03-20
Global ID : T0619784179
Status : Open - Site Assessment

Map Id: E29
Direction: NW
Distance: 0.118 mi., 622 ft.
Elevation: 612 ft.
Relative: Higher

Site Name : TAMMY TRUAX
3542 DE LEONE RD
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HWG - CA, MANIFEST EPA, RCRA_NONGEN]

Envirosite ID: 42318428
EPA ID: N/R

ECHO

Facility Name :	TAMMY TRUAX
Facility Address :	3542 DE LEONE RD, SAN MARCOS, CA 92069
County :	SAN DIEGO
Last Inspection Date :	N/R
Registry ID :	110071103656
FIPS Code :	N/R
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	_____
Collection Method :	Zip Code Centroid
Reference Point :	N/R
Accuracy Meters :	10000
Derived Tribes :	N/R
Derived HUC :	N/R
Derived WBD :	N/R
Derived STCTY FIPS :	N/R
Derived Zip :	N/R
Derived CD113 :	N/R
Derived CB2010 :	N/R
MYRTK Universe :	NNN
NPDES IDs :	N/R
CWA Permit Types :	N/R
CWA Compliance Tracking :	N/R
CWA NAICS :	N/R
CWA SICS :	N/R
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	N/R
CWA Current Compliance Status :	N/R
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	N/R
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	N/R
Facility NAICS :	56299 - All Other Waste Management Services

Map Id: E29
Direction: NW
Distance: 0.118 mi., 622 ft.
Elevation: 612 ft.
Relative: Higher

Site Name : TAMMY TRUAX
3542 DE LEONE RD
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HWG - CA, MANIFEST EPA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 42318428
EPA ID: N/R

ECHO ***(cont.)***

Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	N/R
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	N
SDWIS Flag :	N
RCRA Flag :	Y
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	N/R
NAA Flag :	N
Latitude :	33.194075
Longitude :	-117.16177
Last Date in Agency List :	2022-01-17

Last Inspection Date :	N/R
Registry ID :	N/R
FIPS Code :	N/R
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	_____
Collection Method :	Zip Code Centroid
Reference Point :	N/R
Accuracy Meters :	10000
Derived Tribes :	N/R
Derived HUC :	N/R
Derived WBD :	N/R
Derived STCTY FIPS :	N/R
Derived Zip :	N/R
Derived CD113 :	N/R
Derived CB2010 :	N/R

Map Id: E29
Direction: NW
Distance: 0.118 mi., 622 ft.
Elevation: 612 ft.
Relative: Higher

Site Name : TAMMY TRUAX
3542 DE LEONE RD
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HWG - CA, MANIFEST EPA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 42318428
EPA ID: N/R

ECHO ***(cont.)***

MYRTK Universe :	NNN
NPDES IDs :	N/R
CWA Permit Types :	N/R
CWA Compliance Tracking :	N/R
CWA NAICS :	N/R
CWA SICS :	N/R
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	N/R
CWA Current Compliance Status :	N/R
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	N/R
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	N/R
Facility NAICS :	56299 - All Other Waste Management Services
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	N/R
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	N
SDWIS Flag :	N
RCRA Flag :	Y
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	N/R
NAA Flag :	N
Latitude :	33.194075
Longitude :	-117.16177
Last Date in Agency List :	2021-10-15

Last Inspection Date :	N/R
Registry ID :	N/R
FIPS Code :	N/R
EPA Region :	09
Inspection Count :	0

Map Id: E29
Direction: NW
Distance: 0.118 mi., 622 ft.
Elevation: 612 ft.
Relative: Higher

Site Name : TAMMY TRUAX
3542 DE LEONE RD
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HWG - CA, MANIFEST EPA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 42318428
EPA ID: N/R

ECHO ***(cont.)***

Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	_____
Collection Method :	Zip Code Centroid
Reference Point :	N/R
Accuracy Meters :	10000
Derived Tribes :	N/R
Derived HUC :	N/R
Derived WBD :	N/R
Derived STCTY FIPS :	N/R
Derived Zip :	N/R
Derived CD113 :	N/R
Derived CB2010 :	N/R
MYRTK Universe :	NNN
NPDES IDs :	N/R
CWA Permit Types :	N/R
CWA Compliance Tracking :	N/R
CWA NAICS :	N/R
CWA SICS :	N/R
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	N/R
CWA Current Compliance Status :	N/R
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	N/R
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	N/R
Facility NAICS :	56299 - All Other Waste Management Services
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N

Map Id: E29
Direction: NW
Distance: 0.118 mi., 622 ft.
Elevation: 612 ft.
Relative: Higher

Site Name : TAMMY TRUAX
3542 DE LEONE RD
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HWG - CA, MANIFEST EPA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 42318428
EPA ID: N/R

ECHO ***(cont.)***

Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	N/R
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	N
SDWIS Flag :	N
RCRA Flag :	Y
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	N/R
NAA Flag :	N
Latitude :	33.194075
Longitude :	-117.16177
Last Date in Agency List :	2021-10-15

FRS

Facility Name :	TAMMY TRUAX
Facility Address :	3542 DE LEONE RD, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Registry ID :	110071103656
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Source Description

Source Description :

RCRAInfo is EPA's comprehensive information system that supports the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984 through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA. RCRAInfo also supports generation of the National Hazardous Waste Biennial Report. All generators and treatment, storage, and disposal facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years to support creation of the Biennial Report.

FRS Environmental Interest

Source and System ID :	RCRAINFO - CAC003117122 RCRAINFO - CAC003130195

HWG - CA

Facility Name :	TAMMY TRUAX
Facility Address :	3542 DE LEONE RD, SAN MARCOS, CA 92069
County :	SAN DIEGO

Map Id: E29
Direction: NW
Distance: 0.118 mi., 622 ft.
Elevation: 612 ft.
Relative: Higher

Site Name : TAMMY TRUAX
3542 DE LEONE RD
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HWG - CA, MANIFEST EPA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 42318428
EPA ID: N/R

HWG - CA ***(cont.)***

EPA ID :	CAC003117122
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	3542 DE LEONE RD, SAN MARCOS, CA 92069
Owner Name :	TAMMY TRUAX
Owner Address :	3542 DE LEONE RD, SAN MARCOS, CA 92069
Operator Name :	TAMMY TRUAX
Operator Address :	3542 DE LEONE RD, SAN MARCOS, CA 92069
Latitude :	33.153602
Longitude :	-117.196801

EPA ID :	CAC003130195
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	3542 DE LEONE RD, SAN MARCOS, CA 92069
Owner Name :	TAMMY TRUAX
Owner Address :	3542 DE LEONE RD, SAN MARCOS, CA 92069
Operator Name :	TAMMY TRUAX
Operator Address :	3542 DE LEONE RD, SAN MARCOS, CA 92069
Latitude :	33.153554
Longitude :	-117.196881

MANIFEST EPA

Manifest Details

Manifest Number :	022171005JJK
Shipped Date :	2021-08-03
Updated Date :	2021-08-24
Received Date :	2021-08-17
Status :	Signed
Generator ID :	CAC003130195
Generator Name :	TAMMY TRUAX
Generator Address :	3542 DE LEONE RD, SAN MARCOS, CA 92069
Generator Mailing :	3542 DE LEONE RD, SAN MARCOS, CA 92069
Generator Contact :	N/R
Destination ID :	AZR000520882
Destination Name :	LA PAZ COUNTY LANDFILL
Destination Mailing :	26999 HIGHWAY 95, PARKER, AZ 85344
Destination Address :	26999 HIGHWAY 95, PARKER, AZ 85344
Destination Contact :	N/R
Submission Type :	DataImage5Copy
Origin Type :	Web
Manifest Residue :	N
Rejection :	N
Last Date in Agency List :	2022-01-14

Waste Details

Waste Line Number :	1
Is DOT Hazardous :	Y

Map Id: E29
Direction: NW
Distance: 0.118 mi., 622 ft.
Elevation: 612 ft.
Relative: Higher

Site Name : TAMMY TRUAX
3542 DE LEONE RD
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HWG - CA, MANIFEST EPA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 42318428
EPA ID: N/R

MANIFEST EPA ***(cont.)***

DOT ID Number :	NA2212
DOT Information :	RQ NA2212, ASBESTOS, 9, PGIII
Non Waste Description :	N/R
Quantity :	2 Cubic Yards
Quantity Tons, Acute, Non-Acute :	1.68, 0, 1.68
Quantity Kg, Acute, Non-Acute :	0, 1523.8104
Management Method :	H132 - LANDFILL (WITH PRIOR TREATMENT AND/OR STABILIZATION)
Is EPA Waste :	N
Federal Code :	N/R
State Code :	CA - 151

Manifest Details

Manifest Number :	022170451JJK
Shipped Date :	2021-05-13
Updated Date :	2021-06-07
Received Date :	2021-05-21
Status :	Signed
Generator ID :	N/R
Generator Name :	TAMMY TRUAX
Generator Address :	3542 DE LEONE RD, SAN MARCOS, CA 92069
Generator Mailing :	3542 DE LEONE RD, SAN MARCOS, CA 92069
Generator Contact :	N/R
Destination ID :	NVT330010000
Destination Name :	US ECOLOGY NEVADA, INC.
Destination Mailing :	HWY 95 11 MILES S. OF BEATTY, BEATTY, NV 89003
Destination Address :	HWY 95 11 MILES S. OF BEATTY, BEATTY, NV 89003
Destination Contact :	N/R
Submission Type :	DataImage5Copy
Origin Type :	Service
Manifest Residue :	N
Rejection :	N
Last Date in Agency List :	2022-01-14

Waste Details

Waste Line Number :	1
Is DOT Hazardous :	Y
DOT ID Number :	NA3077
DOT Information :	NA3077, HAZARDOUS WASTE, SOLID, N.O.S., (LEAD), 9, PG III
Non Waste Description :	N/R
Quantity :	24 Pounds
Quantity Tons, Acute, Non-Acute :	0.012, 0, 0.012
Quantity Kg, Acute, Non-Acute :	0, 10.88436
Management Method :	H132 - LANDFILL (WITH PRIOR TREATMENT AND/OR STABILIZATION)
Is EPA Waste :	Y
Federal Code :	D008
State Code :	CA - 181

Manifest Details

Manifest Number :	022170450JJK
Shipped Date :	2021-05-11

Map Id: E29
Direction: NW
Distance: 0.118 mi., 622 ft.
Elevation: 612 ft.
Relative: Higher

Site Name : TAMMY TRUAX
3542 DE LEONE RD
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HWG - CA, MANIFEST EPA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 42318428
EPA ID: N/R

MANIFEST EPA ***(cont.)***

Updated Date :	2021-05-28
Received Date :	2021-05-24
Status :	Signed
Generator ID :	CAC003117122
Generator Name :	TAMMY TRUAX
Generator Address :	3542 DE LEONE RD, SAN MARCOS, CA 92069
Generator Mailing :	3542 DE LEONE RD, SAN MARCOS, CA 92069
Generator Contact :	N/R
Destination ID :	AZR000520882
Destination Name :	LA PAZ COUNTY LANDFILL
Destination Mailing :	26999 HIGHWAY 95, PARKER, AZ 85344
Destination Address :	26999 HIGHWAY 95, PARKER, AZ 85344
Destination Contact :	N/R
Submission Type :	DataImage5Copy
Origin Type :	Web
Manifest Residue :	N
Rejection :	N
Last Date in Agency List :	2022-01-14

Waste Details

Waste Line Number :	1
Is DOT Hazardous :	Y
DOT ID Number :	NA2212
DOT Information :	RQ NA2212, ASBESTOS, 9, PGIII
Non Waste Description :	N/R
Quantity :	10 Cubic Yards
Quantity Tons, Acute, Non-Acute :	8.4, 0, 8.4
Quantity Kg, Acute, Non-Acute :	0, 7619.052
Management Method :	H132 - LANDFILL (WITH PRIOR TREATMENT AND/OR STABILIZATION)
Is EPA Waste :	N
Federal Code :	N/R
State Code :	CA - 151

RCRA_NONGEN

Facility Name :	TAMMY TRUAX
Facility Address :	3542 DE LEONE RD, SAN MARCOS, CA 92069
County :	SAN DIEGO
Date Form Received by Agency :	2021-07-20
EPA ID :	CAC003130195
Mailing Address :	3542 DE LEONE RD, SAN MARCOS, CA 92069
Contact :	TAMMY TRUAX
Contact Address :	3542 DE LEONE RD, SAN MARCOS, CA 92069
Contact Country :	N/R
Contact Telephone :	760-688-2340
Contact Email :	TAMMYLTRUAX@HOTMAIL.COM
EPA Region :	09
Land Type :	Not Reported
Source Type :	Implementer
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2022-01-26

Map Id: E29
Direction: NW
Distance: 0.118 mi., 622 ft.
Elevation: 612 ft.
Relative: Higher

Site Name : TAMMY TRUAX
3542 DE LEONE RD
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HWG - CA, MANIFEST EPA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 42318428
EPA ID: N/R

RCRA_NONGEN ***(cont.)***

Owner/Operator Summary

Owner/Operator Name :	TAMMY TRUAX
Owner/Operator Address :	3542 DE LEONE RD, SAN MARCOS, CA 92069
Owner/Operator Country :	N/R
Owner/Operator Telephone :	760-688-2340
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Owner/Operator Name :	TAMMY TRUAX
Owner/Operator Address :	3542 DE LEONE RD, SAN MARCOS, CA 92069
Owner/Operator Country :	N/R
Owner/Operator Telephone :	760-688-2340
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N/R
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Notices of Violations Summary

Regulation Violated :	N

Date Form Received by Agency :	2021-04-28
EPA ID :	CAC003117122
Mailing Address :	3542 DE LEONE RD, SAN MARCOS, CA 92069
Contact :	TAMMY TRUAX
Contact Address :	3542 DE LEONE RD, SAN MARCOS, CA 92069
Contact Country :	N/R
Contact Telephone :	760-688-2340

Map Id: E29
Direction: NW
Distance: 0.118 mi., 622 ft.
Elevation: 612 ft.
Relative: Higher

Site Name : TAMMY TRUAX
3542 DE LEONE RD
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HWG - CA, MANIFEST EPA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 42318428
EPA ID: N/R

RCRA_NONGEN ***(cont.)***

Contact Email :	TAMMYLTRUAX@HOTMAIL.COM
EPA Region :	09
Land Type :	Not Reported
Source Type :	Implementer
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2022-01-26

Owner/Operator Summary

Owner/Operator Name :	TAMMY TRUAX
Owner/Operator Address :	3542 DE LEONE RD, SAN MARCOS, CA 92069
Owner/Operator Country :	N/R
Owner/Operator Telephone :	760-688-2340
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Owner/Operator Name :	TAMMY TRUAX
Owner/Operator Address :	3542 DE LEONE RD, SAN MARCOS, CA 92069
Owner/Operator Country :	N/R
Owner/Operator Telephone :	760-688-2340
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N/R
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Map Id: E29
Direction: NW
Distance: 0.118 mi., 622 ft.
Elevation: 612 ft.
Relative: Higher

Site Name : TAMMY TRUAX
3542 DE LEONE RD
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HWG - CA, MANIFEST EPA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 42318428
EPA ID: N/R

RCRA_NONGEN ***(cont.)***

Notices of Violations Summary
Regulation Violated : N

Map Id: D30
Direction: WSW
Distance: 0.118 mi., 624 ft.
Elevation: 618 ft.
Relative: Higher

Site Name : GLENN YOUNG ARCO #6200 | SAN MARCOS AMPM | RANCHO SANTA FE ARCO
125 N RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA]

Envirosite ID: 257410
EPA ID: CAL000260996

CALEPA SITES - CA

Facility Name : 125 MATTHEW INC.
Facility Address : 125 N RANCHO SANTA FE RD, SAN MARCOS, 92069

Site ID : 64690
EI ID : 10375633
EI Description : Hazardous Waste Generator
Latitude : 33.150830
Longitude : -117.197460
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-01-07

Site ID : 64690
EI ID : 10375633
EI Description : Underground Storage Tank
Latitude : 33.150830
Longitude : -117.197460
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-01-07

Site ID : 64690
EI ID : 10375633
EI Description : Chemical Storage Facilities
Latitude : 33.150830
Longitude : -117.197460
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-01-07

Map Id: D30
Direction: WSW
Distance: 0.118 mi., 624 ft.
Elevation: 618 ft.
Relative: Higher

Site Name : GLENN YOUNG ARCO #6200 | SAN MARCOS AMPM | RANCHO SANTA FE ARCO
125 N RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257410
EPA ID: CAL000260996

CALEPA SITES - CA ***(cont.)***

Facility Name : GLENN YOUNG ARCO #6200
Facility Address : 125 N RANCHO SANTA FE RD, SAN MARCOS, 920691217

Site ID : 220242
EI ID : T0607300398
EI Description : Leaking Underground Storage Tank Cleanup Site
Latitude : 33.150832
Longitude : -117.197464
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-01-07

Site ID : 220242
EI ID : T0608148767
EI Description : Cleanup Program Site
Latitude : 33.150832
Longitude : -117.197464
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-01-07

Site ID : 220242
EI ID : T0607301273
EI Description : Leaking Underground Storage Tank Cleanup Site
Latitude : 33.150832
Longitude : -117.197464
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-01-07

Site ID : 220242
EI ID : T0608153478
EI Description : Cleanup Program Site
Latitude : 33.150832
Longitude : -117.197464
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-01-07

Facility Name : SAN MARCOS AMPM
Facility Address : 125 N RANCHO SANTA FE RD, SAN MARCOS, 92069

Site ID : 64690
EI ID : 10375633
EI Description : Chemical Storage Facilities
Latitude : 33.150830

Map Id: D30
Direction: WSW
Distance: 0.118 mi., 624 ft.
Elevation: 618 ft.
Relative: Higher

Site Name : GLENN YOUNG ARCO #6200 | SAN MARCOS AMPM | RANCHO SANTA FE ARCO
125 N RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257410
EPA ID: CAL000260996

CALEPA SITES - CA ***(cont.)***

Longitude :	-117.197460
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-10-14

Site ID :	64690
EI ID :	10375633
EI Description :	Underground Storage Tank
Latitude :	33.150830
Longitude :	-117.197460
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-10-14

Site ID :	64690
EI ID :	10375633
EI Description :	Hazardous Waste Generator
Latitude :	33.150830
Longitude :	-117.197460
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-10-14

CASE LIST_SAN DIEGO COUNTY - CA

Facility Name :	GLENN YOUNG ARCO #6200
Facility Address :	125 N RANCHO SANTA FE RD, SAN MARCOS, CA 920691217
County :	San Diego

Site Details

Status Date :	1991-07-12
Status :	Completed - Case Closed
Begin Date :	1987-01-30
Global ID :	T0608153478
Site History :	N/R
RB Case Number :	N/R
Potential Media Affected :	N/R
Potential Contaminants of Concern :	N/R
Local Agency :	SAN DIEGO COUNTY LOP
Local Case Number :	H05181-001
Lead Agency :	SAN DIEGO COUNTY LOP
File Location :	Local Agency
CUF Case :	NO
Caseworker :	NS
Case Type :	Cleanup Program Site
How Discovered :	N/R
How Discovered Description :	N/R

Map Id: D30
Direction: WSW
Distance: 0.118 mi., 624 ft.
Elevation: 618 ft.
Relative: Higher

Site Name : GLENN YOUNG ARCO #6200 | SAN MARCOS AMPM | RANCHO SANTA FE ARCO
125 N RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257410
EPA ID: CAL000260996

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Stop Method :	N/R
Stop Description :	N/R
Calwater Watershed Name :	Carlsbad - San Marcos - Richland (904.52)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)
Disadvantaged Community :	N/R
Latitude :	33.150832
Longitude :	-117.197464
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-09

Contacts Summary

Global ID :	T0608153478
Contact Name :	NASSER SIONIT
Contact Type :	Local Agency Caseworker
Organization Name :	SAN DIEGO COUNTY LOP
Address :	P.O. Box 129261
City :	San Diego
Phone Number :	N/R
Email :	nasser.sionit@sdcounty.ca.gov

Regulatory Activities

Date :	N/R
Global ID :	T0608153478
Action Type :	N/R
Action :	N/R

Status History

Status Date :	1991-07-12
Global ID :	T0608153478
Status :	Completed - Case Closed
Status Date :	1987-01-30
Global ID :	T0608153478
Status :	Open - Case Begin Date

Site Details

Status Date :	1991-06-20
Status :	Completed - Case Closed
Begin Date :	1989-09-12

Map Id: D30
Direction: WSW
Distance: 0.118 mi., 624 ft.
Elevation: 618 ft.
Relative: Higher

Site Name : GLENN YOUNG ARCO #6200 | SAN MARCOS AMPM | RANCHO SANTA FE ARCO
125 N RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257410
EPA ID: CAL000260996

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Global ID :	T0607300398
Site History :	N/R
RB Case Number :	9UT1578
Potential Media Affected :	Soil
Potential Contaminants of Concern :	Gasoline
Local Agency :	SAN DIEGO COUNTY LOP
Local Case Number :	H05181-002
Lead Agency :	SAN DIEGO COUNTY LOP
File Location :	Local Agency
CUF Case :	YES
Caseworker :	NS
Case Type :	LUST Cleanup Site
How Discovered :	N/R
How Discovered Description :	N/R
Stop Method :	N/R
Stop Description :	N/R
Calwater Watershed Name :	Carlsbad - San Marcos - Richland (904.52)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)
Disadvantaged Community :	N/R
Latitude :	33.150833
Longitude :	-117.197446
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-09

Contacts Summary

Global ID :	T0607300398
Contact Name :	NASSER SIONIT
Contact Type :	Local Agency Caseworker
Organization Name :	SAN DIEGO COUNTY LOP
Address :	P.O. Box 129261
City :	San Diego
Phone Number :	N/R
Email :	nasser.sionit@sdcounty.ca.gov

Regulatory Activities

Date :	1989-09-13
Global ID :	T0607300398
Action Type :	Other
Action :	Leak Reported

Date :	1989-09-12
Global ID :	T0607300398
Action Type :	Other

Map Id: D30
Direction: WSW
Distance: 0.118 mi., 624 ft.
Elevation: 618 ft.
Relative: Higher

Site Name : GLENN YOUNG ARCO #6200 | SAN MARCOS AMPM | RANCHO SANTA FE ARCO
125 N RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257410
EPA ID: CAL000260996

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Action : Leak Discovery

Date : 1989-09-12
Global ID : T0607300398
Action Type : Other
Action : Leak Began

Date : 1989-09-12
Global ID : T0607300398
Action Type : Other
Action : Leak Stopped

Status History

Status Date : 1991-06-20
Global ID : T0607300398
Status : Completed - Case Closed

Status Date : 1989-09-12
Global ID : T0607300398
Status : Open - Case Begin Date

Site Details

Status Date : 2018-05-16
Status : Completed - Case Closed
Begin Date : 1993-06-21
Global ID : T0607301273

Site History :

The Site is an active gasoline station and mini-market at 125 North Ranch Santa Fe Road in San Marcos, California. Station facilities consist of four underground storage tanks (USTs), two dispenser islands, a building, parking, and a landscaped area (southern portion of the Site). The USTs, associated dispensers and product piping were replaced in October 1993 and the dispensers and product piping were replaced again in November 2003. Based on the results of soil sampling, Unauthorized Release Case H05181-004 was opened. Soil removed during the 1993 UST removal was placed back in the excavation area for future remediation. In addition, soil was excavated for the current UST area, which is adjacent and to the west of the former USTs. Most of the soil removed was transported off-site for disposal, but 80-100 cubic yards of soil removed between 5 and 15 feet bgs from the southern portion of the current UST area was reportedly used to complete backfilling the former UST area. A total of approximately 1,100 cubic yards (1,479 tons) of soil have been removed from the Site to date. Measurable free product have previously been reported in wells MW-1, MW-2, MW-3, MW-6 and MW-8. LPH was last reported in well MW-1 (sheen detected during well purging) in May 2008. Approximately 132 gallons of LPH have been reportedly removed from

Map Id: D30
Direction: WSW
Distance: 0.118 mi., 624 ft.
Elevation: 618 ft.
Relative: Higher

Site Name : GLENN YOUNG ARCO #6200 | SAN MARCOS AMPM | RANCHO SANTA FE ARCO
125 N RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257410
EPA ID: CAL000260996

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Site wells to date using a vacuum truck, petro trap and rubberizer boom, and by hand bailing. An unknown amount has been removed from the use of absorbent socks, previous remedial system operation, and 2003 high vacuum dual-phase extraction (HVDPE) feasibility testing. In March 2011, extraction well EW-1 and injection wells IW-1, IW-2, IW-3 were installed, for use during the feasibility testing. From September 13 through 16, 2011, an in situ chemical oxidation (ISCO) test was conducted, which involved the injection of approximately 1,436 gallons of a 12% solution of sodium persulfate, approximately 15.5 gallons of a 6% solution of hydrogen peroxide into IW-1, IW-2 and IW-3, and approximately 20.5 gallons of a 3% solution of hydrogen peroxide into wells IW-1 and IW-3. The high vacuum dual-phase extraction (HVDPE) testing involved three events that were performed during three consecutive months, utilizing EW-1 for extraction. A 117-hour event was performed in November, a 90-hour HVDPE event in December 2011 and a 90-hour event in January 2012, resulting in the removal of a total of approximately 2,190 gallons of groundwater and 26 pounds of gasoline range organics (GRO) as vapor. In August 2003, a CAP was submitted, recommending soil vapor extraction (SVE), followed by remediation by natural attenuation (RNA) as the most cost-effective remedial action for the Site. In January 2004, a SVE system was installed at the Site and operation began. Due to asymptotic vapor concentrations from source wells, SECOR discontinued system operation in January 2006. The system removed and treated approximately 2,762 pounds of GRO (also reported as volatile fuel hydrocarbons in previous reports), 1.34 pounds of benzene and 2.9 pounds of MTBE from wells VE-1, VE-2, MW-1, MW-2, MW-3, MW-4, MW-8, and MW-9. In June 2008, four vapor points were installed around the station building, as part of a vapor risk assessment (VRA). Based on the soil vapor sample data, none of the analyzed VOCs that were listed in the VRA model were detected at or above laboratory reporting limits. The excess cancer risk to workers and customers in the existing or possible future buildings on the site was determined to be less than the one-in-a-million level. In March 2003, a high-vacuum dual-phase extraction (HVDPE) feasibility testing was performed using a mobile remediation system. A 24-hour test was performed using MW-2 as the extraction well and a 23-hour test was performed using MW-3 as the extraction well. Based on the testing data, HVDPE appeared to be an effective method to remove subsurface hydrocarbons beneath the site, but the groundwater recovery was slow and inconsistent. Approximately 400 gallons of fluids and 273 pounds of hydrocarbons as vapor were removed during testing, with an average groundwater removal rate of 0.14 gallons per minute (per well). Evaluation of benzene and MTBE concentration trends using linear regression trend lines, consideration of decreasing average benzene and MTBE concentrations, and BIOSCREEN modeling provide converging lines of evidence that RNA is occurring at the site and benzene and MTBE concentrations will reach MCLs through RNA processes. Estimates of the time needed for benzene and MTBE to reach MCLs (derived from estimates based on BIOSCREEN) are less than 50 years for benzene and less than 25 years for MTBE. These appear to correlate well with the estimates for near-source area wells MW-1 and MW-3 from linear regression trend lines with benzene ranging from 6 to 49 years, and MTBE ranging from <1 to 24 years. Based on the pounds of hydrocarbons removed during SVE and the HVDPE test, the estimated hydrocarbon mass remaining in soil is 2,075 pounds.

RB Case Number :	9UT2527
Potential Media Affected :	Aquifer used for drinking water supply
Potential Contaminants of Concern :	Gasoline
Local Agency :	SAN DIEGO COUNTY LOP
Local Case Number :	H05181-004
Lead Agency :	SAN DIEGO COUNTY LOP
File Location :	Local Agency
CUF Case :	NO
Caseworker :	JC
Case Type :	LUST Cleanup Site
How Discovered :	Tank Closure, UST System Modification
How Discovered Description :	N/R
Stop Method :	Close and Replace Tank

Map Id: D30
Direction: WSW
Distance: 0.118 mi., 624 ft.
Elevation: 618 ft.
Relative: Higher

Site Name : GLENN YOUNG ARCO #6200 | SAN MARCOS AMPM | RANCHO SANTA FE ARCO
125 N RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257410
EPA ID: CAL000260996

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Stop Description :	CLOSE AND REPLACE TANK
Calwater Watershed Name :	Carlsbad - Agua Hedionda - Buena (904.32)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)
Disadvantaged Community :	Severely Disadvantaged Community
Latitude :	33.150934
Longitude :	-117.197758
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-09

Contacts Summary

Global ID :	T0607301273
Contact Name :	JAMES CLAY
Contact Type :	Local Agency Caseworker
Organization Name :	SAN DIEGO COUNTY LOP
Address :	P.O. Box 129261
City :	San Diego
Phone Number :	N/R
Email :	james.clay@sdcounty.ca.gov

Regulatory Activities

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Date :	2018-05-16
Global ID :	T0607301273
Action Type :	ENFORCEMENT
Action :	Closure/No Further Action Letter

Date :	2017-04-28
Global ID :	T0607301273
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other

Date :	2016-12-09
Global ID :	T0607301273
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other

Map Id: D30
Direction: WSW
Distance: 0.118 mi., 624 ft.
Elevation: 618 ft.
Relative: Higher

Site Name : GLENN YOUNG ARCO #6200 | SAN MARCOS AMPM | RANCHO SANTA FE ARCO
125 N RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257410
EPA ID: CAL000260996

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Date : 2016-09-08
Global ID : T0607301273
Action Type : RESPONSE
Action : Correspondence

Date : 2016-08-31
Global ID : T0607301273
Action Type : ENFORCEMENT
Action : Technical Correspondence / Assistance / Other

Date : 2016-07-30
Global ID : T0607301273
Action Type : RESPONSE
Action : Monitoring Report - Semi-Annually

Date : 2016-07-27
Global ID : T0607301273
Action Type : RESPONSE
Action : Other Report / Document - Regulator Responded

Date : 2016-06-22
Global ID : T0607301273
Action Type : RESPONSE
Action : Email Correspondence

Date : 2016-06-01
Global ID : T0607301273
Action Type : RESPONSE
Action : Other Report / Document

Date : 2016-03-21
Global ID : T0607301273
Action Type : RESPONSE
Action : Monitoring Report - Other

Status History
Status Date : 2018-05-16
Global ID : T0607301273
Status : Completed - Case Closed

Map Id: D30
Direction: WSW
Distance: 0.118 mi., 624 ft.
Elevation: 618 ft.
Relative: Higher

Site Name : GLENN YOUNG ARCO #6200 | SAN MARCOS AMPM | RANCHO SANTA FE ARCO
125 N RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257410
EPA ID: CAL000260996

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Status Date :	1994-01-01
Global ID :	T0607301273
Status :	Open - Remediation

Status Date :	1993-06-21
Global ID :	T0607301273
Status :	Open - Case Begin Date

Site Details

Status Date :	1991-08-06
Status :	Completed - Case Closed
Begin Date :	1986-10-16
Global ID :	T0608148767
Site History :	N/R
RB Case Number :	N/R
Potential Media Affected :	Under Investigation
Potential Contaminants of Concern :	Gasoline
Local Agency :	N/R
Local Case Number :	H05181-003
Lead Agency :	SAN DIEGO COUNTY LOP
File Location :	Local Agency
CUF Case :	NO
Caseworker :	N/R
Case Type :	Cleanup Program Site
How Discovered :	N/R
How Discovered Description :	N/R
Stop Method :	N/R
Stop Description :	N/R
Calwater Watershed Name :	Carlsbad - San Marcos - Richland (904.52)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)
Disadvantaged Community :	N/R
Latitude :	33.150832
Longitude :	-117.197464
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-09

Contacts Summary

Global ID :	T0608148767
Contact Name :	N/R
Contact Type :	N/R
Organization Name :	N/R
Address :	N/R
City :	N/R

Map Id: D30
Direction: WSW
Distance: 0.118 mi., 624 ft.
Elevation: 618 ft.
Relative: Higher

Site Name : GLENN YOUNG ARCO #6200 | SAN MARCOS AMPM | RANCHO SANTA FE ARCO
125 N RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257410
EPA ID: CAL000260996

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Phone Number : N/R
Email : N/R

Regulatory Activities
Date : 1987-01-27
Global ID : T0608148767
Action Type : Other
Action : Leak Reported

Date : 1986-10-16
Global ID : T0608148767
Action Type : Other
Action : Leak Began

Date : 1986-10-16
Global ID : T0608148767
Action Type : Other
Action : Leak Discovery

Status History
Status Date : 1991-08-06
Global ID : T0608148767
Status : Completed - Case Closed

Status Date : 1986-10-16
Global ID : T0608148767
Status : Open - Case Begin Date

ECHO

Facility Name : RANCHO SANTA FE ARCO
Facility Address : 125 N RANCHO SANTA FE RD, SAN MARCOS, CA 92069
County : SAN DIEGO

Last Inspection Date : N/R
Registry ID : 110070413943
FIPS Code : N/R
EPA Region : 09
Inspection Count : 0
Last Inspection Days : N/R

Map Id: D30
Direction: WSW
Distance: 0.118 mi., 624 ft.
Elevation: 618 ft.
Relative: Higher

Site Name : GLENN YOUNG ARCO #6200 | SAN MARCOS AMPM | RANCHO SANTA FE ARCO
125 N RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257410
EPA ID: CAL000260996

ECHO ***(cont.)***

Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	_____
Collection Method :	Zip Code Centroid
Reference Point :	N/R
Accuracy Meters :	10000
Derived Tribes :	N/R
Derived HUC :	N/R
Derived WBD :	N/R
Derived STCTY FIPS :	N/R
Derived Zip :	N/R
Derived CD113 :	N/R
Derived CB2010 :	N/R
MYRTK Universe :	NNN
NPDES IDs :	N/R
CWA Permit Types :	N/R
CWA Compliance Tracking :	N/R
CWA NAICS :	N/R
CWA SICS :	N/R
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	N/R
CWA Current Compliance Status :	N/R
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	N/R
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	N/R
Facility NAICS :	44719 - Other Gasoline Stations
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R

Map Id: D30
Direction: WSW
Distance: 0.118 mi., 624 ft.
Elevation: 618 ft.
Relative: Higher

Site Name : GLENN YOUNG ARCO #6200 | SAN MARCOS AMPM | RANCHO SANTA FE ARCO
125 N RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257410
EPA ID: CAL000260996

ECHO ***(cont.)***

Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	N/R
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	N
SDWIS Flag :	N
RCRA Flag :	Y
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	Y
NAA Flag :	N
Latitude :	33.194075
Longitude :	-117.16177
Last Date in Agency List :	2022-01-17

EPA LUST

Facility Name :	GLENN YOUNG ARCO #6200
Facility Address :	125 N RANCHO SANTA FE RD, SAN MARCOS, California 920691217
County :	N/R
Facility ID :	N/R
LUST ID :	CAT0607301273
Reported Date :	N/R
Status :	No Further Action
Substance :	N/R
Closed With Residual Contamination (Tribal Only):	N/R
NFA_Letter (Tribal Only) :	N/R
Tribe (Tribal Only) :	N/R
EPA Region :	9
Estimated Population within 1500ft :	2233
Estimated Private Domestic Wells within 1500ft:	0
Within Source Water Protection Area (SPA):	No
SPA Public Water System and Facility ID:	N/R
SPA Water Type :	N/R

Map Id: D30
Direction: WSW
Distance: 0.118 mi., 624 ft.
Elevation: 618 ft.
Relative: Higher

Site Name : GLENN YOUNG ARCO #6200 | SAN MARCOS AMPM | RANCHO SANTA FE ARCO
125 N RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257410
EPA ID: CAL000260996

EPA LUST ***(cont.)***

SPA Facility Type :	N/R
SPA HUC12 :	N/R
Within Groundwater Wellhead Protection Area (WHPA):	No
WHPA Public Water System and Facility ID:	N/R
WHPA Water Type :	N/R
WHPA Facility Type :	N/R
WHPA HUC12 :	N/R
Within Estimated 100-year Floodplain:	No
Latitude :	33.150930000000002
Longitude :	-117.197770000000006
Last Date in Agency List :	2022-01-04

Facility ID :	N/R
LUST ID :	CAT0607300398
Reported Date :	N/R
Status :	No Further Action
Substance :	N/R
Closed With Residual Contamination (Tribal Only):	N/R
NFA_Letter (Tribal Only) :	N/R
Tribe (Tribal Only) :	N/R
EPA Region :	9
Estimated Population within 1500ft :	2233
Estimated Private Domestic Wells within 1500ft:	0
Within Source Water Protection Area (SPA):	No
SPA Public Water System and Facility ID:	N/R
SPA Water Type :	N/R
SPA Facility Type :	N/R
SPA HUC12 :	N/R
Within Groundwater Wellhead Protection Area (WHPA):	No
WHPA Public Water System and Facility ID:	N/R
WHPA Water Type :	N/R
WHPA Facility Type :	N/R
WHPA HUC12 :	N/R
Within Estimated 100-year Floodplain:	No
Latitude :	33.150930000000002
Longitude :	-117.197770000000006
Last Date in Agency List :	2022-01-04

Map Id: D30
Direction: WSW
Distance: 0.118 mi., 624 ft.
Elevation: 618 ft.
Relative: Higher

Site Name : GLENN YOUNG ARCO #6200 | SAN MARCOS AMPM | RANCHO SANTA FE ARCO
125 N RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257410
EPA ID: CAL000260996

EPA UST

Facility Name :	San Marcos AMPM
Facility Address :	125 N RANCHO SANTA FE RD, SAN MARCOS, California 92069
County :	N/R
Facility ID :	CA10375633
Facility Status :	Open UST(s)
Open USTs :	4
Closed USTs :	N/R
Temporarily Out of Service USTs :	N/R
Date of Last Inspection :	N/R
EPA Region :	9
Tribe :	N/R
Facility ID 2 :	N/R
Latitude :	33.150930014974897
Longitude :	-117.197392013482002
Last Date in Agency List :	2021-12-27

Tank Details

Tank ID :	CA10375633-001_A Stand-alone Tank_1
Tank Status :	Open
Installation Date :	1993-01-01
Removal Date :	N/R
Capacity :	10000
Substances :	Premium Unleaded
Tank Wall Type :	Double Wall
Tank ID :	CA10375633-002_A Stand-alone Tank_1
Tank Status :	Open
Installation Date :	1993-01-01
Removal Date :	N/R
Capacity :	10000
Substances :	Regular Unleaded
Tank Wall Type :	Double Wall
Tank ID :	CA10375633-003_A Stand-alone Tank_1
Tank Status :	Open
Installation Date :	1993-01-01
Removal Date :	N/R
Capacity :	10000
Substances :	Regular Unleaded
Tank Wall Type :	Double Wall

Map Id: D30
Direction: WSW
Distance: 0.118 mi., 624 ft.
Elevation: 618 ft.
Relative: Higher

Site Name : GLENN YOUNG ARCO #6200 | SAN MARCOS AMPM | RANCHO SANTA FE ARCO
125 N RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257410
EPA ID: CAL000260996

EPA UST ***(cont.)***

Tank ID :	CA10375633-004_A Stand-alone Tank_1
Tank Status :	Open
Installation Date :	1993-01-01
Removal Date :	N/R
Capacity :	10000
Substances :	Diesel
Tank Wall Type :	Double Wall

FID UST - CA

Facility Name :	125 Matthew Inc.
Facility Address :	125 N RANCHO SANTA FE RD, SAN MARCOS, 92069
County :	San Diego
Facility ID :	37-000-105181
CERSID :	10375633
Permitting Agency :	San Diego County Department of Environmental Health
Latitude :	33.15083
Longitude :	-117.19746
Last Date in Agency List :	2022-03-14
Facility Name :	GLENN YOUNG ARCO #6200
Facility Address :	125 N RANCHO SANTA FE RD, SAN MARCOS, 92069
County :	San Diego
Facility ID :	H05181
CERSID :	N/R
Permitting Agency :	SAN DIEGO COUNTY
Latitude :	33.152182
Longitude :	-117.196116
Last Date in Agency List :	2018-05-14
Facility Name :	San Marcos AMPM
Facility Address :	125 N RANCHO SANTA FE RD, SAN MARCOS, 92069
County :	San Diego
Facility ID :	37-000-105181
CERSID :	10375633
Permitting Agency :	San Diego County Department of Environmental Health
Latitude :	33.15083
Longitude :	-117.19746
Last Date in Agency List :	2021-09-17

Map Id: D30
Direction: WSW
Distance: 0.118 mi., 624 ft.
Elevation: 618 ft.
Relative: Higher

Site Name : GLENN YOUNG ARCO #6200 | SAN MARCOS AMPM | RANCHO SANTA FE ARCO
125 N RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257410
EPA ID: CAL000260996

FRS

Facility Name : GLENN YOUNG ARCO #6200
Facility Address : 125 N RANCHO SANTA FE RD, SAN MARCOS, CA 920691217
County : SAN DIEGO

Site Details
Registry ID : 110066553642
FRS Facility URL : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-02-17

Source Description

Source Description :

The California Environmental Protection Agency (CalEPA) has recently implemented a new data warehouse system (nSite). This data warehouse combines and merges facility and site information from five different systems managed within CalEPA. The five systems are: California Environmental Reporting System (CERS), EnviroStor, GeoTracker, California Integrated Water Quality System (CIWQS), and Toxic Release Inventory (TRI).

FRS Environmental Interest
Source and System ID : CA-ENVIROVIEW - 220242

Facility Name : RANCHO SANTA FE ARCO
Facility Address : 125 N RANCHO SANTA FE RD, SAN MARCOS, CA 92069
County : SAN DIEGO

Site Details
Registry ID : 110070413943
FRS Facility URL : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-02-17

Source Description

Map Id: D30
Direction: WSW
Distance: 0.118 mi., 624 ft.
Elevation: 618 ft.
Relative: Higher

Site Name : GLENN YOUNG ARCO #6200 | SAN MARCOS AMPM | RANCHO SANTA FE ARCO
125 N RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257410
EPA ID: CAL000260996

FRS ***(cont.)***

Source Description :

RCRAInfo is EPA's comprehensive information system that supports the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984 through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA. RCRAInfo also supports generation of the National Hazardous Waste Biennial Report. All generators and treatment, storage, and disposal facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years to support creation of the Biennial Report.

FRS Environmental Interest

Source and System ID :	RCRAINFO - CAL000388657
Facility Name :	SAN MARCOS AMPM
Facility Address :	125 N RANCHO SANTA FE RD, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Registry ID :	110065782861
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Source Description

Source Description :

The California Environmental Protection Agency (CalEPA) has recently implemented a new data warehouse system (nSite). This data warehouse combines and merges facility and site information from five different systems managed within CalEPA. The five systems are: California Environmental Reporting System (CERS), EnviroStor, GeoTracker, California Integrated Water Quality System (CIWQS), and Toxic Release Inventory (TRI).

FRS Environmental Interest

Source and System ID :	CA-ENVIROVIEW - 64690

HAZMAT_SAN DIEGO COUNTY - CA

Facility Name :	San Marcos AMPM
Facility Address :	125 N RANCHO SANTA FE RD, SAN MARCOS, CA 92069

Map Id: D30
Direction: WSW
Distance: 0.118 mi., 624 ft.
Elevation: 618 ft.
Relative: Higher

Site Name : GLENN YOUNG ARCO #6200 | SAN MARCOS AMPM | RANCHO SANTA FE ARCO
125 N RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257410
EPA ID: CAL000260996

HAZMAT_SAN DIEGO COUNTY - CA ***(cont.)***

Date :	2002-05-04
Record ID :	DEH2002-HUPFP-105181
Record Type :	Unified Program Facility Permit
Status :	Permit Renewed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23

HAZNET - CA

Facility Name :	BILL REEDY DBA SAN MARCOS AM/PM
Facility Address :	125 N RANCHO SANTA FE RD, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000260996
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	125 N RANCHO SANTA FE RD, SAN MARCOS, CA 92069
Latitude :	33.15098719
Longitude :	-117.19772672
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Facility Name :	BP WEST COAST PRODUCTS LLC 06200
Facility Address :	125 N RANCHO SANTA FE RD, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000225531
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	PO BOX 80249, RANCHO SANTA MARGARI, CA 920688000
Latitude :	33.15098719
Longitude :	-117.19772672

Map Id: D30
Direction: WSW
Distance: 0.118 mi., 624 ft.
Elevation: 618 ft.
Relative: Higher

Site Name : GLENN YOUNG ARCO #6200 | SAN MARCOS AMPM | RANCHO SANTA FE ARCO
125 N RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257410
EPA ID: CAL000260996

HAZNET - CA ***(cont.)***

Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2021-07-08

Waste Generator Details
State Waste :
2013: 134 - Aqueous solution with total organic residues less than 10 percent, 0.21 tons to CAT080013352
2012: 134 - Aqueous solution with total organic residues less than 10 percent, 0.021 tons to CAT080013352
2011: 134 - Aqueous solution with total organic residues less than 10 percent, 0.1386 tons to CAT080013352
2011: 352 - Other organic solids, 0.05 tons to NVT330010000
2011: 135 - Unspecified aqueous solution, 1.512 tons to NVT330010000
2010: 134 - Aqueous solution with total organic residues less than 10 percent, 0.1386 tons to CAT080013352
2009: 352 - Other organic solids, 0.1 tons to NVT330010000
2009: 134 - Aqueous solution with total organic residues less than 10 percent, 0.147 tons to CAT080013352
2008: 134 - Aqueous solution with total organic residues less than 10 percent, 0.021 tons to CAT080013352
2007: 134 - Aqueous solution with total organic residues less than 10 percent, 1.029 tons to CAT080013352
2007: 134 - Aqueous solution with total organic residues less than 10 percent, 2.478 tons to CAT080013352
2007: 352 - Other organic solids, 0.0625 tons to NVT330010000
2006: 134 - Aqueous solution with total organic residues less than 10 percent, 0.084 tons to CAT080013352
2006: 134 - Aqueous solution with total organic residues less than 10 percent, 0.168 tons to CAT080013352
2005: 134 - Aqueous solution with total organic residues less than 10 percent, 0.168 tons to CAT080013352
2004: 134 - Aqueous solution with total organic residues less than 10 percent, 2.856 tons to CAT080013352
2003: 134 - Aqueous solution with total organic residues less than 10 percent, 7.266 tons to CAT080013352
2002: 134 - Aqueous solution with total organic residues less than 10 percent, 0.126 tons to CAT080013352
2002: 134 - Aqueous solution with total organic residues less than 10 percent, 1.1046 tons to CAT080013352

Facility Name : RANCHO SANTA FE ARCO
Facility Address : 125 N RANCHO SANTA FE RD, SAN MARCOS, CA 92069
County : SAN DIEGO

Map Id: D30
Direction: WSW
Distance: 0.118 mi., 624 ft.
Elevation: 618 ft.
Relative: Higher

Site Name : GLENN YOUNG ARCO #6200 | SAN MARCOS AMPM | RANCHO SANTA FE ARCO
125 N RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257410
EPA ID: CAL000260996

HAZNET - CA ***(cont.)***

Site Details

Generator EPA ID :	CAL000388657
Active :	Active
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	125 N RANCHO SANTA FE RD, SAN MARCOS, CA 920690000
Latitude :	33.15093300
Longitude :	-117.19739250
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	2019: 134 - Aqueous solution with total organic residues less than 10 percent, 0.58800 tons to AZR000510065 2014: 134 - Aqueous solution with total organic residues less than 10 percent, 1.05 tons to CAT080013352
Facility Name :	SAN MARCOS AM/PM
Facility Address :	125 N RANCHO SANTA FE RD, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000182209
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	125 N RANCHO SANTA FE RD, SAN MARCOS, CA 920690000
Latitude :	33.15098719
Longitude :	-117.19772672
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Generator EPA ID :	CAL000299402
Active :	Inactive
Category :	STATE
Facility Types :	N/R

Map Id: D30
Direction: WSW
Distance: 0.118 mi., 624 ft.
Elevation: 618 ft.
Relative: Higher

Site Name : GLENN YOUNG ARCO #6200 | SAN MARCOS AMPM | RANCHO SANTA FE ARCO
125 N RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257410
EPA ID: CAL000260996

HAZNET - CA ***(cont.)***

Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	125 N RANCHO SANTA FE RD, SAN MARCOS, CA 920690000
Latitude :	33.15098719
Longitude :	-117.19772672
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :
2013: 352 - Other organic solids, 0.075 tons to NVT330010000
2012: 352 - Other organic solids, 0.0625 tons to NVT330010000
2011: 352 - Other organic solids, 0.15 tons to NVT330010000
2007: 352 - Other organic solids, 0.125 tons to NVT330010000
2005: 352 - Other organic solids, 0.2 tons to NVT330010000

HWG - CA

Facility Name :	BILL REEDY DBA SAN MARCOS AM/PM
Facility Address :	125 N RANCHO SANTA FE RD, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAL000260996
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	125 N RANCHO SANTA FE RD, SAN MARCOS, CA 92069
Owner Name :	BILL REEDY
Owner Address :	125 N RANCHO SANTA FE RD, SAN MARCOS, CA 92069
Operator Name :	BILL REEDY
Operator Address :	125 N RANCHO SANTA FE RD, SAN MARCOS, CA 92069
Latitude :	33.150987
Longitude :	-117.197727

Facility Name :	BP WEST COAST PRODUCTS LLC 06200
Facility Address :	125 N RANCHO SANTA FE RD, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAL000225531
Status :	Inactive
Category :	STATE
Type :	PERMANENT

Map Id: D30
Direction: WSW
Distance: 0.118 mi., 624 ft.
Elevation: 618 ft.
Relative: Higher

Site Name : GLENN YOUNG ARCO #6200 | SAN MARCOS AMPM | RANCHO SANTA FE ARCO
125 N RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257410
EPA ID: CAL000260996

HWG - CA ***(cont.)***

Facility Type :	N/R
Mailing Address :	PO BOX 80249, RANCHO SANTA MARGARI, CA 920688000
Owner Name :	BP WEST COAST PRODUCTS LLC
Owner Address :	4519 GRANDVIEW RD, BLAINE, WA 982300000
Operator Name :	SARAH SAMUELS
Operator Address :	4519 GRANDVIEW RD, BLAINE, WA 982300000
Latitude :	33.150948
Longitude :	-117.197799

Facility Name :	RANCHO SANTA FE ARCO
Facility Address :	125 N RANCHO SANTA FE RD, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAL000388657
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	125 N RANCHO SANTA FE RD, SAN MARCOS, CA 920690000
Owner Name :	PERRY ASGHARZADEH
Owner Address :	125 N RANCHO SANTA FE RD, SAN MARCOS, CA 920690000
Operator Name :	PERRY ASGHARZADEH
Operator Address :	125 N RANCHO SANTA FE RD, SAN MARCOS, CA 92069
Latitude :	33.15083
Longitude :	-117.19746

Facility Name :	SAN MARCOS AM/PM
Facility Address :	125 N RANCHO SANTA FE RD, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAL000299402
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	125 N RANCHO SANTA FE RD, SAN MARCOS, CA 920690000
Owner Name :	PERRY ASHARZADEH
Owner Address :	125 N RANCHO SANTA FE RD, SAN DIEGO, CA 920690000
Operator Name :	PERRY ASGHARZADEH
Operator Address :	125 N RANCHO SANTA FE RD, SAN MARCOS, CA 920690000
Latitude :	33.150948
Longitude :	-117.197799

Map Id: D30
Direction: WSW
Distance: 0.118 mi., 624 ft.
Elevation: 618 ft.
Relative: Higher

Site Name : GLENN YOUNG ARCO #6200 | SAN MARCOS AMPM | RANCHO SANTA FE ARCO
125 N RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257410
EPA ID: CAL000260996

HWG - CA ***(cont.)***

EPA ID :	CAL000182209
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	125 N RANCHO SANTA FE RD, SAN MARCOS, CA 920690000
Owner Name :	GLENN YOUNG
Owner Address :	125 N RANCHO SANTA FE RD, SAN MARCOS, CA 920690000
Operator Name :	STEVE YOUNG - MANAGER
Operator Address :	SAN MARCOS, CA 920690000
Latitude :	33.150935
Longitude :	-117.197864

LUST REG 9 - CA

Facility Name :	GLENN YOUNG ARCO #6200
Facility Address :	125 N RANCHO SANTA FE RD, SAN MARCOS, CA 920691217
County :	San Diego

Site Details

Status Date :	1991-06-20
Status :	Completed - Case Closed
Begin Date :	1989-09-12
Global ID :	T0607300398
Region :	REGION 9
Site History :	N/R
RB Case Number :	9UT1578
Potential Media Affected :	Soil
Potential Contaminants of Concern :	Gasoline
Local Agency :	SAN DIEGO COUNTY LOP
Local Case Number :	H05181-002
Lead Agency :	SAN DIEGO COUNTY LOP
File Location :	Local Agency
CUF Case :	YES
Caseworker :	NS
Case Type :	LUST Cleanup Site
How Discovered :	N/R
How Discovered Description :	N/R
Stop Method :	N/R
Stop Description :	N/R
Calwater Watershed Name :	Carlsbad - San Marcos - Richland (904.52)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)
Disadvantaged Community :	N/R
Latitude :	33.150833
Longitude :	-117.197446
Agency URL :	Click here for hyperlink provided by the agency.

Map Id: D30
Direction: WSW
Distance: 0.118 mi., 624 ft.
Elevation: 618 ft.
Relative: Higher

Site Name : GLENN YOUNG ARCO #6200 | SAN MARCOS AMPM | RANCHO SANTA FE ARCO
125 N RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257410
EPA ID: CAL000260996

LUST REG 9 - CA ***(cont.)***

Last Date in Agency List : 2022-02-11

Contacts Summary
Global ID : T0607300398
Contact Name : NASSER SIONIT
Contact Type : Local Agency Caseworker
Organization Name : SAN DIEGO COUNTY LOP
Address : P.O. Box 129261
City : San Diego
Phone Number : N/R
Email : nasser.sionit@sdcounty.ca.gov

Regulatory Activities
Date : 1989-09-13
Global ID : T0607300398
Action Type : Other
Action : Leak Reported

Date : 1989-09-12
Global ID : T0607300398
Action Type : Other
Action : Leak Discovery

Date : 1989-09-12
Global ID : T0607300398
Action Type : Other
Action : Leak Began

Date : 1989-09-12
Global ID : T0607300398
Action Type : Other
Action : Leak Stopped

Status History
Status Date : 1991-06-20
Global ID : T0607300398
Status : Completed - Case Closed

Map Id: D30
Direction: WSW
Distance: 0.118 mi., 624 ft.
Elevation: 618 ft.
Relative: Higher

Site Name : GLENN YOUNG ARCO #6200 | SAN MARCOS AMPM | RANCHO SANTA FE ARCO
125 N RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257410
EPA ID: CAL000260996

LUST REG 9 - CA ***(cont.)***

Status Date :	1989-09-12
Global ID :	T0607300398
Status :	Open - Case Begin Date

Site Details

Status Date :	2018-05-16
Status :	Completed - Case Closed
Begin Date :	1993-06-21
Global ID :	T0607301273
Region :	REGION 9

Site History :

The Site is an active gasoline station and mini-market at 125 North Ranch Santa Fe Road in San Marcos, California. Station facilities consist of four underground storage tanks (USTs), two dispenser islands, a building, parking, and a landscaped area (southern portion of the Site). The USTs, associated dispensers and product piping were replaced in October 1993 and the dispensers and product piping were replaced again in November 2003. Based on the results of soil sampling, Unauthorized Release Case H05181-004 was opened. Soil removed during the 1993 UST removal was placed back in the excavation area for future remediation. In addition, soil was excavated for the current UST area, which is adjacent and to the west of the former USTs. Most of the soil removed was transported off-site for disposal, but 80-100 cubic yards of soil removed between 5 and 15 feet bgs from the southern portion of the current UST area was reportedly used to complete backfilling the former UST area. A total of approximately 1,100 cubic yards (1,479 tons) of soil have been removed from the Site to date. Measurable free product have previously been reported in wells MW-1, MW-2, MW-3, MW-6 and MW-8. LPH was last reported in well MW-1 (sheen detected during well purging) in May 2008. Approximately 132 gallons of LPH have been reportedly removed from Site wells to date using a vacuum truck, petro trap and rubberizer boom, and by hand bailing. An unknown amount has been removed from the use of absorbent socks, previous remedial system operation, and 2003 high vacuum dual-phase extraction (HVDPE) feasibility testing. In March 2011, extraction well EW-1 and injection wells IW-1, IW-2, IW-3 were installed, for use during the feasibility testing. From September 13 through 16, 2011, an in situ chemical oxidation (ISCO) test was conducted, which involved the injection of approximately 1,436 gallons of a 12% solution of sodium persulfate, approximately 15.5 gallons of a 6% solution of hydrogen peroxide into IW-1, IW-2 and IW-3, and approximately 20.5 gallons of a 3% solution of hydrogen peroxide into wells IW-1 and IW-3. The high vacuum dual-phase extraction (HVDPE) testing involved three events that were performed during three consecutive months, utilizing EW-1 for extraction. A 117-hour event was performed in November, a 90-hour HVDPE event in December 2011 and a 90-hour event in January 2012, resulting in the removal of a total of approximately 2,190 gallons of groundwater and 26 pounds of gasoline range organics (GRO) as vapor. In August 2003, a CAP was submitted, recommending soil vapor extraction (SVE), followed by remediation by natural attenuation (RNA) as the most cost-effective remedial action for the Site. In January 2004, a SVE system was installed at the Site and operation began. Due to asymptotic vapor concentrations from source wells, SECOR discontinued system operation in January 2006. The system removed and treated approximately 2,762 pounds of GRO (also reported as volatile fuel hydrocarbons in previous reports), 1.34 pounds of benzene and 2.9 pounds of MTBE from wells VE-1, VE-2, MW-1, MW-2, MW-3, MW-4, MW-8, and MW-9. In June 2008, four vapor points were installed around the station building, as part of a vapor risk assessment (VRA). Based on the soil vapor sample data, none of the analyzed VOCs that were listed in the VRA model were detected at or above laboratory reporting limits. The excess cancer risk to workers and customers in the existing or possible future buildings on the site was determined to be less than the one-in-a-million level. In March 2003, a high-vacuum dual-phase extraction (HVDPE) feasibility testing was

Map Id: D30
Direction: WSW
Distance: 0.118 mi., 624 ft.
Elevation: 618 ft.
Relative: Higher

Site Name : GLENN YOUNG ARCO #6200 | SAN MARCOS AMPM | RANCHO SANTA FE ARCO
125 N RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257410
EPA ID: CAL000260996

LUST REG 9 - CA ***(cont.)***

performed using a mobile remediation system. A 24-hour test was performed using MW-2 as the extraction well and a 23-hour test was performed using MW-3 as the extraction well. Based on the testing data, HVDPE appeared to be an effective method to remove subsurface hydrocarbons beneath the site, but the groundwater recovery was slow and inconsistent. Approximately 400 gallons of fluids and 273 pounds of hydrocarbons as vapor were removed during testing, with an average groundwater removal rate of 0.14 gallons per minute (per well). Evaluation of benzene and MTBE concentration trends using linear regression trend lines, consideration of decreasing average benzene and MTBE concentrations, and BIOSCREEN modeling provide converging lines of evidence that RNA is occurring at the site and benzene and MTBE concentrations will reach MCLs through RNA processes. Estimates of the time needed for benzene and MTBE to reach MCLs (derived from estimates based on BIOSCREEN) are less than 50 years for benzene and less than 25 years for MTBE. These appear to correlate well with the estimates for near-source area wells MW-1 and MW-3 from linear regression trend lines with benzene ranging from 6 to 49 years, and MTBE ranging from <1 to 24 years. Based on the pounds of hydrocarbons removed during SVE and the HVDPE test, the estimated hydrocarbon mass remaining in soil is 2,075 pounds.

RB Case Number :	9UT2527
Potential Media Affected :	Aquifer used for drinking water supply
Potential Contaminants of Concern :	Gasoline
Local Agency :	SAN DIEGO COUNTY LOP
Local Case Number :	H05181-004
Lead Agency :	SAN DIEGO COUNTY LOP
File Location :	Local Agency
CUF Case :	NO
Caseworker :	JC
Case Type :	LUST Cleanup Site
How Discovered :	Tank Closure, UST System Modification
How Discovered Description :	N/R
Stop Method :	Close and Replace Tank
Stop Description :	CLOSE AND REPLACE TANK
Calwater Watershed Name :	Carlsbad - Agua Hedionda - Buena (904.32)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)
Disadvantaged Community :	Severely Disadvantaged Community
Latitude :	33.150934
Longitude :	-117.197758
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-11

Contacts Summary

Global ID :	T0607301273
Contact Name :	JAMES CLAY
Contact Type :	Local Agency Caseworker
Organization Name :	SAN DIEGO COUNTY LOP
Address :	P.O. Box 129261
City :	San Diego
Phone Number :	N/R
Email :	james.clay@sdcounty.ca.gov

Map Id: D30
Direction: WSW
Distance: 0.118 mi., 624 ft.
Elevation: 618 ft.
Relative: Higher

Site Name : GLENN YOUNG ARCO #6200 | SAN MARCOS AMPM | RANCHO SANTA FE ARCO
125 N RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257410
EPA ID: CAL000260996

LUST REG 9 - CA ***(cont.)***

Regulatory Activities

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Date :	2018-05-16
Global ID :	T0607301273
Action Type :	ENFORCEMENT
Action :	Closure/No Further Action Letter

Date :	2017-04-28
Global ID :	T0607301273
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other

Date :	2016-12-09
Global ID :	T0607301273
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other

Date :	2016-09-08
Global ID :	T0607301273
Action Type :	RESPONSE
Action :	Correspondence

Date :	2016-08-31
Global ID :	T0607301273
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other

Date :	2016-07-30
Global ID :	T0607301273
Action Type :	RESPONSE
Action :	Monitoring Report - Semi-Annually

Date :	2016-07-27
Global ID :	T0607301273
Action Type :	RESPONSE
Action :	Other Report / Document - Regulator Responded

Map Id: D30
Direction: WSW
Distance: 0.118 mi., 624 ft.
Elevation: 618 ft.
Relative: Higher

Site Name : GLENN YOUNG ARCO #6200 | SAN MARCOS AMPM | RANCHO SANTA FE ARCO
125 N RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257410
EPA ID: CAL000260996

LUST REG 9 - CA ***(cont.)***

Date :	2016-06-22
Global ID :	T0607301273
Action Type :	RESPONSE
Action :	Email Correspondence
Date :	2016-06-01
Global ID :	T0607301273
Action Type :	RESPONSE
Action :	Other Report / Document
Date :	2016-03-21
Global ID :	T0607301273
Action Type :	RESPONSE
Action :	Monitoring Report - Other

Status History

Status Date :	2018-05-16
Global ID :	T0607301273
Status :	Completed - Case Closed
Status Date :	1994-01-01
Global ID :	T0607301273
Status :	Open - Remediation
Status Date :	1993-06-21
Global ID :	T0607301273
Status :	Open - Case Begin Date

MANIFEST EPA

Manifest Details

Manifest Number :	019461850JJK
Shipped Date :	2019-04-30
Updated Date :	2020-01-23
Received Date :	2019-04-30
Status :	Signed
Generator ID :	CAL000388657
Generator Name :	RANCHO SANTA FE ARCO
Generator Address :	125 N RANCHO SANTA FE RD, SAN MARCOS, CA 92069
Generator Mailing :	125 N RANCHO SANTA FE RD, SAN MARCOS, CA 92069-0000
Generator Contact :	N/R
Destination ID :	AZR000510065

Map Id: D30
Direction: WSW
Distance: 0.118 mi., 624 ft.
Elevation: 618 ft.
Relative: Higher

Site Name : GLENN YOUNG ARCO #6200 | SAN MARCOS AMPM | RANCHO SANTA FE ARCO
125 N RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257410
EPA ID: CAL000260996

MANIFEST EPA ***(cont.)***

Destination Name :	US FUEL OIL, LLC
Destination Mailing :	8987 W OLIVE AVE STE 117-27, PEORIA, AZ 85345-9125
Destination Address :	3125 W DOME ROCK RD SPC 300, QUARTZSITE, AZ 85346
Destination Contact :	N/R
Submission Type :	DataImage5Copy
Origin Type :	Web
Manifest Residue :	N
Rejection :	N
Last Date in Agency List :	2022-01-14

Waste Details

Waste Line Number :	1
Is DOT Hazardous :	N
DOT ID Number :	N/R
DOT Information :	N/R
Non Waste Description :	NON-RCRA HAZARDOUS WASTE LIQUID (SB989 TEST WATER)
Quantity :	30 Gallons
Quantity Tons, Acute, Non-Acute :	0.12510425, 0, 0.12510425
Quantity Kg, Acute, Non-Acute :	0, 113.47331
Management Method :	H141 - STORAGE, BULKING AND/OR TRANSFER OFF SITE
Is EPA Waste :	N
Federal Code :	N/R
State Code :	CA - 134

Manifest Details

Manifest Number :	019459922JJK
Shipped Date :	2019-02-28
Updated Date :	2019-11-07
Received Date :	2019-03-01
Status :	Signed
Generator ID :	CAL000388657
Generator Name :	RANCHO SANTA FE ARCO
Generator Address :	125 N RANCHO SANTA FE RD, SAN MARCOS, CA 92069
Generator Mailing :	125 N RANCHO SANTA FE RD, SAN MARCOS, CA 92069-0000
Generator Contact :	N/R
Destination ID :	AZR000510065
Destination Name :	US FUEL OIL, LLC
Destination Mailing :	8987 W OLIVE AVE STE 117-27, PEORIA, AZ 85345-9125
Destination Address :	3125 W DOME ROCK RD SPC 300, QUARTZSITE, AZ 85346
Destination Contact :	N/R
Submission Type :	DataImage5Copy
Origin Type :	Web
Manifest Residue :	N
Rejection :	N

Map Id: D30
Direction: WSW
Distance: 0.118 mi., 624 ft.
Elevation: 618 ft.
Relative: Higher

Site Name : GLENN YOUNG ARCO #6200 | SAN MARCOS AMPM | RANCHO SANTA FE ARCO
125 N RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257410
EPA ID: CAL000260996

MANIFEST EPA ***(cont.)***

Last Date in Agency List : 2022-01-14

Waste Details

Waste Line Number :	1
Is DOT Hazardous :	N
DOT ID Number :	N/R
DOT Information :	N/R
Non Waste Description :	NON-RCRA HAZARDOUS WASTE LIQUID (SB 969 TEST WATER)
Quantity :	110 Gallons
Quantity Tons, Acute, Non-Acute :	0.4587156, 0, 0.4587156
Quantity Kg, Acute, Non-Acute :	0, 416.06882
Management Method :	H141 - STORAGE, BULKING AND/OR TRANSFER OFF SITE
Is EPA Waste :	N
Federal Code :	N/R
State Code :	CA - 134

RCRA_NONGEN

Facility Name :	RANCHO SANTA FE ARCO
Facility Address :	125 N RANCHO SANTA FE RD, SAN MARCOS, CA 92069
County :	SAN DIEGO
Date Form Received by Agency :	2013-08-14
EPA ID :	CAL000388657
Mailing Address :	125 N RANCHO SANTA FE RD, SAN MARCOS, CA 92069-0000
Contact :	PERRY ASGHARZADEH
Contact Address :	125 N RANCHO SANTA FE RD, SAN MARCOS, CA 92069
Contact Country :	N/R
Contact Telephone :	858-243-9595
Contact Email :	PERRYMARYA@AOL.COM
EPA Region :	09
Land Type :	Not Reported
Source Type :	Implementer
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2022-01-26

Owner/Operator Summary

Owner/Operator Name :	PERRY ASGHARZADEH
Owner/Operator Address :	125 N RANCHO SANTA FE RD, SAN MARCOS, CA 92069-0000
Owner/Operator Country :	N/R
Owner/Operator Telephone :	858-243-9595
Owner/Operator Email :	N/R

Map Id: D30
Direction: WSW
Distance: 0.118 mi., 624 ft.
Elevation: 618 ft.
Relative: Higher

Site Name : GLENN YOUNG ARCO #6200 | SAN MARCOS AMPM | RANCHO SANTA FE ARCO
125 N RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257410
EPA ID: CAL000260996

RCRA_NONGEN ***(cont.)***

Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Owner/Operator Name :	PERRY ASGHARZADEH
Owner/Operator Address :	125 N RANCHO SANTA FE RD, SAN MARCOS, CA 92069
Owner/Operator Country :	N/R
Owner/Operator Telephone :	858-243-9595
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Notices of Violations Summary

Regulation Violated :	N

SLIC REG 9 - CA

Facility Name :	GLENN YOUNG ARCO #6200
Facility Address :	125 N RANCHO SANTA FE RD, SAN MARCOS, CA 920691217
County :	San Diego

Map Id: D30
Direction: WSW
Distance: 0.118 mi., 624 ft.
Elevation: 618 ft.
Relative: Higher

Site Name : GLENN YOUNG ARCO #6200 | SAN MARCOS AMPM | RANCHO SANTA FE ARCO
125 N RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257410
EPA ID: CAL000260996

SLIC REG 9 - CA ***(cont.)***

Site Details

Status Date :	1991-07-12
Status :	Completed - Case Closed
Begin Date :	1987-01-30
Global ID :	T0608153478
Region :	REGION 9
Site History :	N/R
RB Case Number :	N/R
Potential Media Affected :	N/R
Potential Contaminants of Concern :	N/R
Local Agency :	SAN DIEGO COUNTY LOP
Local Case Number :	H05181-001
Lead Agency :	SAN DIEGO COUNTY LOP
File Location :	Local Agency
CUF Case :	NO
Caseworker :	NS
Case Type :	Cleanup Program Site
How Discovered :	N/R
How Discovered Description :	N/R
Stop Method :	N/R
Stop Description :	N/R
Calwater Watershed Name :	Carlsbad - San Marcos - Richland (904.52)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)
Disadvantaged Community :	N/R
Latitude :	33.150832
Longitude :	-117.197464
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-11

Contacts Summary

Global ID :	T0608153478
Contact Name :	NASSER SIONIT
Contact Type :	Local Agency Caseworker
Organization Name :	SAN DIEGO COUNTY LOP
Address :	P.O. Box 129261
City :	San Diego
Phone Number :	N/R
Email :	nasser.sionit@sdcounty.ca.gov

Regulatory Activities

Date :	N/R
Global ID :	T0608153478
Action Type :	N/R
Action :	N/R

Map Id: D30
Direction: WSW
Distance: 0.118 mi., 624 ft.
Elevation: 618 ft.
Relative: Higher

Site Name : GLENN YOUNG ARCO #6200 | SAN MARCOS AMPM | RANCHO SANTA FE ARCO
125 N RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257410
EPA ID: CAL000260996

SLIC REG 9 - CA ***(cont.)***

Status History

Status Date :	1991-07-12
Global ID :	T0608153478
Status :	Completed - Case Closed
Status Date :	1987-01-30
Global ID :	T0608153478
Status :	Open - Case Begin Date

Site Details

Status Date :	1991-08-06
Status :	Completed - Case Closed
Begin Date :	1986-10-16
Global ID :	T0608148767
Region :	REGION 9
Site History :	N/R
RB Case Number :	N/R
Potential Media Affected :	Under Investigation
Potential Contaminants of Concern :	Gasoline
Local Agency :	N/R
Local Case Number :	H05181-003
Lead Agency :	SAN DIEGO COUNTY LOP
File Location :	Local Agency
CUF Case :	NO
Caseworker :	N/R
Case Type :	Cleanup Program Site
How Discovered :	N/R
How Discovered Description :	N/R
Stop Method :	N/R
Stop Description :	N/R
Calwater Watershed Name :	Carlsbad - San Marcos - Richland (904.52)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)
Disadvantaged Community :	N/R
Latitude :	33.150832
Longitude :	-117.197464
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-11

Contacts Summary

Global ID :	T0608148767
Contact Name :	N/R
Contact Type :	N/R
Organization Name :	N/R

Map Id: D30
Direction: WSW
Distance: 0.118 mi., 624 ft.
Elevation: 618 ft.
Relative: Higher

Site Name : GLENN YOUNG ARCO #6200 | SAN MARCOS AMPM | RANCHO SANTA FE ARCO
125 N RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257410
EPA ID: CAL000260996

SLIC REG 9 - CA ***(cont.)***

Address :	N/R
City :	N/R
Phone Number :	N/R
Email :	N/R

Regulatory Activities

Date :	1987-01-27
Global ID :	T0608148767
Action Type :	Other
Action :	Leak Reported

Date :	1986-10-16
Global ID :	T0608148767
Action Type :	Other
Action :	Leak Began

Date :	1986-10-16
Global ID :	T0608148767
Action Type :	Other
Action :	Leak Discovery

Status History

Status Date :	1991-08-06
Global ID :	T0608148767
Status :	Completed - Case Closed

Status Date :	1986-10-16
Global ID :	T0608148767
Status :	Open - Case Begin Date

UST - CA

Facility Name :	125 Matthew Inc.
Facility Address :	125 N RANCHO SANTA FE RD, SAN MARCOS, 92069
County :	San Diego

Facility ID :	37-000-105181
CERS ID :	10375633
Permitting Agency :	San Diego County Department of Environmental Health
Latitude :	33.15083

Map Id: D30
Direction: WSW
Distance: 0.118 mi., 624 ft.
Elevation: 618 ft.
Relative: Higher

Site Name : GLENN YOUNG ARCO #6200 | SAN MARCOS AMPM | RANCHO SANTA FE ARCO
125 N RANCHO SANTA FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257410
EPA ID: CAL000260996

UST - CA ***(cont.)***

Longitude :	-117.19746
Last Date in Agency List :	2022-03-07
Facility Name :	GLENN YOUNG ARCO #6200
Facility Address :	125 N RANCHO SANTA FE RD, SAN MARCOS, 92069
County :	San Diego
Facility ID :	H05181
CERS ID :	N/R
Permitting Agency :	SAN DIEGO COUNTY
Latitude :	33.152182
Longitude :	-117.196116
Last Date in Agency List :	2017-01-13
Facility Name :	San Marcos AMPM
Facility Address :	125 N RANCHO SANTA FE RD, SAN MARCOS, 92069
County :	San Diego
Facility ID :	37-000-105181
CERS ID :	10375633
Permitting Agency :	San Diego County Department of Environmental Health
Latitude :	33.15083
Longitude :	-117.19746
Last Date in Agency List :	2021-09-10

Map Id: F31
Direction: ESE
Distance: 0.118 mi., 625 ft.
Elevation: 570 ft.
Relative: Lower

Site Name : TRI CITY COMPETITION SERVICE
1338 N PACIFIC
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 41013376
EPA ID: CAL000060270

HAZNET - CA

Facility Name :	TRI CITY COMPETITION SERVICE
Facility Address :	1338 N PACIFIC, SAN MARCOS, CA 92069
County :	SAN DIEGO

Map Id: F31
Direction: ESE
Distance: 0.118 mi., 625 ft.
Elevation: 570 ft.
Relative: Lower

Site Name : TRI CITY COMPETITION SERVICE
1338 N PACIFIC
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 41013376
EPA ID: CAL000060270

HAZNET - CA ***(cont.)***

Site Details

Generator EPA ID :	CAL000060270
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	1338 N PACIFIC, SAN MARCOS, CA 920690000
Latitude :	33.15039699
Longitude :	-117.19294748
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HWG - CA

Facility Name :	TRI CITY COMPETITION SERVICE
Facility Address :	1338 N PACIFIC, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAL000060270
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	1338 N PACIFIC, SAN MARCOS, CA 920690000
Owner Name :	GREGG LUNEACIC
Owner Address :	N/A
Operator Name :	GREGG LUNEACK
Operator Address :	133B N PACIFIC ST, SAN MARCOS, CA 920690000
Latitude :	33.152426
Longitude :	-117.190614

Map Id: D32
Direction: WSW
Distance: 0.119 mi., 627 ft.
Elevation: 618 ft.
Relative: Higher

Site Name : ARCO PRODUCTS COMPANY | ARCO #6200 | ARCO Facility No. 6200 125 North Rancho Santa Fe Road
125 NORTH RANCHO SANTE FE | 125 RANCHO SANTA FE RD N | 125 North Rancho Santa Fe Road
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS 2 - CA, FRS, HAZNET - CA, HWG - CA]

Envirosite ID: 247289
EPA ID: CAL923584355

CALEPA SITES - CA

Facility Name :	ARCO #6200
Facility Address :	125 RANCHO SANTA FE RD N, SAN MARCOS, 92069-1217

Map Id: D32
Direction: WSW
Distance: 0.119 mi., 627 ft.
Elevation: 618 ft.
Relative: Higher

Site Name : ARCO PRODUCTS COMPANY | ARCO #6200 | ARCO Facility No. 6200 125 North Rancho Santa Fe Road
125 NORTH RANCHO SANTE FE | 125 RANCHO SANTA FE RD N | 125 North Rancho Santa Fe Road
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS 2 - CA, FRS, HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 247289
EPA ID: CAL923584355

CALEPA SITES - CA ***(cont.)***

Site ID :	451995
EI ID :	110021282878
EI Description :	US EPA Air Emission Inventory System (EIS)
Latitude :	33.150950
Longitude :	-117.197810
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07

CIWQS 2 - CA

Facility Name :	ARCO Facility No. 6200 125 North Rancho Santa Fe Road
Facility Address :	125 North Rancho Santa Fe Road, San Marcos, 92609
County :	San Diego
Facility ID :	769480
WDID :	9 000002323
Facility Type :	Industrial
Region :	9
Place Type :	Facility
Place Subtype :	Groundwater Cleanup Site
Ageny Name :	BP West Coast Product LLC
Agency Type :	Privately-Owned Business
Number of Agencies :	1
Status Date :	2014-01-22
Status :	Historical
Status Enrollee :	N
Individual/General :	I
Fee Code :	58 - Non15 Based on (TTWQ)/CPLX)
Staff Assigned :	N/R
Number of Staff Assigned :	N/R
Supervisor :	N/R
Number of Supervisor :	N/R
Number of Amendments :	0
Number of Reg Measures :	1
Baseline Flow :	N/R
Population (MS4)/Acres :	N/R
Reclamation :	N/R
CAFO Type :	N/R
CAFO Subtype :	N/R
CAFO Population :	N/R
Onsite :	N/R
Quality Assurance :	N/R
RCRA Flag :	N/R
Total MMP Violations Number :	0
Total Number of Violations :	0
Total Number of Inspections :	1
Date of Most Recent Completed Inspection:	2012-06-11
Date of Most Recent Received Report :	N/R

Map Id: D32
Direction: WSW
Distance: 0.119 mi., 627 ft.
Elevation: 618 ft.
Relative: Higher

Site Name : ARCO PRODUCTS COMPANY | ARCO #6200 | ARCO Facility No. 6200 125 North Rancho Santa Fe Road
125 NORTH RANCHO SANTE FE | 125 RANCHO SANTA FE RD N | 125 North Rancho Santa Fe Road
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS 2 - CA, FRS, HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 247289
EPA ID: CAL923584355

CIWQS 2 - CA ***(cont.)***

Total Number of Final (A+H) Enforcement Actions:	0
Most Recent Effective Date of Enf Action (A+H):	N/R
Program :	WDRNONMUNIPRCS
Program Category :	WDR
Number of Programs :	1
Complexity :	C
Pretreatment :	N/R
Facility Waste Type :	Miscellaneous
Reg Measure ID :	380703
Reg Measure Type :	Enrollee - WDR
Reg Measure Title :	Enrollee WDR R9-2008-0081 ARCO Facility No. 6200 North Rancho Santa Fe
Reg Measure Description :	N/R
SIC 1 :	-
SIC 2 :	-
SIC 3 :	-
Latitude :	N/R
Longitude :	N/R
Last Date in Agency List :	2022-01-18

FRS

Facility Name :	ARCO #6200
Facility Address :	125 RANCHO SANTA FE RD N, SAN MARCOS, CA 92069-1217
County :	SAN DIEGO

Site Details

Registry ID :	110021282878
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Source Description

Source Description :

The Emission Inventory System (EIS) maintains an inventory of large stationary sources and voluntarily-reported smaller sources of air point pollution emitters. It contains information about facility sites and their physical location, emission units, emission processes, release points, control approaches, and regulations. Facility inventory data are kept separate from the emissions data and have stable identifiers to improve continuity from year to year and to help identify duplicate or missing facilities.

Map Id: D32
Direction: WSW
Distance: 0.119 mi., 627 ft.
Elevation: 618 ft.
Relative: Higher

Site Name : ARCO PRODUCTS COMPANY | ARCO #6200 | ARCO Facility No. 6200 125 North Rancho Santa Fe Road
125 NORTH RANCHO SANTE FE | 125 RANCHO SANTA FE RD N | 125 North Rancho Santa Fe Road
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS 2 - CA, FRS, HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 247289
EPA ID: CAL923584355

FRS ***(cont.)***

FRS Environmental Interest

Source and System ID :	EIS - 3292811

HAZNET - CA

Facility Name :	ARCO PRODUCTS COMPANY
Facility Address :	125 NORTH RANCHO SANTE FE, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL923584355
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	PO BOX 6038, ARTESIA, CA 907026038
Latitude :	33.15093300
Longitude :	-117.19739250
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :

2001: 134 - Aqueous solution with total organic residues less than 10 percent, 1.5792 tons to CAT080013352
2000: 134 - Aqueous solution with total organic residues less than 10 percent, 1.5582 tons to CAT080013352
1999: 134 - Aqueous solution with total organic residues less than 10 percent, 0.6846 tons to CAT080013352
1998: 134 - Aqueous solution with total organic residues less than 10 percent, 0.5124 tons to CAT080013352
1997: 134 - Aqueous solution with total organic residues less than 10 percent, 0.147 tons to CAT080013352
1996: 134 - Aqueous solution with total organic residues less than 10 percent, 2.394 tons to CAT080013352
1995: 134 - Aqueous solution with total organic residues less than 10 percent, 0.147 tons to CAT080013352
1994: 134 - Aqueous solution with total organic residues less than 10 percent, 0.84 tons to CAT080013352
1993: 223 - Unspecified oil-containing waste, 5.004 tons to CAT080013352

HWG - CA

Facility Name :	ARCO PRODUCTS COMPANY
Facility Address :	125 NORTH RANCHO SANTE FE, SAN MARCOS, CA 92069

Map Id: D32
Direction: WSW
Distance: 0.119 mi., 627 ft.
Elevation: 618 ft.
Relative: Higher

Site Name : ARCO PRODUCTS COMPANY | ARCO #6200 | ARCO Facility No. 6200 125 North Rancho Santa Fe Road
125 NORTH RANCHO SANTE FE | 125 RANCHO SANTA FE RD N | 125 North Rancho Santa Fe Road
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS 2 - CA, FRS, HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 247289
EPA ID: CAL923584355

HWG - CA ***(cont.)***

County :	SAN DIEGO
EPA ID :	CAL923584355
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	PO BOX 6038, ARTESIA, CA 907026038
Owner Name :	ATLANTIC RICHFIELD COMPANY
Owner Address :	PO BOX 6038, ARTESIA, CA 907026038
Operator Name :	CARLOS RODRIGUEZ/ENV COMPL ADM
Operator Address :	INACT PER LTR OWNER CHANGE/REORG, ARTESIA, CA 907026038
Latitude :	33.150935
Longitude :	-117.197864

Map Id: F33
Direction: ESE
Distance: 0.120 mi., 632 ft.
Elevation: 570 ft.
Relative: Lower

Site Name : CREATIVE PAINTING & WALL COVERING | PFT STORAGE INC | STOREM SELF STORAGE
185 N PACIFIC ST
SAN MARCOS, CA 92069

Database(s) : [CIWQS - CA, HAZNET - CA, HWG - CA]

Envirosite ID: 522724
EPA ID: N/R

CIWQS - CA

Facility Name :	PFT STORAGE INC
Facility Address :	185 N PACIFIC ST, SAN MARCOS, CA 92069
County :	SAN DIEGO
Place ID :	S883160
Agency Name :	PFT STORAGE INC
Last Date in Agency List :	2021-12-30
Facility Name :	STOREM SELF STORAGE
Facility Address :	185 N PACIFIC ST, SAN MARCOS, CA 92069
County :	SAN DIEGO
Place ID :	S883042
Agency Name :	STOREM SELF STORAGE
Last Date in Agency List :	2021-12-30

Map Id: F33
Direction: ESE
Distance: 0.120 mi., 632 ft.
Elevation: 570 ft.
Relative: Lower

Site Name : CREATIVE PAINTING & WALL COVERING | PFT STORAGE INC | STOREM SELF STORAGE
185 N PACIFIC ST
SAN MARCOS, CA 92069

Database(s) : [CIWQS - CA, HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 522724
EPA ID: N/R

HAZNET - CA

Facility Name :	CREATIVE PAINTING & WALL COVERING
Facility Address :	185 N PACIFIC ST, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAC002515327
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	3028 UNICORNIO ST, LA COSTA, CA 920090000
Latitude :	33.15029728
Longitude :	-117.19293676
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	2001: 291 - Latex waste, 1.6856 tons to CAD982444481 2001: 214 - Unspecified solvent mixture, 0.486 tons to CAD008252405

HWG - CA

Facility Name :	CREATIVE PAINTING & WALL COVERING
Facility Address :	185 N PACIFIC ST, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAC002515327
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	3028 UNICORNIO ST, LA COSTA, CA 920090000
Owner Name :	CHARLES OSTERHOUT
Owner Address :	3028 UNICORNIO ST, LACOSTA, CA 920090000
Operator Name :	CHARLIE OSTERHOUT-OWNER
Operator Address :	3028 UNICORNIO ST, LACOSTA, CA 920090000
Latitude :	33.150182
Longitude :	-117.193103

Map Id: F34
Direction: ESE
Distance: 0.124 mi., 657 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : LOREAL USA INC | 1X FRITO LAY INC
215 PACIFIC ST UNIT 103 | 235 SOUTH PACIFIC
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 41097457
EPA ID: CAC000656960

HAZNET - CA

Facility Name :	1X FRITO LAY INC
Facility Address :	235 SOUTH PACIFIC, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAC000656960
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	7701 LEGACY DRIVE, PLANO, TX 750244099
Latitude :	33.15074224
Longitude :	-117.19279810
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Facility Name :	LOREAL USA INC
Facility Address :	215 PACIFIC ST UNIT 103, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAC002557328
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	6800 ARNIE MILLER PKWY, SOLON, OH 44139
Latitude :	33.14405407
Longitude :	-117.19613909
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HWG - CA

Facility Name :	1X FRITO LAY INC
Facility Address :	235 SOUTH PACIFIC, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAC000656960
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	7701 LEGACY DRIVE, PLANO, TX 750244099
Owner Name :	CORPORATION
Owner Address :	N/A

Map Id: F34
Direction: ESE
Distance: 0.124 mi., 657 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : LOREAL USA INC | 1X FRITO LAY INC
215 PACIFIC ST UNIT 103 | 235 SOUTH PACIFIC
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 41097457
EPA ID: CAC000656960

HWG - CA ***(cont.)***

Operator Name :	CHRIS LAWSON/ENVIRON ENGE
Operator Address :	N/A
Latitude :	33.143812
Longitude :	-117.196334
Facility Name :	LOREAL USA INC
Facility Address :	215 PACIFIC ST UNIT 103, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAC002557328
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	6800 ARNIE MILLER PKWY, SOLON, OH 44139
Owner Name :	LOREAL USA INC
Owner Address :	6800 ARNIE MILLER PKWY, SOLON, CA 44139
Operator Name :	BRUCE CANCASCI
Operator Address :	6800 ARNIE MILLER PKWY, SOLON, OH 44139
Latitude :	33.144217
Longitude :	-117.19613

Map Id: E35
Direction: WNW
Distance: 0.124 mi., 657 ft.
Elevation: 629 ft.
Relative: Higher

Site Name : MINDY LANDRY
3556 DE LEONE RD.
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 700148
EPA ID: CAC002811384

HAZNET - CA

Facility Name :	MINDY LANDRY
Facility Address :	3556 DE LEONE RD., SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAC002811384
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	3556 DE LEONE RD., SAN MARCOS, CA 92069
Latitude :	33.15321633
Longitude :	-117.19721209
Agency Hyperlink :	Click here for hyperlink provided by the agency.

Map Id: E35
Direction: WNW
Distance: 0.124 mi., 657 ft.
Elevation: 629 ft.
Relative: Higher

Site Name : MINDY LANDRY
3556 DE LEONE RD.
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 700148
EPA ID: CAC002811384

HAZNET - CA ***(cont.)***

Last Date in Agency List : 2021-07-08

Waste Generator Details
State Waste : 2015: 151 - Asbestos containing waste, 0.92 tons to AZC950823111

HWG - CA

Facility Name : MINDY LANDRY
Facility Address : 3556 DE LEONE RD., SAN MARCOS, CA 92069
County : SAN DIEGO

EPA ID : CAC002811384
Status : Inactive
Category : STATE
Type : TEMPORARY
Facility Type : N/R
Mailing Address : 3556 DE LEONE RD., SAN MARCOS, CA 92069
Owner Name : MINDY LANDRY
Owner Address : 3556 DE LEONE RD., SAN MARCOS, CA 92069
Operator Name : MINDY LANDRY
Operator Address : 3556 DE LEONE RD., SAN MARCOS, CA 92069
Latitude : 33.153216
Longitude : -117.197212

Map Id: D36
Direction: WSW
Distance: 0.125 mi., 659 ft.
Elevation: 614 ft.
Relative: Higher

Site Name : CONTINENTAL CLEANERS
109 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA

Database(s) : [DRYCLEANERS - CA, HAZNET - CA, HWG - CA]

Envirosite ID: 560981
EPA ID: CAD981574445

DRYCLEANERS - CA

Property Name : Continental Cleaners

HAZNET - CA

Facility Name : CONTINENTAL CLEANERS
Facility Address : 109 S RANCHO SANTA FE RD, SAN MARCOS, CA 92069
County : SAN DIEGO

Site Details
Generator EPA ID : CAD981574445
Active : Inactive
Category : STATE
Facility Types : N/R

Map Id: D36
Direction: WSW
Distance: 0.125 mi., 659 ft.
Elevation: 614 ft.
Relative: Higher

Site Name : CONTINENTAL CLEANERS
109 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA

Database(s) : [DRYCLEANERS - CA, HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 560981
EPA ID: CAD981574445

HAZNET - CA ***(cont.)***

Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	109 S RANCHO SANTA FE RD, SAN MARCOS, CA 920692501
Latitude :	33.14872806
Longitude :	-117.19884497
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :

2002: 741 - Liquids with halogenated organic compounds >= 1,000 Mg. /L, 1.125 tons to CAT000613976
2001: 741 - Liquids with halogenated organic compounds >= 1,000 Mg. /L, 1.3475 tons to CAT000613976
2000: 211 - Halogenated solvents (chloroforms, methyl chloride, perchloroethylene, etc), 0.4192 tons to CAD981397417
2000: 741 - Liquids with halogenated organic compounds >= 1,000 Mg. /L, 0.36 tons to OHD980587364
2000: 741 - Liquids with halogenated organic compounds >= 1,000 Mg. /L, 0.0975 tons to CAT000613976
2000: 211 - Halogenated solvents (chloroforms, methyl chloride, perchloroethylene, etc), 0.6485 tons to CAD981397417
1999: 211 - Halogenated solvents (chloroforms, methyl chloride, perchloroethylene, etc), 1.5285 tons to CAD981397417
1998: 211 - Halogenated solvents (chloroforms, methyl chloride, perchloroethylene, etc), 1.0676 tons to CAD981397417
1997: 211 - Halogenated solvents (chloroforms, methyl chloride, perchloroethylene, etc), 1.297 tons to CAD981397417
1997: N/R - Blank or unknown, 0 tons to CAD981397417
1997: 211 - Halogenated solvents (chloroforms, methyl chloride, perchloroethylene, etc), 0.44 tons to CAD981397417
1996: 211 - Halogenated solvents (chloroforms, methyl chloride, perchloroethylene, etc), 1.5933 tons to CAD981397417
1995: 211 - Halogenated solvents (chloroforms, methyl chloride, perchloroethylene, etc), 0.44 tons to CAD981397417
1995: N/R - Blank or unknown, 0 tons to CAD981397417
1995: 211 - Halogenated solvents (chloroforms, methyl chloride, perchloroethylene, etc), 1.297 tons to CAD981397417

HWG - CA

Facility Name :	CONTINENTAL CLEANERS
Facility Address :	109 S RANCHO SANTA FE RD, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAD981574445
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	109 S RANCHO SANTA FE RD, SAN MARCOS, CA 920692501
Owner Name :	CONTINENTAL CLEANERS
Owner Address :	109 SOUTH RANCHO SANTA FE RD, SAN MARCOS, CA 920692501

Map Id: D36
Direction: WSW
Distance: 0.125 mi., 659 ft.
Elevation: 614 ft.
Relative: Higher

Site Name : CONTINENTAL CLEANERS
109 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA

Database(s) : [DRYCLEANERS - CA, HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 560981
EPA ID: CAD981574445

HWG - CA ***(cont.)***

Operator Name :	JAMES ROUTH /OWNER
Operator Address :	# CANCELED 12/6/01AS, N/A
Latitude :	33.148725
Longitude :	-117.198972

Map Id: D37
Direction: WSW
Distance: 0.126 mi., 668 ft.
Elevation: 614 ft.
Relative: Higher

Site Name : FIVE STAR TEXACO SERVICE CNTR | RANCHO SANTE FE GAS | RANCHO SANTA FE GAS
105 RANCHO SANTA FE RD | 105 S RANCHO SANTA FE RD | 105 RANCHO SANTA FE RD SAP #120462
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA]

Envirosite ID: 257278
EPA ID: N/R

BRS

Facility Name :	TEXACO SERVICE STATION
Facility Address :	105 RANCHO SANTA FE RD SAP #120462, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Date Form Received by Agency :	2004-02-26
EPA ID :	CAR000125989
Mailing Address :	SHELL OIL PRODUCTS US 12700 NORTHBOROUGH DR MFT240G, HOUSTON, TX 77067-2508
Contact :	PAUL S VIDAKOVICH
Contact Address :	N/R
Contact Country :	US
Contact Telephone :	760-720-4236
Contact Email :	PSVIDAKOVICH@SHELLOPUS.COM
EPA Region :	09
Land Type :	Private
Source Type :	Annual/Biennial Report
Classification :	Large Quantity Generator

Map Id: D37
Direction: WSW
Distance: 0.126 mi., 668 ft.
Elevation: 614 ft.
Relative: Higher

Site Name : FIVE STAR TEXACO SERVICE CNTR | RANCHO SANTE FE GAS | RANCHO SANTA FE GAS
105 RANCHO SANTA FE RD | 105 S RANCHO SANTA FE RD | 105 RANCHO SANTA FE RD SAP #120462
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257278
EPA ID: N/R

BRS ***(cont.)***

Description :

Handlers that generate 1,000 kg or more of hazardous waste during any calendar month; or generate more than 1 kg of acutely hazardous waste during any calendar month; or generate more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generate 1 kg or less of acutely hazardous waste during any calendar month, and accumulate more than 1 kg of acutely hazardous waste at any time; or generate 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulated more than 100 kg of that material at any time.

Last Date in Agency List : 2022-01-25

Owner/Operator Summary

Owner/Operator Name :	EQUILON ENTERPRISES LLC DBA SHELL OIL PR
Owner/Operator Address :	PO BOX 2648, HOUSTON, TX 77252
Owner/Operator Country :	US
Owner/Operator Telephone :	N/R
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Private
Owner/Operator Type :	Owner
Owner/Operator Start Date :	1998-08-01
Owner/Operator End Date :	N/R

Owner/Operator Name :	EQUILON ENTERPRISES LLC DBA SHELL OIL PR
Owner/Operator Address :	N/R
Owner/Operator Country :	US
Owner/Operator Telephone :	N/R
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Private
Owner/Operator Type :	Operator
Owner/Operator Start Date :	1998-08-01
Owner/Operator End Date :	N/R

Waste Activity Monitoring

Report Cycle :	2003
Hazardous Waste Page Number :	1
Hazardous Waste Sub-Page Number :	1
BR Form :	GM

Map Id: D37
Direction: WSW
Distance: 0.126 mi., 668 ft.
Elevation: 614 ft.
Relative: Higher

Site Name : FIVE STAR TEXACO SERVICE CNTR | RANCHO SANTE FE GAS | RANCHO SANTA FE GAS
105 RANCHO SANTA FE RD | 105 S RANCHO SANTA FE RD | 105 RANCHO SANTA FE RD SAP #120462
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257278
EPA ID: N/R

BRS ***(cont.)***

Waste Description :	RINSATE - GASOLINE UST
Primary NAICS :	44711 - Gasoline Stations with Convenience Stores
Source Code :	G45 - Underground storage tank cleanup
Form Code :	W113 - Other aqueous waste or wastewaters (fluid but not sludge)
Management Method :	H135 - Discharge to sewer/POTW or NPDES (with prior storage - with or without treatment)
Generation Tons :	7.71
Managed Tons :	0
Shipped Tons :	7.71
Received Tons :	0
Receiver ID :	CAT080013352
Receiver State :	CA
Shipper ID :	CAR000125989
Shipper State :	CA
Waste Minimization :	N/R
Waste Code List :	D001, D018
Waste Code Group :	TCORICR - One or more D018-D043 code
Waste Generation Type :	N/R

CALEPA SITES - CA

Facility Name :	FIVE STAR TEXACO SERVICE CNTR
Facility Address :	105 RANCHO SANTA FE RD, SAN MARCOS, 920691217
Site ID :	200611
EI ID :	T0607301309
EI Description :	Leaking Underground Storage Tank Cleanup Site
Latitude :	33.148884
Longitude :	-117.198805
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07

Site ID :	200611
EI ID :	T0608107669
EI Description :	Cleanup Program Site
Latitude :	33.148884
Longitude :	-117.198805
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07

Map Id: D37
Direction: WSW
Distance: 0.126 mi., 668 ft.
Elevation: 614 ft.
Relative: Higher

Site Name : FIVE STAR TEXACO SERVICE CNTR | RANCHO SANTE FE GAS | RANCHO SANTA FE GAS
105 RANCHO SANTA FE RD | 105 S RANCHO SANTA FE RD | 105 RANCHO SANTA FE RD SAP #120462
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257278
EPA ID: N/R

CALEPA SITES - CA ***(cont.)***

Site ID :	200611
EI ID :	T0607302827
EI Description :	Leaking Underground Storage Tank Cleanup Site
Latitude :	33.148884
Longitude :	-117.198805
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07
Facility Name :	FORMER TEXACO SERVICE STATION
Facility Address :	105 RANCHO SANTA FE ROAD, SAN MARCOS, 92069
Site ID :	315047
EI ID :	724681
EI Description :	Tanks & Ground Water Clean Up
Latitude :	33.145556
Longitude :	-117.200556
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07
Facility Name :	RANCHO SANTE FE GAS
Facility Address :	105 RANCHO SANTA FE RD, SAN MARCOS, 92069
Site ID :	400398
EI ID :	10376056
EI Description :	Underground Storage Tank
Latitude :	33.148570
Longitude :	-117.198720
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07
Site ID :	400398
EI ID :	10376056
EI Description :	Hazardous Waste Generator
Latitude :	33.148570
Longitude :	-117.198720
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07
Site ID :	400398
EI ID :	10376056

Map Id: D37
Direction: WSW
Distance: 0.126 mi., 668 ft.
Elevation: 614 ft.
Relative: Higher

Site Name : FIVE STAR TEXACO SERVICE CNTR | RANCHO SANTE FE GAS | RANCHO SANTA FE GAS
105 RANCHO SANTA FE RD | 105 S RANCHO SANTA FE RD | 105 RANCHO SANTA FE RD SAP #120462
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257278
EPA ID: N/R

CALEPA SITES - CA ***(cont.)***

EI Description :	Chemical Storage Facilities
Latitude :	33.148570
Longitude :	-117.198720
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07

CASE LIST_SAN DIEGO COUNTY - CA

Facility Name :	FIVE STAR TEXACO SERVICE CNTR
Facility Address :	105 RANCHO SANTA FE RD, SAN MARCOS, CA 920691217
County :	San Diego

Site Details

Status Date :	1988-08-25
Status :	Completed - Case Closed
Begin Date :	1987-01-14
Global ID :	T0607302827
Site History :	N/R
RB Case Number :	9UT535
Potential Media Affected :	Aquifer used for drinking water supply
Potential Contaminants of Concern :	Gasoline
Local Agency :	N/R
Local Case Number :	H05804-001
Lead Agency :	SAN DIEGO COUNTY LOP
File Location :	Local Agency
CUF Case :	NO
Caseworker :	N/R
Case Type :	LUST Cleanup Site
How Discovered :	N/R
How Discovered Description :	N/R
Stop Method :	N/R
Stop Description :	N/R
Calwater Watershed Name :	Carlsbad - San Marcos - Richland (904.52)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)
Disadvantaged Community :	Severely Disadvantaged Community
Latitude :	33.148714
Longitude :	-117.198837
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-09

Map Id: D37
Direction: WSW
Distance: 0.126 mi., 668 ft.
Elevation: 614 ft.
Relative: Higher

Site Name : FIVE STAR TEXACO SERVICE CNTR | RANCHO SANTE FE GAS | RANCHO SANTA FE GAS
105 RANCHO SANTA FE RD | 105 S RANCHO SANTA FE RD | 105 RANCHO SANTA FE RD SAP #120462
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257278
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Contacts Summary

Global ID :	T0607302827
Contact Name :	N/R
Contact Type :	N/R
Organization Name :	N/R
Address :	N/R
City :	N/R
Phone Number :	N/R
Email :	N/R

Regulatory Activities

Date :	1987-01-14
Global ID :	T0607302827
Action Type :	Other
Action :	Leak Stopped

Date :	1987-01-14
Global ID :	T0607302827
Action Type :	Other
Action :	Leak Began

Date :	1987-01-14
Global ID :	T0607302827
Action Type :	Other
Action :	Leak Reported

Date :	1987-01-14
Global ID :	T0607302827
Action Type :	Other
Action :	Leak Discovery

Status History

Status Date :	1988-08-25
Global ID :	T0607302827
Status :	Completed - Case Closed

Status Date :	1987-01-14
Global ID :	T0607302827

Map Id: D37
Direction: WSW
Distance: 0.126 mi., 668 ft.
Elevation: 614 ft.
Relative: Higher

Site Name : FIVE STAR TEXACO SERVICE CNTR | RANCHO SANTE FE GAS | RANCHO SANTA FE GAS
105 RANCHO SANTA FE RD | 105 S RANCHO SANTA FE RD | 105 RANCHO SANTA FE RD SAP #120462
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257278
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Status : Open - Case Begin Date

Site Details

Status Date :	2019-11-07
Status :	Completed - Case Closed
Begin Date :	1987-01-22
Global ID :	T0607301309

Site History :

An underground storage tank was damaged during well installation activities resulting in a subsurface release of approximately 3,200 gallons of unleaded gasoline. Contaminated soil was discovered during the removal of the waste oil tank in April 1991, and the gasoline underground storage tanks and dispensers in June 2003. Quarterly groundwater monitoring has been conducted at the site since August 1989. The consultant overseeing this case is also overseeing the Former Chevron Station (H13261-002) and Former Shell Station (H03229-001) that are located on Rancho Santa Fe Road. Groundwater at the three sites is jointly monitored and sampled. See ESI for additional information.

RB Case Number :	9UT2562
Potential Media Affected :	Aquifer used for drinking water supply
Potential Contaminants of Concern :	Gasoline
Local Agency :	N/R
Local Case Number :	N/R
Lead Agency :	SAN DIEGO RWQCB (REGION 9)
File Location :	Regional Board
CUF Case :	NO
Caseworker :	LT
Case Type :	LUST Cleanup Site
How Discovered :	Site Assessment/Site Investigation
How Discovered Description :	N/R
Stop Method :	Other Means
Stop Description :	OTHER MEANS
Calwater Watershed Name :	Carlsbad - San Marcos - Richland (904.52)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)
Disadvantaged Community :	Severely Disadvantaged Community
Latitude :	33.148719
Longitude :	-117.19879
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-09

Map Id: D37
Direction: WSW
Distance: 0.126 mi., 668 ft.
Elevation: 614 ft.
Relative: Higher

Site Name : FIVE STAR TEXACO SERVICE CNTR | RANCHO SANTE FE GAS | RANCHO SANTA FE GAS
105 RANCHO SANTA FE RD | 105 S RANCHO SANTA FE RD | 105 RANCHO SANTA FE RD SAP #120462
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257278
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Contacts Summary

Global ID :	T0607301309
Contact Name :	LALITHA THOTAKURA
Contact Type :	Regional Board Caseworker
Organization Name :	SAN DIEGO RWQCB (REGION 9)
Address :	2375 NORTHSIDE DRIVE, SUITE 100
City :	SAN DIEGO
Phone Number :	6195213002
Email :	lalitha.thotakura@waterboards.ca.gov

Regulatory Activities

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Date :	2019-12-30
Global ID :	T0607301309
Action Type :	RESPONSE
Action :	Other Report / Document

Date :	2019-11-07
Global ID :	T0607301309
Action Type :	ENFORCEMENT
Action :	Closure/No Further Action Letter

Date :	2019-06-28
Global ID :	T0607301309
Action Type :	RESPONSE
Action :	Well Destruction Report

Date :	2019-04-04
Global ID :	T0607301309
Action Type :	ENFORCEMENT
Action :	Email Correspondence

Date :	2019-01-19
Global ID :	T0607301309
Action Type :	ENFORCEMENT
Action :	Staff Letter

Map Id: D37
Direction: WSW
Distance: 0.126 mi., 668 ft.
Elevation: 614 ft.
Relative: Higher

Site Name : FIVE STAR TEXACO SERVICE CNTR | RANCHO SANTE FE GAS | RANCHO SANTA FE GAS
105 RANCHO SANTA FE RD | 105 S RANCHO SANTA FE RD | 105 RANCHO SANTA FE RD SAP #120462
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257278
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Date : 2018-11-05
Global ID : T0607301309
Action Type : ENFORCEMENT
Action : Notification - Public Notice of Case Closure

Date : 2018-07-30
Global ID : T0607301309
Action Type : RESPONSE
Action : Monitoring Report - Semi-Annually

Date : 2018-01-24
Global ID : T0607301309
Action Type : RESPONSE
Action : Monitoring Report - Semi-Annually

Date : 2017-10-11
Global ID : T0607301309
Action Type : RESPONSE
Action : Correspondence

Date : 2017-08-18
Global ID : T0607301309
Action Type : ENFORCEMENT
Action : Clean Up Fund - Case Closure Review Summary Report (RSR)

Status History

Status Date : 2019-11-07
Global ID : T0607301309
Status : Completed - Case Closed

Status Date : 1988-07-14
Global ID : T0607301309
Status : Open - Remediation

Status Date : 1987-01-22
Global ID : T0607301309
Status : Open - Case Begin Date

Map Id: D37
Direction: WSW
Distance: 0.126 mi., 668 ft.
Elevation: 614 ft.
Relative: Higher

Site Name : FIVE STAR TEXACO SERVICE CNTR | RANCHO SANTE FE GAS | RANCHO SANTA FE GAS
105 RANCHO SANTA FE RD | 105 S RANCHO SANTA FE RD | 105 RANCHO SANTA FE RD SAP #120462
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257278
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Site Details

Status Date :	1993-11-04
Status :	Completed - Case Closed
Begin Date :	1992-09-18
Global ID :	T0608107669
Site History :	N/R
RB Case Number :	N/R
Potential Media Affected :	Under Investigation
Potential Contaminants of Concern :	Gasoline
Local Agency :	N/R
Local Case Number :	H05804-003
Lead Agency :	SAN DIEGO COUNTY LOP
File Location :	Local Agency
CUF Case :	NO
Caseworker :	N/R
Case Type :	Cleanup Program Site
How Discovered :	N/R
How Discovered Description :	N/R
Stop Method :	N/R
Stop Description :	N/R
Calwater Watershed Name :	Carlsbad - San Marcos - Richland (904.52)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)
Disadvantaged Community :	Severely Disadvantaged Community
Latitude :	33.148884
Longitude :	-117.198805
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-09

Contacts Summary

Global ID :	T0608107669
Contact Name :	N/R
Contact Type :	N/R
Organization Name :	N/R
Address :	N/R
City :	N/R
Phone Number :	N/R
Email :	N/R

Regulatory Activities

Date :	1993-02-05
Global ID :	T0608107669
Action Type :	Other

Map Id: D37
Direction: WSW
Distance: 0.126 mi., 668 ft.
Elevation: 614 ft.
Relative: Higher

Site Name : FIVE STAR TEXACO SERVICE CNTR | RANCHO SANTE FE GAS | RANCHO SANTA FE GAS
105 RANCHO SANTA FE RD | 105 S RANCHO SANTA FE RD | 105 RANCHO SANTA FE RD SAP #120462
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257278
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Action : Leak Reported

Date : 1992-09-18
Global ID : T0608107669
Action Type : Other
Action : Leak Discovery

Date : 1992-09-18
Global ID : T0608107669
Action Type : Other
Action : Leak Began

Status History
Status Date : 1993-11-04
Global ID : T0608107669
Status : Completed - Case Closed

Status Date : 1992-09-18
Global ID : T0608107669
Status : Open - Case Begin Date

CIWQS - CA

Facility Name : FORMER TEXACO SERVICE STATION
Facility Address : 105 RANCHO SANTA FE ROAD, SAN MARCOS, CA 92069
County : SAN DIEGO

Place ID : 724681
Agency Name : RESOURCE ENVIRONMENTAL LLC
Last Date in Agency List : 2021-12-30

ECHO

Facility Name : RANCHO SANTA FE GAS
Facility Address : 105 S RANCHO SANTA FE RD, SAN MARCOS, CA 92069-0000
County : SAN DIEGO

Map Id: D37
Direction: WSW
Distance: 0.126 mi., 668 ft.
Elevation: 614 ft.
Relative: Higher

Site Name : FIVE STAR TEXACO SERVICE CNTR | RANCHO SANTE FE GAS | RANCHO SANTA FE GAS
105 RANCHO SANTA FE RD | 105 S RANCHO SANTA FE RD | 105 RANCHO SANTA FE RD SAP #120462
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257278
EPA ID: N/R

ECHO ***(cont.)***

Last Inspection Date :	N/R
Registry ID :	N/R
FIPS Code :	N/R
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	No Violation
Three-Year Compliance Status :	_____
Collection Method :	Zip Code Centroid
Reference Point :	N/R
Accuracy Meters :	10000
Derived Tribes :	N/R
Derived HUC :	N/R
Derived WBD :	N/R
Derived STCTY FIPS :	N/R
Derived Zip :	N/R
Derived CD113 :	N/R
Derived CB2010 :	N/R
MYRTK Universe :	NNN
NPDES IDs :	N/R
CWA Permit Types :	N/R
CWA Compliance Tracking :	N/R
CWA NAICS :	N/R
CWA SICS :	N/R
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	N/R
CWA Current Compliance Status :	N/R
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	N/R

Map Id: D37
Direction: WSW
Distance: 0.126 mi., 668 ft.
Elevation: 614 ft.
Relative: Higher

Site Name : FIVE STAR TEXACO SERVICE CNTR | RANCHO SANTE FE GAS | RANCHO SANTA FE GAS
105 RANCHO SANTA FE RD | 105 S RANCHO SANTA FE RD | 105 RANCHO SANTA FE RD SAP #120462
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257278
EPA ID: N/R

ECHO ***(cont.)***

CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	N/R
Facility NAICS :	44719 - Other Gasoline Stations
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	N/R
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	N
SDWIS Flag :	N
RCRA Flag :	Y
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	Y
NAA Flag :	N/R
Latitude :	33.194075
Longitude :	-117.16177
Last Date in Agency List :	2018-12-17

EPA LUST

Facility Name :	FIVE STAR TEXACO SERVICE CNTR
Facility Address :	105 RANCHO SANTA FE RD, SAN MARCOS, California 920691217
County :	N/R
Facility ID :	N/R
LUST ID :	CAT0607302827
Reported Date :	N/R
Status :	No Further Action
Substance :	N/R
Closed With Residual Contamination (Tribal Only):	N/R

Map Id: D37
Direction: WSW
Distance: 0.126 mi., 668 ft.
Elevation: 614 ft.
Relative: Higher

Site Name : FIVE STAR TEXACO SERVICE CNTR | RANCHO SANTE FE GAS | RANCHO SANTA FE GAS
105 RANCHO SANTA FE RD | 105 S RANCHO SANTA FE RD | 105 RANCHO SANTA FE RD SAP #120462
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257278
EPA ID: N/R

EPA LUST ***(cont.)***

NFA_Letter (Tribal Only) :	N/R
Tribe (Tribal Only) :	N/R
EPA Region :	9
Estimated Population within 1500ft :	2159
Estimated Private Domestic Wells within 1500ft:	0
Within Source Water Protection Area (SPA):	No
SPA Public Water System and Facility ID:	N/R
SPA Water Type :	N/R
SPA Facility Type :	N/R
SPA HUC12 :	N/R
Within Groundwater Wellhead Protection Area (WHPA):	No
WHPA Public Water System and Facility ID:	N/R
WHPA Water Type :	N/R
WHPA Facility Type :	N/R
WHPA HUC12 :	N/R
Within Estimated 100-year Floodplain:	No
Latitude :	33.150730000000003
Longitude :	-117.197850000000003
Last Date in Agency List :	2022-01-04

Facility ID :	N/R
LUST ID :	CAT0607301309
Reported Date :	N/R
Status :	No Further Action
Substance :	N/R
Closed With Residual Contamination (Tribal Only):	N/R
NFA_Letter (Tribal Only) :	N/R
Tribe (Tribal Only) :	N/R
EPA Region :	9
Estimated Population within 1500ft :	2159
Estimated Private Domestic Wells within 1500ft:	0
Within Source Water Protection Area (SPA):	No
SPA Public Water System and Facility ID:	N/R
SPA Water Type :	N/R
SPA Facility Type :	N/R
SPA HUC12 :	N/R
Within Groundwater Wellhead Protection Area (WHPA):	No

Map Id: D37
Direction: WSW
Distance: 0.126 mi., 668 ft.
Elevation: 614 ft.
Relative: Higher

Site Name : FIVE STAR TEXACO SERVICE CNTR | RANCHO SANTE FE GAS | RANCHO SANTA FE GAS
105 RANCHO SANTA FE RD | 105 S RANCHO SANTA FE RD | 105 RANCHO SANTA FE RD SAP #120462
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257278
EPA ID: N/R

EPA LUST ***(cont.)***

WHPA Public Water System and Facility ID:	N/R
WHPA Water Type :	N/R
WHPA Facility Type :	N/R
WHPA HUC12 :	N/R
Within Estimated 100-year Floodplain:	No
Latitude :	33.150730000000003
Longitude :	-117.197850000000003
Last Date in Agency List :	2022-01-04

EPA UST

Facility Name :	RANCHO SANTE FE GAS
Facility Address :	105 RANCHO SANTA FE RD, SAN MARCOS, California 92069
County :	N/R
Facility ID :	CA10376056
Facility Status :	Open UST(s)
Open USTs :	3
Closed USTs :	N/R
Temporarily Out of Service USTs :	N/R
Date of Last Inspection :	N/R
EPA Region :	9
Tribe :	N/R
Facility ID 2 :	N/R
Latitude :	33.150730866132299
Longitude :	-117.197851373378995
Last Date in Agency List :	2021-12-27

Tank Details

Tank ID :	CA10376056-001_One in a Compartmented Unit_2
Tank Status :	Open
Installation Date :	2003-05-01
Removal Date :	N/R
Capacity :	15000
Substances :	Premium Unleaded
Tank Wall Type :	Double Wall
Tank ID :	CA10376056-002_One in a Compartmented Unit_2
Tank Status :	Open
Installation Date :	2003-05-01
Removal Date :	N/R

Map Id: D37
Direction: WSW
Distance: 0.126 mi., 668 ft.
Elevation: 614 ft.
Relative: Higher

Site Name : FIVE STAR TEXACO SERVICE CNTR | RANCHO SANTE FE GAS | RANCHO SANTA FE GAS
105 RANCHO SANTA FE RD | 105 S RANCHO SANTA FE RD | 105 RANCHO SANTA FE RD SAP #120462
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257278
EPA ID: N/R

EPA UST ***(cont.)***

Capacity :	5000
Substances :	Diesel
Tank Wall Type :	Double Wall
Tank ID :	CA10376056-003_A Stand-alone Tank_1
Tank Status :	Open
Installation Date :	2003-05-01
Removal Date :	N/R
Capacity :	20000
Substances :	Regular Unleaded
Tank Wall Type :	Double Wall

FID UST - CA

Facility Name :	RANCHO SANTE FE GAS
Facility Address :	105 RANCHO SANTA FE RD, SAN MARCOS, 92069
County :	San Diego
Facility ID :	37-000-202180
CERSID :	10376056
Permitting Agency :	San Diego County Department of Environmental Health
Latitude :	33.14857
Longitude :	-117.19872
Last Date in Agency List :	2022-03-14

FRS

Facility Name :	FIVE STAR TEXACO SERVICE CNTR
Facility Address :	105 RANCHO SANTA FE RD, SAN MARCOS, CA 920691217
County :	SAN DIEGO

Site Details

Registry ID :	110066011620
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Source Description

Map Id: D37
Direction: WSW
Distance: 0.126 mi., 668 ft.
Elevation: 614 ft.
Relative: Higher

Site Name : FIVE STAR TEXACO SERVICE CNTR | RANCHO SANTE FE GAS | RANCHO SANTA FE GAS
105 RANCHO SANTA FE RD | 105 S RANCHO SANTA FE RD | 105 RANCHO SANTA FE RD SAP #120462
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257278
EPA ID: N/R

FRS ***(cont.)***

Source Description :

The California Environmental Protection Agency (CalEPA) has recently implemented a new data warehouse system (nSite). This data warehouse combines and merges facility and site information from five different systems managed within CalEPA. The five systems are: California Environmental Reporting System (CERS), EnviroStor, GeoTracker, California Integrated Water Quality System (CIWQS), and Toxic Release Inventory (TRI).

FRS Environmental Interest

Source and System ID :	CA-ENVIROVIEW - 200611
Facility Name :	FORMER TEXACO SERVICE STATION
Facility Address :	105 RANCHO SANTA FE ROAD, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Registry ID :	110066446803
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Source Description

Source Description :

The California Environmental Protection Agency (CalEPA) has recently implemented a new data warehouse system (nSite). This data warehouse combines and merges facility and site information from five different systems managed within CalEPA. The five systems are: California Environmental Reporting System (CERS), EnviroStor, GeoTracker, California Integrated Water Quality System (CIWQS), and Toxic Release Inventory (TRI).

FRS Environmental Interest

Source and System ID :	CA-ENVIROVIEW - 315047
Facility Name :	TEXACO SERVICE STATION
Facility Address :	105 S RANCHO SANTA FE RD, SAN MARCOS, CA 92069
County :	SAN DIEGO

Map Id: D37
Direction: WSW
Distance: 0.126 mi., 668 ft.
Elevation: 614 ft.
Relative: Higher

Site Name : FIVE STAR TEXACO SERVICE CNTR | RANCHO SANTE FE GAS | RANCHO SANTA FE GAS
105 RANCHO SANTA FE RD | 105 S RANCHO SANTA FE RD | 105 RANCHO SANTA FE RD SAP #120462
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257278
EPA ID: N/R

FRS ***(cont.)***

Site Details
Registry ID : 110018961694
FRS Facility URL : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-02-17

Source Description

Source Description :

HWTS-DATAMART provides California with information on hazardous waste shipments for generators, transporters, and treatment, storage, and disposal facilities.

FRS Environmental Interest
Source and System ID : HWTS-DATAMART - CAR000125989

HAZMAT_SAN DIEGO COUNTY - CA

Facility Name : FIVE STAR TEXACO SERVICE CNTR
Facility Address : 105 RANCHO SANTA FE RD, SAN MARCOS, CA 92069

Date : 2002-05-04
Record ID : DEH2002-HUPFP-105804
Record Type : Unified Program Facility Permit
Status : Completed
Action : N/R
Short Notes : N/R
Last Date in Agency List : 2015-11-23

Facility Name : RANCHO SANTA FE TEXACO REPAIR
Facility Address : 105 S RANCHO SANTA FE RD, SAN MARCOS, CA 92069

Date : 2002-05-04
Record ID : DEH2002-HUPFP-133765
Record Type : Unified Program Facility Permit
Status : Completed
Action : N/R
Short Notes : N/R
Last Date in Agency List : 2015-11-23

Map Id: D37
Direction: WSW
Distance: 0.126 mi., 668 ft.
Elevation: 614 ft.
Relative: Higher

Site Name : FIVE STAR TEXACO SERVICE CNTR | RANCHO SANTE FE GAS | RANCHO SANTA FE GAS
105 RANCHO SANTA FE RD | 105 S RANCHO SANTA FE RD | 105 RANCHO SANTA FE RD SAP #120462
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257278
EPA ID: N/R

HAZMAT_SAN DIEGO COUNTY - CA ***(cont.)***

Facility Name :	RANCHO SANTE FE GAS
Facility Address :	105 RANCHO SANTA FE RD, SAN MARCOS, CA 92069
Date :	2003-07-25
Record ID :	DEH2003-HUPFP-202180
Record Type :	Unified Program Facility Permit
Status :	Permit Renewed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23

HAZNET - CA

Facility Name :	RANCHO SANTA FE GAS
Facility Address :	105 S RANCHO SANTA FE RD, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000287229
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	105 S RANCHO SANTA FE RD, SAN MARCOS, CA 920780000
Latitude :	33.14889127
Longitude :	-117.19876166
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :

2019: 134 - Aqueous solution with total organic residues less than 10 percent, 0.73500 tons to AZR000510065
2016: 241 - Tank bottom waste, 0.68805 tons to CAD028409019
2013: 241 - Tank bottom waste, 0.43785 tons to CAD028409019
2007: 223 - Unspecified oil-containing waste, 0.9174 tons to CAT080013352
2005: 331 - Off-specification, aged or surplus organics, 0.0125 tons to CAD982444481
2005: 222 - Oil/water separation sludge, 0.9174 tons to CAD982444481

Map Id: D37
Direction: WSW
Distance: 0.126 mi., 668 ft.
Elevation: 614 ft.
Relative: Higher

Site Name : FIVE STAR TEXACO SERVICE CNTR | RANCHO SANTE FE GAS | RANCHO SANTA FE GAS
105 RANCHO SANTA FE RD | 105 S RANCHO SANTA FE RD | 105 RANCHO SANTA FE RD SAP #120462
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257278
EPA ID: N/R

HAZNET - CA ***(cont.)***

Facility Name :	RANCHO SANTA FE TEXACO
Facility Address :	105 S RANCHO SANTA FE RD, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL920596598
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	105 S RANCHO SANTA FE RD, SAN MARCOS, CA 920690000
Latitude :	33.14859300
Longitude :	-117.19871550
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	1994: 135 - Unspecified aqueous solution, 0.231 tons to CAT080013352 1993: 135 - Unspecified aqueous solution, 0.189 tons to CAT080013352

HWG - CA

Facility Name :	RANCHO SANTA FE GAS
Facility Address :	105 S RANCHO SANTA FE RD, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAL000287229
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	105 S RANCHO SANTA FE RD, SAN MARCOS, CA 920780000
Owner Name :	SHAWN HINDI
Owner Address :	105 S RANCHO SANTA FE RD, SAN MARCOS, CA 920690000
Operator Name :	SHAWN HINDI
Operator Address :	105 RANCHO SANTA FE RD, SAN MARCOS, CA 92078
Latitude :	33.148891
Longitude :	-117.198762

Map Id: D37
Direction: WSW
Distance: 0.126 mi., 668 ft.
Elevation: 614 ft.
Relative: Higher

Site Name : FIVE STAR TEXACO SERVICE CNTR | RANCHO SANTE FE GAS | RANCHO SANTA FE GAS
105 RANCHO SANTA FE RD | 105 S RANCHO SANTA FE RD | 105 RANCHO SANTA FE RD SAP #120462
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257278
EPA ID: N/R

HWG - CA ***(cont.)***

Facility Name :	RANCHO SANTA FE TEXACO
Facility Address :	105 S RANCHO SANTA FE RD, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAL920596598
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	105 S RANCHO SANTA FE RD, SAN MARCOS, CA 920690000
Owner Name :	MASOOD AHAD
Owner Address :	105 S RANCHO SANTA FE RD, SAN MARCOS, CA 920690000
Operator Name :	INACTIVATED 9/30/94 PER OWNER
Operator Address :	N/A
Latitude :	33.148841
Longitude :	-117.198917

LUST REG 9 - CA

Facility Name :	FIVE STAR TEXACO SERVICE CNTR
Facility Address :	105 RANCHO SANTA FE RD, SAN MARCOS, CA 920691217
County :	San Diego

Site Details

Status Date :	1988-08-25
Status :	Completed - Case Closed
Begin Date :	1987-01-14
Global ID :	T0607302827
Region :	REGION 9
Site History :	N/R
RB Case Number :	9UT535
Potential Media Affected :	Aquifer used for drinking water supply
Potential Contaminants of Concern :	Gasoline
Local Agency :	N/R
Local Case Number :	H05804-001
Lead Agency :	SAN DIEGO COUNTY LOP
File Location :	Local Agency
CUF Case :	NO
Caseworker :	N/R
Case Type :	LUST Cleanup Site
How Discovered :	N/R
How Discovered Description :	N/R
Stop Method :	N/R

Map Id: D37
Direction: WSW
Distance: 0.126 mi., 668 ft.
Elevation: 614 ft.
Relative: Higher

Site Name : FIVE STAR TEXACO SERVICE CNTR | RANCHO SANTE FE GAS | RANCHO SANTA FE GAS
105 RANCHO SANTA FE RD | 105 S RANCHO SANTA FE RD | 105 RANCHO SANTA FE RD SAP #120462
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257278
EPA ID: N/R

LUST REG 9 - CA ***(cont.)***

Stop Description :	N/R
Calwater Watershed Name :	Carlsbad - San Marcos - Richland (904.52)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)
Disadvantaged Community :	Severely Disadvantaged Community
Latitude :	33.148714
Longitude :	-117.198837
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-11

Contacts Summary

Global ID :	T0607302827
Contact Name :	N/R
Contact Type :	N/R
Organization Name :	N/R
Address :	N/R
City :	N/R
Phone Number :	N/R
Email :	N/R

Regulatory Activities

Date :	1987-01-14
Global ID :	T0607302827
Action Type :	Other
Action :	Leak Stopped

Date :	1987-01-14
Global ID :	T0607302827
Action Type :	Other
Action :	Leak Began

Date :	1987-01-14
Global ID :	T0607302827
Action Type :	Other
Action :	Leak Reported

Date :	1987-01-14
Global ID :	T0607302827
Action Type :	Other
Action :	Leak Discovery

Map Id: D37
Direction: WSW
Distance: 0.126 mi., 668 ft.
Elevation: 614 ft.
Relative: Higher

Site Name : FIVE STAR TEXACO SERVICE CNTR | RANCHO SANTE FE GAS | RANCHO SANTA FE GAS
105 RANCHO SANTA FE RD | 105 S RANCHO SANTA FE RD | 105 RANCHO SANTA FE RD SAP #120462
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257278
EPA ID: N/R

LUST REG 9 - CA ***(cont.)***

Status History

Status Date :	1988-08-25
Global ID :	T0607302827
Status :	Completed - Case Closed
Status Date :	1987-01-14
Global ID :	T0607302827
Status :	Open - Case Begin Date

Site Details

Status Date :	2019-11-07
Status :	Completed - Case Closed
Begin Date :	1987-01-22
Global ID :	T0607301309
Region :	REGION 9

Site History :

An underground storage tank was damaged during well installation activities resulting in a subsurface release of approximately 3,200 gallons of unleaded gasoline. Contaminated soil was discovered during the removal of the waste oil tank in April 1991, and the gasoline underground storage tanks and dispensers in June 2003. Quarterly groundwater monitoring has been conducted at the site since August 1989. The consultant overseeing this case is also overseeing the Former Chevron Station (H13261-002) and Former Shell Station (H03229-001) that are located on Rancho Santa Fe Road. Groundwater at the three sites is jointly monitored and sampled. See ESI for additional information.

RB Case Number :	9UT2562
Potential Media Affected :	Aquifer used for drinking water supply
Potential Contaminants of Concern :	Gasoline
Local Agency :	N/R
Local Case Number :	N/R
Lead Agency :	SAN DIEGO RWQCB (REGION 9)
File Location :	Regional Board
CUF Case :	NO
Caseworker :	LT
Case Type :	LUST Cleanup Site
How Discovered :	Site Assessment/Site Investigation
How Discovered Description :	N/R
Stop Method :	Other Means
Stop Description :	OTHER MEANS
Calwater Watershed Name :	Carlsbad - San Marcos - Richland (904.52)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)
Disadvantaged Community :	Severely Disadvantaged Community

Map Id: D37
Direction: WSW
Distance: 0.126 mi., 668 ft.
Elevation: 614 ft.
Relative: Higher

Site Name : FIVE STAR TEXACO SERVICE CNTR | RANCHO SANTE FE GAS | RANCHO SANTA FE GAS
105 RANCHO SANTA FE RD | 105 S RANCHO SANTA FE RD | 105 RANCHO SANTA FE RD SAP #120462
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257278
EPA ID: N/R

LUST REG 9 - CA ***(cont.)***

Latitude :	33.148719
Longitude :	-117.19879
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-11

Contacts Summary

Global ID :	T0607301309
Contact Name :	LALITHA THOTAKURA
Contact Type :	Regional Board Caseworker
Organization Name :	SAN DIEGO RWQCB (REGION 9)
Address :	2375 NORTHSIDE DRIVE, SUITE 100
City :	SAN DIEGO
Phone Number :	6195213002
Email :	lalitha.thotakura@waterboards.ca.gov

Regulatory Activities

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Date :	2019-12-30
Global ID :	T0607301309
Action Type :	RESPONSE
Action :	Other Report / Document

Date :	2019-11-07
Global ID :	T0607301309
Action Type :	ENFORCEMENT
Action :	Closure/No Further Action Letter

Date :	2019-06-28
Global ID :	T0607301309
Action Type :	RESPONSE
Action :	Well Destruction Report

Date :	2019-04-04
Global ID :	T0607301309
Action Type :	ENFORCEMENT

Map Id: D37
Direction: WSW
Distance: 0.126 mi., 668 ft.
Elevation: 614 ft.
Relative: Higher

Site Name : FIVE STAR TEXACO SERVICE CNTR | RANCHO SANTE FE GAS | RANCHO SANTA FE GAS
105 RANCHO SANTA FE RD | 105 S RANCHO SANTA FE RD | 105 RANCHO SANTA FE RD SAP #120462
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257278
EPA ID: N/R

LUST REG 9 - CA ***(cont.)***

Action : Email Correspondence

Date : 2019-01-19
Global ID : T0607301309
Action Type : ENFORCEMENT
Action : Staff Letter

Date : 2018-11-05
Global ID : T0607301309
Action Type : ENFORCEMENT
Action : Notification - Public Notice of Case Closure

Date : 2018-07-30
Global ID : T0607301309
Action Type : RESPONSE
Action : Monitoring Report - Semi-Annually

Date : 2018-01-24
Global ID : T0607301309
Action Type : RESPONSE
Action : Monitoring Report - Semi-Annually

Date : 2017-10-11
Global ID : T0607301309
Action Type : RESPONSE
Action : Correspondence

Date : 2017-08-18
Global ID : T0607301309
Action Type : ENFORCEMENT
Action : Clean Up Fund - Case Closure Review Summary Report (RSR)

Status History
Status Date : 2019-11-07
Global ID : T0607301309
Status : Completed - Case Closed

Map Id: D37
Direction: WSW
Distance: 0.126 mi., 668 ft.
Elevation: 614 ft.
Relative: Higher

Site Name : FIVE STAR TEXACO SERVICE CNTR | RANCHO SANTE FE GAS | RANCHO SANTA FE GAS
105 RANCHO SANTA FE RD | 105 S RANCHO SANTA FE RD | 105 RANCHO SANTA FE RD SAP #120462
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257278
EPA ID: N/R

LUST REG 9 - CA ***(cont.)***

Status Date :	1988-07-14
Global ID :	T0607301309
Status :	Open - Remediation

Status Date :	1987-01-22
Global ID :	T0607301309
Status :	Open - Case Begin Date

MANIFEST EPA

Manifest Details

Manifest Number :	019463325JJK
Shipped Date :	2019-09-26
Updated Date :	2019-11-15
Received Date :	2019-10-03
Status :	Signed
Generator ID :	CAL000287229
Generator Name :	RANCHO SANTA FE GAS
Generator Address :	105 S RANCHO SANTA FE RD, SAN MARCOS, CA 92069
Generator Mailing :	105 S RANCHO SANTA FE RD, SAN MARCOS, CA 92078-0000
Generator Contact :	N/R
Destination ID :	AZR000510065
Destination Name :	US FUEL OIL, LLC
Destination Mailing :	8987 W OLIVE AVE STE 117-27, PEORIA, AZ 85345-9125
Destination Address :	3125 W DOME ROCK RD SPC 300, QUARTZSITE, AZ 85346
Destination Contact :	N/R
Submission Type :	DataImage5Copy
Origin Type :	Web
Manifest Residue :	N
Rejection :	N
Last Date in Agency List :	2022-01-14

Waste Details

Waste Line Number :	1
Is DOT Hazardous :	N
DOT ID Number :	N/R
DOT Information :	N/R
Non Waste Description :	NON-RCRA HAZARDOUS WASTE LIQUID (SB 989 TEST WATER)
Quantity :	175 Gallons
Quantity Tons, Acute, Non-Acute :	0.72977483, 0, 0.72977483
Quantity Kg, Acute, Non-Acute :	0, 661.9277
Management Method :	H141 - STORAGE, BULKING AND/OR TRANSFER OFF SITE
Is EPA Waste :	N

Map Id: D37
Direction: WSW
Distance: 0.126 mi., 668 ft.
Elevation: 614 ft.
Relative: Higher

Site Name : FIVE STAR TEXACO SERVICE CNTR | RANCHO SANTE FE GAS | RANCHO SANTA FE GAS
105 RANCHO SANTA FE RD | 105 S RANCHO SANTA FE RD | 105 RANCHO SANTA FE RD SAP #120462
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257278
EPA ID: N/R

MANIFEST EPA ***(cont.)***

Federal Code :	N/R
State Code :	CA - 134

RCRA_NONGEN

Facility Name :	RANCHO SANTA FE GAS
Facility Address :	105 S RANCHO SANTA FE RD, SAN MARCOS, CA 92069-0000
County :	SAN DIEGO
Date Form Received by Agency :	2004-10-15
EPA ID :	CAL000287229
Mailing Address :	105 S RANCHO SANTA FE RD, SAN MARCOS, CA 92078-0000
Contact :	SHAWN HINDI
Contact Address :	105 RANCHO SANTA FE RD, SAN MARCOS, CA 92078
Contact Country :	N/R
Contact Telephone :	760-471-5448
Contact Email :	PAUL@PCETINC.COM
EPA Region :	09
Land Type :	Not Reported
Source Type :	Implementer
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2022-01-26

Owner/Operator Summary

Owner/Operator Name :	SHAWN HINDI
Owner/Operator Address :	105 S RANCHO SANTA FE RD, SAN MARCOS, CA 92069-0000
Owner/Operator Country :	N/R
Owner/Operator Telephone :	760-471-5448
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Owner/Operator Name :	SHAWN HINDI
Owner/Operator Address :	105 RANCHO SANTA FE RD, SAN MARCOS, CA 92078
Owner/Operator Country :	N/R
Owner/Operator Telephone :	760-471-5448
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R

Map Id: D37
Direction: WSW
Distance: 0.126 mi., 668 ft.
Elevation: 614 ft.
Relative: Higher

Site Name : FIVE STAR TEXACO SERVICE CNTR | RANCHO SANTE FE GAS | RANCHO SANTA FE GAS
105 RANCHO SANTA FE RD | 105 S RANCHO SANTA FE RD | 105 RANCHO SANTA FE RD SAP #120462
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257278
EPA ID: N/R

RCRA_NONGEN ***(cont.)***

Legal Status :	Other land type
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Notices of Violations Summary

Regulation Violated :	N

SLIC REG 9 - CA

Facility Name :	FIVE STAR TEXACO SERVICE CNTR
Facility Address :	105 RANCHO SANTA FE RD, SAN MARCOS, CA 920691217
County :	San Diego

Site Details

Status Date :	1993-11-04
Status :	Completed - Case Closed
Begin Date :	1992-09-18
Global ID :	T0608107669
Region :	REGION 9
Site History :	N/R
RB Case Number :	N/R
Potential Media Affected :	Under Investigation

Map Id: D37
Direction: WSW
Distance: 0.126 mi., 668 ft.
Elevation: 614 ft.
Relative: Higher

Site Name : FIVE STAR TEXACO SERVICE CNTR | RANCHO SANTE FE GAS | RANCHO SANTA FE GAS
105 RANCHO SANTA FE RD | 105 S RANCHO SANTA FE RD | 105 RANCHO SANTA FE RD SAP #120462
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257278
EPA ID: N/R

SLIC REG 9 - CA ***(cont.)***

Potential Contaminants of Concern :	Gasoline
Local Agency :	N/R
Local Case Number :	H05804-003
Lead Agency :	SAN DIEGO COUNTY LOP
File Location :	Local Agency
CUF Case :	NO
Caseworker :	N/R
Case Type :	Cleanup Program Site
How Discovered :	N/R
How Discovered Description :	N/R
Stop Method :	N/R
Stop Description :	N/R
Calwater Watershed Name :	Carlsbad - San Marcos - Richland (904.52)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)
Disadvantaged Community :	Severely Disadvantaged Community
Latitude :	33.148884
Longitude :	-117.198805
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-11

Contacts Summary

Global ID :	T0608107669
Contact Name :	N/R
Contact Type :	N/R
Organization Name :	N/R
Address :	N/R
City :	N/R
Phone Number :	N/R
Email :	N/R

Regulatory Activities

Date :	1993-02-05
Global ID :	T0608107669
Action Type :	Other
Action :	Leak Reported

Date :	1992-09-18
Global ID :	T0608107669
Action Type :	Other
Action :	Leak Discovery

Map Id: D37
Direction: WSW
Distance: 0.126 mi., 668 ft.
Elevation: 614 ft.
Relative: Higher

Site Name : FIVE STAR TEXACO SERVICE CNTR | RANCHO SANTE FE GAS | RANCHO SANTA FE GAS
105 RANCHO SANTA FE RD | 105 S RANCHO SANTA FE RD | 105 RANCHO SANTA FE RD SAP #120462
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_NONGEN, SLIC REG 9 - CA, UST - CA] ***(cont.)***

Envirosite ID: 257278
EPA ID: N/R

SLIC REG 9 - CA ***(cont.)***

Date :	1992-09-18
Global ID :	T0608107669
Action Type :	Other
Action :	Leak Began

Status History

Status Date :	1993-11-04
Global ID :	T0608107669
Status :	Completed - Case Closed

Status Date :	1992-09-18
Global ID :	T0608107669
Status :	Open - Case Begin Date

UST - CA

Facility Name :	RANCHO SANTE FE GAS
Facility Address :	105 RANCHO SANTA FE RD, SAN MARCOS, 92069
County :	San Diego
Facility ID :	37-000-202180
CERS ID :	10376056
Permitting Agency :	San Diego County Department of Environmental Health
Latitude :	33.14857
Longitude :	-117.19872
Last Date in Agency List :	2022-03-07

Map Id: G38
Direction: NNE
Distance: 0.128 mi., 675 ft.
Elevation: 628 ft.
Relative: Higher

Site Name : HELENE NICKEL
406 CONCHA LN
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 404810
EPA ID: CAC002708589

HAZNET - CA

Facility Name :	HELENE NICKEL

Map Id: G38
Direction: NNE
Distance: 0.128 mi., 675 ft.
Elevation: 628 ft.
Relative: Higher

Site Name : HELENE NICKEL
406 CONCHA LN
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 404810
EPA ID: CAC002708589

HAZNET - CA ***(cont.)***

Facility Address :	406 CONCHA LN, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAC002708589
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	406 CONCHA LN, SAN MARCOS, CA 920691338
Latitude :	33.15406014
Longitude :	-117.19415173
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	2012: 151 - Asbestos containing waste, 0.4 tons to AZC950823111

HWG - CA

Facility Name :	HELENE NICKEL
Facility Address :	406 CONCHA LN, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAC002708589
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	406 CONCHA LN, SAN MARCOS, CA 920691338
Owner Name :	HELENE NICKEL
Owner Address :	406 CONCHA LN, SAN MARCOS, CA 920691338
Operator Name :	HELENE NICKEL
Operator Address :	406 CONCHA LN, SAN MARCOS, CA 920691338
Latitude :	33.15428
Longitude :	-117.19426

Map Id: 39
Direction: SE
Distance: 0.130 mi., 685 ft.
Elevation: 568 ft.
Relative: Lower

Site Name : 1X DUPLICATE PARTS COMPANY | DUPLICATE PARTS COMPANY
168 PACIFIC ST | 168 S PACIFIC ST
SAN MARCOS, CA 92069

Database(s) : [HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST HAZNET - CA, HWG - CA]

Envirosite ID: 637697
EPA ID: CAC000106549

HAZMAT_SAN DIEGO COUNTY - CA

Facility Name :	DUPLICATE PARTS CO INC
Facility Address :	168 S PACIFIC ST, SAN MARCOS, CA 92069
Date :	2002-05-04
Record ID :	DEH2002-HUPFP-104190
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23

HAZNET - CA

Facility Name :	1X DUPLICATE PARTS COMPANY
Facility Address :	168 PACIFIC STREET, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAC000106549
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	168 PACIFIC STREET, SAN MARCOS, CA 920690000
Latitude :	33.14963889
Longitude :	-117.19340345
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Facility Name :	DUPLICATE PARTS COMPANY
Facility Address :	168 PACIFIC ST, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000013464
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	168 SOUTH PACIFIC ST, SAN MARCOS, CA 920782594
Latitude :	33.14963889
Longitude :	-117.19340345
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Map Id: 39
Direction: SE
Distance: 0.130 mi., 685 ft.
Elevation: 568 ft.
Relative: Lower

Site Name : 1X DUPLICATE PARTS COMPANY | DUPLICATE PARTS COMPANY
168 PACIFIC ST | 168 S PACIFIC ST
SAN MARCOS, CA 92069

Database(s) : [HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 637697
EPA ID: CAC000106549

HAZNET - CA ***(cont.)***

Facility Name :	DUPLICATE PARTS INC.
Facility Address :	168 PACIFIC ST., SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAX000077503
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	--, SAN MARCOS, CA 920690000
Latitude :	33.14963885
Longitude :	-117.19340334
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HIST HAZNET - CA

Facility Name :	1X DUPLICATE PARTS COMPANY
Facility Address :	168 PACIFIC STREET, SAN MARCOS, 92069
ID Number :	CAC000106549
Last Date in Agency List :	2014-11-17

HWG - CA

Facility Name :	1X DUPLICATE PARTS COMPANY
Facility Address :	168 PACIFIC STREET, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAC000106549
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	168 PACIFIC STREET, SAN MARCOS, CA 920690000
Owner Name :	DUPLICATE PARTS COMPANY
Owner Address :	N/A
Operator Name :	DOTTIE DUPRAZ, OFF MGR
Operator Address :	N/A
Latitude :	33.149784
Longitude :	-117.193307
Facility Name :	DUPLICATE PARTS COMPANY
Facility Address :	168 PACIFIC ST, SAN MARCOS, CA 92069
County :	SAN DIEGO

Map Id: 39
Direction: SE
Distance: 0.130 mi., 685 ft.
Elevation: 568 ft.
Relative: Lower

Site Name : 1X DUPLICATE PARTS COMPANY | DUPLICATE PARTS COMPANY
168 PACIFIC ST | 168 S PACIFIC ST
SAN MARCOS, CA 92069

Database(s) : [HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 637697
EPA ID: CAC000106549

HWG - CA ***(cont.)***

EPA ID :	CAL000013464
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	168 SOUTH PACIFIC ST, SAN MARCOS, CA 920782594
Owner Name :	TIMOTHY D GUNTER
Owner Address :	168 PACIFIC ST SOUTH, SAN MARCOS, CA 920782594
Operator Name :	TIMOTHY D GUNTER OWNER
Operator Address :	168 PACIFIC ST SOUTH, SAN MARCOS, CA 920782594
Latitude :	33.149784
Longitude :	-117.193307

Facility Name :	DUPLICATE PARTS INC.
Facility Address :	168 PACIFIC ST., SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAX000077503
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	SAN MARCOS, CA 920690000
Owner Name :	N/R
Owner Address :	N/A
Operator Name :	LOU NELSON
Operator Address :	INACT PER 98VQ FINAL NOTICE, N/A
Latitude :	33.149784
Longitude :	-117.193307

Map Id: F40
Direction: E
Distance: 0.131 mi., 690 ft.
Elevation: 570 ft.
Relative: Lower

Site Name : EAGLE SAFE CORP
320 SO PACIFIC
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 41062810
EPA ID: CAX000244301

HAZNET - CA

Facility Name :	EAGLE SAFE CORP
Facility Address :	320 SO PACIFIC, SAN MARCOS, CA 92069
County :	SAN DIEGO

Map Id: F40
Direction: E
Distance: 0.131 mi., 690 ft.
Elevation: 570 ft.
Relative: Lower

Site Name : EAGLE SAFE CORP
320 SO PACIFIC
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 41062810
EPA ID: CAX000244301

HAZNET - CA ***(cont.)***

Site Details

Generator EPA ID :	CAX000244301
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	H S MORTON, SAN MARCOS, CA 920690000
Latitude :	33.15106052
Longitude :	-117.19234988
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HWG - CA

Facility Name :	EAGLE SAFE CORP
Facility Address :	320 SO PACIFIC, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAX000244301
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	H S MORTON, SAN MARCOS, CA 920690000
Owner Name :	N/R
Owner Address :	N/A
Operator Name :	UNDELIVERABLE SURVEY 1-28-95JV
Operator Address :	N/A
Latitude :	33.141003
Longitude :	-117.197759

Map Id: D41
Direction: WSW
Distance: 0.134 mi., 706 ft.
Elevation: 613 ft.
Relative: Higher

Site Name : BRADLEY PARK OLD LINDA VSTA LF | SD CO OF PUB WKS SAN MARCOS I LANDFILL | BRADLEY PARK - OLD LINDA VSTA LANDFILL (SAN MARCOS I LANDFILL) RANCHO SANTA FE & LINDA VISTA | RANCHO SANTE FE RD/LINDA VISTA | RANCHO SANTA FE/LINDA VISTA RD SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, EMI - CA, FRS, HIST LDS - CA, LDS - CA, RFR - CA]

Envirosite ID: 280367
EPA ID: N/R

CALEPA SITES - CA

Facility Name : BRADLEY PARK - OLD LINDA VSTA LANDFILL (SAN MARCOS I LANDFILL)
Facility Address : RANCHO SANTA FE & LINDA VISTA, SAN MARCOS, 92069

Site ID : 13301
EI ID : L10006943141
EI Description : Land Disposal Site
Latitude : 33.138175
Longitude : -117.201804
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-01-07

Site ID : 13301
EI ID : 210207
EI Description : Tanks & Ground Water Clean Up
Latitude : 33.138175
Longitude : -117.201804
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-01-07

Facility Name : SD CO OF PUB WKS SAN MARCOS I LANDFILL
Facility Address : RANCHO SANTA FE LINDA VISTA RD, SAN MARCOS, 92069-0000

Site ID : 493120
EI ID : 110013823568
EI Description : US EPA Air Emission Inventory System (EIS)
Latitude : 33.151260
Longitude : -117.197660
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-01-07

CASE LIST_SAN DIEGO COUNTY - CA

Facility Name : BRADLEY PARK - OLD LINDA VSTA LANDFILL (SAN MARCOS I LANDFILL)
Facility Address : RANCHO SANTA FE & LINDA VISTA, SAN MARCOS, CA 92069
County : San Diego

Site Details
Status Date : 2015-06-30
Status : Open - Closed/with Monitoring
Begin Date : 1997-04-07
Global ID : L10006943141

Map Id: D41
Direction: WSW
Distance: 0.134 mi., 706 ft.
Elevation: 613 ft.
Relative: Higher

Site Name : BRADLEY PARK OLD LINDA VSTA LF | SD CO OF PUB WKS SAN MARCOS I LANDFILL | BRADLEY PARK - OLD LINDA VSTA LANDFILL (SAN MARCOS I LANDFILL) RANCHO SANTA FE & LINDA VISTA | RANCHO SANTE FE RD/LINDA VISTA | RANCHO SANTA FE/LINDA VISTA RD SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, EMI - CA, FRS, HIST LDS - CA, LDS - CA, RFR - CA] ***(cont.)***

Envirosite ID: 280367
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Site History :

This site is under an investigative order (Order R9-2006-0044) requiring the discharger to initiate an Evluation Monitoring Program (EMP under CCR Tiitle 27) submittal of an amended Report of Waste Discharge (ROWD). The ROWD should be submitted to the Regional Board for review and comment in June 2009. Upon completion of the ROWD, the Regional Board will issue a corrective action monitoring program and likely, a cleanup and abatement order to implement corrective action alternatives at the site. Corrective action is complete and the site is no longer in cost recovery.

RB Case Number :	2090028
Potential Media Affected :	Soil Vapor, Surface water
Potential Contaminants of Concern :	Benzene, Other Solvent or Non-Petroleum Hydrocarbon, Trichloroethylene (TCE), Vinyl chloride
Local Agency :	N/R
Local Case Number :	N/R
Lead Agency :	SAN DIEGO RWQCB (REGION 9)
File Location :	Regional Board
CUF Case :	NO
Caseworker :	ALG
Case Type :	Land Disposal Site
How Discovered :	N/R
How Discovered Description :	N/R
Stop Method :	N/R
Stop Description :	N/R
Calwater Watershed Name :	Carlsbad - San Marcos - Richland (904.52)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)
Disadvantaged Community :	Severely Disadvantaged Community
Latitude :	33.138175
Longitude :	-117.201804
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-09

Contacts Summary

Global ID :	L10006943141
Contact Name :	AMY L. GROVE
Contact Type :	Regional Board Caseworker
Organization Name :	SAN DIEGO RWQCB (REGION 9)
Address :	2375 NORTHSIDE DRIVE, SUITE 100
City :	SAN DIEGO
Phone Number :	N/R
Email :	amy.grove@waterboards.ca.gov

Map Id: D41
Direction: WSW
Distance: 0.134 mi., 706 ft.
Elevation: 613 ft.
Relative: Higher

Site Name : BRADLEY PARK OLD LINDA VSTA LF | SD CO OF PUB WKS SAN MARCOS I LANDFILL | BRADLEY PARK - OLD LINDA VSTA LANDFILL (SAN MARCOS I LANDFILL) RANCHO SANTA FE & LINDA VISTA | RANCHO SANTE FE RD/LINDA VISTA | RANCHO SANTA FE/LINDA VISTA RD SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, EMI - CA, FRS, HIST LDS - CA, LDS - CA, RFR - CA] ***(cont.)***

Envirosite ID: 280367
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Regulatory Activities

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Date :	2019-12-18
Global ID :	L10006943141
Action Type :	RESPONSE
Action :	Monitoring Report - Other

Date :	2019-09-06
Global ID :	L10006943141
Action Type :	ENFORCEMENT
Action :	Email Correspondence

Date :	2019-07-22
Global ID :	L10006943141
Action Type :	ENFORCEMENT
Action :	Staff Letter

Date :	2019-05-20
Global ID :	L10006943141
Action Type :	RESPONSE
Action :	Other Workplan - Regulator Responded

Date :	2019-05-20
Global ID :	L10006943141
Action Type :	RESPONSE
Action :	Water and Leachate Investigation Workplan

Date :	2019-04-20
Global ID :	L10006943141
Action Type :	RESPONSE
Action :	Questionnaire Response

Date :	2019-03-20
Global ID :	L10006943141
Action Type :	ENFORCEMENT
Action :	PFAS Order - #WQ 2019-0006-DWQ

Map Id: D41
Direction: WSW
Distance: 0.134 mi., 706 ft.
Elevation: 613 ft.
Relative: Higher

Site Name : BRADLEY PARK OLD LINDA VSTA LF | SD CO OF PUB WKS SAN MARCOS I LANDFILL | BRADLEY PARK - OLD LINDA VSTA LANDFILL (SAN MARCOS I LANDFILL) RANCHO SANTA FE & LINDA VISTA | RANCHO SANTE FE RD/LINDA VISTA | RANCHO SANTA FE/LINDA VISTA RD SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, EMI - CA, FRS, HIST LDS - CA, LDS - CA, RFR - CA] ***(cont.)***

Envirosite ID: 280367
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Date : 2012-07-23
Global ID : L10006943141
Action Type : ENFORCEMENT
Action : Site Visit / Inspection / Sampling

Date : 2011-04-29
Global ID : L10006943141
Action Type : ENFORCEMENT
Action : File review

Date : 2010-10-27
Global ID : L10006943141
Action Type : ENFORCEMENT
Action : 13267 Monitoring Program - #R9-2010-0123

Status History
Status Date : 2015-06-30
Global ID : L10006943141
Status : Open - Closed/with Monitoring

Status Date : 2009-03-13
Global ID : L10006943141
Status : Open - Verification Monitoring

Status Date : 1997-04-07
Global ID : L10006943141
Status : Open - Case Begin Date

CIWQS - CA

Facility Name : BRADLEY PARK OLD LINDA VSTA LF
Facility Address : RANCHO SANTA FE & LINDA VISTA, SAN MARCOS, CA 92069
County : SAN DIEGO

Place ID : 210207
Agency Name : SAN MARCOS CITY
Last Date in Agency List : 2021-12-30

Facility Name : BRADLEY PARK P-LINE 3&4 RELOC
Facility Address : RANCHO SANTE FE RD/LINDA VISTA, SAN MARCOS, CA 92069

Map Id: D41
Direction: WSW
Distance: 0.134 mi., 706 ft.
Elevation: 613 ft.
Relative: Higher

Site Name : BRADLEY PARK OLD LINDA VSTA LF | SD CO OF PUB WKS SAN MARCOS I LANDFILL | BRADLEY PARK - OLD LINDA VSTA LANDFILL (SAN MARCOS I LANDFILL) RANCHO SANTA FE & LINDA VISTA | RANCHO SANTE FE RD/LINDA VISTA | RANCHO SANTA FE/LINDA VISTA RD SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, EMI - CA, FRS, HIST LDS - CA, LDS - CA, RFR - CA] ***(cont.)***

Envirosite ID: 280367
EPA ID: N/R

CIWQS - CA ***(cont.)***

County :	SAN DIEGO
Place ID :	210209
Agency Name :	SAN DIEGO COUNTY WATER AUTHORITY
Last Date in Agency List :	2021-12-30

CIWQS 2 - CA

Facility Name :	Bradley Park Old Linda Vsta LF
Facility Address :	Rancho Santa Fe & Linda Vista, San Marcos, 92069
County :	San Diego
Facility ID :	210207
WDID :	N/R
Facility Type :	Solid Waste Class III - nonhazardous solid wastes
Region :	9
Place Type :	Waste Management Unit
Place Subtype :	Land fill
Ageny Name :	N/R
Agency Type :	N/R
Number of Agencies :	N/R
Status Date :	N/R
Status :	N/R
Status Enrollee :	N/R
Individual/General :	N/R
Fee Code :	N/R
Staff Assigned :	N/R
Number of Staff Assigned :	N/R
Supervisor :	N/R
Number of Supervisor :	N/R
Number of Amendments :	0
Number of Reg Measures :	N/R
Baseline Flow :	N/R
Population (MS4)/Acres :	N/R
Reclamation :	N/R
CAFO Type :	N/R
CAFO Subtype :	N/R
CAFO Population :	N/R
Onsite :	N/R
Quality Assurance :	N/R
RCRA Flag :	N
Total MMP Violations Number :	0
Total Number of Violations :	4
Total Number of Inspections :	0
Date of Most Recent Completed Inspection:	N/R

Map Id: D41
Direction: WSW
Distance: 0.134 mi., 706 ft.
Elevation: 613 ft.
Relative: Higher

Site Name : BRADLEY PARK OLD LINDA VSTA LF | SD CO OF PUB WKS SAN MARCOS I LANDFILL | BRADLEY PARK - OLD LINDA VSTA LANDFILL (SAN MARCOS I LANDFILL) RANCHO SANTA FE & LINDA VISTA | RANCHO SANTE FE RD/LINDA VISTA | RANCHO SANTA FE/LINDA VISTA RD SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, EMI - CA, FRS, HIST LDS - CA, LDS - CA, RFR - CA] ***(cont.)***

Envirosite ID: 280367
EPA ID: N/R

CIWQS 2 - CA ***(cont.)***

Date of Most Recent Received Report :	N/R
Total Number of Final (A+H) Enforcement Actions:	1
Most Recent Effective Date of Enf Action (A+H):	2008-05-30
Program :	LNDISP
Program Category :	LNDISP
Number of Programs :	N/R
Complexity :	N/R
Pretreatment :	N/R
Facility Waste Type :	N/R
Reg Measure ID :	N/R
Reg Measure Type :	N/R
Reg Measure Title :	N/R
Reg Measure Description :	N/R
SIC 1 :	4953 - Refuse Systems
SIC 2 :	9511 - Air and Water Resource and Solid Waste Management
SIC 3 :	-
Latitude :	N/R
Longitude :	N/R
Last Date in Agency List :	2022-01-18

Facility ID :	210207
WDID :	9 000316N99
Facility Type :	Solid Waste Class III - nonhazardous solid wastes
Region :	9
Place Type :	Waste Management Unit
Place Subtype :	Land fill
Ageny Name :	San Marcos City
Agency Type :	City Agency
Number of Agencies :	1
Status Date :	2019-08-27
Status :	Historical
Status Enrollee :	N
Individual/General :	I
Fee Code :	N/R
Staff Assigned :	N/R
Number of Staff Assigned :	N/R
Supervisor :	N/R
Number of Supervisor :	N/R
Number of Amendments :	0
Number of Reg Measures :	1
Baseline Flow :	N/R
Population (MS4)/Acres :	N/R
Reclamation :	N/R
CAFO Type :	N/R
CAFO Subtype :	N/R

Map Id: D41
Direction: WSW
Distance: 0.134 mi., 706 ft.
Elevation: 613 ft.
Relative: Higher

Site Name : BRADLEY PARK OLD LINDA VSTA LF | SD CO OF PUB WKS SAN MARCOS I LANDFILL | BRADLEY PARK - OLD LINDA VSTA LANDFILL (SAN MARCOS I LANDFILL) RANCHO SANTA FE & LINDA VISTA | RANCHO SANTE FE RD/LINDA VISTA | RANCHO SANTA FE/LINDA VISTA RD SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, EMI - CA, FRS, HIST LDS - CA, LDS - CA, RFR - CA] ***(cont.)***

Envirosite ID: 280367
EPA ID: N/R

CIWQS 2 - CA ***(cont.)***

CAFO Population :	N/R
Onsite :	N/R
Quality Assurance :	N/R
RCRA Flag :	N
Total MMP Violations Number :	0
Total Number of Violations :	3
Total Number of Inspections :	0
Date of Most Recent Completed Inspection:	N/R
Date of Most Recent Received Report :	N/R
Total Number of Final (A+H) Enforcement Actions:	0
Most Recent Effective Date of Enf Action (A+H):	N/R
Program :	DISCHLND
Program Category :	UNREGS
Number of Programs :	1
Complexity :	N/R
Pretreatment :	N/R
Facility Waste Type :	N/R
Reg Measure ID :	162072
Reg Measure Type :	Unregulated
Reg Measure Title :	Unregulated 9 000316N99 Bradley Park Old Linda Vista Landfill
Reg Measure Description :	N/R
SIC 1 :	4953 - Refuse Systems
SIC 2 :	9511 - Air and Water Resource and Solid Waste Management
SIC 3 :	-
Latitude :	N/R
Longitude :	N/R
Last Date in Agency List :	2022-01-18

Facility ID :	210207
WDID :	N/R
Facility Type :	Solid Waste Class III - nonhazardous solid wastes
Region :	9
Place Type :	Waste Management Unit
Place Subtype :	Land fill
Ageny Name :	San Marcos City
Agency Type :	City Agency
Number of Agencies :	1
Status Date :	2020-12-03
Status :	Active
Status Enrollee :	N
Individual/General :	I
Fee Code :	N/R
Staff Assigned :	N/R
Number of Staff Assigned :	N/R

Map Id: D41
Direction: WSW
Distance: 0.134 mi., 706 ft.
Elevation: 613 ft.
Relative: Higher

Site Name : BRADLEY PARK OLD LINDA VSTA LF | SD CO OF PUB WKS SAN MARCOS I LANDFILL | BRADLEY PARK - OLD LINDA VSTA LANDFILL (SAN MARCOS I LANDFILL) RANCHO SANTA FE & LINDA VISTA | RANCHO SANTE FE RD/LINDA VISTA | RANCHO SANTA FE/LINDA VISTA RD SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, EMI - CA, FRS, HIST LDS - CA, LDS - CA, RFR - CA] ***(cont.)***

Envirosite ID: 280367
EPA ID: N/R

CIWQS 2 - CA ***(cont.)***

Supervisor :	N/R
Number of Supervisor :	N/R
Number of Amendments :	0
Number of Reg Measures :	1
Baseline Flow :	N/R
Population (MS4)/Acres :	N/R
Reclamation :	N/R
CAFO Type :	N/R
CAFO Subtype :	N/R
CAFO Population :	N/R
Onsite :	N/R
Quality Assurance :	N/R
RCRA Flag :	N
Total MMP Violations Number :	0
Total Number of Violations :	0
Total Number of Inspections :	0
Date of Most Recent Completed Inspection:	N/R
Date of Most Recent Received Report :	N/R
Total Number of Final (A+H) Enforcement Actions:	0
Most Recent Effective Date of Enf Action (A+H):	N/R
Program :	SLIC
Program Category :	TANKS
Number of Programs :	1
Complexity :	N/R
Pretreatment :	N/R
Facility Waste Type :	N/R
Reg Measure ID :	441432
Reg Measure Type :	Co-Permitee
Reg Measure Title :	13627 Order Co-Permitee under 2019-0006-DWQ for San Marcos City
Reg Measure Description :	13267 Order requiring PFAS investigation at Landfills. Order requires most facilities to report monitoring results to GeoTracker.
SIC 1 :	4953 - Refuse Systems
SIC 2 :	9511 - Air and Water Resource and Solid Waste Management
SIC 3 :	-
Latitude :	N/R
Longitude :	N/R
Last Date in Agency List :	2022-01-18
Facility ID :	210207
WDID :	9 000000918
Facility Type :	Solid Waste Class III - nonhazardous solid wastes
Region :	9

Map Id: D41
Direction: WSW
Distance: 0.134 mi., 706 ft.
Elevation: 613 ft.
Relative: Higher

Site Name : BRADLEY PARK OLD LINDA VSTA LF | SD CO OF PUB WKS SAN MARCOS I LANDFILL | BRADLEY PARK - OLD LINDA VSTA LANDFILL (SAN MARCOS I LANDFILL) RANCHO SANTA FE & LINDA VISTA | RANCHO SANTE FE RD/LINDA VISTA | RANCHO SANTA FE/LINDA VISTA RD SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, EMI - CA, FRS, HIST LDS - CA, LDS - CA, RFR - CA] ***(cont.)***

Envirosite ID: 280367
EPA ID: N/R

CIWQS 2 - CA ***(cont.)***

Place Type :	Waste Management Unit
Place Subtype :	Land fill
Ageny Name :	San Marcos City
Agency Type :	City Agency
Number of Agencies :	1
Status Date :	2018-02-28
Status :	Active
Status Enrollee :	Y
Individual/General :	I
Fee Code :	59 - Land Disposal Site not paying tipping fee
Staff Assigned :	N/R
Number of Staff Assigned :	N/R
Supervisor :	N/R
Number of Supervisor :	N/R
Number of Amendments :	0
Number of Reg Measures :	2
Baseline Flow :	N/R
Population (MS4)/Acres :	N/R
Reclamation :	N - No
CAFO Type :	N/R
CAFO Subtype :	N/R
CAFO Population :	N/R
Onsite :	N/R
Quality Assurance :	N/R
RCRA Flag :	N
Total MMP Violations Number :	0
Total Number of Violations :	8
Total Number of Inspections :	15
Date of Most Recent Completed Inspection:	2019-05-10
Date of Most Recent Received Report :	N/R
Total Number of Final (A+H) Enforcement Actions:	6
Most Recent Effective Date of Enf Action (A+H):	2008-12-10
Program :	LFNONOPER
Program Category :	LNDISP
Number of Programs :	1
Complexity :	B
Pretreatment :	N - POTW does not have EPA approved pretreatment prog.
Facility Waste Type :	Solid wastes, NEC
Reg Measure ID :	214040
Reg Measure Type :	Enrollee
Reg Measure Title :	Enrollee R9-2012-0001 Bradley Park/Linda Vista Landfill
Reg Measure Description :	Enrolled in Order R9-2012-0001: General WDRs for Maintenance and Monitoring of Closed/Inactive Landfills.

Map Id: D41
Direction: WSW
Distance: 0.134 mi., 706 ft.
Elevation: 613 ft.
Relative: Higher

Site Name : BRADLEY PARK OLD LINDA VSTA LF | SD CO OF PUB WKS SAN MARCOS I LANDFILL | BRADLEY PARK - OLD LINDA VSTA LANDFILL (SAN MARCOS I LANDFILL) RANCHO SANTA FE & LINDA VISTA | RANCHO SANTE FE RD/LINDA VISTA | RANCHO SANTA FE/LINDA VISTA RD SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, EMI - CA, FRS, HIST LDS - CA, LDS - CA, RFR - CA] ***(cont.)***

Envirosite ID: 280367
EPA ID: N/R

CIWQS 2 - CA ***(cont.)***

SIC 1 :	4953 - Refuse Systems
SIC 2 :	9511 - Air and Water Resource and Solid Waste Management
SIC 3 :	-
Latitude :	N/R
Longitude :	N/R
Last Date in Agency List :	2022-01-18
Facility Name :	Bradley Park P-Line 3&4 Reloc
Facility Address :	Rancho Sante Fe Rd/Linda Vista, San Marcos, 92069
County :	San Diego
Facility ID :	210209
WDID :	9 000001027
Facility Type :	All other facilities
Region :	9
Place Type :	Facility
Place Subtype :	N/R
Ageny Name :	San Diego County Water Authority
Agency Type :	Government Agency Combination
Number of Agencies :	1
Status Date :	2004-07-06
Status :	Historical
Status Enrollee :	Y
Individual/General :	I
Fee Code :	N/R
Staff Assigned :	N/R
Number of Staff Assigned :	N/R
Supervisor :	N/R
Number of Supervisor :	N/R
Number of Amendments :	0
Number of Reg Measures :	1
Baseline Flow :	1.008
Population (MS4)/Acres :	N/R
Reclamation :	N/R
CAFO Type :	N/R
CAFO Subtype :	N/R
CAFO Population :	N/R
Onsite :	N/R
Quality Assurance :	N/R
RCRA Flag :	N
Total MMP Violations Number :	0
Total Number of Violations :	4
Total Number of Inspections :	0
Date of Most Recent Completed Inspection:	N/R
Date of Most Recent Received Report :	N/R

Map Id: D41
Direction: WSW
Distance: 0.134 mi., 706 ft.
Elevation: 613 ft.
Relative: Higher

Site Name : BRADLEY PARK OLD LINDA VSTA LF | SD CO OF PUB WKS SAN MARCOS I LANDFILL | BRADLEY PARK - OLD LINDA VSTA LANDFILL (SAN MARCOS I LANDFILL) RANCHO SANTA FE & LINDA VISTA | RANCHO SANTE FE RD/LINDA VISTA | RANCHO SANTA FE/LINDA VISTA RD SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, EMI - CA, FRS, HIST LDS - CA, LDS - CA, RFR - CA] ***(cont.)***

Envirosite ID: 280367
EPA ID: N/R

CIWQS 2 - CA ***(cont.)***

Total Number of Final (A+H) Enforcement Actions:	2
Most Recent Effective Date of Enf Action (A+H):	2004-05-12
Program :	NPDNONMUNIPRCS
Program Category :	NPDESWW
Number of Programs :	1
Complexity :	A
Pretreatment :	N/R
Facility Waste Type :	Miscellaneous
Reg Measure ID :	214098
Reg Measure Type :	Enrollee
Reg Measure Title :	Enrolleee 2001-96: SDCWA Bradley Park P-Line 3&4 Reloc 9-1027
Reg Measure Description :	enrollee under general NPDES Permit CAG919002, Order No. 2001-96 for discharges of groundwater to surface waters
SIC 1 :	1623 - Water, Sewer, Pipeline, and Communications and Power Line Construction
SIC 2 :	-
SIC 3 :	-
Latitude :	N/R
Longitude :	N/R
Last Date in Agency List :	2022-01-18

EMI - CA

Facility Name :	SD CO OF PUB WKS SAN MARCOS I LANDFILL
Facility Address :	RANCHO SANTA FE LINDA VISTA RD, SAN MARCOS, 92069
County :	San Diego
Facility ID :	88177
Air Basin Code :	San Diego
District :	SAN DIEGO COUNTY APCD
County ID :	SD
SIC Code :	4953
CHAPIS :	N/R
CERR Code :	N/R
Last Date in Agency List :	2019-02-18

Additional Details

Year :	2013
Total Organic Gases (Tons/Year) :	51.6

Map Id: D41
Direction: WSW
Distance: 0.134 mi., 706 ft.
Elevation: 613 ft.
Relative: Higher

Site Name : BRADLEY PARK OLD LINDA VSTA LF | SD CO OF PUB WKS SAN MARCOS I LANDFILL | BRADLEY PARK - OLD LINDA VSTA LANDFILL (SAN MARCOS I LANDFILL) RANCHO SANTA FE & LINDA VISTA | RANCHO SANTE FE RD/LINDA VISTA | RANCHO SANTA FE/LINDA VISTA RD SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, EMI - CA, FRS, HIST LDS - CA, LDS - CA, RFR - CA] ***(cont.)***

Envirosite ID: 280367
EPA ID: N/R

EMI - CA ***(cont.)***

Reactive Organic Gases (Tons/Year) :	.41
Carbon Monoxide (Tons/Year) :	.03
Nitrogen Oxides (Tons/Year) :	N/R
Sulfur Oxides (Tons/Year) :	N/R
Particulate Matter (Tons/Year) :	N/R
Fine Particulate Matter (Tons/Year) :	N/R

Year :	2012
Total Organic Gases (Tons/Year) :	51.6
Reactive Organic Gases (Tons/Year) :	.41
Carbon Monoxide (Tons/Year) :	.03
Nitrogen Oxides (Tons/Year) :	N/R
Sulfur Oxides (Tons/Year) :	N/R
Particulate Matter (Tons/Year) :	N/R
Fine Particulate Matter (Tons/Year) :	N/R

Facility Name :	S. D. COUNTY - SAN MARCOS 1 LA
Facility Address :	RANCHO SANTA FE/LINDA VISTA RD, SAN MARCOS, 92069
County :	San Diego

Facility ID :	88177
Air Basin Code :	San Diego
District :	SAN DIEGO COUNTY APCD
County ID :	SD
SIC Code :	4953
CHAPIS :	N/R
CERR Code :	N/R
Last Date in Agency List :	2019-02-18

Additional Details

Year :	2011
Total Organic Gases (Tons/Year) :	51.6
Reactive Organic Gases (Tons/Year) :	.41
Carbon Monoxide (Tons/Year) :	.03
Nitrogen Oxides (Tons/Year) :	N/R
Sulfur Oxides (Tons/Year) :	N/R
Particulate Matter (Tons/Year) :	N/R
Fine Particulate Matter (Tons/Year) :	N/R

Year :	2010
Total Organic Gases (Tons/Year) :	51.59
Reactive Organic Gases (Tons/Year) :	.41

Map Id: D41
Direction: WSW
Distance: 0.134 mi., 706 ft.
Elevation: 613 ft.
Relative: Higher

Site Name : BRADLEY PARK OLD LINDA VSTA LF | SD CO OF PUB WKS SAN MARCOS I LANDFILL | BRADLEY PARK - OLD LINDA VSTA LANDFILL (SAN MARCOS I LANDFILL) RANCHO SANTA FE & LINDA VISTA | RANCHO SANTE FE RD/LINDA VISTA | RANCHO SANTA FE/LINDA VISTA RD SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, EMI - CA, FRS, HIST LDS - CA, LDS - CA, RFR - CA] ***(cont.)***

Envirosite ID: 280367
EPA ID: N/R

EMI - CA ***(cont.)***

Carbon Monoxide (Tons/Year) :	.03
Nitrogen Oxides (Tons/Year) :	N/R
Sulfur Oxides (Tons/Year) :	N/R
Particulate Matter (Tons/Year) :	N/R
Fine Particulate Matter (Tons/Year) :	N/R

FRS

Facility Name :	BRADLEY PARK OLD LINDA VSTA LF
Facility Address :	RANCHO SANTA FE & LINDA VISTA, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Registry ID :	110065013470
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Source Description

Source Description :

The California Environmental Protection Agency (CalEPA) has recently implemented a new data warehouse system (nSite). This data warehouse combines and merges facility and site information from five different systems managed within CalEPA. The five systems are: California Environmental Reporting System (CERS), EnviroStor, GeoTracker, California Integrated Water Quality System (CIWQS), and Toxic Release Inventory (TRI).

FRS Environmental Interest

Source and System ID :	CA-ENVIROVIEW - 13301

Facility Name :	BRADLEY PARK P-LINE 3&4 RELOC
Facility Address :	RANCHO SANTE FE RD/LINDA VISTA, SAN MARCOS, CA 92069
County :	SAN DIEGO COUNTY

Site Details

Registry ID :	110065549311
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Map Id: D41
Direction: WSW
Distance: 0.134 mi., 706 ft.
Elevation: 613 ft.
Relative: Higher

Site Name : BRADLEY PARK OLD LINDA VSTA LF | SD CO OF PUB WKS SAN MARCOS I LANDFILL | BRADLEY PARK - OLD LINDA VSTA LANDFILL (SAN MARCOS I LANDFILL) RANCHO SANTA FE & LINDA VISTA | RANCHO SANTE FE RD/LINDA VISTA | RANCHO SANTA FE/LINDA VISTA RD SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, EMI - CA, FRS, HIST LDS - CA, LDS - CA, RFR - CA] ***(cont.)***

Envirosite ID: 280367
EPA ID: N/R

FRS ***(cont.)***

Source Description

Source Description :

The California Environmental Protection Agency (CalEPA) has recently implemented a new data warehouse system (nSite). This data warehouse combines and merges facility and site information from five different systems managed within CalEPA. The five systems are: California Environmental Reporting System (CERS), EnviroStor, GeoTracker, California Integrated Water Quality System (CIWQS), and Toxic Release Inventory (TRI).

FRS Environmental Interest

Source and System ID :	CA-ENVIROVIEW - 348968
Facility Name :	SD CO OF PUB WKS SAN MARCOS I LANDFILL
Facility Address :	RANCHO SANTA FE LINDA VISTA RD, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Registry ID :	110041142590
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2014-03-25

Source Description

Source Description :

The Emission Inventory System (EIS) maintains an inventory of large stationary sources and voluntarily-reported smaller sources of air point pollution emitters. It contains information about facility sites and their physical location, emission units, emission processes, release points, control approaches, and regulations. Facility inventory data are kept separate from the emissions data and have stable identifiers to improve continuity from year to year and to help identify duplicate or missing facilities.

FRS Environmental Interest

Source and System ID :	EIS - 2395411
Facility Name :	SD CO OF PUB WKS SAN MARCOS I LANDFILL
Facility Address :	RANCHO SANTA FE LINDA VISTA RD, SAN MARCOS, CA 92069-0000
County :	SAN DIEGO

Map Id: D41
Direction: WSW
Distance: 0.134 mi., 706 ft.
Elevation: 613 ft.
Relative: Higher

Site Name : BRADLEY PARK OLD LINDA VSTA LF | SD CO OF PUB WKS SAN MARCOS I LANDFILL | BRADLEY PARK - OLD LINDA VSTA LANDFILL (SAN MARCOS I LANDFILL) RANCHO SANTA FE & LINDA VISTA | RANCHO SANTE FE RD/LINDA VISTA | RANCHO SANTA FE/LINDA VISTA RD SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, EMI - CA, FRS, HIST LDS - CA, LDS - CA, RFR - CA] ***(cont.)***

Envirosite ID: 280367
EPA ID: N/R

FRS ***(cont.)***

Site Details

Registry ID :	110013823568
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Source Description

Source Description :

The Emission Inventory System (EIS) maintains an inventory of large stationary sources and voluntarily-reported smaller sources of air point pollution emitters. It contains information about facility sites and their physical location, emission units, emission processes, release points, control approaches, and regulations. Facility inventory data are kept separate from the emissions data and have stable identifiers to improve continuity from year to year and to help identify duplicate or missing facilities.

FRS Environmental Interest

Source and System ID :	EIS - 2395411

HIST LDS - CA

Facility Name :	BRADLEY PARK OLD LINDA VSTA LF
Facility Address :	RANCHO SANTA FE & LINDA VISTA, SAN MARCOS, CA 92069
County :	SAN DIEGO
Facility ID :	N/R
Facility Type :	LAND DISPOSAL SITE
Status :	OPEN - VERIFICATION MONITORING
Global ID :	L10006943141
Site Code :	N/R
Last Date in Agency List :	2014-07-10

LDS - CA

Facility Name :	BRADLEY PARK - OLD LINDA VSTA LANDFILL (SAN MARCOS I LANDFILL)
Facility Address :	RANCHO SANTA FE & LINDA VISTA, SAN MARCOS, CA 92069
County :	San Diego

Site Details

Status Date :	2015-06-30
Status :	Open - Closed/with Monitoring
Begin Date :	1997-04-07

Map Id: D41
Direction: WSW
Distance: 0.134 mi., 706 ft.
Elevation: 613 ft.
Relative: Higher

Site Name : BRADLEY PARK OLD LINDA VSTA LF | SD CO OF PUB WKS SAN MARCOS I LANDFILL | BRADLEY PARK - OLD LINDA VSTA LANDFILL (SAN MARCOS I LANDFILL) RANCHO SANTA FE & LINDA VISTA | RANCHO SANTE FE RD/LINDA VISTA | RANCHO SANTA FE/LINDA VISTA RD SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, EMI - CA, FRS, HIST LDS - CA, LDS - CA, RFR - CA] ***(cont.)***

Envirosite ID: 280367
EPA ID: N/R

LDS - CA ***(cont.)***

Global ID : L10006943141

Site History :

This site is under an investigative order (Order R9-2006-0044) requiring the discharger to initiate an Evluation Monitoring Program (EMP under CCR Tiitle 27) submittal of an amended Report of Waste Discharge (ROWD). The ROWD should be submitted to the Regional Board for review and comment in June 2009. Upon completion of the ROWD, the Regional Board will issue a corrective action monitoring program and likely, a cleanup and abatement order to implement corrective action alternatives at the site. Corrective action is complete and the site is no longer in cost recovery.

RB Case Number :	2090028
Potential Media Affected :	Soil Vapor, Surface water
Potential Contaminants of Concern :	Benzene, Other Solvent or Non-Petroleum Hydrocarbon, Trichloroethylene (TCE), Vinyl chloride
Local Agency :	N/R
Local Case Number :	N/R
Lead Agency :	SAN DIEGO RWQCB (REGION 9)
File Location :	Regional Board
CUF Case :	NO
Caseworker :	ALG
Case Type :	Land Disposal Site
How Discovered :	N/R
How Discovered Description :	N/R
Stop Method :	N/R
Stop Description :	N/R
Calwater Watershed Name :	Carlsbad - San Marcos - Richland (904.52)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)
Disadvantaged Community :	Severely Disadvantaged Community
Latitude :	33.138175
Longitude :	-117.201804
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-21

Contacts Summary

Global ID :	L10006943141
Contact Name :	AMY L. GROVE
Contact Type :	Regional Board Caseworker
Organization Name :	SAN DIEGO RWQCB (REGION 9)
Address :	2375 NORTHSIDE DRIVE, SUITE 100
City :	SAN DIEGO
Phone Number :	N/R
Email :	amy.grove@waterboards.ca.gov

Map Id: D41
Direction: WSW
Distance: 0.134 mi., 706 ft.
Elevation: 613 ft.
Relative: Higher

Site Name : BRADLEY PARK OLD LINDA VSTA LF | SD CO OF PUB WKS SAN MARCOS I LANDFILL | BRADLEY PARK - OLD LINDA VSTA LANDFILL (SAN MARCOS I LANDFILL) RANCHO SANTA FE & LINDA VISTA | RANCHO SANTE FE RD/LINDA VISTA | RANCHO SANTA FE/LINDA VISTA RD SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, EMI - CA, FRS, HIST LDS - CA, LDS - CA, RFR - CA] ***(cont.)***

Envirosite ID: 280367
EPA ID: N/R

LDS - CA ***(cont.)***

Regulatory Activities

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Date :	2019-12-18
Global ID :	L10006943141
Action Type :	RESPONSE
Action :	Monitoring Report - Other

Date :	2019-09-06
Global ID :	L10006943141
Action Type :	ENFORCEMENT
Action :	Email Correspondence

Date :	2019-07-22
Global ID :	L10006943141
Action Type :	ENFORCEMENT
Action :	Staff Letter

Date :	2019-05-20
Global ID :	L10006943141
Action Type :	RESPONSE
Action :	Other Workplan - Regulator Responded

Date :	2019-05-20
Global ID :	L10006943141
Action Type :	RESPONSE
Action :	Water and Leachate Investigation Workplan

Date :	2019-04-20
Global ID :	L10006943141
Action Type :	RESPONSE
Action :	Questionnaire Response

Date :	2019-03-20
Global ID :	L10006943141
Action Type :	ENFORCEMENT
Action :	PFAS Order - #WQ 2019-0006-DWQ

Map Id: D41
Direction: WSW
Distance: 0.134 mi., 706 ft.
Elevation: 613 ft.
Relative: Higher

Site Name : BRADLEY PARK OLD LINDA VSTA LF | SD CO OF PUB WKS SAN MARCOS I LANDFILL | BRADLEY PARK - OLD LINDA VSTA LANDFILL (SAN MARCOS I LANDFILL) RANCHO SANTA FE & LINDA VISTA | RANCHO SANTE FE RD/LINDA VISTA | RANCHO SANTA FE/LINDA VISTA RD SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, EMI - CA, FRS, HIST LDS - CA, LDS - CA, RFR - CA] ***(cont.)***

Envirosite ID: 280367
EPA ID: N/R

LDS - CA ***(cont.)***

Date :	2012-07-23
Global ID :	L10006943141
Action Type :	ENFORCEMENT
Action :	Site Visit / Inspection / Sampling
Date :	2011-04-29
Global ID :	L10006943141
Action Type :	ENFORCEMENT
Action :	File review
Date :	2010-10-27
Global ID :	L10006943141
Action Type :	ENFORCEMENT
Action :	13267 Monitoring Program - #R9-2010-0123
Date :	2008-12-19
Global ID :	L10006943141
Action Type :	ENFORCEMENT
Action :	Administrative Civil Liabilities Order - #R9-2008-0155
Date :	2007-05-18
Global ID :	L10006943141
Action Type :	RESPONSE
Action :	Other Report / Document
Date :	2007-05-18
Global ID :	L10006943141
Action Type :	RESPONSE
Action :	NPDES / WDR Reports
Date :	2007-05-09
Global ID :	L10006943141
Action Type :	ENFORCEMENT
Action :	Preparation of Agenda Item - #2006-0044
Date :	2007-04-30
Global ID :	L10006943141
Action Type :	RESPONSE
Action :	Monitoring Report - Quarterly

Map Id: D41
Direction: WSW
Distance: 0.134 mi., 706 ft.
Elevation: 613 ft.
Relative: Higher

Site Name : BRADLEY PARK OLD LINDA VSTA LF | SD CO OF PUB WKS SAN MARCOS I LANDFILL | BRADLEY PARK - OLD LINDA VSTA LANDFILL (SAN MARCOS I LANDFILL) RANCHO SANTA FE & LINDA VISTA | RANCHO SANTE FE RD/LINDA VISTA | RANCHO SANTA FE/LINDA VISTA RD SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, EMI - CA, FRS, HIST LDS - CA, LDS - CA, RFR - CA] ***(cont.)***

Envirosite ID: 280367
EPA ID: N/R

LDS - CA ***(cont.)***

Date : 2007-01-05
Global ID : L10006943141
Action Type : ENFORCEMENT
Action : 13267 Requirement - #2006-044-A02

Date : 2006-10-31
Global ID : L10006943141
Action Type : RESPONSE
Action : Other Workplan

Date : 2006-10-30
Global ID : L10006943141
Action Type : RESPONSE
Action : Monitoring Report - Quarterly

Date : 2006-10-16
Global ID : L10006943141
Action Type : ENFORCEMENT
Action : Site Visit / Inspection / Sampling - #97-011

Date : 2006-09-28
Global ID : L10006943141
Action Type : ENFORCEMENT
Action : 13267 Requirement - #2006-044-A01

Status History

Status Date : 2015-06-30
Global ID : L10006943141
Status : Open - Closed/with Monitoring

Status Date : 2009-03-13
Global ID : L10006943141
Status : Open - Verification Monitoring

Status Date : 1997-04-07
Global ID : L10006943141
Status : Open - Case Begin Date

Map Id: D41
Direction: WSW
Distance: 0.134 mi., 706 ft.
Elevation: 613 ft.
Relative: Higher

Site Name : BRADLEY PARK OLD LINDA VSTA LF | SD CO OF PUB WKS SAN MARCOS I LANDFILL | BRADLEY PARK - OLD LINDA VSTA LANDFILL (SAN MARCOS I LANDFILL) RANCHO SANTA FE & LINDA VISTA | RANCHO SANTE FE RD/LINDA VISTA | RANCHO SANTA FE/LINDA VISTA RD SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, EMI - CA, FRS, HIST LDS - CA, LDS - CA, RFR - CA] ***(cont.)***

Envirosite ID: 280367
EPA ID: N/R

RFR - CA

Facility Name :	Bradley Park Old Linda Vsta LF
Facility Address :	Rancho Santa Fe & Linda Vista, San Marcos, CA 92069
County :	San Diego
Effective Date :	1997-04-12
Adoption Date :	N/R
Termination Date :	N/R
Expiration/Review Date :	2017-06-13
NPDES Number :	N/R
Order Number :	R9-2012-0001
WDID :	9 000000918
SIC/NAICS :	4953(+)
Program :	LFNONOPER
Regulatory Measure Status :	Active
Regulatory Measure Type :	Enrollee
Place/Project Type :	Land fill
Region :	9
Design Flow :	N/R
Major/Minor :	N/R
Complexity :	B
TTWQ :	1
Number of Enforcement Actions within Five Years:	N/R
Number of Violations within Five Years:	N/R
Agency :	San Marcos City
Agency Address :	1 Civic Center Drive, San Marcos, CA 92069
Latitude :	N/R
Longitude :	N/R
Last Date in Agency List :	2020-10-08

Effective Date :	2019-03-20
Adoption Date :	N/R
Termination Date :	N/R
Expiration/Review Date :	N/R
NPDES Number :	N/R
Order Number :	2019-0006-DWQ
WDID :	N/R
SIC/NAICS :	4953(+)
Program :	LFNONOPER, SLIC
Regulatory Measure Status :	Active
Regulatory Measure Type :	Co-Permitee
Place/Project Type :	Land fill
Region :	SB
Design Flow :	N/R
Major/Minor :	N/R
Complexity :	N/R

Map Id: D41
Direction: WSW
Distance: 0.134 mi., 706 ft.
Elevation: 613 ft.
Relative: Higher

Site Name : BRADLEY PARK OLD LINDA VSTA LF | SD CO OF PUB WKS SAN MARCOS I LANDFILL | BRADLEY PARK - OLD LINDA VSTA LANDFILL (SAN MARCOS I LANDFILL)
RANCHO SANTA FE & LINDA VISTA | RANCHO SANTE FE RD/LINDA VISTA | RANCHO SANTA FE/LINDA VISTA RD
SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, EMI - CA, FRS, HIST LDS - CA, LDS - CA, RFR - CA] ***(cont.)***

Envirosite ID: 280367
EPA ID: N/R

RFR - CA ***(cont.)***

TTWQ :	N/R
Number of Enforcement Actions within Five Years:	N/R
Number of Violations within Five Years:	N/R
Agency :	San Marcos City
Agency Address :	1 Civic Center Drive, San Marcos, CA 92069
Latitude :	N/R
Longitude :	N/R
Last Date in Agency List :	2022-03-07

Map Id: F42
Direction: ESE
Distance: 0.135 mi., 715 ft.
Elevation: 569 ft.
Relative: Lower

Site Name : GENERAL ELECTRONIC DEVICES | PACIFIC AUTO RESTORATION | AM GRAPHICS AND PRINTING
320 S PACIFIC ST | 320 PACIFIC ST
SAN MARCOS, CA 92069

Database(s) : [HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA]

Envirosite ID: 533428
EPA ID: CAL000138025

HAZMAT_SAN DIEGO COUNTY - CA

Facility Name :	GENERAL ELECTRONIC DEVICES
Facility Address :	320 PACIFIC ST, SAN MARCOS, CA 92069
Date :	2002-05-04
Record ID :	DEH2002-HUPFP-108671
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23
Facility Name :	MIKE VERDUGO PRODUCTS, INC (MVP)
Facility Address :	320 S PACIFIC ST, SAN MARCOS, CA 92069
Date :	2003-03-12
Record ID :	DEH2003-HUPFP-201509
Record Type :	Unified Program Facility Permit
Status :	Completed

Map Id: F42
Direction: ESE
Distance: 0.135 mi., 715 ft.
Elevation: 569 ft.
Relative: Lower

Site Name : GENERAL ELECTRONIC DEVICES | PACIFIC AUTO RESTORATION | AM GRAPHICS AND PRINTING
320 S PACIFIC ST | 320 PACIFIC ST
SAN MARCOS, CA 92069

Database(s) : [HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 533428
EPA ID: CAL000138025

HAZMAT_SAN DIEGO COUNTY - CA ***(cont.)***

Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23

HAZNET - CA

Facility Name :	AM GRAPHICS AND PRINTING
Facility Address :	320 S. PACIFIC ST, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000138025
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	320 S PACIFIC ST, SAN MARCOS, CA 920693832
Latitude :	33.14100354
Longitude :	-117.19781346
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Facility Name :	GENERAL ELECTRONIC DEVICES
Facility Address :	320 S PACIFIC ST, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAC002436295
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	320 S PACIFIC ST, SAN MARCOS, CA 920690000
Latitude :	33.14100354
Longitude :	-117.19781346
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	2002: 213 - Hydrocarbon solvents (benzene, hexane, Stoddard, Etc.), 0.0125 tons to CAD044429835 2002: 221 - Waste oil and mixed oil, 0.0114 tons to CAD028409019

Map Id: F42
Direction: ESE
Distance: 0.135 mi., 715 ft.
Elevation: 569 ft.
Relative: Lower

Site Name : GENERAL ELECTRONIC DEVICES | PACIFIC AUTO RESTORATION | AM GRAPHICS AND PRINTING
320 S PACIFIC ST | 320 PACIFIC ST
SAN MARCOS, CA 92069

Database(s) : [HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 533428
EPA ID: CAL000138025

HAZNET - CA ***(cont.)***

2002: 141 - Off-specification, aged or surplus inorganics, 0.0208 tons to CAD044429835

Facility Name : PACIFIC AUTO RESTORATION
Facility Address : 320 S PACIFIC ST, SAN MARCOS, CA 92069
County : SAN DIEGO

Site Details
Generator EPA ID : CAL000174469
Active : Inactive
Category : STATE
Facility Types : N/R
Type : PERMANENT
Contact Name : N/R
Contact Phone : N/R
Facility Mailing Address : 320 S PACIFIC ST, SAN MARCOS, CA 920693832
Latitude : 33.14100354
Longitude : -117.19781346
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2021-07-08

Waste Generator Details
State Waste : 1996: 214 - Unspecified solvent mixture, 0.108 tons to CAD008252405

HWG - CA

Facility Name : AM GRAPHICS AND PRINTING
Facility Address : 320 S. PACIFIC ST, SAN MARCOS, CA 92069
County : SAN DIEGO

EPA ID : CAL000138025
Status : Inactive
Category : STATE
Type : PERMANENT
Facility Type : N/R
Mailing Address : 320 S PACIFIC ST, SAN MARCOS, CA 920693832
Owner Name : KEN CHADHA
Owner Address : 320 S PACIFIC ST, SAN MARCOS, CA 920693832
Operator Name : DEAC PER LTR FROM K HEEMING NS
Operator Address : NONDELIVERABLE VQ98 NK, SAN MARCOS, CA 920693832
Latitude : 33.141003
Longitude : -117.197759

Facility Name : GENERAL ELECTRONIC DEVICES
Facility Address : 320 S PACIFIC ST, SAN MARCOS, CA 92069
County : SAN DIEGO

Map Id: F42
Direction: ESE
Distance: 0.135 mi., 715 ft.
Elevation: 569 ft.
Relative: Lower

Site Name : GENERAL ELECTRONIC DEVICES | PACIFIC AUTO RESTORATION | AM GRAPHICS AND PRINTING
320 S PACIFIC ST | 320 PACIFIC ST
SAN MARCOS, CA 92069

Database(s) : [HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 533428
EPA ID: CAL000138025

HWG - CA ***(cont.)***

EPA ID :	CAC002436295
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	320 S PACIFIC ST, SAN MARCOS, CA 920690000
Owner Name :	MARVIN_EPSTIN
Owner Address :	320 S PACIFIC ST, SAN MARCOS, CA 920690000
Operator Name :	LINDA EPSTIN-VP
Operator Address :	320 S PACIFIC ST, SAN MARCOS, CA 920690000
Latitude :	33.141003
Longitude :	-117.197759

Facility Name :	PACIFIC AUTO RESTORATION
Facility Address :	320 S PACIFIC ST, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAL000174469
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	320 S PACIFIC ST, SAN MARCOS, CA 920693832
Owner Name :	SALVADOR LOPEZ
Owner Address :	605 ONLEY DR, VISTA, CA 920830000
Operator Name :	SALVADOR LOPEZ
Operator Address :	INACTIVE PER NON DELIVERABLE, N/A
Latitude :	33.141003
Longitude :	-117.197759

Map Id: F43
Direction: E
Distance: 0.137 mi., 725 ft.
Elevation: 569 ft.
Relative: Lower

Site Name : RYKO SOLUTIONS
330 S PACIFIC ST, A
SAN MARCOS, CA 92069

Database(s) : [HAZMAT_SAN DIEGO COUNTY - CA]

Envirosite ID: 628861
EPA ID: N/R

HAZMAT_SAN DIEGO COUNTY - CA

Facility Name :	RYKO SOLUTIONS
Facility Address :	330 S PACIFIC ST, A, SAN MARCOS, CA 92069

Date :	2011-12-20
Record ID :	DEH2011-HUPFP-215890
Record Type :	Unified Program Facility Permit

Map Id: F43
Direction: E
Distance: 0.137 mi., 725 ft.
Elevation: 569 ft.
Relative: Lower

Site Name : RYKO SOLUTIONS
330 S PACIFIC ST, A
SAN MARCOS, CA 92069

Database(s) : [HAZMAT_SAN DIEGO COUNTY - CA] ***(cont.)***

Envirosite ID: 628861
EPA ID: N/R

HAZMAT_SAN DIEGO COUNTY - CA ***(cont.)***

Status :	Permit Renewed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23

Map Id: C44
Direction: WNW
Distance: 0.139 mi., 736 ft.
Elevation: 637 ft.
Relative: Higher

Site Name : GARRET KAYE
3570 DE LONE ROAD
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN]

Envirosite ID: 36572358
EPA ID: CAC003084864

ECHO

Facility Name :	GARRET KAYE
Facility Address :	3570 DE LONE ROAD, SAN MARCOS, CA 92069
County :	SAN DIEGO
Last Inspection Date :	N/R
Registry ID :	N/R
FIPS Code :	N/R
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	_____
Collection Method :	Zip Code Centroid
Reference Point :	N/R
Accuracy Meters :	10000
Derived Tribes :	N/R
Derived HUC :	N/R
Derived WBD :	N/R
Derived STCTY FIPS :	N/R
Derived Zip :	N/R
Derived CD113 :	N/R
Derived CB2010 :	N/R
MYRTK Universe :	NNN
NPDES IDs :	N/R
CWA Permit Types :	N/R

Map Id: C44
Direction: WNW
Distance: 0.139 mi., 736 ft.
Elevation: 637 ft.
Relative: Higher

Site Name : GARRET KAYE
3570 DE LONE ROAD
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 36572358
EPA ID: CAC003084864

ECHO ***(cont.)***

CWA Compliance Tracking :	N/R
CWA NAICS :	N/R
CWA SICS :	N/R
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	N/R
CWA Current Compliance Status :	N/R
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	N/R
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	N/R
Facility NAICS :	56299 - All Other Waste Management Services
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	N/R
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	N
SDWIS Flag :	N
RCRA Flag :	Y
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	N/R
NAA Flag :	N
Latitude :	33.194075
Longitude :	-117.16177
Last Date in Agency List :	2021-02-17

Last Inspection Date :	N/R
Registry ID :	110070911213
FIPS Code :	N/R
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R

Map Id: C44
Direction: WNW
Distance: 0.139 mi., 736 ft.
Elevation: 637 ft.
Relative: Higher

Site Name : GARRET KAYE
3570 DE LONE ROAD
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 36572358
EPA ID: CAC003084864

ECHO ***(cont.)***

Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	_____
Collection Method :	Zip Code Centroid
Reference Point :	N/R
Accuracy Meters :	10000
Derived Tribes :	N/R
Derived HUC :	N/R
Derived WBD :	N/R
Derived STCTY FIPS :	N/R
Derived Zip :	N/R
Derived CD113 :	N/R
Derived CB2010 :	N/R
MYRTK Universe :	NNN
NPDES IDs :	N/R
CWA Permit Types :	N/R
CWA Compliance Tracking :	N/R
CWA NAICS :	N/R
CWA SICS :	N/R
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	N/R
CWA Current Compliance Status :	N/R
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	N/R
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	N/R
Facility NAICS :	56299 - All Other Waste Management Services
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	N/R

Map Id: C44
Direction: WNW
Distance: 0.139 mi., 736 ft.
Elevation: 637 ft.
Relative: Higher

Site Name : GARRET KAYE
3570 DE LONE ROAD
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 36572358
EPA ID: CAC003084864

ECHO ***(cont.)***

Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	N
SDWIS Flag :	N
RCRA Flag :	Y
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	N/R
NAA Flag :	N
Latitude :	33.194075
Longitude :	-117.16177
Last Date in Agency List :	2022-01-17

FRS

Facility Name :	GARRET KAYE
Facility Address :	3570 DE LONE ROAD, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Registry ID :	110070911213
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Source Description

Source Description :

RCRAInfo is EPA's comprehensive information system that supports the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984 through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA. RCRAInfo also supports generation of the National Hazardous Waste Biennial Report. All generators and treatment, storage, and disposal facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years to support creation of the Biennial Report.

FRS Environmental Interest

Source and System ID :	RCRAINFO - CAC003084864

HAZNET - CA

Facility Name :	GARRET KAYE
Facility Address :	3570 DE LONE ROAD, SAN MARCOS, CA 92069
County :	SAN DIEGO

Map Id: C44
Direction: WNW
Distance: 0.139 mi., 736 ft.
Elevation: 637 ft.
Relative: Higher

Site Name : GARRET KAYE
3570 DE LONE ROAD
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 36572358
EPA ID: CAC003084864

HAZNET - CA ***(cont.)***

Site Details

Generator EPA ID :	CAC003084864
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	3570 DE LONE ROAD, SAN MARCOS, CA 92069
Latitude :	33.15247899
Longitude :	-117.19790599
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HWG - CA

Facility Name :	GARRET KAYE
Facility Address :	3570 DE LONE ROAD, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAC003084864
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	3570 DE LONE ROAD, SAN MARCOS, CA 92069
Owner Name :	GARRET KAYE
Owner Address :	3570 DE LONE ROAD, SAN MARCOS, CA 92069
Operator Name :	GARRET KAYE
Operator Address :	3570 DE LONE ROAD, SAN MARCOS, CA 92069
Latitude :	33.152479
Longitude :	-117.197906

MANIFEST EPA

Manifest Details

Manifest Number :	021454486JJK
Shipped Date :	2020-11-08
Updated Date :	2020-12-21
Received Date :	2020-11-16
Status :	Signed
Generator ID :	CAC003084864
Generator Name :	GARRET KAYE
Generator Address :	3570 DE LONE ROAD, SAN MARCOS, CA 92069
Generator Mailing :	3570 DE LONE ROAD, SAN MARCOS, CA 92069
Generator Contact :	N/R
Destination ID :	AZR000506980
Destination Name :	SOUTH YUMA COUNTY LANDFILL
Destination Mailing :	PO BOX 5437, YUMA, AZ 85366-2472
Destination Address :	19536 S AVENUE 1 E, YUMA, AZ 85365
Destination Contact :	N/R
Submission Type :	DataImage5Copy
Origin Type :	Service
Manifest Residue :	N
Rejection :	N

Map Id: C44
Direction: WNW
Distance: 0.139 mi., 736 ft.
Elevation: 637 ft.
Relative: Higher

Site Name : GARRET KAYE
3570 DE LONE ROAD
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 36572358
EPA ID: CAC003084864

MANIFEST EPA ***(cont.)***

Last Date in Agency List : 2022-01-14

Waste Details

Waste Line Number :	1
Is DOT Hazardous :	Y
DOT ID Number :	NA2212
DOT Information :	NA2212, Asbestos, 9, PG III, RQ
Non Waste Description :	N/R
Quantity :	1 Cubic Yards
Quantity Tons, Acute, Non-Acute :	0.84, 0, 0.84
Quantity Kg, Acute, Non-Acute :	0, 761.9052
Management Method :	H132 - LANDFILL (WITH PRIOR TREATMENT AND/OR STABILIZATION)
Is EPA Waste :	N
Federal Code :	N/R
State Code :	CA - 151

RCRA_NONGEN

Facility Name :	GARRET KAYE
Facility Address :	3570 DE LONE ROAD, SAN MARCOS, CA 92069
County :	SAN DIEGO
Date Form Received by Agency :	2020-09-22
EPA ID :	CAC003084864
Mailing Address :	3570 DE LONE ROAD, SAN MARCOS, CA 92069
Contact :	GARRET KAYE
Contact Address :	3570 DE LONE ROAD, SAN MARCOS, CA 92069
Contact Country :	N/R
Contact Telephone :	619-370-3879
Contact Email :	RTRIM@HSABATEMENT.COM
EPA Region :	09
Land Type :	Not Reported
Source Type :	Implementer
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2022-01-26

Owner/Operator Summary

Owner/Operator Name :	GARRET KAYE
Owner/Operator Address :	3570 DE LONE ROAD, SAN MARCOS, CA 92069
Owner/Operator Country :	N/R
Owner/Operator Telephone :	619-370-3879
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Map Id: C44
Direction: WNW
Distance: 0.139 mi., 736 ft.
Elevation: 637 ft.
Relative: Higher

Site Name : GARRET KAYE
3570 DE LONE ROAD
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 36572358
EPA ID: CAC003084864

RCRA_NONGEN ***(cont.)***

Owner/Operator Name :	GARRET KAYE
Owner/Operator Address :	3570 DE LONE ROAD, SAN MARCOS, CA 92069
Owner/Operator Country :	N/R
Owner/Operator Telephone :	619-370-3879
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N/R
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Notices of Violations Summary

Regulation Violated :	N

Map Id: F45
Direction: E
Distance: 0.142 mi., 752 ft.
Elevation: 573 ft.
Relative: Lower

Site Name : FREE BUILDING SUPPLY
330 PACIFIC #D
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 41078275
EPA ID: CAL000009065

HAZNET - CA

Facility Name :	FREE BUILDING SUPPLY
Facility Address :	330 PACIFIC #D, SAN MARCOS, CA 92069
County :	SAN DIEGO

Map Id: F45
Direction: E
Distance: 0.142 mi., 752 ft.
Elevation: 573 ft.
Relative: Lower

Site Name : FREE BUILDING SUPPLY
330 PACIFIC #D
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 41078275
EPA ID: CAL000009065

HAZNET - CA ***(cont.)***

Site Details

Generator EPA ID :	CAL000009065
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	1530 LINDA VISTA DR, SAN MARCOS, CA 920690000
Latitude :	33.15115071
Longitude :	-117.19228254
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HWG - CA

Facility Name :	FREE BUILDING SUPPLY
Facility Address :	330 PACIFIC #D, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAL000009065
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	1530 LINDA VISTA DR, SAN MARCOS, CA 920690000
Owner Name :	FREE WESLEY G PRES
Owner Address :	N/A
Operator Name :	N/R
Operator Address :	N/A
Latitude :	33.151024
Longitude :	-117.192316

Map Id: F46
Direction: E
Distance: 0.144 mi., 760 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : HydroPlant Hydroseeding, Inc. |
MOBILEWELD, INC. | HYDRO-PLANTNA INC
356 S PACIFIC ST
SAN MARCOS, CA 92069

Database(s) : [CALEPA SITES - CA, FRS]

Envirosite ID: 883352
EPA ID: N/R

CALEPA SITES - CA

Facility Name :	HydroPlant Hydroseeding, Inc.
Facility Address :	356 S PACIFIC ST, SAN MARCOS, 92069
Site ID :	123654
EI ID :	10375924
EI Description :	Chemical Storage Facilities
Latitude :	33.140170

Map Id: F46
Direction: E
Distance: 0.144 mi., 760 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : HydroPlant Hydroseeding, Inc. | MOBILEWELD, INC. | HYDRO-PLANTNA INC
356 S PACIFIC ST
SAN MARCOS, CA 92069

Database(s) : [CALEPA SITES - CA, FRS] ***(cont.)***

Envirosite ID: 883352
EPA ID: N/R

CALEPA SITES - CA ***(cont.)***

Longitude : -117.198680
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2019-10-02

Site ID : 123654
EI ID : 10375924
EI Description : Hazardous Waste Generator
Latitude : 33.140170
Longitude : -117.198680
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2019-10-02

Facility Name : MOBILEWELD, INC.
Facility Address : 356 S PACIFIC ST, SAN MARCOS, 92069

Site ID : 576422
EI ID : 10375924
EI Description : Chemical Storage Facilities
Latitude : 33.140170
Longitude : -117.198680
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-01-07

FRS

Facility Name : HYDRO-PLANTNA INC
Facility Address : 356 S PACIFIC ST, SAN MARCOS, CA 92069
County : SAN DIEGO

Site Details

Registry ID : 110065619236
FRS Facility URL : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-02-17

Source Description

Source Description :

The California Environmental Protection Agency (CalEPA) has recently implemented a new data warehouse system (nSite). This data warehouse combines and merges facility and site information from five different systems managed within CalEPA. The five systems are: California Environmental Reporting System (CERS), EnviroStor, GeoTracker, California Integrated Water Quality System (CIWQS), and Toxic Release Inventory (TRI).

FRS Environmental Interest

Source and System ID : CA-ENVIROVIEW - 123654

Map Id: F47
Direction: E
Distance: 0.152 mi., 801 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : SAN MARCOS AUTO TRUCK REPAIR
382 SOUTH PACIFIC ST.
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 601098
EPA ID: CAL923524625

HAZNET - CA

Facility Name :	SAN MARCOS AUTO TRUCK REPAIR
Facility Address :	382 SOUTH PACIFIC ST., SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL923524625
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	382 S PACIFIC ST, SAN MARCOS, CA 920690000
Latitude :	33.13923705
Longitude :	-117.19869110
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	1993: 461 - Paint sludge, 0.2085 tons to CAD008302903

HWG - CA

Facility Name :	SAN MARCOS AUTO TRUCK REPAIR
Facility Address :	382 SOUTH PACIFIC ST., SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAL923524625
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	382 S PACIFIC ST, SAN MARCOS, CA 920690000
Owner Name :	DRAGO ATANASOVSKI JR OWNER/OPE
Owner Address :	382 S PACIFIC ST, SAN MARCOS, CA 920690000
Operator Name :	UNDELIVERABLE FEE FORM 1995 NJ
Operator Address :	N/A
Latitude :	33.139192
Longitude :	-117.198677

Map Id: E48
Direction: NW
Distance: 0.157 mi., 830 ft.
Elevation: 620 ft.
Relative: Higher

Site Name : CHIP UYU
3532 HOLLENCREST RD
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 41085209
EPA ID: CAC002840948

HAZNET - CA

Facility Name :	CHIP UYU
Facility Address :	3532 HOLLENCREST RD, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAC002840948
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	3532 HOLLENCREST RD, SAN MARCOS, CA 920691216
Latitude :	33.15358627
Longitude :	-117.19787933
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HWG - CA

Facility Name :	CHIP UYU
Facility Address :	3532 HOLLENCREST RD, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAC002840948
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	3532 HOLLENCREST RD, SAN MARCOS, CA 920691216
Owner Name :	CHIP UYU
Owner Address :	3532 HOLLENCREST RD, SAN MARCOS, CA 920691216
Operator Name :	CHIP UYU
Operator Address :	3532 HOLLENCREST RD, SAN MARCOS, CA 920691216
Latitude :	33.153586
Longitude :	-117.197879

Map Id: F49
Direction: ESE
Distance: 0.160 mi., 846 ft.
Elevation: 568 ft.
Relative: Lower

Site Name : PEACOCK CLEANERS | SUNNY FRESH & PEACOCK CLEANERS | HAPPY CHANGS
1450 W MISSION RD | 1450 W MISSION RD STE S | 1450 W Mission Rd #S
SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, DRYCLEANERS_SAN DIEGO COUNTY - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, MANIFEST EPA]

Envirosite ID: 345825
EPA ID: CAC002629222

CALEPA SITES - CA

Facility Name : PEACOCK CLEANERS
Facility Address : 1450 W MISSION RD STE S, SAN MARCOS, 92069

Site ID : 72233
EI ID : 10376287
EI Description : Hazardous Waste Generator
Latitude : 33.150920
Longitude : -117.191760
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-01-07

Site ID : 72233
EI ID : 10376287
EI Description : Chemical Storage Facilities
Latitude : 33.150920
Longitude : -117.191760
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-01-07

Facility Name : SUNNY FRESH & PEACOCK CLEANERS
Facility Address : 1450 W MISSION RD STE S, SAN MARCOS, 92069

Site ID : 72233
EI ID : 10376287
EI Description : Chemical Storage Facilities
Latitude : 33.150920
Longitude : -117.191760
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2020-02-19

Site ID : 72233
EI ID : 10376287
EI Description : Hazardous Waste Generator
Latitude : 33.150920
Longitude : -117.191760
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2020-02-19

DRYCLEANERS_SAN DIEGO COUNTY - CA

Facility Name : Peacock Cleaners
Facility Address : 1450 W Mission Rd #S, San Marcos, CA 92069

Date Open : 2009-07-31
Last Updated : N/R

Map Id: F49
Direction: ESE
Distance: 0.160 mi., 846 ft.
Elevation: 568 ft.
Relative: Lower

Site Name : PEACOCK CLEANERS | SUNNY FRESH & PEACOCK CLEANERS | HAPPY CHANGS
1450 W MISSION RD | 1450 W MISSION RD STE S | 1450 W Mission Rd #S
SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, DRYCLEANERS_SAN DIEGO COUNTY - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, MANIFEST EPA] ***(cont.)***

Envirosite ID: 345825
EPA ID: CAC002629222

DRYCLEANERS_SAN DIEGO COUNTY - CA ***(cont.)***

Record ID :	N/R
Record Type :	N/R
Equipment Type :	[31B] Facility using Petroleum Based Solvents
Status :	Active
Expiration Status :	N/R
Name :	N/R
Phone :	7605987237
Description :	PETROLEUM-BASED SOLVENT DRY CLEANING OPERATION: ONE (1) UNION MODEL HL850, MACHINE # 606-12-0352-A, 50 LB CAPACITY, CLOSED LOOP DRY-TO-DRY CLEANING MACHINE, EQUIPPED WITH CARTRIDGE FILTRATION, BUILT-IN REFRIGERATION AND SOLVENT DISTILLATION SYSTEMS AND EMPLOYING EXXON DF-2000 DRY CLEANING SOLVENT. 985500(EZI)961858 (5/97)
Short Notes :	N/R
Last Date in Agency List :	2017-07-06
Date Open :	2009-07-31
Last Updated :	N/R
Record ID :	APCD2007-PTO-910396
Record Type :	N/R
Equipment Type :	[31B] Facility using Petroleum Based Solvents
Status :	Active
Expiration Status :	N/R
Name :	Hoon Young Jung
Phone :	7605987237
Description :	PETROLEUM-BASED SOLVENT DRY CLEANING OPERATION: ONE (1) UNION MODEL HL850, MACHINE # 606-12-0352-A, 50 LB CAPACITY, CLOSED LOOP DRY-TO-DRY CLEANING MACHINE, EQUIPPED WITH CARTRIDGE FILTRATION, BUILT-IN REFRIGERATION AND SOLVENT DISTILLATION SYSTEMS A
Short Notes :	N/R
Last Date in Agency List :	2019-04-19

FRS

Facility Name :	SUNNY FRESH & PEACOCK CLEANERS
Facility Address :	1450 W MISSION RD, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Registry ID :	110065396921
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Map Id: F49
Direction: ESE
Distance: 0.160 mi., 846 ft.
Elevation: 568 ft.
Relative: Lower

Site Name : PEACOCK CLEANERS | SUNNY FRESH & PEACOCK CLEANERS | HAPPY CHANGS
1450 W MISSION RD | 1450 W MISSION RD STE S | 1450 W Mission Rd #S
SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, DRYCLEANERS_SAN DIEGO COUNTY - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, MANIFEST EPA] ***(cont.)***

Envirosite ID: 345825
EPA ID: CAC002629222

FRS ***(cont.)***

Source Description

Source Description :

The California Environmental Protection Agency (CalEPA) has recently implemented a new data warehouse system (nSite). This data warehouse combines and merges facility and site information from five different systems managed within CalEPA. The five systems are: California Environmental Reporting System (CERS), EnviroStor, GeoTracker, California Integrated Water Quality System (CIWQS), and Toxic Release Inventory (TRI).

FRS Environmental Interest

Source and System ID :	CA-ENVIROVIEW - 72233

HAZMAT_SAN DIEGO COUNTY - CA

Facility Name :	SUNNY FRESH & PEACOCK CLEANERS
Facility Address :	1450 W MISSION RD, SAN MARCOS, CA 92069
Date :	2008-05-16
Record ID :	DEH2008-HUPFP-209330
Record Type :	Unified Program Facility Permit
Status :	Permit Renewed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23

HAZNET - CA

Facility Name :	HAPPY CHANGS
Facility Address :	1450 W MISSION RD, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAC002629222
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	1878 WARMLANDS AVE, VISTA, CA 92084
Latitude :	33.15039213
Longitude :	-117.19163902
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Map Id: F49
Direction: ESE
Distance: 0.160 mi., 846 ft.
Elevation: 568 ft.
Relative: Lower

Site Name : PEACOCK CLEANERS | SUNNY FRESH & PEACOCK CLEANERS | HAPPY CHANGS
1450 W MISSION RD | 1450 W MISSION RD STE S | 1450 W Mission Rd #S
SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, DRYCLEANERS_SAN DIEGO COUNTY - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, MANIFEST EPA] ***(cont.)***

Envirosite ID: 345825
EPA ID: CAC002629222

HAZNET - CA ***(cont.)***

Facility Name :	PEACOCK CLEANERS
Facility Address :	1450 W MISSION RD STE S, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL921555653
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	1450 W MISSION RD STE S, SAN MARCOS, CA 920691327
Latitude :	33.15092400
Longitude :	-117.19147050
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	1996: 741 - Liquids with halogenated organic compounds >= 1,000 Mg. /L, 0.39 tons to CAT000613976 1994: 741 - Liquids with halogenated organic compounds >= 1,000 Mg. /L, 0.195 tons to CAT000613976 1993: 741 - Liquids with halogenated organic compounds >= 1,000 Mg. /L, 0.3125 tons to CAT000613893

HWG - CA

Facility Name :	HAPPY CHANGS
Facility Address :	1450 W MISSION RD, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAC002629222
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	1878 WARMLANDS AVE, VISTA, CA 92084
Owner Name :	WILLIAM DAVID GUVARA
Owner Address :	1878 WARMLANDS AVE, VISTA, CA 92084
Operator Name :	WILLIAM DAVID GUVARA
Operator Address :	1878 WARMLANDS AVE, VISTA, CA 92084
Latitude :	33.150411
Longitude :	-117.191591

Map Id: F49
Direction: ESE
Distance: 0.160 mi., 846 ft.
Elevation: 568 ft.
Relative: Lower

Site Name : PEACOCK CLEANERS | SUNNY FRESH & PEACOCK CLEANERS | HAPPY CHANGS
1450 W MISSION RD | 1450 W MISSION RD STE S | 1450 W Mission Rd #S
SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, DRYCLEANERS_SAN DIEGO COUNTY - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, MANIFEST EPA] ***(cont.)***

Envirosite ID: 345825
EPA ID: CAC002629222

HWG - CA ***(cont.)***

Facility Name :	PEACOCK CLEANERS
Facility Address :	1450 W MISSION RD STE S, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAL921555653
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	1450 W MISSION RD STE S, SAN MARCOS, CA 920691327
Owner Name :	YOUNG KIM & SOYAN CHEON
Owner Address :	1450 W MISSION RD STE S, SAN MARCOS, CA 920690000
Operator Name :	YOUNG KIM
Operator Address :	INACTIVE PER VQ98 - BMI, SAN MARCOS, CA
Latitude :	33.150411
Longitude :	-117.191591

MANIFEST EPA

Manifest Details

Manifest Number :	007311353SKS
Shipped Date :	2020-06-05
Updated Date :	2020-07-14
Received Date :	2020-06-24
Status :	Signed
Generator ID :	CAL000334565
Generator Name :	Peacock Cleaners
Generator Address :	1450 W Mission Rd, SAN MARCOS, CA 92069
Generator Mailing :	1450 W Mission Rd, SAN Marcos, CA 92069
Generator Contact :	Peacock Cleaners
Destination ID :	NED981723513
Destination Name :	Clean Harbors Environmental Services, Inc.
Destination Mailing :	2247 South Highway 71, Kimball, NE 69145
Destination Address :	2247 South Highway 71, Kimball, NE 69145
Destination Contact :	N/R
Submission Type :	DataImage5Copy
Origin Type :	Service
Manifest Residue :	N
Rejection :	N
Last Date in Agency List :	2022-01-14

Waste Details

Waste Line Number :	1
Is DOT Hazardous :	Y
DOT ID Number :	NA1993

Map Id: F49
Direction: ESE
Distance: 0.160 mi., 846 ft.
Elevation: 568 ft.
Relative: Lower

Site Name : PEACOCK CLEANERS | SUNNY FRESH & PEACOCK CLEANERS | HAPPY CHANGS
1450 W MISSION RD | 1450 W MISSION RD STE S | 1450 W Mission Rd #S
SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, DRYCLEANERS_SAN DIEGO COUNTY - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, MANIFEST EPA] ***(cont.)***

Envirosite ID: 345825
EPA ID: CAC002629222

MANIFEST EPA ***(cont.)***

DOT Information :	NA1993, WASTE NA1993 WASTE COMBUSTIBLE LIQUID, N.O.S. (PETROLEUM NAPHTHA) PGIII RQ(D001) DOT-SP11606 (D007,D039,D040) (ERG#128), COMBUSTIBLE LIQUID, PG III
Non Waste Description :	N/R
Quantity :	50 Pounds
Quantity Tons, Acute, Non-Acute :	0.025, 0, 0.025
Quantity Kg, Acute, Non-Acute :	0, 22.67575
Management Method :	H141 - STORAGE, BULKING AND/OR TRANSFER OFF SITE
Is EPA Waste :	Y
Federal Code :	D001, D007, D039, D040
State Code :	CA - 741

Manifest Details

Manifest Number :	007035275SKS
Shipped Date :	2019-05-30
Updated Date :	2019-09-01
Received Date :	2019-06-21
Status :	Corrected
Generator ID :	CAL000334565
Generator Name :	Peacock Cleaners
Generator Address :	1450 W Mission Rd, SAN MARCOS, CA 92069
Generator Mailing :	1450 W Mission Rd, SAN Marcos, CA 92069
Generator Contact :	N/R
Destination ID :	NED981723513
Destination Name :	Clean Harbors Environmental Services, Inc.
Destination Mailing :	2247 South Highway 71, Kimball, NE 69145
Destination Address :	2247 South Highway 71, Kimball, NE 69145
Destination Contact :	N/R
Submission Type :	DataImage5Copy
Origin Type :	Service
Manifest Residue :	N
Rejection :	N
Last Date in Agency List :	2022-01-14

Waste Details

Waste Line Number :	1
Is DOT Hazardous :	Y
DOT ID Number :	NA1993
DOT Information :	NA1993, WASTE NA1993 WASTE COMBUSTIBLE LIQUID, N.O.S. (PETROLEUM NAPHTHA) PGIII RQ(D001) DOT-SP11606 (D007,D039,D040) (ERG#128), COMBUSTIBLE LIQUID, PG III
Non Waste Description :	N/R
Quantity :	185 Pounds
Quantity Tons, Acute, Non-Acute :	0.0925, 0, 0.0925

Map Id: F49
Direction: ESE
Distance: 0.160 mi., 846 ft.
Elevation: 568 ft.
Relative: Lower

Site Name : PEACOCK CLEANERS | SUNNY FRESH & PEACOCK CLEANERS | HAPPY CHANGS
1450 W MISSION RD | 1450 W MISSION RD STE S | 1450 W Mission Rd #S
SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, DRYCLEANERS_SAN DIEGO COUNTY - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, MANIFEST EPA] ***(cont.)***

Envirosite ID: 345825
EPA ID: CAC002629222

MANIFEST EPA ***(cont.)***

Quantity Kg, Acute, Non-Acute :	0, 83.900276
Management Method :	H141 - STORAGE, BULKING AND/OR TRANSFER OFF SITE
Is EPA Waste :	Y
Federal Code :	D001, D007, D039, D040
State Code :	CA - 741

Map Id: H50
Direction: S
Distance: 0.164 mi., 865 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : SO CAL COUNTERWORKS | EHIINC
120 NORTH PACIFIC ST#D8
SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, ICIS, INACTIVE PCS, NPDES - CA, PCS ENF, PCS FACILITY, RFR - CA, STORMWATER]

Envirosite ID: 719284
EPA ID: N/R

CALEPA SITES - CA

Facility Name :	EHIINC
Facility Address :	120 NORTH PACIFIC ST#D8, SAN MARCOS, 92069
Site ID :	531167
EI ID :	849255
EI Description :	Industrial Facility Storm Water
Latitude :	33.148731
Longitude :	-117.195465
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2019-07-24
Facility Name :	SO CAL COUNTERWORKS
Facility Address :	120 NORTH PACIFIC ST#D8, SAN MARCOS, 92069
Site ID :	531167
EI ID :	849255
EI Description :	Industrial Facility Storm Water
Latitude :	33.148731
Longitude :	-117.195465
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07

CIWQS - CA

Facility Name :	SO CAL COUNTERWORKS

Map Id: H50
Direction: S
Distance: 0.164 mi., 865 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : SO CAL COUNTERWORKS | EHIINC
120 NORTH PACIFIC ST#D8
SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, ICIS, INACTIVE PCS, NPDES - CA, PCS ENF, PCS FACILITY, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 719284
EPA ID: N/R

CIWQS - CA ***(cont.)***

Facility Address :	120 NORTH PACIFIC ST#D8, SAN MARCOS, CA 92069
County :	SAN DIEGO
Place ID :	S849255
Agency Name :	EHIINC
Last Date in Agency List :	2021-12-30

ECHO

Facility Name :	EHIINC
Facility Address :	120 NORTH PACIFIC ST#D8, SAN MARCOS, CA 92069
County :	SAN DIEGO COUNTY
Last Inspection Date :	N/R
Registry ID :	110070096843
FIPS Code :	06073
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	_____
Collection Method :	N/R
Reference Point :	N/R
Accuracy Meters :	17531

Derived Tribes :

San Pasqual Band of Diegueno Mission Indians of California - 12.4 mile(s), Pala Band of Mission Indians - 13.3 mile (s), Rincon Band of Luiseno Mission Indians of the Rincon Reservation, California - 14.1 mile(s), Rincon Band of Luiseno Mission Indians of the Rincon Reservation, California - 16.3 mile(s), Pauma Band of Luiseno Mission Indians of the Pauma & Yuima Reservation, California - 16.9 mile(s), La Jolla Band of Luiseno Indians, California - 17.2 mile (s), Pechanga Band of Luiseno Mission Indians of the Pechanga Reservation, California - 20.5 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 22.5 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 22.9 mile(s), Mesa Grande Band of Diegueno Mission Indians of the Mesa Grande Reservation, California - 23.2 mile(s)

Derived HUC :	18070303
Derived WBD :	180703030503
Derived STCTY FIPS :	06073
Derived Zip :	92069
Derived CD113 :	50

Map Id: H50
Direction: S
Distance: 0.164 mi., 865 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : SO CAL COUNTERWORKS | EHIINC
120 NORTH PACIFIC ST#D8
SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, ICIS, INACTIVE PCS, NPDES - CA, PCS ENF, PCS FACILITY, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 719284
EPA ID: N/R

ECHO ***(cont.)***

Derived CB2010 :	060730200292005
MYRTK Universe :	NNN
NPDES IDs :	CAZ477262
CWA Permit Types :	Minor
CWA Compliance Tracking :	On
CWA NAICS :	N/R
CWA SICS :	3281
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	0
CWA Current Compliance Status :	No Violation Identified
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	_____
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	3281
Facility NAICS :	N/R
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	Y
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	Y
SDWIS Flag :	N
RCRA Flag :	N
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	Y
NAA Flag :	Y
Latitude :	33.148731
Longitude :	-117.195465
Last Date in Agency List :	2019-09-23

Facility Name :	SO CAL COUNTERWORKS
Facility Address :	120 NORTH PACIFIC ST#D8, SAN MARCOS, CA 92069

Map Id: H50
Direction: S
Distance: 0.164 mi., 865 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : SO CAL COUNTERWORKS | EHIINC
120 NORTH PACIFIC ST#D8
SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, ICIS, INACTIVE PCS, NPDES - CA, PCS ENF, PCS FACILITY, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 719284
EPA ID: N/R

ECHO ***(cont.)***

County :	SAN DIEGO COUNTY
Last Inspection Date :	N/R
Registry ID :	110070096843
FIPS Code :	06073
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	1
Last Informal Action Date :	2020-10-26
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	5
Programs IN SNC :	0
Current Compliance Status :	Violation Identified
Three-Year Compliance Status :	_____VVVVV
Collection Method :	N/R
Reference Point :	N/R
Accuracy Meters :	17531

Derived Tribes :

San Pasqual Band of Diegueno Mission Indians of California - 12.4 mile(s), Pala Band of Mission Indians - 13.3 mile (s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 14.1 mile(s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 16.3 mile(s), Pauma Band of Luiseno Mission Indians of the Pauma & Yuima Reservation, California - 16.9 mile(s), La Jolla Band of Luiseno Indians, California - 17.2 mile(s), Pechanga Band of Luiseno Mission Indians of the Pechanga Reservation, California - 20.5 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 22.5 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 22.9 mile(s), Mesa Grande Band of Diegueno Mission Indians of the Mesa Grande Reservation, California - 23.2 mile(s)

Derived HUC :	18070303
Derived WBD :	180703030503
Derived STCTY FIPS :	06073
Derived Zip :	92069
Derived CD113 :	50
Derived CB2010 :	060730200292005
MYRTK Universe :	NNN
NPDES IDs :	CAZ477262
CWA Permit Types :	Minor
CWA Compliance Tracking :	On
CWA NAICS :	N/R
CWA SICS :	3281
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	1
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R

Map Id: H50
Direction: S
Distance: 0.164 mi., 865 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : SO CAL COUNTERWORKS | EHIINC
120 NORTH PACIFIC ST#D8
SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, ICIS, INACTIVE PCS, NPDES - CA, PCS ENF, PCS FACILITY, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 719284
EPA ID: N/R

ECHO ***(cont.)***

CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	5
CWA Current Compliance Status :	Violation Identified
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	_____VVVVV
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	3281
Facility NAICS :	N/R
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	2020-10-26
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	Y
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	Y
SDWIS Flag :	N
RCRA Flag :	N
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	Y
NAA Flag :	Y
Latitude :	33.148731
Longitude :	-117.195465
Last Date in Agency List :	2022-01-17

FRS

Facility Name :	EHIINC
Facility Address :	120 NORTH PACIFIC ST#D8, SAN MARCOS, CA 92069
County :	SAN DIEGO COUNTY

Site Details

Registry ID :	110070096843
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2019-08-12

Map Id: H50
Direction: S
Distance: 0.164 mi., 865 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : SO CAL COUNTERWORKS | EHIINC
120 NORTH PACIFIC ST#D8
SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, ICIS, INACTIVE PCS, NPDES - CA, PCS ENF, PCS FACILITY, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 719284
EPA ID: N/R

FRS ***(cont.)***

Source Description

Source Description :

The NPDES module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

FRS Environmental Interest

Source and System ID : ICIS - CAZ477262

Facility Name : SO CAL COUNTERWORKS
Facility Address : 120 NORTH PACIFIC ST#D8, SAN MARCOS, CA 92069
County : SAN DIEGO COUNTY

Site Details

Registry ID : 110070096843
FRS Facility URL : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-02-17

Source Description

Source Description :

The NPDES module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

FRS Environmental Interest

Source and System ID : ICIS - CAZ477262

ICIS

Facility Name : EHIINC
Facility Address : 120 NORTH PACIFIC ST#D8, SAN MARCOS, CA 92069

Map Id: H50
Direction: S
Distance: 0.164 mi., 865 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : SO CAL COUNTERWORKS | EHIINC
120 NORTH PACIFIC ST#D8
SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, ICIS, INACTIVE PCS, NPDES - CA, PCS ENF, PCS FACILITY, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 719284
EPA ID: N/R

ICIS ***(cont.)***

Site Details

NPDES ID :	CAZ477262
ICIS Facility Interest ID :	3600735561
Facility UIN :	110070096843
Facility Type Code :	Privately Owned Facility
Impaired Waters :	N/R
Latitude :	33.1487
Longitude :	-117.195
Last Date in Agency List :	2019-07-16

Facility SIC

SIC Code :	3281
SIC Description :	Cut Stone And Stone Products

Facility Name :	SO CAL COUNTERWORKS
Facility Address :	120 NORTH PACIFIC ST#D8, SAN MARCOS, CA 92069

Site Details

NPDES ID :	CAZ477262
ICIS Facility Interest ID :	3600735561
Facility UIN :	110070096843
Facility Type Code :	Privately Owned Facility
Impaired Waters :	N/R
Latitude :	33.148731
Longitude :	-117.195465
Last Date in Agency List :	2022-01-12

Facility SIC

SIC Code :	3281
SIC Description :	Cut Stone And Stone Products

INACTIVE PCS

Issue Date :	2016-08-30
Original Issue Date :	2016-08-30
Effective Date :	2016-08-30
Expiration Date :	2020-06-30
Retirement Date :	N/R
Termination Date :	N/R
Issuing Agency :	CA Waterboards
Agency Type :	State
Activity ID :	3601114939
External Permit Number :	CAZ477262
Facility Type Indicator :	NON-POTW
Permit Type :	General Permit Covered Facility-NPDES)
Major Minor Status :	N

Map Id: H50
Direction: S
Distance: 0.164 mi., 865 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : SO CAL COUNTERWORKS | EHIINC
120 NORTH PACIFIC ST#D8
SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, ICIS, INACTIVE PCS, NPDES - CA, PCS ENF, PCS FACILITY, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 719284
EPA ID: N/R

INACTIVE PCS ***(cont.)***

Permit Status :	Expired
Total Design Flow Number :	N/R
Actual Average Flow Number :	N/R
State Water Body :	N/R
State Water Body Name :	N/R
Permit Name :	EHIINC
Permit Comp Status :	Y
RNC Tracking :	Y
Master External Permit Number :	CAS000001
TMDL Interface :	N/R
EDMR Authorization :	N
Pretreatment Indicator :	N/R
Last Date in Agency List :	2022-01-14

NPDES - CA

Facility Name :	EHIINC
Facility Address :	120 North Pacific ST#D8, San Marcos, 92069
County :	San Diego
Effective Date :	2016-08-30
Adoption Date :	N/R
Expiration Date :	N/R
Termination Date :	N/R
Order Number :	97-03-DWQ
NPDES Number :	CAS000001
WDID :	9 37NEC002441
RM Status :	Active
Reg Meas ID :	477262
Reg Meas Type :	Enrollee
Program :	Industrial
Facility Place ID :	N/R
Region Code :	9
Discharger ID :	0
Discharger :	EHIINC
Discharger Address :	120 North Pacific ST#D8, San Marcos, California 92069
Last Date in Agency List :	2019-09-05
Facility Name :	So Cal Counterworks
Facility Address :	120 North Pacific ST#D8, San Marcos, 92069
County :	San Diego
Effective Date :	2016-08-30
Adoption Date :	N/R
Expiration Date :	N/R
Termination Date :	N/R
Order Number :	97-03-DWQ
NPDES Number :	CAS000001
WDID :	9 37NEC002441
RM Status :	Active
Reg Meas ID :	477262

Map Id: H50
Direction: S
Distance: 0.164 mi., 865 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : SO CAL COUNTERWORKS | EHIINC
120 NORTH PACIFIC ST#D8
SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, ICIS, INACTIVE PCS, NPDES - CA, PCS ENF, PCS FACILITY, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 719284
EPA ID: N/R

NPDES - CA ***(cont.)***

Reg Meas Type :	Enrollee
Program :	Industrial
Facility Place ID :	N/R
Region Code :	9
Discharger ID :	0
Discharger :	EHIINC
Discharger Address :	120 North Pacific ST#D8, San Marcos, California 92069
Last Date in Agency List :	2022-02-24

PCS ENF

Site Details

NPDES ID :	CAZ477262
Last Date in Agency List :	2022-01-19

Formal Enforcement Actions

Settlement Entered Date :	N/R
ENF Identifier :	N/R
Activity ID :	N/R
Activity Type :	N/R
ENF Type :	N/R
Agency :	N/R
Fed Penalty Assessed Amount :	N/R
State Local Penalty Amount :	N/R

Informal Enforcement Actions

Achieved Date :	10/26/2020
Registry ID :	110070096843
ENF Identifier :	CA-ZIEA439347
Activity ID :	3602370244
Activity Type :	Administrative - Informal
ENF Type :	Notice of Violation
Agency :	State

PCS FACILITY

Issue Date :	2016-08-30
Original Issue Date :	2016-08-30
Effective Date :	2016-08-30
Expiration Date :	2020-06-30
Retirement Date :	N/R
Termination Date :	N/R
Issuing Agency :	CA Waterboards
Agency Type :	State
Activity ID :	3601114939
External Permit Number :	CAZ477262
Facility Type Indicator :	NON-POTW
Permit Type :	General Permit Covered Facility-NPDES)
Major Minor Status :	N
Permit Status :	Effective

Map Id: H50
Direction: S
Distance: 0.164 mi., 865 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : SO CAL COUNTERWORKS | EHIINC
120 NORTH PACIFIC ST#D8
SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, ICIS, INACTIVE PCS, NPDES - CA, PCS ENF, PCS FACILITY, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 719284
EPA ID: N/R

PCS FACILITY ***(cont.)***

Total Design Flow Number :	N/R
Actual Average Flow Number :	N/R
State Water Body :	N/R
State Water Body Name :	N/R
Permit Name :	EHIINC
Permit Comp Status :	Y
RNC Tracking :	Y
Master External Permit Number :	CAS000001
TMDL Interface :	N/R
EDMR Authorization :	N
Pretreatment Indicator :	N/R
Last Date in Agency List :	2020-02-11

RFR - CA

Facility Name :	EHIINC
Facility Address :	120 North Pacific ST#D8, San Marcos, CA 92069
County :	San Diego
Effective Date :	2016-08-30
Adoption Date :	N/R
Termination Date :	N/R
Expiration/Review Date :	N/R
NPDES Number :	CAS000001
Order Number :	2014-0057-DWQ
WDID :	9 37NEC002441
SIC/NAICS :	3281
Program :	INDSTW
Regulatory Measure Status :	Active
Regulatory Measure Type :	Storm water industrial
Place/Project Type :	Industrial - Cut Stone and Stone Products
Region :	9
Design Flow :	N/R
Major/Minor :	N/R
Complexity :	N/R
TTWQ :	N/R
Number of Enforcement Actions within Five Years:	N/R
Number of Violations within Five Years:	N/R
Agency :	EHIINC
Agency Address :	120 North Pacific ST#D8, San Marcos, CA 92069
Latitude :	33.148731
Longitude :	-117.195465
Last Date in Agency List :	2019-09-09
Facility Name :	So Cal Counterworks
Facility Address :	120 North Pacific ST#D8, San Marcos, CA 92069
County :	San Diego
Effective Date :	2016-08-30
Adoption Date :	N/R

Map Id: H50
Direction: S
Distance: 0.164 mi., 865 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : SO CAL COUNTERWORKS | EHIINC
120 NORTH PACIFIC ST#D8
SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, ICIS, INACTIVE PCS, NPDES - CA, PCS ENF, PCS FACILITY, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 719284
EPA ID: N/R

RFR - CA ***(cont.)***

Termination Date :	N/R
Expiration/Review Date :	N/R
NPDES Number :	CAS000001
Order Number :	2014-0057-DWQ
WDID :	9 37NEC002441
SIC/NAICS :	3281
Program :	INDSTW
Regulatory Measure Status :	Active
Regulatory Measure Type :	Storm water industrial
Place/Project Type :	Industrial - Cut Stone and Stone Products
Region :	9
Design Flow :	N/R
Major/Minor :	N/R
Complexity :	N/R
TTWQ :	N/R
Number of Enforcement Actions within Five Years:	1
Number of Violations within Five Years:	1
Agency :	EHIINC
Agency Address :	120 North Pacific ST#D8, San Marcos, CA 92069
Latitude :	33.148731
Longitude :	-117.195465
Last Date in Agency List :	2022-03-07

STORMWATER

Facility Name :	SO CAL COUNTERWORKS
Facility Address :	120 NORTH PACIFIC ST#D8, SAN MARCOS, CA 92069
NPDES ID :	CAZ477262
Permittee Name :	EHIINC
Permit Status :	Expired
Permit Issuing Name :	State
Issued Date :	2016-08-30
Termination Date :	N/R
Effective Date :	2016-08-30 2020-06-30
EPA Region :	09
SIC Code :	3281
NAICS Code :	N/R
EJ Indexes Above 80th Percentile :	Y
Significant Noncompliance Status :	N/R
Quarters with Noncompliance :	5
Industrial Stormwater Formal Enforcement Actions:	N/R
Facility Map Flag :	Y
DRF URL :	Click here for hyperlink provided by the agency.
Latitude :	33.148731
Longitude :	-117.195465
Last Date in Agency List :	2022-01-11

Map Id: H51
Direction: S
Distance: 0.165 mi., 869 ft.
Elevation: 572 ft.
Relative: Lower

Site Name : BEST AUTO BODY
120 N PACIFIC ST BLDG B-3
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 41112724
EPA ID: CAX000235028

HAZNET - CA

Facility Name :	BEST AUTO BODY
Facility Address :	120 N PACIFIC ST BLDG B-3, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAX000235028
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	CHARLES, SAN MARCOS, CA 920690000
Latitude :	33.14866500
Longitude :	-117.19501650
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HWG - CA

Facility Name :	BEST AUTO BODY
Facility Address :	120 N PACIFIC ST BLDG B-3, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAX000235028
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	CHARLES, SAN MARCOS, CA 920690000
Owner Name :	N/R
Owner Address :	N/A
Operator Name :	CHARLES
Operator Address :	INACT PER 98VQ FINAL NOTICE, N/A
Latitude :	33.148665
Longitude :	-117.195016

Map Id: 52
Direction: WSW
Distance: 0.171 mi., 906 ft.
Elevation: 576 ft.
Relative: Lower

Site Name : METAL SURGE
16115 RANCHO SANTA FE
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 41127302
EPA ID: CAC002243089

HAZNET - CA

Facility Name :	METAL SURGE
Facility Address :	16115 RANCHO SANTA FE, SAN MARCOS, CA 92069
County :	SAN DIEGO

Map Id: 52
Direction: WSW
Distance: 0.171 mi., 906 ft.
Elevation: 576 ft.
Relative: Lower

Site Name : METAL SURGE
16115 RANCHO SANTA FE
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 41127302
EPA ID: CAC002243089

HAZNET - CA ***(cont.)***

Site Details

Generator EPA ID :	CAC002243089
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	16115 RANCHO SANTA FE, SAN MARCOS, CA 920690000
Latitude :	33.15012212
Longitude :	-117.19835320
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	1999: 135 - Unspecified aqueous solution, 0.756 tons to NVD980895338

HWG - CA

Facility Name :	METAL SURGE
Facility Address :	16115 RANCHO SANTA FE, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAC002243089
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	16115 RANCHO SANTA FE, SAN MARCOS, CA 920690000
Owner Name :	METAL SURGE INC
Owner Address :	449 SANTA FE DR STE 219, ENCINITAS, CA 920240000
Operator Name :	RYAN OUELLETTE-OWNER
Operator Address :	16115 RANCHO SANTA FE, SAN MARCOS, CA 920690000
Latitude :	33.103332
Longitude :	-117.223464

Map Id: G53
Direction: NNE
Distance: 0.173 mi., 914 ft.
Elevation: 658 ft.
Relative: Higher

Site Name : GERLAND, KEITH
1634 SADDLEHORN DRIVE
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 1066731
EPA ID: CAC002936761

HAZNET - CA

Facility Name :	GERLAND, KEITH
Facility Address :	1634 SADDLEHORN DRIVE, SAN MARCOS, CA 92069
County :	SAN DIEGO

Map Id: G53
Direction: NNE
Distance: 0.173 mi., 914 ft.
Elevation: 658 ft.
Relative: Higher

Site Name : GERLAND, KEITH
1634 SADDLEHORN DRIVE
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 1066731
EPA ID: CAC002936761

HAZNET - CA ***(cont.)***

Site Details

Generator EPA ID :	CAC002936761
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	1634 SADDLEHORN DRIVE, SAN MARCOS, CA 92069
Latitude :	33.15454815
Longitude :	-117.19357408
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	2017: 151 - Asbestos containing waste, 0.46 tons to AZC950823111

HWG - CA

Facility Name :	GERLAND, KEITH
Facility Address :	1634 SADDLEHORN DRIVE, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAC002936761
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	1634 SADDLEHORN DRIVE, SAN MARCOS, CA 92069
Owner Name :	GERLAND, KEITH
Owner Address :	1634 SADDLEHORN DRIVE, SAN MARCOS, CA 92069
Operator Name :	GERLAND, KEITH
Operator Address :	1634 SADDLEHORN DRIVE, SAN MARCOS, CA 92069
Latitude :	33.154548
Longitude :	-117.193574

Map Id: H54
Direction: S
Distance: 0.173 mi., 914 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : VECCHIO MONDO IMPORTS | TRANSMISSION DEPOT | OLD FASHIONED WOODWORKING
120 N PACIFIC ST H2 | 120 N PACIFIC ST STE L11 | 120 N PACIFIC ST
SAN MARCOS | San Marcos | SAN DIEGO, CA

Database(s) : [CIWQS - CA, ECHO, FRS, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, RCRA_NONGEN, STORMWATER]

Envirosite ID: 33782712
EPA ID: CAC001468360

CIWQS - CA

Facility Name : AUDIENCE AV INC
Facility Address : 120 N PACIFIC STREET SUITE K9, SAN MARCOS, CA 92069
County : SAN DIEGO

Place ID : S849835
Agency Name : AUDIENCE AV INC
Last Date in Agency List : 2021-12-30

Facility Name : AUDIENCE AV INC
Facility Address : 120 N PACIFIC STREET, SUITE K9, SAN MARCOS, CA 92069
County : SAN DIEGO

Place ID : S849620
Agency Name : AUDIENCE AV INC
Last Date in Agency List : 2021-12-30

Facility Name : CREATIVE PRINTING
Facility Address : 120 N PACIFIC ST SUITE B4, SAN MARCOS, CA 92069
County : SAN DIEGO

Place ID : S811355
Agency Name : CHRIS CLARK
Last Date in Agency List : 2021-12-30

Facility Name : MCCALLAS FINE FURNITURE
Facility Address : 120 NORTH PACIFIC STREET, SAN MARCOS, CA 92069
County : SAN DIEGO

Place ID : S853422
Agency Name : MCCALLAS FINE FURNITURE
Last Date in Agency List : 2021-12-30

Facility Name : QUICK PREMIER DELIVERY
Facility Address : 120 N PACIFIC ST G6, SAN DIEGO, CA 92069
County : SAN DIEGO

Place ID : S892740
Agency Name : QUICK PREMIER DELIVERY
Last Date in Agency List : 2021-12-30

Map Id: H54
Direction: S
Distance: 0.173 mi., 914 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : VECCHIO MONDO IMPORTS | TRANSMISSION DEPOT | OLD FASHIONED WOODWORKING
120 N PACIFIC ST H2 | 120 N PACIFIC ST STE L11 | 120 N PACIFIC ST
SAN MARCOS | San Marcos | SAN DIEGO, CA

Database(s) : [CIWQS - CA, ECHO, FRS, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, RCRA_NONGEN, STORMWATER] ***(cont.)***

Envirosite ID: 33782712
EPA ID: CAC001468360

CIWQS - CA ***(cont.)***

Facility Name :	SAN DIEGO KITCHEN PROS
Facility Address :	120 NORTH PACIFIC STREET, SUITE B2, SAN MARCOS, CA 92069
County :	SAN DIEGO
Place ID :	S850125
Agency Name :	SAN DIEGO KITCHEN PROS
Last Date in Agency List :	2021-12-30
Facility Name :	Sunrise Spa Covers Manufacturing
Facility Address :	120 North Pacific Street Suite H5, San Marcos, CA 92069
County :	San Diego
Place ID :	S866849
Agency Name :	Sunrise Spa Covers Manufacturing
Last Date in Agency List :	2020-02-04
Facility Name :	SUNRISE SPA COVERS MANUFACTURING
Facility Address :	120 NORTH PACIFIC STREET SUITE H5, SAN MARCOS, CA 92069
County :	SAN DIEGO
Place ID :	S880237
Agency Name :	SUNRISE SPA COVERS MANUFACTURING
Last Date in Agency List :	2021-12-30
Facility Name :	SUNRISE SPA COVERS MFG
Facility Address :	120 N PACIFIC ST SUITE H5, SAN MARCOS, CA 92069
County :	SAN DIEGO
Place ID :	S811008
Agency Name :	SUNRISE SPA COVERS MFG
Last Date in Agency List :	2021-12-30
Facility Name :	WORLDWIDE AMMUNITION DISTRIBUTION
Facility Address :	120 N PACIFIC ST STE G5, SAN MARCOS, CA 92069
County :	SAN DIEGO
Place ID :	S881582
Agency Name :	WORLDWIDE AMMUNITION DISTRIBUTION
Last Date in Agency List :	2021-12-30

Map Id: H54
Direction: S
Distance: 0.173 mi., 914 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : VECCHIO MONDO IMPORTS | TRANSMISSION DEPOT | OLD FASHIONED WOODWORKING
120 N PACIFIC ST H2 | 120 N PACIFIC ST STE L11 | 120 N PACIFIC ST
SAN MARCOS | San Marcos | SAN DIEGO, CA

Database(s) : [CIWQS - CA, ECHO, FRS, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, RCRA_NONGEN, STORMWATER] ***(cont.)***

Envirosite ID: 33782712
EPA ID: CAC001468360

ECHO

Facility Name :	VECCHIO MONDO IMPORTS
Facility Address :	120 N PACIFIC ST STE L11, SAN MARCOS, CA 92069
County :	SAN DIEGO
Last Inspection Date :	N/R
Registry ID :	110070473313
FIPS Code :	N/R
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	_____
Collection Method :	Zip Code Centroid
Reference Point :	N/R
Accuracy Meters :	10000
Derived Tribes :	N/R
Derived HUC :	N/R
Derived WBD :	N/R
Derived STCTY FIPS :	N/R
Derived Zip :	N/R
Derived CD113 :	N/R
Derived CB2010 :	N/R
MYRTK Universe :	NNN
NPDES IDs :	N/R
CWA Permit Types :	N/R
CWA Compliance Tracking :	N/R
CWA NAICS :	N/R
CWA SICS :	N/R
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	N/R
CWA Current Compliance Status :	N/R

Map Id: H54
Direction: S
Distance: 0.173 mi., 914 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : VECCHIO MONDO IMPORTS | TRANSMISSION DEPOT | OLD FASHIONED WOODWORKING
120 N PACIFIC ST H2 | 120 N PACIFIC ST STE L11 | 120 N PACIFIC ST
SAN MARCOS | San Marcos | SAN DIEGO, CA

Database(s) : [CIWQS - CA, ECHO, FRS, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, RCRA_NONGEN, STORMWATER] ***(cont.)***

Envirosite ID: 33782712
EPA ID: CAC001468360

ECHO ***(cont.)***

CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	N/R
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	N/R
Facility NAICS :	23521 - Painting and Wall Covering Contractors
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	N/R
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	N
SDWIS Flag :	N
RCRA Flag :	Y
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	Y
NAA Flag :	N
Latitude :	33.194075
Longitude :	-117.16177
Last Date in Agency List :	2022-01-17

Facility Name :	WHITING CABINET & CONSTRUCTION
Facility Address :	120 NORTH PACIFIC STREET, SAN MARCOS, CA 92069
County :	SAN DIEGO COUNTY

Last Inspection Date :	N/R
Registry ID :	110070097065
FIPS Code :	06073
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0

Map Id: H54
Direction: S
Distance: 0.173 mi., 914 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : VECCHIO MONDO IMPORTS | TRANSMISSION DEPOT | OLD FASHIONED WOODWORKING
120 N PACIFIC ST H2 | 120 N PACIFIC ST STE L11 | 120 N PACIFIC ST
SAN MARCOS | San Marcos | SAN DIEGO, CA

Database(s) : [CIWQS - CA, ECHO, FRS, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, RCRA_NONGEN, STORMWATER] ***(cont.)***

Envirosite ID: 33782712
EPA ID: CAC001468360

ECHO ***(cont.)***

Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	N/R
Three-Year Compliance Status :	U
Collection Method :	N/R
Reference Point :	N/R
Accuracy Meters :	17531

Derived Tribes :

San Pasqual Band of Diegueno Mission Indians of California - 12.4 mile(s), Pala Band of Mission Indians - 13.3 mile (s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 14.1 mile(s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 16.3 mile(s), Pauma Band of Luiseno Mission Indians of the Pauma & Yuima Reservation, California - 16.9 mile(s), La Jolla Band of Luiseno Indians, California - 17.2 mile(s), Pechanga Band of Luiseno Mission Indians of the Pechanga Reservation, California - 20.5 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 22.6 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 22.9 mile(s), Mesa Grande Band of Diegueno Mission Indians of the Mesa Grande Reservation, California - 23.3 mile(s)

Derived HUC :	18070303
Derived WBD :	180703030503
Derived STCTY FIPS :	06073
Derived Zip :	92069
Derived CD113 :	50
Derived CB2010 :	060730200292005
MYRTK Universe :	NNN
NPDES IDs :	CAZ479875
CWA Permit Types :	Minor
CWA Compliance Tracking :	Off
CWA NAICS :	N/R
CWA SICS :	2434
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	0
CWA Current Compliance Status :	Terminated Permit
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	_U

Map Id: H54
Direction: S
Distance: 0.173 mi., 914 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : VECCHIO MONDO IMPORTS | TRANSMISSION DEPOT | OLD FASHIONED WOODWORKING
120 N PACIFIC ST H2 | 120 N PACIFIC ST STE L11 | 120 N PACIFIC ST
SAN MARCOS | San Marcos | SAN DIEGO, CA

Database(s) : [CIWQS - CA, ECHO, FRS, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, RCRA_NONGEN, STORMWATER] ***(cont.)***

Envirosite ID: 33782712
EPA ID: CAC001468360

ECHO ***(cont.)***

CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	2434
Facility NAICS :	N/R
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	Y
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	Y
SDWIS Flag :	N
RCRA Flag :	N
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	N/R
NAA Flag :	Y
Latitude :	33.14921
Longitude :	-117.195753
Last Date in Agency List :	2022-01-17

FRS

Facility Name :	CANINE CRYOBANK
Facility Address :	120 N PACIFIC ST UNIT A5, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Registry ID :	110055735879
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Map Id: H54
Direction: S
Distance: 0.173 mi., 914 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : VECCHIO MONDO IMPORTS | TRANSMISSION DEPOT | OLD FASHIONED WOODWORKING
120 N PACIFIC ST H2 | 120 N PACIFIC ST STE L11 | 120 N PACIFIC ST
SAN MARCOS | San Marcos | SAN DIEGO, CA

Database(s) : [CIWQS - CA, ECHO, FRS, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, RCRA_NONGEN, STORMWATER] ***(cont.)***

Envirosite ID: 33782712
EPA ID: CAC001468360

FRS ***(cont.)***

Source Description
Source Description :

The California Environmental Reporting System (CERS) is a statewide web-based user and information exchange system to support over 140,000 regulated businesses and over 130 local agencies in electronically collecting and reporting significant hazardous materials, hazardous waste and compliance and enforcement data as mandated by California law. Under oversight by Cal/EPA, certified local governing agencies (Unified Program Agencies - UPAs) consolidate, coordinate and provide consistent regulatory activities for six state and federal environmental programs.
The California Environmental Protection Agency (CalEPA) has recently implemented a new data warehouse system (nSite). This data warehouse combines and merges facility and site information from five different systems managed within CalEPA. The five systems are: California Environmental Reporting System (CERS), EnviroStor, GeoTracker, California Integrated Water Quality System (CIWQS), and Toxic Release Inventory (TRI).

FRS Environmental Interest
Source and System ID :

CA-CERS - 10375999
CA-ENVIROVIEW - 102799

Facility Name : CASEYS AUTO MACHINE
Facility Address : 120 N PACIFIC ST STE G3, SAN MARCOS, CA 92069
County : SAN DIEGO

Site Details
Registry ID : 110009554008
FRS Facility URL : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-02-17

Source Description

Source Description :

HWTS-DATAMART provides California with information on hazardous waste shipments for generators, transporters, and treatment, storage, and disposal facilities.

Map Id: H54
Direction: S
Distance: 0.173 mi., 914 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : VECCHIO MONDO IMPORTS | TRANSMISSION DEPOT | OLD FASHIONED WOODWORKING
120 N PACIFIC ST H2 | 120 N PACIFIC ST STE L11 | 120 N PACIFIC ST
SAN MARCOS | San Marcos | SAN DIEGO, CA

Database(s) : [CIWQS - CA, ECHO, FRS, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, RCRA_NONGEN, STORMWATER] ***(cont.)***

Envirosite ID: 33782712
EPA ID: CAC001468360

FRS ***(cont.)***

Source Description :

RCRAInfo is EPA's comprehensive information system that supports the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984 through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA. RCRAInfo also supports generation of the National Hazardous Waste Biennial Report. All generators and treatment, storage, and disposal facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years to support creation of the Biennial Report.

FRS Environmental Interest

Source and System ID :	HWTS-DATAMART - CAR000067124 RCRAINFO - CAR000067124
Facility Name :	GERLAND MACHINE INC
Facility Address :	120 N PACIFIC ST STE L12, SAN MARCOS, CA 92069-1293
County :	SAN DIEGO

Site Details

Registry ID :	110070467651
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Source Description

Source Description :

RCRAInfo is EPA's comprehensive information system that supports the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984 through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA. RCRAInfo also supports generation of the National Hazardous Waste Biennial Report. All generators and treatment, storage, and disposal facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years to support creation of the Biennial Report.

FRS Environmental Interest

Source and System ID :	RCRAINFO - CAL000301230

Map Id: H54
Direction: S
Distance: 0.173 mi., 914 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : VECCHIO MONDO IMPORTS | TRANSMISSION DEPOT | OLD FASHIONED WOODWORKING
120 N PACIFIC ST H2 | 120 N PACIFIC ST STE L11 | 120 N PACIFIC ST
SAN MARCOS | San Marcos | SAN DIEGO, CA

Database(s) : [CIWQS - CA, ECHO, FRS, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, RCRA_NONGEN, STORMWATER] ***(cont.)***

Envirosite ID: 33782712
EPA ID: CAC001468360

FRS ***(cont.)***

Facility Name : OLD FORD GARAGE
Facility Address : 120 N PACIFIC ST UNIT K6, SAN MARCOS, CA 92069
County : SAN DIEGO

Site Details
Registry ID : 110002668104
FRS Facility URL : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-02-17

Source Description

Source Description :

RCRAInfo is EPA's comprehensive information system that supports the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984 through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA. RCRAInfo also supports generation of the National Hazardous Waste Biennial Report. All generators and treatment, storage, and disposal facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years to support creation of the Biennial Report.

FRS Environmental Interest
Source and System ID : RCRAINFO - CAD121704688

Facility Name : VECCHIO MONDO IMPORTS
Facility Address : 120 N PACIFIC ST STE L11, SAN MARCOS, CA 92069-1293
County : SAN DIEGO

Site Details
Registry ID : 110070473313
FRS Facility URL : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-02-17

Source Description

Map Id: H54
Direction: S
Distance: 0.173 mi., 914 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : VECCHIO MONDO IMPORTS | TRANSMISSION DEPOT | OLD FASHIONED WOODWORKING
120 N PACIFIC ST H2 | 120 N PACIFIC ST STE L11 | 120 N PACIFIC ST
SAN MARCOS | San Marcos | SAN DIEGO, CA

Database(s) : [CIWQS - CA, ECHO, FRS, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, RCRA_NONGEN, STORMWATER] ***(cont.)***

Envirosite ID: 33782712
EPA ID: CAC001468360

FRS ***(cont.)***

Source Description :

RCRAInfo is EPA's comprehensive information system that supports the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984 through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA. RCRAInfo also supports generation of the National Hazardous Waste Biennial Report. All generators and treatment, storage, and disposal facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years to support creation of the Biennial Report.

FRS Environmental Interest

Source and System ID :	RCRAINFO - CAL000338198

HAZNET - CA

Facility Name :	120 NORTH PACIFIC, LLC
Facility Address :	120 N PACIFIC ST, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAC001468360
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	120 N PACIFIC ST STE D6, SAN MARCOS, CA 920690000
Latitude :	33.14818460
Longitude :	-117.19417119
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	1999: 221 - Waste oil and mixed oil, 0.19 tons to CAD099452708

Facility Name :	AUTOBAHN MOTORSPORTS
Facility Address :	120 N PACIFIC ST B-2, SAN MARCOS, CA 92069
County :	SAN DIEGO

Map Id: H54
Direction: S
Distance: 0.173 mi., 914 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : VECCHIO MONDO IMPORTS | TRANSMISSION DEPOT | OLD FASHIONED WOODWORKING
120 N PACIFIC ST H2 | 120 N PACIFIC ST STE L11 | 120 N PACIFIC ST
SAN MARCOS | San Marcos | SAN DIEGO, CA

Database(s) : [CIWQS - CA, ECHO, FRS, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, RCRA_NONGEN, STORMWATER] ***(cont.)***

Envirosite ID: 33782712
EPA ID: CAC001468360

HAZNET - CA ***(cont.)***

Site Details

Generator EPA ID :	CAL000064987
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	120 N PACIFIC ST STE B2, SAN MARCOS, CA 920691260
Latitude :	33.14818460
Longitude :	-117.19417119
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08
Facility Name :	BIOCLINOVA
Facility Address :	120 N PACIFIC ST STE A4, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000251470
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	300 CARLSBAD VILLAGE DR STE 108 A #, CARLSBAD, CA 92008
Latitude :	33.14818460
Longitude :	-117.19417119
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08
Facility Name :	casey's auto machine
Facility Address :	120 n pacific st ste g3, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAR000067124
Active :	Inactive
Category :	FEDERAL
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	casey rummerfield

Map Id: H54
Direction: S
Distance: 0.173 mi., 914 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : VECCHIO MONDO IMPORTS | TRANSMISSION DEPOT | OLD FASHIONED WOODWORKING
120 N PACIFIC ST H2 | 120 N PACIFIC ST STE L11 | 120 N PACIFIC ST
SAN MARCOS | San Marcos | SAN DIEGO, CA

Database(s) : [CIWQS - CA, ECHO, FRS, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, RCRA_NONGEN, STORMWATER] ***(cont.)***

Envirosite ID: 33782712
EPA ID: CAC001468360

HAZNET - CA ***(cont.)***

Contact Phone :	7605913450
Facility Mailing Address :	120 N PACIFIC ST STE G2 & G3, san marcos, CA 92069
Latitude :	33.14866500
Longitude :	-117.19501650
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :

2006: 223 - Unspecified oil-containing waste, 0.4587 tons to AZR000501510
2005: 223 - Unspecified oil-containing waste, 0.2 tons to CAD980884183
2004: 223 - Unspecified oil-containing waste, 0.375 tons to CAT080013352
2004: 134 - Aqueous solution with total organic residues less than 10 percent, 0.6342 tons to CAT000613893
2004: 134 - Aqueous solution with total organic residues less than 10 percent, 0.2688 tons to CAT000613893
2003: 221 - Waste oil and mixed oil, 0.209 tons to AZD980892731
2003: 181 - Other inorganic solid waste, 0.375 tons to AZD980892731
2003: 134 - Aqueous solution with total organic residues less than 10 percent, 0.315 tons to CAT000613893
2001: 134 - Aqueous solution with total organic residues less than 10 percent, 1.0836 tons to CAT000613893
2001: 223 - Unspecified oil-containing waste, 0.2293 tons to AZD980892731
2000: 223 - Unspecified oil-containing waste, 0.3375 tons to AZD980892731
2000: 134 - Aqueous solution with total organic residues less than 10 percent, 1.176 tons to CAT000613893

Facility Name :	EL BUKI AUTO BODY
Facility Address :	120 NORTH PACIFIC ST STE L5, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000159634
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	120 N PACIFIC ST STE L5, SAN MARCOS, CA 920691269
Latitude :	33.14818460

Map Id: H54
Direction: S
Distance: 0.173 mi., 914 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : VECCHIO MONDO IMPORTS | TRANSMISSION DEPOT | OLD FASHIONED WOODWORKING
120 N PACIFIC ST H2 | 120 N PACIFIC ST STE L11 | 120 N PACIFIC ST
SAN MARCOS | San Marcos | SAN DIEGO, CA

Database(s) : [CIWQS - CA, ECHO, FRS, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, RCRA_NONGEN, STORMWATER] ***(cont.)***

Envirosite ID: 33782712
EPA ID: CAC001468360

HAZNET - CA ***(cont.)***

Longitude :	-117.19417119
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08
Facility Name :	GERLAND MACHINE INC
Facility Address :	120 N PACIFIC ST STE L12, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000301230
Active :	Active
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	120 N PACIFIC ST STE L12, SAN MARCOS, CA 920691293
Latitude :	33.14818460
Longitude :	-117.19417119
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	2015: 135 - Unspecified aqueous solution, 0.126 tons to CAT080013352 2011: 223 - Unspecified oil-containing waste, 0.1251 tons to CAD981696420 2009: 223 - Unspecified oil-containing waste, 0.1251 tons to CAD098169642
Facility Name :	HOUSE OF MB
Facility Address :	120 N PACIFIC ST STE D8, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000319900
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R

Map Id: H54
Direction: S
Distance: 0.173 mi., 914 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : VECCHIO MONDO IMPORTS | TRANSMISSION DEPOT | OLD FASHIONED WOODWORKING
120 N PACIFIC ST H2 | 120 N PACIFIC ST STE L11 | 120 N PACIFIC ST
SAN MARCOS | San Marcos | SAN DIEGO, CA

Database(s) : [CIWQS - CA, ECHO, FRS, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, RCRA_NONGEN, STORMWATER] ***(cont.)***

Envirosite ID: 33782712
EPA ID: CAC001468360

HAZNET - CA ***(cont.)***

Facility Mailing Address :	120 N PACIFIC ST STE D8, SAN MARCOS, CA 92069
Latitude :	33.14818460
Longitude :	-117.19417119
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08
Facility Name :	JRL STREET RODS
Facility Address :	120 NORTH PACIFIC ST, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000098292
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	120 NORTH PACIFIC ST, SAN MARCOS, CA 920690000
Latitude :	33.14818460
Longitude :	-117.19417119
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08
Facility Name :	KCM RACE CARS INC DBA HNM MOTORSPORTS
Facility Address :	120 N PACIFIC ST STE F1, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000330264
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	120 N PACIFIC ST STE F1, SAN MARCOS, CA 920691264
Latitude :	33.14818460
Longitude :	-117.19417119
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Map Id: H54
Direction: S
Distance: 0.173 mi., 914 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : VECCHIO MONDO IMPORTS | TRANSMISSION DEPOT | OLD FASHIONED WOODWORKING
120 N PACIFIC ST H2 | 120 N PACIFIC ST STE L11 | 120 N PACIFIC ST
SAN MARCOS | San Marcos | SAN DIEGO, CA

Database(s) : [CIWQS - CA, ECHO, FRS, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, RCRA_NONGEN, STORMWATER] ***(cont.)***

Envirosite ID: 33782712
EPA ID: CAC001468360

HAZNET - CA ***(cont.)***

Facility Name :	LAUREL KLEIBER
Facility Address :	120 N PACIFIC ST STE L9, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAC002682177
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	120 N PACIFIC ST STE L9, SAN MARCOS, CA 920691269
Latitude :	33.14818460
Longitude :	-117.19417119
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Facility Name :	OLD FORD GARAGE
Facility Address :	120 N PACIFIC ST UNIT K6, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAD121704688
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	120 N PACIFIC ST UNIT K6, SAN MARCOS, CA 920690000
Latitude :	33.14818460
Longitude :	-117.19417119
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Facility Name :	PACIFIC FOREIGN CAR SPECIALIST
Facility Address :	120 N PACIFIC ST STE A11, SAN MARCOS, CA 92069
County :	SAN DIEGO

Map Id: H54
Direction: S
Distance: 0.173 mi., 914 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : VECCHIO MONDO IMPORTS | TRANSMISSION DEPOT | OLD FASHIONED WOODWORKING
120 N PACIFIC ST H2 | 120 N PACIFIC ST STE L11 | 120 N PACIFIC ST
SAN MARCOS | San Marcos | SAN DIEGO, CA

Database(s) : [CIWQS - CA, ECHO, FRS, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, RCRA_NONGEN, STORMWATER] ***(cont.)***

Envirosite ID: 33782712
EPA ID: CAC001468360

HAZNET - CA ***(cont.)***

Site Details

Generator EPA ID :	CAL000089901
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	375 S RANCHO SANTA FE RD STE 109, SAN MARCOS, CA 920692345
Latitude :	33.14818460
Longitude :	-117.19417119
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	1998: 135 - Unspecified aqueous solution, 0.462 tons to CAD099452708 1998: 221 - Waste oil and mixed oil, 1.254 tons to CAD099452708 1997: 135 - Unspecified aqueous solution, 0.231 tons to CAD099452708 1997: 221 - Waste oil and mixed oil, 1.254 tons to CAD099452708 1997: 133 - Aqueous solution with total organic residues 10 percent or more, 0.2293 tons to CAD099452708 1996: 135 - Unspecified aqueous solution, 0.231 tons to CAD099452708 1996: 221 - Waste oil and mixed oil, 1.881 tons to CAD099452708 1995: 133 - Aqueous solution with total organic residues 10 percent or more, 0.2293 tons to CAD099452708 1995: 135 - Unspecified aqueous solution, 0.231 tons to CAD099452708 1995: 221 - Waste oil and mixed oil, 1.254 tons to CAD099452708
Facility Name :	QUALITY STEERING PARTS
Facility Address :	120 N PACIFIC ST STE 5, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000352873
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	120 N PACIFIC ST STE 5, SAN MARCOS, CA 920691258
Latitude :	33.14866500
Longitude :	-117.19501650
Agency Hyperlink :	Click here for hyperlink provided by the agency.

Map Id: H54
Direction: S
Distance: 0.173 mi., 914 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : VECCHIO MONDO IMPORTS | TRANSMISSION DEPOT | OLD FASHIONED WOODWORKING
120 N PACIFIC ST H2 | 120 N PACIFIC ST STE L11 | 120 N PACIFIC ST
SAN MARCOS | San Marcos | SAN DIEGO, CA

Database(s) : [CIWQS - CA, ECHO, FRS, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, RCRA_NONGEN, STORMWATER] ***(cont.)***

Envirosite ID: 33782712
EPA ID: CAC001468360

HAZNET - CA ***(cont.)***

Last Date in Agency List : 2021-07-08

Facility Name : RICHARDS AUTOMOTIVE
Facility Address : 120 N PACIFIC ST, SAN MARCOS, CA 92069
County : SAN DIEGO

Site Details
Generator EPA ID : CAL000176504
Active : Inactive
Category : STATE
Facility Types : N/R
Type : PERMANENT
Contact Name : N/R
Contact Phone : N/R
Facility Mailing Address : 120 N PACIFIC ST, SAN MARCOS, CA 920690000
Latitude : 33.14818460
Longitude : -117.19417119
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2021-07-08

Facility Name : R P M AUTO TECH
Facility Address : 120 N PACIFIC L-5, SAN MARCOS, CA 92069
County : SAN DIEGO

Site Details
Generator EPA ID : CAL000011104
Active : Inactive
Category : STATE
Facility Types : N/R
Type : PERMANENT
Contact Name : N/R
Contact Phone : N/R
Facility Mailing Address : 120 N PACIFIC L-5, SAN MARCOS, CA 920690000
Latitude : 33.14818460
Longitude : -117.19417119
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2021-07-08

Facility Name : STRIDER KNIVES INC
Facility Address : 120 N PACIFIC ST STE L7, SAN MARCOS, CA 92069
County : SAN DIEGO

Map Id: H54
Direction: S
Distance: 0.173 mi., 914 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : VECCHIO MONDO IMPORTS | TRANSMISSION DEPOT | OLD FASHIONED WOODWORKING
120 N PACIFIC ST H2 | 120 N PACIFIC ST STE L11 | 120 N PACIFIC ST
SAN MARCOS | San Marcos | SAN DIEGO, CA

Database(s) : [CIWQS - CA, ECHO, FRS, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, RCRA_NONGEN, STORMWATER] ***(cont.)***

Envirosite ID: 33782712
EPA ID: CAC001468360

HAZNET - CA ***(cont.)***

Site Details

Generator EPA ID :	CAL000295645
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	565 COUNTRY CLUB DRIVE, ESCONDIDO, CA 920291510
Latitude :	33.14818460
Longitude :	-117.19417119
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :

2014: 133 - Aqueous solution with total organic residues 10 percent or more, 0.4587 tons to CAT080013352
2013: 221 - Waste oil and mixed oil, 0.209 tons to CAT080013352
2013: 133 - Aqueous solution with total organic residues 10 percent or more, 0.9174 tons to CAT080013352
2010: 133 - Aqueous solution with total organic residues 10 percent or more, 0.4587 tons to CAT080013352
2009: 133 - Aqueous solution with total organic residues 10 percent or more, 0.4587 tons to CAT080013352
2009: 221 - Waste oil and mixed oil, 0.209 tons to CAT080013352
2008: 221 - Waste oil and mixed oil, 0.209 tons to AZR000035915
2008: 133 - Aqueous solution with total organic residues 10 percent or more, 0.4587 tons to AZR000035915
2006: 221 - Waste oil and mixed oil, 0.418 tons to AZR000035915
2006: 221 - Waste oil and mixed oil, 0.152 tons to AZR000035915
2006: 133 - Aqueous solution with total organic residues 10 percent or more, 1.14675 tons to AZR000035915
2006: 133 - Aqueous solution with total organic residues 10 percent or more, 0.4587 tons to AZR000035915

Facility Name :	THUMPER PERFORMANCE
Facility Address :	120 N PACIFIC ST STE H5, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000265043
Active :	Inactive
Category :	STATE
Facility Types :	N/R

Map Id: H54
Direction: S
Distance: 0.173 mi., 914 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : VECCHIO MONDO IMPORTS | TRANSMISSION DEPOT | OLD FASHIONED WOODWORKING
120 N PACIFIC ST H2 | 120 N PACIFIC ST STE L11 | 120 N PACIFIC ST
SAN MARCOS | San Marcos | SAN DIEGO, CA

Database(s) : [CIWQS - CA, ECHO, FRS, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, RCRA_NONGEN, STORMWATER] ***(cont.)***

Envirosite ID: 33782712
EPA ID: CAC001468360

HAZNET - CA ***(cont.)***

Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	4409 48TH AVE, MILAN, IL 612640000
Latitude :	33.14818460
Longitude :	-117.19417119
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	2004: 252 - Other still bottom waste, 0.018 tons to KYD053348108 2004: 134 - Aqueous solution with total organic residues less than 10 percent, 0.6888 tons to CAT000613893 2003: 134 - Aqueous solution with total organic residues less than 10 percent, 0.42 tons to CAT000613893
Facility Name :	TRANSMISSION DEPOT
Facility Address :	120 N PACIFIC AVE STE F1, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000207977
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	120 N PACIFIC AVE STE F1, SAN MARCOS, CA 920690000
Latitude :	33.14818460
Longitude :	-117.19417119
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08
Facility Name :	TRANSMISSION DEPOT
Facility Address :	120 N PACIFIC ST UNIT F1, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000222113
Active :	Inactive

Map Id: H54
Direction: S
Distance: 0.173 mi., 914 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : VECCHIO MONDO IMPORTS | TRANSMISSION DEPOT | OLD FASHIONED WOODWORKING
120 N PACIFIC ST H2 | 120 N PACIFIC ST STE L11 | 120 N PACIFIC ST
SAN MARCOS | San Marcos | SAN DIEGO, CA

Database(s) : [CIWQS - CA, ECHO, FRS, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, RCRA_NONGEN, STORMWATER] ***(cont.)***

Envirosite ID: 33782712
EPA ID: CAC001468360

HAZNET - CA ***(cont.)***

Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	561 WAVERLY PL, ESCONDIDO, CA 92025
Latitude :	33.14818460
Longitude :	-117.19417119
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	2002: 222 - Oil/water separation sludge, 0.46287 tons to CAT080013352 2002: 222 - Oil/water separation sludge, 1.7097 tons to CAT080013352 2001: 222 - Oil/water separation sludge, 2.2142 tons to CAT080013352
Facility Name :	VECCHIO MONDO IMPORTS
Facility Address :	120 N PACIFIC ST STE L11, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000338198
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	3397 GOLFERS DR, OCEANSIDE, CA 920560000
Latitude :	33.14818460
Longitude :	-117.19417119
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	2018: 214 - Unspecified solvent mixture, 0.39600 tons to CAD008252405 2016: 214 - Unspecified solvent mixture, 0.198 tons to CAD008252405 2015: 214 - Unspecified solvent mixture, 0.324 tons to CAD008252405 2014: 214 - Unspecified solvent mixture, 0.2772 tons to CAD008252405 2012: 214 - Unspecified solvent mixture, 0.162 tons to CAD008252405 2011: 214 - Unspecified solvent mixture, 0.1836 tons to CAD008252405 2010: 214 - Unspecified solvent mixture, 0.216 tons to CAD008252405

Map Id: H54
Direction: S
Distance: 0.173 mi., 914 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : VECCHIO MONDO IMPORTS | TRANSMISSION DEPOT | OLD FASHIONED WOODWORKING
120 N PACIFIC ST H2 | 120 N PACIFIC ST STE L11 | 120 N PACIFIC ST
SAN MARCOS | San Marcos | SAN DIEGO, CA

Database(s) : [CIWQS - CA, ECHO, FRS, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, RCRA_NONGEN, STORMWATER] ***(cont.)***

Envirosite ID: 33782712
EPA ID: CAC001468360

HAZNET - CA ***(cont.)***

2009: 214 - Unspecified solvent mixture, 0.36 tons to CAD008252405

Facility Name : VON ROTH'S FOREIGN
Facility Address : 120 N PACIFIC ST #A-9, SAN MARCOS, CA 92069
County : SAN DIEGO

Site Details
Generator EPA ID : CAL920475141
Active : Inactive
Category : STATE
Facility Types : N/R
Type : PERMANENT
Contact Name : N/R
Contact Phone : N/R
Facility Mailing Address : 120 N PACIFIC ST #A-9, SAN MARCOS, CA 920690000
Latitude : 33.14866500
Longitude : -117.19501650
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2021-07-08

Facility Name : WEBERS CUSTOM STUDIO
Facility Address : 120 NO PACIFIC, SAN MARCOS, CA 92069
County : SAN DIEGO

Site Details
Generator EPA ID : CAL000029314
Active : Inactive
Category : STATE
Facility Types : N/R
Type : PERMANENT
Contact Name : N/R
Contact Phone : N/R
Facility Mailing Address : 120 NO PACIFIC SUITE L10, SAN MARCOS, CA 920690000
Latitude : 33.14818460
Longitude : -117.19417119
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2021-07-08

HWG - CA

Facility Name : 120 NORTH PACIFIC, LLC
Facility Address : 120 N PACIFIC ST, SAN MARCOS, CA 92069
County : SAN DIEGO

Map Id: H54
Direction: S
Distance: 0.173 mi., 914 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : VECCHIO MONDO IMPORTS | TRANSMISSION DEPOT | OLD FASHIONED WOODWORKING
120 N PACIFIC ST H2 | 120 N PACIFIC ST STE L11 | 120 N PACIFIC ST
SAN MARCOS | San Marcos | SAN DIEGO, CA

Database(s) : [CIWQS - CA, ECHO, FRS, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, RCRA_NONGEN, STORMWATER] ***(cont.)***

Envirosite ID: 33782712
EPA ID: CAC001468360

HWG - CA ***(cont.)***

EPA ID :	CAC001468360
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	120 N PACIFIC ST STE D6, SAN MARCOS, CA 920690000
Owner Name :	120 NORTH PACIFIC, LLC
Owner Address :	120 N PACIFIC ST STE D6, SAN MARCOS, CA 920690000
Operator Name :	NATALIE BLACKBURN/PROP MGR
Operator Address :	120 N PACIFIC ST STE D6, SAN MARCOS, CA 920690000
Latitude :	33.148356
Longitude :	-117.194046

Facility Name :	AUTOBAHN MOTORSPORTS
Facility Address :	120 N PACIFIC ST B-2, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAL000064987
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	120 N PACIFIC ST STE B2, SAN MARCOS, CA 920691260
Owner Name :	ROBERT T HARWICK
Owner Address :	N/A
Operator Name :	N/R
Operator Address :	INACTIVE PER NON DELIVERABLE, N/A
Latitude :	33.148185
Longitude :	-117.194171

Facility Name :	BIOCLINOVA
Facility Address :	120 N PACIFIC ST STE A4, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAL000251470
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	300 CARLSBAD VILLAGE DR STE 108 A #, CARLSBAD, CA 92008
Owner Name :	PETER DIAS
Owner Address :	300 CARLSBAD VILLAGE DR STE 108 A #, CARLSBAD, CA 92008
Operator Name :	PETER DIAS
Operator Address :	300 CARLSBAD VILLAGE DR STE 108 A #, CARLSBAD, CA 92008
Latitude :	33.148356

Map Id: H54
Direction: S
Distance: 0.173 mi., 914 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : VECCHIO MONDO IMPORTS | TRANSMISSION DEPOT | OLD FASHIONED WOODWORKING
120 N PACIFIC ST H2 | 120 N PACIFIC ST STE L11 | 120 N PACIFIC ST
SAN MARCOS | San Marcos | SAN DIEGO, CA

Database(s) : [CIWQS - CA, ECHO, FRS, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, RCRA_NONGEN, STORMWATER] ***(cont.)***

Envirosite ID: 33782712
EPA ID: CAC001468360

HWG - CA ***(cont.)***

Longitude :	-117.194046
Facility Name :	casey's auto machine
Facility Address :	120 n pacific st ste g3, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	car000067124
Status :	Inactive
Category :	FEDERAL
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	120 N PACIFIC ST STE G2 & G3, SAN MARCOS, CA 92069
Owner Name :	CASEY'S AUTO MACHINE
Owner Address :	120 N PACIFIC ST STE G2 & G3, SAN MARCOS, CA 920690000
Operator Name :	CASEY RUMMERFIELD
Operator Address :	120 N PACIFIC ST G2 & G3, SAN MARCOS, CA 920690000
Latitude :	33.148365
Longitude :	-117.194054
Facility Name :	EL BUKI AUTO BODY
Facility Address :	120 NORTH PACIFIC ST STE L5, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAL000159634
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	120 N PACIFIC ST STE L5, SAN MARCOS, CA 920691269
Owner Name :	CARLOS VILLAGOMEZ
Owner Address :	120 N PACIFIC ST STE L5, SAN MARCOS, CA 920691269
Operator Name :	CARLOS VILLAGOMEZ-OWNER
Operator Address :	UNDELIVERABLE VF97 LC, SAN MARCOS, CA 920691269
Latitude :	33.148356
Longitude :	-117.194046
Facility Name :	GERLAND MACHINE INC
Facility Address :	120 N PACIFIC ST STE L12, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAL000301230
Status :	Active
Category :	STATE

Map Id: H54
Direction: S
Distance: 0.173 mi., 914 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : VECCHIO MONDO IMPORTS | TRANSMISSION DEPOT | OLD FASHIONED WOODWORKING
120 N PACIFIC ST H2 | 120 N PACIFIC ST STE L11 | 120 N PACIFIC ST
SAN MARCOS | San Marcos | SAN DIEGO, CA

Database(s) : [CIWQS - CA, ECHO, FRS, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, RCRA_NONGEN, STORMWATER] ***(cont.)***

Envirosite ID: 33782712
EPA ID: CAC001468360

HWG - CA ***(cont.)***

Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	120 N PACIFIC ST STE L12, SAN MARCOS, CA 920691293
Owner Name :	KEITH A GERLAND
Owner Address :	120 N PACIFIC ST STE L-12, SAN MARCOS, CA 920691293
Operator Name :	KEITH A GERLAND
Operator Address :	120 N PACIFIC ST STE L-12, SAN MARCOS, CA 92069
Latitude :	33.147717
Longitude :	-117.194382

Facility Name :	HOUSE OF MB
Facility Address :	120 N PACIFIC ST STE D8, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAL000319900
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	120 N PACIFIC ST STE D8, SAN MARCOS, CA 92069
Owner Name :	HERBERT RUPPERT
Owner Address :	3717 VIA CABRILLO, OCEANSIDE, CA 92056
Operator Name :	HERBERT RUPPERT
Operator Address :	120 N PACIFIC ST STE D8, SAN MARCOS, CA 92069
Latitude :	33.147756
Longitude :	-117.194492

Facility Name :	JRL STREET RODS
Facility Address :	120 NORTH PACIFIC ST, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAL000098292
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	120 NORTH PACIFIC ST, SAN MARCOS, CA 920690000
Owner Name :	JOSEPH LAPORTE
Owner Address :	120 NORTH PACIFIC ST, SAN MARCOS, CA 920690000
Operator Name :	DEACT PER VQ96
Operator Address :	120 NORTH PACIFIC ST, SAN MARCOS, CA 920690000
Latitude :	33.148356
Longitude :	-117.194046

Map Id: H54
Direction: S
Distance: 0.173 mi., 914 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : VECCHIO MONDO IMPORTS | TRANSMISSION DEPOT | OLD FASHIONED WOODWORKING
120 N PACIFIC ST H2 | 120 N PACIFIC ST STE L11 | 120 N PACIFIC ST
SAN MARCOS | San Marcos | SAN DIEGO, CA

Database(s) : [CIWQS - CA, ECHO, FRS, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, RCRA_NONGEN, STORMWATER] ***(cont.)***

Envirosite ID: 33782712
EPA ID: CAC001468360

HWG - CA ***(cont.)***

Facility Name :	KCM RACE CARS INC DBA HNM MOTORSPORTS
Facility Address :	120 N PACIFIC ST STE F1, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAL000330264
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	120 N PACIFIC ST STE F1, SAN MARCOS, CA 920691264
Owner Name :	KCM RACE CARS INC
Owner Address :	120 N PACIFIC ST STE F1, SAN MARCOS, CA 920691264
Operator Name :	KEVIN MAHAN
Operator Address :	120 N PACIFIC ST STE F1, SAN MARCOS, CA 920691264
Latitude :	33.14867
Longitude :	-117.19502
Facility Name :	LAUREL KLEIBER
Facility Address :	120 N PACIFIC ST STE L9, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAC002682177
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	120 N PACIFIC ST STE L9, SAN MARCOS, CA 920691269
Owner Name :	LAUREL KLEIBER
Owner Address :	120 N PACIFIC ST STE L9, SAN MARCOS, CA 920691269
Operator Name :	LAUREL KLEIBER
Operator Address :	120 N PACIFIC ST STE L9, SAN MARCOS, CA 920691269
Latitude :	33.148669
Longitude :	-117.195016
Facility Name :	OLD FORD GARAGE
Facility Address :	120 N PACIFIC ST UNIT K6, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAD121704688
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	120 N PACIFIC ST UNIT K6, SAN MARCOS, CA 920690000

Map Id: H54
Direction: S
Distance: 0.173 mi., 914 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : VECCHIO MONDO IMPORTS | TRANSMISSION DEPOT | OLD FASHIONED WOODWORKING
120 N PACIFIC ST H2 | 120 N PACIFIC ST STE L11 | 120 N PACIFIC ST
SAN MARCOS | San Marcos | SAN DIEGO, CA

Database(s) : [CIWQS - CA, ECHO, FRS, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, RCRA_NONGEN, STORMWATER] ***(cont.)***

Envirosite ID: 33782712
EPA ID: CAC001468360

HWG - CA ***(cont.)***

Owner Name :	N/R
Owner Address :	N/A
Operator Name :	UNDELIVERABLE PER SURVEY
Operator Address :	12/94 AD, N/A
Latitude :	33.148161
Longitude :	-117.194372

Facility Name :	PACIFIC FOREIGN CAR SPECIALIST
Facility Address :	120 N PACIFIC ST STE A11, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAL000089901
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	375 S RANCHO SANTA FE RD STE 109, SAN MARCOS, CA 920692345
Owner Name :	FRED SCHREIBER
Owner Address :	1203 CORTE SIERRA, SAN MARCOS, CA 920690000
Operator Name :	FRED SCHREIBER
Operator Address :	375 S RANCHO SANTA FE RD STE 109, SAN MARCOS, CA 920692345
Latitude :	33.148356
Longitude :	-117.194046

Facility Name :	QUALITY STEERING PARTS
Facility Address :	120 N PACIFIC ST STE 5, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAL000352873
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	120 N PACIFIC ST STE 5, SAN MARCOS, CA 920691258
Owner Name :	CRISPIN RIVERA
Owner Address :	120 N PACIFIC ST STE 5, SAN MARCOS, CA 920691258
Operator Name :	YAZMIN RIVERA
Operator Address :	120 N PACIFIC ST STE 5, SAN MARCOS, CA 920691258
Latitude :	33.14867
Longitude :	-117.19502

Facility Name :	RICHARDS AUTOMOTIVE
Facility Address :	120 N PACIFIC ST, SAN MARCOS, CA 92069
County :	SAN DIEGO

Map Id: H54
Direction: S
Distance: 0.173 mi., 914 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : VECCHIO MONDO IMPORTS | TRANSMISSION DEPOT | OLD FASHIONED WOODWORKING
120 N PACIFIC ST H2 | 120 N PACIFIC ST STE L11 | 120 N PACIFIC ST
SAN MARCOS | San Marcos | SAN DIEGO, CA

Database(s) : [CIWQS - CA, ECHO, FRS, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, RCRA_NONGEN, STORMWATER] ***(cont.)***

Envirosite ID: 33782712
EPA ID: CAC001468360

HWG - CA ***(cont.)***

EPA ID :	CAL000176504
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	120 N PACIFIC ST, SAN MARCOS, CA 920690000
Owner Name :	JOSE COMPOS
Owner Address :	120 N PACIFIC ST, SAN MARCOS, CA 920690000
Operator Name :	OCO CLEMENT/JOSE COMPOS
Operator Address :	INACT PER NONDEL 99VQ - CR, SAN MARCOS, CA 920690000
Latitude :	33.148356
Longitude :	-117.194046
Facility Name :	R P M AUTO TECH
Facility Address :	120 N PACIFIC L-5, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAL000011104
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	120 N PACIFIC L-5, SAN MARCOS, CA 920690000
Owner Name :	SMITH RICHARD
Owner Address :	N/A
Operator Name :	UNDELIVERABLE PER SURVEY
Operator Address :	12/94 AD, N/A
Latitude :	33.148356
Longitude :	-117.194046
Facility Name :	STRIDER KNIVES INC
Facility Address :	120 N PACIFIC ST STE L7, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAL000295645
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	565 COUNTRY CLUB DRIVE, ESCONDIDO, CA 920291510
Owner Name :	STRIDER KNIVES INC
Owner Address :	120 N PACIFIC ST STE L7, SAN MARCOS, CA 920691269
Operator Name :	STEVE NEWELL
Operator Address :	120 N PACIFIC ST STE L7, SAN MARCOS, CA 920691269
Latitude :	33.148365

Map Id: H54
Direction: S
Distance: 0.173 mi., 914 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : VECCHIO MONDO IMPORTS | TRANSMISSION DEPOT | OLD FASHIONED WOODWORKING
120 N PACIFIC ST H2 | 120 N PACIFIC ST STE L11 | 120 N PACIFIC ST
SAN MARCOS | San Marcos | SAN DIEGO, CA

Database(s) : [CIWQS - CA, ECHO, FRS, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, RCRA_NONGEN, STORMWATER] ***(cont.)***

Envirosite ID: 33782712
EPA ID: CAC001468360

HWG - CA ***(cont.)***

Longitude :	-117.194054
Facility Name :	THUMPER PERFORMANCE
Facility Address :	120 N PACIFIC ST STE H5, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAL000265043
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	4409 48TH AVE, MILAN, IL 612640000
Owner Name :	DANA MONSON
Owner Address :	120 N PACIFIC ST STE H5, SAN MARCOS, CA 92069
Operator Name :	LINDA JOHNSON OFFICE MANAGER
Operator Address :	120 N PACIFIC ST STE H5, SAN MARCOS, CA 92069
Latitude :	33.148356
Longitude :	-117.194046
Facility Name :	TRANSMISSION DEPOT
Facility Address :	120 N PACIFIC AVE STE F1, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAL000207977
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	120 N PACIFIC AVE STE F1, SAN MARCOS, CA 920690000
Owner Name :	BEN WILLIAMS
Owner Address :	120 N PACIFIC AVE STE F1, SAN MARCOS, CA 920690000
Operator Name :	BEN WILLIAMS/OWNER
Operator Address :	INACT PER NONDEL 00VQ - CR, SAN MARCOS, CA 920690000
Latitude :	33.148356
Longitude :	-117.194046
Facility Name :	TRANSMISSION DEPOT
Facility Address :	120 N PACIFIC ST UNIT F1, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAL000222113
Status :	Inactive
Category :	STATE

Map Id: H54
Direction: S
Distance: 0.173 mi., 914 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : VECCHIO MONDO IMPORTS | TRANSMISSION DEPOT | OLD FASHIONED WOODWORKING
120 N PACIFIC ST H2 | 120 N PACIFIC ST STE L11 | 120 N PACIFIC ST
SAN MARCOS | San Marcos | SAN DIEGO, CA

Database(s) : [CIWQS - CA, ECHO, FRS, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, RCRA_NONGEN, STORMWATER] ***(cont.)***

Envirosite ID: 33782712
EPA ID: CAC001468360

HWG - CA ***(cont.)***

Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	561 WAVERLY PL, ESCONDIDO, CA 92025
Owner Name :	BEN WILLIAMS
Owner Address :	561 WAVERLY PL, ESCONDIDO, CA 92025
Operator Name :	BEN WILLIAMS-OWNER
Operator Address :	561 WAVERLY PL, ESCONDIDO, CA 92025
Latitude :	33.148356
Longitude :	-117.194046

Facility Name :	VECCHIO MONDO IMPORTS
Facility Address :	120 N PACIFIC ST STE L11, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAL000338198
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	3397 GOLFERS DR, OCEANSIDE, CA 920560000
Owner Name :	EDDIE BOZZA
Owner Address :	3397 GOLFERS DR, OCEANSIDE, CA 920560000
Operator Name :	EDDIE BOZZA
Operator Address :	3397 GOLFERS DR, OCEANSIDE, CA 92056
Latitude :	33.147756
Longitude :	-117.194492

Facility Name :	VON ROTH'S FOREIGN
Facility Address :	120 N PACIFIC ST #A-9, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAL920475141
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	120 N PACIFIC ST #A-9, SAN MARCOS, CA 920690000
Owner Name :	VON ROTH ERIC
Owner Address :	120 N PACIFIC ST #A-9, SAN MARCOS, CA 920690000
Operator Name :	UNDELIVERABLE 1996 FEES FORM
Operator Address :	N/A
Latitude :	33.148356
Longitude :	-117.194046

Map Id: H54
Direction: S
Distance: 0.173 mi., 914 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : VECCHIO MONDO IMPORTS | TRANSMISSION DEPOT | OLD FASHIONED WOODWORKING
120 N PACIFIC ST H2 | 120 N PACIFIC ST STE L11 | 120 N PACIFIC ST
SAN MARCOS | San Marcos | SAN DIEGO, CA

Database(s) : [CIWQS - CA, ECHO, FRS, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, RCRA_NONGEN, STORMWATER] ***(cont.)***

Envirosite ID: 33782712
EPA ID: CAC001468360

HWG - CA ***(cont.)***

Facility Name :	WEBERS CUSTOM STUDIO
Facility Address :	120 NO PACIFIC, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAL000029314
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	120 NO PACIFIC SUITE L10, SAN MARCOS, CA 920690000
Owner Name :	WEBER DENNIS
Owner Address :	N/A
Operator Name :	UNDELIVERABLE FEE FORM 4-94
Operator Address :	N/A
Latitude :	33.148356
Longitude :	-117.194046

ICIS

Facility Name :	OLD FASHIONED WOODWORKING
Facility Address :	120 N PACIFIC ST H2, SAN MARCOS, CA 92069

Site Details

NPDES ID :	CAZ521733
ICIS Facility Interest ID :	3601208881
Facility UIN :	110070801197
Facility Type Code :	Privately Owned Facility
Impaired Waters :	N/R
Latitude :	33.14865
Longitude :	-117.1951
Last Date in Agency List :	2022-01-12

Facility SIC

SIC Code :	2434
SIC Description :	Wood Kitchen Cabinets

Site Details

NPDES ID :	CAZ521733
ICIS Facility Interest ID :	3601208881
Facility UIN :	110070801197
Facility Type Code :	Privately Owned Facility
Impaired Waters :	N/R

Map Id: H54
Direction: S
Distance: 0.173 mi., 914 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : VECCHIO MONDO IMPORTS | TRANSMISSION DEPOT | OLD FASHIONED WOODWORKING
120 N PACIFIC ST H2 | 120 N PACIFIC ST STE L11 | 120 N PACIFIC ST
SAN MARCOS | San Marcos | SAN DIEGO, CA

Database(s) : [CIWQS - CA, ECHO, FRS, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, RCRA_NONGEN, STORMWATER] ***(cont.)***

Envirosite ID: 33782712
EPA ID: CAC001468360

ICIS ***(cont.)***

Latitude :	33.14865
Longitude :	-117.1951
Last Date in Agency List :	2021-08-17

Facility SIC

SIC Code :	2434
SIC Description :	Wood Kitchen Cabinets

INACTIVE PCS

Issue Date :	2020-06-17
Original Issue Date :	2020-06-17
Effective Date :	2020-06-17
Expiration Date :	2020-06-30
Retirement Date :	N/R
Termination Date :	2021-05-04
Issuing Agency :	CA Waterboards
Agency Type :	State
Activity ID :	3602219877
External Permit Number :	CAZ521733
Facility Type Indicator :	NON-POTW
Permit Type :	General Permit Covered Facility-NPDES)
Major Minor Status :	N
Permit Status :	Terminated
Total Design Flow Number :	N/R
Actual Average Flow Number :	N/R
State Water Body :	N/R
State Water Body Name :	N/R
Permit Name :	Old Fashioned Woodworking
Permit Comp Status :	Y
RNC Tracking :	Y
Master External Permit Number :	CAS000001
TMDL Interface :	N/R
EDMR Authorization :	N
Pretreatment Indicator :	N/R
Last Date in Agency List :	2022-01-14

Issue Date :	2020-06-17
Original Issue Date :	2020-06-17
Effective Date :	2020-06-17
Expiration Date :	2020-06-30
Retirement Date :	N/R
Termination Date :	2021-05-04
Issuing Agency :	CA Waterboards
Agency Type :	State
Activity ID :	3602219877

Map Id: H54
Direction: S
Distance: 0.173 mi., 914 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : VECCHIO MONDO IMPORTS | TRANSMISSION DEPOT | OLD FASHIONED WOODWORKING
120 N PACIFIC ST H2 | 120 N PACIFIC ST STE L11 | 120 N PACIFIC ST
SAN MARCOS | San Marcos | SAN DIEGO, CA

Database(s) : [CIWQS - CA, ECHO, FRS, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, RCRA_NONGEN, STORMWATER] ***(cont.)***

Envirosite ID: 33782712
EPA ID: CAC001468360

INACTIVE PCS ***(cont.)***

External Permit Number :	CAZ521733
Facility Type Indicator :	NON-POTW
Permit Type :	General Permit Covered Facility-NPDES)
Major Minor Status :	N
Permit Status :	Terminated
Total Design Flow Number :	N/R
Actual Average Flow Number :	N/R
State Water Body :	N/R
State Water Body Name :	N/R
Permit Name :	Old Fashioned Woodworking
Permit Comp Status :	Y
RNC Tracking :	Y
Master External Permit Number :	CAS000001
TMDL Interface :	N/R
EDMR Authorization :	N
Pretreatment Indicator :	N/R
Last Date in Agency List :	2021-08-19

NPDES - CA

Facility Name :	Old Fashioned Woodworking
Facility Address :	120 N Pacific St H2, San Marcos, 92069
County :	San Diego
Effective Date :	2020-06-17
Adoption Date :	N/R
Expiration Date :	N/R
Termination Date :	2021-05-04
Order Number :	97-03-DWQ
NPDES Number :	CAS000001
WDID :	9 37NEC006862
RM Status :	Terminated
Reg Meas ID :	521733
Reg Meas Type :	Enrollee
Program :	Industrial
Facility Place ID :	N/R
Region Code :	9
Discharger ID :	0
Discharger :	Old Fashioned Woodworking
Discharger Address :	120 N Pacific St H2, San Marcos, California 92069
Last Date in Agency List :	2022-02-24
Facility Name :	Pioneer Industrial Condominiums
Facility Address :	120 N Pacific St H2, San Marcos, 92069
County :	San Diego

Map Id: H54
Direction: S
Distance: 0.173 mi., 914 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : VECCHIO MONDO IMPORTS | TRANSMISSION DEPOT | OLD FASHIONED WOODWORKING
120 N PACIFIC ST H2 | 120 N PACIFIC ST STE L11 | 120 N PACIFIC ST
SAN MARCOS | San Marcos | SAN DIEGO, CA

Database(s) : [CIWQS - CA, ECHO, FRS, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, RCRA_NONGEN, STORMWATER] ***(cont.)***

Envirosite ID: 33782712
EPA ID: CAC001468360

NPDES - CA ***(cont.)***

Effective Date :	2020-06-17
Adoption Date :	N/R
Expiration Date :	N/R
Termination Date :	N/R
Order Number :	97-03-DWQ
NPDES Number :	CAS000001
WDID :	9 37NEC006862
RM Status :	Active
Reg Meas ID :	521733
Reg Meas Type :	Enrollee
Program :	Industrial
Facility Place ID :	N/R
Region Code :	9
Discharger ID :	0
Discharger :	Old Fashioned Woodworking
Discharger Address :	120 N Pacific St H2, San Marcos, California 92069
Last Date in Agency List :	2021-03-23

RCRA_NONGEN

Facility Name :	GERLAND MACHINE INC
Facility Address :	120 N PACIFIC ST STE L12, SAN MARCOS, CA 92069-1293
County :	SAN DIEGO
Date Form Received by Agency :	2005-12-08
EPA ID :	CAL000301230
Mailing Address :	120 N PACIFIC ST STE L12, SAN MARCOS, CA 92069-1293
Contact :	KEITH A GERLAND
Contact Address :	120 N PACIFIC ST STE L-12, SAN MARCOS, CA 92069
Contact Country :	N/R
Contact Telephone :	760-744-0821
Contact Email :	QUALITY@GERLANDMACHINE.COM
EPA Region :	09
Land Type :	Not Reported
Source Type :	Implementer
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2022-01-26

Owner/Operator Summary

Owner/Operator Name :	KEITH A GERLAND
Owner/Operator Address :	120 N PACIFIC ST STE L12, SAN MARCOS, CA 92069-1293
Owner/Operator Country :	N/R
Owner/Operator Telephone :	619-857-7827
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R

Map Id: H54
Direction: S
Distance: 0.173 mi., 914 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : VECCHIO MONDO IMPORTS | TRANSMISSION DEPOT | OLD FASHIONED WOODWORKING
120 N PACIFIC ST H2 | 120 N PACIFIC ST STE L11 | 120 N PACIFIC ST
SAN MARCOS | San Marcos | SAN DIEGO, CA

Database(s) : [CIWQS - CA, ECHO, FRS, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, RCRA_NONGEN, STORMWATER] ***(cont.)***

Envirosite ID: 33782712
EPA ID: CAC001468360

RCRA_NONGEN ***(cont.)***

Legal Status :	Other land type
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R
Owner/Operator Name :	KEITH A GERLAND
Owner/Operator Address :	120 N PACIFIC ST STE L-12, SAN MARCOS, CA 92069
Owner/Operator Country :	N/R
Owner/Operator Telephone :	760-744-0821
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Notices of Violations Summary

Regulation Violated :	N
Facility Name :	VECCHIO MONDO IMPORTS
Facility Address :	120 N PACIFIC ST STE L11, SAN MARCOS, CA 92069-1293
County :	SAN DIEGO
Date Form Received by Agency :	2008-11-25
EPA ID :	CAL000338198

Map Id: H54
Direction: S
Distance: 0.173 mi., 914 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : VECCHIO MONDO IMPORTS | TRANSMISSION DEPOT | OLD FASHIONED WOODWORKING
120 N PACIFIC ST H2 | 120 N PACIFIC ST STE L11 | 120 N PACIFIC ST
SAN MARCOS | San Marcos | SAN DIEGO, CA

Database(s) : [CIWQS - CA, ECHO, FRS, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, RCRA_NONGEN, STORMWATER] ***(cont.)***

Envirosite ID: 33782712
EPA ID: CAC001468360

RCRA_NONGEN ***(cont.)***

Mailing Address :	3397 GOLFERS DR, OCEANSIDE, CA 92056-0000
Contact :	EDDIE BOZZA
Contact Address :	3397 GOLFERS DR, OCEANSIDE, CA 92056
Contact Country :	N/R
Contact Telephone :	858-229-3713
Contact Email :	BOZZA@SBCGLOBAL.NET
EPA Region :	09
Land Type :	Not Reported
Source Type :	Implementer
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2022-01-26

Owner/Operator Summary

Owner/Operator Name :	EDDIE BOZZA
Owner/Operator Address :	3397 GOLFERS DR, OCEANSIDE, CA 92056-0000
Owner/Operator Country :	N/R
Owner/Operator Telephone :	858-229-3713
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Owner/Operator Name :	EDDIE BOZZA
Owner/Operator Address :	3397 GOLFERS DR, OCEANSIDE, CA 92056
Owner/Operator Country :	N/R
Owner/Operator Telephone :	858-229-3713
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N

Map Id: H54
Direction: S
Distance: 0.173 mi., 914 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : VECCHIO MONDO IMPORTS | TRANSMISSION DEPOT | OLD FASHIONED WOODWORKING
120 N PACIFIC ST H2 | 120 N PACIFIC ST STE L11 | 120 N PACIFIC ST
SAN MARCOS | San Marcos | SAN DIEGO, CA

Database(s) : [CIWQS - CA, ECHO, FRS, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, RCRA_NONGEN, STORMWATER] ***(cont.)***

Envirosite ID: 33782712
EPA ID: CAC001468360

RCRA_NONGEN ***(cont.)***

Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Notices of Violations Summary

Regulation Violated :	N

STORMWATER

Facility Name :	OLD FASHIONED WOODWORKING
Facility Address :	120 N PACIFIC ST H2, SAN MARCOS, CA 92069
NPDES ID :	CAZ521733
Permittee Name :	Old Fashioned Woodworking
Permit Status :	Terminated
Permit Issuing Name :	State
Issued Date :	2020-06-17
Termination Date :	2021-05-04
Effective Date :	2020-06-17
	2020-06-30
EPA Region :	09
SIC Code :	2434
NAICS Code :	N/R
EJ Indexes Above 80th Percentile :	Y
Significant Noncompliance Status :	N/R
Quarters with Noncompliance :	0
Industrial Stormwater Formal Enforcement Actions:	N/R
Facility Map Flag :	Y
DRF URL :	Click here for hyperlink provided by the agency.
Latitude :	33.14865
Longitude :	-117.1951
Last Date in Agency List :	2022-01-11

Map Id: 55
Direction: W
Distance: 0.173 mi., 916 ft.
Elevation: 612 ft.
Relative: Higher

Site Name : SAN MARCOS ANIMAL MEDICAL CENTER | SIENNA PRINT & DESIGN INC DBA ALPHAGRAPHICS 554 | THE NORTH COUNTY EMERGENCY ANIMAL CLINIC
100 N RANCHO SANTA FE RD | 100 N RANCHO SANTA FE RD STE 127 | 100 N RANCHO SANTA FE RD, 133
SAN MARCOS, CA

Database(s) : [HAZNET - CA, HWG - CA, SCHOOLS PUBLIC]

Envirosite ID: 41147004
EPA ID: CAL000390526

HAZNET - CA

Facility Name :	SAN MARCOS ANIMAL MEDICAL CENTER
Facility Address :	100 N RANCHO SANTA FE RD, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000390526
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	100 N RANCHO SANTA FE RD, SAN MARCOS, CA 920690000
Latitude :	33.15172500
Longitude :	-117.19913400
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Facility Name :	SIENNA PRINT & DESIGN INC DBA ALPHAGRAPHICS 554
Facility Address :	100 N RANCHO SANTA FE RD STE 127, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000341752
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	1205 LINDA VISTA DR STE A, SAN MARCOS, CA 920780000
Latitude :	33.15168617
Longitude :	-117.19768703
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Facility Name :	THE NORTH COUNTY EMERGENCY ANIMAL CLINIC
Facility Address :	100 N RANCHO SANTA FE RD, 133, SAN MARCOS, CA 92069
County :	SAN DIEGO

Map Id: 55
Direction: W
Distance: 0.173 mi., 916 ft.
Elevation: 612 ft.
Relative: Higher

Site Name : SAN MARCOS ANIMAL MEDICAL CENTER | SIENNA PRINT & DESIGN INC DBA ALPHAGRAPHICS 554 | THE NORTH COUNTY EMERGENCY ANIMAL CLINIC
100 N RANCHO SANTA FE RD | 100 N RANCHO SANTA FE RD STE 127 | 100 N RANCHO SANTA FE RD, 133
SAN MARCOS, CA

Database(s) : [HAZNET - CA, HWG - CA, SCHOOLS PUBLIC] ***(cont.)***

Envirosite ID: 41147004
EPA ID: CAL000390526

HAZNET - CA ***(cont.)***

Site Details

Generator EPA ID :	CAL000175837
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	100 N RANCHO SANTA FE RD # 133, SAN MARCOS, CA 920690000
Latitude :	33.15168617
Longitude :	-117.19768703
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HWG - CA

Facility Name :	SAN MARCOS ANIMAL MEDICAL CENTER
Facility Address :	100 N RANCHO SANTA FE RD, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAL000390526
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	100 N RANCHO SANTA FE RD, SAN MARCOS, CA 920690000
Owner Name :	DR BRIAN HOSKING
Owner Address :	100 N RANCHO SANTA FE RD, SAN MARCOS, CA 920690000
Operator Name :	DR BRIAN HOSKING
Operator Address :	100 N RANCHO SANTA FE RD, SAN MARCOS, CA 920690000
Latitude :	33.151725
Longitude :	-117.199134
Facility Name :	SIENNA PRINT & DESIGN INC DBA ALPHAGRAPHICS 554
Facility Address :	100 N RANCHO SANTA FE RD STE 127, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAL000341752
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	1205 LINDA VISTA DR STE A, SAN MARCOS, CA 920780000
Owner Name :	SIENNA PRINT & DESIGN INC
Owner Address :	100 N RANCHO SANTA FE RD STE 127, SAN MARCOS, CA 920691294
Operator Name :	GARY TREIBER
Operator Address :	1205 LINDA VISTA DR STE A, SAN MARCOS, CA 920780000

Map Id: 55
Direction: W
Distance: 0.173 mi., 916 ft.
Elevation: 612 ft.
Relative: Higher

Site Name : SAN MARCOS ANIMAL MEDICAL CENTER | SIENNA PRINT & DESIGN INC DBA ALPHAGRAPHICS 554 | THE NORTH COUNTY EMERGENCY ANIMAL CLINIC
100 N RANCHO SANTA FE RD | 100 N RANCHO SANTA FE RD STE 127 | 100 N RANCHO SANTA FE RD, 133
SAN MARCOS, CA

Database(s) : [HAZNET - CA, HWG - CA, SCHOOLS PUBLIC] ***(cont.)***

Envirosite ID: 41147004
EPA ID: CAL000390526

HWG - CA ***(cont.)***

Latitude :	33.15179
Longitude :	-117.19892
Facility Name :	THE NORTH COUNTY EMERGENCY ANIMAL CLINIC
Facility Address :	100 N RANCHO SANTA FE RD, 133, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAL000175837
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	100 N RANCHO SANTA FE RD # 133, SAN MARCOS, CA 920690000
Owner Name :	NORTH COUNTY EMERGENCY ANIMAL
Owner Address :	100 N RANCHO SANTA FE RD, 133, SAN MARCOS, CA
Operator Name :	DR ROGER ROWLEY
Operator Address :	INACTIVE PER VQ00 - BMI, N/A
Latitude :	33.150642
Longitude :	-117.198005

SCHOOLS PUBLIC

Facility Name :	TAYLION SAN DIEGO ACADEMY
Facility Address :	100 N. RANCHO SANTE FE RD. #1, SAN MARCOS, CA 92069-1279
County :	SAN DIEGO
NCES ID :	064071013696
TYPE ID :	1
Status :	1
Population :	161
NAICS Code :	611110
NAICS Desc :	ELEMENTARY AND SECONDARY SCHOOLS
Level :	OTHER
Enrollment :	153
ST Grade :	KG
End Grade :	12
FT Teacher :	8
Telephone :	(760) 295-5564
County Fips :	06073
Country :	USA
District ID :	640710
Shelter ID :	NOT AVAILABLE
Souce Date :	2016-01-05
Val Date :	2016-01-15
Source :	Click here for hyperlink provided by the agency.
Latitude :	33.151614
Longitude :	-117.198997

Map Id: 55
Direction: W
Distance: 0.173 mi., 916 ft.
Elevation: 612 ft.
Relative: Higher

Site Name : SAN MARCOS ANIMAL MEDICAL CENTER | SIENNA PRINT & DESIGN INC DBA ALPHAGRAPHICS 554 | THE NORTH COUNTY EMERGENCY ANIMAL CLINIC
100 N RANCHO SANTA FE RD | 100 N RANCHO SANTA FE RD STE 127 | 100 N RANCHO SANTA FE RD, 133
SAN MARCOS, CA

Database(s) : [HAZNET - CA, HWG - CA, SCHOOLS PUBLIC] ***(cont.)***

Envirosite ID: 41147004
EPA ID: CAL000390526

SCHOOLS PUBLIC ***(cont.)***

Last Date in Agency List : 2022-02-23

Map Id: I56
Direction: SSE
Distance: 0.177 mi., 933 ft.
Elevation: 567 ft.
Relative: Lower

Site Name : UNICAP MOLD CO
140 N PACIFIC ST STE K
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 831435
EPA ID: CAC002574067

HAZNET - CA

Facility Name : UNICAP MOLD CO
Facility Address : 140 N PACIFIC ST STE K, SAN MARCOS, CA 92069
County : SAN DIEGO

Site Details
Generator EPA ID : CAC002574067
Active : Inactive
Category : STATE
Facility Types : N/R
Type : TEMPORARY
Contact Name : N/R
Contact Phone : N/R
Facility Mailing Address : 140 N PACIFIC ST STE K, SAN MARCOS, CA 92069
Latitude : 33.14864265
Longitude : -117.19390979
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2021-07-08

Waste Generator Details
State Waste : 2004: 221 - Waste oil and mixed oil, 0.2375 tons to CAT080033681

HWG - CA

Facility Name : UNICAP MOLD CO
Facility Address : 140 N PACIFIC ST STE K, SAN MARCOS, CA 92069
County : SAN DIEGO

EPA ID : CAC002574067
Status : Inactive

Map Id: I56
Direction: SSE
Distance: 0.177 mi., 933 ft.
Elevation: 567 ft.
Relative: Lower

Site Name : UNICAP MOLD CO
140 N PACIFIC ST STE K
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 831435
EPA ID: CAC002574067

HWG - CA ***(cont.)***

Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	140 N PACIFIC ST STE K, SAN MARCOS, CA 92069
Owner Name :	UNICAP MOLD CO
Owner Address :	140 N PACIFIC ST STE K, SAN MARCOS, CA 92069
Operator Name :	RANDY PEREZ
Operator Address :	140 N PACIFIC ST STE K, SAN MARCOS, CA 92069
Latitude :	33.149086
Longitude :	-117.193665

Map Id: I57
Direction: SSE
Distance: 0.177 mi., 934 ft.
Elevation: 567 ft.
Relative: Lower

Site Name : STONE ELEMENT | SCD FABRICATION
143 N PACIFIC ST #K | 143 S PACIFIC ST
SAN MARCOS, CA

Database(s) : [CIWQS - CA, HAZMAT_SAN DIEGO COUNTY - CA]

Envirosite ID: 280059
EPA ID: N/R

CIWQS - CA

Facility Name :	STONE ELEMENT
Facility Address :	143 N PACIFIC ST #K, SAN MARCOS, CA 92084
County :	SAN DIEGO
Place ID :	S723758
Agency Name :	STONE ELEMENT
Last Date in Agency List :	2021-12-30

HAZMAT_SAN DIEGO COUNTY - CA

Facility Name :	SCD FABRICATION
Facility Address :	143 S PACIFIC ST, SAN MARCOS, CA 92069
Date :	2011-01-12
Record ID :	DEH2011-HUPFP-213476
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23

Map Id: E58
Direction: NW
Distance: 0.179 mi., 945 ft.
Elevation: 599 ft.
Relative: Higher

Site Name : ERNESTO RAYMUNDO
3520 HOLLENCREST RD
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN]

Envirosite ID: 40542940
EPA ID: CAC003107027

ECHO

Facility Name :	ERNESTO RAYMUNDO
Facility Address :	3520 HOLLENCREST RD, SAN MARCOS, CA 92069
County :	SAN DIEGO
Last Inspection Date :	N/R
Registry ID :	110071055227
FIPS Code :	N/R
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	_____
Collection Method :	Zip Code Centroid
Reference Point :	N/R
Accuracy Meters :	10000
Derived Tribes :	N/R
Derived HUC :	N/R
Derived WBD :	N/R
Derived STCTY FIPS :	N/R
Derived Zip :	N/R
Derived CD113 :	N/R
Derived CB2010 :	N/R
MYRTK Universe :	NNN
NPDES IDs :	N/R
CWA Permit Types :	N/R
CWA Compliance Tracking :	N/R
CWA NAICS :	N/R
CWA SICS :	N/R
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	N/R
CWA Current Compliance Status :	N/R
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	N/R
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	N/R
Facility NAICS :	56299 - All Other Waste Management Services

Map Id: E58
Direction: NW
Distance: 0.179 mi., 945 ft.
Elevation: 599 ft.
Relative: Higher

Site Name : ERNESTO RAYMUNDO
3520 HOLLENCREST RD
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 40542940
EPA ID: CAC003107027

ECHO ***(cont.)***

Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	N/R
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	N
SDWIS Flag :	N
RCRA Flag :	Y
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	N/R
NAA Flag :	N
Latitude :	33.194075
Longitude :	-117.16177
Last Date in Agency List :	2022-01-17

Last Inspection Date :	N/R
Registry ID :	N/R
FIPS Code :	N/R
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	_____
Collection Method :	Zip Code Centroid
Reference Point :	N/R
Accuracy Meters :	10000
Derived Tribes :	N/R
Derived HUC :	N/R
Derived WBD :	N/R
Derived STCTY FIPS :	N/R
Derived Zip :	N/R
Derived CD113 :	N/R
Derived CB2010 :	N/R

Map Id: E58
Direction: NW
Distance: 0.179 mi., 945 ft.
Elevation: 599 ft.
Relative: Higher

Site Name : ERNESTO RAYMUNDO
3520 HOLLENCREST RD
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 40542940
EPA ID: CAC003107027

ECHO ***(cont.)***

MYRTK Universe :	NNN
NPDES IDs :	N/R
CWA Permit Types :	N/R
CWA Compliance Tracking :	N/R
CWA NAICS :	N/R
CWA SICS :	N/R
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	N/R
CWA Current Compliance Status :	N/R
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	N/R
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	N/R
Facility NAICS :	56299 - All Other Waste Management Services
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	N/R
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	N
SDWIS Flag :	N
RCRA Flag :	Y
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	N/R
NAA Flag :	N
Latitude :	33.194075
Longitude :	-117.16177
Last Date in Agency List :	2021-04-16

FRS

Facility Name :	ERNESTO RAYMUNDO
Facility Address :	3520 HOLLENCREST RD, SAN MARCOS, CA 92069
County :	SAN DIEGO

Map Id: E58
Direction: NW
Distance: 0.179 mi., 945 ft.
Elevation: 599 ft.
Relative: Higher

Site Name : ERNESTO RAYMUNDO
3520 HOLLENCREST RD
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 40542940
EPA ID: CAC003107027

FRS ***(cont.)***

Site Details

Registry ID :	110071055227
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Source Description

Source Description :

RCRAInfo is EPA's comprehensive information system that supports the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984 through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA. RCRAInfo also supports generation of the National Hazardous Waste Biennial Report. All generators and treatment, storage, and disposal facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years to support creation of the Biennial Report.

FRS Environmental Interest

Source and System ID :	RCRAINFO - CAC003107027

HAZNET - CA

Facility Name :	ERNESTO RAYMUNDO
Facility Address :	3520 HOLLENCREST RD, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAC003107027
Active :	Active
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	3520 HOLLENCREST RD, SAN MARCOS, CA 92069
Latitude :	33.15415499
Longitude :	-117.19757499
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HWG - CA

Facility Name :	ERNESTO RAYMUNDO
Facility Address :	3520 HOLLENCREST RD, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAC003107027
Status :	Inactive
Category :	STATE

Map Id: E58
Direction: NW
Distance: 0.179 mi., 945 ft.
Elevation: 599 ft.
Relative: Higher

Site Name : ERNESTO RAYMUNDO
3520 HOLLENCREST RD
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 40542940
EPA ID: CAC003107027

HWG - CA ***(cont.)***

Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	3520 HOLLENCREST RD, SAN MARCOS, CA 92069
Owner Name :	ERNESTO RAYMUNDO
Owner Address :	3520 HOLLENCREST RD, SAN MARCOS, CA 92069
Operator Name :	ERNESTO RAYMUNDO
Operator Address :	3520 HOLLENCREST RD, SAN MARCOS, CA 92069
Latitude :	33.154155
Longitude :	-117.197575

MANIFEST EPA

Manifest Details

Manifest Number :	022170028JJK
Shipped Date :	2021-02-26
Updated Date :	2021-03-16
Received Date :	2021-03-04
Status :	Signed
Generator ID :	CAC003107027
Generator Name :	ERNESTO RAYMUNDO
Generator Address :	3520 HOLLENCREST RD, SAN MARCOS, CA 92069
Generator Mailing :	3520 HOLLENCREST RD, SAN MARCOS, CA 92069
Generator Contact :	N/R
Destination ID :	AZR000520882
Destination Name :	LA PAZ COUNTY LANDFILL
Destination Mailing :	26999 HIGHWAY 95, PARKER, AZ 85344
Destination Address :	26999 HIGHWAY 95, PARKER, AZ 85344
Destination Contact :	N/R
Submission Type :	DataImage5Copy
Origin Type :	Web
Manifest Residue :	N
Rejection :	N
Last Date in Agency List :	2022-01-14

Waste Details

Waste Line Number :	1
Is DOT Hazardous :	Y
DOT ID Number :	NA2212
DOT Information :	R.Q. NA2212, ASBESTOS, 9, PGIII
Non Waste Description :	N/R
Quantity :	1 Cubic Yards
Quantity Tons, Acute, Non-Acute :	0.84, 0, 0.84
Quantity Kg, Acute, Non-Acute :	0, 761.9052
Management Method :	H132 - LANDFILL (WITH PRIOR TREATMENT AND/OR STABILIZATION)
Is EPA Waste :	Y
Federal Code :	N/R
State Code :	CA - 151

RCRA_NONGEN

Facility Name :	ERNESTO RAYMUNDO
Facility Address :	3520 HOLLENCREST RD, SAN MARCOS, CA 92069
County :	SAN DIEGO

Map Id: E58
Direction: NW
Distance: 0.179 mi., 945 ft.
Elevation: 599 ft.
Relative: Higher

Site Name : ERNESTO RAYMUNDO
3520 HOLLENCREST RD
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 40542940
EPA ID: CAC003107027

RCRA_NONGEN ***(cont.)***

Date Form Received by Agency :	2021-02-23
EPA ID :	CAC003107027
Mailing Address :	3520 HOLLENCREST RD, SAN MARCOS, CA 92069
Contact :	ERNESTO RAYMUNDO
Contact Address :	3520 HOLLENCREST RD, SAN MARCOS, CA 92069
Contact Country :	N/R
Contact Telephone :	760-580-2688
Contact Email :	ERNIE13M@HOTMAIL.COM
EPA Region :	09
Land Type :	Not Reported
Source Type :	Implementer
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2022-01-26

Owner/Operator Summary

Owner/Operator Name :	ERNESTO RAYMUNDO
Owner/Operator Address :	3520 HOLLENCREST RD, SAN MARCOS, CA 92069
Owner/Operator Country :	N/R
Owner/Operator Telephone :	760-580-2688
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Owner/Operator Name :	ERNESTO RAYMUNDO
Owner/Operator Address :	3520 HOLLENCREST RD, SAN MARCOS, CA 92069
Owner/Operator Country :	N/R
Owner/Operator Telephone :	760-580-2688
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N/R
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N

Map Id: E58
Direction: NW
Distance: 0.179 mi., 945 ft.
Elevation: 599 ft.
Relative: Higher

Site Name : ERNESTO RAYMUNDO
3520 HOLLENCREST RD
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 40542940
EPA ID: CAC003107027

RCRA_NONGEN ***(cont.)***

Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Notices of Violations Summary

Regulation Violated :	N

Map Id: I59
Direction: SSE
Distance: 0.181 mi., 956 ft.
Elevation: 567 ft.
Relative: Lower

Site Name : BENCHMARK LANDSCAPE SERVICES INC
1/1/07 | Benchmark Landscape - San Marcos | BENCHMARK LANSCAPE INC
145 N PACIFIC ST
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, DEBRIS EPA SWRCY, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LF_SAN DIEGO COUNTY - CA, RCRA_NONGEN, SWF/LF - CA]

Envirosite ID: 480471
EPA ID: N/R

CALEPA SITES - CA

Facility Name :	BENCHMARK LANDSCAPE- SAN MARCOS
Facility Address :	145 N. PACIFIC ST., SAN MARCOS
Site ID :	507027
EI ID :	37-AA-0986
EI Description :	Solid Waste and Recycle Sites
Latitude :	33.147800
Longitude :	-117.192000
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07

Facility Name :	BENCHMARK LANSCAPE INC
Facility Address :	145 N PACIFIC ST, SAN MARCOS, 92069
Site ID :	98169
EI ID :	10376257
EI Description :	Hazardous Waste Generator
Latitude :	33.147823
Longitude :	-117.192055
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07

Map Id: I59
Direction: SSE
Distance: 0.181 mi., 956 ft.
Elevation: 567 ft.
Relative: Lower

Site Name : BENCHMARK LANDSCAPE SERVICES INC
1/1/07 | Benchmark Landscape - San Marcos | BENCHMARK LANSCAPE INC
145 N PACIFIC ST
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, DEBRIS EPA SWRCY, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LF_SAN DIEGO COUNTY - CA, RCRA_NONGEN, SWF/LF - CA] ***(cont.)***

Envirosite ID: 480471
EPA ID: N/R

CALEPA SITES - CA ***(cont.)***

Site ID :	98169
EI ID :	10376257
EI Description :	Chemical Storage Facilities
Latitude :	33.147823
Longitude :	-117.192055
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07

DEBRIS EPA SWRCY

Facility Name :	Benchmark Landscape - San Marcos
Facility Address :	145 N Pacific St, San Marcos, CA 92069
Phone :	858-513-7190
Region :	9
Recovery :	Yes
Landfill :	No
C D :	No
Composting :	No
Demolition :	No
Electronic :	No
HHW :	No
Metals :	No
Tires :	No
Transfer Station :	Yes
Vehicles :	No
LF C D :	No
LF HW :	No
LF MSW :	No
Latitude :	33.147828
Longitude :	-117.192051
Last Date in Agency List :	2022-02-02

ECHO

Facility Name :	BENCHMARK LANDSCAPE SERVICES INC 1/1/07
Facility Address :	145 N PACIFIC ST, SAN MARCOS, CA 92069
County :	SAN DIEGO
Last Inspection Date :	N/R
Registry ID :	110065045766
FIPS Code :	06073
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0

Map Id: I59
Direction: SSE
Distance: 0.181 mi., 956 ft.
Elevation: 567 ft.
Relative: Lower

Site Name : BENCHMARK LANDSCAPE SERVICES INC
1/1/07 | Benchmark Landscape - San Marcos | BENCHMARK LANSCAPE INC
145 N PACIFIC ST
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, DEBRIS EPA SWRCY, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LF_SAN DIEGO COUNTY - CA, RCRA_NONGEN, SWF/LF - CA] ***(cont.)***

Envirosite ID: 480471
EPA ID: N/R

ECHO ***(cont.)***

Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	_____
Collection Method :	ADDRESS MATCHING-HOUSE NUMBER
Reference Point :	CENTER OF A FACILITY OR STATION
Accuracy Meters :	30

Derived Tribes :

San Pasqual Band of Diegueno Mission Indians of California - 12.2 mile(s), Pala Band of Mission Indians - 13.2 mile (s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 13.9 mile(s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 16.1 mile(s), Pauma Band of Luiseno Mission Indians of the Pauma & Yuima Reservation, California - 16.9 mile(s), La Jolla Band of Luiseno Indians, California - 17 mile(s), Pechanga Band of Luiseno Mission Indians of the Pechanga Reservation, California - 20.5 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 22.4 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 22.7 mile(s), Mesa Grande Band of Diegueno Mission Indians of the Mesa Grande Reservation, California - 23 mile(s)

Derived HUC :	18070303
Derived WBD :	180703030503
Derived STCTY FIPS :	06073
Derived Zip :	92069
Derived CD113 :	50
Derived CB2010 :	060730200292003
MYRTK Universe :	NNN
NPDES IDs :	N/R
CWA Permit Types :	N/R
CWA Compliance Tracking :	N/R
CWA NAICS :	N/R
CWA SICS :	N/R
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	N/R
CWA Current Compliance Status :	N/R
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	N/R
CWA 13 Quarters Effluent Exceedances:	N/R

Map Id: I59
Direction: SSE
Distance: 0.181 mi., 956 ft.
Elevation: 567 ft.
Relative: Lower

Site Name : BENCHMARK LANDSCAPE SERVICES INC
1/1/07 | Benchmark Landscape - San Marcos | BENCHMARK LANSCAPE INC
145 N PACIFIC ST
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, DEBRIS EPA SWRCY, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LF_SAN DIEGO COUNTY - CA, RCRA_NONGEN, SWF/LF - CA] ***(cont.)***

Envirosite ID: 480471
EPA ID: N/R

ECHO ***(cont.)***

CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	N/R
Facility NAICS :	56173 - Landscaping Services
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	Y
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	N
SDWIS Flag :	N
RCRA Flag :	Y
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	Y
NAA Flag :	Y
Latitude :	33.14783
Longitude :	-117.19205
Last Date in Agency List :	2022-01-17

Facility Name :	BENCHMARK LANDSCAPE SERVICES INC 1/1/07
Facility Address :	145 N PACIFIC ST, SAN MARCOS, CA 92069-1222
County :	SAN DIEGO

Last Inspection Date :	N/R
Registry ID :	N/R
FIPS Code :	N/R
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R

Map Id: I59
Direction: SSE
Distance: 0.181 mi., 956 ft.
Elevation: 567 ft.
Relative: Lower

Site Name : BENCHMARK LANDSCAPE SERVICES INC
1/1/07 | Benchmark Landscape - San Marcos | BENCHMARK LANSCAPE INC
145 N PACIFIC ST
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, DEBRIS EPA SWRCY, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LF_SAN DIEGO COUNTY - CA, RCRA_NONGEN, SWF/LF - CA] ***(cont.)***

Envirosite ID: 480471
EPA ID: N/R

ECHO ***(cont.)***

Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	_____
Collection Method :	Zip Code Centroid
Reference Point :	N/R
Accuracy Meters :	10000
Derived Tribes :	N/R
Derived HUC :	N/R
Derived WBD :	N/R
Derived STCTY FIPS :	N/R
Derived Zip :	N/R
Derived CD113 :	N/R
Derived CB2010 :	N/R
MYRTK Universe :	NNN
NPDES IDs :	N/R
CWA Permit Types :	N/R
CWA Compliance Tracking :	N/R
CWA NAICS :	N/R
CWA SICS :	N/R
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	N/R
CWA Current Compliance Status :	N/R
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	N/R
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	N/R
Facility NAICS :	56173 - Landscaping Services
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R

Map Id: I59
Direction: SSE
Distance: 0.181 mi., 956 ft.
Elevation: 567 ft.
Relative: Lower

Site Name : BENCHMARK LANDSCAPE SERVICES INC 1/1/07 | Benchmark Landscape - San Marcos | BENCHMARK LANSCAPE INC
145 N PACIFIC ST
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, DEBRIS EPA SWRCY, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LF_SAN DIEGO COUNTY - CA, RCRA_NONGEN, SWF/LF - CA] ***(cont.)***

Envirosite ID: 480471
EPA ID: N/R

ECHO ***(cont.)***

US Mexico Border Flag :	N/R
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	N
SDWIS Flag :	N
RCRA Flag :	Y
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	Y
NAA Flag :	N/R
Latitude :	33.194075
Longitude :	-117.16177
Last Date in Agency List :	2019-07-15

FRS

Facility Name :	BENCHMARK LANDSCAPE SERVICES INC 1/1/07
Facility Address :	145 N PACIFIC ST, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Registry ID :	110065045766
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Source Description

Source Description :

The California Environmental Protection Agency (CalEPA) has recently implemented a new data warehouse system (nSite). This data warehouse combines and merges facility and site information from five different systems managed within CalEPA. The five systems are: California Environmental Reporting System (CERS), EnviroStor, GeoTracker, California Integrated Water Quality System (CIWQS), and Toxic Release Inventory (TRI).

Source Description :

RCRAInfo is EPA’s comprehensive information system that supports the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984 through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA. RCRAInfo also supports generation of the National Hazardous Waste Biennial Report. All generators and treatment, storage, and disposal facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years to support creation of the Biennial Report.

Map Id: I59
Direction: SSE
Distance: 0.181 mi., 956 ft.
Elevation: 567 ft.
Relative: Lower

Site Name : BENCHMARK LANDSCAPE SERVICES INC 1/1/07 | Benchmark Landscape - San Marcos | BENCHMARK LANSCAPE INC
145 N PACIFIC ST
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, DEBRIS EPA SWRCY, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LF_SAN DIEGO COUNTY - CA, RCRA_NONGEN, SWF/LF - CA] ***(cont.)***

Envirosite ID: 480471
EPA ID: N/R

FRS ***(cont.)***

FRS Environmental Interest

Source and System ID :	CA-ENVIROVIEW - 98169 RCRAINFO - CAL000319551

HAZMAT_SAN DIEGO COUNTY - CA

Facility Name :	BENCHMARK LANSCAPE INC
Facility Address :	145 N PACIFIC ST, SAN MARCOS, CA 92069
Date :	2007-07-19
Record ID :	DEH2007-HUPFP-208337
Record Type :	Unified Program Facility Permit
Status :	Permit Renewed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23

HAZNET - CA

Facility Name :	BENCHMARK LANDSCAPE SERVICES INC 1/1/07
Facility Address :	145 N PACIFIC ST, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000319551
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	12575 STOWE DR, POWAY, CA 920640000
Latitude :	33.14858371
Longitude :	-117.19380615
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Facility Name :	SIERRA SPRINGS WATER CO
Facility Address :	145 N PACIFIC ST, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAC002594244
Active :	Inactive

Map Id: I59
Direction: SSE
Distance: 0.181 mi., 956 ft.
Elevation: 567 ft.
Relative: Lower

Site Name : BENCHMARK LANDSCAPE SERVICES INC
1/1/07 | Benchmark Landscape - San Marcos | BENCHMARK LANSCAPE INC
145 N PACIFIC ST
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, DEBRIS EPA SWRCY, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LF_SAN DIEGO COUNTY - CA, RCRA_NONGEN, SWF/LF - CA] ***(cont.)***

Envirosite ID: 480471
EPA ID: N/R

HAZNET - CA ***(cont.)***

Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	2980 1ST ST STE N, LAVERNE, CA 91750
Latitude :	33.14858371
Longitude :	-117.19380615
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HWG - CA

Facility Name :	BENCHMARK LANDSCAPE SERVICES INC 1/1/07
Facility Address :	145 N PACIFIC ST, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAL000319551
Status :	Active
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	12575 STOWE DR, POWAY, CA 920640000
Owner Name :	BENCH MARK LANDSCAPE INC
Owner Address :	8177 SANTALUZ VILLAGE GREEN S, SAN DIEGO, CA 92127
Operator Name :	JOHN DEMOSS
Operator Address :	12575 STOWE DR, POWAY, CA 92064
Latitude :	33.148201
Longitude :	-117.194137
Facility Name :	SIERRA SPRINGS WATER CO
Facility Address :	145 N PACIFIC ST, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAC002594244
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	2980 1ST ST STE N, LAVERNE, CA 91750
Owner Name :	SIERRA SPRINGS WATER CO
Owner Address :	2980 1ST ST STE N, LAVERNE, CA 91750
Operator Name :	HARRY PETERSON
Operator Address :	2980 1ST ST STE N, LAVERNE, CA 91750
Latitude :	33.148584
Longitude :	-117.193934

Map Id: I59
Direction: SSE
Distance: 0.181 mi., 956 ft.
Elevation: 567 ft.
Relative: Lower

Site Name : BENCHMARK LANDSCAPE SERVICES INC 1/1/07 | Benchmark Landscape - San Marcos | BENCHMARK LANSCAPE INC
145 N PACIFIC ST
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, DEBRIS EPA SWRCY, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LF_SAN DIEGO COUNTY - CA, RCRA_NONGEN, SWF/LF - CA] ***(cont.)***

Envirosite ID: 480471
EPA ID: N/R

LF_SAN DIEGO COUNTY - CA

Facility Name :	Benchmark Landscape - San Marcos
Facility Address :	145 N. Pacific Street, San Marcos
Est Number :	DEH2013-CLEA-000178
SWIS Number :	37-AA-0986
Type of Operation :	Ltd Vol Transfer Op
Operation Status :	N/R
Inspection Frequency :	Semi-Ann
Activity Code :	N/R
Insp Code :	N/R
Permit Fees :	N/R
Owner :	N/R
Operator :	N/R
Permit Tier :	N/R
Latitude :	33.1478
Longitude :	-117.1919
Last Date in Agency List :	2022-02-04

RCRA_NONGEN

Facility Name :	BENCHMARK LANDSCAPE SERVICES INC 1/1/07
Facility Address :	145 N PACIFIC ST, SAN MARCOS, CA 92069-1222
County :	SAN DIEGO
Date Form Received by Agency :	2007-05-11
EPA ID :	CAL000319551
Mailing Address :	12575 STOWE DR, POWAY, CA 92064-0000
Contact :	JOHN DEMOSS
Contact Address :	12575 STOWE DR 92064, POWAY, CA 92064
Contact Country :	N/R
Contact Telephone :	858-513-7190
Contact Email :	JOHND@BENCHMARKLANDSCAPE.COM
EPA Region :	09
Land Type :	Not Reported
Source Type :	Implementer
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2022-01-26

Owner/Operator Summary

Owner/Operator Name :	JOHN DEMOSS
Owner/Operator Address :	12575 STOWE DR 92064, POWAY, CA 92064
Owner/Operator Country :	N/R
Owner/Operator Telephone :	858-513-7190
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R

Map Id: I59
Direction: SSE
Distance: 0.181 mi., 956 ft.
Elevation: 567 ft.
Relative: Lower

Site Name : BENCHMARK LANDSCAPE SERVICES INC
1/1/07 | Benchmark Landscape - San Marcos | BENCHMARK LANSCAPE INC
145 N PACIFIC ST
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, DEBRIS EPA SWRCY, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LF_SAN DIEGO COUNTY - CA, RCRA_NONGEN, SWF/LF - CA] ***(cont.)***

Envirosite ID: 480471
EPA ID: N/R

RCRA_NONGEN ***(cont.)***

Legal Status :	Other land type
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R
Owner/Operator Name :	JOHN MOHNS
Owner/Operator Address :	12575 STOWE DR, POWAY, CA 92064-0000
Owner/Operator Country :	N/R
Owner/Operator Telephone :	858-513-7190
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N
Recycler of Hazardous Waste :	Y
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	Y
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Notices of Violations Summary

Regulation Violated :	N

SWF/LF - CA

Facility Name :	Benchmark Landscape- San Marcos
Facility Address :	145 N. Pacific St., San Marcos
County :	San Diego

Map Id: I59
Direction: SSE
Distance: 0.181 mi., 956 ft.
Elevation: 567 ft.
Relative: Lower

Site Name : BENCHMARK LANDSCAPE SERVICES INC
1/1/07 | Benchmark Landscape - San Marcos | BENCHMARK LANSCAPE INC
145 N PACIFIC ST
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, DEBRIS EPA SWRCY, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LF_SAN DIEGO COUNTY - CA, RCRA_NONGEN, SWF/LF - CA] ***(cont.)***

Envirosite ID: 480471
EPA ID: N/R

SWF/LF - CA ***(cont.)***

Site Details

Permit Date :	N/R
Permit Status :	Notification
Swis Number :	37-AA-0986
Land Use :	N/R
Operator :	N/R
Operator Address :	N/R
Operator Phone :	N/R
Latitude :	33.1478
Longitude :	-117.1919
Last Date in Agency List :	2022-03-14

Owner Summary

Owner :	Benchmark Landscape LLC
Owner Address :	N/R
Owner Phone :	(858) 513-7190

Unit Information

Closure Date :	N/R
Closure Type :	N/R
Unit Number :	N/R
Regulatory Status :	Notification
Operational Status :	Active
Category :	Transfer/Processing
Activity :	Solid Waste Operation
Inspection Frequency :	Semi-annual
Accepted Waste :	N/R
Program Type :	N/R
Throughput :	1
Throughput Units :	Tons per day
Capacity :	600
Capacity Units :	Tons per year
Acreage :	1.2
Disposal Acreage :	N/R
Remaining Capacity :	N/R
WDR Number :	N/R

Map Id: I60
Direction: SSE
Distance: 0.182 mi., 960 ft.
Elevation: 567 ft.
Relative: Lower

Site Name : MEL'S AUTO REPAIR, LLC | K & D MACHINE | MEL'S AUTO REPAIRNA LLC 139 NORTH PACIFIC STE A1 | 139 N PACIFIC ST | 139 N PACIFIC ST, SUITE B SAN MARCOS, CA 92069

Database(s) : [CALEPA SITES - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN]

Envirosite ID: 279028
EPA ID: N/R

CALEPA SITES - CA

Facility Name :	MEL'S AUTO REPAIR, LLC
Facility Address :	139 N PACIFIC ST, SAN MARCOS, 92069
Site ID :	47908
EI ID :	10375861
EI Description :	Chemical Storage Facilities
Latitude :	33.148506
Longitude :	-117.193863
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-08-26

Site ID :	47908
EI ID :	10375861
EI Description :	Hazardous Waste Generator
Latitude :	33.148506
Longitude :	-117.193863
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-08-26

ECHO

Facility Name :	MEL'S AUTO REPAIR LLC
Facility Address :	139 NORTH PACIFIC STE A1, SAN MARCOS, CA 92069
County :	SAN DIEGO
Last Inspection Date :	N/R
Registry ID :	110070445059
FIPS Code :	N/R
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	_____
Collection Method :	Zip Code Centroid
Reference Point :	N/R
Accuracy Meters :	10000
Derived Tribes :	N/R
Derived HUC :	N/R

Map Id: I60
Direction: SSE
Distance: 0.182 mi., 960 ft.
Elevation: 567 ft.
Relative: Lower

Site Name : MEL'S AUTO REPAIR, LLC | K & D MACHINE | MEL'S AUTO REPAIRNA LLC 139 NORTH PACIFIC STE A1 | 139 N PACIFIC ST | 139 N PACIFIC ST, SUITE B SAN MARCOS, CA 92069

Database(s) : [CALEPA SITES - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 279028
EPA ID: N/R

ECHO ***(cont.)***

Derived WBD :	N/R
Derived STCTY FIPS :	N/R
Derived Zip :	N/R
Derived CD113 :	N/R
Derived CB2010 :	N/R
MYRTK Universe :	NNN
NPDES IDs :	N/R
CWA Permit Types :	N/R
CWA Compliance Tracking :	N/R
CWA NAICS :	N/R
CWA SICS :	N/R
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	N/R
CWA Current Compliance Status :	N/R
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	N/R
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	N/R
Facility NAICS :	811111 - General Automotive Repair
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	N/R
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	N
SDWIS Flag :	N
RCRA Flag :	Y
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	Y
NAA Flag :	N
Latitude :	33.194075

Map Id: I60
Direction: SSE
Distance: 0.182 mi., 960 ft.
Elevation: 567 ft.
Relative: Lower

Site Name : MEL'S AUTO REPAIR, LLC | K & D MACHINE | MEL'S AUTO REPAIRNA LLC 139 NORTH PACIFIC STE A1 | 139 N PACIFIC ST | 139 N PACIFIC ST, SUITE B SAN MARCOS, CA 92069

Database(s) : [CALEPA SITES - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 279028
EPA ID: N/R

ECHO ***(cont.)***

Longitude : -117.16177
Last Date in Agency List : 2022-01-17

FRS

Facility Name : JESUS ERNESTO VELASQUEZ & ROSA MARIA VELASQUEZ, INDIVDUALLY AND JOINTLY
Facility Address : 139 N. PACIFIC STREET, SAN MARCOS, CA 92069
County : N/R

Site Details
Registry ID : 110070286071
FRS Facility URL : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-02-17

Source Description
Source Description : OSHA-OIS

FRS Environmental Interest
Source and System ID : OSHA-OIS - 340564095

Facility Name : K & D MACHINE
Facility Address : 139 N PACIFIC ST, SAN MARCOS, CA 92069
County : SAN DIEGO

Site Details
Registry ID : 110065756989
FRS Facility URL : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-02-17

Source Description

Source Description :

The California Environmental Protection Agency (CalEPA) has recently implemented a new data warehouse system (nSite). This data warehouse combines and merges facility and site information from five different systems managed within CalEPA. The five systems are: California Environmental Reporting System (CERS), EnviroStor, GeoTracker, California Integrated Water Quality System (CIWQS), and Toxic Release Inventory (TRI).

Map Id: I60
Direction: SSE
Distance: 0.182 mi., 960 ft.
Elevation: 567 ft.
Relative: Lower

Site Name : MEL'S AUTO REPAIR, LLC | K & D MACHINE | MEL'S AUTO REPAIRNA LLC 139 NORTH PACIFIC STE A1 | 139 N PACIFIC ST | 139 N PACIFIC ST, SUITE B SAN MARCOS, CA 92069

Database(s) : [CALEPA SITES - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 279028
EPA ID: N/R

FRS ***(cont.)***

FRS Environmental Interest
Source and System ID : CA-ENVIROVIEW - 126989

Facility Name : MARCO VELASQUEZ-MEDINA
Facility Address : 139 N. PACIFIC STREET, SAN MARCOS, CA 92069
County : N/R

Site Details
Registry ID : 110070289390
FRS Facility URL : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-02-17

Source Description
Source Description : OSHA-OIS

FRS Environmental Interest
Source and System ID : OSHA-OIS - 340694215
OSHA-OIS - 341758001

Facility Name : MEL'S AUTO REPAIR LLC
Facility Address : 139 NORTH PACIFIC STE A1, SAN MARCOS, CA 92069-0000
County : SAN DIEGO

Site Details
Registry ID : 110070445059
FRS Facility URL : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-02-17

Source Description

Source Description :

RCRAInfo is EPA's comprehensive information system that supports the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984 through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA. RCRAInfo also supports generation of the National Hazardous Waste Biennial Report. All generators and treatment, storage, and disposal facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years to support creation of the Biennial Report.

Map Id: I60
Direction: SSE
Distance: 0.182 mi., 960 ft.
Elevation: 567 ft.
Relative: Lower

Site Name : MEL'S AUTO REPAIR, LLC | K & D MACHINE | MEL'S AUTO REPAIRNA LLC 139 NORTH PACIFIC STE A1 | 139 N PACIFIC ST | 139 N PACIFIC ST, SUITE B SAN MARCOS, CA 92069

Database(s) : [CALEPA SITES - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 279028
EPA ID: N/R

FRS ***(cont.)***

FRS Environmental Interest

Source and System ID :	RCRAINFO - CAL000063269
Facility Name :	MEL'S AUTO REPAIRNA LLC
Facility Address :	139 N PACIFIC ST, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Registry ID :	110066173241
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Source Description

Source Description :

The California Environmental Protection Agency (CalEPA) has recently implemented a new data warehouse system (nSite). This data warehouse combines and merges facility and site information from five different systems managed within CalEPA. The five systems are: California Environmental Reporting System (CERS), EnviroStor, GeoTracker, California Integrated Water Quality System (CIWQS), and Toxic Release Inventory (TRI).

FRS Environmental Interest

Source and System ID :	CA-ENVIROVIEW - 47908

HAZMAT_SAN DIEGO COUNTY - CA

Facility Name :	DAVID CABRERA
Facility Address :	139 N PACIFIC ST, SAN MARCOS, CA 92069
Date :	2011-02-07
Record ID :	DEH2011-HUPFP-213699
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23
Facility Name :	DT AUTOBODY
Facility Address :	139 N PACIFIC ST, SAN MARCOS, CA 92069

Map Id: I60
Direction: SSE
Distance: 0.182 mi., 960 ft.
Elevation: 567 ft.
Relative: Lower

Site Name : MEL'S AUTO REPAIR, LLC | K & D MACHINE | MEL'S AUTO REPAIRNA LLC 139 NORTH PACIFIC STE A1 | 139 N PACIFIC ST | 139 N PACIFIC ST, SUITE B SAN MARCOS, CA 92069

Database(s) : [CALEPA SITES - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 279028
EPA ID: N/R

HAZMAT_SAN DIEGO COUNTY - CA ***(cont.)***

Date :	2012-04-18
Record ID :	DEH2012-HUPFP-216339
Record Type :	Unified Program Facility Permit
Status :	Permit Suspended
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23
Facility Name :	K & D MACHINE
Facility Address :	139 N PACIFIC ST, SUITE B, SAN MARCOS, CA 92069
Date :	2012-08-23
Record ID :	DEH2012-HUPFP-216956
Record Type :	Unified Program Facility Permit
Status :	Permit Renewed
Action :	Pay Fees Due
Short Notes :	N/R
Last Date in Agency List :	2015-11-23

HAZNET - CA

Facility Name :	MEL'S AUTO REPAIR LLC
Facility Address :	139 NORTH PACIFIC STE A1, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000063269
Active :	Active
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	139 N PACIFIC ST STE A-1, SAN MARCOS, CA 920690000
Latitude :	33.14847710
Longitude :	-117.19386677
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HWG - CA

Facility Name :	MEL'S AUTO REPAIR LLC
Facility Address :	139 NORTH PACIFIC STE A1, SAN MARCOS, CA 92069
County :	SAN DIEGO

Map Id: I60
Direction: SSE
Distance: 0.182 mi., 960 ft.
Elevation: 567 ft.
Relative: Lower

Site Name : MEL'S AUTO REPAIR, LLC | K & D MACHINE | MEL'S AUTO REPAIRNA LLC 139 NORTH PACIFIC STE A1 | 139 N PACIFIC ST | 139 N PACIFIC ST, SUITE B SAN MARCOS, CA 92069

Database(s) : [CALEPA SITES - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 279028
EPA ID: N/R

HWG - CA ***(cont.)***

EPA ID :	CAL000063269
Status :	Active
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	139 N PACIFIC ST STE A-1, SAN MARCOS, CA 920690000
Owner Name :	MEL'S AUTO REPAIR LLC
Owner Address :	139 N PACIFIC ST STE A-1, SAN MARCOS, CA 920690000
Operator Name :	MEL MUZIO
Operator Address :	139 NORTH PACIFIC STE A1, SAN MARCOS, CA 92069
Latitude :	33.148041
Longitude :	-117.194088

MANIFEST EPA

Manifest Details

Manifest Number :	017707117JJK
Shipped Date :	2019-04-26
Updated Date :	2021-02-25
Received Date :	2019-05-08
Status :	Corrected
Generator ID :	CAL000063269
Generator Name :	MEL'S AUTO REPAIR LLC
Generator Address :	139 NORTH PACIFIC STE A1, SAN MARCOS, CA 92069
Generator Mailing :	139 N PACIFIC ST STE A-1, SAN MARCOS, CA 92069-0000
Generator Contact :	N/R
Destination ID :	CAD097030993
Destination Name :	US ECOLOGY VERNON INC
Destination Mailing :	5375 SOUTH BOYLE AVENUE CA90058 CA037US 5375, VERNON, CA 90058
Destination Address :	5375 SOUTH BOYLE AVENUE, LOS ANGELES, CA 90058-0000
Destination Contact :	N/R
Submission Type :	DataImage5Copy
Origin Type :	Service
Manifest Residue :	N
Rejection :	N
Last Date in Agency List :	2022-01-14

Waste Details

Waste Line Number :	1
Is DOT Hazardous :	N
DOT ID Number :	N/R
DOT Information :	N/R
Non Waste Description :	Non Hazardous Solid
Quantity :	100 Pounds
Quantity Tons, Acute, Non-Acute :	0.05, 0, 0.05
Quantity Kg, Acute, Non-Acute :	0, 45.3515
Management Method :	H141 - STORAGE, BULKING AND/OR TRANSFER OFF SITE
Is EPA Waste :	N

Map Id: I60
Direction: SSE
Distance: 0.182 mi., 960 ft.
Elevation: 567 ft.
Relative: Lower

Site Name : MEL'S AUTO REPAIR, LLC | K & D MACHINE | MEL'S AUTO REPAIRNA LLC 139 NORTH PACIFIC STE A1 | 139 N PACIFIC ST | 139 N PACIFIC ST, SUITE B SAN MARCOS, CA 92069

Database(s) : [CALEPA SITES - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 279028
EPA ID: N/R

MANIFEST EPA ***(cont.)***

Federal Code :	N/R
State Code :	CA - 352

RCRA_NONGEN

Facility Name :	MEL'S AUTO REPAIR LLC
Facility Address :	139 NORTH PACIFIC STE A1, SAN MARCOS, CA 92069-0000
County :	SAN DIEGO
Date Form Received by Agency :	1993-07-28
EPA ID :	CAL000063269
Mailing Address :	139 N PACIFIC ST STE A-1, SAN MARCOS, CA 92069-0000
Contact :	MEL MUZIO
Contact Address :	139 NORTH PACIFIC STE A1, SAN MARCOS, CA 92069
Contact Country :	N/R
Contact Telephone :	760-591-0311
Contact Email :	MJCAUTO@AOL.COM
EPA Region :	09
Land Type :	Not Reported
Source Type :	Implementer
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2022-01-26

Owner/Operator Summary

Owner/Operator Name :	MEL MUZIO
Owner/Operator Address :	139 NORTH PACIFIC STE A1, SAN MARCOS, CA 92069
Owner/Operator Country :	N/R
Owner/Operator Telephone :	760-591-0311
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Owner/Operator Name :	MEL'S AUTO REPAIR LLC
Owner/Operator Address :	139 N PACIFIC ST STE A-1, SAN MARCOS, CA 92069-0000
Owner/Operator Country :	N/R
Owner/Operator Telephone :	760-591-0311
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Map Id: I60
Direction: SSE
Distance: 0.182 mi., 960 ft.
Elevation: 567 ft.
Relative: Lower

Site Name : MEL'S AUTO REPAIR, LLC | K & D MACHINE | MEL'S AUTO REPAIRNA LLC
139 NORTH PACIFIC STE A1 | 139 N PACIFIC ST | 139 N PACIFIC ST, SUITE B
SAN MARCOS, CA 92069

Database(s) : [CALEPA SITES - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 279028
EPA ID: N/R

RCRA_NONGEN ***(cont.)***

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Notices of Violations Summary

Regulation Violated :	N

Map Id: I61
Direction: SSE
Distance: 0.182 mi., 962 ft.
Elevation: 567 ft.
Relative: Lower

Site Name : J J & S ASBESTOS REMOVAL , INC., DBA: J J & S CONSTRUCTION | NORTH COUNTY HYDRAULICS | JJ&S CONSTRUCTION
141 N PACIFIC ST STE D | 141 NORTH PACIFIC STREET, SUITE D | 143 N PACIFIC ST # K
SAN MARCOS, CA 92069

Database(s) : [CIWQS - CA, HAZNET - CA, HWG - CA, HWT - CA]

Envirosite ID: 764974
EPA ID: CAC002728375

CIWQS - CA

Facility Name :	CUTTING EDGE STONE LLC
Facility Address :	143 N PACIFIC ST # K, SAN MARCOS, CA 92069
County :	SAN DIEGO
Place ID :	S633338
Agency Name :	CUTTING EDGE STONE LLC
Last Date in Agency List :	2021-12-30

Map Id: I61
Direction: SSE
Distance: 0.182 mi., 962 ft.
Elevation: 567 ft.
Relative: Lower

Site Name : J J & S ASBESTOS REMOVAL , INC., DBA: J J & S CONSTRUCTION | NORTH COUNTY HYDRAULICS | JJ&S CONSTRUCTION
141 N PACIFIC ST STE D | 141 NORTH PACIFIC STREET, SUITE D | 143 N PACIFIC ST # K
SAN MARCOS, CA 92069

Database(s) : [CIWQS - CA, HAZNET - CA, HWG - CA, HWT - CA] ***(cont.)***

Envirosite ID: 764974
EPA ID: CAC002728375

HAZNET - CA

Facility Name : J J & S ASBESTOS REMOVAL , INC., DBA: J J & S CONSTRUCTION
Facility Address : 141 N PACIFIC ST STE D, SAN MARCOS, CA 92069
County : SAN DIEGO

Site Details
Generator EPA ID : CAL000389831
Active : Inactive
Category : STATE
Facility Types : N/R
Type : PERMANENT
Contact Name : N/R
Contact Phone : N/R
Facility Mailing Address : 141 N PACIFIC ST STE D, SAN MARCOS, CA 920691274
Latitude : 33.14851274
Longitude : -117.19384662
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2021-07-08

Generator EPA ID : CAC002728375
Active : Inactive
Category : STATE
Facility Types : N/R
Type : TEMPORARY
Contact Name : N/R
Contact Phone : N/R
Facility Mailing Address : 141 N PACIFIC ST STE D, SAN MARCOS, CA 920691274
Latitude : 33.14851264
Longitude : -117.19384656
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2021-07-08

Facility Name : NORTH COUNTY HYDRAULICS
Facility Address : 141 N PACIFIC ST STE D, SAN MARCOS, CA 92069
County : SAN DIEGO

Site Details
Generator EPA ID : CAL000289203
Active : Inactive
Category : STATE
Facility Types : N/R
Type : PERMANENT
Contact Name : N/R
Contact Phone : N/R
Facility Mailing Address : 141 N PACIFIC ST STE D, SAN MARCOS, CA 92069
Latitude : 33.14851264

Map Id: I61
Direction: SSE
Distance: 0.182 mi., 962 ft.
Elevation: 567 ft.
Relative: Lower

Site Name : J J & S ASBESTOS REMOVAL , INC., DBA: J J & S CONSTRUCTION | NORTH COUNTY HYDRAULICS | JJ&S CONSTRUCTION
141 N PACIFIC ST STE D | 141 NORTH PACIFIC STREET, SUITE D | 143 N PACIFIC ST # K
SAN MARCOS, CA 92069

Database(s) : [CIWQS - CA, HAZNET - CA, HWG - CA, HWT - CA] ***(cont.)***

Envirosite ID: 764974
EPA ID: CAC002728375

HAZNET - CA ***(cont.)***

Longitude :	-117.19384656
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HWG - CA

Facility Name :	J J & S ASBESTOS REMOVAL , INC., DBA: J J & S CONSTRUCTION
Facility Address :	141 N PACIFIC ST STE D, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAC002728375
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	141 N PACIFIC ST STE D, SAN MARCOS, CA 920691274
Owner Name :	JOSE ARAYA
Owner Address :	PO BOX 730, VISTA, CA 920850730
Operator Name :	EDUARDO D. GUELMAN
Operator Address :	141 N PACIFIC ST STE D, SAN MARCOS, CA 920691274
Latitude :	33.14801
Longitude :	-117.19257
EPA ID :	CAL000389831
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	141 N PACIFIC ST STE D, SAN MARCOS, CA 920691274
Owner Name :	J&J & S ASBESTOS REMOVAL INC
Owner Address :	17304 4S RANCH PKWY, SAN DIEGO, CA 92127
Operator Name :	EDUARDO GUELMAN/PRESIDENT
Operator Address :	141 N PACIFIC ST SUITE D, SAN MARCOS, CA 920690000
Latitude :	33.148513
Longitude :	-117.193847
Facility Name :	NORTH COUNTY HYDRAULICS
Facility Address :	141 N PACIFIC ST STE D, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAL000289203
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	141 N PACIFIC ST STE D, SAN MARCOS, CA 92069
Owner Name :	JUAN HINOJOSA

Map Id: I61
Direction: SSE
Distance: 0.182 mi., 962 ft.
Elevation: 567 ft.
Relative: Lower

Site Name : J J & S ASBESTOS REMOVAL , INC., DBA: J J & S CONSTRUCTION | NORTH COUNTY HYDRAULICS | JJ&S CONSTRUCTION
141 N PACIFIC ST STE D | 141 NORTH PACIFIC STREET, SUITE D | 143 N PACIFIC ST # K
SAN MARCOS, CA 92069

Database(s) : [CIWQS - CA, HAZNET - CA, HWG - CA, HWT - CA] ***(cont.)***

Envirosite ID: 764974
EPA ID: CAC002728375

HWG - CA ***(cont.)***

Owner Address :	742 AVENIDA CODORNIZ, SAN MARCOS, CA 92069
Operator Name :	JUAN HINOJOSA
Operator Address :	141 N PACIFIC ST STE D, SAN MARCOS, CA 92069
Latitude :	33.14812
Longitude :	-117.194178

HWT - CA

Facility Name :	JJ&S CONSTRUCTION
Facility Address :	141 NORTH PACIFIC STREET, SUITE D, SAN MARCOS, CA 92069
County :	SAN DIEGO
Expiration Date :	2016-10-31
Registration Number :	6292
Last Date in Agency List :	2017-05-11
Expiration Date :	2015-10-31
Registration Number :	6292
Last Date in Agency List :	2017-05-11
Expiration Date :	2014-09-30
Registration Number :	6292
Last Date in Agency List :	2017-05-11

Map Id: I62
Direction: SSE
Distance: 0.183 mi., 967 ft.
Elevation: 562 ft.
Relative: Lower

Site Name : NEILL WORKS LLC DBA MEL'S AUTO REPAIR | KB MOTORSPORTS INC | MEL'S AUTO REPAIR
139 N PACIFIC ST | 139 N PACIFIC ST STE A | 139 N PACIFIC ST STE A-1
SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, ECHO, FRS, HWG - CA]

Envirosite ID: 43270932
EPA ID: CAL000373985

CALEPA SITES - CA

Facility Name :	MEL'S AUTO REPAIR
Facility Address :	139 N PACIFIC ST STE A-1, SAN MARCOS, 92069
Site ID :	47908
EI ID :	10375861

Map Id: I62
Direction: SSE
Distance: 0.183 mi., 967 ft.
Elevation: 562 ft.
Relative: Lower

Site Name : NEILL WORKS LLC DBA MEL'S AUTO REPAIR | KB MOTORSPORTS INC | MEL'S AUTO REPAIR
139 N PACIFIC ST | 139 N PACIFIC ST STE A | 139 N PACIFIC ST STE A-1
SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, ECHO, FRS, HWG - CA] ***(cont.)***

Envirosite ID: 43270932
EPA ID: CAL000373985

CALEPA SITES - CA ***(cont.)***

EI Description :	Chemical Storage Facilities
Latitude :	33.148510
Longitude :	-117.193860
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07

Site ID :	47908
EI ID :	10375861
EI Description :	Hazardous Waste Generator
Latitude :	33.148510
Longitude :	-117.193860
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07

ECHO

Facility Name :	NEILL WORKS LLC DBA MEL'S AUTO REPAIR
Facility Address :	139 N PACIFIC ST, SAN MARCOS, CA 92069
County :	SAN DIEGO

Last Inspection Date :	N/R
Registry ID :	110071138040
FIPS Code :	N/R
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	_____
Collection Method :	Zip Code Centroid
Reference Point :	N/R
Accuracy Meters :	10000
Derived Tribes :	N/R
Derived HUC :	N/R
Derived WBD :	N/R
Derived STCTY FIPS :	N/R
Derived Zip :	N/R
Derived CD113 :	N/R
Derived CB2010 :	N/R
MYRTK Universe :	NNN
NPDES IDs :	N/R
CWA Permit Types :	N/R

Map Id: I62
Direction: SSE
Distance: 0.183 mi., 967 ft.
Elevation: 562 ft.
Relative: Lower

Site Name : NEILL WORKS LLC DBA MEL'S AUTO REPAIR | KB MOTORSPORTS INC | MEL'S AUTO REPAIR
139 N PACIFIC ST | 139 N PACIFIC ST STE A | 139 N PACIFIC ST STE A-1
SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, ECHO, FRS, HWG - CA] ***(cont.)***

Envirosite ID: 43270932
EPA ID: CAL000373985

ECHO ***(cont.)***

CWA Compliance Tracking :	N/R
CWA NAICS :	N/R
CWA SICS :	N/R
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	N/R
CWA Current Compliance Status :	N/R
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	N/R
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	N/R
Facility NAICS :	811111 - General Automotive Repair
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	N/R
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	N
SDWIS Flag :	N
RCRA Flag :	Y
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	N/R
NAA Flag :	N
Latitude :	33.194075
Longitude :	-117.16177
Last Date in Agency List :	2022-01-17

FRS

Facility Name :	NEILL WORKS LLC DBA MEL'S AUTO REPAIR
Facility Address :	139 N PACIFIC ST, SAN MARCOS, CA 92069
County :	SAN DIEGO

Map Id: I62
Direction: SSE
Distance: 0.183 mi., 967 ft.
Elevation: 562 ft.
Relative: Lower

Site Name : NEILL WORKS LLC DBA MEL'S AUTO REPAIR | KB MOTORSPORTS INC | MEL'S AUTO REPAIR
139 N PACIFIC ST | 139 N PACIFIC ST STE A | 139 N PACIFIC ST STE A-1
SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, ECHO, FRS, HWG - CA] ***(cont.)***

Envirosite ID: 43270932
EPA ID: CAL000373985

FRS ***(cont.)***

Site Details

Registry ID :	110071138040
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Source Description

Source Description :

RCRAInfo is EPA's comprehensive information system that supports the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984 through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA. RCRAInfo also supports generation of the National Hazardous Waste Biennial Report. All generators and treatment, storage, and disposal facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years to support creation of the Biennial Report.

FRS Environmental Interest

Source and System ID :	RCRAINFO - CAL000464025

HWG - CA

Facility Name :	DT AUTOBODY
Facility Address :	139 N PACIFIC ST STE D, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAL000373985
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	213 WESTLAKE DR UNIT 3, SAN MARCOS, CA 920693704
Owner Name :	DAVID TAN
Owner Address :	213 WESTLAKE DR UNIT 3, SAN MARCOS, CA 920693704
Operator Name :	DAVID TAN
Operator Address :	213 WESTLAKE DR UNIT 3, SAN MARCOS, CA 92069
Latitude :	33.148552
Longitude :	-117.193821

Facility Name :	KB MOTORSPORTS INC
Facility Address :	139 N PACIFIC ST STE A, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAL000187872
Status :	Inactive

Map Id: I62
Direction: SSE
Distance: 0.183 mi., 967 ft.
Elevation: 562 ft.
Relative: Lower

Site Name : NEILL WORKS LLC DBA MEL'S AUTO REPAIR | KB MOTORSPORTS INC | MEL'S AUTO REPAIR
139 N PACIFIC ST | 139 N PACIFIC ST STE A | 139 N PACIFIC ST STE A-1
SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, ECHO, FRS, HWG - CA] ***(cont.)***

Envirosite ID: 43270932
EPA ID: CAL000373985

HWG - CA ***(cont.)***

Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	225 S PACIFIC ST, SAN MARCOS, CA 920782429
Owner Name :	KIP BUSSE
Owner Address :	139 N PACIFIC ST STE A, SAN MARCOS, CA 920690000
Operator Name :	KIP BUSSE
Operator Address :	225 S PACIFIC ST, SAN MARCOS, CA 920782429
Latitude :	33.14852
Longitude :	-117.19393

Facility Name :	K&D MACHINE
Facility Address :	139 N PACIFIC ST STE B, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAL000377771
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	139 N PACIFIC ST STE B, SAN MARCOS, CA 920690000
Owner Name :	DAVID FORGE
Owner Address :	139 N PACIFIC ST STE B, SAN MARCOS, CA 920690000
Operator Name :	DAVID FORGE
Operator Address :	139 N PACIFIC ST STE B, SAN MARCOS, CA 920690000
Latitude :	33.148552
Longitude :	-117.193821

Facility Name :	MELS AUTO REPAIR
Facility Address :	139 N PACIFIC STREET, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAL912323495
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	139 N PACIFIC ST STE A-1, SAN MARCOS, CA 920691273
Owner Name :	MEL MUZIO
Owner Address :	139 N PACIFIC ST STE A-1, SAN MARCOS, CA 920691273
Operator Name :	N/R
Operator Address :	INACTIVE PER VQ99 - BMI, N/A
Latitude :	33.149036
Longitude :	-117.193691

Facility Name :	NEILL WORKS LLC DBA MEL'S AUTO REPAIR
Facility Address :	139 N PACIFIC ST, SAN MARCOS, CA 92069
County :	SAN DIEGO

Map Id: I62
Direction: SSE
Distance: 0.183 mi., 967 ft.
Elevation: 562 ft.
Relative: Lower

Site Name : NEILL WORKS LLC DBA MEL'S AUTO REPAIR | KB MOTORSPORTS INC | MEL'S AUTO REPAIR
139 N PACIFIC ST | 139 N PACIFIC ST STE A | 139 N PACIFIC ST STE A-1
SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, ECHO, FRS, HWG - CA] ***(cont.)***

Envirosite ID: 43270932
EPA ID: CAL000373985

HWG - CA ***(cont.)***

EPA ID :	CAL000464025
Status :	Active
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	578 ROBIN HILL LN, ESCONDIDO, CA 92026
Owner Name :	NEILL WORKS LLC
Owner Address :	578 ROBIN HILL LN, ESCONDIDO, CA 92026
Operator Name :	BRENDON NEILL
Operator Address :	578 ROBIN HILL LN, ESCONDIDO, CA 92026
Latitude :	33.148488
Longitude :	-117.193858

Facility Name :	PACIFIC MACHINING
Facility Address :	139 N PACIFIC ST STE G, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAD115337461
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	139 N PACIFIC ST STE G, SAN MARCOS, CA 920690000
Owner Name :	N/R
Owner Address :	N/A
Operator Name :	UNDELIVERABLE SURVEY 1-14-95LC
Operator Address :	LC, N/A
Latitude :	33.149036
Longitude :	-117.193691

Facility Name :	S & S ENTERPRISES
Facility Address :	139 N Pacific St, San Marcos, CA 92069
County :	SAN DIEGO

EPA ID :	CAL000050269
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	139 NORTH PACIFIC STREET, SAN MARCOS, CA 000000000
Owner Name :	N/R
Owner Address :	N/A
Operator Name :	DEACT NON-DELIV. PER 95 FEES -
Operator Address :	P.H., N/A
Latitude :	33.148532
Longitude :	-117.193962

Map Id: I63
Direction: SSE
Distance: 0.183 mi., 968 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : ARENDSE MOTORSPORTS | BULTER MACHINING & DESIGN INC | REBEL FABRICATION
137 N PACIFIC ST | 137 N PACIFIC ST STE E
SAN MARCOS, CA 92069

Database(s) : [HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA]

Envirosite ID: 280008
EPA ID: N/R

HAZMAT_SAN DIEGO COUNTY - CA

Facility Name : BULTER MACHINING & DESIGN INC
Facility Address : 137 N PACIFIC ST, SAN MARCOS, CA 92069

Date : 2005-03-14
Record ID : DEH2005-HUPFP-205032
Record Type : Unified Program Facility Permit
Status : Completed
Action : N/R
Short Notes : N/R
Last Date in Agency List : 2015-11-23

Facility Name : REBEL FABRICATION
Facility Address : 137 N PACIFIC ST, SAN MARCOS, CA 92069

Date : 2003-03-12
Record ID : DEH2003-HUPFP-201513
Record Type : Unified Program Facility Permit
Status : Completed
Action : N/R
Short Notes : N/R
Last Date in Agency List : 2015-11-23

Facility Name : TMS MACHINING
Facility Address : 137 N PACIFIC ST, SAN MARCOS, CA 92069

Date : 2011-01-21
Record ID : DEH2011-HUPFP-213581
Record Type : Unified Program Facility Permit
Status : Completed
Action : N/R
Short Notes : N/R
Last Date in Agency List : 2015-11-23

HAZNET - CA

Facility Name : ARENDSE MOTORSPORTS
Facility Address : 137 N PACIFIC ST STE E, SAN MARCOS, CA 92069
County : SAN DIEGO

Site Details
Generator EPA ID : CAL000394961
Active : Inactive
Category : STATE
Facility Types : N/R
Type : PERMANENT

Map Id: I63
Direction: SSE
Distance: 0.183 mi., 968 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : ARENDSE MOTORSPORTS | BULTER MACHINING & DESIGN INC | REBEL FABRICATION
137 N PACIFIC ST | 137 N PACIFIC ST STE E
SAN MARCOS, CA 92069

Database(s) : [HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 280008
EPA ID: N/R

HAZNET - CA ***(cont.)***

Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	137 N PACIFIC ST STE E, SAN MARCOS, CA 920690000
Latitude :	33.14844164
Longitude :	-117.19388705
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HWG - CA

Facility Name :	ARENDSE MOTORSPORTS
Facility Address :	137 N PACIFIC ST STE E, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAL000394961
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	137 N PACIFIC ST STE E, SAN MARCOS, CA 920690000
Owner Name :	ADRIAN ARENDSE
Owner Address :	137 N PACIFIC ST STE E, SAN MARCOS, CA 920690000
Operator Name :	ADRIAN ARENDSE
Operator Address :	137 N PACIFIC ST STE E, SAN MARCOS, CA 920690000
Latitude :	33.148442
Longitude :	-117.193887

Map Id: I64
Direction: SSE
Distance: 0.184 mi., 974 ft.
Elevation: 567 ft.
Relative: Lower

Site Name : AVISTA TECHNOLOGIES | TRI-CITY COMPETITION
133 N PACIFIC ST
SAN MARCOS, CA 92069

Database(s) : [HAZMAT_SAN DIEGO COUNTY - CA]

Envirosite ID: 637869
EPA ID: N/R

HAZMAT_SAN DIEGO COUNTY - CA

Facility Name :	AVISTA TECHNOLOGIES
Facility Address :	133 N PACIFIC ST, SAN MARCOS, CA 92069
Date :	2002-05-04
Record ID :	DEH2002-HUPFP-105738
Record Type :	Unified Program Facility Permit
Status :	Completed

Map Id: I64
Direction: SSE
Distance: 0.184 mi., 974 ft.
Elevation: 567 ft.
Relative: Lower

Site Name : AVISTA TECHNOLOGIES | TRI-CITY COMPETITION
133 N PACIFIC ST
SAN MARCOS, CA 92069

Database(s) : [HAZMAT_SAN DIEGO COUNTY - CA] ***(cont.)***

Envirosite ID: 637869
EPA ID: N/R

HAZMAT_SAN DIEGO COUNTY - CA ***(cont.)***

Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23
Facility Name :	TRI-CITY COMPETITION
Facility Address :	133 N PACIFIC ST, SAN MARCOS, CA 92069
Date :	2002-05-04
Record ID :	DEH2002-HUPFP-128907
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23

Map Id: I65
Direction: SSE
Distance: 0.184 mi., 974 ft.
Elevation: 567 ft.
Relative: Lower

Site Name : ANTUAN KASSABRY EUROPEAN WOODWORKS
137 PACIFIC ST
SAN MARCOS, CA 92069

Database(s) : [HAZMAT_SAN DIEGO COUNTY - CA]

Envirosite ID: 629180
EPA ID: N/R

HAZMAT_SAN DIEGO COUNTY - CA

Facility Name :	ANTUAN KASSABRY EUROPEAN WOODWORKS
Facility Address :	137 PACIFIC ST, SAN MARCOS, CA 92069
Date :	2010-08-03
Record ID :	DEH2010-HUPFP-212450
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23

Map Id: F66
Direction: ESE
Distance: 0.186 mi., 985 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : PEACOCK CLEANERS
1450 MISSION RD | 1450 MISSION RD
STE S | 1450 Mision Road West #S
SAN MARCOS | San Marcos, CA 92069

Database(s) : [DRYCLEANERS - CA, ECHO, FRS, HAZNET - CA, HWG - CA, RCRA_NONGEN]

Envirosite ID: 343274
EPA ID: CAL000334565

DRYCLEANERS - CA

Property Name :	Peacock Cleaners

ECHO

Facility Name :	PEACOCK CLEANERS
Facility Address :	1450 MISSION RD, SAN MARCOS, CA 92069
County :	SAN DIEGO
Last Inspection Date :	N/R
Registry ID :	110070471273
FIPS Code :	N/R
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	_____
Collection Method :	Zip Code Centroid
Reference Point :	N/R
Accuracy Meters :	10000
Derived Tribes :	N/R
Derived HUC :	N/R
Derived WBD :	N/R
Derived STCTY FIPS :	N/R
Derived Zip :	N/R
Derived CD113 :	N/R
Derived CB2010 :	N/R
MYRTK Universe :	NNN
NPDES IDs :	N/R
CWA Permit Types :	N/R
CWA Compliance Tracking :	N/R
CWA NAICS :	N/R
CWA SICS :	N/R
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	N/R
CWA Current Compliance Status :	N/R
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	N/R

Map Id: F66
Direction: ESE
Distance: 0.186 mi., 985 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : PEACOCK CLEANERS
1450 MISSION RD | 1450 MISSION RD
STE S | 1450 Mision Road West #S
SAN MARCOS | San Marcos, CA 92069

Database(s) : [DRYCLEANERS - CA, ECHO, FRS, HAZNET - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 343274
EPA ID: CAL000334565

ECHO ***(cont.)***

CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	N/R
Facility NAICS :	81232 - Drycleaning and Laundry Services (except Coin-Operated)
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	N/R
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	N
SDWIS Flag :	N
RCRA Flag :	Y
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	Y
NAA Flag :	N
Latitude :	33.194075
Longitude :	-117.16177
Last Date in Agency List :	2022-01-17

FRS

Facility Name :	PEACOCK CLEANERS
Facility Address :	1450 MISSION RD, SAN MARCOS, CA 92069-0000
County :	SAN DIEGO

Site Details

Registry ID :	110070471273
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Source Description

Map Id: F66
Direction: ESE
Distance: 0.186 mi., 985 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : PEACOCK CLEANERS
1450 MISSION RD | 1450 MISSION RD
STE S | 1450 Mision Road West #S
SAN MARCOS | San Marcos, CA 92069

Database(s) : [DRYCLEANERS - CA, ECHO, FRS, HAZNET - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 343274
EPA ID: CAL000334565

FRS ***(cont.)***

Source Description :

RCRAInfo is EPA's comprehensive information system that supports the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984 through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA. RCRAInfo also supports generation of the National Hazardous Waste Biennial Report. All generators and treatment, storage, and disposal facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years to support creation of the Biennial Report.

FRS Environmental Interest

Source and System ID :	RCRAINFO - CAL000334565

HAZNET - CA

Facility Name :	PEACOCK CLEANERS
Facility Address :	1450 MISSION RD, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000334565
Active :	Active
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	1450 W MISSION RD STE S, SAN MARCOS, CA 920690000
Latitude :	33.15039213
Longitude :	-117.19163902
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :

2018: 741 - Liquids with halogenated organic compounds >= 1,000 Mg. /L, 0.07500 tons to NED981723513
2016: 741 - Liquids with halogenated organic compounds >= 1,000 Mg. /L, 0.165 tons to NED981723513
2015: 741 - Liquids with halogenated organic compounds >= 1,000 Mg. /L, 0.1 tons to NED981723513
2014: 741 - Liquids with halogenated organic compounds >= 1,000 Mg. /L, 0.1 tons to TXD077603371
2014: 741 - Liquids with halogenated organic compounds >= 1,000 Mg. /L, 0.1 tons to NED981723513
2013: 741 - Liquids with halogenated organic compounds >= 1,000 Mg. /L, 0.125 tons to TXD077603371
2012: 741 - Liquids with halogenated organic compounds >= 1,000 Mg. /L, 0.125 tons to TXD077603371

Map Id: F66
Direction: ESE
Distance: 0.186 mi., 985 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : PEACOCK CLEANERS
1450 MISSION RD | 1450 MISSION RD
STE S | 1450 Mision Road West #S
SAN MARCOS | San Marcos, CA 92069

Database(s) : [DRYCLEANERS - CA, ECHO, FRS, HAZNET - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 343274
EPA ID: CAL000334565

HAZNET - CA ***(cont.)***

2011: 741 - Liquids with halogenated organic compounds >= 1,000 Mg. /L, 0.15 tons to TXD077603371
2010: 741 - Liquids with halogenated organic compounds >= 1,000 Mg. /L, 0.325 tons to TXD077603371
2009: 741 - Liquids with halogenated organic compounds >= 1,000 Mg. /L, 0.3 tons to TXD077603371
2008: 741 - Liquids with halogenated organic compounds >= 1,000 Mg. /L, 0.3 tons to OHD980587364

Facility Name : PEACOCK CLEANERS
Facility Address : 1450 MISSION RD STE S, SAN MARCOS, CA 92069
County : SAN DIEGO

Site Details
Generator EPA ID : CAL000139035
Active : Inactive
Category : STATE
Facility Types : N/R
Type : PERMANENT
Contact Name : N/R
Contact Phone : N/R
Facility Mailing Address : 1450 W MISSION RD STE S, SAN MARCOS, CA 920690000
Latitude : 33.15039213
Longitude : -117.19163902
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2021-07-08

Waste Generator Details
State Waste :

2002: 741 - Liquids with halogenated organic compounds >= 1,000 Mg. /L, 0.115 tons to CAT000613893
2001: 741 - Liquids with halogenated organic compounds >= 1,000 Mg. /L, 0.195 tons to CAT000613976
1999: 741 - Liquids with halogenated organic compounds >= 1,000 Mg. /L, 0.1275 tons to CAT000613976
1998: 741 - Liquids with halogenated organic compounds >= 1,000 Mg. /L, 0.195 tons to CAT000613976
1997: 741 - Liquids with halogenated organic compounds >= 1,000 Mg. /L, 0.1575 tons to CAT000613976
1995: 741 - Liquids with halogenated organic compounds >= 1,000 Mg. /L, 0.1575 tons to CAT000613976

HWG - CA

Facility Name : PEACOCK CLEANERS
Facility Address : 1450 MISSION RD, SAN MARCOS, CA 92069
County : SAN DIEGO

EPA ID : CAL000334565
Status : Active

Map Id: F66
Direction: ESE
Distance: 0.186 mi., 985 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : PEACOCK CLEANERS
1450 MISSION RD | 1450 MISSION RD
STE S | 1450 Mision Road West #S
SAN MARCOS | San Marcos, CA 92069

Database(s) : [DRYCLEANERS - CA, ECHO, FRS, HAZNET - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 343274
EPA ID: CAL000334565

HWG - CA ***(cont.)***

Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	1450 W MISSION RD STE S, SAN MARCOS, CA 920690000
Owner Name :	HOON YOUNG JUNG
Owner Address :	1219 MCGEARY RD, ESCONDIDO, CA 920260000
Operator Name :	HOON YOUNG JUNG
Operator Address :	1219 MCGEARY RD, ESCONDIDO, CA 92026
Latitude :	33.134611
Longitude :	-117.128433

Facility Name :	PEACOCK CLEANERS
Facility Address :	1450 MISSION RD STE S, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAL000139035
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	1450 W MISSION RD STE S, SAN MARCOS, CA 920690000
Owner Name :	YUN SONG CHOE
Owner Address :	1450 W MISSION RD STE S, SAN MARCOS, CA 920690000
Operator Name :	YUN SONG CHOE-OWNER
Operator Address :	1450 W MISSION RD STE S, SAN MARCOS, CA 920690000
Latitude :	33.134611
Longitude :	-117.128433

RCRA_NONGEN

Facility Name :	PEACOCK CLEANERS
Facility Address :	1450 MISSION RD, SAN MARCOS, CA 92069-0000
County :	SAN DIEGO

Date Form Received by Agency :	2008-07-16
EPA ID :	CAL000334565
Mailing Address :	1450 MISSION RD STE S SUITE # S, SAN MARCOS, CA 92069-0000
Contact :	HOON YOUNG JUNG
Contact Address :	1450 MISSION RD STE S, SAN MARCOS, CA 92069
Contact Country :	N/R
Contact Telephone :	760-598-7237
Contact Email :	HJAPPA@GMAIL.COM
EPA Region :	09
Land Type :	Not Reported
Source Type :	Implementer
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2022-01-26

Map Id: F66
Direction: ESE
Distance: 0.186 mi., 985 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : PEACOCK CLEANERS
1450 MISSION RD | 1450 MISSION RD
STE S | 1450 Mision Road West #S
SAN MARCOS | San Marcos, CA 92069

Database(s) : [DRYCLEANERS - CA, ECHO, FRS, HAZNET - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 343274
EPA ID: CAL000334565

RCRA_NONGEN ***(cont.)***

Owner/Operator Summary

Owner/Operator Name :	HOON YOUNG JUNG
Owner/Operator Address :	1450 MISSION RD STE S, SAN MARCOS, CA 92069
Owner/Operator Country :	N/R
Owner/Operator Telephone :	760-598-7237
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Owner/Operator Name :	HOON YOUNG JUNG
Owner/Operator Address :	1450 MISSION RD SUITE # S, SAN MARCOS, CA 92069-0000
Owner/Operator Country :	N/R
Owner/Operator Telephone :	858-922-8335
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Notices of Violations Summary

Regulation Violated :	N

Map Id: I67
Direction: SSE
Distance: 0.187 mi., 987 ft.
Elevation: 567 ft.
Relative: Lower

Site Name : ADVANCED ENGINEERING SOLUTIONS | METAL ARTS | TOM MAXWELL ENTERPRISES
135 N PACIFIC ST
SAN MARCOS, CA 92069
Database(s) : [HAZMAT_SAN DIEGO COUNTY - CA]

Envirosite ID: 630296
EPA ID: N/R

HAZMAT_SAN DIEGO COUNTY - CA

Facility Name :	ADVANCED ENGINEERING SOLUTIONS
Facility Address :	135 N PACIFIC ST, SAN MARCOS, CA 92069
Date :	2008-07-30
Record ID :	DEH2008-HUPFP-209569
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23
Facility Name :	METAL ARTS
Facility Address :	135 N PACIFIC ST, SAN MARCOS, CA 92069
Date :	2002-05-04
Record ID :	DEH2002-HUPFP-128908
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23
Facility Name :	TOM MAXWELL ENTERPRISES
Facility Address :	135 N PACIFIC ST, SAN MARCOS, CA 92069
Date :	2002-05-04
Record ID :	DEH2002-HUPFP-137039
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23

Map Id: 68
Direction: ENE
Distance: 0.188 mi., 995 ft.
Elevation: 587 ft.
Relative: Lower

Site Name : SCOTT SAALFELD
441 SILVER SPUR WAY
SAN MARCOS, CA 92069
Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 768083
EPA ID: CAC002844702

HAZNET - CA

Facility Name :	SCOTT SAALFELD
Facility Address :	441 SILVER SPUR WAY, SAN MARCOS, CA 92069

Map Id: 68
Direction: ENE
Distance: 0.188 mi., 995 ft.
Elevation: 587 ft.
Relative: Lower

Site Name : SCOTT SAALFELD
441 SILVER SPUR WAY
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 768083
EPA ID: CAC002844702

HAZNET - CA ***(cont.)***

County : SAN DIEGO

Site Details

Generator EPA ID :	CAC002844702
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	441 SILVER SPUR WAY, SAN MARCOS, CA 92069
Latitude :	33.15253178
Longitude :	-117.19190139
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste : 2016: 151 - Asbestos containing waste, 0.23 tons to CAD009007626

HWG - CA

Facility Name :	SCOTT SAALFELD
Facility Address :	441 SILVER SPUR WAY, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAC002844702
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	441 SILVER SPUR WAY, SAN MARCOS, CA 92069
Owner Name :	SCOTT SAALFELD
Owner Address :	441 SILVER SPUR WAY, SAN MARCOS, CA 92069
Operator Name :	SCOTT SAALFELD
Operator Address :	441 SILVER SPUR WAY, SAN MARCOS, CA 92069
Latitude :	33.152532
Longitude :	-117.191901

Map Id: I69
Direction: SSE
Distance: 0.192 mi., 1015 ft.
Elevation: 565 ft.
Relative: Lower

Site Name : NEILL WORKS LLC DBA MEL'S AUTO REPAIR | MONY'S AUTO REPAIR | MANNING MOTOR SPORT PERFORMANCE
139 N PACIFIC ST | 139 N PACIFIC ST #A | 139 NORTH PACIFIC ST #D
SAN MARCOS | San Marcos, CA 92069

Database(s) : [ECHO, HAZNET - CA, HWG - CA, RCRA_NONGEN]

Envirosite ID: 41012887
EPA ID: CAL000373985

ECHO

Facility Name :	NEILL WORKS LLC DBA MEL'S AUTO REPAIR
Facility Address :	139 N PACIFIC ST, SAN MARCOS, CA 92069
County :	SAN DIEGO
Last Inspection Date :	N/R
Registry ID :	N/R
FIPS Code :	N/R
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	_____
Collection Method :	Zip Code Centroid
Reference Point :	N/R
Accuracy Meters :	10000
Derived Tribes :	N/R
Derived HUC :	N/R
Derived WBD :	N/R
Derived STCTY FIPS :	N/R
Derived Zip :	N/R
Derived CD113 :	N/R
Derived CB2010 :	N/R
MYRTK Universe :	NNN
NPDES IDs :	N/R
CWA Permit Types :	N/R
CWA Compliance Tracking :	N/R
CWA NAICS :	N/R
CWA SICS :	N/R
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	N/R
CWA Current Compliance Status :	N/R
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	N/R
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R

Map Id: I69
Direction: SSE
Distance: 0.192 mi., 1015 ft.
Elevation: 565 ft.
Relative: Lower

Site Name : NEILL WORKS LLC DBA MEL'S AUTO REPAIR | MONY'S AUTO REPAIR | MANNING MOTOR SPORT PERFORMANCE
139 N PACIFIC ST | 139 N PACIFIC ST #A | 139 NORTH PACIFIC ST #D
SAN MARCOS | San Marcos, CA 92069

Database(s) : [ECHO, HAZNET - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 41012887
EPA ID: CAL000373985

ECHO ***(cont.)***

DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	N/R
Facility NAICS :	811111 - General Automotive Repair
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	N/R
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	N
SDWIS Flag :	N
RCRA Flag :	Y
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	N/R
NAA Flag :	N
Latitude :	33.194075
Longitude :	-117.16177
Last Date in Agency List :	2021-10-15

HAZNET - CA

Facility Name :	DT AUTOBODY
Facility Address :	139 N PACIFIC ST STE D, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000373985
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	213 WESTLAKE DR UNIT 3, SAN MARCOS, CA 920693704
Latitude :	33.14847719
Longitude :	-117.19386683
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Map Id: I69
Direction: SSE
Distance: 0.192 mi., 1015 ft.
Elevation: 565 ft.
Relative: Lower

Site Name : NEILL WORKS LLC DBA MEL'S AUTO REPAIR | MONY'S AUTO REPAIR | MANNING MOTOR SPORT PERFORMANCE
139 N PACIFIC ST | 139 N PACIFIC ST #A | 139 NORTH PACIFIC ST #D
SAN MARCOS | San Marcos, CA 92069

Database(s) : [ECHO, HAZNET - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 41012887
EPA ID: CAL000373985

HAZNET - CA ***(cont.)***

Facility Name : KB MOTORSPORTS INC
Facility Address : 139 N PACIFIC ST STE A, SAN MARCOS, CA 92069
County : SAN DIEGO

Site Details
Generator EPA ID : CAL000187872
Active : Inactive
Category : STATE
Facility Types : N/R
Type : PERMANENT
Contact Name : N/R
Contact Phone : N/R
Facility Mailing Address : 225 S PACIFIC ST, SAN MARCOS, CA 920782429
Latitude : 33.14847710
Longitude : -117.19386677
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2021-07-08

Waste Generator Details
State Waste : 2003: 741 - Liquids with halogenated organic compounds >= 1,000 Mg. /L, 0.05004 tons to CAD008252405
2003: 352 - Other organic solids, 0.05 tons to IND000646943
1999: 133 - Aqueous solution with total organic residues 10 percent or more, 0.2085 tons to CAT080013352
1998: 221 - Waste oil and mixed oil, 0.418 tons to CAD099452708
1997: 133 - Aqueous solution with total organic residues 10 percent or more, 0.2085 tons to CAT080013352
1995: 133 - Aqueous solution with total organic residues 10 percent or more, 0.2085 tons to CAT080013352

Facility Name : K&D MACHINE
Facility Address : 139 N PACIFIC ST STE B, SAN MARCOS, CA 92069
County : SAN DIEGO

Site Details
Generator EPA ID : CAL000377771
Active : Inactive
Category : STATE
Facility Types : N/R
Type : PERMANENT
Contact Name : N/R
Contact Phone : N/R
Facility Mailing Address : 139 N PACIFIC ST STE B, SAN MARCOS, CA 920690000
Latitude : 33.14847719
Longitude : -117.19386683

Map Id: I69
Direction: SSE
Distance: 0.192 mi., 1015 ft.
Elevation: 565 ft.
Relative: Lower

Site Name : NEILL WORKS LLC DBA MEL'S AUTO REPAIR | MONY'S AUTO REPAIR | MANNING MOTOR SPORT PERFORMANCE
139 N PACIFIC ST | 139 N PACIFIC ST #A | 139 NORTH PACIFIC ST #D
SAN MARCOS | San Marcos, CA 92069

Database(s) : [ECHO, HAZNET - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 41012887
EPA ID: CAL000373985

HAZNET - CA ***(cont.)***

Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2021-07-08

Facility Name : MANNING MOTOR SPORT PERFORMANCE
Facility Address : 139 NORTH PACIFIC ST #D, SAN MARCOS, CA 92069
County : SAN DIEGO

Site Details
Generator EPA ID : CAL000205837
Active : Inactive
Category : STATE
Facility Types : N/R
Type : PERMANENT
Contact Name : N/R
Contact Phone : N/R
Facility Mailing Address : 139 NORTH PACIFIC ST #D, SAN MARCOS, CA 920690000
Latitude : 33.14847710
Longitude : -117.19386677
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2021-07-08

Facility Name : MELS AUTO REPAIR
Facility Address : 139 N PACIFIC STREET, SAN MARCOS, CA 92069
County : SAN DIEGO

Site Details
Generator EPA ID : CAL912323495
Active : Inactive
Category : STATE
Facility Types : N/R
Type : PERMANENT
Contact Name : N/R
Contact Phone : N/R
Facility Mailing Address : 139 N PACIFIC ST STE A-1, SAN MARCOS, CA 920691273
Latitude : 33.14847719
Longitude : -117.19386683
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2021-07-08

Facility Name : MONY'S AUTO REPAIR
Facility Address : 139 N PACIFIC ST #A, SAN MARCOS, CA 92069
County : SAN DIEGO

Map Id: I69
Direction: SSE
Distance: 0.192 mi., 1015 ft.
Elevation: 565 ft.
Relative: Lower

Site Name : NEILL WORKS LLC DBA MEL'S AUTO REPAIR | MONY'S AUTO REPAIR | MANNING MOTOR SPORT PERFORMANCE
139 N PACIFIC ST | 139 N PACIFIC ST #A | 139 NORTH PACIFIC ST #D
SAN MARCOS | San Marcos, CA 92069

Database(s) : [ECHO, HAZNET - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 41012887
EPA ID: CAL000373985

HAZNET - CA ***(cont.)***

Site Details

Generator EPA ID :	CAL000072244
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	139 N PACIFIC ST #A, SAN MARCOS, CA 920690000
Latitude :	33.14847710
Longitude :	-117.19386677
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08
Facility Name :	PACIFIC MACHINING
Facility Address :	139 N PACIFIC ST STE G, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAD115337461
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	139 N PACIFIC ST STE G, SAN MARCOS, CA 920690000
Latitude :	33.14847710
Longitude :	-117.19386677
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08
Facility Name :	S & S ENTERPRISES
Facility Address :	139 N Pacific St, San Marcos, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000050269
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	139 NORTH PACIFIC STREET, SAN MARCOS, CA
Latitude :	33.14847710

Map Id: I69
Direction: SSE
Distance: 0.192 mi., 1015 ft.
Elevation: 565 ft.
Relative: Lower

Site Name : NEILL WORKS LLC DBA MEL'S AUTO REPAIR | MONY'S AUTO REPAIR | MANNING MOTOR SPORT PERFORMANCE
139 N PACIFIC ST | 139 N PACIFIC ST #A | 139 NORTH PACIFIC ST #D
SAN MARCOS | San Marcos, CA 92069

Database(s) : [ECHO, HAZNET - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 41012887
EPA ID: CAL000373985

HAZNET - CA ***(cont.)***

Longitude :	-117.19386677
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HWG - CA

Facility Name :	MANNING MOTOR SPORT PERFORMANCE
Facility Address :	139 NORTH PACIFIC ST #D, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAL000205837
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	139 NORTH PACIFIC ST #D, SAN MARCOS, CA 920690000
Owner Name :	BARRY POWELL
Owner Address :	139 NORTH PACIFIC ST #D, SAN MARCOS, CA 920690000
Operator Name :	BARRY POWELL/OWNER
Operator Address :	139 NORTH PACIFIC ST #D, SAN MARCOS, CA 920690000
Latitude :	33.149036
Longitude :	-117.193691
Facility Name :	MONY'S AUTO REPAIR
Facility Address :	139 N PACIFIC ST #A, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAL000072244
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	139 N PACIFIC ST #A, SAN MARCOS, CA 920690000
Owner Name :	OSUNG ERNESTO
Owner Address :	N/A
Operator Name :	UNDELIVERABLE 1996 FEES FORM
Operator Address :	N/A
Latitude :	33.148477
Longitude :	-117.193867

RCRA_NONGEN

Facility Name :	NEILL WORKS LLC DBA MEL'S AUTO REPAIR
Facility Address :	139 N PACIFIC ST, SAN MARCOS, CA 92069
County :	SAN DIEGO
Date Form Received by Agency :	2021-07-15
EPA ID :	CAL000464025

Map Id: I69
Direction: SSE
Distance: 0.192 mi., 1015 ft.
Elevation: 565 ft.
Relative: Lower

Site Name : NEILL WORKS LLC DBA MEL'S AUTO REPAIR | MONY'S AUTO REPAIR | MANNING MOTOR SPORT PERFORMANCE
139 N PACIFIC ST | 139 N PACIFIC ST #A | 139 NORTH PACIFIC ST #D
SAN MARCOS | San Marcos, CA 92069

Database(s) : [ECHO, HAZNET - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 41012887
EPA ID: CAL000373985

RCRA_NONGEN ***(cont.)***

Mailing Address :	578 ROBIN HILL LN, ESCONDIDO, CA 92026
Contact :	BRENDON NEILL
Contact Address :	578 ROBIN HILL LN, ESCONDIDO, CA 92026
Contact Country :	N/R
Contact Telephone :	661-623-1071
Contact Email :	BRENDON_NEILL@YAHOO.COM
EPA Region :	09
Land Type :	Not Reported
Source Type :	Implementer
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2022-01-26

Owner/Operator Summary

Owner/Operator Name :	BRENDON NEILL
Owner/Operator Address :	578 ROBIN HILL LN, ESCONDIDO, CA 92026
Owner/Operator Country :	N/R
Owner/Operator Telephone :	661-623-1071
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Owner/Operator Name :	NEILL WORKS LLC
Owner/Operator Address :	578 ROBIN HILL LN, ESCONDIDO, CA 92026
Owner/Operator Country :	N/R
Owner/Operator Telephone :	661-623-1071
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N/R
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N

Map Id: I69
Direction: SSE
Distance: 0.192 mi., 1015 ft.
Elevation: 565 ft.
Relative: Lower

Site Name : NEILL WORKS LLC DBA MEL'S AUTO REPAIR | MONY'S AUTO REPAIR | MANNING MOTOR SPORT PERFORMANCE
139 N PACIFIC ST | 139 N PACIFIC ST #A | 139 NORTH PACIFIC ST #D
SAN MARCOS | San Marcos, CA 92069

Database(s) : [ECHO, HAZNET - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 41012887
EPA ID: CAL000373985

RCRA_NONGEN ***(cont.)***

Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Notices of Violations Summary

Regulation Violated :	N

Map Id: J70
Direction: E
Distance: 0.194 mi., 1025 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : MELLES GRIOT | MELLES GRIOT SAN MARCOS CO
435 S PACIFIC ST
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, RCRA_SQG]

Envirosite ID: 560385
EPA ID: N/R

ECHO

Facility Name :	MELLES GRIOT
Facility Address :	435 S PACIFIC ST, SAN MARCOS, CA 92069
County :	SAN DIEGO
Last Inspection Date :	1992-05-12
Registry ID :	110002668131
FIPS Code :	06073
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	10813
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	_____
Collection Method :	ADDRESS MATCHING-HOUSE NUMBER
Reference Point :	PLANT ENTRANCE (GENERAL)

Map Id: J70
Direction: E
Distance: 0.194 mi., 1025 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : MELLES GRIOT | MELLES GRIOT SAN MARCOS CO
435 S PACIFIC ST
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, RCRA_SQG] ***(cont.)***

Envirosite ID: 560385
EPA ID: N/R

ECHO ***(cont.)***

Accuracy Meters :	150

Derived Tribes :

San Pasqual Band of Diegueno Mission Indians of California - 12.8 mile(s), Pala Band of Mission Indians - 14.1 mile (s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 14.7 mile(s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 16.8 mile(s), Pauma Band of Luiseno Mission Indians of the Pauma & Yuima Reservation, California - 17.7 mile(s), La Jolla Band of Luiseno Indians, California - 17.7 mile(s), Pechanga Band of Luiseno Mission Indians of the Pechanga Reservation, California - 21.3 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 22.3 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 22.7 mile(s), Mesa Grande Band of Diegueno Mission Indians of the Mesa Grande Reservation, California - 23.5 mile(s)

Derived HUC :	18070303
Derived WBD :	180703030503
Derived STCTY FIPS :	06073
Derived Zip :	92078
Derived CD113 :	50
Derived CB2010 :	060730200291028
MYRTK Universe :	NNN
NPDES IDs :	N/R
CWA Permit Types :	N/R
CWA Compliance Tracking :	N/R
CWA NAICS :	N/R
CWA SICS :	N/R
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	N/R
CWA Current Compliance Status :	N/R
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	N/R
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	N/R
Facility NAICS :	N/R
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	1992-05-12
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N

Map Id: J70
Direction: E
Distance: 0.194 mi., 1025 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : MELLES GRIOT | MELLES GRIOT SAN MARCOS CO
435 S PACIFIC ST
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, RCRA_SQG] ***(cont.)***

Envirosite ID: 560385
EPA ID: N/R

ECHO ***(cont.)***

Federal Flag :	N/R
US Mexico Border Flag :	Y
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	N
SDWIS Flag :	N
RCRA Flag :	Y
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	Y
NAA Flag :	Y
Latitude :	33.137721
Longitude :	-117.199691
Last Date in Agency List :	2022-01-17

FRS

Facility Name :	MELLES GRIOT
Facility Address :	435 S PACIFIC ST, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Registry ID :	110002668131
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Source Description

Source Description :

RCRAInfo is EPA's comprehensive information system that supports the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984 through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA. RCRAInfo also supports generation of the National Hazardous Waste Biennial Report. All generators and treatment, storage, and disposal facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years to support creation of the Biennial Report.

FRS Environmental Interest

Source and System ID :	RCRAINFO - CAD121712988

HAZMAT_SAN DIEGO COUNTY - CA

Facility Name :	MELLES GRIOT SAN MARCOS CO
Facility Address :	435 S PACIFIC ST, SAN MARCOS, CA 92069

Map Id: J70
Direction: E
Distance: 0.194 mi., 1025 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : MELLES GRIOT | MELLES GRIOT SAN MARCOS CO
435 S PACIFIC ST
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, RCRA_SQG] ***(cont.)***

Envirosite ID: 560385
EPA ID: N/R

HAZMAT_SAN DIEGO COUNTY - CA ***(cont.)***

Date :	2002-05-04
Record ID :	DEH2002-HUPFP-108130
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23

HAZNET - CA

Facility Name :	MELLES GRIOT
Facility Address :	435 S PACIFIC ST, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAD121712988
Active :	Inactive
Category :	FEDERAL
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	435 S PACIFIC ST, SAN MARCOS, CA 920690000
Latitude :	33.13769533
Longitude :	-117.19935554
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :
1993: 512 - Other empty containers 30 gallons or more, 0.105 tons to CAT080010101
1993: 724 - Liquids with lead >= 500 Mg./L, 0.1245 tons to AZD089308803
1993: 223 - Unspecified oil-containing waste, 0.45 tons to CAT080010101

HWG - CA

Facility Name :	MELLES GRIOT
Facility Address :	435 S PACIFIC ST, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAD121712988
Status :	Inactive
Category :	FEDERAL
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	435 S PACIFIC ST, SAN MARCOS, CA 920690000

Map Id: J70
Direction: E
Distance: 0.194 mi., 1025 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : MELLES GRIOT | MELLES GRIOT SAN MARCOS CO
435 S PACIFIC ST
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, RCRA_SQG] ***(cont.)***

Envirosite ID: 560385
EPA ID: N/R

HWG - CA ***(cont.)***

Owner Name :	N/R
Owner Address :	N/A
Operator Name :	UNDELIVERABLE FEE FORM 4-94
Operator Address :	N/A
Latitude :	33.137723
Longitude :	-117.19969

RCRA_SQG

Facility Name :	MELLES GRIOT
Facility Address :	435 S PACIFIC ST, SAN MARCOS, CA 92069
County :	SAN DIEGO
Date Form Received by Agency :	1996-09-01
EPA ID :	CAD121712988
Mailing Address :	435 S PACIFIC ST, SAN MARCOS, CA 92069
Contact :	N/R
Contact Address :	N/R
Contact Country :	US
Contact Telephone :	N/R
Contact Email :	N/R
EPA Region :	09
Land Type :	Not Reported
Source Type :	Implementer
Classification :	Small Quantity Generator
Description :	Handlers that generate more than 100 and less than 1000 kilograms of hazardous waste during any calendar month and accumulate less than 6000 kg of hazardous waste at any time; or generate 100 kg or less of hazardous waste during any calendar month, and accumulate more than 1000 kg of hazardous waste at any time.
Last Date in Agency List :	2022-01-25

Owner/Operator Summary

Owner/Operator Name :	NOT REQUIRED
Owner/Operator Address :	NOT REQUIRED, NOT REQUIRED, ME 99999
Owner/Operator Country :	N/R
Owner/Operator Telephone :	415-555-1212
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Private
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Map Id: J70
Direction: E
Distance: 0.194 mi., 1025 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : MELLES GRIOT | MELLES GRIOT SAN MARCOS CO
435 S PACIFIC ST
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, RCRA_SQG] ***(cont.)***

Envirosite ID: 560385
EPA ID: N/R

RCRA_SQG ***(cont.)***

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Historical Generators

Date Form Received by Agency :	1985-10-29
Facility Name :	MELLES GRIOT
Classification :	Large Quantity Generator

Notices of Violations Summary

Date of Violation :	1992-05-12
Date Achieved Compliance :	1997-05-12
Regulation Violated :	Y
Area of Violation :	Generators - General
Enforcement Action :	N/R
Enforcement Action Date :	N/R
Enf. Disposition Status :	N/R
Enf. Disp. Status Date :	N/R
Violation Lead Agency :	State
Enforcement Lead Agency :	N/R
Proposed Penalty Amount :	N/R
Final Penalty Amount :	N/R
Paid Penalty Amount :	N/R

Evaluation Action Summary

Evaluation Date :	1992-05-12
Evaluation :	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of Violation :	Generators - General
Date Achieved Compliance :	1997-05-12
Evaluation Lead Agency :	State Contractor/Grantee

Map Id: J71
Direction: E
Distance: 0.196 mi., 1034 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : SOUTHERN CALIFORNIA FLEET SERVICES | SOUTHERN CALIFORNIA FLEET SER
437 S PACIFIC ST | 437 SOUTH PACIFIC ST
SAN MARCOS, CA 92069

Database(s) : [HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA]

Envirosite ID: 570808
EPA ID: CAL000098317

HAZMAT_SAN DIEGO COUNTY - CA

Facility Name :	SOUTHERN CALIFORNIA FLEET SER
Facility Address :	437 S PACIFIC ST, SAN MARCOS, CA 92069
Date :	2002-05-04
Record ID :	DEH2002-HUPFP-132976
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23

HAZNET - CA

Facility Name :	SOUTHERN CALIFORNIA FLEET SERVICES
Facility Address :	437 S PACIFIC ST, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000098317
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	437 S PACIFIC ST, SAN MARCOS, CA 920693816
Latitude :	33.13765279
Longitude :	-117.19937717
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Facility Name :	SOUTHERN CALIFORNIA FLEET SERVICES INC
Facility Address :	437 SOUTH PACIFIC ST, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000097272
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	450 CORPORATE DR, ESCONDIDO, CA 920291509
Latitude :	33.13765279
Longitude :	-117.19937717
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Map Id: J71
Direction: E
Distance: 0.196 mi., 1034 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : SOUTHERN CALIFORNIA FLEET SERVICES | SOUTHERN CALIFORNIA FLEET SER
437 S PACIFIC ST | 437 SOUTH PACIFIC ST
SAN MARCOS, CA 92069

Database(s) : [HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 570808
EPA ID: CAL000098317

HAZNET - CA ***(cont.)***

Waste Generator Details

State Waste :	2004: 343 - Unspecified organic liquid mixture, 0.17 tons to CAT080013352 2004: 352 - Other organic solids, 0.975 tons to CAT080033681 2002: 352 - Other organic solids, 0.055 tons to CAT080033681 2002: 223 - Unspecified oil-containing waste, 3.1692 tons to CAT080013352 1999: 352 - Other organic solids, 0.15 tons to CAT080033681 1999: 133 - Aqueous solution with total organic residues 10 percent or more, 0.6255 tons to CAT080013352 1996: 223 - Unspecified oil-containing waste, 0 tons to CAT080022148

HWG - CA

Facility Name :	SOUTHERN CALIFORNIA FLEET SERVICES
Facility Address :	437 S PACIFIC ST, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAL000098317
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	437 S PACIFIC ST, SAN MARCOS, CA 920693816
Owner Name :	TOM V. FRANCHINA
Owner Address :	437 S PACIFIC ST, SAN MARCOS, CA 920693816
Operator Name :	INACTIVE PER PH CONV 11/17/94
Operator Address :	W/ VIOLET TRUJILLO/ USING, SAN MARCOS, CA 920693816
Latitude :	33.137836
Longitude :	-117.199367

Facility Name :	SOUTHERN CALIFORNIA FLEET SERVICES INC
Facility Address :	437 SOUTH PACIFIC ST, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAL000097272
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	450 CORPORATE DR, ESCONDIDO, CA 920291509
Owner Name :	SOUTHERN CALIF FLEET SERVICES
Owner Address :	12701 MAGNOLIA AVE, R V, CA 925033816
Operator Name :	LARRY HUNDORF/SUPERVISOR
Operator Address :	437 S PACIFIC ST, SAN MARCOS, CA 920693816
Latitude :	33.137568
Longitude :	-117.199503

Map Id: K72
Direction: WSW
Distance: 0.197 mi., 1042 ft.
Elevation: 593 ft.
Relative: Higher

Site Name : MATTESON PRINT INC
1665 S RANCHO SANTA FE SUITE-
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 41068284
EPA ID: CAL000044281

HAZNET - CA

Facility Name :	MATTESON PRINT INC
Facility Address :	1665 S RANCHO SANTA FE SUITE-, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000044281
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	1665 S RANCHO SANTA FE SUITE-, SAN MARCOS, CA 920690000
Latitude :	33.14971800
Longitude :	-117.19857150
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HWG - CA

Facility Name :	MATTESON PRINT INC
Facility Address :	1665 S RANCHO SANTA FE SUITE-, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAL000044281
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	1665 S RANCHO SANTA FE SUITE-, SAN MARCOS, CA 920690000
Owner Name :	MATTESON TOM
Owner Address :	N/A
Operator Name :	DEACT NON-DELIV. PER 95 FEES -
Operator Address :	P.H., N/A
Latitude :	33.118341
Longitude :	-117.223703

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER]

Envirosite ID: 280139
EPA ID: N/R

CALEPA SITES - CA

Facility Name : AUDIENCE AV INC
Facility Address : 120 N PACIFIC STREET, SAN MARCOS, 92069

Site ID : 526759
EI ID : 849835
EI Description : Industrial Facility Storm Water
Latitude : 33.148545
Longitude : -117.195011
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-01-07

Facility Name : CANINE CRYOBANK
Facility Address : 120 N PACIFIC ST STE A5, SAN MARCOS, 92069

Site ID : 102799
EI ID : 10375999
EI Description : Chemical Storage Facilities
Latitude : 33.148650
Longitude : -117.195100
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-01-07

Facility Name : San Diego Kitchen Pros
Facility Address : 120 NORTH PACIFIC STREET, SUITE B2, SAN MARCOS, 92069

Site ID : 541613
EI ID : 850125
EI Description : Industrial Facility Storm Water
Latitude : 32.715730
Longitude : -117.161080
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2019-10-02

Facility Name : Sunrise Spa Covers Manufacturing
Facility Address : 120 NORTH PACIFIC STREET SUITE H5, SAN DIEGO, 92069

Site ID : 543598
EI ID : 849607
EI Description : Industrial Facility Storm Water

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

CALEPA SITES - CA ***(cont.)***

Latitude :	33.149075
Longitude :	-117.195284
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2019-10-02
Facility Name :	SUNRISE SPA COVERS MANUFACTURING
Facility Address :	120 NORTH PACIFIC STREET SUITE H5, SAN MARCOS, 92069
Site ID :	589584
EI ID :	880237
EI Description :	Industrial Facility Storm Water
Latitude :	33.148650
Longitude :	-117.195100
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07
Facility Name :	WORLDWIDE AMMUNITION DISTRIBUTION
Facility Address :	120 N PACIFIC ST STE G5, SAN MARCOS, 92069
Site ID :	592055
EI ID :	881582
EI Description :	Industrial Facility Storm Water
Latitude :	33.148780
Longitude :	-117.194600
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07

CIWQS - CA

Facility Name :	KEITH GERLAND
Facility Address :	120 N PACIFIC ST SUITE L 12, SAN MARCOS, CA 92069
County :	SAN DIEGO
Place ID :	S808324
Agency Name :	KEITH GERLAND
Last Date in Agency List :	2021-12-30
Facility Name :	SUNRISE SPA COVERS MANUFACTURING
Facility Address :	120 NORTH PACIFIC STREET SUITE H5, SAN DIEGO, CA 92069
County :	SAN DIEGO

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

CIWQS - CA ***(cont.)***

Place ID :	S849607
Agency Name :	SUNRISE SPA COVERS MANUFACTURING
Last Date in Agency List :	2021-12-30
Facility Name :	WHITING CABINET & CONSTRUCTION
Facility Address :	120 NORTH PACIFIC STREET H-1, SAN MARCOS, CA 92069
County :	SAN DIEGO
Place ID :	S850765
Agency Name :	WHITING CABINET & CONSTRUCTION
Last Date in Agency List :	2021-12-30

ECHO

Facility Name :	AUDIENCE AV INC
Facility Address :	120 N PACIFIC STREET, SAN MARCOS, CA 92069
County :	N/R
Last Inspection Date :	N/R
Registry ID :	110070096923
FIPS Code :	06073
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	_____
Collection Method :	N/R
Reference Point :	N/R
Accuracy Meters :	17531

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

ECHO ***(cont.)***

Derived Tribes :

San Pasqual Band of Diegueno Mission Indians of California - 12.4 mile(s), Pala Band of Mission Indians - 13.3 mile (s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 14.1 mile(s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 16.3 mile(s), Pauma Band of Luiseno Mission Indians of the Pauma & Yuima Reservation, California - 16.9 mile(s), La Jolla Band of Luiseno Indians, California - 17.2 mile(s), Pechanga Band of Luiseno Mission Indians of the Pechanga Reservation, California - 20.5 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 22.5 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 22.9 mile(s), Mesa Grande Band of Diegueno Mission Indians of the Mesa Grande Reservation, California - 23.2 mile(s)

Derived HUC :	18070303
Derived WBD :	180703030503
Derived STCTY FIPS :	06073
Derived Zip :	92069
Derived CD113 :	50
Derived CB2010 :	060730200292005
MYRTK Universe :	NNN
NPDES IDs :	CAZ478131
CWA Permit Types :	Minor
CWA Compliance Tracking :	On
CWA NAICS :	N/R
CWA SICS :	3651
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	0
CWA Current Compliance Status :	No Violation Identified
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	_____
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	3651
Facility NAICS :	N/R
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

ECHO ***(cont.)***

Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	Y
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	Y
SDWIS Flag :	N
RCRA Flag :	N
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	Y
NAA Flag :	Y
Latitude :	33.148545
Longitude :	-117.195011
Last Date in Agency List :	2022-01-17
Facility Name :	CASEYS AUTO MACHINE
Facility Address :	120 N PACIFIC ST STE G3, SAN MARCOS, CA 92069
County :	SAN DIEGO
Last Inspection Date :	N/R
Registry ID :	110009554008
FIPS Code :	06073
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	_____

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

ECHO ***(cont.)***

Collection Method :	ADDRESS MATCHING-HOUSE NUMBER
Reference Point :	CENTER OF A FACILITY OR STATION
Accuracy Meters :	30

Derived Tribes :

San Pasqual Band of Diegueno Mission Indians of California - 12.3 mile(s), Pala Band of Mission Indians - 13.3 mile (s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 14 mile(s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 16.2 mile(s), Pauma Band of Luiseno Mission Indians of the Pauma & Yuima Reservation, California - 16.9 mile(s), La Jolla Band of Luiseno Indians, California - 17.1 mile(s), Pechanga Band of Luiseno Mission Indians of the Pechanga Reservation, California - 20.5 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 22.5 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 22.8 mile(s), Mesa Grande Band of Diegueno Mission Indians of the Mesa Grande Reservation, California - 23.2 mile(s)

Derived HUC :	18070303
Derived WBD :	180703030503
Derived STCTY FIPS :	06073
Derived Zip :	92069
Derived CD113 :	50
Derived CB2010 :	060730200292003
MYRTK Universe :	NNN
NPDES IDs :	N/R
CWA Permit Types :	N/R
CWA Compliance Tracking :	N/R
CWA NAICS :	N/R
CWA SICS :	N/R
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	N/R
CWA Current Compliance Status :	N/R
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	N/R
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	N/R
Facility NAICS :	N/R
Facility Last Inspection EPA Date :	N/R

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

ECHO ***(cont.)***

Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	Y
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	N
SDWIS Flag :	N
RCRA Flag :	Y
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	Y
NAA Flag :	Y
Latitude :	33.14818
Longitude :	-117.19411
Last Date in Agency List :	2022-01-17

Facility Name :	CREATIVE PRINTING
Facility Address :	120 N PACIFIC ST SUITE B4, SAN MARCOS, CA 92069
County :	N/R

Last Inspection Date :	N/R
Registry ID :	110070085290
FIPS Code :	N/R
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

ECHO ***(cont.)***

QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	N/R
Three-Year Compliance Status :	N/R
Collection Method :	Zip Code Centroid
Reference Point :	N/R
Accuracy Meters :	10000
Derived Tribes :	N/R
Derived HUC :	N/R
Derived WBD :	N/R
Derived STCTY FIPS :	N/R
Derived Zip :	N/R
Derived CD113 :	N/R
Derived CB2010 :	N/R
MYRTK Universe :	NNN
NPDES IDs :	CAW417619
CWA Permit Types :	Minor
CWA Compliance Tracking :	N/R
CWA NAICS :	N/R
CWA SICS :	N/R
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	0
CWA Current Compliance Status :	Not Applicable
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	N/R
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	N/R
Facility NAICS :	N/R
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

ECHO ***(cont.)***

Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	N/R
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	Y
SDWIS Flag :	N
RCRA Flag :	N
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	N/R
NAA Flag :	N
Latitude :	33.194075
Longitude :	-117.16177
Last Date in Agency List :	2022-01-17
Facility Name :	GERLAND MACHINE INC
Facility Address :	120 N PACIFIC ST STE L12, SAN MARCOS, CA 92069
County :	SAN DIEGO
Last Inspection Date :	N/R
Registry ID :	110070467651
FIPS Code :	N/R
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	_____
Collection Method :	Zip Code Centroid
Reference Point :	N/R
Accuracy Meters :	10000
Derived Tribes :	N/R

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

ECHO ***(cont.)***

Derived HUC :	N/R
Derived WBD :	N/R
Derived STCTY FIPS :	N/R
Derived Zip :	N/R
Derived CD113 :	N/R
Derived CB2010 :	N/R
MYRTK Universe :	NNN
NPDES IDs :	N/R
CWA Permit Types :	N/R
CWA Compliance Tracking :	N/R
CWA NAICS :	N/R
CWA SICS :	N/R
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	N/R
CWA Current Compliance Status :	N/R
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	N/R
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	N/R
Facility NAICS :	33429 - Other Communications Equipment Manufacturing
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	N/R
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	N
SDWIS Flag :	N

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

ECHO ***(cont.)***

RCRA Flag :	Y
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	Y
NAA Flag :	N
Latitude :	33.194075
Longitude :	-117.16177
Last Date in Agency List :	2022-01-17
Facility Name :	KEITH GERLAND
Facility Address :	120 N PACIFIC ST SUITE L 12, SAN MARCOS, CA 92069
County :	N/R
Last Inspection Date :	N/R
Registry ID :	110070085093
FIPS Code :	N/R
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	N/R
Three-Year Compliance Status :	N/R
Collection Method :	Zip Code Centroid
Reference Point :	N/R
Accuracy Meters :	10000
Derived Tribes :	N/R
Derived HUC :	N/R
Derived WBD :	N/R
Derived STCTY FIPS :	N/R
Derived Zip :	N/R
Derived CD113 :	N/R
Derived CB2010 :	N/R
MYRTK Universe :	NNN
NPDES IDs :	CAW412647

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

ECHO ***(cont.)***

CWA Permit Types :	Minor
CWA Compliance Tracking :	N/R
CWA NAICS :	N/R
CWA SICS :	N/R
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	0
CWA Current Compliance Status :	Not Applicable
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	N/R
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	N/R
Facility NAICS :	N/R
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	N/R
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	Y
SDWIS Flag :	N
RCRA Flag :	N
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	N/R
NAA Flag :	N
Latitude :	33.194075
Longitude :	-117.16177

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

ECHO ***(cont.)***

Last Date in Agency List :	2022-01-17
Facility Name :	OLD FORD GARAGE
Facility Address :	120 N PACIFIC ST UNIT K6, SAN MARCOS, CA 92069
County :	SAN DIEGO
Last Inspection Date :	N/R
Registry ID :	110002668104
FIPS Code :	06073
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	_____
Collection Method :	ADDRESS MATCHING-HOUSE NUMBER
Reference Point :	CENTER OF A FACILITY OR STATION
Accuracy Meters :	30

Derived Tribes :

San Pasqual Band of Diegueno Mission Indians of California - 12.3 mile(s), Pala Band of Mission Indians - 13.3 mile (s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 14 mile(s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 16.2 mile(s), Pauma Band of Luiseno Mission Indians of the Pauma & Yuima Reservation, California - 16.9 mile(s), La Jolla Band of Luiseno Indians, California - 17.1 mile(s), Pechanga Band of Luiseno Mission Indians of the Pechanga Reservation, California - 20.5 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 22.5 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 22.8 mile(s), Mesa Grande Band of Diegueno Mission Indians of the Mesa Grande Reservation, California - 23.2 mile(s)

Derived HUC :	18070303
Derived WBD :	180703030503
Derived STCTY FIPS :	06073
Derived Zip :	92069

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

ECHO ***(cont.)***

Derived CD113 :	50
Derived CB2010 :	060730200292003
MYRTK Universe :	NNN
NPDES IDs :	N/R
CWA Permit Types :	N/R
CWA Compliance Tracking :	N/R
CWA NAICS :	N/R
CWA SICS :	N/R
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	N/R
CWA Current Compliance Status :	N/R
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	N/R
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	N/R
Facility NAICS :	N/R
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	Y
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	N
SDWIS Flag :	N
RCRA Flag :	Y
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

ECHO ***(cont.)***

Active Flag :	Y
NAA Flag :	Y
Latitude :	33.14818
Longitude :	-117.19411
Last Date in Agency List :	2022-01-17
Facility Name :	SAN DIEGO KITCHEN PROS
Facility Address :	120 NORTH PACIFIC STREET, SUITE B2, SAN MARCOS, CA 92069
County :	N/R
Last Inspection Date :	N/R
Registry ID :	110070096968
FIPS Code :	06073
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	1
Programs IN SNC :	0
Current Compliance Status :	N/R
Three-Year Compliance Status :	___V
Collection Method :	N/R
Reference Point :	N/R
Accuracy Meters :	36031

Derived Tribes :

Sycuan Band of the Kumeyaay Nation - 16.2 mile(s), Jamul Indian Village of California - 16.7 mile(s), Sycuan Band of the Kumeyaay Nation - 19 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 20.8 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 21.7 mile(s), Capitan Grande Band of Diegueno Mission Indians of California (Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California; Viejas (Baron Long) Group of Capitan Grande Band of Mission Indians of the Viejas Reservation, California) - 24.8 mile(s)

Derived HUC :	18070304
Derived WBD :	180703041202

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

ECHO ***(cont.)***

Derived STCTY FIPS :	06073
Derived Zip :	92101
Derived CD113 :	52
Derived CB2010 :	060730053001015
MYRTK Universe :	NNN
NPDES IDs :	CAZ478586
CWA Permit Types :	Minor
CWA Compliance Tracking :	Off
CWA NAICS :	N/R
CWA SICS :	2434
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	1
CWA Current Compliance Status :	Terminated Permit
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	___V
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	2434
Facility NAICS :	N/R
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	Y
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	Y
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	Y
SDWIS Flag :	N
RCRA Flag :	N
TRI Flag :	N

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

ECHO ***(cont.)***

GHG Flag :	N
Major Flag :	N/R
Active Flag :	N/R
NAA Flag :	Y
Latitude :	32.71573
Longitude :	-117.16108
Last Date in Agency List :	2022-01-17
Facility Name :	SUNRISE SPA COVERS MANUFACTURING
Facility Address :	120 NORTH PACIFIC STREET SUITE H5, SAN DIEGO, CA 92069
County :	SAN DIEGO COUNTY
Last Inspection Date :	N/R
Registry ID :	110070085283
FIPS Code :	06073
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	1
Programs IN SNC :	0
Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	___V_____
Collection Method :	N/R
Reference Point :	N/R
Accuracy Meters :	17531

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

ECHO ***(cont.)***

Derived Tribes :

San Pasqual Band of Diegueno Mission Indians of California - 12.4 mile(s), Pala Band of Mission Indians - 13.3 mile (s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 14.1 mile(s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 16.2 mile(s), Pauma Band of Luiseno Mission Indians of the Pauma & Yuima Reservation, California - 16.9 mile(s), La Jolla Band of Luiseno Indians, California - 17.2 mile(s), Pechanga Band of Luiseno Mission Indians of the Pechanga Reservation, California - 20.5 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 22.6 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 22.9 mile(s), Mesa Grande Band of Diegueno Mission Indians of the Mesa Grande Reservation, California - 23.2 mile(s)

Derived HUC :	18070303
Derived WBD :	180703030503
Derived STCTY FIPS :	06073
Derived Zip :	92069
Derived CD113 :	50
Derived CB2010 :	060730200292005
MYRTK Universe :	NNN
NPDES IDs :	CAW417039 CAZ477829 CAZ518604
CWA Permit Types :	Minor
CWA Compliance Tracking :	On
CWA NAICS :	N/R
CWA SICS :	3999
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	1
CWA Current Compliance Status :	No Violation Identified
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	___V_____
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	3999
Facility NAICS :	N/R
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

ECHO ***(cont.)***

Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	Y
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	Y
SDWIS Flag :	N
RCRA Flag :	N
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	Y
NAA Flag :	Y
Latitude :	33.149075
Longitude :	-117.195284
Last Date in Agency List :	2022-01-17
Facility Name :	SUNRISE SPA COVERS MFG
Facility Address :	120 N PACIFIC ST SUITE H5, SAN MARCOS, CA 92069
County :	N/R
Last Inspection Date :	N/R
Registry ID :	110070085283
FIPS Code :	06073
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	No Violation
Three-Year Compliance Status :	_____

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

ECHO ***(cont.)***

Collection Method :	N/R
Reference Point :	N/R
Accuracy Meters :	17531

Derived Tribes :

San Pasqual Band of Diegueno Mission Indians of California - 12.4 mile(s), Pala Band of Luiseno Mission Indians of the Pala Reservation, California - 13.3 mile(s), Rincon Band of Luiseno Mission Indians of the Rincon Reservation, California - 14.1 mile(s), Pauma Band of Luiseno Mission Indians of the Pauma & Yuima Reservation, California - 16.9 mile(s), La Jolla Band of Luiseno Indians, California - 17.2 mile(s), Pechanga Band of Luiseno Mission Indians of the Pechanga Reservation, California - 20.5 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 22.9 mile(s), Mesa Grande Band of Diegueno Mission Indians of the Mesa Grande Reservation, California - 23.2 mile(s), Iipay Nation of Santa Ysabel, California - 23.7 mile(s)

Derived HUC :	18070303
Derived WBD :	180703030503
Derived STCTY FIPS :	06073
Derived Zip :	92069
Derived CD113 :	50
Derived CB2010 :	060730200292005
MYRTK Universe :	NNN
NPDES IDs :	CAW417039 CAZ477829
CWA Permit Types :	Minor
CWA Compliance Tracking :	On
CWA NAICS :	N/R
CWA SICS :	3999
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	0
CWA Current Compliance Status :	No Violation
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	_____
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	3999
Facility NAICS :	N/R
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

ECHO ***(cont.)***

Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	Y
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	Y
SDWIS Flag :	N
RCRA Flag :	N
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	Y
NAA Flag :	Y
Latitude :	33.149075
Longitude :	-117.195284
Last Date in Agency List :	2018-10-08
Facility Name :	WORLDWIDE AMMUNITION DISTRIBUTION
Facility Address :	120 N PACIFIC ST STE G5, SAN MARCOS, CA 92069
County :	N/R
Last Inspection Date :	N/R
Registry ID :	110070793052
FIPS Code :	06073
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

ECHO ***(cont.)***

Programs IN SNC :	0
Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	_____
Collection Method :	N/R
Reference Point :	N/R
Accuracy Meters :	17531

Derived Tribes :

San Pasqual Band of Diegueno Mission Indians of California - 12.4 mile(s), Pala Band of Mission Indians - 13.3 mile (s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 14 mile(s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 16.2 mile(s), Pauma Band of Luiseno Mission Indians of the Pauma & Yuima Reservation, California - 16.9 mile(s), La Jolla Band of Luiseno Indians, California - 17.1 mile(s), Pechanga Band of Luiseno Mission Indians of the Pechanga Reservation, California - 20.5 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 22.5 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 22.9 mile(s), Mesa Grande Band of Diegueno Mission Indians of the Mesa Grande Reservation, California - 23.2 mile(s)

Derived HUC :	18070303
Derived WBD :	180703030503
Derived STCTY FIPS :	06073
Derived Zip :	92069
Derived CD113 :	50
Derived CB2010 :	060730200292005
MYRTK Universe :	NNN
NPDES IDs :	CAZ520383
CWA Permit Types :	Minor
CWA Compliance Tracking :	On
CWA NAICS :	N/R
CWA SICS :	3482
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	0
CWA Current Compliance Status :	No Violation Identified
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	_____
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

ECHO ***(cont.)***

Facility SIC :	3482
Facility NAICS :	N/R
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	Y
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	Y
SDWIS Flag :	N
RCRA Flag :	N
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	Y
NAA Flag :	Y
Latitude :	33.14878
Longitude :	-117.1946
Last Date in Agency List :	2022-01-17

FRS

Facility Name :	AUDIENCE AV INC
Facility Address :	120 N PACIFIC STREET, SAN MARCOS, CA 92069
County :	N/R

Site Details

Registry ID :	110070096923
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

FRS ***(cont.)***

Source Description

Source Description :

The NPDES module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

FRS Environmental Interest

Source and System ID : ICIS - CAZ478131

Facility Name : CREATIVE PRINTING
Facility Address : 120 N PACIFIC ST SUITE B4, SAN MARCOS, CA 92069
County : N/R

Site Details

Registry ID : 110070085290
FRS Facility URL : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-02-17

Source Description

Source Description :

The NPDES module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

FRS Environmental Interest

Source and System ID : ICIS - CAW417619

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

FRS ***(cont.)***

Facility Name : KEITH GERLAND
Facility Address : 120 N PACIFIC ST SUITE L 12, SAN MARCOS, CA 92069
County : N/R

Site Details
Registry ID : 110070085093
FRS Facility URL : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-02-17

Source Description

Source Description :

The NPDES module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

FRS Environmental Interest
Source and System ID : ICIS - CAW412647

Facility Name : SAN DIEGO KITCHEN PROS
Facility Address : 120 NORTH PACIFIC STREET, SUITE B2, SAN MARCOS, CA 92069
County : N/R

Site Details
Registry ID : 110070096968
FRS Facility URL : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-02-17

Source Description

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

FRS ***(cont.)***

Source Description :

The NPDES module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

FRS Environmental Interest

Source and System ID :	ICIS - CAZ478586
Facility Name :	SUNRISE SPA COVERS MANUFACTURING
Facility Address :	120 NORTH PACIFIC STREET SUITE H5, SAN DIEGO, CA 92069
County :	SAN DIEGO COUNTY

Site Details

Registry ID :	110070085283
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Source Description

Source Description :

The NPDES module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

FRS Environmental Interest

Source and System ID :	ICIS - CAW417039 ICIS - CAZ477829 ICIS - CAZ518604

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

FRS ***(cont.)***

Facility Name : SUNRISE SPA COVERS MFG
Facility Address : 120 N PACIFIC ST SUITE H5, SAN MARCOS, CA 92069
County : N/R

Site Details
Registry ID : 110070085283
FRS Facility URL : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2018-09-13

Source Description

Source Description :

The NPDES module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

FRS Environmental Interest
Source and System ID : ICIS - CAW417039
ICIS - CAZ477829

Facility Name : THE KITCHEN CENTER INC
Facility Address : 120 N. PACIFIC STREET, SUITE B-2, SAN MARCOS, CA 92069
County : N/R

Site Details
Registry ID : 110070560591
FRS Facility URL : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2020-08-31

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

FRS ***(cont.)***

Source Description

Source Description :

ICIS provides a database that, when complete, will contain enforcement and compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions and a subset of the Permit Compliance System (PCS), which supports the National Pollutant Discharge Elimination System (NPDES). This information is maintained in ICIS by EPA in the Regional offices and at Headquarters. A future release of ICIS will completely replace PCS and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities that support compliance and enforcement programs, including incident tracking, compliance assistance, and compliance monitoring.

FRS Environmental Interest

Source and System ID :	ICIS - 3601092481
Facility Name :	THE KITCHEN CENTER INC
Facility Address :	120 N PACIFIC ST STE B-2, SAN MARCOS, CA 92069
County :	SAN DIEGO COUNTY

Site Details

Registry ID :	110070560591
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Source Description

Source Description :

ICIS provides a database that, when complete, will contain enforcement and compliance information across most of EPA's programs. The vision for ICIS is to replace EPA's independent databases that contain enforcement data with a single repository for that information. Currently, ICIS contains all Federal Administrative and Judicial enforcement actions and a subset of the Permit Compliance System (PCS), which supports the National Pollutant Discharge Elimination System (NPDES). This information is maintained in ICIS by EPA in the Regional offices and at Headquarters. A future release of ICIS will completely replace PCS and will integrate that information with Federal actions already in the system. ICIS also has the capability to track other activities that support compliance and enforcement programs, including incident tracking, compliance assistance, and compliance monitoring.

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

FRS ***(cont.)***

FRS Environmental Interest
Source and System ID : ICIS - 3601092481

Facility Name : WHITING CABINET & CONSTRUCTION
Facility Address : 120 NORTH PACIFIC STREET, SAN MARCOS, CA 92069
County : SAN DIEGO COUNTY

Site Details
Registry ID : 110070097065
FRS Facility URL : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-02-17

Source Description

Source Description :

The NPDES module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

FRS Environmental Interest
Source and System ID : ICIS - CAZ479875

Facility Name : WORLDWIDE AMMUNITION DISTRIBUTION
Facility Address : 120 N PACIFIC ST STE G5, SAN MARCOS, CA 92069
County : N/R

Site Details
Registry ID : 110070793052
FRS Facility URL : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-02-17

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

FRS ***(cont.)***

Source Description

Source Description :

The NPDES module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

FRS Environmental Interest

Source and System ID :	ICIS - CAZ520383

HAZMAT_SAN DIEGO COUNTY - CA

Facility Name :	BIOCLINOVA CORPORATION
Facility Address :	120 N PACIFIC ST, SAN MARCOS, CA 92069
Date :	2002-07-22
Record ID :	DEH2002-HUPFP-200325
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23
Facility Name :	CARPET CLEANERS DEPOT
Facility Address :	120 N PACIFIC ST, SAN MARCOS, CA 92069
Date :	2002-05-04
Record ID :	DEH2002-HUPFP-135665
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23
Facility Name :	CASEY'S AUTO MACHINE
Facility Address :	120 N PACIFIC ST, SAN MARCOS, CA 92069

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

HAZMAT_SAN DIEGO COUNTY - CA ***(cont.)***

Date :	2002-05-04
Record ID :	DEH2002-HUPFP-116173
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23
Facility Name :	C & G CLASSIC GERMAN AUTO
Facility Address :	120 N PACIFIC ST, SAN MARCOS, CA 92069
Date :	2002-05-04
Record ID :	DEH2002-HUPFP-131158
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23
Facility Name :	CHANDLER'S SERVICES
Facility Address :	120 N PACIFIC ST, SAN MARCOS, CA 92069
Date :	2010-08-04
Record ID :	DEH2010-HUPFP-212474
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23
Facility Name :	CRG WELDING
Facility Address :	120 N PACIFIC ST, SAN MARCOS, CA 92069
Date :	2010-03-03
Record ID :	DEH2010-HUPFP-211846
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

HAZMAT_SAN DIEGO COUNTY - CA ***(cont.)***

Facility Name :	DEZERT STEEL
Facility Address :	120 N PACIFIC ST, SAN MARCOS, CA 92069
Date :	2006-10-13
Record ID :	DEH2006-HUPFP-207344
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23
Facility Name :	ENVIRO TEK, INC
Facility Address :	120 N PACIFIC ST, SAN MARCOS, CA 92069
Date :	2002-05-04
Record ID :	DEH2002-HUPFP-131163
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23
Facility Name :	EXTREME RACING MOTORSPORTS
Facility Address :	120 N PACIFIC ST, SAN MARCOS, CA 92069
Date :	2002-07-22
Record ID :	DEH2002-HUPFP-200327
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23
Facility Name :	FURNITURE MEDIC
Facility Address :	120 N PACIFIC ST, SAN MARCOS, CA 92069
Date :	2004-08-04
Record ID :	DEH2004-HUPFP-203847
Record Type :	Unified Program Facility Permit

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

HAZMAT_SAN DIEGO COUNTY - CA ***(cont.)***

Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23
Facility Name :	GERLAND MACHINE, INC
Facility Address :	120 N PACIFIC ST, SAN MARCOS, CA 92069
Date :	2010-10-29
Record ID :	DEH2010-HUPFP-212991
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23
Facility Name :	GUS'S RADIATOR
Facility Address :	120 N PACIFIC ST, SAN MARCOS, CA 92069
Date :	2002-05-04
Record ID :	DEH2002-HUPFP-137045
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23
Facility Name :	H & M OFF ROAD MOTORSPORTS
Facility Address :	120 N PACIFIC ST, SAN MARCOS, CA 92069
Date :	2003-08-12
Record ID :	DEH2003-HUPFP-202247
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

HAZMAT_SAN DIEGO COUNTY - CA ***(cont.)***

Facility Name :	H&M OFF ROAD MOTORSPORTS
Facility Address :	120 N PACIFIC ST, SAN MARCOS, CA 92069
Date :	2002-05-04
Record ID :	DEH2002-HUPFP-102980
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23
Facility Name :	HORIZON WOOD WORKS
Facility Address :	120 N PACIFIC ST, SAN MARCOS, CA 92069
Date :	2010-11-23
Record ID :	DEH2010-HUPFP-213099
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23
Facility Name :	ICANDY MOTORSPORTS
Facility Address :	120 N PACIFIC ST, SAN MARCOS, CA 92069
Date :	2010-11-30
Record ID :	DEH2010-HUPFP-213155
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23
Facility Name :	JDN REVELATIONS
Facility Address :	120 N PACIFIC ST, SAN MARCOS, CA 92069
Date :	2005-03-03
Record ID :	DEH2005-HUPFP-204981
Record Type :	Unified Program Facility Permit

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

HAZMAT_SAN DIEGO COUNTY - CA ***(cont.)***

Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23
Facility Name :	JUNCOS AUTO
Facility Address :	120 N PACIFIC ST, SAN MARCOS, CA 92069
Date :	2002-05-04
Record ID :	DEH2002-HUPFP-137017
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23
Facility Name :	KAUFMAN'S KABINETS
Facility Address :	120 N PACIFIC ST, SAN MARCOS, CA 92069
Date :	2010-12-07
Record ID :	DEH2010-HUPFP-213210
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23
Facility Name :	KEITHS CUSTOM PINSTRIPING
Facility Address :	120 N PACIFIC ST, SAN MARCOS, CA 92069
Date :	2002-05-04
Record ID :	DEH2002-HUPFP-116172
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

HAZMAT_SAN DIEGO COUNTY - CA ***(cont.)***

Facility Name :	LIQUID ELEMENTS, LLC
Facility Address :	120 N PACIFIC ST, SAN MARCOS, CA 92069
Date :	2006-07-14
Record ID :	DEH2006-HUPFP-206973
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23
Facility Name :	LOOFAH BY THE SEA
Facility Address :	120 N PACIFIC ST, SAN MARCOS, CA 92069
Date :	2010-12-29
Record ID :	DEH2010-HUPFP-213284
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23
Facility Name :	MATRIX CONCEPTS INC
Facility Address :	120 N PACIFIC ST, SAN MARCOS, CA 92069
Date :	2003-05-29
Record ID :	DEH2003-HUPFP-201894
Record Type :	Unified Program Facility Permit
Status :	Permit Suspended
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23
Facility Name :	REBEL FABRICATION
Facility Address :	120 N PACIFIC ST, SAN MARCOS, CA 92069
Date :	2005-09-27
Record ID :	DEH2005-HUPFP-205865
Record Type :	Unified Program Facility Permit

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

HAZMAT_SAN DIEGO COUNTY - CA ***(cont.)***

Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23
Facility Name :	RICHARDS AUTOMOTIVE REPAIR
Facility Address :	120 N PACIFIC ST, SAN MARCOS, CA 92069
Date :	2002-05-04
Record ID :	DEH2002-HUPFP-134042
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23
Facility Name :	THUMPER PERFORMANCE
Facility Address :	120 N PACIFIC ST, SAN MARCOS, CA 92069
Date :	2002-10-03
Record ID :	DEH2002-HUPFP-200775
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23
Facility Name :	TRANSMISSION DEPOT
Facility Address :	120 N PACIFIC ST, SAN MARCOS, CA 92069
Date :	2002-05-04
Record ID :	DEH2002-HUPFP-103982
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

HAZMAT_SAN DIEGO COUNTY - CA ***(cont.)***

Facility Name :	UNICAP MOLD CO
Facility Address :	120 N PACIFIC ST, SAN MARCOS, CA 92069
Date :	2003-12-02
Record ID :	DEH2003-HUPFP-202789
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23
Facility Name :	US FAB WORKS, LLC
Facility Address :	120 N PACIFIC ST, SAN MARCOS, CA 92069
Date :	2009-10-06
Record ID :	DEH2009-HUPFP-211355
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23

HAZNET - CA

Facility Name :	ED RICE PRINTING
Facility Address :	120 N PACIFIC ST STE E1, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAC002608545
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	120 N PACIFIC ST STE E1, SAN MARCOS, CA 920691263
Latitude :	33.14818460
Longitude :	-117.19417119
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

HAZNET - CA ***(cont.)***

Waste Generator Details

State Waste :	2006: 214 - Unspecified solvent mixture, 0.18 tons to CAD044429835

HWG - CA

Facility Name :	ED RICE PRINTING
Facility Address :	120 N PACIFIC ST STE E1, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAC002608545
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	120 N PACIFIC ST STE E1, SAN MARCOS, CA 920691263
Owner Name :	--ED RICE PRINTING
Owner Address :	120 N PACIFIC ST STE E1, SAN MARCOS, CA 920691263
Operator Name :	SHARON FISHER
Operator Address :	120 N PACIFIC ST STE E1, SAN MARCOS, CA 920691263
Latitude :	33.147717
Longitude :	-117.194382

ICIS

Facility Name :	AUDIENCE AV INC
Facility Address :	120 N PACIFIC STREET, SAN MARCOS, CA 92069

Site Details

NPDES ID :	CAZ478131
ICIS Facility Interest ID :	3600735650
Facility UIN :	110070096923
Facility Type Code :	Privately Owned Facility
Impaired Waters :	N/R
Latitude :	33.148545
Longitude :	-117.195011
Last Date in Agency List :	2022-01-12

Facility SIC

SIC Code :	3651
SIC Description :	Household Audio And Video Equipment

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

ICIS ***(cont.)***

Facility Name : CREATIVE PRINTING
Facility Address : 120 N PACIFIC ST SUITE B4, SAN MARCOS, CA 92069

Site Details
NPDES ID : CAW417619
ICIS Facility Interest ID : 3600737766
Facility UIN : 110070085290
Facility Type Code : N/R
Impaired Waters : N/R
Latitude : N/R
Longitude : N/R
Last Date in Agency List : 2022-01-12

Facility Name : KEITH GERLAND
Facility Address : 120 N PACIFIC ST SUITE L 12, SAN MARCOS, CA 92069

Site Details
NPDES ID : CAW412647
ICIS Facility Interest ID : 3600737529
Facility UIN : 110070085093
Facility Type Code : N/R
Impaired Waters : N/R
Latitude : N/R
Longitude : N/R
Last Date in Agency List : 2022-01-12

Facility Name : SAN DIEGO KITCHEN PROS
Facility Address : 120 NORTH PACIFIC STREET, SUITE B2, SAN MARCOS, CA 92069

Site Details
NPDES ID : CAZ478586
ICIS Facility Interest ID : 3600735704
Facility UIN : 110070096968
Facility Type Code : Privately Owned Facility
Impaired Waters : 303(D) Listed
Latitude : 32.71573
Longitude : -117.16108
Last Date in Agency List : 2022-01-12

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

ICIS ***(cont.)***

Facility SIC
SIC Code : 2434
SIC Description : Wood Kitchen Cabinets

Facility Name : SUNRISE SPA COVERS MANUFACTURING
Facility Address : 120 NORTH PACIFIC STREET SUITE H5, SAN DIEGO, CA 92069

Site Details
NPDES ID : CAZ477829
ICIS Facility Interest ID : 3600735628
Facility UIN : 110070085283
Facility Type Code : Municipal or Water District
Impaired Waters : N/R
Latitude : 33.149075
Longitude : -117.195284
Last Date in Agency List : 2022-01-12

Facility SIC
SIC Code : 3999
SIC Description : Manufacturing Industries

Facility Name : SUNRISE SPA COVERS MANUFACTURING
Facility Address : 120 NORTH PACIFIC STREET SUITE H5, SAN MARCOS, CA 92069

Site Details
NPDES ID : CAZ518604
ICIS Facility Interest ID : 3601184513
Facility UIN : 110070085283
Facility Type Code : Municipal or Water District
Impaired Waters : N/R
Latitude : 33.14865
Longitude : -117.1951
Last Date in Agency List : 2022-01-12

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

ICIS ***(cont.)***

Facility SIC
SIC Code : 3999
SIC Description : Manufacturing Industries

Facility Name : SUNRISE SPA COVERS MFG
Facility Address : 120 N PACIFIC ST SUITE H5, SAN MARCOS, CA 92069

Site Details
NPDES ID : CAW417039
ICIS Facility Interest ID : 3600737755
Facility UIN : 110070085283
Facility Type Code : N/R
Impaired Waters : N/R
Latitude : 33.149075
Longitude : -117.195284
Last Date in Agency List : 2022-01-12

Facility Name : WHITING CABINET & CONSTRUCTION
Facility Address : 120 NORTH PACIFIC STREET, SAN MARCOS, CA 92069

Site Details
NPDES ID : CAZ479875
ICIS Facility Interest ID : 3600735852
Facility UIN : 110070097065
Facility Type Code : Privately Owned Facility
Impaired Waters : N/R
Latitude : 33.14921
Longitude : -117.195753
Last Date in Agency List : 2022-01-12

Facility SIC
SIC Code : 2434
SIC Description : Wood Kitchen Cabinets

Facility Name : WORLDWIDE AMMUNITION DISTRIBUTION
Facility Address : 120 N PACIFIC ST STE G5, SAN MARCOS, CA 92069

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

ICIS ***(cont.)***

Site Details

NPDES ID :	CAZ520383
ICIS Facility Interest ID :	3601198948
Facility UIN :	110070793052
Facility Type Code :	Privately Owned Facility
Impaired Waters :	N/R
Latitude :	33.14878
Longitude :	-117.1946
Last Date in Agency List :	2022-01-12

Facility SIC

SIC Code :	3482
SIC Description :	Small Arms Ammunition

INACTIVE PCS

Issue Date :	2016-12-06
Original Issue Date :	2016-12-06
Effective Date :	2016-12-06
Expiration Date :	2020-06-30
Retirement Date :	N/R
Termination Date :	N/R
Issuing Agency :	CA Waterboards
Agency Type :	State
Activity ID :	3601115026
External Permit Number :	CAZ478131
Facility Type Indicator :	NON-POTW
Permit Type :	General Permit Covered Facility-NPDES)
Major Minor Status :	N
Permit Status :	Expired
Total Design Flow Number :	N/R
Actual Average Flow Number :	N/R
State Water Body :	N/R
State Water Body Name :	N/R
Permit Name :	Audience AV Inc
Permit Comp Status :	Y
RNC Tracking :	Y
Master External Permit Number :	CAS000001
TMDL Interface :	N/R
EDMR Authorization :	N
Pretreatment Indicator :	N/R
Last Date in Agency List :	2022-01-14

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

INACTIVE PCS ***(cont.)***

Issue Date :	2016-10-12
Original Issue Date :	2016-10-12
Effective Date :	2016-10-12
Expiration Date :	2020-06-30
Retirement Date :	N/R
Termination Date :	2019-10-23
Issuing Agency :	CA Waterboards
Agency Type :	State
Activity ID :	3601115078
External Permit Number :	CAZ478586
Facility Type Indicator :	NON-POTW
Permit Type :	General Permit Covered Facility-NPDES)
Major Minor Status :	N
Permit Status :	Terminated
Total Design Flow Number :	N/R
Actual Average Flow Number :	N/R
State Water Body :	N/R
State Water Body Name :	N/R
Permit Name :	San Diego Kitchen Pros
Permit Comp Status :	Y
RNC Tracking :	Y
Master External Permit Number :	CAS000001
TMDL Interface :	N/R
EDMR Authorization :	N
Pretreatment Indicator :	N/R
Last Date in Agency List :	2022-01-14

Issue Date :	2016-09-30
Original Issue Date :	2016-09-30
Effective Date :	2016-09-30
Expiration Date :	2020-06-30
Retirement Date :	N/R
Termination Date :	2019-10-23
Issuing Agency :	CA Waterboards
Agency Type :	State
Activity ID :	3601114997
External Permit Number :	CAZ477829
Facility Type Indicator :	NON-POTW
Permit Type :	General Permit Covered Facility-NPDES)
Major Minor Status :	N
Permit Status :	Terminated
Total Design Flow Number :	N/R
Actual Average Flow Number :	N/R
State Water Body :	N/R
State Water Body Name :	N/R

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

INACTIVE PCS ***(cont.)***

Permit Name :	Sunrise Spa Covers Manufacturing
Permit Comp Status :	Y
RNC Tracking :	Y
Master External Permit Number :	CAS000001
TMDL Interface :	N/R
EDMR Authorization :	N
Pretreatment Indicator :	N/R
Last Date in Agency List :	2022-01-14

Issue Date :	2020-05-14
Original Issue Date :	2020-05-14
Effective Date :	2020-05-14
Expiration Date :	2020-06-30
Retirement Date :	N/R
Termination Date :	N/R
Issuing Agency :	CA Waterboards
Agency Type :	State
Activity ID :	3602197827
External Permit Number :	CAZ520383
Facility Type Indicator :	NON-POTW
Permit Type :	General Permit Covered Facility-NPDES)
Major Minor Status :	N
Permit Status :	Expired
Total Design Flow Number :	N/R
Actual Average Flow Number :	N/R
State Water Body :	N/R
State Water Body Name :	N/R
Permit Name :	Worldwide Ammunition Distribution
Permit Comp Status :	Y
RNC Tracking :	Y
Master External Permit Number :	CAS000001
TMDL Interface :	N/R
EDMR Authorization :	N
Pretreatment Indicator :	N/R
Last Date in Agency List :	2022-01-14

Issue Date :	2020-03-20
Original Issue Date :	2020-03-20
Effective Date :	2020-03-20
Expiration Date :	2020-06-30
Retirement Date :	N/R
Termination Date :	N/R
Issuing Agency :	CA Waterboards
Agency Type :	State

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

INACTIVE PCS ***(cont.)***

Activity ID :	3602154416
External Permit Number :	CAZ518604
Facility Type Indicator :	NON-POTW
Permit Type :	General Permit Covered Facility-NPDES)
Major Minor Status :	N
Permit Status :	Expired
Total Design Flow Number :	N/R
Actual Average Flow Number :	N/R
State Water Body :	N/R
State Water Body Name :	N/R
Permit Name :	Sunrise Spa Covers Manufacturing
Permit Comp Status :	Y
RNC Tracking :	Y
Master External Permit Number :	CAS000001
TMDL Interface :	N/R
EDMR Authorization :	N
Pretreatment Indicator :	N/R
Last Date in Agency List :	2022-01-14

Issue Date :	2016-11-09
Original Issue Date :	2016-11-09
Effective Date :	2016-11-09
Expiration Date :	2020-06-30
Retirement Date :	N/R
Termination Date :	2019-01-08
Issuing Agency :	CA Waterboards
Agency Type :	State
Activity ID :	3601115226
External Permit Number :	CAZ479875
Facility Type Indicator :	NON-POTW
Permit Type :	General Permit Covered Facility-NPDES)
Major Minor Status :	N
Permit Status :	Terminated
Total Design Flow Number :	N/R
Actual Average Flow Number :	N/R
State Water Body :	N/R
State Water Body Name :	N/R
Permit Name :	Whiting Cabinet & Construction
Permit Comp Status :	Y
RNC Tracking :	Y
Master External Permit Number :	CAS000001
TMDL Interface :	N/R
EDMR Authorization :	N
Pretreatment Indicator :	N/R
Last Date in Agency List :	2022-01-14

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

NPDES - CA

Facility Name :	Audience AV Inc
Facility Address :	120 N Pacific Street, San Marcos, 92069
County :	San Diego
Effective Date :	2016-12-06
Adoption Date :	N/R
Expiration Date :	N/R
Termination Date :	N/R
Order Number :	97-03-DWQ
NPDES Number :	CAS000001
WDID :	9 37NEC002782
RM Status :	Active
Reg Meas ID :	478131
Reg Meas Type :	Enrollee
Program :	Industrial
Facility Place ID :	N/R
Region Code :	9
Discharger ID :	0
Discharger :	Audience AV Inc
Discharger Address :	120 N Pacific Street, San Marcos, California 92069
Last Date in Agency List :	2022-02-24

Facility Name :	McCallas Fine Furniture
Facility Address :	120 North Pacific Street, San Marcos, 92069
County :	San Diego
Effective Date :	2017-02-24
Adoption Date :	N/R
Expiration Date :	N/R
Termination Date :	2017-03-01
Order Number :	97-03-DWQ
NPDES Number :	CAS000001
WDID :	9 37NEC003014
RM Status :	Terminated
Reg Meas ID :	483831
Reg Meas Type :	Enrollee
Program :	Industrial
Facility Place ID :	N/R
Region Code :	9
Discharger ID :	0
Discharger :	McCallas Fine Furniture
Discharger Address :	120 North Pacific Street, San Marcos, California 92069
Last Date in Agency List :	2020-01-23

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

NPDES - CA ***(cont.)***

Facility Name :	San Diego Kitchen Pros
Facility Address :	120 North Pacific Street, Suite B2, San Marcos, 92069
County :	San Diego
Effective Date :	2016-10-12
Adoption Date :	N/R
Expiration Date :	N/R
Termination Date :	2019-10-23
Order Number :	97-03-DWQ
NPDES Number :	CAS000001
WDID :	9 37NEC002609
RM Status :	Terminated
Reg Meas ID :	478586
Reg Meas Type :	Enrollee
Program :	Industrial
Facility Place ID :	N/R
Region Code :	9
Discharger ID :	0
Discharger :	San Diego Kitchen Pros
Discharger Address :	120 North Pacific Street, San Marcos, California 92069
Last Date in Agency List :	2022-02-24

Facility Name :	Sunrise Spa Covers Manufacturing
Facility Address :	120 North Pacific Street Suite H5, San Diego, 92069
County :	San Diego
Effective Date :	2016-09-30
Adoption Date :	N/R
Expiration Date :	N/R
Termination Date :	2019-10-23
Order Number :	97-03-DWQ
NPDES Number :	CAS000001
WDID :	9 37NEC002575
RM Status :	Terminated
Reg Meas ID :	477829
Reg Meas Type :	Enrollee
Program :	Industrial
Facility Place ID :	N/R
Region Code :	9
Discharger ID :	0
Discharger :	Sunrise Spa Covers Manufacturing
Discharger Address :	120 North Pacific Street Suite H5, San Marcos, California 92069
Last Date in Agency List :	2022-02-24

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

NPDES - CA ***(cont.)***

Facility Name :	Sunrise Spa Covers Manufacturing
Facility Address :	120 North Pacific Street Suite H5, San Marcos, 92069
County :	San Diego
Effective Date :	2020-03-20
Adoption Date :	N/R
Expiration Date :	N/R
Termination Date :	N/R
Order Number :	97-03-DWQ
NPDES Number :	CAS000001
WDID :	9 37NEC006405
RM Status :	Active
Reg Meas ID :	518604
Reg Meas Type :	Enrollee
Program :	Industrial
Facility Place ID :	N/R
Region Code :	9
Discharger ID :	0
Discharger :	Sunrise Spa Covers Manufacturing
Discharger Address :	120 North Pacific Street Suite H5, San Marcos, California 92069
Last Date in Agency List :	2022-02-24

Facility Name :	Whiting Cabinet & Construction
Facility Address :	120 North Pacific Street, San Marcos, 92069
County :	San Diego
Effective Date :	2016-11-09
Adoption Date :	N/R
Expiration Date :	N/R
Termination Date :	2019-01-08
Order Number :	97-03-DWQ
NPDES Number :	CAS000001
WDID :	9 37NEC002693
RM Status :	Terminated
Reg Meas ID :	479875
Reg Meas Type :	Enrollee
Program :	Industrial
Facility Place ID :	N/R
Region Code :	9
Discharger ID :	0
Discharger :	Whiting Cabinet & Construction
Discharger Address :	120 North Pacific Street H1, San Marcos, California 92069
Last Date in Agency List :	2021-12-07

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

NPDES - CA ***(cont.)***

Facility Name :	Worldwide Ammunition Distribution
Facility Address :	120 N Pacific St Ste G5, San Marcos, 92069
County :	San Diego
Effective Date :	2020-05-14
Adoption Date :	N/R
Expiration Date :	N/R
Termination Date :	N/R
Order Number :	97-03-DWQ
NPDES Number :	CAS000001
WDID :	9 37NEC006673
RM Status :	Active
Reg Meas ID :	520383
Reg Meas Type :	Enrollee
Program :	Industrial
Facility Place ID :	N/R
Region Code :	9
Discharger ID :	0
Discharger :	Worldwide Ammunition Distribution
Discharger Address :	120 N Pacific Street Ste E5, San Marcos, California 92069
Last Date in Agency List :	2022-02-24

PCS FACILITY

Issue Date :	2016-10-12
Original Issue Date :	2016-10-12
Effective Date :	2016-10-12
Expiration Date :	2020-06-30
Retirement Date :	N/R
Termination Date :	N/R
Issuing Agency :	CA Waterboards
Agency Type :	State
Activity ID :	3601115078
External Permit Number :	CAZ478586
Facility Type Indicator :	NON-POTW
Permit Type :	General Permit Covered Facility-NPDES)
Major Minor Status :	N
Permit Status :	Effective
Total Design Flow Number :	N/R
Actual Average Flow Number :	N/R
State Water Body :	N/R
State Water Body Name :	N/R
Permit Name :	San Diego Kitchen Pros
Permit Comp Status :	Y
RNC Tracking :	Y

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

PCS FACILITY ***(cont.)***

Master External Permit Number :	CAS000001
TMDL Interface :	N/R
EDMR Authorization :	N
Pretreatment Indicator :	N/R
Last Date in Agency List :	2019-09-24

Issue Date :	2016-11-09
Original Issue Date :	2016-11-09
Effective Date :	2016-11-09
Expiration Date :	2020-06-30
Retirement Date :	N/R
Termination Date :	N/R
Issuing Agency :	CA Waterboards
Agency Type :	State
Activity ID :	3601115226
External Permit Number :	CAZ479875
Facility Type Indicator :	NON-POTW
Permit Type :	General Permit Covered Facility-NPDES)
Major Minor Status :	N
Permit Status :	Effective
Total Design Flow Number :	N/R
Actual Average Flow Number :	N/R
State Water Body :	N/R
State Water Body Name :	N/R
Permit Name :	Whiting Cabinet & Construction
Permit Comp Status :	Y
RNC Tracking :	Y
Master External Permit Number :	CAS000001
TMDL Interface :	N/R
EDMR Authorization :	N
Pretreatment Indicator :	N/R
Last Date in Agency List :	2018-12-18

Issue Date :	2016-12-06
Original Issue Date :	2016-12-06
Effective Date :	2016-12-06
Expiration Date :	2020-06-30
Retirement Date :	N/R
Termination Date :	N/R
Issuing Agency :	CA Waterboards
Agency Type :	State
Activity ID :	3601115026
External Permit Number :	CAZ478131
Facility Type Indicator :	NON-POTW

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

PCS FACILITY ***(cont.)***

Permit Type :	General Permit Covered Facility-NPDES)
Major Minor Status :	N
Permit Status :	Effective
Total Design Flow Number :	N/R
Actual Average Flow Number :	N/R
State Water Body :	N/R
State Water Body Name :	N/R
Permit Name :	Audience AV Inc
Permit Comp Status :	Y
RNC Tracking :	Y
Master External Permit Number :	CAS000001
TMDL Interface :	N/R
EDMR Authorization :	N
Pretreatment Indicator :	N/R
Last Date in Agency List :	2020-02-11

Issue Date :	2016-09-30
Original Issue Date :	2016-09-30
Effective Date :	2016-09-30
Expiration Date :	2020-06-30
Retirement Date :	N/R
Termination Date :	N/R
Issuing Agency :	CA Waterboards
Agency Type :	State
Activity ID :	3601114997
External Permit Number :	CAZ477829
Facility Type Indicator :	NON-POTW
Permit Type :	General Permit Covered Facility-NPDES)
Major Minor Status :	N
Permit Status :	Effective
Total Design Flow Number :	N/R
Actual Average Flow Number :	N/R
State Water Body :	N/R
State Water Body Name :	N/R
Permit Name :	Sunrise Spa Covers Manufacturing
Permit Comp Status :	Y
RNC Tracking :	Y
Master External Permit Number :	CAS000001
TMDL Interface :	N/R
EDMR Authorization :	N
Pretreatment Indicator :	N/R
Last Date in Agency List :	2019-09-24

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

RCRA_SQG

Facility Name :	CASEYS AUTO MACHINE
Facility Address :	120 N PACIFIC ST STE G3, SAN MARCOS, CA 92069
County :	SAN DIEGO
Date Form Received by Agency :	2000-03-07
EPA ID :	CAR000067124
Mailing Address :	120 N PACIFIC ST STE G3, SAN MARCOS, CA 92069
Contact :	CASEY RUMMERFIELD
Contact Address :	1416 SHADOW HILLS DR, SAN MARCOS, CA 92069
Contact Country :	US
Contact Telephone :	760-591-3450
Contact Email :	N/R
EPA Region :	09
Land Type :	Private
Source Type :	Notification
Classification :	Small Quantity Generator
Description :	Handlers that generate more than 100 and less than 1000 kilograms of hazardous waste during any calendar month and accumulate less than 6000 kg of hazardous waste at any time; or generate 100 kg or less of hazardous waste during any calendar month, and accumulate more than 1000 kg of hazardous waste at any time.
Last Date in Agency List :	2022-01-25

Owner/Operator Summary

Owner/Operator Name :	CASEY RUMMERFIELD
Owner/Operator Address :	1416 SHADOW HILLS DR, SAN MARCOS, CA 92069
Owner/Operator Country :	N/R
Owner/Operator Telephone :	760-741-4925
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Private
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N
Recycler of Hazardous Waste :	N

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

RCRA_SQG ***(cont.)***

Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Hazardous Waste Summary

Waste Code / Name :	D039 - TETRACHLOROETHYLENE

Notices of Violations Summary

Regulation Violated :	N

Facility Name :	OLD FORD GARAGE
Facility Address :	120 N PACIFIC ST UNIT K6, SAN MARCOS, CA 92069
County :	SAN DIEGO
Date Form Received by Agency :	1996-09-01
EPA ID :	CAD121704688
Mailing Address :	120 N PACIFIC ST UNIT K6, SAN MARCOS, CA 92069
Contact :	N/R
Contact Address :	N/R
Contact Country :	US
Contact Telephone :	N/R
Contact Email :	N/R
EPA Region :	09
Land Type :	Not Reported
Source Type :	Implementer
Classification :	Small Quantity Generator

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

RCRA_SQG ***(cont.)***

Description : Handlers that generate more than 100 and less than 1000 kilograms of hazardous waste during any calendar month and accumulate less than 6000 kg of hazardous waste at any time; or generate 100 kg or less of hazardous waste during any calendar month, and accumulate more than 1000 kg of hazardous waste at any time.

Last Date in Agency List : 2022-01-25

Owner/Operator Summary

Owner/Operator Name :	JAMES NORMAN
Owner/Operator Address :	NOT REQUIRED, NOT REQUIRED, ME 99999
Owner/Operator Country :	N/R
Owner/Operator Telephone :	415-555-1212
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Private
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Owner/Operator Name :	NOT REQUIRED
Owner/Operator Address :	NOT REQUIRED, NOT REQUIRED, ME 99999
Owner/Operator Country :	N/R
Owner/Operator Telephone :	415-555-1212
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Private
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

RCRA_SQG ***(cont.)***

Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Notices of Violations Summary

Regulation Violated :	N

RFR - CA

Facility Name :	Audience AV Inc
Facility Address :	120 N Pacific Street Suite K9, San Marcos, CA 92069
County :	San Diego
Effective Date :	2016-12-06
Adoption Date :	N/R
Termination Date :	N/R
Expiration/Review Date :	N/R
NPDES Number :	CAS000001
Order Number :	2014-0057-DWQ
WDID :	9 37NEC002782
SIC/NAICS :	3651
Program :	INDSTW
Regulatory Measure Status :	Active
Regulatory Measure Type :	Storm water industrial
Place/Project Type :	Industrial - Household Audio and Video Equipment
Region :	9
Design Flow :	N/R
Major/Minor :	N/R
Complexity :	N/R
TTWQ :	N/R
Number of Enforcement Actions within Five Years:	N/R
Number of Violations within Five Years:	N/R
Agency :	Audience AV Inc
Agency Address :	120 N Pacific Street Suite K9, San Marcos, CA 92069
Latitude :	33.148545
Longitude :	-117.195011
Last Date in Agency List :	2022-03-07

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

RFR - CA ***(cont.)***

Facility Name :	San Diego Kitchen Pros
Facility Address :	120 North Pacific Street, Suite B2, San Marcos, CA 92069
County :	San Diego
Effective Date :	2016-10-12
Adoption Date :	N/R
Termination Date :	N/R
Expiration/Review Date :	N/R
NPDES Number :	CAS000001
Order Number :	2014-0057-DWQ
WDID :	9 37NEC002609
SIC/NAICS :	2434
Program :	INDSTW
Regulatory Measure Status :	Active
Regulatory Measure Type :	Storm water industrial
Place/Project Type :	Industrial - Wood Kitchen Cabinets
Region :	9
Design Flow :	N/R
Major/Minor :	N/R
Complexity :	N/R
TTWQ :	N/R
Number of Enforcement Actions within Five Years:	N/R
Number of Violations within Five Years:	N/R
Agency :	San Diego Kitchen Pros
Agency Address :	120 North Pacific Street Suite B2, San Marcos, CA 92069
Latitude :	32.71573
Longitude :	-117.16108
Last Date in Agency List :	2019-09-09
Facility Name :	Sunrise Spa Covers Manufacturing
Facility Address :	120 North Pacific Street Suite H5, San Diego, CA 92069
County :	San Diego
Effective Date :	2016-09-30
Adoption Date :	N/R
Termination Date :	N/R
Expiration/Review Date :	N/R
NPDES Number :	CAS000001
Order Number :	2014-0057-DWQ
WDID :	9 37NEC002575
SIC/NAICS :	3999
Program :	INDSTW

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

RFR - CA ***(cont.)***

Regulatory Measure Status :	Active
Regulatory Measure Type :	Storm water industrial
Place/Project Type :	Industrial - Manufacturing Industries, NEC
Region :	9
Design Flow :	N/R
Major/Minor :	N/R
Complexity :	N/R
TTWQ :	N/R
Number of Enforcement Actions within Five Years:	N/R
Number of Violations within Five Years:	N/R
Agency :	Sunrise Spa Covers Manufacturing
Agency Address :	120 North Pacific Street Suite H5, San Marcos, CA 92069
Latitude :	33.149075
Longitude :	-117.195284
Last Date in Agency List :	2019-09-09
Facility Name :	Sunrise Spa Covers Manufacturing
Facility Address :	120 North Pacific Street Suite H5, San Marcos, CA 92069
County :	San Diego
Effective Date :	2020-03-20
Adoption Date :	N/R
Termination Date :	N/R
Expiration/Review Date :	N/R
NPDES Number :	CAS000001
Order Number :	2014-0057-DWQ
WDID :	9 37NEC006405
SIC/NAICS :	3999
Program :	INDSTW
Regulatory Measure Status :	Active
Regulatory Measure Type :	Storm water industrial
Place/Project Type :	Industrial - Manufacturing Industries, NEC
Region :	9
Design Flow :	N/R
Major/Minor :	N/R
Complexity :	N/R
TTWQ :	N/R
Number of Enforcement Actions within Five Years:	N/R
Number of Violations within Five Years:	N/R
Agency :	Sunrise Spa Covers Manufacturing
Agency Address :	120 North Pacific Street Suite H5, San Marcos, CA 92069
Latitude :	33.14865

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

RFR - CA ***(cont.)***

Longitude :	-117.1951
Last Date in Agency List :	2022-03-07
Facility Name :	Whiting Cabinet & Construction
Facility Address :	120 North Pacific Street H-1, San Marcos, CA 92069
County :	San Diego
Effective Date :	2016-11-09
Adoption Date :	N/R
Termination Date :	N/R
Expiration/Review Date :	N/R
NPDES Number :	CAS000001
Order Number :	2014-0057-DWQ
WDID :	9 37NEC002693
SIC/NAICS :	2434
Program :	INDSTW
Regulatory Measure Status :	Active
Regulatory Measure Type :	Storm water industrial
Place/Project Type :	Industrial - Wood Kitchen Cabinets
Region :	9
Design Flow :	N/R
Major/Minor :	N/R
Complexity :	N/R
TTWQ :	N/R
Number of Enforcement Actions within Five Years:	N/R
Number of Violations within Five Years:	N/R
Agency :	Whiting Cabinet & Construction
Agency Address :	120 North Pacific Street H1 H1, San Marcos, CA 92069
Latitude :	33.14921
Longitude :	-117.195753
Last Date in Agency List :	2019-02-11
Facility Name :	Worldwide Ammunition Distribution
Facility Address :	120 N Pacific St Ste G5, San Marcos, CA 92069
County :	San Diego
Effective Date :	2020-05-14
Adoption Date :	N/R
Termination Date :	N/R
Expiration/Review Date :	N/R
NPDES Number :	CAS000001

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

RFR - CA ***(cont.)***

Order Number :	2014-0057-DWQ
WDID :	9 37NEC006673
SIC/NAICS :	3482
Program :	INDSTW
Regulatory Measure Status :	Active
Regulatory Measure Type :	Storm water industrial
Place/Project Type :	Industrial - Small Arms Ammunition
Region :	9
Design Flow :	N/R
Major/Minor :	N/R
Complexity :	N/R
TTWQ :	N/R
Number of Enforcement Actions within Five Years:	N/R
Number of Violations within Five Years:	N/R
Agency :	Worldwide Ammunition Distribution
Agency Address :	120 N Pacific Street Ste E5, San Marcos, CA 92069
Latitude :	33.14878
Longitude :	-117.1946
Last Date in Agency List :	2022-03-07

STORMWATER

Facility Name :	AUDIENCE AV INC
Facility Address :	120 N PACIFIC STREET, SAN MARCOS, CA 92069
NPDES ID :	CAZ478131
Permittee Name :	Audience AV Inc
Permit Status :	Expired
Permit Issuing Name :	State
Issued Date :	2016-12-06
Termination Date :	N/R
Effective Date :	2016-12-06 2020-06-30
EPA Region :	09
SIC Code :	3651
NAICS Code :	N/R
EJ Indexes Above 80th Percentile :	Y
Significant Noncompliance Status :	N/R
Quarters with Noncompliance :	0
Industrial Stormwater Formal Enforcement Actions:	N/R
Facility Map Flag :	Y
DRF URL :	Click here for hyperlink provided by the agency.
Latitude :	33.148545

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

STORMWATER ***(cont.)***

Longitude :	-117.195011
Last Date in Agency List :	2022-01-11
Facility Name :	SAN DIEGO KITCHEN PROS
Facility Address :	120 NORTH PACIFIC STREET, SUITE B2, SAN MARCOS, CA 92069
NPDES ID :	CAZ478586
Permittee Name :	San Diego Kitchen Pros
Permit Status :	Terminated
Permit Issuing Name :	State
Issued Date :	2016-10-12
Termination Date :	2019-10-23
Effective Date :	2016-10-12 2020-06-30
EPA Region :	09
SIC Code :	2434
NAICS Code :	N/R
EJ Indexes Above 80th Percentile :	Y
Significant Noncompliance Status :	N/R
Quarters with Noncompliance :	1
Industrial Stormwater Formal Enforcement Actions:	N/R
Facility Map Flag :	Y
DRF URL :	Click here for hyperlink provided by the agency.
Latitude :	32.71573
Longitude :	-117.16108
Last Date in Agency List :	2022-01-11
Facility Name :	SUNRISE SPA COVERS MANUFACTURING
Facility Address :	120 NORTH PACIFIC STREET SUITE H5, SAN DIEGO, CA 92069
NPDES ID :	CAZ477829
Permittee Name :	Sunrise Spa Covers Manufacturing
Permit Status :	Terminated
Permit Issuing Name :	State
Issued Date :	2016-09-30
Termination Date :	2019-10-23
Effective Date :	2016-09-30 2020-06-30
EPA Region :	09
SIC Code :	3999
NAICS Code :	N/R

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

STORMWATER ***(cont.)***

EJ Indexes Above 80th Percentile :	Y
Significant Noncompliance Status :	N/R
Quarters with Noncompliance :	1
Industrial Stormwater Formal Enforcement Actions:	N/R
Facility Map Flag :	Y
DRF URL :	Click here for hyperlink provided by the agency.
Latitude :	33.149075
Longitude :	-117.195284
Last Date in Agency List :	2022-01-11
Facility Name :	SUNRISE SPA COVERS MANUFACTURING
Facility Address :	120 NORTH PACIFIC STREET SUITE H5, SAN MARCOS, CA 92069
NPDES ID :	CAZ518604
Permittee Name :	Sunrise Spa Covers Manufacturing
Permit Status :	Expired
Permit Issuing Name :	State
Issued Date :	2020-03-20
Termination Date :	N/R
Effective Date :	2020-03-20 2020-06-30
EPA Region :	09
SIC Code :	3999
NAICS Code :	N/R
EJ Indexes Above 80th Percentile :	Y
Significant Noncompliance Status :	N/R
Quarters with Noncompliance :	0
Industrial Stormwater Formal Enforcement Actions:	N/R
Facility Map Flag :	Y
DRF URL :	Click here for hyperlink provided by the agency.
Latitude :	33.149075
Longitude :	-117.195284
Last Date in Agency List :	2022-01-11
Facility Name :	WHITING CABINET & CONSTRUCTION
Facility Address :	120 NORTH PACIFIC STREET, SAN MARCOS, CA 92069
NPDES ID :	CAZ479875
Permittee Name :	Whiting Cabinet & Construction
Permit Status :	Terminated

Map Id: I73
Direction: SSE
Distance: 0.201 mi., 1061 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Sunrise Spa Covers Manufacturing | AUDIENCE AV INC | San Diego Kitchen Pros
120 N PACIFIC ST | 120 NORTH PACIFIC STREET SUITE H5 | 120 NORTH PACIFIC STREET, SUITE B2
SAN MARCOS | San Marcos | SAN DIEGO, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 280139
EPA ID: N/R

STORMWATER ***(cont.)***

Permit Issuing Name :	State
Issued Date :	2016-11-09
Termination Date :	2019-01-08
Effective Date :	2016-11-09
	2020-06-30
EPA Region :	09
SIC Code :	2434
NAICS Code :	N/R
EJ Indexes Above 80th Percentile :	Y
Significant Noncompliance Status :	N/R
Quarters with Noncompliance :	0
Industrial Stormwater Formal Enforcement Actions:	N/R
Facility Map Flag :	Y
DRF URL :	Click here for hyperlink provided by the agency.
Latitude :	33.14921
Longitude :	-117.195753
Last Date in Agency List :	2022-01-11

Facility Name :	WORLDWIDE AMMUNITION DISTRIBUTION
Facility Address :	120 N PACIFIC ST STE G5, SAN MARCOS, CA 92069

NPDES ID :	CAZ520383
Permittee Name :	Worldwide Ammunition Distribution
Permit Status :	Expired
Permit Issuing Name :	State
Issued Date :	2020-05-14
Termination Date :	N/R
Effective Date :	2020-05-14
	2020-06-30
EPA Region :	09
SIC Code :	3482
NAICS Code :	N/R
EJ Indexes Above 80th Percentile :	Y
Significant Noncompliance Status :	N/R
Quarters with Noncompliance :	0
Industrial Stormwater Formal Enforcement Actions:	N/R
Facility Map Flag :	Y
DRF URL :	Click here for hyperlink provided by the agency.
Latitude :	33.14878
Longitude :	-117.1946
Last Date in Agency List :	2022-01-11

Map Id: I74
Direction: SSE
Distance: 0.201 mi., 1063 ft.
Elevation: 565 ft.
Relative: Lower

Site Name : MOTOTECH DIVISION OF JADAT INC | PACIFIC BODY & PAINT | EXTREME RACING MOTORSPORTS INC
120 N PACIFIC AVE #D6 | 120 N PACIFIC ST BLDG E3 | 120 N PACIFIC ST STE E-2
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 40999525
EPA ID: CAL000171316

HAZNET - CA

Facility Name : CASEY'S AUTO MACHINE
Facility Address : 120 N PACIFIC ST STE G2 & G3, SAN MARCOS, CA 92069
County : SAN DIEGO

Site Details
Generator EPA ID : CAL000171316
Active : Inactive
Category : STATE
Facility Types : N/R
Type : PERMANENT
Contact Name : N/R
Contact Phone : N/R
Facility Mailing Address : 120 N PACIFIC ST STE G2 & G3, SAN MARCOS, CA 920690000
Latitude : 33.14818460
Longitude : -117.19417119
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2021-07-08

Facility Name : EXTREME RACING MOTORSPORTS INC
Facility Address : 120 N PACIFIC ST BLDG E3, SAN MARCOS, CA 92069
County : SAN DIEGO

Site Details
Generator EPA ID : CAL000249372
Active : Inactive
Category : STATE
Facility Types : N/R
Type : PERMANENT
Contact Name : N/R
Contact Phone : N/R
Facility Mailing Address : 120 N PACIFIC ST #E-2, SAN MARCOS, CA 920690000
Latitude : 33.14818460
Longitude : -117.19417119
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2021-07-08

Facility Name : FURNITURE MEDIC
Facility Address : 120 N PACIFIC ST STE K-4, SAN MARCOS, CA 92069
County : SAN DIEGO

Site Details
Generator EPA ID : CAL000286395
Active : Inactive
Category : STATE
Facility Types : N/R
Type : PERMANENT

Map Id: I74
Direction: SSE
Distance: 0.201 mi., 1063 ft.
Elevation: 565 ft.
Relative: Lower

Site Name : MOTOTECH DIVISION OF JADAT INC | PACIFIC BODY & PAINT | EXTREME RACING MOTORSPORTS INC
120 N PACIFIC AVE #D6 | 120 N PACIFIC ST BLDG E3 | 120 N PACIFIC ST STE E-2
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 40999525
EPA ID: CAL000171316

HAZNET - CA ***(cont.)***

Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	2408 LA TINADA CT, CARLSBAD, CA 92009
Latitude :	33.14818460
Longitude :	-117.19417119
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08
Facility Name :	JDM REVELATIONS
Facility Address :	120 N PACIFIC ST STE E-2, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000292055
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	120 N PACIFIC ST STE E-2, SAN MARCOS, CA 92069
Latitude :	33.14818460
Longitude :	-117.19417119
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08
Facility Name :	M G M PLASTICS INC
Facility Address :	120 N PACIFIC ST UNIT J-1, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAD982026148
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	120 N PACIFIC ST STE J-1, VISTA, CA 920690000
Latitude :	33.14818460
Longitude :	-117.19417119
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08
Facility Name :	MOTOTECH DIVISION OF JADAT INC
Facility Address :	120 N PACIFIC AVE #D6, SAN MARCOS, CA 92069
County :	SAN DIEGO

Map Id: I74
Direction: SSE
Distance: 0.201 mi., 1063 ft.
Elevation: 565 ft.
Relative: Lower

Site Name : MOTOTECH DIVISION OF JADAT INC | PACIFIC BODY & PAINT | EXTREME RACING MOTORSPORTS INC
120 N PACIFIC AVE #D6 | 120 N PACIFIC ST BLDG E3 | 120 N PACIFIC ST STE E-2
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 40999525
EPA ID: CAL000171316

HAZNET - CA ***(cont.)***

Site Details

Generator EPA ID :	CAL000097949
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	120 N PACIFIC D6, SAN MARCOS, CA 920690000
Latitude :	33.14818460
Longitude :	-117.19417119
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08
Facility Name :	PACIFIC BODY & PAINT
Facility Address :	120 N PACIFIC AVE #D6, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000158938
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	120 N PACIFIC ST STE D6, SAN MARCOS, CA 920691262
Latitude :	33.14818460
Longitude :	-117.19417119
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08
Facility Name :	PURRFORMANCE CENTER
Facility Address :	120 NORTH PACIFIC SUITE D-6, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000076543
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	120 NORTH PACIFIC SUITE D-6, SAN MARCOS, CA 920690000
Latitude :	33.14818460
Longitude :	-117.19417119
Agency Hyperlink :	Click here for hyperlink provided by the agency.

Map Id: I74
Direction: SSE
Distance: 0.201 mi., 1063 ft.
Elevation: 565 ft.
Relative: Lower

Site Name : MOTOTECH DIVISION OF JADAT INC | PACIFIC BODY & PAINT | EXTREME RACING MOTORSPORTS INC
120 N PACIFIC AVE #D6 | 120 N PACIFIC ST BLDG E3 | 120 N PACIFIC ST STE E-2
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 40999525
EPA ID: CAL000171316

HAZNET - CA ***(cont.)***

Last Date in Agency List : 2021-07-08

Facility Name : SUPERBIKE
Facility Address : 120 N PACIFIC SUITE B-2, SAN MARCOS, CA 92069
County : SAN DIEGO

Site Details

Generator EPA ID : CAL000032843
Active : Inactive
Category : STATE
Facility Types : N/R
Type : PERMANENT
Contact Name : N/R
Contact Phone : N/R
Facility Mailing Address : 120 N PACIFIC SUITE B-2, SAN MARCOS, CA 920690000
Latitude : 33.14818460
Longitude : -117.19417119
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2021-07-08

HWG - CA

Facility Name : CASEY'S AUTO MACHINE
Facility Address : 120 N PACIFIC ST STE G2 & G3, SAN MARCOS, CA 92069
County : SAN DIEGO

EPA ID : CAL000171316
Status : Inactive
Category : STATE
Type : PERMANENT
Facility Type : N/R
Mailing Address : 120 N PACIFIC ST STE G2 & G3, SAN MARCOS, CA 920690000
Owner Name : CASEY RUMMERFIELD
Owner Address : 120 N PACIFIC ST STE G2 & G3, SAN MARCOS, CA 920690000
Operator Name : CASEY RUMMERFIELD-OWNER
Operator Address : SAN MARCOS, CA 920690000
Latitude : 33.148185
Longitude : -117.194171

Facility Name : EXTREME RACING MOTORSPORTS INC
Facility Address : 120 N PACIFIC ST BLDG E3, SAN MARCOS, CA 92069
County : SAN DIEGO

EPA ID : CAL000249372
Status : Inactive
Category : STATE
Type : PERMANENT
Facility Type : N/R

Map Id: I74
Direction: SSE
Distance: 0.201 mi., 1063 ft.
Elevation: 565 ft.
Relative: Lower

Site Name : MOTOTECH DIVISION OF JADAT INC | PACIFIC BODY & PAINT | EXTREME RACING MOTORSPORTS INC
120 N PACIFIC AVE #D6 | 120 N PACIFIC ST BLDG E3 | 120 N PACIFIC ST STE E-2
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 40999525
EPA ID: CAL000171316

HWG - CA ***(cont.)***

Mailing Address :	120 N PACIFIC ST #E-2, SAN MARCOS, CA 920690000
Owner Name :	EXTREME RACING MOTOR SPORTS INC
Owner Address :	120 N PACIFIC ST BLDG E3, SAN MARCOS, CA 92069
Operator Name :	BAY TRINH
Operator Address :	120 N PACIFIC ST BLDG E3, SAN MARCOS, CA 92069
Latitude :	33.148185
Longitude :	-117.194171

Facility Name :	FURNITURE MEDIC
Facility Address :	120 N PACIFIC ST STE K-4, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAL000286395
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	2408 LA TINADA CT, CARLSBAD, CA 92009
Owner Name :	MIKE & JEANNE LAWBAUGH
Owner Address :	2408 LA TINADA CT, CARLSBAD, CA 92009
Operator Name :	MIKE LAWBAUGH
Operator Address :	2408 LA TINADA CT, CARLSBAD, CA 92009
Latitude :	33.147717
Longitude :	-117.194382

Facility Name :	JDM REVELATIONS
Facility Address :	120 N PACIFIC ST STE E-2, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAL000292055
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	120 N PACIFIC ST STE E-2, SAN MARCOS, CA 92069
Owner Name :	MARCO RAMIREZ
Owner Address :	1615 MANOR DR, VISTA, CA 92084
Operator Name :	JONATHAN FLORES
Operator Address :	1615 MANOR DR, VISTA, CA 92084
Latitude :	33.148365
Longitude :	-117.194054

Facility Name :	M G M PLASTICS INC
Facility Address :	120 N PACIFIC ST UNIT J-1, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAD982026148
Status :	Inactive

Map Id: I74
Direction: SSE
Distance: 0.201 mi., 1063 ft.
Elevation: 565 ft.
Relative: Lower

Site Name : MOTOTECH DIVISION OF JADAT INC | PACIFIC BODY & PAINT | EXTREME RACING MOTORSPORTS INC
120 N PACIFIC AVE #D6 | 120 N PACIFIC ST BLDG E3 | 120 N PACIFIC ST STE E-2
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 40999525
EPA ID: CAL000171316

HWG - CA ***(cont.)***

Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	120 N PACIFIC ST STE J-1, VISTA, CA 920690000
Owner Name :	MIKE MCMILLEN
Owner Address :	251 POINTSETTIA, VISTA, CA 920830000
Operator Name :	UNDELIVERABLE PER 95 FEES FORM
Operator Address :	NW, N/A
Latitude :	33.148356
Longitude :	-117.194046

Facility Name :	MOTOTECH DIVISION OF JADAT INC
Facility Address :	120 N PACIFIC AVE #D6, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAL000097949
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	120 N PACIFIC D6, SAN MARCOS, CA 920690000
Owner Name :	JADAT INC JOHN THOMAS TRES
Owner Address :	N/A
Operator Name :	NON-DELIVERABLE 4/94 FEE FORM
Operator Address :	N/A
Latitude :	33.148356
Longitude :	-117.194046

Facility Name :	PACIFIC BODY & PAINT
Facility Address :	120 N PACIFIC AVE #D6, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAL000158938
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	120 N PACIFIC ST STE D6, SAN MARCOS, CA 920691262
Owner Name :	PASI KALLUNKI
Owner Address :	120 N PACIFIC AVE #D6, SAN MARCOS, CA 920690000
Operator Name :	GEORGE THOMAS
Operator Address :	UNDELIVERABLE VF97 LC, SAN MARCOS, CA 920690000
Latitude :	33.148356
Longitude :	-117.194046

Facility Name :	PURRFORMANCE CENTER
Facility Address :	120 NORTH PACIFIC SUITE D-6, SAN MARCOS, CA 92069
County :	SAN DIEGO

Map Id: I74
Direction: SSE
Distance: 0.201 mi., 1063 ft.
Elevation: 565 ft.
Relative: Lower

Site Name : MOTOTECH DIVISION OF JADAT INC | PACIFIC BODY & PAINT | EXTREME RACING MOTORSPORTS INC
120 N PACIFIC AVE #D6 | 120 N PACIFIC ST BLDG E3 | 120 N PACIFIC ST STE E-2
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 40999525
EPA ID: CAL000171316

HWG - CA ***(cont.)***

EPA ID :	CAL000076543
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	120 NORTH PACIFIC SUITE D-6, SAN MARCOS, CA 920690000
Owner Name :	DUFRENE ED
Owner Address :	N/A
Operator Name :	MOVED
Operator Address :	N/A
Latitude :	33.148356
Longitude :	-117.194046

Facility Name :	SUPERBIKE
Facility Address :	120 N PACIFIC SUITE B-2, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAL000032843
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	120 N PACIFIC SUITE B-2, SAN MARCOS, CA 920690000
Owner Name :	BIGGS WILLIAM OWNER
Owner Address :	N/A
Operator Name :	UNDELIVERABLE PER SURVEY
Operator Address :	INACTIVE PER NON DELIVERABLE, N/A
Latitude :	33.148356
Longitude :	-117.194046

Map Id: L75
Direction: WNW
Distance: 0.203 mi., 1073 ft.
Elevation: 611 ft.
Relative: Higher

Site Name : LUIS RODRIGUEZ
3518 CAPALINA ROAD
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 935925
EPA ID: CAC002908072

HAZNET - CA

Facility Name :	LUIS RODRIGUEZ
Facility Address :	3518 CAPALINA ROAD, SAN MARCOS, CA 92069
County :	SAN DIEGO

Map Id: L75
Direction: WNW
Distance: 0.203 mi., 1073 ft.
Elevation: 611 ft.
Relative: Higher

Site Name : LUIS RODRIGUEZ
3518 CAPALINA ROAD
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 935925
EPA ID: CAC002908072

HAZNET - CA ***(cont.)***

Site Details

Generator EPA ID :	CAC002908072
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	3518 CAPALINA ROAD, SAN MARCOS, CA 92069
Latitude :	33.15251618
Longitude :	-117.19905032
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	2017: 151 - Asbestos containing waste, 2.07 tons to

HWG - CA

Facility Name :	LUIS RODRIGUEZ
Facility Address :	3518 CAPALINA ROAD, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAC002908072
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	3518 CAPALINA ROAD, SAN MARCOS, CA 92069
Owner Name :	LUIS RODRIGUEZ
Owner Address :	3518 CAPALINA ROAD, SAN MARCOS, CA 92069
Operator Name :	LUIS RODRIGUEZ
Operator Address :	3518 CAPALINA ROAD, SAN MARCOS, CA 92069
Latitude :	-90.0
Longitude :	180.0

Map Id: I76
Direction: SSE
Distance: 0.203 mi., 1075 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Old World Wood | PIONEER INDUSTRIAL PARK | BEST AUTO BODY AND FRAME
120 N PACIFIC ST STE D4 | 120 N PACIFIC STE G3 | 120 N PACIFIC
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER]

Envirosite ID: 512104
EPA ID: CAL000000385

CALEPA SITES - CA

Facility Name :	Old World Wood
Facility Address :	120 N PACIFIC ST STE D4, SAN MARCOS, 92009
Site ID :	538354
EI ID :	849303
EI Description :	Industrial Facility Storm Water
Latitude :	33.143400
Longitude :	-117.166100
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2019-07-24

CIWQS - CA

Facility Name :	GLASS IMPRESSIONS BY D ALAN
Facility Address :	120 PACIFIC STREET A10, SAN MARCOS, CA 92069
County :	SAN DIEGO
Place ID :	S804994
Agency Name :	DAVID A KALOC
Last Date in Agency List :	2021-12-30
Facility Name :	OLD WORLD WOOD
Facility Address :	120 N PACIFIC ST STE D4 3011 SEGOVIA WAY, SAN MARCOS, CA 92009
County :	SAN DIEGO
Place ID :	S849303
Agency Name :	OLD WORLD WOOD
Last Date in Agency List :	2021-12-30

ECHO

Facility Name :	BEST AUTO BODY AND FRAME
Facility Address :	120 N PACIFIC B3, SAN MARCOS, CA 92069
County :	SAN DIEGO
Last Inspection Date :	N/R
Registry ID :	110009545091
FIPS Code :	06073
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0

Map Id: I76
Direction: SSE
Distance: 0.203 mi., 1075 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Old World Wood | PIONEER INDUSTRIAL PARK | BEST AUTO BODY AND FRAME
120 N PACIFIC ST STE D4 | 120 N PACIFIC STE G3 | 120 N PACIFIC
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 512104
EPA ID: CAL000000385

ECHO ***(cont.)***

Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	_____
Collection Method :	ADDRESS MATCHING-HOUSE NUMBER
Reference Point :	CENTER OF A FACILITY OR STATION
Accuracy Meters :	30

Derived Tribes :

San Pasqual Band of Diegueno Mission Indians of California - 12.3 mile(s), Pala Band of Mission Indians - 13.3 mile (s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 14 mile(s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 16.2 mile(s), Pauma Band of Luiseno Mission Indians of the Pauma & Yuima Reservation, California - 16.9 mile(s), La Jolla Band of Luiseno Indians, California - 17.1 mile(s), Pechanga Band of Luiseno Mission Indians of the Pechanga Reservation, California - 20.5 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 22.5 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 22.8 mile(s), Mesa Grande Band of Diegueno Mission Indians of the Mesa Grande Reservation, California - 23.2 mile(s)

Derived HUC :	18070303
Derived WBD :	180703030503
Derived STCTY FIPS :	06073
Derived Zip :	92069
Derived CD113 :	50
Derived CB2010 :	060730200292003
MYRTK Universe :	NNN
NPDES IDs :	N/R
CWA Permit Types :	N/R
CWA Compliance Tracking :	N/R
CWA NAICS :	N/R
CWA SICS :	N/R
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	N/R
CWA Current Compliance Status :	N/R
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	N/R

Map Id: I76
Direction: SSE
Distance: 0.203 mi., 1075 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Old World Wood | PIONEER INDUSTRIAL PARK | BEST AUTO BODY AND FRAME
120 N PACIFIC ST STE D4 | 120 N PACIFIC STE G3 | 120 N PACIFIC
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 512104
EPA ID: CAL000000385

ECHO ***(cont.)***

CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	N/R
Facility NAICS :	N/R
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	Y
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	N
SDWIS Flag :	N
RCRA Flag :	Y
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	Y
NAA Flag :	Y
Latitude :	33.14818
Longitude :	-117.19411
Last Date in Agency List :	2022-01-17

Facility Name :	GLASS IMPRESSIONS BY D ALAN
Facility Address :	120 PACIFIC STREET A10, SAN MARCOS, CA 92069
County :	SAN DIEGO COUNTY

Last Inspection Date :	N/R
Registry ID :	110070084852
FIPS Code :	N/R
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0

Map Id: I76
Direction: SSE
Distance: 0.203 mi., 1075 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Old World Wood | PIONEER INDUSTRIAL PARK | BEST AUTO BODY AND FRAME 120 N PACIFIC ST STE D4 | 120 N PACIFIC STE G3 | 120 N PACIFIC
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 512104
EPA ID: CAL000000385

ECHO ***(cont.)***

Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	N/R
Three-Year Compliance Status :	N/R
Collection Method :	Zip Code Centroid
Reference Point :	N/R
Accuracy Meters :	10000
Derived Tribes :	N/R
Derived HUC :	N/R
Derived WBD :	N/R
Derived STCTY FIPS :	N/R
Derived Zip :	N/R
Derived CD113 :	N/R
Derived CB2010 :	N/R
MYRTK Universe :	NNN
NPDES IDs :	CAW406244
CWA Permit Types :	Minor
CWA Compliance Tracking :	N/R
CWA NAICS :	N/R
CWA SICS :	N/R
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	0
CWA Current Compliance Status :	Not Applicable
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	N/R
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	N/R
Facility NAICS :	N/R
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R

Map Id: I76
Direction: SSE
Distance: 0.203 mi., 1075 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Old World Wood | PIONEER INDUSTRIAL PARK | BEST AUTO BODY AND FRAME
120 N PACIFIC ST STE D4 | 120 N PACIFIC STE G3 | 120 N PACIFIC
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 512104
EPA ID: CAL000000385

ECHO ***(cont.)***

Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	N/R
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	Y
SDWIS Flag :	N
RCRA Flag :	N
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	N/R
NAA Flag :	N
Latitude :	33.194075
Longitude :	-117.16177
Last Date in Agency List :	2022-01-17

Facility Name :	OLD WORLD WOOD
Facility Address :	120 N PACIFIC ST STE D4, SAN MARCOS, CA 92009
County :	SAN DIEGO COUNTY

Last Inspection Date :	N/R
Registry ID :	110070096851
FIPS Code :	06073
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	N/R
Three-Year Compliance Status :	__U
Collection Method :	N/R
Reference Point :	N/R
Accuracy Meters :	34911

Map Id: I76
Direction: SSE
Distance: 0.203 mi., 1075 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Old World Wood | PIONEER INDUSTRIAL PARK | BEST AUTO BODY AND FRAME
120 N PACIFIC ST STE D4 | 120 N PACIFIC STE G3 | 120 N PACIFIC
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 512104
EPA ID: CAL000000385

ECHO ***(cont.)***

Derived Tribes :

San Pasqual Band of Diegueno Mission Indians of California - 10.8 mile(s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 12.8 mile(s), Pala Band of Mission Indians - 12.8 mile(s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 15 mile(s), La Jolla Band of Luiseno Indians, California - 15.8 mile (s), Pauma Band of Luiseno Mission Indians of the Pauma & Yuima Reservation, California - 16.1 mile(s), Pechanga Band of Luiseno Mission Indians of the Pechanga Reservation, California - 20.4 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 21 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 21.3 mile(s), Mesa Grande Band of Diegueno Mission Indians of the Mesa Grande Reservation, California - 21.5 mile(s)

Derived HUC :	18070303
Derived WBD :	180703030503
Derived STCTY FIPS :	06073
Derived Zip :	92069
Derived CD113 :	50
Derived CB2010 :	060730200212016
MYRTK Universe :	NNN
NPDES IDs :	CAZ477351
CWA Permit Types :	Minor
CWA Compliance Tracking :	Off
CWA NAICS :	N/R
CWA SICS :	2434
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	0
CWA Current Compliance Status :	Terminated Permit
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	___U
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	2434
Facility NAICS :	N/R
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R

Map Id: I76
Direction: SSE
Distance: 0.203 mi., 1075 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Old World Wood | PIONEER INDUSTRIAL PARK | BEST AUTO BODY AND FRAME
120 N PACIFIC ST STE D4 | 120 N PACIFIC STE G3 | 120 N PACIFIC
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 512104
EPA ID: CAL000000385

ECHO ***(cont.)***

Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	Y
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	Y
SDWIS Flag :	N
RCRA Flag :	N
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	N/R
NAA Flag :	Y
Latitude :	33.1434
Longitude :	-117.1661
Last Date in Agency List :	2022-01-17
Facility Name :	PIONEER INDUSTRIAL CONDOMINIUMS
Facility Address :	120 N PACIFIC STE G3, SAN MARCOS, CA 92069
County :	SAN DIEGO
Last Inspection Date :	N/R
Registry ID :	110070801197
FIPS Code :	06073
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	_____
Collection Method :	N/R
Reference Point :	N/R
Accuracy Meters :	17531

Map Id: I76
Direction: SSE
Distance: 0.203 mi., 1075 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Old World Wood | PIONEER INDUSTRIAL PARK | BEST AUTO BODY AND FRAME
120 N PACIFIC ST STE D4 | 120 N PACIFIC STE G3 | 120 N PACIFIC
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 512104
EPA ID: CAL000000385

ECHO ***(cont.)***

Derived Tribes :

San Pasqual Band of Diegueno Mission Indians of California - 12.4 mile(s), Pala Band of Mission Indians - 13.3 mile (s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 14.1 mile(s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 16.3 mile(s), Pauma Band of Luiseno Mission Indians of the Pauma & Yuima Reservation, California - 16.9 mile(s), La Jolla Band of Luiseno Indians, California - 17.2 mile(s), Pechanga Band of Luiseno Mission Indians of the Pechanga Reservation, California - 20.5 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 22.5 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 22.9 mile(s), Mesa Grande Band of Diegueno Mission Indians of the Mesa Grande Reservation, California - 23.2 mile(s)

Derived HUC :	18070303
Derived WBD :	180703030503
Derived STCTY FIPS :	06073
Derived Zip :	92069
Derived CD113 :	50
Derived CB2010 :	060730200292005
MYRTK Universe :	NNN
NPDES IDs :	CAZ521733
CWA Permit Types :	Minor
CWA Compliance Tracking :	On
CWA NAICS :	N/R
CWA SICS :	2434
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	0
CWA Current Compliance Status :	No Violation Identified
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	_____
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	2434
Facility NAICS :	N/R
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R

Map Id: I76
Direction: SSE
Distance: 0.203 mi., 1075 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Old World Wood | PIONEER INDUSTRIAL PARK | BEST AUTO BODY AND FRAME
120 N PACIFIC ST STE D4 | 120 N PACIFIC STE G3 | 120 N PACIFIC
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 512104
EPA ID: CAL000000385

ECHO ***(cont.)***

Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	Y
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	Y
SDWIS Flag :	N
RCRA Flag :	Y
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	Y
NAA Flag :	Y
Latitude :	33.14865
Longitude :	-117.1951
Last Date in Agency List :	2021-02-17

Facility Name :	PIONEER INDUSTRIAL PARK
Facility Address :	120 N PACIFIC STE G3, SAN MARCOS, CA 92069
County :	SAN DIEGO

Last Inspection Date :	N/R
Registry ID :	110070801197
FIPS Code :	06073
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	_____U__
Collection Method :	N/R
Reference Point :	N/R
Accuracy Meters :	17531

Map Id: I76
Direction: SSE
Distance: 0.203 mi., 1075 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Old World Wood | PIONEER INDUSTRIAL PARK | BEST AUTO BODY AND FRAME 120 N PACIFIC ST STE D4 | 120 N PACIFIC STE G3 | 120 N PACIFIC SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 512104
EPA ID: CAL000000385

ECHO ***(cont.)***

Derived Tribes :

San Pasqual Band of Diegueno Mission Indians of California - 12.4 mile(s), Pala Band of Mission Indians - 13.3 mile (s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 14.1 mile(s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 16.3 mile(s), Pauma Band of Luiseno Mission Indians of the Pauma & Yuima Reservation, California - 16.9 mile(s), La Jolla Band of Luiseno Indians, California - 17.2 mile(s), Pechanga Band of Luiseno Mission Indians of the Pechanga Reservation, California - 20.5 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 22.5 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 22.9 mile(s), Mesa Grande Band of Diegueno Mission Indians of the Mesa Grande Reservation, California - 23.2 mile(s)

Derived HUC :	18070303
Derived WBD :	180703030503
Derived STCTY FIPS :	06073
Derived Zip :	92069
Derived CD113 :	50
Derived CB2010 :	060730200292005
MYRTK Universe :	NNN
NPDES IDs :	CAZ521733
CWA Permit Types :	Minor
CWA Compliance Tracking :	Off
CWA NAICS :	N/R
CWA SICS :	2434
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	0
CWA Current Compliance Status :	Terminated Permit
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	_____U
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	2434
Facility NAICS :	N/R
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R

Map Id: I76
Direction: SSE
Distance: 0.203 mi., 1075 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Old World Wood | PIONEER INDUSTRIAL PARK | BEST AUTO BODY AND FRAME
120 N PACIFIC ST STE D4 | 120 N PACIFIC STE G3 | 120 N PACIFIC
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 512104
EPA ID: CAL000000385

ECHO ***(cont.)***

Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	Y
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	Y
SDWIS Flag :	N
RCRA Flag :	Y
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	Y
NAA Flag :	Y
Latitude :	33.14865
Longitude :	-117.1951
Last Date in Agency List :	2022-01-17

FRS

Facility Name :	BEST AUTO BODY AND FRAME
Facility Address :	120 N PACIFIC B3, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Registry ID :	110009545091
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Source Description

Source Description :

RCRAInfo is EPA’s comprehensive information system that supports the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984 through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA. RCRAInfo also supports generation of the National Hazardous Waste Biennial Report. All generators and treatment, storage, and disposal facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years to support creation of the Biennial Report.

Map Id: I76
Direction: SSE
Distance: 0.203 mi., 1075 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Old World Wood | PIONEER INDUSTRIAL PARK | BEST AUTO BODY AND FRAME
120 N PACIFIC ST STE D4 | 120 N PACIFIC STE G3 | 120 N PACIFIC
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 512104
EPA ID: CAL000000385

FRS ***(cont.)***

FRS Environmental Interest
Source and System ID : RCRAINFO - CAD982431512

Facility Name : GLASS IMPRESSIONS BY D ALAN
Facility Address : 120 PACIFIC STREET A10, SAN MARCOS, CA 92069
County : SAN DIEGO COUNTY

Site Details
Registry ID : 110070084852
FRS Facility URL : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-02-17

Source Description

Source Description :

The NPDES module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

FRS Environmental Interest
Source and System ID : ICIS - CAW406244

Facility Name : OLD WORLD WOOD
Facility Address : 120 N PACIFIC ST STE D4, SAN MARCOS, CA 92009
County : SAN DIEGO COUNTY

Site Details
Registry ID : 110070096851
FRS Facility URL : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-02-17

Source Description

Map Id: I76
Direction: SSE
Distance: 0.203 mi., 1075 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Old World Wood | PIONEER INDUSTRIAL PARK | BEST AUTO BODY AND FRAME
120 N PACIFIC ST STE D4 | 120 N PACIFIC STE G3 | 120 N PACIFIC
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 512104
EPA ID: CAL000000385

FRS ***(cont.)***

Source Description :

The NPDES module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

FRS Environmental Interest

Source and System ID :	ICIS - CAZ477351
Facility Name :	PIONEER INDUSTRIAL CONDOMINIUMS
Facility Address :	120 N PACIFIC STE G3, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Registry ID :	110070801197
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-05-03

Source Description

Source Description :

The NPDES module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

Source Description :

RCRAInfo is EPA’s comprehensive information system that supports the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984 through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA. RCRAInfo also supports generation of the National Hazardous Waste Biennial Report. All generators and treatment, storage, and disposal facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years to support creation of the Biennial Report.

Map Id: I76
Direction: SSE
Distance: 0.203 mi., 1075 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Old World Wood | PIONEER INDUSTRIAL PARK | BEST AUTO BODY AND FRAME
120 N PACIFIC ST STE D4 | 120 N PACIFIC STE G3 | 120 N PACIFIC
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 512104
EPA ID: CAL000000385

FRS ***(cont.)***

FRS Environmental Interest
Source and System ID : ICIS - CAZ521733
RCRAINFO - CAP000048090

Facility Name : PIONEER INDUSTRIAL PARK
Facility Address : 120 N PACIFIC STE G3, SAN MARCOS, CA 92069
County : SAN DIEGO

Site Details
Registry ID : 110070801197
FRS Facility URL : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-02-17

Source Description

Source Description :

The NPDES module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

Source Description :

RCRAInfo is EPA's comprehensive information system that supports the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984 through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA. RCRAInfo also supports generation of the National Hazardous Waste Biennial Report. All generators and treatment, storage, and disposal facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years to support creation of the Biennial Report.

FRS Environmental Interest
Source and System ID : ICIS - CAZ521733
RCRAINFO - CAP000048090

HAZMAT_SAN DIEGO COUNTY - CA

Facility Name : BEST WAY ENGINES
Facility Address : 120 PACIFIC ST, SAN MARCOS, CA 92069

Map Id: I76
Direction: SSE
Distance: 0.203 mi., 1075 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Old World Wood | PIONEER INDUSTRIAL PARK | BEST AUTO BODY AND FRAME
120 N PACIFIC ST STE D4 | 120 N PACIFIC STE G3 | 120 N PACIFIC
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 512104
EPA ID: CAL000000385

HAZMAT_SAN DIEGO COUNTY - CA ***(cont.)***

Date :	2002-05-04
Record ID :	DEH2002-HUPFP-135935
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23

HAZNET - CA

Facility Name :	ALOHA AUTOMOTIVE
Facility Address :	120 N PACIFIC STE D4, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000000385
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	120 N PACIFIC STE D4, SAN MARCOS, CA 920690000
Latitude :	33.14818460
Longitude :	-117.19417119
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	2001: 134 - Aqueous solution with total organic residues less than 10 percent, 0.0168 tons to CAT000613893

Facility Name :	BEST AUTO BODY AND FRAME
Facility Address :	120 N PACIFIC B3, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAD982431512
Active :	Inactive
Category :	STATE
Facility Types :	N/R

Map Id: I76
Direction: SSE
Distance: 0.203 mi., 1075 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Old World Wood | PIONEER INDUSTRIAL PARK | BEST AUTO BODY AND FRAME
120 N PACIFIC ST STE D4 | 120 N PACIFIC STE G3 | 120 N PACIFIC
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 512104
EPA ID: CAL000000385

HAZNET - CA ***(cont.)***

Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	120 N PACIFIC ST STE B3, SAN MARCOS, CA 920691260
Latitude :	33.14818460
Longitude :	-117.19417119
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	1993: 214 - Unspecified solvent mixture, 0.2016 tons to CAD008252405 1993: 214 - Unspecified solvent mixture, 0.09 tons to CAD008252405
Facility Name :	CLASSIC GERMAN AUTO
Facility Address :	120 N PACIFIC, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000034038
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	120 N PACIFIC AVE #C4, SAN MARCOS, CA 920690000
Latitude :	33.14818460
Longitude :	-117.19417119
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08
Facility Name :	KEITH'S CUSTOMS
Facility Address :	120 N PACIFIC, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAD981391790
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT

Map Id: I76
Direction: SSE
Distance: 0.203 mi., 1075 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Old World Wood | PIONEER INDUSTRIAL PARK | BEST AUTO BODY AND FRAME
120 N PACIFIC ST STE D4 | 120 N PACIFIC STE G3 | 120 N PACIFIC
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 512104
EPA ID: CAL000000385

HAZNET - CA ***(cont.)***

Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	120 N PACIFIC, SAN MARCOS, CA 920690000
Latitude :	33.14818460
Longitude :	-117.19417119
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08
Facility Name :	Pioneer Industrial Park
Facility Address :	120 N Pacific Ste G3, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAP000048090
Active :	Inactive
Category :	FEDERAL
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	120 N PACIFIC STE G3, SAN MARCOS, CA 920690000
Latitude :	33.14866500
Longitude :	-117.19501650
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	1999: 214 - Unspecified solvent mixture, 0.108 tons to CAD008302903 1999: 181 - Other inorganic solid waste, 0.075 tons to CAT080033681
Facility Name :	PIONEER INDUSTRIAL PARK
Facility Address :	120 NO PACIFIC AVE, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAC001402496
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R

Map Id: I76
Direction: SSE
Distance: 0.203 mi., 1075 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Old World Wood | PIONEER INDUSTRIAL PARK | BEST AUTO BODY AND FRAME
120 N PACIFIC ST STE D4 | 120 N PACIFIC STE G3 | 120 N PACIFIC
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 512104
EPA ID: CAL000000385

HAZNET - CA ***(cont.)***

Contact Phone :	N/R
Facility Mailing Address :	120 NO PACIFIC AVE #H4, SAN MARCOS, CA 920690000
Latitude :	33.14818460
Longitude :	-117.19417119
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	1998: 212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.), 0.099 tons to CAD008252405 1998: 343 - Unspecified organic liquid mixture, 0.068 tons to CAD008252405
Facility Name :	PIONEER INDUSTRIAL PARK
Facility Address :	120 N PACIFIC, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAC001261240
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	120 N PACIFIC,#H4, SAN MARCOS, CA 920690000
Latitude :	33.14818460
Longitude :	-117.19417119
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	1997: 223 - Unspecified oil-containing waste, 0.5004 tons to CAD982444481 1995: 223 - Unspecified oil-containing waste, 0.5004 tons to CAD982444481
Facility Name :	R. S. AUTO BODY AND PAINT
Facility Address :	120 NORTH PACIFIC, SAN MARCOS, CA 92069
County :	SAN DIEGO

Map Id: I76
Direction: SSE
Distance: 0.203 mi., 1075 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Old World Wood | PIONEER INDUSTRIAL PARK | BEST AUTO BODY AND FRAME
120 N PACIFIC ST STE D4 | 120 N PACIFIC STE G3 | 120 N PACIFIC
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 512104
EPA ID: CAL000000385

HAZNET - CA ***(cont.)***

Site Details

Generator EPA ID :	CAL000124378
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	120 N PACIFIC ST STE L10, SAN MARCOS, CA 920691269
Latitude :	33.14818460
Longitude :	-117.19417119
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	1997: 212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.), 0.112 tons to CAT000613976 1995: 212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.), 0.112 tons to CAT000613976
Facility Name :	THUMPER PERFORMANCE INC
Facility Address :	120 N PACIFIC STE H5, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAC002557178
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	120 N PACIFIC STE H5, SAN MARCOS, CA 92069
Latitude :	33.14818460
Longitude :	-117.19417119
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HWG - CA

Facility Name :	ALOHA AUTOMOTIVE
Facility Address :	120 N PACIFIC STE D4, SAN MARCOS, CA 92069
County :	SAN DIEGO

Map Id: I76
Direction: SSE
Distance: 0.203 mi., 1075 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Old World Wood | PIONEER INDUSTRIAL PARK | BEST AUTO BODY AND FRAME
120 N PACIFIC ST STE D4 | 120 N PACIFIC STE G3 | 120 N PACIFIC
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 512104
EPA ID: CAL000000385

HWG - CA ***(cont.)***

EPA ID :	CAL000000385
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	120 N PACIFIC STE D4, SAN MARCOS, CA 920690000
Owner Name :	N/R
Owner Address :	N/A
Operator Name :	N/R
Operator Address :	UNDEL PER SURVEY 12/94 AD, N/A
Latitude :	33.148356
Longitude :	-117.194046

Facility Name :	BEST AUTO BODY AND FRAME
Facility Address :	120 N PACIFIC B3, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAD982431512
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	120 N PACIFIC ST STE B3, SAN MARCOS, CA 920691260
Owner Name :	CHARLES CHAPPEL
Owner Address :	120 N PACIFIC B3, SAN MARCOS, CA 920690000
Operator Name :	CHARLES CHAPPEL/OWNER
Operator Address :	UNDELIVERABLE VF97 LC, SAN MARCOS, CA 920690000
Latitude :	33.148218
Longitude :	-117.194335

Facility Name :	CLASSIC GERMAN AUTO
Facility Address :	120 N PACIFIC, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAL000034038
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	120 N PACIFIC AVE #C4, SAN MARCOS, CA 920690000
Owner Name :	CLASSIC GERMAN AUTOS
Owner Address :	N/A
Operator Name :	UNDELIVERABLE SURVEY 1-14-95LC
Operator Address :	LC, N/A
Latitude :	33.148356

Map Id: I76
Direction: SSE
Distance: 0.203 mi., 1075 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Old World Wood | PIONEER INDUSTRIAL PARK | BEST AUTO BODY AND FRAME
120 N PACIFIC ST STE D4 | 120 N PACIFIC STE G3 | 120 N PACIFIC
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 512104
EPA ID: CAL000000385

HWG - CA ***(cont.)***

Longitude :	-117.194046
Facility Name :	KEITH'S CUSTOMS
Facility Address :	120 N PACIFIC, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAD981391790
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	120 N PACIFIC, SAN MARCOS, CA 920690000
Owner Name :	N/R
Owner Address :	N/A
Operator Name :	UNDELIVERABLE SURVEY 1-14-95LC
Operator Address :	LC, N/A
Latitude :	33.148356
Longitude :	-117.194046
Facility Name :	Pioneer Industrial Park
Facility Address :	120 N Pacific Ste G3, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAP000048090
Status :	Inactive
Category :	FEDERAL
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	120 N PACIFIC STE G3, SAN MARCOS, CA 920690000
Owner Name :	MS NATALIE BLACKBURN, PROP MGR
Owner Address :	5959 MISSION GORGE RD NO 200, SAN DIEGO, CA 921200000
Operator Name :	MS NATALIE BLACKBURN, PROP MGR
Operator Address :	120 N PACIFIC STE G3, SAN MARCOS, CA 920690000
Latitude :	33.147756
Longitude :	-117.194492
Facility Name :	PIONEER INDUSTRIAL PARK
Facility Address :	120 NO PACIFIC AVE, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAC001402496
Status :	Inactive
Category :	STATE

Map Id: I76
Direction: SSE
Distance: 0.203 mi., 1075 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Old World Wood | PIONEER INDUSTRIAL PARK | BEST AUTO BODY AND FRAME
120 N PACIFIC ST STE D4 | 120 N PACIFIC STE G3 | 120 N PACIFIC
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 512104
EPA ID: CAL000000385

HWG - CA ***(cont.)***

Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	120 NO PACIFIC AVE #H4, SAN MARCOS, CA 920690000
Owner Name :	PIONEER INDUSTRIAL PARK
Owner Address :	120 NO PACIFIC AVE #H4, SAN MARCOS, CA 920690000
Operator Name :	TOM BURNS
Operator Address :	120 NO PACIFIC AVE #H4, SAN MARCOS, CA 920690000
Latitude :	33.148356
Longitude :	-117.194046

Facility Name :	PIONEER INDUSTRIAL PARK
Facility Address :	120 N PACIFIC, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAC001261240
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	120 N PACIFIC,#H4, SAN MARCOS, CA 920690000
Owner Name :	PIONEER IND PARK
Owner Address :	120 N PACIFIC,#H4, SAN MARCOS, CA 920690000
Operator Name :	CLANCY HALSEY
Operator Address :	120 N PACIFIC,#H4, SAN MARCOS, CA 920690000
Latitude :	33.148356
Longitude :	-117.194046

Facility Name :	R. S. AUTO BODY AND PAINT
Facility Address :	120 NORTH PACIFIC, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAL000124378
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	120 N PACIFIC ST STE L10, SAN MARCOS, CA 920691269
Owner Name :	REYNALDO SEGOVIANO, OWNER
Owner Address :	120 N PACIFIC ST STE L10, SAN MARCOS, CA 920691269
Operator Name :	REYNALDO SEGOVIANO, OWNER
Operator Address :	INACT PER NONDEL 98VQ FINAL, SAN MARCOS, CA 920691269
Latitude :	33.148356
Longitude :	-117.194046

Map Id: I76
Direction: SSE
Distance: 0.203 mi., 1075 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Old World Wood | PIONEER INDUSTRIAL PARK | BEST AUTO BODY AND FRAME
120 N PACIFIC ST STE D4 | 120 N PACIFIC STE G3 | 120 N PACIFIC
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 512104
EPA ID: CAL000000385

HWG - CA ***(cont.)***

Facility Name :	THUMPER PERFORMANCE INC
Facility Address :	120 N PACIFIC STE H5, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAC002557178
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	120 N PACIFIC STE H5, SAN MARCOS, CA 92069
Owner Name :	THUMPER PERFORMANCE INC
Owner Address :	120 N PACIFIC STE H5, SAN MARCOS, CA 92069
Operator Name :	DINA MONSON
Operator Address :	120 N PACIFIC STE H5, SAN MARCOS, CA 92069
Latitude :	33.148356
Longitude :	-117.194046

ICIS

Facility Name :	GLASS IMPRESSIONS BY D ALAN
Facility Address :	120 PACIFIC STREET A10, SAN MARCOS, CA 92069

Site Details

NPDES ID :	CAW406244
ICIS Facility Interest ID :	3600737248
Facility UIN :	110070084852
Facility Type Code :	N/R
Impaired Waters :	N/R
Latitude :	N/R
Longitude :	N/R
Last Date in Agency List :	2022-01-12

Facility Name :	OLD WORLD WOOD
Facility Address :	120 N PACIFIC ST STE D4, SAN MARCOS, CA 92009

Site Details

NPDES ID :	CAZ477351
ICIS Facility Interest ID :	3600735569
Facility UIN :	110070096851
Facility Type Code :	Privately Owned Facility
Impaired Waters :	N/R
Latitude :	33.1434
Longitude :	-117.1661

Map Id: I76
Direction: SSE
Distance: 0.203 mi., 1075 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Old World Wood | PIONEER INDUSTRIAL PARK | BEST AUTO BODY AND FRAME
120 N PACIFIC ST STE D4 | 120 N PACIFIC STE G3 | 120 N PACIFIC
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 512104
EPA ID: CAL000000385

ICIS ***(cont.)***

Last Date in Agency List :	2022-01-12

Facility SIC

SIC Code :	2434
SIC Description :	Wood Kitchen Cabinets

INACTIVE PCS

Issue Date :	2016-10-20
Original Issue Date :	2016-10-20
Effective Date :	2016-10-20
Expiration Date :	2020-06-30
Retirement Date :	N/R
Termination Date :	2019-09-20
Issuing Agency :	CA Waterboards
Agency Type :	State
Activity ID :	3601114943
External Permit Number :	CAZ477351
Facility Type Indicator :	NON-POTW
Permit Type :	General Permit Covered Facility-NPDES)
Major Minor Status :	N
Permit Status :	Terminated
Total Design Flow Number :	N/R
Actual Average Flow Number :	N/R
State Water Body :	N/R
State Water Body Name :	N/R
Permit Name :	Old World Wood
Permit Comp Status :	Y
RNC Tracking :	Y
Master External Permit Number :	CAS000001
TMDL Interface :	N/R
EDMR Authorization :	N
Pretreatment Indicator :	N/R
Last Date in Agency List :	2022-01-14

NPDES - CA

Facility Name :	Old World Wood
Facility Address :	120 N PACIFIC ST STE D4, San Marcos, 92009
County :	San Diego
Effective Date :	2016-10-20
Adoption Date :	N/R
Expiration Date :	N/R
Termination Date :	2019-09-20
Order Number :	97-03-DWQ

Map Id: I76
Direction: SSE
Distance: 0.203 mi., 1075 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Old World Wood | PIONEER INDUSTRIAL PARK | BEST AUTO BODY AND FRAME
120 N PACIFIC ST STE D4 | 120 N PACIFIC STE G3 | 120 N PACIFIC
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 512104
EPA ID: CAL000000385

NPDES - CA ***(cont.)***

NPDES Number :	CAS000001
WDID :	9 37NEC002643
RM Status :	Terminated
Reg Meas ID :	477351
Reg Meas Type :	Enrollee
Program :	Industrial
Facility Place ID :	N/R
Region Code :	9
Discharger ID :	0
Discharger :	Old World Wood
Discharger Address :	120 N PACIFIC ST STE D4, SAN MARCOS, California 92069
Last Date in Agency List :	2022-02-24

PCS FACILITY

Issue Date :	2016-10-20
Original Issue Date :	2016-10-20
Effective Date :	2016-10-20
Expiration Date :	2020-06-30
Retirement Date :	N/R
Termination Date :	N/R
Issuing Agency :	CA Waterboards
Agency Type :	State
Activity ID :	3601114943
External Permit Number :	CAZ477351
Facility Type Indicator :	NON-POTW
Permit Type :	General Permit Covered Facility-NPDES)
Major Minor Status :	N
Permit Status :	Effective
Total Design Flow Number :	N/R
Actual Average Flow Number :	N/R
State Water Body :	N/R
State Water Body Name :	N/R
Permit Name :	Old World Wood
Permit Comp Status :	Y
RNC Tracking :	Y
Master External Permit Number :	CAS000001
TMDL Interface :	N/R
EDMR Authorization :	N
Pretreatment Indicator :	N/R
Last Date in Agency List :	2019-09-24

RCRA_SQG

Facility Name :	BEST AUTO BODY AND FRAME
Facility Address :	120 N PACIFIC B3, SAN MARCOS, CA 92069
County :	SAN DIEGO

Map Id: I76
Direction: SSE
Distance: 0.203 mi., 1075 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Old World Wood | PIONEER INDUSTRIAL PARK | BEST AUTO BODY AND FRAME
120 N PACIFIC ST STE D4 | 120 N PACIFIC STE G3 | 120 N PACIFIC
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 512104
EPA ID: CAL000000385

RCRA_SQG ***(cont.)***

Date Form Received by Agency :	1996-09-01
EPA ID :	CAD982431512
Mailing Address :	120 N PACIFIC B3, SAN MARCOS, CA 92069
Contact :	N/R
Contact Address :	N/R
Contact Country :	US
Contact Telephone :	N/R
Contact Email :	N/R
EPA Region :	09
Land Type :	Not Reported
Source Type :	Implementer
Classification :	Small Quantity Generator
Description :	Handlers that generate more than 100 and less than 1000 kilograms of hazardous waste during any calendar month and accumulate less than 6000 kg of hazardous waste at any time; or generate 100 kg or less of hazardous waste during any calendar month, and accumulate more than 1000 kg of hazardous waste at any time.
Last Date in Agency List :	2022-01-25

Owner/Operator Summary

Owner/Operator Name :	CHARLES CHAPPEL
Owner/Operator Address :	NOT REQUIRED, NOT REQUIRED, ME 99999
Owner/Operator Country :	N/R
Owner/Operator Telephone :	415-555-1212
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Private
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Owner/Operator Name :	NOT REQUIRED
Owner/Operator Address :	NOT REQUIRED, NOT REQUIRED, ME 99999
Owner/Operator Country :	N/R
Owner/Operator Telephone :	415-555-1212
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Private
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Map Id: I76
Direction: SSE
Distance: 0.203 mi., 1075 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Old World Wood | PIONEER INDUSTRIAL PARK | BEST AUTO BODY AND FRAME
120 N PACIFIC ST STE D4 | 120 N PACIFIC STE G3 | 120 N PACIFIC
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 512104
EPA ID: CAL000000385

RCRA_SQG ***(cont.)***

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Notices of Violations Summary

Regulation Violated :	N

Facility Name :	PIONEER INDUSTRIAL PARK
Facility Address :	120 N PACIFIC STE G3, SAN MARCOS, CA 92069
County :	SAN DIEGO
Date Form Received by Agency :	1999-02-01
EPA ID :	CAP000048090
Mailing Address :	120 N PACIFIC STE G3, SAN MARCOS, CA 92069
Contact :	NATALIE BLACKBURN
Contact Address :	120 N PACIFIC STE G3, SAN MARCOS, CA 92069
Contact Country :	US
Contact Telephone :	760-471-6092
Contact Email :	N/R
EPA Region :	09
Land Type :	Private
Source Type :	Notification
Classification :	Small Quantity Generator
Description :	Handlers that generate more than 100 and less than 1000 kilograms of hazardous waste during any calendar month and accumulate less than 6000 kg of hazardous waste at any time; or generate 100 kg or less of hazardous waste during any calendar month, and accumulate more than 1000 kg of hazardous waste at any time.
Last Date in Agency List :	2022-01-25

Map Id: I76
Direction: SSE
Distance: 0.203 mi., 1075 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Old World Wood | PIONEER INDUSTRIAL PARK | BEST AUTO BODY AND FRAME
120 N PACIFIC ST STE D4 | 120 N PACIFIC STE G3 | 120 N PACIFIC
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 512104
EPA ID: CAL000000385

RCRA_SQG ***(cont.)***

Owner/Operator Summary

Owner/Operator Name :	120 N PACIFIC LLC
Owner/Operator Address :	5959 MISSION GORGE RD NO 200, SAN DIEGO, CA 92120
Owner/Operator Country :	N/R
Owner/Operator Telephone :	619-563-1198
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Private
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Notices of Violations Summary

Regulation Violated :	N

RFR - CA

Facility Name :	Old World Wood
Facility Address :	120 N PACIFIC ST STE D4 3011 Segovia Way, San Marcos, CA 92009
County :	San Diego
Effective Date :	2016-10-20
Adoption Date :	N/R
Termination Date :	N/R
Expiration/Review Date :	N/R
NPDES Number :	CAS000001
Order Number :	2014-0057-DWQ

Map Id: I76
Direction: SSE
Distance: 0.203 mi., 1075 ft.
Elevation: 566 ft.
Relative: Lower

Site Name : Old World Wood | PIONEER INDUSTRIAL PARK | BEST AUTO BODY AND FRAME
120 N PACIFIC ST STE D4 | 120 N PACIFIC STE G3 | 120 N PACIFIC
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS - CA, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS FACILITY, RCRA_SQG, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 512104
EPA ID: CAL000000385

RFR - CA ***(cont.)***

WDID :	9 37NEC002643
SIC/NAICS :	2434
Program :	INDSTW
Regulatory Measure Status :	Active
Regulatory Measure Type :	Storm water industrial
Place/Project Type :	Industrial - Wood Kitchen Cabinets
Region :	9
Design Flow :	N/R
Major/Minor :	N/R
Complexity :	N/R
TTWQ :	N/R
Number of Enforcement Actions within Five Years:	N/R
Number of Violations within Five Years:	N/R
Agency :	Old World Wood
Agency Address :	120 N PACIFIC ST STE D4, San Marcos, CA 92069
Latitude :	33.1434
Longitude :	-117.1661
Last Date in Agency List :	2019-09-09

STORMWATER

Facility Name :	OLD WORLD WOOD
Facility Address :	120 N PACIFIC ST STE D4, SAN MARCOS, CA 92009
NPDES ID :	CAZ477351
Permittee Name :	Old World Wood
Permit Status :	Terminated
Permit Issuing Name :	State
Issued Date :	2016-10-20
Termination Date :	2019-09-20
Effective Date :	2016-10-20 2020-06-30
EPA Region :	09
SIC Code :	2434
NAICS Code :	N/R
EJ Indexes Above 80th Percentile :	Y
Significant Noncompliance Status :	N/R
Quarters with Noncompliance :	0
Industrial Stormwater Formal Enforcement Actions:	N/R
Facility Map Flag :	Y
DRF URL :	Click here for hyperlink provided by the agency.
Latitude :	33.1434
Longitude :	-117.1661
Last Date in Agency List :	2022-01-11

Map Id: M77
Direction: SE
Distance: 0.206 mi., 1086 ft.
Elevation: 559 ft.
Relative: Lower

Site Name : DEMON FABRICATION, INC
169 BALBOA ST
SAN MARCOS, CA 92069

Database(s) : [HAZMAT_SAN DIEGO COUNTY - CA]

Envirosite ID: 630272
EPA ID: N/R

HAZMAT_SAN DIEGO COUNTY - CA

Facility Name :	DEMON FABRICATION, INC
Facility Address :	169 BALBOA ST, SAN MARCOS, CA 92069
Date :	2008-08-25
Record ID :	DEH2008-HUPFP-209645
Record Type :	Unified Program Facility Permit
Status :	Permit Suspended
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23

Map Id: M78
Direction: SE
Distance: 0.208 mi., 1099 ft.
Elevation: 558 ft.
Relative: Lower

Site Name : TECHNOGRAPHICS CO
181 BALBOA STREET
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, RCRA_NONGEN]

Envirosite ID: 972221
EPA ID: N/R

ECHO

Facility Name :	TECHNOGRAPHICS CO
Facility Address :	181 BALBOA STREET, SAN MARCOS, CA 92069
County :	SAN DIEGO
Last Inspection Date :	N/R
Registry ID :	110070442628
FIPS Code :	N/R
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	_____
Collection Method :	Zip Code Centroid
Reference Point :	N/R
Accuracy Meters :	10000
Derived Tribes :	N/R
Derived HUC :	N/R

Map Id: M78
Direction: SE
Distance: 0.208 mi., 1099 ft.
Elevation: 558 ft.
Relative: Lower

Site Name : TECHNOGRAPHICS CO
181 BALBOA STREET
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 972221
EPA ID: N/R

ECHO ***(cont.)***

Derived WBD :	N/R
Derived STCTY FIPS :	N/R
Derived Zip :	N/R
Derived CD113 :	N/R
Derived CB2010 :	N/R
MYRTK Universe :	NNN
NPDES IDs :	N/R
CWA Permit Types :	N/R
CWA Compliance Tracking :	N/R
CWA NAICS :	N/R
CWA SICS :	N/R
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	N/R
CWA Current Compliance Status :	N/R
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	N/R
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	N/R
Facility NAICS :	32311 - Printing
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	N/R
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	N
SDWIS Flag :	N
RCRA Flag :	Y
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	Y
NAA Flag :	N
Latitude :	33.194075
Longitude :	-117.16177
Last Date in Agency List :	2022-01-17

Map Id: M78
Direction: SE
Distance: 0.208 mi., 1099 ft.
Elevation: 558 ft.
Relative: Lower

Site Name : TECHNOGRAPHICS CO
181 BALBOA STREET
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 972221
EPA ID: N/R

FRS

Facility Name :	TECHNOGRAPHICS CO
Facility Address :	181 BALBOA STREET, SAN MARCOS, CA 92069-0000
County :	SAN DIEGO

Site Details

Registry ID :	110070442628
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Source Description

Source Description :

RCRAInfo is EPA's comprehensive information system that supports the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984 through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA. RCRAInfo also supports generation of the National Hazardous Waste Biennial Report. All generators and treatment, storage, and disposal facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years to support creation of the Biennial Report.

FRS Environmental Interest

Source and System ID :	RCRAINFO - CAL000091925

HAZMAT_SAN DIEGO COUNTY - CA

Facility Name :	TECHNOGRAPHICS
Facility Address :	181 BALBOA ST, CA
Date :	2002-05-04
Record ID :	DEH2002-HUPFP-133191
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23

HAZNET - CA

Facility Name :	TECHNOGRAPHICS CO
Facility Address :	181 BALBOA STREET, SAN MARCOS, CA 92069
County :	SAN DIEGO

Map Id: M78
Direction: SE
Distance: 0.208 mi., 1099 ft.
Elevation: 558 ft.
Relative: Lower

Site Name : TECHNOGRAPHICS CO
181 BALBOA STREET
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 972221
EPA ID: N/R

HAZNET - CA ***(cont.)***

Site Details

Generator EPA ID :	CAL000091925
Active :	Active
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	181 BALBOA ST STE 102, SAN MARCOS, CA 920690000
Latitude :	33.14902555
Longitude :	-117.19213635
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HWG - CA

Facility Name :	TECHNOGRAPHICS CO
Facility Address :	181 BALBOA STREET, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAL000091925
Status :	Active
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	181 BALBOA ST STE 102, SAN MARCOS, CA 920690000
Owner Name :	TECHNOGRAPHICS
Owner Address :	181 BALBOA ST #102, SAN MARCOS, CA 920690000
Operator Name :	BRADEN THOMAS
Operator Address :	181 BALBOA ST STE 102, SAN MARCOS, CA 0
Latitude :	33.149105
Longitude :	-117.192182

RCRA_NONGEN

Facility Name :	TECHNOGRAPHICS CO
Facility Address :	181 BALBOA STREET, SAN MARCOS, CA 92069-0000
County :	SAN DIEGO
Date Form Received by Agency :	1994-10-04
EPA ID :	CAL000091925
Mailing Address :	181 BALBOA ST STE 102, SAN MARCOS, CA 92069-0000
Contact :	BRADEN THOMAS
Contact Address :	181 BALBOA ST STE 102, SAN MARCOS, CA 00000
Contact Country :	N/R
Contact Telephone :	760-744-8540
Contact Email :	TECHNOGRAPHICSBRAD@YAHOO.COM
EPA Region :	09
Land Type :	Not Reported
Source Type :	Implementer
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2022-01-26

Map Id: M78
Direction: SE
Distance: 0.208 mi., 1099 ft.
Elevation: 558 ft.
Relative: Lower

Site Name : TECHNOGRAPHICS CO
181 BALBOA STREET
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 972221
EPA ID: N/R

RCRA_NONGEN ***(cont.)***

Owner/Operator Summary

Owner/Operator Name :	BRADEN THOMAS
Owner/Operator Address :	181 BALBOA ST STE 102, SAN MARCOS, CA 00000
Owner/Operator Country :	N/R
Owner/Operator Telephone :	760-744-8540
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Owner/Operator Name :	TECHNOGRAPHICS STUDENT INC
Owner/Operator Address :	181 BALBOA ST #102, SAN MARCOS, CA 92069-0000
Owner/Operator Country :	N/R
Owner/Operator Telephone :	760-744-8540
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Notices of Violations Summary

Regulation Violated :	N

Map Id: K79
Direction: WSW
Distance: 0.210 mi., 1110 ft.
Elevation: 591 ft.
Relative: Higher

Site Name : CHEVRON
110 RANCHO SANTE FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, ECHO, FRS]

Envirosite ID: 911043
EPA ID: N/R

CALEPA SITES - CA

Facility Name :	CHEVRON
Facility Address :	110 RANCHO SANTE FE RD, SAN MARCOS, 92078-2502
Site ID :	459166
EI ID :	110002897508
EI Description :	US EPA Air Emission Inventory System (EIS)
Latitude :	33.149137
Longitude :	-117.198870
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07

ECHO

Facility Name :	CHEVRON
Facility Address :	110 RANCHO SANTE FE RD, SAN MARCOS, CA 92078
County :	SAN DIEGO
Last Inspection Date :	N/R
Registry ID :	110002897508
FIPS Code :	06073
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	_____
Collection Method :	ADDRESS MATCHING-HOUSE NUMBER
Reference Point :	ENTRANCE POINT OF A FACILITY OR STATION
Accuracy Meters :	50

Derived Tribes :

San Pasqual Band of Diegueno Mission Indians of California - 12.6 mile(s), Pala Band of Mission Indians - 13.4 mile (s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 14.2 mile(s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 16.4 mile(s), Pauma Band of Luiseno Mission Indians of the Pauma & Yuima Reservation, California - 17.1 mile(s), La Jolla Band of Luiseno Indians, California - 17.3 mile(s), Pechanga Band of Luiseno Mission Indians of the Pechanga Reservation, California - 20.6 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 22.7 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 23.1 mile(s), Mesa Grande Band of Diegueno Mission Indians of the Mesa Grande Reservation, California - 23.4 mile(s)

Derived HUC :	18070303
Derived WBD :	180703030502
Derived STCTY FIPS :	06073
Derived Zip :	92078

Map Id: K79
Direction: WSW
Distance: 0.210 mi., 1110 ft.
Elevation: 591 ft.
Relative: Higher

Site Name : CHEVRON
110 RANCHO SANTE FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, ECHO, FRS] ***(cont.)***

Envirosite ID: 911043
EPA ID: N/R

ECHO ***(cont.)***

Derived CD113 :	50
Derived CB2010 :	060730200183001
MYRTK Universe :	NNN
NPDES IDs :	N/R
CWA Permit Types :	N/R
CWA Compliance Tracking :	N/R
CWA NAICS :	N/R
CWA SICS :	N/R
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	N/R
CWA Current Compliance Status :	N/R
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	N/R
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	N/R
Facility NAICS :	56291 - Remediation Services, 447110 - Gasoline Stations with Convenience Stores
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	Y
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	N
SDWIS Flag :	N
RCRA Flag :	Y
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	N/R
NAA Flag :	Y
Latitude :	33.149137
Longitude :	-117.198878
Last Date in Agency List :	2022-01-17

Map Id: K79
Direction: WSW
Distance: 0.210 mi., 1110 ft.
Elevation: 591 ft.
Relative: Higher

Site Name : CHEVRON
110 RANCHO SANTE FE RD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, ECHO, FRS] ***(cont.)***

Envirosite ID: 911043
EPA ID: N/R

FRS

Facility Name : CHEVRON
Facility Address : 110 RANCHO SANTE FE RD, SAN MARCOS, CA 92078-2502
County : SAN DIEGO

Site Details

Registry ID : 110002897508
FRS Facility URL : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-02-17

Source Description

Source Description :

The Emission Inventory System (EIS) maintains an inventory of large stationary sources and voluntarily-reported smaller sources of air point pollution emitters. It contains information about facility sites and their physical location, emission units, emission processes, release points, control approaches, and regulations. Facility inventory data are kept separate from the emissions data and have stable identifiers to improve continuity from year to year and to help identify duplicate or missing facilities.
HWTS-DATAMART provides California with information on hazardous waste shipments for generators, transporters, and treatment, storage, and disposal facilities.

Source Description :

RCRAInfo is EPA’s comprehensive information system that supports the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984 through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA. RCRAInfo also supports generation of the National Hazardous Waste Biennial Report. All generators and treatment, storage, and disposal facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years to support creation of the Biennial Report.

FRS Environmental Interest

Source and System ID : EIS - 1252411
HWTS-DATAMART - CAD983666017
RCRAINFO - CAD983666017

Map Id: E80
Direction: NW
Distance: 0.211 mi., 1113 ft.
Elevation: 600 ft.
Relative: Higher

Site Name : JOSE LOPEZ
3514 BARRANCA ROAD
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HWG - CA, RCRA_NONGEN]

Envirosite ID: 44401932
EPA ID: N/R

ECHO

Facility Name :	JOSE LOPEZ
Facility Address :	3514 BARRANCA ROAD, SAN MARCOS, CA 92069
County :	SAN DIEGO
Last Inspection Date :	N/R
Registry ID :	N/R
FIPS Code :	N/R
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	_____
Collection Method :	Zip Code Centroid
Reference Point :	N/R
Accuracy Meters :	10000
Derived Tribes :	N/R
Derived HUC :	N/R
Derived WBD :	N/R
Derived STCTY FIPS :	N/R
Derived Zip :	N/R
Derived CD113 :	N/R
Derived CB2010 :	N/R
MYRTK Universe :	NNN
NPDES IDs :	N/R
CWA Permit Types :	N/R
CWA Compliance Tracking :	N/R
CWA NAICS :	N/R
CWA SICS :	N/R
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	N/R
CWA Current Compliance Status :	N/R
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	N/R
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	N/R
Facility NAICS :	56299 - All Other Waste Management Services

Map Id: E80
Direction: NW
Distance: 0.211 mi., 1113 ft.
Elevation: 600 ft.
Relative: Higher

Site Name : JOSE LOPEZ
3514 BARRANCA ROAD
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 44401932
EPA ID: N/R

ECHO ***(cont.)***

Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	N/R
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	N
SDWIS Flag :	N
RCRA Flag :	Y
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	N/R
NAA Flag :	N
Latitude :	33.194075
Longitude :	-117.16177
Last Date in Agency List :	2022-01-17

FRS

Facility Name :	JOSE LOPEZ
Facility Address :	3514 BARRANCA ROAD, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Registry ID :	110071183688
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Source Description

Source Description :

RCRAInfo is EPA’s comprehensive information system that supports the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984 through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA. RCRAInfo also supports generation of the National Hazardous Waste Biennial Report. All generators and treatment, storage, and disposal facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years to support creation of the Biennial Report.

Map Id: E80
Direction: NW
Distance: 0.211 mi., 1113 ft.
Elevation: 600 ft.
Relative: Higher

Site Name : JOSE LOPEZ
3514 BARRANCA ROAD
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 44401932
EPA ID: N/R

FRS ***(cont.)***

FRS Environmental Interest

Source and System ID :	RCRAINFO - CAC003150884

HWG - CA

Facility Name :	JOSE LOPEZ
Facility Address :	3514 BARRANCA ROAD, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAC003150884
Status :	Active
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	3514 BARRANCA ROAD, SAN MARCOS, CA 92069
Owner Name :	JOSE LOPEZ
Owner Address :	3514 BARRANCA ROAD, SAN MARCOS, CA 92069
Operator Name :	JOSE LOPEZ
Operator Address :	3514 BARRANCA ROAD, SAN MARCOS, CA 92069
Latitude :	33.154034
Longitude :	-117.198419

RCRA_NONGEN

Facility Name :	JOSE LOPEZ
Facility Address :	3514 BARRANCA ROAD, SAN MARCOS, CA 92069
County :	SAN DIEGO
Date Form Received by Agency :	2021-12-02
EPA ID :	CAC003150884
Mailing Address :	3514 BARRANCA ROAD, SAN MARCOS, CA 92069
Contact :	JOSE LOPEZ
Contact Address :	3514 BARRANCA ROAD, SAN MARCOS, CA 92069
Contact Country :	N/R
Contact Telephone :	559-765-8541
Contact Email :	JSARDO@HSABATEMENT.COM
EPA Region :	09
Land Type :	Not Reported
Source Type :	Implementer
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2022-01-26

Owner/Operator Summary

Owner/Operator Name :	JOSE LOPEZ
Owner/Operator Address :	3514 BARRANCA ROAD, SAN MARCOS, CA 92069
Owner/Operator Country :	N/R
Owner/Operator Telephone :	559-765-8541
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Owner

Map Id: E80
Direction: NW
Distance: 0.211 mi., 1113 ft.
Elevation: 600 ft.
Relative: Higher

Site Name : JOSE LOPEZ
3514 BARRANCA ROAD
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 44401932
EPA ID: N/R

RCRA_NONGEN ***(cont.)***

Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R
Owner/Operator Name :	JOSE LOPEZ
Owner/Operator Address :	3514 BARRANCA ROAD, SAN MARCOS, CA 92069
Owner/Operator Country :	N/R
Owner/Operator Telephone :	559-765-8541
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N/R
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Notices of Violations Summary

Regulation Violated :	N

Map Id: M81
Direction: SE
Distance: 0.211 mi., 1113 ft.
Elevation: 558 ft.
Relative: Lower

Site Name : PACIFIC YACHT TOWERS | HENRY MACHINE, INC.
165 BALBOA ST
SAN MARCOS, CA 92069

Database(s) : [FRS, HAZMAT_SAN DIEGO COUNTY - CA]

Envirosite ID: 638093
EPA ID: N/R

FRS

Facility Name :	PACIFIC YACHT TOWERS

Map Id: M81
Direction: SE
Distance: 0.211 mi., 1113 ft.
Elevation: 558 ft.
Relative: Lower

Site Name : PACIFIC YACHT TOWERS | HENRY MACHINE, INC.
165 BALBOA ST
SAN MARCOS, CA 92069

Database(s) : [FRS, HAZMAT_SAN DIEGO COUNTY - CA] ***(cont.)***

Envirosite ID: 638093
EPA ID: N/R

FRS ***(cont.)***

Facility Address : 165 BALBOA ST, SAN MARCOS, CA 92069
County : SAN DIEGO

Site Details
Registry ID : 110065677887
FRS Facility URL : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-02-17

Source Description

Source Description :

The California Environmental Protection Agency (CalEPA) has recently implemented a new data warehouse system (nSite). This data warehouse combines and merges facility and site information from five different systems managed within CalEPA. The five systems are: California Environmental Reporting System (CERS), EnviroStor, GeoTracker, California Integrated Water Quality System (CIWQS), and Toxic Release Inventory (TRI).

FRS Environmental Interest
Source and System ID : CA-ENVIROVIEW - 141149

HAZMAT_SAN DIEGO COUNTY - CA

Facility Name : HENRY MACHINE, INC.
Facility Address : 165 BALBOA ST, SAN MARCOS, CA 92069

Date : 2002-05-04
Record ID : DEH2002-HUPFP-139433
Record Type : Unified Program Facility Permit
Status : Completed
Action : N/R
Short Notes : N/R
Last Date in Agency List : 2015-11-23

Facility Name : PACIFIC YACHT TOWERS
Facility Address : 165 BALBOA ST, SAN MARCOS, CA 92069

Date : 2005-01-10
Record ID : DEH2005-HUPFP-204666
Record Type : Unified Program Facility Permit
Status : Permit Renewed
Action : N/R
Short Notes : N/R
Last Date in Agency List : 2015-11-23

Map Id: M82
Direction: SE
Distance: 0.211 mi., 1115 ft.
Elevation: 557 ft.
Relative: Lower

Site Name : CONCOURS CLASSICS | XREFURB CENTER
155 BALBOA SUITE D-2 | 155 BALBOA DR
| 155 BALBOA DR STE D13
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HAZNET - CA, HWG - CA, RCRA_SQG]

Envirosite ID: 592022
EPA ID: CAL000055200

ECHO

Facility Name :	CONCOURS CLASSICS
Facility Address :	155 BALBOA SUITE D-2, SAN MARCOS, CA 92069
County :	SAN DIEGO
Last Inspection Date :	N/R
Registry ID :	110002675999
FIPS Code :	06073
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	_____
Collection Method :	ADDRESS MATCHING-HOUSE NUMBER
Reference Point :	CENTER OF A FACILITY OR STATION
Accuracy Meters :	30

Derived Tribes :

San Pasqual Band of Diegueno Mission Indians of California - 12.2 mile(s), Pala Band of Mission Indians - 13.2 mile (s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 13.9 mile(s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 16.1 mile(s), Pauma Band of Luiseno Mission Indians of the Pauma & Yuima Reservation, California - 16.8 mile(s), La Jolla Band of Luiseno Indians, California - 17 mile(s), Pechanga Band of Luiseno Mission Indians of the Pechanga Reservation, California - 20.5 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 22.4 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 22.8 mile(s), Mesa Grande Band of Diegueno Mission Indians of the Mesa Grande Reservation, California - 23.1 mile(s)

Derived HUC :	18070303
Derived WBD :	180703030503
Derived STCTY FIPS :	06073
Derived Zip :	92069
Derived CD113 :	50
Derived CB2010 :	060730200292004
MYRTK Universe :	NNN
NPDES IDs :	N/R
CWA Permit Types :	N/R
CWA Compliance Tracking :	N/R
CWA NAICS :	N/R
CWA SICS :	N/R
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R

Map Id: M82
Direction: SE
Distance: 0.211 mi., 1115 ft.
Elevation: 557 ft.
Relative: Lower

Site Name : CONCOURS CLASSICS | XREFURB CENTER
155 BALBOA SUITE D-2 | 155 BALBOA DR
| 155 BALBOA DR STE D13
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HAZNET - CA, HWG - CA, RCRA_SQG] ***(cont.)***

Envirosite ID: 592022
EPA ID: CAL000055200

ECHO ***(cont.)***

CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	N/R
CWA Current Compliance Status :	N/R
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	N/R
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	N/R
Facility NAICS :	811121 - Automotive Body, Paint, and Interior Repair and Maintenance
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	Y
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	N
SDWIS Flag :	N
RCRA Flag :	Y
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	Y
NAA Flag :	Y
Latitude :	33.14859
Longitude :	-117.19246
Last Date in Agency List :	2022-01-17

FRS

Facility Name :	CONCOURS CLASSICS
Facility Address :	155 BALBOA SUITE D-2, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Registry ID :	110002675999
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Map Id: M82
Direction: SE
Distance: 0.211 mi., 1115 ft.
Elevation: 557 ft.
Relative: Lower

Site Name : CONCOURS CLASSICS | XREFURB CENTER
155 BALBOA SUITE D-2 | 155 BALBOA DR
| 155 BALBOA DR STE D13
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HAZNET - CA, HWG - CA, RCRA_SQG] ***(cont.)***

Envirosite ID: 592022
EPA ID: CAL000055200

FRS ***(cont.)***

Source Description

Source Description :

RCRAInfo is EPA's comprehensive information system that supports the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984 through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA. RCRAInfo also supports generation of the National Hazardous Waste Biennial Report. All generators and treatment, storage, and disposal facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years to support creation of the Biennial Report.

FRS Environmental Interest

Source and System ID :	RCRAINFO - CAD980891386

HAZNET - CA

Facility Name :	CONCOURS CLASSICS
Facility Address :	155 BALBOA DR, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000055200
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	155 BALBOA DR, SAN MARCOS, CA 920690000
Latitude :	33.14886320
Longitude :	-117.19224235
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	2003: 221 - Waste oil and mixed oil, 0.209 tons to CAT080013352 2003: 214 - Unspecified solvent mixture, 0.198 tons to CAT080013352 2003: 291 - Latex waste, 0.22935 tons to CAT080013352 2001: 221 - Waste oil and mixed oil, 0.225 tons to AZD980892731 2001: 214 - Unspecified solvent mixture, 0.2875 tons to AZD980892731
Facility Name :	CONCOURS CLASSICS
Facility Address :	155 BALBOA SUITE D-2, SAN MARCOS, CA 92069
County :	SAN DIEGO

Map Id: M82
Direction: SE
Distance: 0.211 mi., 1115 ft.
Elevation: 557 ft.
Relative: Lower

Site Name : CONCOURS CLASSICS | XREFURB CENTER
155 BALBOA SUITE D-2 | 155 BALBOA DR
| 155 BALBOA DR STE D13
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HAZNET - CA, HWG - CA, RCRA_SQG] ***(cont.)***

Envirosite ID: 592022
EPA ID: CAL000055200

HAZNET - CA ***(cont.)***

Site Details

Generator EPA ID :	CAD980891386
Active :	Inactive
Category :	FEDERAL
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	155 BALBOA ST STE D2, SAN MARCOS, CA 920691346
Latitude :	33.14886320
Longitude :	-117.19224235
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08
Facility Name :	XREFURB CENTER
Facility Address :	155 BALBOA DR STE D13, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000282384
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	169 BALBOA ST SUITE B2, SAN MARCOS, CA 920690000
Latitude :	33.14886320
Longitude :	-117.19224235
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HWG - CA

Facility Name :	CONCOURS CLASSICS
Facility Address :	155 BALBOA DR, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAL000055200
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	155 BALBOA DR, SAN MARCOS, CA 920690000
Owner Name :	N/R
Owner Address :	N/A
Operator Name :	INACTIVE DUP NUM IN BLK LOGBK
Operator Address :	N/A
Latitude :	33.148928
Longitude :	-117.192274

Map Id: M82
Direction: SE
Distance: 0.211 mi., 1115 ft.
Elevation: 557 ft.
Relative: Lower

Site Name : CONCOURS CLASSICS | XREFURB CENTER
155 BALBOA SUITE D-2 | 155 BALBOA DR
| 155 BALBOA DR STE D13
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HAZNET - CA, HWG - CA, RCRA_SQG] ***(cont.)***

Envirosite ID: 592022
EPA ID: CAL000055200

HWG - CA ***(cont.)***

Facility Name :	CONCOURS CLASSICS
Facility Address :	155 BALBOA SUITE D-2, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAD980891386
Status :	Inactive
Category :	FEDERAL
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	155 BALBOA ST STE D2, SAN MARCOS, CA 920691346
Owner Name :	N/R
Owner Address :	N/A
Operator Name :	N/R
Operator Address :	INACT 99VQ FINAL NOTICE - BATCH, N/A
Latitude :	33.148462
Longitude :	-117.192839
Facility Name :	XREFURB CENTER
Facility Address :	155 BALBOA DR STE D13, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAL000282384
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	169 BALBOA ST SUITE B2, SAN MARCOS, CA 920690000
Owner Name :	MARK ABRAHAMS
Owner Address :	169 BALBOA ST STE B2, SAN MARCOS, CA 920690000
Operator Name :	MARK ABRAHAMS
Operator Address :	155 BALBOA DR STE D13, SAN MARCOS, CA 920690000
Latitude :	33.148928
Longitude :	-117.192274

RCRA_SQG

Facility Name :	CONCOURS CLASSICS
Facility Address :	155 BALBOA SUITE D-2, SAN MARCOS, CA 92069
County :	SAN DIEGO
Date Form Received by Agency :	1996-09-01
EPA ID :	CAD980891386
Mailing Address :	155 BALBOA SUITE D-2, SAN MARCOS, CA 92069
Contact :	N/R
Contact Address :	N/R
Contact Country :	US
Contact Telephone :	N/R
Contact Email :	N/R
EPA Region :	09
Land Type :	Not Reported
Source Type :	Implementer

Map Id: M82
Direction: SE
Distance: 0.211 mi., 1115 ft.
Elevation: 557 ft.
Relative: Lower

Site Name : CONCOURS CLASSICS | XREFURB CENTER
155 BALBOA SUITE D-2 | 155 BALBOA DR
| 155 BALBOA DR STE D13
SAN MARCOS, CA 92069

Database(s) : [ECHO, FRS, HAZNET - CA, HWG - CA, RCRA_SQG] ***(cont.)***

Envirosite ID: 592022
EPA ID: CAL000055200

RCRA_SQG ***(cont.)***

Classification : Small Quantity Generator

Description : Handlers that generate more than 100 and less than 1000 kilograms of hazardous waste during any calendar month and accumulate less than 6000 kg of hazardous waste at any time; or generate 100 kg or less of hazardous waste during any calendar month, and accumulate more than 1000 kg of hazardous waste at any time.

Last Date in Agency List : 2022-01-25

Owner/Operator Summary

Owner/Operator Name :	NOT REQUIRED
Owner/Operator Address :	NOT REQUIRED, NOT REQUIRED, ME 99999
Owner/Operator Country :	N/R
Owner/Operator Telephone :	415-555-1212
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Private
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Historical Generators

Date Form Received by Agency :	1985-10-01
Facility Name :	CONCOURS CLASSICS
Classification :	Large Quantity Generator

Notices of Violations Summary

Regulation Violated :	N

Map Id: M83
Direction: SE
Distance: 0.211 mi., 1115 ft.
Elevation: 558 ft.
Relative: Lower

Site Name : HENRY MACHINE INC
165 BALBOA ST UNIT C-11
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 41083899
EPA ID: CAL000219101

HAZNET - CA

Facility Name :	HENRY MACHINE INC
Facility Address :	165 BALBOA ST UNIT C-11, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000219101
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	820 LOS VALLECITOS BLVD STE E, SAN MARCOS, CA 920690000
Latitude :	33.14892852
Longitude :	-117.19220389
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HWG - CA

Facility Name :	HENRY MACHINE INC
Facility Address :	165 BALBOA ST UNIT C-11, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAL000219101
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	820 LOS VALLECITOS BLVD STE E, SAN MARCOS, CA 920690000
Owner Name :	HENRY MACHINE INC
Owner Address :	165 BALBOA ST UNIT C-11, SAN MARCOS, CA 920690000
Operator Name :	NHAN VO/PRESIDENT
Operator Address :	820 LOS VALLECITOS BLVD STE E, SAN MARCOS, CA 920690000
Latitude :	33.148996
Longitude :	-117.192238

Map Id: 84
Direction: NNW
Distance: 0.216 mi., 1140 ft.
Elevation: 549 ft.
Relative: Lower

Site Name : AUTO ELECTRIC | ROMA MARBLE | BATZS CAR CARE CENTER
3110 S SANTA FE | 3110 SOUTH SANTA FE
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 512251
EPA ID: CAL000261009

HAZNET - CA

Facility Name :	AUTO ELECTRIC

Map Id: 84
Direction: NNW
Distance: 0.216 mi., 1140 ft.
Elevation: 549 ft.
Relative: Lower

Site Name : AUTO ELECTRIC | ROMA MARBLE | BATZS CAR CARE CENTER
3110 S SANTA FE | 3110 SOUTH SANTA FE
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 512251
EPA ID: CAL000261009

HAZNET - CA ***(cont.)***

Facility Address :	3110 S SANTA FE, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000261009
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	3110 S SANTA FE, SAN MARCOS, CA 92069
Latitude :	33.15527415
Longitude :	-117.19699333
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Facility Name :	BATZS CAR CARE CENTER
Facility Address :	3110 SOUTH SANTA FE, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000171729
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	3110 SOUTH SANTA FE, SAN MARCOS, CA 920690000
Latitude :	33.15527415
Longitude :	-117.19699333
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	1998: 133 - Aqueous solution with total organic residues 10 percent or more, 0.4378 tons to CAT080013352

Facility Name :	ROMA MARBLE
Facility Address :	3110 S SANTA FE BLVD, SAN MARCOS, CA 92069
County :	SAN DIEGO

Map Id: 84
Direction: NNW
Distance: 0.216 mi., 1140 ft.
Elevation: 549 ft.
Relative: Lower

Site Name : AUTO ELECTRIC | ROMA MARBLE | BATZS CAR CARE CENTER
3110 S SANTA FE | 3110 SOUTH SANTA FE
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 512251
EPA ID: CAL000261009

HAZNET - CA ***(cont.)***

Site Details

Generator EPA ID :	CAC001261184
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	2638 S SANTA FE BLVD, SAN MARCOS, CA 920690000
Latitude :	33.15527415
Longitude :	-117.19699333
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :

1997: 741 - Liquids with halogenated organic compounds >= 1,000 Mg. /L, 0.0208 tons to CAD008252405
1997: 343 - Unspecified organic liquid mixture, 0 tons to CAD008252405
1997: 352 - Other organic solids, 0.1 tons to CAD008252405
1995: 343 - Unspecified organic liquid mixture, 0 tons to CAD008252405
1995: 352 - Other organic solids, 0.1 tons to CAD008252405
1995: 741 - Liquids with halogenated organic compounds >= 1,000 Mg. /L, 0.0208 tons to CAD008252405

HWG - CA

Facility Name :	AUTO ELECTRIC
Facility Address :	3110 S SANTA FE, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAL000261009
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	3110 S SANTA FE, SAN MARCOS, CA 92069
Owner Name :	SERGIO SOLORZANO
Owner Address :	3110 S SANTA FE, SAN MARCOS, CA 92069
Operator Name :	SERGIO SOLORZANO
Operator Address :	3110 S SANTA FE, SAN MARCOS, CA 92069
Latitude :	33.155614
Longitude :	-117.197509
Facility Name :	BATZS CAR CARE CENTER
Facility Address :	3110 SOUTH SANTA FE, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAL000171729
Status :	Inactive
Category :	STATE

Map Id: 84
Direction: NNW
Distance: 0.216 mi., 1140 ft.
Elevation: 549 ft.
Relative: Lower

Site Name : AUTO ELECTRIC | ROMA MARBLE | BATZS CAR CARE CENTER
3110 S SANTA FE | 3110 SOUTH SANTA FE
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 512251
EPA ID: CAL000261009

HWG - CA ***(cont.)***

Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	3110 SOUTH SANTA FE, SAN MARCOS, CA 920690000
Owner Name :	GUSTAVO BATZ & OLGA SOLORZANO
Owner Address :	3110 SOUTH SANTA FE, SAN MARCOS, CA 920690000
Operator Name :	MARCIO DAZALOS/PARTNER
Operator Address :	INACT 99VQ FINAL NOTICE - BATCH, SAN MARCOS, CA 920690000
Latitude :	33.155614
Longitude :	-117.197509

Facility Name :	ROMA MARBLE
Facility Address :	3110 S SANTA FE BLVD, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAC001261184
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	2638 S SANTA FE BLVD, SAN MARCOS, CA 920690000
Owner Name :	ROMA MARBLE
Owner Address :	2638 S SANTA FE BLVD, SAN MARCOS, CA 920690000
Operator Name :	BRUNO DEANGELIS
Operator Address :	2638 S SANTA FE BLVD, SAN MARCOS, CA 920690000
Latitude :	33.155614
Longitude :	-117.197509

Map Id: K85
Direction: WSW
Distance: 0.218 mi., 1150 ft.
Elevation: 588 ft.
Relative: Higher

Site Name : APRO LLC DBA UNITED PACIFIC 0659 | UNITED PACIFIC 0659 | GSE San Marcos 851632
112 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA 92078

Database(s) : [CALEPA SITES - CA, ECHO, EPA UST, FID UST - CA, FRS, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN, UST - CA]

Envirosite ID: 410862
EPA ID: CAL000453913

CALEPA SITES - CA

Facility Name :	GSE San Marcos 851632
Facility Address :	112 S RANCHO SANTA FE RD, SAN MARCOS, 92078

Site ID :	60393
EI ID :	10376716

Map Id: K85
Direction: WSW
Distance: 0.218 mi., 1150 ft.
Elevation: 588 ft.
Relative: Higher

Site Name : APRO LLC DBA UNITED PACIFIC 0659 | UNITED PACIFIC 0659 | GSE San Marcos 851632
112 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA 92078

Database(s) : [CALEPA SITES - CA, ECHO, EPA UST, FID UST - CA, FRS, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 410862
EPA ID: CAL000453913

CALEPA SITES - CA ***(cont.)***

EI Description : Chemical Storage Facilities
Latitude : 33.149530
Longitude : -117.199040
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2020-02-19

Site ID : 60393
EI ID : 10376716
EI Description : Hazardous Waste Generator
Latitude : 33.149530
Longitude : -117.199040
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2020-02-19

Site ID : 60393
EI ID : 10376716
EI Description : Underground Storage Tank
Latitude : 33.149530
Longitude : -117.199040
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2020-02-19

Facility Name : UNITED PACIFIC 0659
Facility Address : 112 S RANCHO SANTA FE RD, SAN MARCOS, 92078

Site ID : 60393
EI ID : 10376716
EI Description : Chemical Storage Facilities
Latitude : 33.149530
Longitude : -117.199040
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-01-07

Site ID : 60393
EI ID : 10376716
EI Description : Hazardous Waste Generator
Latitude : 33.149530
Longitude : -117.199040
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-01-07

Site ID : 60393
EI ID : 10376716
EI Description : Underground Storage Tank
Latitude : 33.149530

Map Id: K85
Direction: WSW
Distance: 0.218 mi., 1150 ft.
Elevation: 588 ft.
Relative: Higher

Site Name : APRO LLC DBA UNITED PACIFIC 0659 | UNITED PACIFIC 0659 | GSE San Marcos 851632
112 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA 92078

Database(s) : [CALEPA SITES - CA, ECHO, EPA UST, FID UST - CA, FRS, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 410862
EPA ID: CAL000453913

CALEPA SITES - CA ***(cont.)***

Longitude :	-117.199040
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07

ECHO

Facility Name :	APRO LLC DBA UNITED PACIFIC 0659
Facility Address :	112 S RANCHO SANTA FE RD, SAN MARCOS, CA 92078
County :	SAN DIEGO
Last Inspection Date :	N/R
Registry ID :	110070798909
FIPS Code :	N/R
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	_____
Collection Method :	Zip Code Centroid
Reference Point :	N/R
Accuracy Meters :	10000
Derived Tribes :	N/R
Derived HUC :	N/R
Derived WBD :	N/R
Derived STCTY FIPS :	N/R
Derived Zip :	N/R
Derived CD113 :	N/R
Derived CB2010 :	N/R
MYRTK Universe :	NNN
NPDES IDs :	N/R
CWA Permit Types :	N/R
CWA Compliance Tracking :	N/R
CWA NAICS :	N/R
CWA SICS :	N/R
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R

Map Id: K85
Direction: WSW
Distance: 0.218 mi., 1150 ft.
Elevation: 588 ft.
Relative: Higher

Site Name : APRO LLC DBA UNITED PACIFIC 0659 | UNITED PACIFIC 0659 | GSE San Marcos 851632
112 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA 92078

Database(s) : [CALEPA SITES - CA, ECHO, EPA UST, FID UST - CA, FRS, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 410862
EPA ID: CAL000453913

ECHO ***(cont.)***

CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	N/R
CWA Current Compliance Status :	N/R
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	N/R
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	N/R
Facility NAICS :	447190 - Other Gasoline Stations
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	N/R
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	N
SDWIS Flag :	N
RCRA Flag :	Y
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	N/R
NAA Flag :	N
Latitude :	33.125563
Longitude :	-117.183287
Last Date in Agency List :	2022-01-17

EPA UST

Facility Name :	United Pacific 0659
Facility Address :	112 S Rancho Santa Fe Rd, San Marcos, California 92078
County :	N/R
Facility ID :	CA10376716
Facility Status :	Open UST(s)
Open USTs :	3
Closed USTs :	N/R
Temporarily Out of Service USTs :	N/R
Date of Last Inspection :	N/R

Map Id: K85
Direction: WSW
Distance: 0.218 mi., 1150 ft.
Elevation: 588 ft.
Relative: Higher

Site Name : APRO LLC DBA UNITED PACIFIC 0659 | UNITED PACIFIC 0659 | GSE San Marcos 851632
112 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA 92078

Database(s) : [CALEPA SITES - CA, ECHO, EPA UST, FID UST - CA, FRS, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 410862
EPA ID: CAL000453913

EPA UST ***(cont.)***

EPA Region :	9
Tribe :	N/R
Facility ID 2 :	N/R
Latitude :	33.149450986250002
Longitude :	-117.199068980850001
Last Date in Agency List :	2021-12-27

Tank Details

Tank ID :	CA10376716-001_A Stand-alone Tank_1
Tank Status :	Open
Installation Date :	1982-01-01
Removal Date :	N/R
Capacity :	10000
Substances :	Regular Unleaded
Tank Wall Type :	Single Wall

Tank ID :	CA10376716-002_A Stand-alone Tank_1
Tank Status :	Open
Installation Date :	1982-01-01
Removal Date :	N/R
Capacity :	10000
Substances :	Premium Unleaded
Tank Wall Type :	Single Wall

Tank ID :	CA10376716-003_A Stand-alone Tank_1
Tank Status :	Open
Installation Date :	1982-01-01
Removal Date :	N/R
Capacity :	10000
Substances :	Diesel
Tank Wall Type :	Single Wall

FID UST - CA

Facility Name :	GSE San Marcos 851632
Facility Address :	112 S Rancho Santa Fe Rd, San Marcos, 92078
County :	San Diego

Facility ID :	37-000-217308
CERSID :	10376716
Permitting Agency :	San Diego County Department of Environmental Health
Latitude :	N/R
Longitude :	N/R
Last Date in Agency List :	2020-10-12

Map Id: K85
Direction: WSW
Distance: 0.218 mi., 1150 ft.
Elevation: 588 ft.
Relative: Higher

Site Name : APRO LLC DBA UNITED PACIFIC 0659 | UNITED PACIFIC 0659 | GSE San Marcos 851632
112 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA 92078

Database(s) : [CALEPA SITES - CA, ECHO, EPA UST, FID UST - CA, FRS, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 410862
EPA ID: CAL000453913

FID UST - CA ***(cont.)***

Facility Name :	United Pacific 0659
Facility Address :	112 S Rancho Santa Fe Rd, San Marcos, 92078
County :	San Diego
Facility ID :	37-000-217308
CERSID :	10376716
Permitting Agency :	San Diego County Department of Environmental Health
Latitude :	N/R
Longitude :	N/R
Last Date in Agency List :	2022-03-14

FRS

Facility Name :	APRO LLC DBA UNITED PACIFIC 0659
Facility Address :	112 S RANCHO SANTA FE RD, SAN MARCOS, CA 92078
County :	SAN DIEGO

Site Details

Registry ID :	110070798909
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Source Description

Source Description :

RCRAInfo is EPA's comprehensive information system that supports the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984 through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA. RCRAInfo also supports generation of the National Hazardous Waste Biennial Report. All generators and treatment, storage, and disposal facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years to support creation of the Biennial Report.

FRS Environmental Interest

Source and System ID :	RCRAINFO - CAL000453913
Facility Name :	RANCHO SANTA FE 76
Facility Address :	112 S RANCHO SANTA FE RD, SAN MARCOS, CA 92078
County :	SAN DIEGO

Map Id: K85
Direction: WSW
Distance: 0.218 mi., 1150 ft.
Elevation: 588 ft.
Relative: Higher

Site Name : APRO LLC DBA UNITED PACIFIC 0659 | UNITED PACIFIC 0659 | GSE San Marcos 851632
112 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA 92078

Database(s) : [CALEPA SITES - CA, ECHO, EPA UST, FID UST - CA, FRS, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 410862
EPA ID: CAL000453913

FRS ***(cont.)***

Site Details

Registry ID :	110066048663
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Source Description

Source Description :

The California Environmental Protection Agency (CalEPA) has recently implemented a new data warehouse system (nSite). This data warehouse combines and merges facility and site information from five different systems managed within CalEPA. The five systems are: California Environmental Reporting System (CERS), EnviroStor, GeoTracker, California Integrated Water Quality System (CIWQS), and Toxic Release Inventory (TRI).

FRS Environmental Interest

Source and System ID :	CA-ENVIROVIEW - 60393

HAZNET - CA

Facility Name :	APRO LLC DBA UNITED PACIFIC 0659
Facility Address :	112 S RANCHO SANTA FE RD, SAN MARCOS, CA 92078
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000453913
Active :	Active
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	4130 COVER ST, LONG BEACH, CA 90808
Latitude :	33.14944800
Longitude :	-117.19907100
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Facility Name :	G & M OIL CO INC #171
Facility Address :	112 S RANCHO SANTA FE RD, SAN MARCOS, CA 92078
County :	SAN DIEGO

Map Id: K85
Direction: WSW
Distance: 0.218 mi., 1150 ft.
Elevation: 588 ft.
Relative: Higher

Site Name : APRO LLC DBA UNITED PACIFIC 0659 | UNITED PACIFIC 0659 | GSE San Marcos 851632
112 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA 92078

Database(s) : [CALEPA SITES - CA, ECHO, EPA UST, FID UST - CA, FRS, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 410862
EPA ID: CAL000453913

HAZNET - CA ***(cont.)***

Site Details

Generator EPA ID :	CAL000338216
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	16868 A LANE, HUNTINGTON BEACH, CA 926474831
Latitude :	33.14925986
Longitude :	-117.19887820
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :
2012: 352 - Other organic solids, 0.05 tons to CAD981696420
2012: 135 - Unspecified aqueous solution, 0.021 tons to CAD981696420
2011: 352 - Other organic solids, 0.075 tons to CAD008252405
2011: 135 - Unspecified aqueous solution, 0.21 tons to CAD981696420
2010: 352 - Other organic solids, 0.125 tons to CAD097030993
2010: 343 - Unspecified organic liquid mixture, 0.085 tons to CAD044429835
2009: 352 - Other organic solids, 0.03 tons to CAD981696420
2009: 343 - Unspecified organic liquid mixture, 0.459 tons to CAD028409019

Facility Name :	NEW WEST PETROLEUM SD1 # 1041
Facility Address :	112 S RANCHO SANTA FE RD, SAN MARCOS, CA 92078
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000189853
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	16868 A LN, HUNTINGTON BEACH, CA 926474831
Latitude :	33.14925986
Longitude :	-117.19887820
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Map Id: K85
Direction: WSW
Distance: 0.218 mi., 1150 ft.
Elevation: 588 ft.
Relative: Higher

Site Name : APRO LLC DBA UNITED PACIFIC 0659 | UNITED PACIFIC 0659 | GSE San Marcos 851632
112 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA 92078

Database(s) : [CALEPA SITES - CA, ECHO, EPA UST, FID UST - CA, FRS, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 410862
EPA ID: CAL000453913

HAZNET - CA ***(cont.)***

Waste Generator Details

State Waste :
2013: 241 - Tank bottom waste, 0.2502 tons to CAD028409019
2012: 241 - Tank bottom waste, 5.32926 tons to CAD028409019
2011: 133 - Aqueous solution with total organic residues 10 percent or more, 2.70216 tons to CAT080013352
2010: 133 - Aqueous solution with total organic residues 10 percent or more, 2.0016 tons to CAT080013352
2009: 134 - Aqueous solution with total organic residues less than 10 percent, 0.2184 tons to CAT080013352
2007: 343 - Unspecified organic liquid mixture, 0.187 tons to CAT080013352
2007: 134 - Aqueous solution with total organic residues less than 10 percent, 2.52 tons to AZR000035915
2007: 221 - Waste oil and mixed oil, 2.28 tons to AZR000035915
2007: 134 - Aqueous solution with total organic residues less than 10 percent, 0.126 tons to CAT080013352
2006: 134 - Aqueous solution with total organic residues less than 10 percent, 0.231 tons to CAT080013352
2005: 134 - Aqueous solution with total organic residues less than 10 percent, 0.147 tons to CAT080013352
2004: 213 - Hydrocarbon solvents (benzene, hexane, Stoddard, Etc.), 0.02 tons to CAD008252405
2000: 134 - Aqueous solution with total organic residues less than 10 percent, 0.0966 tons to CAT080013352
1999: 221 - Waste oil and mixed oil, 0.209 tons to CAD028409019

Facility Name : RANCHO SANTE FE 76
Facility Address : 112 S RANCHO SANTA FE RD, SAN MARCOS, CA 92078
County : SAN DIEGO

Site Details

Generator EPA ID : CAL000377559
Active : Inactive
Category : STATE
Facility Types : N/R
Type : PERMANENT
Contact Name : N/R
Contact Phone : N/R
Facility Mailing Address : 29501 CANWOOD ST STE 200, AGOURA HILLS, CA 913011570
Latitude : 33.14944800
Longitude : -117.19907100
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2021-07-08

Map Id: K85
Direction: WSW
Distance: 0.218 mi., 1150 ft.
Elevation: 588 ft.
Relative: Higher

Site Name : APRO LLC DBA UNITED PACIFIC 0659 | UNITED PACIFIC 0659 | GSE San Marcos 851632
112 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA 92078

Database(s) : [CALEPA SITES - CA, ECHO, EPA UST, FID UST - CA, FRS, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 410862
EPA ID: CAL000453913

HAZNET - CA ***(cont.)***

Waste Generator Details
State Waste :
2016: 352 - Other organic solids, 0.165 tons to CAD044429835
2016: 134 - Aqueous solution with total organic residues less than 10 percent, 0.2 tons to CAD044429835
2015: 352 - Other organic solids, 0.33 tons to CAD044429835
2015: 352 - Other organic solids, 0.1 tons to CAD982444481
2014: 352 - Other organic solids, 0.15 tons to CAD982444481
2014: 241 - Tank bottom waste, 1.52205 tons to CAD028409019
2013: 241 - Tank bottom waste, 2.31435 tons to CAD028409019
2013: 241 - Tank bottom waste, 0.22935 tons to CAL000377559
2013: 352 - Other organic solids, 0.25 tons to CAD982444481
2012: 241 - Tank bottom waste, 0.78396 tons to CAD028409019

HWG - CA

Facility Name : APRO LLC DBA UNITED PACIFIC 0659
Facility Address : 112 S RANCHO SANTA FE RD, SAN MARCOS, CA 92078
County : SAN DIEGO

EPA ID : CAL000453913
Status : Active
Category : STATE
Type : PERMANENT
Facility Type : N/R
Mailing Address : 4130 COVER ST, LONG BEACH, CA 90808
Owner Name : APRO LLC DBA UNITED PACIFIC
Owner Address : 4130 COVER ST, LONG BEACH, CA 90808
Operator Name : UMANGDEEP SINGH
Operator Address : 4130COVER ST, LONG BEACH, CA 90808
Latitude : 33.149448
Longitude : -117.199071

Facility Name : G & M OIL CO INC #171
Facility Address : 112 S RANCHO SANTA FE RD, SAN MARCOS, CA 92078
County : SAN DIEGO

EPA ID : CAL000338216
Status : Inactive
Category : STATE
Type : PERMANENT
Facility Type : N/R
Mailing Address : 16868 A LANE, HUNTINGTON BEACH, CA 926474831
Owner Name : G & M OIL CO INC
Owner Address : 16868 A LANE, HUNTINGTON BEACH, CA 926470000
Operator Name : SOLEDAD GERMAN
Operator Address : 16868 A LANE, HUNTINGTON BEACH, CA 92647
Latitude : 33.149177
Longitude : -117.198823

Map Id: K85
Direction: WSW
Distance: 0.218 mi., 1150 ft.
Elevation: 588 ft.
Relative: Higher

Site Name : APRO LLC DBA UNITED PACIFIC 0659 | UNITED PACIFIC 0659 | GSE San Marcos 851632
112 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA 92078

Database(s) : [CALEPA SITES - CA, ECHO, EPA UST, FID UST - CA, FRS, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 410862
EPA ID: CAL000453913

HWG - CA ***(cont.)***

Facility Name :	NEW WEST PETROLEUM SD1 # 1041
Facility Address :	112 S RANCHO SANTA FE RD, SAN MARCOS, CA 92078
County :	SAN DIEGO
EPA ID :	CAL000189853
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	16868 A LN, HUNTINGTON BEACH, CA 926474831
Owner Name :	G & M OIL CO LLC
Owner Address :	16868 A LN, HUNTINGTON BEACH, CA 926470000
Operator Name :	SOLEDAD GERMAN
Operator Address :	16868 A LANE, HUNTINGTON BEACH, CA 92647
Latitude :	33.149177
Longitude :	-117.198823
Facility Name :	RANCHO SANTE FE 76
Facility Address :	112 S RANCHO SANTA FE RD, SAN MARCOS, CA 92078
County :	SAN DIEGO
EPA ID :	CAL000377559
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	29501 CANWOOD ST STE 200, AGOURA HILLS, CA 913011570
Owner Name :	WESTERN FUEL GROUP INC
Owner Address :	29501 CANWOOD ST STE 200, AGOURA HILLS, CA 913011570
Operator Name :	LISA THOMPSON
Operator Address :	29501 CANWOOD ST STE 200, AGOURA HILLS, CA 91301
Latitude :	33.148939
Longitude :	-117.199056

MANIFEST EPA

Manifest Details

Manifest Number :	022895019JJK
Shipped Date :	2021-07-12
Updated Date :	2021-08-16
Received Date :	2021-07-22
Status :	Signed
Generator ID :	CAL000453913
Generator Name :	APRO LLC DBA UNITED PACIFIC 0659
Generator Address :	112 S RANCHO SANTA FE RD, SAN MARCOS, CA 92078
Generator Mailing :	4130 COVER ST, LONG BEACH, CA 90808
Generator Contact :	N/R
Destination ID :	CAD028409019

Map Id: K85
Direction: WSW
Distance: 0.218 mi., 1150 ft.
Elevation: 588 ft.
Relative: Higher

Site Name : APRO LLC DBA UNITED PACIFIC 0659 | UNITED PACIFIC 0659 | GSE San Marcos 851632
112 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA 92078

Database(s) : [CALEPA SITES - CA, ECHO, EPA UST, FID UST - CA, FRS, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 410862
EPA ID: CAL000453913

MANIFEST EPA ***(cont.)***

Destination Name :	CROSBY & OVERTON
Destination Mailing :	1630 W. 17TH STREET CA90813 CA037US 1630, LONG BEACH, CA 90813
Destination Address :	1630 W. 17TH STREET, LONG BEACH, CA 90813-0000
Destination Contact :	N/R
Submission Type :	DataImage5Copy
Origin Type :	Web
Manifest Residue :	N
Rejection :	N
Last Date in Agency List :	2022-01-14

Waste Details

Waste Line Number :	1
Is DOT Hazardous :	N
DOT ID Number :	N/R
DOT Information :	N/R
Non Waste Description :	NON RCRA HAZARDOUS WASTE LIQUID
Quantity :	30 Gallons
Quantity Tons, Acute, Non-Acute :	0.12510425, 0, 0.12510425
Quantity Kg, Acute, Non-Acute :	0, 113.47331
Management Method :	H135 - DISCHARGE TO SEWER/POTW OR NPDES
Is EPA Waste :	N
Federal Code :	N/R
State Code :	CA - 241

Manifest Details

Manifest Number :	023393002JJK
Shipped Date :	2021-07-12
Updated Date :	2021-08-17
Received Date :	2021-07-22
Status :	Signed
Generator ID :	CAL000453913
Generator Name :	APRO LLC DBA UNITED PACIFIC 0659
Generator Address :	112 S RANCHO SANTA FE RD, SAN MARCOS, CA 92078
Generator Mailing :	4130 COVER ST, LONG BEACH, CA 90808
Generator Contact :	N/R
Destination ID :	CAD028409019
Destination Name :	CROSBY & OVERTON
Destination Mailing :	1630 W. 17TH STREET CA90813 CA037US 1630, LONG BEACH, CA 90813
Destination Address :	1630 W. 17TH STREET, LONG BEACH, CA 90813-0000
Destination Contact :	N/R
Submission Type :	DataImage5Copy
Origin Type :	Web
Manifest Residue :	N
Rejection :	N
Last Date in Agency List :	2022-01-14

Map Id: K85
Direction: WSW
Distance: 0.218 mi., 1150 ft.
Elevation: 588 ft.
Relative: Higher

Site Name : APRO LLC DBA UNITED PACIFIC 0659 | UNITED PACIFIC 0659 | GSE San Marcos 851632
112 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA 92078

Database(s) : [CALEPA SITES - CA, ECHO, EPA UST, FID UST - CA, FRS, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 410862
EPA ID: CAL000453913

MANIFEST EPA ***(cont.)***

Waste Details

Waste Line Number :	1
Is DOT Hazardous :	N
DOT ID Number :	N/R
DOT Information :	N/R
Non Waste Description :	NON RCRA HAZARDOUS WASTE SOLID
Quantity :	150 Pounds
Quantity Tons, Acute, Non-Acute :	0.075, 0, 0.075
Quantity Kg, Acute, Non-Acute :	0, 68.02725
Management Method :	H141 - STORAGE, BULKING AND/OR TRANSFER OFF SITE
Is EPA Waste :	N
Federal Code :	N/R
State Code :	CA - 352

Manifest Details

Manifest Number :	018273908JJK
Shipped Date :	2020-12-28
Updated Date :	2021-02-03
Received Date :	2021-01-07
Status :	Signed
Generator ID :	CAL000453913
Generator Name :	APRO LLC DBA UNITED PACIFIC 0659
Generator Address :	112 S RANCHO SANTA FE RD, SAN MARCOS, CA 92078
Generator Mailing :	4130 COVER ST, LONG BEACH, CA 90808
Generator Contact :	N/R
Destination ID :	CAD028409019
Destination Name :	CROSBY & OVERTON
Destination Mailing :	1630 W. 17TH STREET CA90813 CA037US 1630, LONG BEACH, CA 90813
Destination Address :	1630 W. 17TH STREET, LONG BEACH, CA 90813-0000
Destination Contact :	N/R
Submission Type :	DataImage5Copy
Origin Type :	Web
Manifest Residue :	N
Rejection :	N
Last Date in Agency List :	2022-01-14

Waste Details

Waste Line Number :	1
Is DOT Hazardous :	N
DOT ID Number :	N/R
DOT Information :	N/R
Non Waste Description :	NON RCRA HAZARDOUS WASTE LIQUID
Quantity :	30 Gallons
Quantity Tons, Acute, Non-Acute :	0.12510425, 0, 0.12510425
Quantity Kg, Acute, Non-Acute :	0, 113.47331
Management Method :	H135 - DISCHARGE TO SEWER/POTW OR NPDES
Is EPA Waste :	N

Map Id: K85
Direction: WSW
Distance: 0.218 mi., 1150 ft.
Elevation: 588 ft.
Relative: Higher

Site Name : APRO LLC DBA UNITED PACIFIC 0659 | UNITED PACIFIC 0659 | GSE San Marcos 851632
112 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA 92078

Database(s) : [CALEPA SITES - CA, ECHO, EPA UST, FID UST - CA, FRS, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 410862
EPA ID: CAL000453913

MANIFEST EPA ***(cont.)***

Federal Code :	N/R
State Code :	CA - 241

RCRA_NONGEN

Facility Name :	APRO LLC DBA UNITED PACIFIC 0659
Facility Address :	112 S RANCHO SANTA FE RD, SAN MARCOS, CA 92078
County :	SAN DIEGO
Date Form Received by Agency :	2020-03-25
EPA ID :	CAL000453913
Mailing Address :	4130 COVER ST, LONG BEACH, CA 90808
Contact :	TOM ROBINS
Contact Address :	4130 COVER ST, LONG BEACH, CA 90808
Contact Country :	US
Contact Telephone :	310-323-3992
Contact Email :	TOM.ROBINS@UNITEDPACIFIC.COM
EPA Region :	09
Land Type :	Private
Source Type :	Implementer
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2022-01-26

Owner/Operator Summary

Owner/Operator Name :	APRO LLC DBA UNITED PACIFIC
Owner/Operator Address :	4130 COVER ST, LONG BEACH, CA 90808
Owner/Operator Country :	US
Owner/Operator Telephone :	310-323-3992
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Private
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Owner/Operator Name :	APRO LLC DBA UNITED PACIFIC
Owner/Operator Address :	4130 COVER ST, LONG BEACH, CA 90808
Owner/Operator Country :	US
Owner/Operator Telephone :	310-323-3992
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Private
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Map Id: K85
Direction: WSW
Distance: 0.218 mi., 1150 ft.
Elevation: 588 ft.
Relative: Higher

Site Name : APRO LLC DBA UNITED PACIFIC 0659 | UNITED PACIFIC 0659 | GSE San Marcos 851632
112 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA 92078

Database(s) : [CALEPA SITES - CA, ECHO, EPA UST, FID UST - CA, FRS, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 410862
EPA ID: CAL000453913

RCRA_NONGEN ***(cont.)***

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N/R
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Notices of Violations Summary

Regulation Violated :	N

UST - CA

Facility Name :	GSE San Marcos 851632
Facility Address :	112 S Rancho Santa Fe Rd, San Marcos, 92078
County :	San Diego
Facility ID :	37-000-217308
CERS ID :	10376716
Permitting Agency :	San Diego County Department of Environmental Health
Latitude :	N/R
Longitude :	N/R
Last Date in Agency List :	2020-06-21
Facility Name :	United Pacific 0659
Facility Address :	112 S Rancho Santa Fe Rd, San Marcos, 92078
County :	San Diego
Facility ID :	37-000-217308
CERS ID :	10376716
Permitting Agency :	San Diego County Department of Environmental Health
Latitude :	N/R
Longitude :	N/R
Last Date in Agency List :	2022-03-07

Map Id: 86
Direction: ESE
Distance: 0.219 mi., 1158 ft.
Elevation: 564 ft.
Relative: Lower

Site Name : PEACOCK CLEANERS
1450 MISSION RD W #S
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, FRS]

Envirosite ID: 231240
EPA ID: N/R

CALEPA SITES - CA

Facility Name :	PEACOCK CLEANERS
Facility Address :	1450 MISSION RD W #S, SAN MARCOS, 92069-1327
Site ID :	486512
EI ID :	110013855792
EI Description :	US EPA Air Emission Inventory System (EIS)
Latitude :	33.150640
Longitude :	-117.192070
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07

FRS

Facility Name :	PEACOCK CLEANERS
Facility Address :	1450 MISSION RD W #S, SAN MARCOS, CA 92069-1327
County :	SAN DIEGO

Site Details

Registry ID :	110013855792
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Source Description

Source Description :

The Emission Inventory System (EIS) maintains an inventory of large stationary sources and voluntarily-reported smaller sources of air point pollution emitters. It contains information about facility sites and their physical location, emission units, emission processes, release points, control approaches, and regulations. Facility inventory data are kept separate from the emissions data and have stable identifiers to improve continuity from year to year and to help identify duplicate or missing facilities.

FRS Environmental Interest

Source and System ID :	EIS - 1614411

Map Id: K87
Direction: SW
Distance: 0.220 mi., 1162 ft.
Elevation: 587 ft.
Relative: Lower

Site Name : COUNTY OF SAN DIEGO PUBLIC WORKS
1660 DESCANSO AV
SAN MARCOS, CA 92123

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 41147869
EPA ID: CAX000085647

HAZNET - CA

Facility Name :	COUNTY OF SAN DIEGO PUBLIC WORKS

Map Id: K87
Direction: SW
Distance: 0.220 mi., 1162 ft.
Elevation: 587 ft.
Relative: Lower

Site Name : COUNTY OF SAN DIEGO PUBLIC WORKS
1660 DESCANSO AV
SAN MARCOS, CA 92123

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 41147869
EPA ID: CAX000085647

HAZNET - CA ***(cont.)***

Facility Address :	1660 DESCANSO AV, SAN MARCOS, CA 92123
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAX000085647
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	5555 OVERLAND AV, SAN DIEGO, CA 921230000
Latitude :	33.14879260
Longitude :	-117.19816389
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HWG - CA

Facility Name :	COUNTY OF SAN DIEGO PUBLIC WORKS
Facility Address :	1660 DESCANSO AV, SAN MARCOS, CA 92123
County :	SAN DIEGO

EPA ID :	CAX000085647
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	5555 OVERLAND AV, SAN DIEGO, CA 921230000
Owner Name :	N/R
Owner Address :	N/A
Operator Name :	DAN YUBBEN
Operator Address :	INACT PER 98VQ FINAL NOTICE, N/A
Latitude :	32.799863
Longitude :	-116.864176

Map Id: M88
Direction: SE
Distance: 0.220 mi., 1163 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : BUTLER MACHINING AND DESIGN INCORPORATED | PACIFIC METAL PRODUCTS | ANVIL DESIGNS
155 BALBOA ST D4 | 155 BALBOA ST UNIT D13 | 155 BALBOA ST
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS - CA, DOCKET, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS ENF, PCS FACILITY, RFR - CA, STORMWATER]

Envirosite ID: 637381
EPA ID: N/R

CALEPA SITES - CA

Facility Name :	Butler Machining and Design Incorporated
Facility Address :	155 BALBOA ST. D4, SAN MARCOS, 92069
Site ID :	528094
EI ID :	848362
EI Description :	Industrial Facility Storm Water
Latitude :	33.148371
Longitude :	-117.191930
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-08-26
Facility Name :	PACIFIC METAL PRODUCTS
Facility Address :	155 BALBOA STREET, SUITE D13, SAN MARCOS, 92069
Site ID :	566306
EI ID :	10842595
EI Description :	Hazardous Waste Generator
Latitude :	33.148440
Longitude :	-117.191990
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07
Site ID :	566306
EI ID :	10842595
EI Description :	Chemical Storage Facilities
Latitude :	33.148440
Longitude :	-117.191990
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07
Facility Name :	PACIFIC METAL PRODUCTS
Facility Address :	155 BALBOA ST UNIT D13, SAN MARCOS, 92069
Site ID :	586731
EI ID :	888321
EI Description :	Industrial Facility Storm Water
Latitude :	33.148390
Longitude :	-117.192050
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07

Map Id: M88
Direction: SE
Distance: 0.220 mi., 1163 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : BUTLER MACHINING AND DESIGN INCORPORATED | PACIFIC METAL PRODUCTS | ANVIL DESIGNS
155 BALBOA ST D4 | 155 BALBOA ST UNIT D13 | 155 BALBOA ST
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS - CA, DOCKET, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS ENF, PCS FACILITY, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 637381
EPA ID: N/R

CIWQS - CA

Facility Name :	Butler Machining and Design Incorporated
Facility Address :	155 Balboa St. D4, San Marcos, CA 92069
County :	San Diego
Place ID :	S848362
Agency Name :	Butler Machining and Design Incorporated
Last Date in Agency List :	2020-10-30
Facility Name :	BUTLER MACHINING AND DESIGN INCORPORATED
Facility Address :	155 BALBOA ST D4, SAN MARCOS, CA 92069
County :	SAN DIEGO
Place ID :	S848362
Agency Name :	BUTLER MACHINING AND DESIGN INCORPORATED
Last Date in Agency List :	2021-12-30

DOCKET

Facility Name :	BUTLER MACHINING AND DESIGN INCORPORATED
Facility Address :	155 BALBOA ST. D4, SAN MARCOS, CA 92069

Standard Industrial Classification(SIC) Summary

Enforcement Action Name :	BUTLER MACHINING AND DESIGN INCORPORATED
Registry ID :	110070096731
Primary SIC :	3499 - FABRICATED METAL PRODUCTS, NOT ELSEWHERE CLASSIFIED
Primary NAICS :	N/R
Last Date in Agency List :	2018-12-17
Enforcement Action Case Number :	N/R
Activity ID :	N/R
Final Ordr Iss/Final Order Enter Date:	N/R
Final Order Name :	N/R
Settlement FRS ICIS Facility ID :	N/R
Final Order FRS Name :	N/R
SEP Category :	N/R
SEP Description :	N/R

Map Id: M88
Direction: SE
Distance: 0.220 mi., 1163 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : BUTLER MACHINING AND DESIGN INCORPORATED | PACIFIC METAL PRODUCTS | ANVIL DESIGNS
155 BALBOA ST D4 | 155 BALBOA ST UNIT D13 | 155 BALBOA ST
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS - CA, DOCKET, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS ENF, PCS FACILITY, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 637381
EPA ID: N/R

DOCKET ***(cont.)***

Complaint Summary

Respondent/Defendant Name :	N/R
Named in Complaint :	N/R
Named in Final Order :	N/R

Pollutant Summary

Pollutants (SRS) :	N/R

Violation and Enforcement Action Summary

Court Docket Number :	N/R
Complaint/Proposed Order Actual Date:	N/R
Final Order Issued Actual Date :	N/R
Admin EA Closed Actual Date :	2017-10-05
Enforcement Action Name :	N/R
Enforcement Action Resolution :	N/R
Violation Type :	N/R
Statute Code :	CWA
Law Section Code :	OTHER
Law Section Description :	Violations not covered elsewhere

Violation Penalties and Compliance Summary

Compliance Action Cost :	N/R
EPA Penalty Assessed Amount :	N/R
Cost Recovery Required :	N/R
Cost of SEP :	N/R
Cost of Complying Actions :	N/R

ECHO

Facility Name :	BUTLER MACHINING AND DESIGN INCORPORATED
Facility Address :	155 BALBOA ST D4, SAN MARCOS, CA 92069
County :	SAN DIEGO COUNTY

Map Id: M88
Direction: SE
Distance: 0.220 mi., 1163 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : BUTLER MACHINING AND DESIGN INCORPORATED | PACIFIC METAL PRODUCTS | ANVIL DESIGNS
155 BALBOA ST D4 | 155 BALBOA ST UNIT D13 | 155 BALBOA ST
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS - CA, DOCKET, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS ENF, PCS FACILITY, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 637381
EPA ID: N/R

ECHO ***(cont.)***

Last Inspection Date :	N/R
Registry ID :	110070096731
FIPS Code :	06073
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	1
Last Informal Action Date :	2020-10-26
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	9
Programs IN SNC :	0
Current Compliance Status :	N/R
Three-Year Compliance Status :	VVVVVVVVV
Collection Method :	N/R
Reference Point :	N/R
Accuracy Meters :	17531

Derived Tribes :

San Pasqual Band of Diegueno Mission Indians of California - 12.2 mile(s), Pala Band of Mission Indians - 13.2 mile (s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 13.9 mile(s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 16.1 mile(s), Pauma Band of Luiseno Mission Indians of the Pauma & Yuima Reservation, California - 16.8 mile(s), La Jolla Band of Luiseno Indians, California - 17 mile(s), Pechanga Band of Luiseno Mission Indians of the Pechanga Reservation, California - 20.5 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 22.4 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 22.7 mile(s), Mesa Grande Band of Diegueno Mission Indians of the Mesa Grande Reservation, California - 23 mile(s)

Derived HUC :	18070303
Derived WBD :	180703030503
Derived STCTY FIPS :	06073
Derived Zip :	92069
Derived CD113 :	50
Derived CB2010 :	060730200292003
MYRTK Universe :	NNN
NPDES IDs :	CAZ475887
CWA Permit Types :	Minor
CWA Compliance Tracking :	Off
CWA NAICS :	N/R
CWA SICS :	3499
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	1

Map Id: M88
Direction: SE
Distance: 0.220 mi., 1163 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : BUTLER MACHINING AND DESIGN INCORPORATED | PACIFIC METAL PRODUCTS | ANVIL DESIGNS
155 BALBOA ST D4 | 155 BALBOA ST UNIT D13 | 155 BALBOA ST
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS - CA, DOCKET, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS ENF, PCS FACILITY, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 637381
EPA ID: N/R

ECHO ***(cont.)***

CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	10
CWA Current Compliance Status :	Terminated Permit
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	VVVVVVVVVV
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	3499
Facility NAICS :	N/R
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	2020-10-26
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	Y
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	Y
SDWIS Flag :	N
RCRA Flag :	N
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	N/R
NAA Flag :	Y
Latitude :	33.148371
Longitude :	-117.19193
Last Date in Agency List :	2022-01-17

Facility Name :	BUTLER MACHINING AND DESIGN INCORPORATED
Facility Address :	155 BALBOA ST. D4, SAN MARCOS, CA 92069
County :	SAN DIEGO COUNTY

Last Inspection Date :	N/R
Registry ID :	110070096731

Map Id: M88
Direction: SE
Distance: 0.220 mi., 1163 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : BUTLER MACHINING AND DESIGN INCORPORATED | PACIFIC METAL PRODUCTS | ANVIL DESIGNS
155 BALBOA ST D4 | 155 BALBOA ST UNIT D13 | 155 BALBOA ST
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS - CA, DOCKET, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS ENF, PCS FACILITY, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 637381
EPA ID: N/R

ECHO ***(cont.)***

FIPS Code :	06073
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	12
Programs IN SNC :	0
Current Compliance Status :	Violation Identified
Three-Year Compliance Status :	VVVVVVVVVVVV
Collection Method :	N/R
Reference Point :	N/R
Accuracy Meters :	17531

Derived Tribes :

San Pasqual Band of Diegueno Mission Indians of California - 12.2 mile(s), Pala Band of Mission Indians - 13.2 mile (s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 13.9 mile(s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 16.1 mile(s), Pauma Band of Luiseno Mission Indians of the Pauma & Yuima Reservation, California - 16.8 mile(s), La Jolla Band of Luiseno Indians, California - 17 mile(s), Pechanga Band of Luiseno Mission Indians of the Pechanga Reservation, California - 20.5 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 22.4 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 22.7 mile(s), Mesa Grande Band of Diegueno Mission Indians of the Mesa Grande Reservation, California - 23 mile(s)

Derived HUC :	18070303
Derived WBD :	180703030503
Derived STCTY FIPS :	06073
Derived Zip :	92069
Derived CD113 :	50
Derived CB2010 :	060730200292003
MYRTK Universe :	NNN
NPDES IDs :	CAZ475887
CWA Permit Types :	Minor
CWA Compliance Tracking :	On
CWA NAICS :	N/R
CWA SICS :	3499
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R

Map Id: M88
Direction: SE
Distance: 0.220 mi., 1163 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : BUTLER MACHINING AND DESIGN INCORPORATED | PACIFIC METAL PRODUCTS | ANVIL DESIGNS
155 BALBOA ST D4 | 155 BALBOA ST UNIT D13 | 155 BALBOA ST
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS - CA, DOCKET, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS ENF, PCS FACILITY, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 637381
EPA ID: N/R

ECHO ***(cont.)***

CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	12
CWA Current Compliance Status :	Violation Identified
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	VVVVVVVVVVVVV
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	3499
Facility NAICS :	N/R
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	Y
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	Y
SDWIS Flag :	N
RCRA Flag :	N
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	Y
NAA Flag :	Y
Latitude :	33.148371
Longitude :	-117.19193
Last Date in Agency List :	2021-02-17

FRS

Facility Name :	BUTLER MACHINING AND DESIGN INCORPORATED
Facility Address :	155 BALBOA ST D4, SAN MARCOS, CA 92069
County :	SAN DIEGO COUNTY

Map Id: M88
Direction: SE
Distance: 0.220 mi., 1163 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : BUTLER MACHINING AND DESIGN INCORPORATED | PACIFIC METAL PRODUCTS | ANVIL DESIGNS
155 BALBOA ST D4 | 155 BALBOA ST UNIT D13 | 155 BALBOA ST
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS - CA, DOCKET, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS ENF, PCS FACILITY, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 637381
EPA ID: N/R

FRS ***(cont.)***

Site Details
Registry ID : 110070096731
FRS Facility URL : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-02-17

Source Description

Source Description :

The NPDES module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

FRS Environmental Interest
Source and System ID : ICIS - CAZ475887

Facility Name : BUTLER MACHINING AND DESIGN INCORPORATED
Facility Address : 155 BALBOA ST. D4, SAN MARCOS, CA 92069
County : SAN DIEGO COUNTY

Site Details
Registry ID : 110070096731
FRS Facility URL : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2021-05-03

Source Description

Source Description :

The NPDES module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.

Map Id: M88
Direction: SE
Distance: 0.220 mi., 1163 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : BUTLER MACHINING AND DESIGN INCORPORATED | PACIFIC METAL PRODUCTS | ANVIL DESIGNS
155 BALBOA ST D4 | 155 BALBOA ST UNIT D13 | 155 BALBOA ST
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS - CA, DOCKET, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS ENF, PCS FACILITY, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 637381
EPA ID: N/R

FRS ***(cont.)***

FRS Environmental Interest
Source and System ID : ICIS - CAZ475887

HAZMAT_SAN DIEGO COUNTY - CA

Facility Name : ANVIL DESIGNS
Facility Address : 155 BALBOA ST, SAN MARCOS, CA 92069

Date : 2002-05-04
Record ID : DEH2002-HUPFP-126032
Record Type : Unified Program Facility Permit
Status : Completed
Action : N/R
Short Notes : N/R
Last Date in Agency List : 2015-11-23

Facility Name : Pacific Metal Products
Facility Address : 155 BALBOA ST, SUITE D13, SAN MARCOS, CA 920691346

Date : 2020-05-27
Record ID : DEH2020-HUPFP-005866
Record Type : Unified Program Facility Permit
Status : Pending Inspection
Action : N/R
Short Notes : N/R
Last Date in Agency List : 2021-02-19

ICIS

Facility Name : BUTLER MACHINING AND DESIGN INCORPORATED
Facility Address : 155 BALBOA ST D4, SAN MARCOS, CA 92069

Site Details
NPDES ID : CAZ475887
ICIS Facility Interest ID : 3600735417
Facility UIN : 110070096731
Facility Type Code : Privately Owned Facility
Impaired Waters : N/R
Latitude : 33.148371
Longitude : -117.19193
Last Date in Agency List : 2022-01-12

Map Id: M88
Direction: SE
Distance: 0.220 mi., 1163 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : BUTLER MACHINING AND DESIGN INCORPORATED | PACIFIC METAL PRODUCTS | ANVIL DESIGNS
155 BALBOA ST D4 | 155 BALBOA ST UNIT D13 | 155 BALBOA ST
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS - CA, DOCKET, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS ENF, PCS FACILITY, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 637381
EPA ID: N/R

ICIS ***(cont.)***

Facility SIC

SIC Code :	3499
SIC Description :	Fabricated Metal Products
Facility Name :	BUTLER MACHINING AND DESIGN INCORPORATED
Facility Address :	155 BALBOA ST. D4, SAN MARCOS, CA 92069

Site Details

NPDES ID :	CAZ475887
ICIS Facility Interest ID :	3600735417
Facility UIN :	110070096731
Facility Type Code :	Privately Owned Facility
Impaired Waters :	N/R
Latitude :	33.148371
Longitude :	-117.19193
Last Date in Agency List :	2021-03-15

Facility SIC

SIC Code :	3499
SIC Description :	Fabricated Metal Products

INACTIVE PCS

Issue Date :	2016-08-03
Original Issue Date :	2016-08-03
Effective Date :	2016-08-03
Expiration Date :	2020-06-30
Retirement Date :	N/R
Termination Date :	2020-12-22
Issuing Agency :	CA Waterboards
Agency Type :	State
Activity ID :	3601114791
External Permit Number :	CAZ475887
Facility Type Indicator :	NON-POTW
Permit Type :	General Permit Covered Facility-NPDES)
Major Minor Status :	N
Permit Status :	Terminated
Total Design Flow Number :	N/R
Actual Average Flow Number :	N/R
State Water Body :	N/R
State Water Body Name :	N/R
Permit Name :	Butler Machining and Design Incorporated
Permit Comp Status :	Y
RNC Tracking :	Y

Map Id: M88
Direction: SE
Distance: 0.220 mi., 1163 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : BUTLER MACHINING AND DESIGN INCORPORATED | PACIFIC METAL PRODUCTS | ANVIL DESIGNS
155 BALBOA ST D4 | 155 BALBOA ST UNIT D13 | 155 BALBOA ST
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS - CA, DOCKET, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS ENF, PCS FACILITY, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 637381
EPA ID: N/R

INACTIVE PCS ***(cont.)***

Master External Permit Number :	CAS000001
TMDL Interface :	N/R
EDMR Authorization :	N
Pretreatment Indicator :	N/R
Last Date in Agency List :	2022-01-14
Issue Date :	2016-08-03
Original Issue Date :	2016-08-03
Effective Date :	2016-08-03
Expiration Date :	2020-06-30
Retirement Date :	N/R
Termination Date :	N/R
Issuing Agency :	CA Waterboards
Agency Type :	State
Activity ID :	3601114791
External Permit Number :	CAZ475887
Facility Type Indicator :	NON-POTW
Permit Type :	General Permit Covered Facility-NPDES)
Major Minor Status :	N
Permit Status :	Expired
Total Design Flow Number :	N/R
Actual Average Flow Number :	N/R
State Water Body :	N/R
State Water Body Name :	N/R
Permit Name :	Butler Machining and Design Incorporated
Permit Comp Status :	Y
RNC Tracking :	Y
Master External Permit Number :	CAS000001
TMDL Interface :	N/R
EDMR Authorization :	N
Pretreatment Indicator :	N/R
Last Date in Agency List :	2021-03-17

NPDES - CA

Facility Name :	Butler Machining and Design Incorporated
Facility Address :	155 Balboa St D4, San Marcos, 92069
County :	San Diego
Effective Date :	2016-08-03
Adoption Date :	N/R
Expiration Date :	N/R
Termination Date :	2020-12-22
Order Number :	97-03-DWQ
NPDES Number :	CAS000001
WDID :	9 37NEC002356
RM Status :	Terminated

Map Id: M88
Direction: SE
Distance: 0.220 mi., 1163 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : BUTLER MACHINING AND DESIGN INCORPORATED | PACIFIC METAL PRODUCTS | ANVIL DESIGNS
155 BALBOA ST D4 | 155 BALBOA ST UNIT D13 | 155 BALBOA ST
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS - CA, DOCKET, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS ENF, PCS FACILITY, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 637381
EPA ID: N/R

NPDES - CA ***(cont.)***

Reg Meas ID :	475887
Reg Meas Type :	Enrollee
Program :	Industrial
Facility Place ID :	N/R
Region Code :	9
Discharger ID :	0
Discharger :	Butler Machining and Design Incorporated
Discharger Address :	155 Balboa Street, San Marcos, California 92069
Last Date in Agency List :	2022-02-24
Facility Name :	Butler Machining and Design Incorporated
Facility Address :	155 Balboa St. D4, San Marcos, 92069
County :	San Diego
Effective Date :	2016-08-03
Adoption Date :	N/R
Expiration Date :	N/R
Termination Date :	N/R
Order Number :	97-03-DWQ
NPDES Number :	CAS000001
WDID :	9 37NEC002356
RM Status :	Active
Reg Meas ID :	475887
Reg Meas Type :	Enrollee
Program :	Industrial
Facility Place ID :	N/R
Region Code :	9
Discharger ID :	0
Discharger :	Butler Machining and Design Incorporated
Discharger Address :	155 Balboa Street, San Marcos, California 92069
Last Date in Agency List :	2021-01-23
Facility Name :	PACIFIC METAL PRODUCTS
Facility Address :	155 BALBOA ST UNIT D13, San Marcos, 92069
County :	San Diego
Effective Date :	2020-12-08
Adoption Date :	N/R
Expiration Date :	N/R
Termination Date :	N/R
Order Number :	97-03-DWQ
NPDES Number :	CAS000001
WDID :	9 37NEC008079
RM Status :	Active
Reg Meas ID :	529055

Map Id: M88
Direction: SE
Distance: 0.220 mi., 1163 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : BUTLER MACHINING AND DESIGN INCORPORATED | PACIFIC METAL PRODUCTS | ANVIL DESIGNS
155 BALBOA ST D4 | 155 BALBOA ST UNIT D13 | 155 BALBOA ST
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS - CA, DOCKET, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS ENF, PCS FACILITY, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 637381
EPA ID: N/R

NPDES - CA ***(cont.)***

Reg Meas Type :	Enrollee
Program :	Industrial
Facility Place ID :	N/R
Region Code :	9
Discharger ID :	0
Discharger :	PACIFIC METAL PRODUCTS
Discharger Address :	155 BALBOA ST UNIT D13, San Marcos, California 92069
Last Date in Agency List :	2022-02-24

PCS ENF

Site Details

NPDES ID :	CAZ475887
Last Date in Agency List :	2021-03-17

Formal Enforcement Actions

Settlement Entered Date :	N/R
ENF Identifier :	N/R
Activity ID :	N/R
Activity Type :	N/R
ENF Type :	N/R
Agency :	N/R
Fed Penalty Assessed Amount :	N/R
State Local Penalty Amount :	N/R

Informal Enforcement Actions

Achieved Date :	10/26/2020
Registry ID :	110070096731
ENF Identifier :	CA-ZIEA439345
Activity ID :	3602370234
Activity Type :	Administrative - Informal
ENF Type :	Notice of Violation
Agency :	State

Achieved Date :	10/05/2017
Registry ID :	110070096731
ENF Identifier :	CA-ZIEA428634
Activity ID :	3601334194
Activity Type :	Administrative - Informal
ENF Type :	Phone Call/ EMAIL
Agency :	State

Map Id: M88
Direction: SE
Distance: 0.220 mi., 1163 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : BUTLER MACHINING AND DESIGN INCORPORATED | PACIFIC METAL PRODUCTS | ANVIL DESIGNS
155 BALBOA ST D4 | 155 BALBOA ST UNIT D13 | 155 BALBOA ST
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS - CA, DOCKET, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS ENF, PCS FACILITY, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 637381
EPA ID: N/R

PCS ENF ***(cont.)***

Site Details

NPDES ID :	CAZ475887
Last Date in Agency List :	2022-01-19

Formal Enforcement Actions

Settlement Entered Date :	N/R
ENF Identifier :	N/R
Activity ID :	N/R
Activity Type :	N/R
ENF Type :	N/R
Agency :	N/R
Fed Penalty Assessed Amount :	N/R
State Local Penalty Amount :	N/R

Informal Enforcement Actions

Achieved Date :	10/26/2020
Registry ID :	110070096731
ENF Identifier :	CA-ZIEA439345
Activity ID :	3602370234
Activity Type :	Administrative - Informal
ENF Type :	Notice of Violation
Agency :	State

Achieved Date :	10/05/2017
Registry ID :	110070096731
ENF Identifier :	CA-ZIEA428634
Activity ID :	3601334194
Activity Type :	Administrative - Informal
ENF Type :	Phone Call/ EMAIL
Agency :	State

PCS FACILITY

Issue Date :	2016-08-03
Original Issue Date :	2016-08-03
Effective Date :	2016-08-03
Expiration Date :	2020-06-30
Retirement Date :	N/R
Termination Date :	N/R
Issuing Agency :	CA Waterboards
Agency Type :	State
Activity ID :	3601114791
External Permit Number :	CAZ475887
Facility Type Indicator :	NON-POTW

Map Id: M88
Direction: SE
Distance: 0.220 mi., 1163 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : BUTLER MACHINING AND DESIGN INCORPORATED | PACIFIC METAL PRODUCTS | ANVIL DESIGNS
155 BALBOA ST D4 | 155 BALBOA ST UNIT D13 | 155 BALBOA ST
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS - CA, DOCKET, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS ENF, PCS FACILITY, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 637381
EPA ID: N/R

PCS FACILITY ***(cont.)***

Permit Type :	General Permit Covered Facility-NPDES)
Major Minor Status :	N
Permit Status :	Effective
Total Design Flow Number :	N/R
Actual Average Flow Number :	N/R
State Water Body :	N/R
State Water Body Name :	N/R
Permit Name :	Butler Machining and Design Incorporated
Permit Comp Status :	Y
RNC Tracking :	Y
Master External Permit Number :	CAS000001
TMDL Interface :	N/R
EDMR Authorization :	N
Pretreatment Indicator :	N/R
Last Date in Agency List :	2020-02-11

RFR - CA

Facility Name :	Butler Machining and Design Incorporated
Facility Address :	155 Balboa St. D4, San Marcos, CA 92069
County :	San Diego
Effective Date :	2016-08-03
Adoption Date :	N/R
Termination Date :	N/R
Expiration/Review Date :	N/R
NPDES Number :	CAS000001
Order Number :	2014-0057-DWQ
WDID :	9 37NEC002356
SIC/NAICS :	3499
Program :	INDSTW
Regulatory Measure Status :	Active
Regulatory Measure Type :	Storm water industrial
Place/Project Type :	Industrial - Fabricated Metal Products, NEC
Region :	9
Design Flow :	N/R
Major/Minor :	N/R
Complexity :	N/R
TTWQ :	N/R
Number of Enforcement Actions within Five Years:	1
Number of Violations within Five Years:	1
Agency :	Butler Machining and Design Incorporated
Agency Address :	155 Balboa Street D4, San Marcos, CA 92069
Latitude :	33.148371
Longitude :	-117.19193
Last Date in Agency List :	2021-01-28

Map Id: M88
Direction: SE
Distance: 0.220 mi., 1163 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : BUTLER MACHINING AND DESIGN INCORPORATED | PACIFIC METAL PRODUCTS | ANVIL DESIGNS
155 BALBOA ST D4 | 155 BALBOA ST UNIT D13 | 155 BALBOA ST
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CIWQS - CA, DOCKET, ECHO, FRS, HAZMAT_SAN DIEGO COUNTY - CA, ICIS, INACTIVE PCS, NPDES - CA, PCS ENF, PCS FACILITY, RFR - CA, STORMWATER] ***(cont.)***

Envirosite ID: 637381
EPA ID: N/R

STORMWATER

Facility Name :	BUTLER MACHINING AND DESIGN INCORPORATED
Facility Address :	155 BALBOA ST D4, SAN MARCOS, CA 92069
NPDES ID :	CAZ475887
Permittee Name :	Butler Machining and Design Incorporated
Permit Status :	Terminated
Permit Issuing Name :	State
Issued Date :	2016-08-03
Termination Date :	2020-12-22
Effective Date :	2016-08-03 2020-06-30
EPA Region :	09
SIC Code :	3499
NAICS Code :	N/R
EJ Indexes Above 80th Percentile :	Y
Significant Noncompliance Status :	N/R
Quarters with Noncompliance :	10
Industrial Stormwater Formal Enforcement Actions:	N/R
Facility Map Flag :	Y
DRF URL :	Click here for hyperlink provided by the agency.
Latitude :	33.148371
Longitude :	-117.19193
Last Date in Agency List :	2022-01-11

Map Id: M89
Direction: SE
Distance: 0.223 mi., 1179 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : 1X BALBOA NAVAL HOSPITAL
BUILDING 121
SAN DIEGO, CA

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 41048889
EPA ID: CAP999001121

HAZNET - CA

Facility Name :	1X BALBOA NAVAL HOSPITAL
Facility Address :	BUILDING 121, SAN DIEGO, CA
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAP999001121
Active :	Inactive

Map Id: M89
Direction: SE
Distance: 0.223 mi., 1179 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : 1X BALBOA NAVAL HOSPITAL
BUILDING 121
SAN DIEGO, CA

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 41048889
EPA ID: CAP999001121

HAZNET - CA ***(cont.)***

Category :	FEDERAL
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	--, NORTH GLENN, CO
Latitude :	33.14850426
Longitude :	-117.19245602
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HWG - CA

Facility Name :	1X BALBOA NAVAL HOSPITAL
Facility Address :	BUILDING 121, SAN DIEGO, CA 00000
County :	SAN DIEGO
EPA ID :	CAP999001121
Status :	Inactive
Category :	FEDERAL
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	NORTH GLENN, CO 000000000
Owner Name :	N/R
Owner Address :	N/A
Operator Name :	TOM CODE
Operator Address :	N/A
Latitude :	33.148504
Longitude :	-117.192456

Map Id: K90
Direction: SW
Distance: 0.224 mi., 1184 ft.
Elevation: 583 ft.
Relative: Lower

Site Name : SAN DIEGO CO DPW DIV II
1600 DESCANSO AVE
SAN MARCOS, CA 92078

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 302506
EPA ID: CAD981454465

HAZNET - CA

Facility Name :	SAN DIEGO CO DPW DIV II
Facility Address :	1600 DESCANSO AVE, SAN MARCOS, CA 92078
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAD981454465
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT

Map Id: K90
Direction: SW
Distance: 0.224 mi., 1184 ft.
Elevation: 583 ft.
Relative: Lower

Site Name : SAN DIEGO CO DPW DIV II
1600 DESCANSO AVE
SAN MARCOS, CA 92078

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 302506
EPA ID: CAD981454465

HAZNET - CA ***(cont.)***

Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	5469 KEARNY VILLA RD STE 201, SAN DIEGO, CA 921231219
Latitude :	33.14865682
Longitude :	-117.19781712
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

State Waste :

2007: 213 - Hydrocarbon solvents (benzene, hexane, Stoddard, Etc.), 0.1668 tons to CAD044429835
2007: 331 - Off-specification, aged or surplus organics, 0.594 tons to CAD044429835
2006: 181 - Other inorganic solid waste, 0.18 tons to CAD028409019
2006: 343 - Unspecified organic liquid mixture, 0.374 tons to CAT080013352
2006: 331 - Off-specification, aged or surplus organics, 0.0825 tons to CAD044429835
2005: 343 - Unspecified organic liquid mixture, 1.071 tons to CAT080013352
2004: 352 - Other organic solids, 0.075 tons to CAD008252405
2004: 352 - Other organic solids, 0.5 tons to CAT080033681
2003: 352 - Other organic solids, 0.125 tons to IND000646943
2003: 352 - Other organic solids, 0.04 tons to CAT080033681
2002: 352 - Other organic solids, 0.6 tons to CAT080033681
2002: 352 - Other organic solids, 0.355 tons to CAD980884183
2001: 134 - Aqueous solution with total organic residues less than 10 percent, 0.65 tons to CAT080013352
2001: 352 - Other organic solids, 0.15 tons to CAD980884183
2000: 352 - Other organic solids, 5.45 tons to CAT080033681
1999: 181 - Other inorganic solid waste, 7.8 tons to CAT080033681
1999: 133 - Aqueous solution with total organic residues 10 percent or more, 0.6255 tons to CAT080013352
1999: 352 - Other organic solids, 0.3 tons to CAT080033681
1998: 133 - Aqueous solution with total organic residues 10 percent or more, 0.417 tons to CAT080013352
1998: 352 - Other organic solids, 0.0275 tons to CAD028409019
1997: 223 - Unspecified oil-containing waste, 0.075 tons to CAD050806850
1997: 221 - Waste oil and mixed oil, 0.418 tons to CAT080025711
1997: 741 - Liquids with halogenated organic compounds >= 1,000 Mg. /L, 0.2 tons to CAD050806850
1997: 352 - Other organic solids, 0.1075 tons to CAD028409019
1997: 133 - Aqueous solution with total organic residues 10 percent or more, 0.0834 tons to CAT080013352
1996: 214 - Unspecified solvent mixture, 0.198 tons to AZD049318009
1995: 223 - Unspecified oil-containing waste, 0.075 tons to CAD050806850
1995: 741 - Liquids with halogenated organic compounds >= 1,000 Mg. /L, 0.2 tons to CAD050806850

Map Id: K90
Direction: SW
Distance: 0.224 mi., 1184 ft.
Elevation: 583 ft.
Relative: Lower

Site Name : SAN DIEGO CO DPW DIV II
1600 DESCANSO AVE
SAN MARCOS, CA 92078

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 302506
EPA ID: CAD981454465

HAZNET - CA ***(cont.)***

1995: 133 - Aqueous solution with total organic residues 10 percent or more, 0.0834 tons to CAT080013352
1995: 221 - Waste oil and mixed oil, 0.418 tons to CAT080025711

HWG - CA

Facility Name :	SAN DIEGO CO DPW DIV II
Facility Address :	1600 DESCANSO AVE, SAN MARCOS, CA 92078
County :	SAN DIEGO
EPA ID :	CAD981454465
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	5469 KEARNY VILLA RD STE 201, SAN DIEGO, CA 921231219
Owner Name :	COUNTY/SAN DIEGO/DEPT/PUBLIC W
Owner Address :	5469 KEARNY VILLA RD STE 201, SAN DIEGO, CA 921231219
Operator Name :	TOM HERZBERGER, DPW MANAGER
Operator Address :	5469 KEARNY VILLA RD STE 201, SAN DIEGO, CA 921231141
Latitude :	33.148669
Longitude :	-117.198031

Map Id: I91
Direction: SSE
Distance: 0.229 mi., 1207 ft.
Elevation: 564 ft.
Relative: Lower

Site Name : BARREL SERVICE CO | BARREL SERVICE COMPANY - 203419
105 S PACIFIC ST | 105 SOUTH PACIFIC ST
SAN MARCOS, CA 92069

Database(s) : [FRS, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_SQG]

Envirosite ID: 282717
EPA ID: CAD981453467

FRS

Facility Name :	BARREL SERVICE CO
Facility Address :	105 S PACIFIC ST, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Registry ID :	110055735824
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2014-03-25

Source Description

Map Id: I91
Direction: SSE
Distance: 0.229 mi., 1207 ft.
Elevation: 564 ft.
Relative: Lower

Site Name : BARREL SERVICE CO | BARREL SERVICE COMPANY - 203419
105 S PACIFIC ST | 105 SOUTH PACIFIC ST
SAN MARCOS, CA 92069

Database(s) : [FRS, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_SQG] ***(cont.)***

Envirosite ID: 282717
EPA ID: CAD981453467

FRS ***(cont.)***

Source Description :

The California Environmental Reporting System (CERS) is a statewide web-based user and information exchange system to support over 140,000 regulated businesses and over 130 local agencies in electronically collecting and reporting significant hazardous materials, hazardous waste and compliance and enforcement data as mandated by California law. Under oversight by Cal/EPA, certified local governing agencies (Unified Program Agencies - UPAs) consolidate, coordinate and provide consistent regulatory activities for six state and federal environmental programs.

FRS Environmental Interest

Source and System ID :	CA-CERS - 10375951

HAZNET - CA

Facility Name :	BARREL SERVICE CO.
Facility Address :	105 S PACIFIC ST., SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAX000061036
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	105 S. PACIFIC ST., SAN MARCOS, CA 920690000
Latitude :	33.14605500
Longitude :	-117.19460250
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HWG - CA

Facility Name :	BARREL SERVICE CO.
Facility Address :	105 S PACIFIC ST., SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAX000061036
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	105 S. PACIFIC ST., SAN MARCOS, CA 920690000
Owner Name :	N/R
Owner Address :	N/A
Operator Name :	INACTIVE PER SURVEY 1-25-95LH
Operator Address :	N/A
Latitude :	33.145455
Longitude :	-117.195496

Map Id: I91
Direction: SSE
Distance: 0.229 mi., 1207 ft.
Elevation: 564 ft.
Relative: Lower

Site Name : BARREL SERVICE CO | BARREL SERVICE COMPANY - 203419
105 S PACIFIC ST | 105 SOUTH PACIFIC ST
SAN MARCOS, CA 92069

Database(s) : [FRS, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_SQG] ***(cont.)***

Envirosite ID: 282717
EPA ID: CAD981453467

MANIFEST EPA

Manifest Details

Manifest Number :	020806985JJK
Shipped Date :	2020-05-28
Updated Date :	2020-06-23
Received Date :	2020-06-01
Status :	Signed
Generator ID :	CAD981453467
Generator Name :	BARREL SERVICE COMPANY - 203419
Generator Address :	105 SOUTH PACIFIC ST, SAN MARCOS, CA 92069
Generator Mailing :	105 SOUTH PACIFIC ST, SAN MARCOS, CA 92069
Generator Contact :	N/R
Destination ID :	CAT080013352
Destination Name :	WORLD OIL RECYCLING
Destination Mailing :	2000 N. ALAMEDA STREET CA90222 CA037US 2000, COMPTON, CA 90222
Destination Address :	2000 N. ALAMEDA STREET, COMPTON, CA 90222-0000
Destination Contact :	N/R
Submission Type :	DataImage5Copy
Origin Type :	Service
Manifest Residue :	N
Rejection :	N
Last Date in Agency List :	2022-01-14

Waste Details

Waste Line Number :	1
Is DOT Hazardous :	N
DOT ID Number :	N/R
DOT Information :	N/R
Non Waste Description :	NON RCRA HAZARDOUS WASTE, LIQUID (OILY WATER)
Quantity :	110 Gallons
Quantity Tons, Acute, Non-Acute :	0.4587156, 0, 0.4587156
Quantity Kg, Acute, Non-Acute :	0, 416.06882
Management Method :	H039 - OTHER RECOVERY OR RECLAMATION FOR REUSE
Is EPA Waste :	N
Federal Code :	N/R
State Code :	CA - 223

Manifest Details

Manifest Number :	020806484JJK
Shipped Date :	2020-04-29
Updated Date :	2020-05-26
Received Date :	2020-05-07
Status :	Signed
Generator ID :	CAD981453467
Generator Name :	BARREL SERVICE COMPANY
Generator Address :	105 SOUTH PACIFIC STREET, SAN MARCOS, CA 92069
Generator Mailing :	105 SOUTH PACIFIC ST, SAN MARCOS, CA 92069
Generator Contact :	N/R
Destination ID :	AZR000521146
Destination Name :	YUMA YES 2 WASTE TRANSFER STATION
Destination Mailing :	2621 GREEN RIVER RD STE 105, CORONA, CA 92882

Map Id: I91
Direction: SSE
Distance: 0.229 mi., 1207 ft.
Elevation: 564 ft.
Relative: Lower

Site Name : BARREL SERVICE CO | BARREL SERVICE COMPANY - 203419
105 S PACIFIC ST | 105 SOUTH PACIFIC ST
SAN MARCOS, CA 92069

Database(s) : [FRS, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_SQG] ***(cont.)***

Envirosite ID: 282717
EPA ID: CAD981453467

MANIFEST EPA ***(cont.)***

Destination Address :	6500 S US HIGHWAY 95, YUMA, AZ 85365
Destination Contact :	N/R
Submission Type :	DataImage5Copy
Origin Type :	Service
Manifest Residue :	N
Rejection :	N
Last Date in Agency List :	2022-01-14

Waste Details

Waste Line Number :	1
Is DOT Hazardous :	N
DOT ID Number :	N/R
DOT Information :	N/R
Non Waste Description :	Non-RCRA Hazardous Waste, solid (oily debris)
Quantity :	400 Pounds
Quantity Tons, Acute, Non-Acute :	0.2, 0, 0.2
Quantity Kg, Acute, Non-Acute :	0, 181.406
Management Method :	H141 - STORAGE, BULKING AND/OR TRANSFER OFF SITE
Is EPA Waste :	N
Federal Code :	N/R
State Code :	CA - 352

Manifest Details

Manifest Number :	018202461JJK
Shipped Date :	2018-12-20
Updated Date :	2019-01-11
Received Date :	2018-12-27
Status :	Signed
Generator ID :	CAD981453467
Generator Name :	BARREL SERVICE COMPANY
Generator Address :	105 SOUTH PACIFIC STREET, SAN MARCOS, CA 92069
Generator Mailing :	105 SOUTH PACIFIC ST, SAN MARCOS, CA 92069
Generator Contact :	N/R
Destination ID :	AZR000515924
Destination Name :	YUMA YES WASTE TRANSFER FACILITY
Destination Mailing :	2730 E 13TH ST, YUMA, AZ 85365-1901
Destination Address :	2730 E 13TH ST, YUMA, AZ 85365-1901
Destination Contact :	N/R
Submission Type :	DataImage5Copy
Origin Type :	Service
Manifest Residue :	N
Rejection :	N
Last Date in Agency List :	2022-01-14

Waste Details

Waste Line Number :	1
Is DOT Hazardous :	N
DOT ID Number :	N/R
DOT Information :	N/R

Map Id: I91
Direction: SSE
Distance: 0.229 mi., 1207 ft.
Elevation: 564 ft.
Relative: Lower

Site Name : BARREL SERVICE CO | BARREL SERVICE COMPANY - 203419
105 S PACIFIC ST | 105 SOUTH PACIFIC ST
SAN MARCOS, CA 92069

Database(s) : [FRS, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_SQG] ***(cont.)***

Envirosite ID: 282717
EPA ID: CAD981453467

MANIFEST EPA ***(cont.)***

Non Waste Description :	NON RCRA HAZARDOUS WASTE SOLID (OILY DEBRIS)
Quantity :	400 Pounds
Quantity Tons, Acute, Non-Acute :	0.2, 0, 0.2
Quantity Kg, Acute, Non-Acute :	0, 181.406
Management Method :	H141 - STORAGE, BULKING AND/OR TRANSFER OFF SITE
Is EPA Waste :	N
Federal Code :	N/R
State Code :	CA - 352

Manifest Details

Manifest Number :	018190510JJK
Shipped Date :	2018-12-19
Updated Date :	2019-01-14
Received Date :	2018-12-20
Status :	Signed
Generator ID :	CAD981453467
Generator Name :	BARREL SERVICE COMPANY
Generator Address :	105 SOUTH PACIFIC ST, SAN MARCOS, CA 92069
Generator Mailing :	105 SOUTH PACIFIC ST, SAN MARCOS, CA 92069
Generator Contact :	N/R
Destination ID :	CAT080013352
Destination Name :	DEMENNO/KERDOON
Destination Mailing :	2000 2000 N. ALAMEDA STREET CA90222 CA037US 2000, COMPTON, CA 90222
Destination Address :	2000 2000 N. ALAMEDA STREET, COMPTON, CA 90222-0000
Destination Contact :	N/R
Submission Type :	DataImage5Copy
Origin Type :	Service
Manifest Residue :	N
Rejection :	N
Last Date in Agency List :	2022-01-14

Waste Details

Waste Line Number :	1
Is DOT Hazardous :	N
DOT ID Number :	N/R
DOT Information :	N/R
Non Waste Description :	NON RCRA HAZARDOUS WASTE, LIQUID (OILY WATER)
Quantity :	240 Gallons
Quantity Tons, Acute, Non-Acute :	1.000834, 0, 1.000834
Quantity Kg, Acute, Non-Acute :	0, 907.7865
Management Method :	H039 - OTHER RECOVERY OR RECLAMATION FOR REUSE
Is EPA Waste :	N
Federal Code :	N/R
State Code :	CA - 223

Manifest Details

Manifest Number :	018190256JJK
Shipped Date :	2018-08-02

Map Id: I91
Direction: SSE
Distance: 0.229 mi., 1207 ft.
Elevation: 564 ft.
Relative: Lower

Site Name : BARREL SERVICE CO | BARREL SERVICE COMPANY - 203419
105 S PACIFIC ST | 105 SOUTH PACIFIC ST
SAN MARCOS, CA 92069

Database(s) : [FRS, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_SQG] ***(cont.)***

Envirosite ID: 282717
EPA ID: CAD981453467

MANIFEST EPA ***(cont.)***

Updated Date :	2019-06-26
Received Date :	2018-08-18
Status :	Signed
Generator ID :	CAD981453467
Generator Name :	BARREL SERVICE COMPANY
Generator Address :	105 SOUTH PACIFIC STREET, SAN MARCOS, CA 92069
Generator Mailing :	105 SOUTH PACIFIC ST, SAN MARCOS, CA 92069
Generator Contact :	N/R
Destination ID :	AZR000515924
Destination Name :	YUMA YES WASTE TRANSFER FACILITY
Destination Mailing :	2730 E 13TH ST, YUMA, AZ 85365-1901
Destination Address :	2730 E 13TH ST, YUMA, AZ 85365-1901
Destination Contact :	N/R
Submission Type :	DataImage5Copy
Origin Type :	Web
Manifest Residue :	N
Rejection :	N
Last Date in Agency List :	2022-01-14

Waste Details

Waste Line Number :	1
Is DOT Hazardous :	N
DOT ID Number :	N/R
DOT Information :	N/R
Non Waste Description :	NON-RCRA HAZARDOUS WASTE, SOLID (OILY DEBRIS)
Quantity :	350 Pounds
Quantity Tons, Acute, Non-Acute :	0.175, 0, 0.175
Quantity Kg, Acute, Non-Acute :	0, 158.73026
Management Method :	H141 - STORAGE, BULKING AND/OR TRANSFER OFF SITE
Is EPA Waste :	N
Federal Code :	N/R
State Code :	CA - 352

RCRA_SQG

Facility Name :	BARREL SERVICE COMPANY
Facility Address :	105 SOUTH PACIFIC STREET, SAN MARCOS, CA 92069
County :	SAN DIEGO
Date Form Received by Agency :	1986-03-18
EPA ID :	CAD981453467
Mailing Address :	105 SOUTH PACIFIC ST, SAN MARCOS, CA 92069
Contact :	ENVIRONMENTAL MANAGER
Contact Address :	105 SOUTH PACIFIC STREET, SAN MARCOS, CA 92069
Contact Country :	US
Contact Telephone :	619-744-2122
Contact Email :	N/R
EPA Region :	09
Land Type :	Other land type
Source Type :	Notification
Classification :	Small Quantity Generator

Map Id: I91
Direction: SSE
Distance: 0.229 mi., 1207 ft.
Elevation: 564 ft.
Relative: Lower

Site Name : BARREL SERVICE CO | BARREL SERVICE COMPANY - 203419
105 S PACIFIC ST | 105 SOUTH PACIFIC ST
SAN MARCOS, CA 92069

Database(s) : [FRS, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_SQG] ***(cont.)***

Envirosite ID: 282717
EPA ID: CAD981453467

RCRA_SQG ***(cont.)***

Description : Handlers that generate more than 100 and less than 1000 kilograms of hazardous waste during any calendar month and accumulate less than 6000 kg of hazardous waste at any time; or generate 100 kg or less of hazardous waste during any calendar month, and accumulate more than 1000 kg of hazardous waste at any time.

Last Date in Agency List : 2022-01-25

Owner/Operator Summary

Owner/Operator Name :	NOT REQUIRED
Owner/Operator Address :	NOT REQUIRED, NOT REQUIRED, ME 99999
Owner/Operator Country :	N/R
Owner/Operator Telephone :	415-555-1212
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Private
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Owner/Operator Name :	R A BRAMBLE
Owner/Operator Address :	NOT REQUIRED, NOT REQUIRED, ME 99999
Owner/Operator Country :	N/R
Owner/Operator Telephone :	415-555-1212
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Private
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Map Id: I91
Direction: SSE
Distance: 0.229 mi., 1207 ft.
Elevation: 564 ft.
Relative: Lower

Site Name : BARREL SERVICE CO | BARREL SERVICE COMPANY - 203419
105 S PACIFIC ST | 105 SOUTH PACIFIC ST
SAN MARCOS, CA 92069

Database(s) : [FRS, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_SQG] ***(cont.)***

Envirosite ID: 282717
EPA ID: CAD981453467

RCRA_SQG ***(cont.)***

Notices of Violations Summary
Regulation Violated : N

Map Id: J92
Direction: E
Distance: 0.229 mi., 1210 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : JOHN PERRY
412 PALMAC ST
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 41079308
EPA ID: CAC002762108

HAZNET - CA

Facility Name : JOHN PERRY
Facility Address : 412 PALMAC ST, SAN MARCOS, CA 92069
County : SAN DIEGO

Site Details
Generator EPA ID : CAC002762108
Active : Inactive
Category : STATE
Facility Types : N/R
Type : TEMPORARY
Contact Name : N/R
Contact Phone : N/R
Facility Mailing Address : 412 PALMAC ST, SAN MARCOS, CA 920691315
Latitude : 33.15122780
Longitude : -117.19064489
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2021-07-08

HWG - CA

Facility Name : JOHN PERRY
Facility Address : 412 PALMAC ST, SAN MARCOS, CA 92069
County : SAN DIEGO

EPA ID : CAC002762108
Status : Inactive
Category : STATE
Type : TEMPORARY
Facility Type : N/R
Mailing Address : 412 PALMAC ST, SAN MARCOS, CA 920691315
Owner Name : JOHN PERRY
Owner Address : 412 PALMAC ST, SAN MARCOS, CA 920691315
Operator Name : JOHN PERRY
Operator Address : 412 PALMAC ST, SAN MARCOS, CA 920691315
Latitude : 33.151228

Map Id: J92
Direction: E
Distance: 0.229 mi., 1210 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : JOHN PERRY
412 PALMAC ST
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 41079308
EPA ID: CAC002762108

HWG - CA ***(cont.)***

Longitude :	-117.190645

Map Id: K93
Direction: WSW
Distance: 0.230 mi., 1215 ft.
Elevation: 586 ft.
Relative: Lower

Site Name : GSE SAN MARCOS 851632 | EXXON #1041
112 S RANCHO SANTA FE | 112 RANCHO SANTA FE RD | 112 South Rancho Santa Fe
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, ECHO, FRS, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN]

Envirosite ID: 231148
EPA ID: N/R

CALEPA SITES - CA

Facility Name :	EXXON #1041
Facility Address :	112 RANCHO SANTA FE RD, SAN MARCOS, 92078-2502
Site ID :	467157
EI ID :	110013853516
EI Description :	US EPA Air Emission Inventory System (EIS)
Latitude :	33.149420
Longitude :	-117.198730
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07

ECHO

Facility Name :	GSE SAN MARCOS 851632
Facility Address :	112 S RANCHO SANTA FE, SAN MARCOS, CA 92078
County :	SAN DIEGO
Last Inspection Date :	N/R
Registry ID :	110070422138
FIPS Code :	N/R
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0

Map Id: K93
Direction: WSW
Distance: 0.230 mi., 1215 ft.
Elevation: 586 ft.
Relative: Lower

Site Name : GSE SAN MARCOS 851632 | EXXON #1041
112 S RANCHO SANTA FE | 112 RANCHO SANTA FE RD | 112 South Rancho Santa Fe
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, ECHO, FRS, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 231148
EPA ID: N/R

ECHO ***(cont.)***

Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	_____
Collection Method :	Zip Code Centroid
Reference Point :	N/R
Accuracy Meters :	10000
Derived Tribes :	N/R
Derived HUC :	N/R
Derived WBD :	N/R
Derived STCTY FIPS :	N/R
Derived Zip :	N/R
Derived CD113 :	N/R
Derived CB2010 :	N/R
MYRTK Universe :	NNN
NPDES IDs :	N/R
CWA Permit Types :	N/R
CWA Compliance Tracking :	N/R
CWA NAICS :	N/R
CWA SICS :	N/R
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	N/R
CWA Current Compliance Status :	N/R
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	N/R
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	N/R
Facility NAICS :	44719 - Other Gasoline Stations
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	N/R
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	N
SDWIS Flag :	N

Map Id: K93
Direction: WSW
Distance: 0.230 mi., 1215 ft.
Elevation: 586 ft.
Relative: Lower

Site Name : GSE SAN MARCOS 851632 | EXXON #1041
112 S RANCHO SANTA FE | 112 RANCHO SANTA FE RD | 112 South Rancho Santa Fe
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, ECHO, FRS, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 231148
EPA ID: N/R

ECHO ***(cont.)***

RCRA Flag :	Y
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	Y
NAA Flag :	N
Latitude :	33.125563
Longitude :	-117.183287
Last Date in Agency List :	2022-01-17

FRS

Facility Name :	EXXON #1041
Facility Address :	112 RANCHO SANTA FE RD, SAN MARCOS, CA 92078-2502
County :	SAN DIEGO

Site Details

Registry ID :	110013853516
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Source Description

Source Description :

The Emission Inventory System (EIS) maintains an inventory of large stationary sources and voluntarily-reported smaller sources of air point pollution emitters. It contains information about facility sites and their physical location, emission units, emission processes, release points, control approaches, and regulations. Facility inventory data are kept separate from the emissions data and have stable identifiers to improve continuity from year to year and to help identify duplicate or missing facilities.

FRS Environmental Interest

Source and System ID :	EIS - 2282011

Facility Name :	GSE SAN MARCOS 851632
Facility Address :	112 S RANCHO SANTA FE, SAN MARCOS, CA 92078
County :	SAN DIEGO

Site Details

Registry ID :	110070422138
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Map Id: K93
Direction: WSW
Distance: 0.230 mi., 1215 ft.
Elevation: 586 ft.
Relative: Lower

Site Name : GSE SAN MARCOS 851632 | EXXON #1041
112 S RANCHO SANTA FE | 112 RANCHO SANTA FE RD | 112 South Rancho Santa Fe
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, ECHO, FRS, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 231148
EPA ID: N/R

FRS ***(cont.)***

Source Description

Source Description :

RCRAInfo is EPA's comprehensive information system that supports the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984 through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA. RCRAInfo also supports generation of the National Hazardous Waste Biennial Report. All generators and treatment, storage, and disposal facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years to support creation of the Biennial Report.

FRS Environmental Interest

Source and System ID :	RCRAINFO - CAL000422807

HAZNET - CA

Facility Name :	GSE SAN MARCOS 851632
Facility Address :	112 S RANCHO SANTA FE, SAN MARCOS, CA 92078
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000422807
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	29501 CANWOOD ST STE 200, AGOURA HILLS, CA 91301
Latitude :	33.14944800
Longitude :	-117.19907100
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	2018: 352 - Other organic solids, 0.06250 tons to CAD044429835 2018: 134 - Aqueous solution with total organic residues less than 10 percent, 0.21250 tons to CAD044429835 2017: 352 - Other organic solids, 0.09 tons to CAD044429835 2017: 134 - Aqueous solution with total organic residues less than 10 percent, 0.1 tons to CAD044429835

Map Id: K93
Direction: WSW
Distance: 0.230 mi., 1215 ft.
Elevation: 586 ft.
Relative: Lower

Site Name : GSE SAN MARCOS 851632 | EXXON #1041
112 S RANCHO SANTA FE | 112 RANCHO SANTA FE RD | 112 South Rancho Santa Fe
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, ECHO, FRS, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 231148
EPA ID: N/R

HWG - CA

Facility Name :	GSE SAN MARCOS 851632
Facility Address :	112 S RANCHO SANTA FE, SAN MARCOS, CA 92078
County :	SAN DIEGO
EPA ID :	CAL000422807
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	29501 CANWOOD ST STE 200, AGOURA HILLS, CA 91301
Owner Name :	GOLDEN STATE ENTERPRISES
Owner Address :	29501 CANWOOD ST STE 200, AGOURA HILLS, CA 91301
Operator Name :	LISA THOMPSON
Operator Address :	29501 CANWOOD ST STE 200, AGOURA HILLS, CA 91301
Latitude :	33.149448
Longitude :	-117.199071

MANIFEST EPA

Manifest Details

Manifest Number :	021591908JJK
Shipped Date :	2020-06-23
Updated Date :	2020-07-21
Received Date :	2020-06-24
Status :	Signed
Generator ID :	CAL000422807
Generator Name :	GSE SAN MARCOS 851632
Generator Address :	112 S RANCHO SANTA FE, SAN MARCOS, CA 92078
Generator Mailing :	29501 CANWOOD ST STE 200, AGOURA HILLS, CA 91301
Generator Contact :	N/R
Destination ID :	CAD028409019
Destination Name :	CROSBY & OVERTON
Destination Mailing :	1630 W. 17TH STREET CA90813 CA037US 1630, LONG BEACH, CA 90813
Destination Address :	1630 W. 17TH STREET, LONG BEACH, CA 90813-0000
Destination Contact :	N/R
Submission Type :	DataImage5Copy
Origin Type :	Web
Manifest Residue :	N
Rejection :	N
Last Date in Agency List :	2022-01-14

Waste Details

Waste Line Number :	1
Is DOT Hazardous :	N
DOT ID Number :	N/R
DOT Information :	N/R
Non Waste Description :	NON RCRA HAZARDOUS WASTE SOLID
Quantity :	350 Pounds

Map Id: K93
Direction: WSW
Distance: 0.230 mi., 1215 ft.
Elevation: 586 ft.
Relative: Lower

Site Name : GSE SAN MARCOS 851632 | EXXON #1041
112 S RANCHO SANTA FE | 112 RANCHO SANTA FE RD | 112 South Rancho Santa Fe
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, ECHO, FRS, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 231148
EPA ID: N/R

MANIFEST EPA ***(cont.)***

Quantity Tons, Acute, Non-Acute :	0.175, 0, 0.175
Quantity Kg, Acute, Non-Acute :	0, 158.73026
Management Method :	H141 - STORAGE, BULKING AND/OR TRANSFER OFF SITE
Is EPA Waste :	N
Federal Code :	N/R
State Code :	CA - 352

Waste Line Number :	2
Is DOT Hazardous :	N
DOT ID Number :	N/R
DOT Information :	N/R
Non Waste Description :	NON RCRA HAZARDOUS WASTE SOLID
Quantity :	55 Pounds
Quantity Tons, Acute, Non-Acute :	0.0275, 0, 0.0275
Quantity Kg, Acute, Non-Acute :	0, 24.943325
Management Method :	H141 - STORAGE, BULKING AND/OR TRANSFER OFF SITE
Is EPA Waste :	N
Federal Code :	N/R
State Code :	CA - 512

Manifest Details

Manifest Number :	021591606JJK
Shipped Date :	2020-03-24
Updated Date :	2020-04-17
Received Date :	2020-03-27
Status :	Signed
Generator ID :	CAL000422807
Generator Name :	GSE SAN MARCOS 851632
Generator Address :	112 S RANCHO SANTA FE, SAN MARCOS, CA 92078
Generator Mailing :	29501 CANWOOD ST STE 200, AGOURA HILLS, CA 91301
Generator Contact :	N/R
Destination ID :	CAT080013352
Destination Name :	WORLD OIL RECYCLING
Destination Mailing :	2000 N. ALAMEDA STREET CA90222 CA037US 2000, COMPTON, CA 90222
Destination Address :	2000 N. ALAMEDA STREET, COMPTON, CA 90222-0000
Destination Contact :	N/R
Submission Type :	DataImage5Copy
Origin Type :	Service
Manifest Residue :	N
Rejection :	N
Last Date in Agency List :	2022-01-14

Waste Details

Waste Line Number :	1
Is DOT Hazardous :	Y

Map Id: K93
Direction: WSW
Distance: 0.230 mi., 1215 ft.
Elevation: 586 ft.
Relative: Lower

Site Name : GSE SAN MARCOS 851632 | EXXON #1041
112 S RANCHO SANTA FE | 112 RANCHO SANTA FE RD | 112 South Rancho Santa Fe
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, ECHO, FRS, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 231148
EPA ID: N/R

MANIFEST EPA ***(cont.)***

DOT ID Number :	UN1993
DOT Information :	UN1993, Waste Flammable liquids n.o.s.,(GASOLINE/DIESEL) 3, PG II ERG# 128
Non Waste Description :	N/R
Quantity :	35 Gallons
Quantity Tons, Acute, Non-Acute :	0.14595497, 0, 0.14595497
Quantity Kg, Acute, Non-Acute :	0, 132.38554
Management Method :	H039 - OTHER RECOVERY OR RECLAMATION FOR REUSE
Is EPA Waste :	Y
Federal Code :	D001
State Code :	CA - 134

Manifest Details

Manifest Number :	012670083FLE
Shipped Date :	2019-06-05
Updated Date :	2019-08-27
Received Date :	2019-06-17
Status :	Corrected
Generator ID :	CAL000422807
Generator Name :	GSE San Marcos 851632
Generator Address :	112 South Rancho Santa Fe, San Marcos, CA 92078
Generator Mailing :	29501 Canwood Street Suite 200, Agoura Hills, CA 91301
Generator Contact :	N/R
Destination ID :	CAD044429835
Destination Name :	Clean Harbors Wilmington LLC
Destination Mailing :	1737 East Denni Street, Wilmington, CA 90744
Destination Address :	1737 East Denni Street, Wilmington, CA 90744
Destination Contact :	N/R
Submission Type :	DataImage5Copy
Origin Type :	Service
Manifest Residue :	N
Rejection :	N
Last Date in Agency List :	2022-01-14

Waste Details

Waste Line Number :	1
Is DOT Hazardous :	N
DOT ID Number :	N/R
DOT Information :	N/R
Non Waste Description :	NONE, NON-RCRA HAZARDOUS WASTE, SOLID (FILTERS, ABSORBENT), N/A, NONE
Quantity :	150 Pounds
Quantity Tons, Acute, Non-Acute :	0.075, 0, 0.075
Quantity Kg, Acute, Non-Acute :	0, 68.02725
Management Method :	H141 - STORAGE, BULKING AND/OR TRANSFER OFF SITE
Is EPA Waste :	N
Federal Code :	N/R

Map Id: K93
Direction: WSW
Distance: 0.230 mi., 1215 ft.
Elevation: 586 ft.
Relative: Lower

Site Name : GSE SAN MARCOS 851632 | EXXON #1041
112 S RANCHO SANTA FE | 112 RANCHO SANTA FE RD | 112 South Rancho Santa Fe
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, ECHO, FRS, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 231148
EPA ID: N/R

MANIFEST EPA ***(cont.)***

State Code :	CA - 352

RCRA_NONGEN

Facility Name :	GSE SAN MARCOS 851632
Facility Address :	112 S RANCHO SANTA FE, SAN MARCOS, CA 92078
County :	SAN DIEGO
Date Form Received by Agency :	2016-12-06
EPA ID :	CAL000422807
Mailing Address :	29501 CANWOOD ST STE 200, AGOURA HILLS, CA 91301
Contact :	LISA THOMPSON
Contact Address :	29501 CANWOOD ST STE 200, AGOURA HILLS, CA 91301
Contact Country :	N/R
Contact Telephone :	818-206-5700
Contact Email :	LTHOMPSON@GSG.EMAIL
EPA Region :	09
Land Type :	Not Reported
Source Type :	Implementer
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2022-01-26

Owner/Operator Summary

Owner/Operator Name :	GOLDEN STATE ENTERPRISES
Owner/Operator Address :	29501 CANWOOD ST STE 200, AGOURA HILLS, CA 91301
Owner/Operator Country :	N/R
Owner/Operator Telephone :	818-206-5700
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Owner/Operator Name :	LISA THOMPSON
Owner/Operator Address :	29501 CANWOOD ST STE 200, AGOURA HILLS, CA 91301
Owner/Operator Country :	N/R
Owner/Operator Telephone :	818-206-5700
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Map Id: K93
Direction: WSW
Distance: 0.230 mi., 1215 ft.
Elevation: 586 ft.
Relative: Lower

Site Name : GSE SAN MARCOS 851632 | EXXON #1041
112 S RANCHO SANTA FE | 112 RANCHO SANTA FE RD | 112 South Rancho Santa Fe
SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, ECHO, FRS, HAZNET - CA, HWG - CA, MANIFEST EPA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 231148
EPA ID: N/R

RCRA_NONGEN ***(cont.)***

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Notices of Violations Summary

Regulation Violated :	N

Map Id: M94
Direction: SE
Distance: 0.231 mi., 1220 ft.
Elevation: 560 ft.
Relative: Lower

Site Name : HIGH TECH EDM | 1X MISSION INDUSTRIAL SQUARE
175 BALBOA ST STE A4 | 175 N BALBOA ST
SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, HAZNET - CA, HWG - CA, RFR - CA]

Envirosite ID: 41021348
EPA ID: N/R

CALEPA SITES - CA

Facility Name :	HIGH TECH EDM
Facility Address :	175 BALBOA ST STE A4, SAN MARCOS, 92069
Site ID :	583305
EI ID :	883379
EI Description :	Industrial Facility Storm Water
Latitude :	33.149030
Longitude :	-117.191730
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07

Map Id: M94
Direction: SE
Distance: 0.231 mi., 1220 ft.
Elevation: 560 ft.
Relative: Lower

Site Name : HIGH TECH EDM | 1X MISSION INDUSTRIAL SQUARE
175 BALBOA ST STE A4 | 175 N BALBOA ST
SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, HAZNET - CA, HWG - CA, RFR - CA] ***(cont.)***

Envirosite ID: 41021348
EPA ID: N/R

CIWQS - CA

Facility Name :	HIGH TECH EDM
Facility Address :	175 BALBOA ST STE A4, SAN MARCOS, CA 92069
County :	SAN DIEGO
Place ID :	S883379
Agency Name :	HIGH TECH EDM
Last Date in Agency List :	2021-12-30

HAZNET - CA

Facility Name :	1X MISSION INDUSTRIAL SQUARE
Facility Address :	175 N BALBOA ST, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAX000245258
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	LOLA HAYS, SAN MARCOS, CA 920690000
Latitude :	33.14898779
Longitude :	-117.19216250
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HWG - CA

Facility Name :	1X MISSION INDUSTRIAL SQUARE
Facility Address :	175 N BALBOA ST, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAX000245258
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	LOLA HAYS, SAN MARCOS, CA 920690000
Owner Name :	N/R
Owner Address :	N/A
Operator Name :	LOLA HAYS
Operator Address :	N/A
Latitude :	33.149064
Longitude :	-117.192203

Map Id: M94
Direction: SE
Distance: 0.231 mi., 1220 ft.
Elevation: 560 ft.
Relative: Lower

Site Name : HIGH TECH EDM | 1X MISSION INDUSTRIAL SQUARE
175 BALBOA ST STE A4 | 175 N BALBOA ST
SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, CIWQS - CA, HAZNET - CA, HWG - CA, RFR - CA] ***(cont.)***

Envirosite ID: 41021348
EPA ID: N/R

RFR - CA

Facility Name :	High Tech EDM
Facility Address :	175 Balboa St Ste A4, San Marcos, CA 92069
County :	San Diego
Effective Date :	2020-07-02
Adoption Date :	N/R
Termination Date :	N/R
Expiration/Review Date :	N/R
NPDES Number :	CAS000001
Order Number :	2014-0057-DWQ
WDID :	9 37NEC006957
SIC/NAICS :	3541
Program :	INDSTW
Regulatory Measure Status :	Active
Regulatory Measure Type :	Storm water industrial
Place/Project Type :	Industrial - Machine Tools, Metal Cutting Type
Region :	9
Design Flow :	N/R
Major/Minor :	N/R
Complexity :	N/R
TTWQ :	N/R
Number of Enforcement Actions within Five Years:	2
Number of Violations within Five Years:	1
Agency :	High Tech EDM
Agency Address :	175 Balboa St Ste A4, San Marcos, CA 92069
Latitude :	33.14903
Longitude :	-117.19173
Last Date in Agency List :	2022-03-07

Map Id: M95
Direction: SE
Distance: 0.234 mi., 1238 ft.
Elevation: 560 ft.
Relative: Lower

Site Name : ALLSTAR GRAPHICS & SCREEN PRINTING | JRL STREET ROD | C & G EARLY FORD PARTS
165 BALBOA ST C-13 | 165 BALBOA ST C-5 | 165 BALBOA ST C11
SAN MARCOS | San Marcos, CA 92069

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 41009949
EPA ID: CAL000122848

HAZNET - CA

Facility Name :	ALLSTAR GRAPHICS & SCREEN PRINTING
Facility Address :	165 BALBOA ST C-13, SAN MARCOS, CA 92069
County :	SAN DIEGO

Map Id: M95
Direction: SE
Distance: 0.234 mi., 1238 ft.
Elevation: 560 ft.
Relative: Lower

Site Name : ALLSTAR GRAPHICS & SCREEN PRINTING | JRL STREET ROD | C & G EARLY FORD PARTS
165 BALBOA ST C-13 | 165 BALBOA ST C-5 | 165 BALBOA ST C11
SAN MARCOS | San Marcos, CA 92069
Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 41009949
EPA ID: CAL000122848

HAZNET - CA ***(cont.)***

Site Details

Generator EPA ID :	CAL000122848
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	165 BALBOA ST C-13, SAN MARCOS, CA 920690000
Latitude :	33.14892852
Longitude :	-117.19220389
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08
Facility Name :	C & G EARLY FORD PARTS
Facility Address :	165 BALBOA ST C11, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAD981172406
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	165 BALBOA ST, STE C11, SAN MARCOS, CA 920690000
Latitude :	33.14892852
Longitude :	-117.19220389
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08
Facility Name :	COUNTY CHEMICALS
Facility Address :	165 N BALBOA C13, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000045642
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	PO BOX 670, CARLSBAD, CA 920180000
Latitude :	33.14892852
Longitude :	-117.19220389
Agency Hyperlink :	Click here for hyperlink provided by the agency.

Map Id: M95
Direction: SE
Distance: 0.234 mi., 1238 ft.
Elevation: 560 ft.
Relative: Lower

Site Name : ALLSTAR GRAPHICS & SCREEN PRINTING | JRL STREET ROD | C & G EARLY FORD PARTS
165 BALBOA ST C-13 | 165 BALBOA ST C-5 | 165 BALBOA ST C11
SAN MARCOS | San Marcos, CA 92069
Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 41009949
EPA ID: CAL000122848

HAZNET - CA ***(cont.)***

Last Date in Agency List : 2021-07-08

Facility Name : JRL FABRICATION
Facility Address : 165 Balboa St, San Marcos, CA 92069
County : SAN DIEGO

Site Details
Generator EPA ID : CAL000050668
Active : Inactive
Category : STATE
Facility Types : N/R
Type : PERMANENT
Contact Name : N/R
Contact Phone : N/R
Facility Mailing Address : 165 BALBOA STREET, SAN MARCOS, CA
Latitude : 33.14892852
Longitude : -117.19220389
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2021-07-08

Facility Name : JRL STREET ROD
Facility Address : 165 BALBOA ST C-5, SAN MARCOS, CA 92069
County : SAN DIEGO

Site Details
Generator EPA ID : CAL000073735
Active : Inactive
Category : STATE
Facility Types : N/R
Type : PERMANENT
Contact Name : N/R
Contact Phone : N/R
Facility Mailing Address : 165 BALBOA ST C-5, SAN MARCOS, CA 920690000
Latitude : 33.14892852
Longitude : -117.19220389
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2021-07-08

HWG - CA

Facility Name : ALLSTAR GRAPHICS & SCREEN PRINTING
Facility Address : 165 BALBOA ST C-13, SAN MARCOS, CA 92069
County : SAN DIEGO

EPA ID : CAL000122848
Status : Inactive

Map Id: M95
Direction: SE
Distance: 0.234 mi., 1238 ft.
Elevation: 560 ft.
Relative: Lower

Site Name : ALLSTAR GRAPHICS & SCREEN PRINTING | JRL STREET ROD | C & G EARLY FORD PARTS
165 BALBOA ST C-13 | 165 BALBOA ST C-5 | 165 BALBOA ST C11
SAN MARCOS | San Marcos, CA 92069

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 41009949
EPA ID: CAL000122848

HWG - CA ***(cont.)***

Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	165 BALBOA ST C-13, SAN MARCOS, CA 920690000
Owner Name :	MATTHEW D. NERBONNE
Owner Address :	165 BALBOA ST C-13, SAN MARCOS, CA 920690000
Operator Name :	INACT PER VQ 95 AD
Operator Address :	MATTHEW D NERBONNE, SAN MARCOS, CA 920690000
Latitude :	33.148996
Longitude :	-117.192238

Facility Name :	C & G EARLY FORD PARTS
Facility Address :	165 BALBOA ST C11, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAD981172406
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	165 BALBOA ST, STE C11, SAN MARCOS, CA 920690000
Owner Name :	N/R
Owner Address :	N/A
Operator Name :	UNDELIVERABLE SURVEY 1-14-95LC
Operator Address :	LC, N/A
Latitude :	33.148929
Longitude :	-117.192204

Facility Name :	COUNTY CHEMICALS
Facility Address :	165 N BALBOA C13, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAL000045642
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	PO BOX 670, CARLSBAD, CA 920180000
Owner Name :	BELASCO JOHN
Owner Address :	N/A
Operator Name :	INACT PER SURVEY 1-12-95 MB
Operator Address :	N/A
Latitude :	33.148929
Longitude :	-117.192204

Facility Name :	JRL FABRICATION
Facility Address :	165 Balboa St, San Marcos, CA 92069
County :	SAN DIEGO

Map Id: M95
Direction: SE
Distance: 0.234 mi., 1238 ft.
Elevation: 560 ft.
Relative: Lower

Site Name : ALLSTAR GRAPHICS & SCREEN PRINTING | JRL STREET ROD | C & G EARLY FORD PARTS
165 BALBOA ST C-13 | 165 BALBOA ST C-5 | 165 BALBOA ST C11
SAN MARCOS | San Marcos, CA 92069
Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 41009949
EPA ID: CAL000122848

HWG - CA ***(cont.)***

EPA ID :	CAL000050668
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	165 BALBOA STREET, SAN MARCOS, CA 000000000
Owner Name :	N/R
Owner Address :	N/A
Operator Name :	DEACT PER VQ96
Operator Address :	N/A
Latitude :	33.148996
Longitude :	-117.192238

Facility Name :	JRL STREET ROD
Facility Address :	165 BALBOA ST C-5, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAL000073735
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	165 BALBOA ST C-5, SAN MARCOS, CA 920690000
Owner Name :	JOSEPH LAPORTE
Owner Address :	N/A
Operator Name :	DEACT NON-DELIV. PER 95 FEES -
Operator Address :	P.H., N/A
Latitude :	33.148996
Longitude :	-117.192238

Map Id: J96
Direction: E
Distance: 0.235 mi., 1244 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : MR. GEISER
441 PALMAC
SAN MARCOS, CA 92069
Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 509807
EPA ID: CAC000981392

HAZNET - CA

Facility Name :	MR. GEISER
Facility Address :	441 PALMAC, SAN MARCOS, CA 92069
County :	SAN DIEGO

Map Id: J96
Direction: E
Distance: 0.235 mi., 1244 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : MR. GEISER
441 PALMAC
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 509807
EPA ID: CAC000981392

HAZNET - CA ***(cont.)***

Site Details

Generator EPA ID :	CAC000981392
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	441 PALMAC, SAN MARCOS, CA 920690000
Latitude :	33.15140234
Longitude :	-117.19042206
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HWG - CA

Facility Name :	MR. GEISER
Facility Address :	441 PALMAC, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAC000981392
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	441 PALMAC, SAN MARCOS, CA 920690000
Owner Name :	MR. GEISER
Owner Address :	441 PALMAC, SAN MARCOS, CA 920690000
Operator Name :	MR. GEISER
Operator Address :	441 PALMAC, SAN MARCOS, CA 920690000
Latitude :	33.151523
Longitude :	-117.1904

Map Id: L97
Direction: WNW
Distance: 0.239 mi., 1264 ft.
Elevation: 588 ft.
Relative: Higher

Site Name : SCHIEBERT, JENNIFER | JENNIFER SCHIEBERT
3502 CAPALINA ROAD
SAN MARCOS, CA

Database(s) : [ECHO, FRS, HWG - CA, RCRA_NONGEN]

Envirosite ID: 44218573
EPA ID: N/R

ECHO

Facility Name :	JENNIFER SCHIEBERT
Facility Address :	3502 CAPALINA ROAD, SAN MARCOS, CA 92069
County :	SAN DIEGO
Last Inspection Date :	N/R
Registry ID :	110071126246

Map Id: L97
Direction: WNW
Distance: 0.239 mi., 1264 ft.
Elevation: 588 ft.
Relative: Higher

Site Name : SCHIEBERT, JENNIFER | JENNIFER SCHIEBERT
3502 CAPALINA ROAD
SAN MARCOS, CA

Database(s) : [ECHO, FRS, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 44218573
EPA ID: N/R

ECHO ***(cont.)***

FIPS Code :	N/R
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	_____
Collection Method :	Zip Code Centroid
Reference Point :	N/R
Accuracy Meters :	10000
Derived Tribes :	N/R
Derived HUC :	N/R
Derived WBD :	N/R
Derived STCTY FIPS :	N/R
Derived Zip :	N/R
Derived CD113 :	N/R
Derived CB2010 :	N/R
MYRTK Universe :	NNN
NPDES IDs :	N/R
CWA Permit Types :	N/R
CWA Compliance Tracking :	N/R
CWA NAICS :	N/R
CWA SICS :	N/R
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	N/R
CWA Current Compliance Status :	N/R
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	N/R
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	N/R
Facility NAICS :	56299 - All Other Waste Management Services
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R

Map Id: L97
Direction: WNW
Distance: 0.239 mi., 1264 ft.
Elevation: 588 ft.
Relative: Higher

Site Name : SCHIEBERT, JENNIFER | JENNIFER SCHIEBERT
3502 CAPALINA ROAD
SAN MARCOS, CA

Database(s) : [ECHO, FRS, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 44218573
EPA ID: N/R

ECHO ***(cont.)***

Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	N/R
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	N
SDWIS Flag :	N
RCRA Flag :	Y
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	N/R
NAA Flag :	N
Latitude :	33.194075
Longitude :	-117.16177
Last Date in Agency List :	2022-01-17

Facility Name :	SCHIEBERT, JENNIFER
Facility Address :	3502 CAPALINA ROAD, SAN MARCOS, CA 92069
County :	SAN DIEGO

Last Inspection Date :	N/R
Registry ID :	110071123749
FIPS Code :	N/R
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	_____
Collection Method :	Zip Code Centroid
Reference Point :	N/R
Accuracy Meters :	10000
Derived Tribes :	N/R
Derived HUC :	N/R
Derived WBD :	N/R
Derived STCTY FIPS :	N/R
Derived Zip :	N/R
Derived CD113 :	N/R
Derived CB2010 :	N/R

Map Id: L97
Direction: WNW
Distance: 0.239 mi., 1264 ft.
Elevation: 588 ft.
Relative: Higher

Site Name : SCHIEBERT, JENNIFER | JENNIFER SCHIEBERT
3502 CAPALINA ROAD
SAN MARCOS, CA

Database(s) : [ECHO, FRS, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 44218573
EPA ID: N/R

ECHO ***(cont.)***

MYRTK Universe :	NNN
NPDES IDs :	N/R
CWA Permit Types :	N/R
CWA Compliance Tracking :	N/R
CWA NAICS :	N/R
CWA SICS :	N/R
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	N/R
CWA Current Compliance Status :	N/R
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	N/R
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	N/R
Facility NAICS :	56299 - All Other Waste Management Services
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	N/R
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	N
SDWIS Flag :	N
RCRA Flag :	Y
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	N/R
NAA Flag :	N
Latitude :	33.194075
Longitude :	-117.16177
Last Date in Agency List :	2022-01-17

FRS

Facility Name :	JENNIFER SCHIEBERT
Facility Address :	3502 CAPALINA ROAD, SAN MARCOS, CA 92069-1235
County :	SAN DIEGO

Map Id: L97
Direction: WNW
Distance: 0.239 mi., 1264 ft.
Elevation: 588 ft.
Relative: Higher

Site Name : SCHIEBERT, JENNIFER | JENNIFER SCHIEBERT
3502 CAPALINA ROAD
SAN MARCOS, CA

Database(s) : [ECHO, FRS, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 44218573
EPA ID: N/R

FRS ***(cont.)***

Site Details
Registry ID : 110071126246
FRS Facility URL : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-02-17

Source Description

Source Description :

RCRAInfo is EPA's comprehensive information system that supports the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984 through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA. RCRAInfo also supports generation of the National Hazardous Waste Biennial Report. All generators and treatment, storage, and disposal facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years to support creation of the Biennial Report.

FRS Environmental Interest
Source and System ID : RCRAINFO - CAC003141889

Facility Name : SCHIEBERT, JENNIFER
Facility Address : 3502 CAPALINA ROAD, SAN MARCOS, CA 92069
County : SAN DIEGO

Site Details
Registry ID : 110071123749
FRS Facility URL : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-02-17

Source Description

Source Description :

RCRAInfo is EPA's comprehensive information system that supports the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984 through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA. RCRAInfo also supports generation of the National Hazardous Waste Biennial Report. All generators and treatment, storage, and disposal facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years to support creation of the Biennial Report.

Map Id: L97
Direction: WNW
Distance: 0.239 mi., 1264 ft.
Elevation: 588 ft.
Relative: Higher

Site Name : SCHIEBERT, JENNIFER | JENNIFER SCHIEBERT
3502 CAPALINA ROAD
SAN MARCOS, CA

Database(s) : [ECHO, FRS, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 44218573
EPA ID: N/R

FRS ***(cont.)***

FRS Environmental Interest
Source and System ID : RCRAINFO - CAC003143545

HWG - CA

Facility Name : JENNIFER SCHIEBERT
Facility Address : 3502 CAPALINA ROAD, SAN MARCOS, CA 92069
County : SAN DIEGO

EPA ID : CAC003141889
Status : Active
Category : STATE
Type : TEMPORARY
Facility Type : N/R
Mailing Address : 3502 CAPALINA ROAD, SAN MARCOS, CA 920691235
Owner Name : JENNIFER SCHIEBERT
Owner Address : 3502 CAPALINA ROAD, SAN MARCOS, CA 920691235
Operator Name : JENNIFER SCHIEBERT
Operator Address : 3502 CAPALINA ROAD, SAN MARCOS, CA 920691235
Latitude : 33.152849
Longitude : -117.199601

Facility Name : SCHIEBERT, JENNIFER
Facility Address : 3502 CAPALINA ROAD, SAN MARCOS, CA 92069
County : SAN DIEGO

EPA ID : CAC003143545
Status : Active
Category : STATE
Type : TEMPORARY
Facility Type : N/R
Mailing Address : 3502 CAPALINA ROAD, SAN MARCOS, CA 92069
Owner Name : SCHIEBERT, JENNIFER
Owner Address : 3502 CAPALINA ROAD, SAN MARCOS, CA 92069
Operator Name : SCHIEBERT, JENNIFER
Operator Address : 3502 CAPALINA ROAD, SAN MARCOS, CA 92069
Latitude : 33.152849
Longitude : -117.199601

RCRA_NONGEN

Facility Name : JENNIFER SCHIEBERT
Facility Address : 3502 CAPALINA ROAD, SAN MARCOS, CA 92069-1235
County : SAN DIEGO

Date Form Received by Agency : 2021-10-04
EPA ID : CAC003141889
Mailing Address : 3502 CAPALINA ROAD, SAN MARCOS, CA 92069-1235
Contact : JENNIFER SCHIEBERT
Contact Address : 3502 CAPALINA ROAD, SAN MARCOS, CA 92069-1235
Contact Country : N/R

Map Id: L97
Direction: WNW
Distance: 0.239 mi., 1264 ft.
Elevation: 588 ft.
Relative: Higher

Site Name : SCHIEBERT, JENNIFER | JENNIFER SCHIEBERT
3502 CAPALINA ROAD
SAN MARCOS, CA

Database(s) : [ECHO, FRS, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 44218573
EPA ID: N/R

RCRA_NONGEN ***(cont.)***

Contact Telephone :	760-846-0713
Contact Email :	NCBS21@GMAIL.COM
EPA Region :	09
Land Type :	Not Reported
Source Type :	Implementer
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2022-01-26

Owner/Operator Summary

Owner/Operator Name :	JENNIFER SCHIEBERT
Owner/Operator Address :	3502 CAPALINA ROAD, SAN MARCOS, CA 92069-1235
Owner/Operator Country :	N/R
Owner/Operator Telephone :	760-846-0713
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Owner/Operator Name :	JENNIFER SCHIEBERT
Owner/Operator Address :	3502 CAPALINA ROAD, SAN MARCOS, CA 92069-1235
Owner/Operator Country :	N/R
Owner/Operator Telephone :	760-846-0713
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N/R
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Map Id: L97
Direction: WNW
Distance: 0.239 mi., 1264 ft.
Elevation: 588 ft.
Relative: Higher

Site Name : SCHIEBERT, JENNIFER | JENNIFER SCHIEBERT
3502 CAPALINA ROAD
SAN MARCOS, CA

Database(s) : [ECHO, FRS, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 44218573
EPA ID: N/R

RCRA_NONGEN ***(cont.)***

Notices of Violations Summary

Regulation Violated :	N
Facility Name :	SCHIEBERT, JENNIFER
Facility Address :	3502 CAPALINA ROAD, SAN MARCOS, CA 92069
County :	SAN DIEGO
Date Form Received by Agency :	2021-10-13
EPA ID :	CAC003143545
Mailing Address :	3502 CAPALINA ROAD, SAN MARCOS, CA 92069
Contact :	SCHIEBERT, JENNIFER
Contact Address :	3502 CAPALINA ROAD, SAN MARCOS, CA 92069
Contact Country :	N/R
Contact Telephone :	760-846-0713
Contact Email :	NCBS21@GMAIL.COM
EPA Region :	09
Land Type :	Not Reported
Source Type :	Implementer
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2022-01-26

Owner/Operator Summary

Owner/Operator Name :	SCHIEBERT, JENNIFER
Owner/Operator Address :	3502 CAPALINA ROAD, SAN MARCOS, CA 92069
Owner/Operator Country :	N/R
Owner/Operator Telephone :	760-846-0713
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Owner/Operator Name :	SCHIEBERT, JENNIFER
Owner/Operator Address :	3502 CAPALINA ROAD, SAN MARCOS, CA 92069
Owner/Operator Country :	N/R
Owner/Operator Telephone :	760-846-0713
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N/R

Map Id: L97
Direction: WNW
Distance: 0.239 mi., 1264 ft.
Elevation: 588 ft.
Relative: Higher

Site Name : SCHIEBERT, JENNIFER | JENNIFER SCHIEBERT
3502 CAPALINA ROAD
SAN MARCOS, CA

Database(s) : [ECHO, FRS, HWG - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 44218573
EPA ID: N/R

RCRA_NONGEN ***(cont.)***

Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Notices of Violations Summary

Regulation Violated :	N

Map Id: L98
Direction: WNW
Distance: 0.240 mi., 1268 ft.
Elevation: 601 ft.
Relative: Higher

Site Name : JAVIER LUCAS | JIMMY HARRIS
3522 BADILLO ROAD
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 41022698
EPA ID: CAC002940982

HAZNET - CA

Facility Name :	JAVIER LUCAS
Facility Address :	3522 BADILLO ROAD, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAC002940982
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	3522 BADILLO ROAD, SAN MARCOS, CA 92069
Latitude :	33.15331773
Longitude :	-117.19942147
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Map Id: L98
Direction: WNW
Distance: 0.240 mi., 1268 ft.
Elevation: 601 ft.
Relative: Higher

Site Name : JAVIER LUCAS | JIMMY HARRIS
3522 BADILLO ROAD
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 41022698
EPA ID: CAC002940982

HAZNET - CA ***(cont.)***

Facility Name :	JIMMY HARRIS
Facility Address :	3522 BADILLO ROAD, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAC002940995
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	3522 BADILLO ROAD, SAN MARCOS, CA 92069
Latitude :	33.15331773
Longitude :	-117.19942147
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HWG - CA

Facility Name :	JAVIER LUCAS
Facility Address :	3522 BADILLO ROAD, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAC002940982
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	3522 BADILLO ROAD, SAN MARCOS, CA 92069
Owner Name :	JAVIER LUCAS
Owner Address :	3522 BADILLO ROAD, SAN MARCOS, CA 92069
Operator Name :	JAVIER LUCAS
Operator Address :	3522 BADILLO ROAD, SAN MARCOS, CA 92069
Latitude :	33.153318
Longitude :	-117.199421

Facility Name :	JIMMY HARRIS
Facility Address :	3522 BADILLO ROAD, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAC002940995
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	3522 BADILLO ROAD, SAN MARCOS, CA 92069
Owner Name :	JIMMY HARRIS
Owner Address :	3522 BADILLO ROAD, SAN MARCOS, CA 92069
Operator Name :	JIMMY HARRIS
Operator Address :	3522 BADILLO ROAD, SAN MARCOS, CA 92069
Latitude :	33.153318

Map Id: L98
Direction: WNW
Distance: 0.240 mi., 1268 ft.
Elevation: 601 ft.
Relative: Higher

Site Name : JAVIER LUCAS | JIMMY HARRIS
3522 BADILLO ROAD
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 41022698
EPA ID: CAC002940982

HWG - CA ***(cont.)***

Longitude :	-117.199421

Map Id: K99
Direction: SW
Distance: 0.245 mi., 1294 ft.
Elevation: 584 ft.
Relative: Lower

Site Name : RANCHO SANTE FE GAS | RANCHO SANTA FE GAS
105 RANCHO SANTA FE ROAD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, ECHO, FRS]

Envirosite ID: 482927
EPA ID: N/R

CALEPA SITES - CA

Facility Name :	RANCHO SANTA FE GAS
Facility Address :	105 RANCHO SANTA FE ROAD, SAN MARCOS, 92078-2501
Site ID :	489272
EI ID :	110013862016
EI Description :	US EPA Air Emission Inventory System (EIS)
Latitude :	33.148650
Longitude :	-117.198950
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07

ECHO

Facility Name :	RANCHO SANTA FE GAS
Facility Address :	105 RANCHO SANTA FE ROAD, SAN MARCOS, CA 92078
County :	SAN DIEGO
Last Inspection Date :	N/R
Registry ID :	110013862016
FIPS Code :	06073
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	_____
Collection Method :	ADDRESS MATCHING-HOUSE NUMBER
Reference Point :	CENTER OF A FACILITY OR STATION
Accuracy Meters :	30

Map Id: K99
Direction: SW
Distance: 0.245 mi., 1294 ft.
Elevation: 584 ft.
Relative: Lower

Site Name : RANCHO SANTE FE GAS | RANCHO SANTA FE GAS
105 RANCHO SANTA FE ROAD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, ECHO, FRS] ***(cont.)***

Envirosite ID: 482927
EPA ID: N/R

ECHO ***(cont.)***

Derived Tribes :

San Pasqual Band of Diegueno Mission Indians of California - 12.6 mile(s), Pala Band of Mission Indians - 13.4 mile (s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 14.3 mile(s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 16.5 mile(s), Pauma Band of Luiseno Mission Indians of the Pauma & Yuima Reservation, California - 17.1 mile(s), La Jolla Band of Luiseno Indians, California - 17.4 mile(s), Pechanga Band of Luiseno Mission Indians of the Pechanga Reservation, California - 20.6 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 22.7 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 23.1 mile(s), Mesa Grande Band of Diegueno Mission Indians of the Mesa Grande Reservation, California - 23.4 mile(s)

Derived HUC :	18070303
Derived WBD :	180703030503
Derived STCTY FIPS :	06073
Derived Zip :	92078
Derived CD113 :	50
Derived CB2010 :	060730200291006
MYRTK Universe :	NNN
NPDES IDs :	N/R
CWA Permit Types :	N/R
CWA Compliance Tracking :	N/R
CWA NAICS :	N/R
CWA SICS :	N/R
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	N/R
CWA Current Compliance Status :	N/R
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	N/R
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	N/R
Facility NAICS :	56291 - Remediation Services, 447110 - Gasoline Stations with Convenience Stores, 44719 - Other Gasoline Stations
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R

Map Id: K99
Direction: SW
Distance: 0.245 mi., 1294 ft.
Elevation: 584 ft.
Relative: Lower

Site Name : RANCHO SANTE FE GAS | RANCHO SANTA FE GAS
105 RANCHO SANTA FE ROAD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, ECHO, FRS] ***(cont.)***

Envirosite ID: 482927
EPA ID: N/R

ECHO ***(cont.)***

US Mexico Border Flag :	Y
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	N
SDWIS Flag :	N
RCRA Flag :	Y
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	Y
NAA Flag :	Y
Latitude :	33.14865
Longitude :	-117.19895
Last Date in Agency List :	2021-04-16
Facility Name :	RANCHO SANTE FE GAS
Facility Address :	105 RANCHO SANTA FE ROAD, SAN MARCOS, CA 92078
County :	SAN DIEGO
Last Inspection Date :	N/R
Registry ID :	110013862016
FIPS Code :	06073
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	_____
Collection Method :	ADDRESS MATCHING-HOUSE NUMBER
Reference Point :	CENTER OF A FACILITY OR STATION
Accuracy Meters :	30

Derived Tribes :

San Pasqual Band of Diegueno Mission Indians of California - 12.6 mile(s), Pala Band of Mission Indians - 13.4 mile (s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 14.3 mile(s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 16.5 mile(s), Pauma Band of Luiseno Mission Indians of the Pauma & Yuima Reservation, California - 17.1 mile(s), La Jolla Band of Luiseno Indians, California - 17.4 mile(s), Pechanga Band of Luiseno Mission Indians of the Pechanga Reservation, California - 20.6 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 22.7 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 23.1 mile(s), Mesa Grande Band of Diegueno Mission Indians of the Mesa Grande Reservation, California - 23.4 mile(s)

Derived HUC : 18070303

Map Id: K99
Direction: SW
Distance: 0.245 mi., 1294 ft.
Elevation: 584 ft.
Relative: Lower

Site Name : RANCHO SANTE FE GAS | RANCHO SANTA FE GAS
105 RANCHO SANTA FE ROAD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, ECHO, FRS] ***(cont.)***

Envirosite ID: 482927
EPA ID: N/R

ECHO ***(cont.)***

Derived WBD :	180703030503
Derived STCTY FIPS :	06073
Derived Zip :	92078
Derived CD113 :	50
Derived CB2010 :	060730200291006
MYRTK Universe :	NNN
NPDES IDs :	N/R
CWA Permit Types :	N/R
CWA Compliance Tracking :	N/R
CWA NAICS :	N/R
CWA SICS :	N/R
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	N/R
CWA Current Compliance Status :	N/R
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	N/R
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	N/R
Facility NAICS :	447110 - Gasoline Stations with Convenience Stores, 56291 - Remediation Services, 44719 - Other Gasoline Stations
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	Y
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	N
SDWIS Flag :	N
RCRA Flag :	Y
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	Y
NAA Flag :	Y
Latitude :	33.14865
Longitude :	-117.19895

Map Id: K99
Direction: SW
Distance: 0.245 mi., 1294 ft.
Elevation: 584 ft.
Relative: Lower

Site Name : RANCHO SANTE FE GAS | RANCHO SANTA FE GAS
105 RANCHO SANTA FE ROAD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, ECHO, FRS] ***(cont.)***

Envirosite ID: 482927
EPA ID: N/R

ECHO ***(cont.)***

Last Date in Agency List : 2022-01-17

FRS

Facility Name : RANCHO SANTA FE GAS
Facility Address : 105 RANCHO SANTA FE ROAD, SAN MARCOS, CA 92078-2501
County : SAN DIEGO

Site Details

Registry ID : 110013862016
FRS Facility URL : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2021-07-17

Source Description

Source Description : All generators and treatment, storage, and disposal (TSD) facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years. The data collected is used to create the National Biennial Resource Conservation and Recovery Act (RCRA) Hazardous Waste Report. This data is processed within the RCRA Information (RCRAInfo) database.
The California Environmental Protection Agency (CalEPA) has recently implemented a new data warehouse system (nSite). This data warehouse combines and merges facility and site information from five different systems managed within CalEPA. The five systems are: California Environmental Reporting System (CERS), EnviroStor, GeoTracker, California Integrated Water Quality System (CIWQS), and Toxic Release Inventory (TRI).

Source Description :

The Emission Inventory System (EIS) maintains an inventory of large stationary sources and voluntarily-reported smaller sources of air point pollution emitters. It contains information about facility sites and their physical location, emission units, emission processes, release points, control approaches, and regulations. Facility inventory data are kept separate from the emissions data and have stable identifiers to improve continuity from year to year and to help identify duplicate or missing facilities.

Source Description :

RCRAInfo is EPA’s comprehensive information system that supports the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984 through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA. RCRAInfo also supports generation of the National Hazardous Waste Biennial Report. All generators and treatment, storage, and disposal facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years to support creation of the Biennial Report.

FRS Environmental Interest

Source and System ID : CA-ENVIROVIEW - 146584
EIS - 853211

Map Id: K99
Direction: SW
Distance: 0.245 mi., 1294 ft.
Elevation: 584 ft.
Relative: Lower

Site Name : RANCHO SANTE FE GAS | RANCHO SANTA FE GAS
105 RANCHO SANTA FE ROAD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, ECHO, FRS] ***(cont.)***

Envirosite ID: 482927
EPA ID: N/R

FRS ***(cont.)***

RCRAINFO - CAL000287229
RCRAINFO - CAR000125989

Facility Name : RANCHO SANTE FE GAS
Facility Address : 105 RANCHO SANTA FE RD, SAN MARCOS, CA 92078
County : SAN DIEGO

Site Details
Registry ID : 110041173379
FRS Facility URL : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2014-03-25

Source Description

Source Description :

The Emission Inventory System (EIS) maintains an inventory of large stationary sources and voluntarily-reported smaller sources of air point pollution emitters. It contains information about facility sites and their physical location, emission units, emission processes, release points, control approaches, and regulations. Facility inventory data are kept separate from the emissions data and have stable identifiers to improve continuity from year to year and to help identify duplicate or missing facilities.

FRS Environmental Interest
Source and System ID : EIS - 853211

Facility Name : RANCHO SANTE FE GAS
Facility Address : 105 RANCHO SANTA FE ROAD, SAN MARCOS, CA 92078-2501
County : SAN DIEGO

Site Details
Registry ID : 110013862016
FRS Facility URL : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-02-17

Source Description
Source Description : All generators and treatment, storage, and disposal (TSD) facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years. The data collected is used to create the National Biennial Resource Conservation and Recovery Act (RCRA) Hazardous Waste Report. This data is processed within the RCRA Information (RCRAInfo) database.

Map Id: K99
Direction: SW
Distance: 0.245 mi., 1294 ft.
Elevation: 584 ft.
Relative: Lower

Site Name : RANCHO SANTE FE GAS | RANCHO SANTA FE GAS
105 RANCHO SANTA FE ROAD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, ECHO, FRS] ***(cont.)***

Envirosite ID: 482927
EPA ID: N/R

FRS ***(cont.)***

The California Environmental Protection Agency (CalEPA) has recently implemented a new data warehouse system (nSite). This data warehouse combines and merges facility and site information from five different systems managed within CalEPA. The five systems are: California Environmental Reporting System (CERS), EnviroStor, GeoTracker, California Integrated Water Quality System (CIWQS), and Toxic Release Inventory (TRI).

Source Description :

The Emission Inventory System (EIS) maintains an inventory of large stationary sources and voluntarily-reported smaller sources of air point pollution emitters. It contains information about facility sites and their physical location, emission units, emission processes, release points, control approaches, and regulations. Facility inventory data are kept separate from the emissions data and have stable identifiers to improve continuity from year to year and to help identify duplicate or missing facilities.

Source Description :

RCRAInfo is EPA's comprehensive information system that supports the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984 through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA. RCRAInfo also supports generation of the National Hazardous Waste Biennial Report. All generators and treatment, storage, and disposal facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years to support creation of the Biennial Report.

FRS Environmental Interest
Source and System ID :
CA-ENVIROVIEW - 146584
EIS - 853211
RCRAINFO - CAL000287229
RCRAINFO - CAR000125989

Map Id: 100
Direction: NW
Distance: 0.247 mi., 1306 ft.
Elevation: 569 ft.
Relative: Lower

Site Name : GIANNA JIMENEZ
3501 HOLLENCREST ROAD'
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 41099389
EPA ID: CAC002950265

HAZNET - CA

Facility Name : GIANNA JIMENEZ
Facility Address : 3501 HOLLENCREST ROAD', SAN MARCOS, CA 92069
County : SAN DIEGO

Map Id: 100
Direction: NW
Distance: 0.247 mi., 1306 ft.
Elevation: 569 ft.
Relative: Lower

Site Name : GIANNA JIMENEZ
3501 HOLLENCREST ROAD'
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 41099389
EPA ID: CAC002950265

HAZNET - CA ***(cont.)***

Site Details

Generator EPA ID :	CAC002950265
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	3501 HOLLENCREST ROAD', SAN MARCOS, CA 92069
Latitude :	33.15479531
Longitude :	-117.19875359
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	2018: 151 - Asbestos containing waste, 0.46000 tons to AZC950823111

HWG - CA

Facility Name :	GIANNA JIMENEZ
Facility Address :	3501 HOLLENCREST ROAD', SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAC002950265
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	3501 HOLLENCREST ROAD', SAN MARCOS, CA 92069
Owner Name :	GIANNA JIMENEZ
Owner Address :	3501 HOLLENCREST ROAD', SAN MARCOS, CA 92069
Operator Name :	GIANNA JIMENEZ
Operator Address :	3501 HOLLENCREST ROAD', SAN MARCOS, CA 92069
Latitude :	33.154795
Longitude :	-117.198754

Map Id: J101
Direction: E
Distance: 0.248 mi., 1309 ft.
Elevation: 579 ft.
Relative: Lower

Site Name : DEAN TILTON
431 N PACIFIC ST SUITE D
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA]

Envirosite ID: 41125490
EPA ID: CAC002715955

HAZNET - CA

Facility Name :	DEAN TILTON
Facility Address :	431 N PACIFIC ST SUITE D, SAN MARCOS, CA 92069
County :	SAN DIEGO

Map Id: J101
Direction: E
Distance: 0.248 mi., 1309 ft.
Elevation: 579 ft.
Relative: Lower

Site Name : DEAN TILTON
431 N PACIFIC ST SUITE D
SAN MARCOS, CA 92069

Database(s) : [HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 41125490
EPA ID: CAC002715955

HAZNET - CA ***(cont.)***

Site Details

Generator EPA ID :	CAC002715955
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	128 N LAS POSAS RD, SAN MARCOS, CA 92069
Latitude :	33.15191112
Longitude :	-117.19119469
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HWG - CA

Facility Name :	DEAN TILTON
Facility Address :	431 N PACIFIC ST SUITE D, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAC002715955
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	128 N LAS POSAS RD, SAN MARCOS, CA 92069
Owner Name :	DEAN TILTON
Owner Address :	128 N LAS POSAS RD, SAN MARCOS, CA 920691420
Operator Name :	MIKE MULLOY
Operator Address :	431 N PACIFIC ST, SAN MARCOS, CA 920691330
Latitude :	33.151911
Longitude :	-117.191195

Map Id: M102
Direction: SE
Distance: 0.250 mi., 1320 ft.
Elevation: 559 ft.
Relative: Lower

Site Name : PACIFIC METAL PRODUCTS | 1X ROOT TRUCKING CO INC
155 BALBOA ST UNIT D13 | 155 N BALBOA ST
SAN MARCOS | San Marcos, CA 92069

Database(s) : [CIWQS - CA, HAZNET - CA, HWG - CA, RFR - CA]

Envirosite ID: 41004477
EPA ID: N/R

CIWQS - CA

Facility Name :	PACIFIC METAL PRODUCTS
Facility Address :	155 BALBOA ST UNIT D13, SAN MARCOS, CA 92069
County :	SAN DIEGO

Map Id: M102
Direction: SE
Distance: 0.250 mi., 1320 ft.
Elevation: 559 ft.
Relative: Lower

Site Name : PACIFIC METAL PRODUCTS | 1X ROOT TRUCKING CO INC
155 BALBOA ST UNIT D13 | 155 N BALBOA ST
SAN MARCOS | San Marcos, CA 92069

Database(s) : [CIWQS - CA, HAZNET - CA, HWG - CA, RFR - CA] ***(cont.)***

Envirosite ID: 41004477
EPA ID: N/R

CIWQS - CA ***(cont.)***

Place ID :	S888321
Agency Name :	PACIFIC METAL PRODUCTS
Last Date in Agency List :	2021-12-30

HAZNET - CA

Facility Name :	1X ROOT TRUCKING CO INC
Facility Address :	155 N BALBOA ST, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAC000603360
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	155 N BALBOA ST #D1, SAN MARCOS, CA 920690000
Latitude :	33.14886320
Longitude :	-117.19224235
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HWG - CA

Facility Name :	1X ROOT TRUCKING CO INC
Facility Address :	155 N BALBOA ST, SAN MARCOS, CA 92069
County :	SAN DIEGO

EPA ID :	CAC000603360
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	155 N BALBOA ST #D1, SAN MARCOS, CA 920690000
Owner Name :	BOND, J D
Owner Address :	N/A
Operator Name :	MYERS, DENNIS
Operator Address :	N/A
Latitude :	33.148928
Longitude :	-117.192274

RFR - CA

Facility Name :	PACIFIC METAL PRODUCTS
Facility Address :	155 BALBOA ST UNIT D13, San Marcos, CA 92069
County :	San Diego

Map Id: M102
Direction: SE
Distance: 0.250 mi., 1320 ft.
Elevation: 559 ft.
Relative: Lower

Site Name : PACIFIC METAL PRODUCTS | 1X ROOT TRUCKING CO INC
155 BALBOA ST UNIT D13 | 155 N BALBOA ST
SAN MARCOS | San Marcos, CA 92069

Database(s) : [CIWQS - CA, HAZNET - CA, HWG - CA, RFR - CA] ***(cont.)***

Envirosite ID: 41004477
EPA ID: N/R

RFR - CA ***(cont.)***

Effective Date :	2020-12-08
Adoption Date :	N/R
Termination Date :	N/R
Expiration/Review Date :	N/R
NPDES Number :	CAS000001
Order Number :	2014-0057-DWQ
WDID :	9 37NEC008079
SIC/NAICS :	3499(+)
Program :	INDSTW
Regulatory Measure Status :	Active
Regulatory Measure Type :	Storm water industrial
Place/Project Type :	Industrial - Fabricated Metal Products, NEC
Region :	9
Design Flow :	N/R
Major/Minor :	N/R
Complexity :	N/R
TTWQ :	N/R
Number of Enforcement Actions within Five Years:	2
Number of Violations within Five Years:	1
Agency :	PACIFIC METAL PRODUCTS
Agency Address :	155 BALBOA ST UNIT D13, San Marcos, CA 92069
Latitude :	33.14839
Longitude :	-117.19205
Last Date in Agency List :	2022-03-07

Map Id: K103
Direction: SW
Distance: 0.262 mi., 1384 ft.
Elevation: 584 ft.
Relative: Lower

Site Name : FORMER CONTINENTAL CLEANERS | RESOURCE ENVIRONMENTAL LLC
TEXACO STATION | CONTINENTAL CLEANERS
109 SOUTH RANCHO SANTA FE ROAD | 105 S RANCHO SANTA FE RD | 109 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA 92078

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, FRS, HAZNET - CA, HWG - CA, RCRA_NONGEN, SLIC REG 9 - CA]

Envirosite ID: 257305
EPA ID: CAL000238056

CALEPA SITES - CA

Facility Name :	FORMER CONTINENTAL CLEANERS
Facility Address :	109 SOUTH RANCHO SANTA FE ROAD, SAN MARCOS, 92078

Map Id: K103
Direction: SW
Distance: 0.262 mi., 1384 ft.
Elevation: 584 ft.
Relative: Lower

Site Name : FORMER CONTINENTAL CLEANERS | RESOURCE ENVIRONMENTAL LLC
TEXACO STATION | CONTINENTAL CLEANERS
109 SOUTH RANCHO SANTA FE ROAD | 105 S RANCHO SANTA FE RD | 109 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA 92078

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, FRS, HAZNET - CA, HWG - CA, RCRA_NONGEN, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 257305
EPA ID: CAL000238056

CALEPA SITES - CA ***(cont.)***

Site ID :	253466
EI ID :	T10000005844
EI Description :	Cleanup Program Site
Latitude :	33.148396
Longitude :	-117.198244
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07

CASE LIST_SAN DIEGO COUNTY - CA

Facility Name :	Former Continental Cleaners
Facility Address :	109 South Rancho Santa Fe Road, San Marcos, CA 92078
County :	San Diego

Site Details

Status Date :	2018-06-20
Status :	Completed - Case Closed
Begin Date :	2014-04-11
Global ID :	T10000005844

Site History :

This Voluntary Assistance Program Case was opened in February 14, 2014 to further evaluate the impacts from chlorinated compounds and provide mitigation, if needed, for a former dry cleaner. Five soil borings were installed on site as part of a July 2006, Phase II Environmental Site Assessment Report. Groundwater samples were taken from the borings which were then converted to soil vapor probes. Additional site assessment was performed in June to July 2015 with the installation of eight soil vapor probes. These probes were sampled three times within a six week period. In addition, three permanent Monitoring Wells (MWs) were installed. Based on the concentrations of PCE and TCE from the soil borings, vapor probes, and MWs, it was determined that a greater than one in a million excess cancer risk existed on site. DEH concurred with this and recommended further evaluation. On June 28, 2017, SCS Engineers (SCS) conducted a radon tracer study to evaluate a site-specific slab attenuation rate. The results of such were submitted in a November 28, 2017 Subsurface Assessment Report and Vapor Intrusion Risk Assessment (SAR-VIRA). The SAR-VIRA compiled the sub-slab soil vapor results and the radon study and concluded that indoor air would be below screening levels for PCE and TCE. DEH indicated that indoor air sampling and an additional round of groundwater sampling be performed to provide a third line of evidence. An April 19, 2018 Groundwater and Indoor Air Sampling Report indicated that PCE and TCE were not present in detectable concentrations in Indoor Air (IA). Volatile Organic Compounds such as benzene, which were present in IA, were also present in the Outdoor Ambient Air (OA) sample. SCS concluded that they were most likely associated with the gasoline service station adjacent to the site. Moreover, other compounds, such as carbon tetrachloride, were present in equal amounts in the IA and OA samples. Based on this the consultant concluded that these compounds are typical of urban areas and are not associated with the dry cleaning chlorinated release from this site. The presence of chloroform in the IA sample nearest the restroom is most likely from chlorinated tap water. This is because the toilet was continuously running due to plumbing issues during the collection of IA samples. SCS states that because PCE, TCE, and the breakdown products were not reported at detectible concentrations in indoor air, in conjunction with other lines of evidence (SAR-VIRA and the radon tracer study), a significant health risk does not exist at the Site as a result of vapor phase migration of PCE and TCE in soil vapor. DEH concurs. SCS further states

Map Id: K103
Direction: SW
Distance: 0.262 mi., 1384 ft.
Elevation: 584 ft.
Relative: Lower

Site Name : FORMER CONTINENTAL CLEANERS | RESOURCE ENVIRONMENTAL LLC TEXACO STATION | CONTINENTAL CLEANERS
109 SOUTH RANCHO SANTA FE ROAD | 105 S RANCHO SANTA FE RD | 109 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA 92078

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, FRS, HAZNET - CA, HWG - CA, RCRA_NONGEN, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 257305
EPA ID: CAL000238056

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

that PCE and TCE concentrations in groundwater are lower and are generally stable or decreasing. DEH also concurs.

RB Case Number :	N/R
Potential Media Affected :	N/R
Potential Contaminants of Concern :	N/R
Local Agency :	SAN DIEGO COUNTY LOP
Local Case Number :	DEH2014-LSAM-000243
Lead Agency :	SAN DIEGO COUNTY LOP
File Location :	Local Agency
CUF Case :	NO
Caseworker :	EM
Case Type :	Cleanup Program Site
How Discovered :	N/R
How Discovered Description :	N/R
Stop Method :	N/R
Stop Description :	N/R
Calwater Watershed Name :	Carlsbad - San Marcos - Richland (904.52)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)
Disadvantaged Community :	Severely Disadvantaged Community
Latitude :	33.148396
Longitude :	-117.198244
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-09

Contacts Summary

Global ID :	T10000005844
Contact Name :	EWAN MOFFAT
Contact Type :	Local Agency Caseworker
Organization Name :	SAN DIEGO COUNTY LOP
Address :	P.O. Box 129261
City :	San Diego
Phone Number :	N/R
Email :	ewan.moffat@sdcounty.ca.gov

Regulatory Activities

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Date :	2018-06-20
Global ID :	T10000005844
Action Type :	ENFORCEMENT

Map Id: K103
Direction: SW
Distance: 0.262 mi., 1384 ft.
Elevation: 584 ft.
Relative: Lower

Site Name : FORMER CONTINENTAL CLEANERS | RESOURCE ENVIRONMENTAL LLC TEXACO STATION | CONTINENTAL CLEANERS
109 SOUTH RANCHO SANTA FE ROAD | 105 S RANCHO SANTA FE RD | 109 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA 92078

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, FRS, HAZNET - CA, HWG - CA, RCRA_NONGEN, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 257305
EPA ID: CAL000238056

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Action :	Closure/No Further Action Letter
Date :	2018-03-05
Global ID :	T10000005844
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other
Date :	2018-02-27
Global ID :	T10000005844
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other
Date :	2018-02-22
Global ID :	T10000005844
Action Type :	RESPONSE
Action :	Other Workplan - Regulator Responded
Date :	2017-12-06
Global ID :	T10000005844
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other
Date :	2017-11-28
Global ID :	T10000005844
Action Type :	ENFORCEMENT
Action :	Meeting
Date :	2017-08-14
Global ID :	T10000005844
Action Type :	RESPONSE
Action :	Soil Vapor Intrusion Investigation Report
Date :	2017-06-21
Global ID :	T10000005844
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other
Date :	2017-06-07
Global ID :	T10000005844
Action Type :	RESPONSE

Map Id: K103
Direction: SW
Distance: 0.262 mi., 1384 ft.
Elevation: 584 ft.
Relative: Lower

Site Name : FORMER CONTINENTAL CLEANERS | RESOURCE ENVIRONMENTAL LLC TEXACO STATION | CONTINENTAL CLEANERS
109 SOUTH RANCHO SANTA FE ROAD | 105 S RANCHO SANTA FE RD | 109 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA 92078

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, FRS, HAZNET - CA, HWG - CA, RCRA_NONGEN, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 257305
EPA ID: CAL000238056

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Action : Soil Vapor Intrusion Investigation Workplan - Regulator Responded

Date : 2017-05-11
Global ID : T10000005844
Action Type : ENFORCEMENT
Action : Meeting

Status History
Status Date : 2018-06-20
Global ID : T10000005844
Status : Completed - Case Closed

Status Date : 2014-04-16
Global ID : T10000005844
Status : Open - Site Assessment

Status Date : 2014-04-11
Global ID : T10000005844
Status : Open - Case Begin Date

FRS

Facility Name : FORMER CONTINENTAL CLEANERS
Facility Address : 109 SOUTH RANCHO SANTA FE ROAD, SAN MARCOS, CA 92078
County : SAN DIEGO

Site Details
Registry ID : 110065935402
FRS Facility URL : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-02-17

Source Description

Source Description :

The California Environmental Protection Agency (CalEPA) has recently implemented a new data warehouse system (nSite). This data warehouse combines and merges facility and site information from five different systems managed within CalEPA. The five systems are: California Environmental Reporting System (CERS), EnviroStor, GeoTracker, California Integrated Water Quality System (CIWQS), and Toxic Release Inventory (TRI).

Map Id: K103
Direction: SW
Distance: 0.262 mi., 1384 ft.
Elevation: 584 ft.
Relative: Lower

Site Name : FORMER CONTINENTAL CLEANERS | RESOURCE ENVIRONMENTAL LLC TEXACO STATION | CONTINENTAL CLEANERS
109 SOUTH RANCHO SANTA FE ROAD | 105 S RANCHO SANTA FE RD | 109 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA 92078

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, FRS, HAZNET - CA, HWG - CA, RCRA_NONGEN, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 257305
EPA ID: CAL000238056

FRS ***(cont.)***

FRS Environmental Interest
Source and System ID : CA-ENVIROVIEW - 253466

HAZNET - CA

Facility Name : CONTINENTAL CLEANERS
Facility Address : 109 S RANCHO SANTA FE RD, SAN MARCOS, CA 92078
County : SAN DIEGO

Site Details
Generator EPA ID : CAL000238056
Active : Inactive
Category : STATE
Facility Types : N/R
Type : PERMANENT
Contact Name : N/R
Contact Phone : N/R
Facility Mailing Address : 109 S RANCHO SANTA FE RD, SAN MARCOS, CA 920690000
Latitude : 33.14872806
Longitude : -117.19884497
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2021-07-08

Waste Generator Details
State Waste : 2003: 741 - Liquids with halogenated organic compounds >= 1,000 Mg. /L, 0.68 tons to CAT000613893
2002: 741 - Liquids with halogenated organic compounds >= 1,000 Mg. /L, 0.25 tons to CAT000613893

Facility Name : RESOURCE ENVIRONMENTAL LLC TEXACO STATION
Facility Address : 105 S RANCHO SANTA FE RD, SAN MARCOS, CA 92078
County : SAN DIEGO

Site Details
Generator EPA ID : CAR000125989
Active : Inactive
Category : FEDERAL
Facility Types : N/R
Type : PERMANENT
Contact Name : N/R
Contact Phone : N/R

Map Id: K103
Direction: SW
Distance: 0.262 mi., 1384 ft.
Elevation: 584 ft.
Relative: Lower

Site Name : FORMER CONTINENTAL CLEANERS | RESOURCE ENVIRONMENTAL LLC TEXACO STATION | CONTINENTAL CLEANERS
109 SOUTH RANCHO SANTA FE ROAD | 105 S RANCHO SANTA FE RD | 109 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA 92078

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, FRS, HAZNET - CA, HWG - CA, RCRA_NONGEN, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 257305
EPA ID: CAL000238056

HAZNET - CA ***(cont.)***

Facility Mailing Address :	4700 LOUISIANA HIGHWAY 22 STE 520, MANDEVILLE, LA 70471
Latitude :	33.14859300
Longitude :	-117.19871550
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :

2012: 122 - Alkaline solution without metals pH >= 12.5, 0.2085 tons to CAD097030993
2011: 122 - Alkaline solution without metals pH >= 12.5, 0.8757 tons to CAD097030993
2009: 122 - Alkaline solution without metals pH >= 12.5, 0.417 tons to CAD097030993
2003: 512 - Other empty containers 30 gallons or more, 13.25 tons to CAD982484933
2003: 512 - Other empty containers 30 gallons or more, 0.75 tons to CAD982484933
2003: 241 - Tank bottom waste, 4.17 tons to CAT080013352
2003: 134 - Aqueous solution with total organic residues less than 10 percent, 3.57 tons to CAT080013352
2002: 241 - Tank bottom waste, 0.72141 tons to CAD028409019

HWG - CA

Facility Name :	CONTINENTAL CLEANERS
Facility Address :	109 S RANCHO SANTA FE RD, SAN MARCOS, CA 92078
County :	SAN DIEGO
EPA ID :	CAL000238056
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	109 S RANCHO SANTA FE RD, SAN MARCOS, CA 920690000
Owner Name :	SARA VAN WAGNER
Owner Address :	109 S RANCHO SANTA FE RD, SAN MARCOS, CA 920690000
Operator Name :	SARA VAN WAGNER OWNER
Operator Address :	109 S RANCHO SANTA FE RD, SAN MARCOS, CA 920690000
Latitude :	33.14873
Longitude :	-117.198885

Facility Name :	RESOURCE ENVIRONMENTAL LLC TEXACO STATION
Facility Address :	105 S RANCHO SANTA FE RD, SAN MARCOS, CA 92078
County :	SAN DIEGO

Map Id: K103
Direction: SW
Distance: 0.262 mi., 1384 ft.
Elevation: 584 ft.
Relative: Lower

Site Name : FORMER CONTINENTAL CLEANERS | RESOURCE ENVIRONMENTAL LLC
TEXACO STATION | CONTINENTAL CLEANERS
109 SOUTH RANCHO SANTA FE ROAD | 105 S RANCHO SANTA FE RD | 109 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA 92078

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, FRS, HAZNET - CA, HWG - CA, RCRA_NONGEN, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 257305
EPA ID: CAL000238056

HWG - CA ***(cont.)***

EPA ID :	CAR000125989
Status :	Inactive
Category :	FEDERAL
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	4700 LOUISIANA HIGHWAY 22 STE 520, MANDEVILLE, LA 70471
Owner Name :	RESOURCE ENVIRONMENTAL LLC
Owner Address :	4700 LOUISIANA HIGHWAY 22 STE 520, MANDEVILLE, LA 70471
Operator Name :	JOHN ENGLEHARDT
Operator Address :	4700 LA HIGHWAY 22 #520, MANDEVILLE, LA 70471
Latitude :	33.148841
Longitude :	-117.198917

RCRA_NONGEN

Facility Name :	RANCHO SANTA FE GAS
Facility Address :	105 S RANCHO SANTA FE RD, SAN MARCOS, CA 92078
County :	SAN DIEGO

Date Form Received by Agency :	2018-12-24
EPA ID :	CAR000125989
Mailing Address :	4700 LA HIGHWAY 22 STE 520, MANDEVILLE, LA 70471
Contact :	JOHN ENGLEHARDT
Contact Address :	4700 LA HIGHWAY 22 STE 520, MANDEVILLE, LA 70471
Contact Country :	US
Contact Telephone :	985-792-1302
Contact Email :	JENG@RELLC.NET
EPA Region :	09
Land Type :	Private
Source Type :	Deactivation
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2022-01-26

Owner/Operator Summary

Owner/Operator Name :	RESOURCE ENVIRONMENTAL LLC
Owner/Operator Address :	N/R
Owner/Operator Country :	N/R
Owner/Operator Telephone :	N/R
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Private
Owner/Operator Type :	Operator
Owner/Operator Start Date :	2007-04-06
Owner/Operator End Date :	N/R

Map Id: K103
Direction: SW
Distance: 0.262 mi., 1384 ft.
Elevation: 584 ft.
Relative: Lower

Site Name : FORMER CONTINENTAL CLEANERS | RESOURCE ENVIRONMENTAL LLC
TEXACO STATION | CONTINENTAL CLEANERS
109 SOUTH RANCHO SANTA FE ROAD | 105 S RANCHO SANTA FE RD | 109 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA 92078

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, FRS, HAZNET - CA, HWG - CA, RCRA_NONGEN, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 257305
EPA ID: CAL000238056

RCRA_NONGEN ***(cont.)***

Owner/Operator Name :	RESOURCE ENVIRONMENTAL LLC
Owner/Operator Address :	4700 LA HIGHWAY 22 STE 520, MANDEVILLE, LA 70471
Owner/Operator Country :	US
Owner/Operator Telephone :	N/R
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Private
Owner/Operator Type :	Owner
Owner/Operator Start Date :	2007-04-06
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Historical Generators

Date Form Received by Agency :	2009-03-27
Facility Name :	RANCHO SANTA FE GAS
Classification :	Small Quantity Generator
Date Form Received by Agency :	2004-02-26
Facility Name :	TEXACO SERVICE STATION
Classification :	Small Quantity Generator
Date Form Received by Agency :	2004-02-26
Facility Name :	TEXACO SERVICE STATION
Classification :	Large Quantity Generator

Map Id: K103
Direction: SW
Distance: 0.262 mi., 1384 ft.
Elevation: 584 ft.
Relative: Lower

Site Name : FORMER CONTINENTAL CLEANERS | RESOURCE ENVIRONMENTAL LLC
TEXACO STATION | CONTINENTAL CLEANERS
109 SOUTH RANCHO SANTA FE ROAD | 105 S RANCHO SANTA FE RD | 109 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA 92078

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, FRS, HAZNET - CA, HWG - CA, RCRA_NONGEN, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 257305
EPA ID: CAL000238056

RCRA_NONGEN ***(cont.)***

Date Form Received by Agency :	2002-08-16
Facility Name :	TEXACO SERVICE STATION
Classification :	Small Quantity Generator

Notices of Violations Summary

Regulation Violated :	N

SLIC REG 9 - CA

Facility Name :	Former Continental Cleaners
Facility Address :	109 South Rancho Santa Fe Road, San Marcos, CA 92078
County :	San Diego

Site Details

Status Date :	2018-06-20
Status :	Completed - Case Closed
Begin Date :	2014-04-11
Global ID :	T10000005844
Region :	REGION 9

Site History :

This Voluntary Assistance Program Case was opened in February 14, 2014 to further evaluate the impacts from chlorinated compounds and provide mitigation, if needed, for a former dry cleaner. Five soil borings were installed on site as part of a July 2006, Phase II Environmental Site Assessment Report. Groundwater samples were taken from the borings which were then converted to soil vapor probes. Additional site assessment was performed in June to July 2015 with the installation of eight soil vapor probes. These probes were sampled three times within a six week period. In addition, three permanent Monitoring Wells (MWs) were installed. Based on the concentrations of PCE and TCE from the soil borings, vapor probes, and MWs, it was determined that a greater than one in a million excess cancer risk existed on site. DEH concurred with this and recommended further evaluation. On June 28, 2017, SCS Engineers (SCS) conducted a radon tracer study to evaluate a site-specific slab attenuation rate. The results of such were submitted in a November 28, 2017 Subsurface Assessment Report and Vapor Intrusion Risk Assessment (SAR-VIRA). The SAR-VIRA compiled the sub-slab soil vapor results and the radon study and concluded that indoor air would be below screening levels for PCE and TCE. DEH indicated that indoor air sampling and an additional round of groundwater sampling be performed to provide a third line of evidence. An April 19, 2018 Groundwater and Indoor Air Sampling Report indicated that PCE and TCE were not present in detectable concentrations in Indoor Air (IA). Volatile Organic Compounds such as benzene, which were present in IA, were also present in the Outdoor Ambient Air (OA) sample. SCS concluded that they were most likely associated with the gasoline service station adjacent to the site. Moreover, other compounds, such as carbon tetrachloride, were present in equal amounts in the IA and OA samples. Based on this the consultant concluded that these compounds are typical of urban areas and are not associated with the dry cleaning chlorinated release from this site. The presence of chloroform in the IA sample nearest the restroom is most likely from chlorinated tap water. This is because the toilet was continuously running due to plumbing issues during the collection of IA samples. SCS states that because PCE, TCE, and the breakdown products were not reported at detectible concentrations in indoor air, in

Map Id: K103
Direction: SW
Distance: 0.262 mi., 1384 ft.
Elevation: 584 ft.
Relative: Lower

Site Name : FORMER CONTINENTAL CLEANERS | RESOURCE ENVIRONMENTAL LLC TEXACO STATION | CONTINENTAL CLEANERS
109 SOUTH RANCHO SANTA FE ROAD | 105 S RANCHO SANTA FE RD | 109 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA 92078

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, FRS, HAZNET - CA, HWG - CA, RCRA_NONGEN, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 257305
EPA ID: CAL000238056

SLIC REG 9 - CA ***(cont.)***

conjunction with other lines of evidence (SAR-VIRA and the radon tracer study), a significant health risk does not exist at the Site as a result of vapor phase migration of PCE and TCE in soil vapor. DEH concurs. SCS further states that PCE and TCE concentrations in groundwater are lower and are generally stable or decreasing. DEH also concurs.

RB Case Number :	N/R
Potential Media Affected :	N/R
Potential Contaminants of Concern :	N/R
Local Agency :	SAN DIEGO COUNTY LOP
Local Case Number :	DEH2014-LSAM-000243
Lead Agency :	SAN DIEGO COUNTY LOP
File Location :	Local Agency
CUF Case :	NO
Caseworker :	EM
Case Type :	Cleanup Program Site
How Discovered :	N/R
How Discovered Description :	N/R
Stop Method :	N/R
Stop Description :	N/R
Calwater Watershed Name :	Carlsbad - San Marcos - Richland (904.52)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)
Disadvantaged Community :	Severely Disadvantaged Community
Latitude :	33.148396
Longitude :	-117.198244
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-11

Contacts Summary

Global ID :	T10000005844
Contact Name :	EWAN MOFFAT
Contact Type :	Local Agency Caseworker
Organization Name :	SAN DIEGO COUNTY LOP
Address :	P.O. Box 129261
City :	San Diego
Phone Number :	N/R
Email :	ewan.moffat@sdcounty.ca.gov

Regulatory Activities

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Map Id: K103
Direction: SW
Distance: 0.262 mi., 1384 ft.
Elevation: 584 ft.
Relative: Lower

Site Name : FORMER CONTINENTAL CLEANERS | RESOURCE ENVIRONMENTAL LLC TEXACO STATION | CONTINENTAL CLEANERS
109 SOUTH RANCHO SANTA FE ROAD | 105 S RANCHO SANTA FE RD | 109 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA 92078

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, FRS, HAZNET - CA, HWG - CA, RCRA_NONGEN, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 257305
EPA ID: CAL000238056

SLIC REG 9 - CA ***(cont.)***

Date :	2018-06-20
Global ID :	T10000005844
Action Type :	ENFORCEMENT
Action :	Closure/No Further Action Letter
Date :	2018-03-05
Global ID :	T10000005844
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other
Date :	2018-02-27
Global ID :	T10000005844
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other
Date :	2018-02-22
Global ID :	T10000005844
Action Type :	RESPONSE
Action :	Other Workplan - Regulator Responded
Date :	2017-12-06
Global ID :	T10000005844
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other
Date :	2017-11-28
Global ID :	T10000005844
Action Type :	ENFORCEMENT
Action :	Meeting
Date :	2017-08-14
Global ID :	T10000005844
Action Type :	RESPONSE
Action :	Soil Vapor Intrusion Investigation Report
Date :	2017-06-21
Global ID :	T10000005844
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other

Map Id: K103
Direction: SW
Distance: 0.262 mi., 1384 ft.
Elevation: 584 ft.
Relative: Lower

Site Name : FORMER CONTINENTAL CLEANERS | RESOURCE ENVIRONMENTAL LLC TEXACO STATION | CONTINENTAL CLEANERS
109 SOUTH RANCHO SANTA FE ROAD | 105 S RANCHO SANTA FE RD | 109 S RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA 92078

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, FRS, HAZNET - CA, HWG - CA, RCRA_NONGEN, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 257305
EPA ID: CAL000238056

SLIC REG 9 - CA ***(cont.)***

Date : 2017-06-07
Global ID : T10000005844
Action Type : RESPONSE
Action : Soil Vapor Intrusion Investigation Workplan - Regulator Responded

Date : 2017-05-11
Global ID : T10000005844
Action Type : ENFORCEMENT
Action : Meeting

Status History

Status Date : 2018-06-20
Global ID : T10000005844
Status : Completed - Case Closed

Status Date : 2014-04-16
Global ID : T10000005844
Status : Open - Site Assessment

Status Date : 2014-04-11
Global ID : T10000005844
Status : Open - Case Begin Date

Map Id: 104
Direction: ENE
Distance: 0.274 mi., 1447 ft.
Elevation: N/R
Relative: N/R

Site Name : N/R
33.179126, -117.200551
CA

Database(s) : [FIRE AREAS - CA]

Envirosite ID: 43294650
EPA ID: N/R

FIRE AREAS - CA

Year : 1970
Alarm Date : N/R
Containment Date : N/R
Fire Number : 00000000
Fire Name : N/R
Agency : CDF

Map Id: 104
Direction: ENE
Distance: 0.274 mi., 1447 ft.
Elevation: N/R
Relative: N/R

Site Name : N/R
33.179126, -117.200551
CA

Database(s) : [FIRE AREAS - CA] ***(cont.)***

Envirosite ID: 43294650
EPA ID: N/R

FIRE AREAS - CA ***(cont.)***

Unit ID :	MVU
INC Number :	00000000
Cause :	14
Estimated Area Cosumed Report :	N/R
GIS Acres :	1916.63916
Collection Method :	N/R
Objective :	1
Comments :	N/R
Last Date in Agency List :	2022-01-27

Map Id: 105
Direction: SSW
Distance: 0.294 mi., 1551 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : SAN MARCOS HDQTRS/DIVISION II | COUNTY OF SAN DIEGO DPW DIV II | DPW DIV II HEADQUARTERS
1579 OSAGE ST
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, RCRA_SQG]

Envirosite ID: 258431
EPA ID: N/R

CALEPA SITES - CA

Facility Name :	SAN MARCOS HDQTRS/DIVISION II
Facility Address :	1579 OSAGE ST, SAN MARCOS, 920692504
Site ID :	210778
EI ID :	T0607302697
EI Description :	Leaking Underground Storage Tank Cleanup Site
Latitude :	33.148398
Longitude :	-117.197650
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07

Site ID :	210778
EI ID :	T0607302282
EI Description :	Leaking Underground Storage Tank Cleanup Site
Latitude :	33.148398
Longitude :	-117.197650
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07

CASE LIST_SAN DIEGO COUNTY - CA

Facility Name :	SAN MARCOS HDQTRS/DIVISION II
Facility Address :	1579 OSAGE ST, SAN MARCOS, CA 920692504
County :	San Diego

Map Id: 105
Direction: SSW
Distance: 0.294 mi., 1551 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : SAN MARCOS HDQTRS/DIVISION II | COUNTY OF SAN DIEGO DPW DIV II | DPW DIV II HEADQUARTERS
1579 OSAGE ST
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, RCRA_SQG] ***(cont.)***

Envirosite ID: 258431
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Site Details

Status Date :	2011-07-06
Status :	Completed - Case Closed
Begin Date :	1999-05-14
Global ID :	T0607302697

Site History :

The Site is a maintenance/operations facility owned and operated by the County of San Diego. In May 1999, two USTs were removed and soil samples were collected and analyzed under the direction of DEH. Based on laboratory results, case H04814-002 was opened on July 8, 1999. A total of seven groundwater monitoring wells have been installed to investigate the petroleum release at this Site. The wells were monitored and sampled at various times between 2000 and 2009. The sampling events demonstrated that the benzene and MTBE dissolved plumes have not migrated offsite and are localized in the area of the former underground storage tank and dispensers. The consultant, by trend analysis, estimates that benzene in groundwater will reach MCLs by 2015. The consultant estimates that MTBE in groundwater will reach MCLs by 2022. TBA concentrations in some wells have increased due to the breakdown of MTBE; however the plume appears stable and the residual TBA will not adversely impact human health or the environment. DEH estimates that TBA will attenuate to action levels 10 years beyond the degradation of MTBE or by approximately 2032. The consultant estimates that the volume of petroleum hydrocarbon-impacted soil with Total Petroleum Hydrocarbon concentrations as gasoline above 100 mg/kg is approximately 35 cubic yards. A Corrective Action Plan was prepared and completed its public review period on June 4, 2010. The remedial action chosen was natural attenuation. Additionally, public notification was completed to adjacent property owners. No groundwater production wells are located on, adjacent to or within mile of the Site. The closest surface water body to the Site is approximately 1.14 miles. The residual petroleum hydrocarbons in soil and groundwater do not present a significant risk to human health or the environment. DEH concurs with the recommendation of No Further Action.

RB Case Number :	9UT3937
Potential Media Affected :	Aquifer used for drinking water supply
Potential Contaminants of Concern :	Gasoline
Local Agency :	SAN DIEGO COUNTY LOP
Local Case Number :	H04814-002
Lead Agency :	SAN DIEGO COUNTY LOP
File Location :	Local Agency
CUF Case :	YES
Caseworker :	JC
Case Type :	LUST Cleanup Site
How Discovered :	UST System Modification
How Discovered Description :	UST Mod
Stop Method :	Close and Replace Tank
Stop Description :	OTHER MEANS
Calwater Watershed Name :	Carlsbad - San Marcos - Richland (904.52)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)
Disadvantaged Community :	N/R
Latitude :	33.14752
Longitude :	-117.196661
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-09

Map Id: 105
Direction: SSW
Distance: 0.294 mi., 1551 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : SAN MARCOS HDQTRS/DIVISION II | COUNTY OF SAN DIEGO DPW DIV II | DPW DIV II HEADQUARTERS
1579 OSAGE ST
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, RCRA_SQG] ***(cont.)***

Envirosite ID: 258431
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Contacts Summary

Global ID :	T0607302697
Contact Name :	JAMES CLAY
Contact Type :	Local Agency Caseworker
Organization Name :	SAN DIEGO COUNTY LOP
Address :	P.O. Box 129261
City :	San Diego
Phone Number :	N/R
Email :	james.clay@sdcounty.ca.gov

Regulatory Activities

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Date :	2011-07-06
Global ID :	T0607302697
Action Type :	ENFORCEMENT
Action :	Closure/No Further Action Letter

Date :	2011-02-15
Global ID :	T0607302697
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other

Date :	2010-12-21
Global ID :	T0607302697
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other

Date :	2010-04-20
Global ID :	T0607302697
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other

Date :	2010-04-15
Global ID :	T0607302697
Action Type :	ENFORCEMENT
Action :	Notification - Public Notice of ROD/RAP/CAP

Date :	2010-04-08
Global ID :	T0607302697

Map Id: 105
Direction: SSW
Distance: 0.294 mi., 1551 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : SAN MARCOS HDQTRS/DIVISION II | COUNTY OF SAN DIEGO DPW DIV II | DPW DIV II HEADQUARTERS
1579 OSAGE ST
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, RCRA_SQG] ***(cont.)***

Envirosite ID: 258431
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Action Type : ENFORCEMENT
Action : Technical Correspondence / Assistance / Other

Date : 2009-07-14
Global ID : T0607302697
Action Type : ENFORCEMENT
Action : Letter - Notice

Date : 2009-03-16
Global ID : T0607302697
Action Type : RESPONSE
Action : Corrective Action Plan / Remedial Action Plan - Addendum

Date : 2008-12-23
Global ID : T0607302697
Action Type : ENFORCEMENT
Action : Notification - Public Notice of ROD/RAP/CAP

Date : 1999-07-08
Global ID : T0607302697
Action Type : ENFORCEMENT
Action : Notice of Responsibility

Status History

Status Date : 2011-07-06
Global ID : T0607302697
Status : Completed - Case Closed

Status Date : 2009-07-07
Global ID : T0607302697
Status : Completed - Case Closed

Status Date : 2009-07-07
Global ID : T0607302697
Status : Open - Site Assessment

Status Date : 2000-10-23
Global ID : T0607302697
Status : Open - Remediation

Map Id: 105
Direction: SSW
Distance: 0.294 mi., 1551 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : SAN MARCOS HDQTRS/DIVISION II | COUNTY OF SAN DIEGO DPW DIV II | DPW DIV II HEADQUARTERS
1579 OSAGE ST
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, RCRA_SQG] ***(cont.)***

Envirosite ID: 258431
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Status Date :	1999-05-14
Global ID :	T0607302697
Status :	Open - Case Begin Date

Site Details

Status Date :	2004-11-23
Status :	Completed - Case Closed
Begin Date :	1997-07-09
Global ID :	T0607302282
Site History :	N/R
RB Case Number :	9UT3514
Potential Media Affected :	Aquifer used for drinking water supply
Potential Contaminants of Concern :	Diesel
Local Agency :	SAN DIEGO COUNTY LOP
Local Case Number :	H04814-001
Lead Agency :	SAN DIEGO COUNTY LOP
File Location :	Local Agency
CUF Case :	NO
Caseworker :	JC
Case Type :	LUST Cleanup Site
How Discovered :	N/R
How Discovered Description :	N/R
Stop Method :	Close and Remove Tank
Stop Description :	CLOSE AND REMOVE TANK
Calwater Watershed Name :	Carlsbad - San Marcos - Richland (904.52)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)
Disadvantaged Community :	N/R
Latitude :	33.148398
Longitude :	-117.197651
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-09

Contacts Summary

Global ID :	T0607302282
Contact Name :	JAMES CLAY
Contact Type :	Local Agency Caseworker
Organization Name :	SAN DIEGO COUNTY LOP
Address :	P.O. Box 129261
City :	San Diego
Phone Number :	N/R
Email :	james.clay@sdcounty.ca.gov

Map Id: 105
Direction: SSW
Distance: 0.294 mi., 1551 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : SAN MARCOS HDQTRS/DIVISION II | COUNTY OF SAN DIEGO DPW DIV II | DPW DIV II HEADQUARTERS
1579 OSAGE ST
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, RCRA_SQG] ***(cont.)***

Envirosite ID: 258431
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Regulatory Activities

Date :	2004-11-23
Global ID :	T0607302282
Action Type :	ENFORCEMENT
Action :	Closure/No Further Action Letter
Date :	1997-08-01
Global ID :	T0607302282
Action Type :	ENFORCEMENT
Action :	Notice of Responsibility
Date :	1997-07-09
Global ID :	T0607302282
Action Type :	Other
Action :	Leak Discovery
Date :	1997-07-09
Global ID :	T0607302282
Action Type :	Other
Action :	Leak Began
Date :	1997-07-09
Global ID :	T0607302282
Action Type :	Other
Action :	Leak Stopped
Date :	1997-07-09
Global ID :	T0607302282
Action Type :	Other
Action :	Leak Reported

Status History

Status Date :	2004-11-23
Global ID :	T0607302282
Status :	Completed - Case Closed
Status Date :	1997-07-09
Global ID :	T0607302282
Status :	Open - Case Begin Date

Map Id: 105
Direction: SSW
Distance: 0.294 mi., 1551 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : SAN MARCOS HDQTRS/DIVISION II | COUNTY OF SAN DIEGO DPW DIV II | DPW DIV II HEADQUARTERS
1579 OSAGE ST
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, RCRA_SQG] ***(cont.)***

Envirosite ID: 258431
EPA ID: N/R

ECHO

Facility Name :	COUNTY OF SAN DIEGO DPW DIV II
Facility Address :	1579 OSAGE ST, SAN MARCOS, CA 92069
County :	SAN DIEGO
Last Inspection Date :	N/R
Registry ID :	110065076651
FIPS Code :	06073
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	_____
Collection Method :	ADDRESS MATCHING-HOUSE NUMBER
Reference Point :	CENTER OF A FACILITY OR STATION
Accuracy Meters :	30

Derived Tribes :

San Pasqual Band of Diegueno Mission Indians of California - 12.5 mile(s), Pala Band of Mission Indians - 13.4 mile (s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 14.2 mile(s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 16.4 mile(s), Pauma Band of Luiseno Mission Indians of the Pauma & Yuima Reservation, California - 17.1 mile(s), La Jolla Band of Luiseno Indians, California - 17.3 mile(s), Pechanga Band of Luiseno Mission Indians of the Pechanga Reservation, California - 20.6 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 22.5 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 22.9 mile(s), Mesa Grande Band of Diegueno Mission Indians of the Mesa Grande Reservation, California - 23.3 mile(s)

Derived HUC :	18070303
Derived WBD :	180703030503
Derived STCTY FIPS :	06073
Derived Zip :	92078
Derived CD113 :	50
Derived CB2010 :	060730200291001
MYRTK Universe :	NNN
NPDES IDs :	N/R
CWA Permit Types :	N/R
CWA Compliance Tracking :	N/R
CWA NAICS :	N/R

Map Id: 105
Direction: SSW
Distance: 0.294 mi., 1551 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : SAN MARCOS HDQTRS/DIVISION II | COUNTY OF SAN DIEGO DPW DIV II | DPW DIV II HEADQUARTERS
1579 OSAGE ST
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, RCRA_SQG] ***(cont.)***

Envirosite ID: 258431
EPA ID: N/R

ECHO ***(cont.)***

CWA SICS :	N/R
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	N/R
CWA Current Compliance Status :	N/R
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	N/R
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	N/R
Facility NAICS :	48849 - Other Support Activities for Road Transportation
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	Y
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	N
SDWIS Flag :	N
RCRA Flag :	Y
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	N/R
NAA Flag :	Y
Latitude :	33.14693
Longitude :	-117.19627
Last Date in Agency List :	2022-01-17

Facility Name :	DPW DIV II HEADQUARTERS
Facility Address :	1579 OSAGE ST, SAN MARCOS, CA 92069
County :	SAN DIEGO

Map Id: 105
Direction: SSW
Distance: 0.294 mi., 1551 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : SAN MARCOS HDQTRS/DIVISION II | COUNTY OF SAN DIEGO DPW DIV II | DPW DIV II HEADQUARTERS
1579 OSAGE ST
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, RCRA_SQG] ***(cont.)***

Envirosite ID: 258431
EPA ID: N/R

ECHO ***(cont.)***

Last Inspection Date :	N/R
Registry ID :	110046524631
FIPS Code :	06073
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	_____
Collection Method :	ADDRESS MATCHING-HOUSE NUMBER
Reference Point :	CENTER OF A FACILITY OR STATION
Accuracy Meters :	30

Derived Tribes :

San Pasqual Band of Diegueno Mission Indians of California - 12.5 mile(s), Pala Band of Mission Indians - 13.4 mile (s), Rincon Band of Luiseno Mission Indians of the Rincon Reservation, California - 14.2 mile(s), Rincon Band of Luiseno Mission Indians of the Rincon Reservation, California - 16.4 mile(s), Pauma Band of Luiseno Mission Indians of the Pauma & Yuima Reservation, California - 17.1 mile(s), La Jolla Band of Luiseno Indians, California - 17.3 mile (s), Pechanga Band of Luiseno Mission Indians of the Pechanga Reservation, California - 20.7 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 22.5 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 22.9 mile(s), Mesa Grande Band of Diegueno Mission Indians of the Mesa Grande Reservation, California - 23.3 mile(s)

Derived HUC :	18070303
Derived WBD :	180703030503
Derived STCTY FIPS :	06073
Derived Zip :	92078
Derived CD113 :	50
Derived CB2010 :	060730200291001
MYRTK Universe :	NNN
NPDES IDs :	N/R
CWA Permit Types :	N/R
CWA Compliance Tracking :	N/R
CWA NAICS :	N/R
CWA SICS :	N/R
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R

Map Id: 105
Direction: SSW
Distance: 0.294 mi., 1551 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : SAN MARCOS HDQTRS/DIVISION II | COUNTY OF SAN DIEGO DPW DIV II | DPW DIV II HEADQUARTERS
1579 OSAGE ST
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, RCRA_SQG] ***(cont.)***

Envirosite ID: 258431
EPA ID: N/R

ECHO ***(cont.)***

CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	N/R
CWA Current Compliance Status :	N/R
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	N/R
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	N/R
Facility NAICS :	23731 - Highway, Street, and Bridge Construction, 23411 - Highway and Street Construction
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	Y
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	N
SDWIS Flag :	N
RCRA Flag :	Y
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	Y
NAA Flag :	Y
Latitude :	33.14691
Longitude :	-117.19646
Last Date in Agency List :	2019-09-23
Facility Name :	SAN MARCOS HDQTRS/DIVISION II
Facility Address :	1579 OSAGE ST, SAN MARCOS, CA 92069
County :	SAN DIEGO

Map Id: 105
Direction: SSW
Distance: 0.294 mi., 1551 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : SAN MARCOS HDQTRS/DIVISION II | COUNTY OF SAN DIEGO DPW DIV II | DPW DIV II HEADQUARTERS
1579 OSAGE ST
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, RCRA_SQG] ***(cont.)***

Envirosite ID: 258431
EPA ID: N/R

ECHO ***(cont.)***

Last Inspection Date :	N/R
Registry ID :	110065076651
FIPS Code :	06073
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	_____
Collection Method :	ADDRESS MATCHING-HOUSE NUMBER
Reference Point :	CENTER OF A FACILITY OR STATION
Accuracy Meters :	30

Derived Tribes :

San Pasqual Band of Diegueno Mission Indians of California - 12.5 mile(s), Pala Band of Mission Indians - 13.4 mile (s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 14.2 mile(s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 16.4 mile(s), Pauma Band of Luiseno Mission Indians of the Pauma & Yuima Reservation, California - 17.1 mile(s), La Jolla Band of Luiseno Indians, California - 17.3 mile(s), Pechanga Band of Luiseno Mission Indians of the Pechanga Reservation, California - 20.6 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 22.5 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 22.9 mile(s), Mesa Grande Band of Diegueno Mission Indians of the Mesa Grande Reservation, California - 23.3 mile(s)

Derived HUC :	18070303
Derived WBD :	180703030503
Derived STCTY FIPS :	06073
Derived Zip :	92078
Derived CD113 :	50
Derived CB2010 :	060730200291001
MYRTK Universe :	NNN
NPDES IDs :	N/R
CWA Permit Types :	N/R
CWA Compliance Tracking :	N/R
CWA NAICS :	N/R
CWA SICS :	N/R
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R

Map Id: 105
Direction: SSW
Distance: 0.294 mi., 1551 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : SAN MARCOS HDQTRS/DIVISION II | COUNTY OF SAN DIEGO DPW DIV II | DPW DIV II HEADQUARTERS
1579 OSAGE ST
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, RCRA_SQG] ***(cont.)***

Envirosite ID: 258431
EPA ID: N/R

ECHO ***(cont.)***

CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	N/R
CWA Current Compliance Status :	N/R
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	N/R
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	N/R
Facility NAICS :	48849 - Other Support Activities for Road Transportation
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	Y
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	N
SDWIS Flag :	N
RCRA Flag :	Y
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	N/R
NAA Flag :	Y
Latitude :	33.14693
Longitude :	-117.19627
Last Date in Agency List :	2021-02-17

EPA LUST

Facility Name :	SAN MARCOS HDQTRS/DIVISION II
Facility Address :	1579 OSAGE ST, SAN MARCOS, California 920692504
County :	N/R
Facility ID :	N/R
LUST ID :	CAT0607302282
Reported Date :	N/R

Map Id: 105
Direction: SSW
Distance: 0.294 mi., 1551 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : SAN MARCOS HDQTRS/DIVISION II | COUNTY OF SAN DIEGO DPW DIV II | DPW DIV II HEADQUARTERS
1579 OSAGE ST
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, RCRA_SQG] ***(cont.)***

Envirosite ID: 258431
EPA ID: N/R

EPA LUST ***(cont.)***

Status :	No Further Action
Substance :	N/R
Closed With Residual Contamination (Tribal Only):	N/R
NFA_Letter (Tribal Only) :	N/R
Tribe (Tribal Only) :	N/R
EPA Region :	9
Estimated Population within 1500ft :	535
Estimated Private Domestic Wells within 1500ft:	0
Within Source Water Protection Area (SPA):	No
SPA Public Water System and Facility ID:	N/R
SPA Water Type :	N/R
SPA Facility Type :	N/R
SPA HUC12 :	N/R
Within Groundwater Wellhead Protection Area (WHPA):	No
WHPA Public Water System and Facility ID:	N/R
WHPA Water Type :	N/R
WHPA Facility Type :	N/R
WHPA HUC12 :	N/R
Within Estimated 100-year Floodplain:	No
Latitude :	33.147170000000003
Longitude :	-117.196939999999003
Last Date in Agency List :	2022-01-04

Facility ID :	N/R
LUST ID :	CAT0607302697
Reported Date :	N/R
Status :	No Further Action
Substance :	N/R
Closed With Residual Contamination (Tribal Only):	N/R
NFA_Letter (Tribal Only) :	N/R
Tribe (Tribal Only) :	N/R
EPA Region :	9
Estimated Population within 1500ft :	535
Estimated Private Domestic Wells within 1500ft:	0
Within Source Water Protection Area (SPA):	No
SPA Public Water System and Facility ID:	N/R
SPA Water Type :	N/R
SPA Facility Type :	N/R
SPA HUC12 :	N/R
Within Groundwater Wellhead Protection Area (WHPA):	No

Map Id: 105
Direction: SSW
Distance: 0.294 mi., 1551 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : SAN MARCOS HDQTRS/DIVISION II | COUNTY OF SAN DIEGO DPW DIV II | DPW DIV II HEADQUARTERS
1579 OSAGE ST
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, RCRA_SQG] ***(cont.)***

Envirosite ID: 258431
EPA ID: N/R

EPA LUST ***(cont.)***

WHPA Public Water System and Facility ID:	N/R
WHPA Water Type :	N/R
WHPA Facility Type :	N/R
WHPA HUC12 :	N/R
Within Estimated 100-year Floodplain:	No
Latitude :	33.147170000000003
Longitude :	-117.196939999999003
Last Date in Agency List :	2022-01-04

FRS

Facility Name :	COUNTY OF SAN DIEGO DPW DIV II
Facility Address :	1579 OSAGE ST, SAN MARCOS, CA 920692504
County :	SAN DIEGO

Site Details

Registry ID :	110065076651
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Source Description

Source Description :

The California Environmental Protection Agency (CalEPA) has recently implemented a new data warehouse system (nSite). This data warehouse combines and merges facility and site information from five different systems managed within CalEPA. The five systems are: California Environmental Reporting System (CERS), EnviroStor, GeoTracker, California Integrated Water Quality System (CIWQS), and Toxic Release Inventory (TRI).

Source Description :

RCRAInfo is EPA's comprehensive information system that supports the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984 through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA. RCRAInfo also supports generation of the National Hazardous Waste Biennial Report. All generators and treatment, storage, and disposal facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years to support creation of the Biennial Report.

FRS Environmental Interest

Source and System ID :	CA-ENVIROVIEW - 210778 RCRAINFO - CAP000222679

Map Id: 105
Direction: SSW
Distance: 0.294 mi., 1551 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : SAN MARCOS HDQTRS/DIVISION II | COUNTY OF SAN DIEGO DPW DIV II | DPW DIV II HEADQUARTERS
1579 OSAGE ST
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, RCRA_SQG] ***(cont.)***

Envirosite ID: 258431
EPA ID: N/R

FRS ***(cont.)***

Facility Name : SAN MARCOS HDQTRS/DIVISION II
Facility Address : 1579 OSAGE ST, SAN MARCOS, CA 920692504
County : SAN DIEGO

Site Details
Registry ID : 110065076651
FRS Facility URL : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2021-05-03

Source Description

Source Description :

The California Environmental Protection Agency (CalEPA) has recently implemented a new data warehouse system (nSite). This data warehouse combines and merges facility and site information from five different systems managed within CalEPA. The five systems are: California Environmental Reporting System (CERS), EnviroStor, GeoTracker, California Integrated Water Quality System (CIWQS), and Toxic Release Inventory (TRI).

Source Description :

RCRAInfo is EPA's comprehensive information system that supports the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984 through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA. RCRAInfo also supports generation of the National Hazardous Waste Biennial Report. All generators and treatment, storage, and disposal facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years to support creation of the Biennial Report.

FRS Environmental Interest
Source and System ID : CA-ENVIROVIEW - 210778
RCRAINFO - CAP000222679

HAZMAT_SAN DIEGO COUNTY - CA

Facility Name : CNTY OF SD SAN MARCOS RD STATION
Facility Address : 1579 OSAGE ST, SAN MARCOS, CA 92069

Date : 2002-11-04
Record ID : DEH2002-HUPFP-200955
Record Type : Unified Program Facility Permit
Status : Permit Renewed
Action : N/R

Map Id: 105
Direction: SSW
Distance: 0.294 mi., 1551 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : SAN MARCOS HDQTRS/DIVISION II | COUNTY OF SAN DIEGO DPW DIV II | DPW DIV II HEADQUARTERS
1579 OSAGE ST
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, RCRA_SQG] ***(cont.)***

Envirosite ID: 258431
EPA ID: N/R

HAZMAT_SAN DIEGO COUNTY - CA ***(cont.)***

Short Notes :	N/R
Last Date in Agency List :	2015-11-23
Facility Name :	SD CNTY FLEET OPERATIONS SAN MARCOS
Facility Address :	1579 OSAGE ST, SAN MARCOS, CA 92069
Date :	2002-05-04
Record ID :	DEH2002-HUPFP-104814
Record Type :	Unified Program Facility Permit
Status :	Permit Renewed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23

HAZNET - CA

Facility Name :	CNTY SAN DIEGO - DEPT PUBLIC WORKS
Facility Address :	1579 OSAGE ST, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000182993
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	5555 OVERLAND AVE, SAN DIEGO, CA 921231295
Latitude :	33.14740288
Longitude :	-117.19748784
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	2002: 352 - Other organic solids, 4 tons to CAT080033681 2000: 352 - Other organic solids, 3.25 tons to CAT080033681

HWG - CA

Facility Name :	CNTY SAN DIEGO - DEPT PUBLIC WORKS
Facility Address :	1579 OSAGE ST, SAN MARCOS, CA 92069
County :	SAN DIEGO

Map Id: 105
Direction: SSW
Distance: 0.294 mi., 1551 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : SAN MARCOS HDQTRS/DIVISION II | COUNTY OF SAN DIEGO DPW DIV II | DPW DIV II HEADQUARTERS
1579 OSAGE ST
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, RCRA_SQG] ***(cont.)***

Envirosite ID: 258431
EPA ID: N/R

HWG - CA ***(cont.)***

EPA ID :	CAL000182993
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	5555 OVERLAND AVE, SAN DIEGO, CA 921231295
Owner Name :	CNTY SAN DIEGO - DPW
Owner Address :	5555 OVERLAND AVE, SAN DIEGO, CA 921231295
Operator Name :	LARRY HORSMAN - CIVIL ENG
Operator Address :	5555 OVERLAND AVE, SAN DIEGO, CA 921231295
Latitude :	33.147067
Longitude :	-117.196695

LUST REG 9 - CA

Facility Name :	SAN MARCOS HDQTRS/DIVISION II
Facility Address :	1579 OSAGE ST, SAN MARCOS, CA 920692504
County :	San Diego

Site Details

Status Date :	2011-07-06
Status :	Completed - Case Closed
Begin Date :	1999-05-14
Global ID :	T0607302697
Region :	REGION 9

Site History :

The Site is a maintenance/operations facility owned and operated by the County of San Diego. In May 1999, two USTs were removed and soil samples were collected and analyzed under the direction of DEH. Based on laboratory results, case H04814-002 was opened on July 8, 1999. A total of seven groundwater monitoring wells have been installed to investigate the petroleum release at this Site. The wells were monitored and sampled at various times between 2000 and 2009. The sampling events demonstrated that the benzene and MTBE dissolved plumes have not migrated offsite and are localized in the area of the former underground storage tank and dispensers. The consultant, by trend analysis, estimates that benzene in groundwater will reach MCLs by 2015. The consultant estimates that MTBE in groundwater will reach MCLs by 2022. TBA concentrations in some wells have increased due to the breakdown of MTBE; however the plume appears stable and the residual TBA will not adversely impact human health or the environment. DEH estimates that TBA will attenuate to action levels 10 years beyond the degradation of MTBE or by approximately 2032. The consultant estimates that the volume of petroleum hydrocarbon-impacted soil with Total Petroleum Hydrocarbon concentrations as gasoline above 100 mg/kg is approximately 35 cubic yards. A Corrective Action Plan was prepared and completed its public review period on June 4, 2010. The remedial action chosen was natural attenuation. Additionally, public notification was completed to adjacent property owners. No groundwater production wells are located on, adjacent to or within mile of the Site. The closest surface water body to the Site is approximately 1.14 miles. The residual petroleum hydrocarbons in soil and groundwater do not present a significant risk to human health or the environment. DEH concurs with the recommendation of No Further Action.

RB Case Number : 9UT3937

Map Id: 105
Direction: SSW
Distance: 0.294 mi., 1551 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : SAN MARCOS HDQTRS/DIVISION II | COUNTY OF SAN DIEGO DPW DIV II | DPW DIV II HEADQUARTERS
1579 OSAGE ST
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, RCRA_SQG] ***(cont.)***

Envirosite ID: 258431
EPA ID: N/R

LUST REG 9 - CA ***(cont.)***

Potential Media Affected :	Aquifer used for drinking water supply
Potential Contaminants of Concern :	Gasoline
Local Agency :	SAN DIEGO COUNTY LOP
Local Case Number :	H04814-002
Lead Agency :	SAN DIEGO COUNTY LOP
File Location :	Local Agency
CUF Case :	YES
Caseworker :	JC
Case Type :	LUST Cleanup Site
How Discovered :	UST System Modification
How Discovered Description :	UST Mod
Stop Method :	Close and Replace Tank
Stop Description :	OTHER MEANS
Calwater Watershed Name :	Carlsbad - San Marcos - Richland (904.52)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)
Disadvantaged Community :	N/R
Latitude :	33.14752
Longitude :	-117.196661
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-11

Contacts Summary

Global ID :	T0607302697
Contact Name :	JAMES CLAY
Contact Type :	Local Agency Caseworker
Organization Name :	SAN DIEGO COUNTY LOP
Address :	P.O. Box 129261
City :	San Diego
Phone Number :	N/R
Email :	james.clay@sdcounty.ca.gov

Regulatory Activities

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Date :	2011-07-06
Global ID :	T0607302697
Action Type :	ENFORCEMENT
Action :	Closure/No Further Action Letter

Date :	2011-02-15
Global ID :	T0607302697
Action Type :	ENFORCEMENT

Map Id: 105
Direction: SSW
Distance: 0.294 mi., 1551 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : SAN MARCOS HDQTRS/DIVISION II | COUNTY OF SAN DIEGO DPW DIV II | DPW DIV II HEADQUARTERS
1579 OSAGE ST
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, RCRA_SQG] ***(cont.)***

Envirosite ID: 258431
EPA ID: N/R

LUST REG 9 - CA ***(cont.)***

Action : Technical Correspondence / Assistance / Other

Date : 2010-12-21
Global ID : T0607302697
Action Type : ENFORCEMENT
Action : Technical Correspondence / Assistance / Other

Date : 2010-04-20
Global ID : T0607302697
Action Type : ENFORCEMENT
Action : Technical Correspondence / Assistance / Other

Date : 2010-04-15
Global ID : T0607302697
Action Type : ENFORCEMENT
Action : Notification - Public Notice of ROD/RAP/CAP

Date : 2010-04-08
Global ID : T0607302697
Action Type : ENFORCEMENT
Action : Technical Correspondence / Assistance / Other

Date : 2009-07-14
Global ID : T0607302697
Action Type : ENFORCEMENT
Action : Letter - Notice

Date : 2009-03-16
Global ID : T0607302697
Action Type : RESPONSE
Action : Corrective Action Plan / Remedial Action Plan - Addendum

Date : 2008-12-23
Global ID : T0607302697
Action Type : ENFORCEMENT
Action : Notification - Public Notice of ROD/RAP/CAP

Date : 1999-07-08
Global ID : T0607302697
Action Type : ENFORCEMENT
Action : Notice of Responsibility

Map Id: 105
Direction: SSW
Distance: 0.294 mi., 1551 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : SAN MARCOS HDQTRS/DIVISION II | COUNTY OF SAN DIEGO DPW DIV II | DPW DIV II HEADQUARTERS
1579 OSAGE ST
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, RCRA_SQG] ***(cont.)***

Envirosite ID: 258431
EPA ID: N/R

LUST REG 9 - CA ***(cont.)***

Status History

Status Date :	2011-07-06
Global ID :	T0607302697
Status :	Completed - Case Closed
Status Date :	2009-07-07
Global ID :	T0607302697
Status :	Completed - Case Closed
Status Date :	2009-07-07
Global ID :	T0607302697
Status :	Open - Site Assessment
Status Date :	2000-10-23
Global ID :	T0607302697
Status :	Open - Remediation
Status Date :	1999-05-14
Global ID :	T0607302697
Status :	Open - Case Begin Date

Site Details

Status Date :	2004-11-23
Status :	Completed - Case Closed
Begin Date :	1997-07-09
Global ID :	T0607302282
Region :	REGION 9
Site History :	N/R
RB Case Number :	9UT3514
Potential Media Affected :	Aquifer used for drinking water supply
Potential Contaminants of Concern :	Diesel
Local Agency :	SAN DIEGO COUNTY LOP
Local Case Number :	H04814-001
Lead Agency :	SAN DIEGO COUNTY LOP
File Location :	Local Agency
CUF Case :	NO
Caseworker :	JC
Case Type :	LUST Cleanup Site
How Discovered :	N/R
How Discovered Description :	N/R
Stop Method :	Close and Remove Tank
Stop Description :	CLOSE AND REMOVE TANK
Calwater Watershed Name :	Carlsbad - San Marcos - Richland (904.52)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)

Map Id: 105
Direction: SSW
Distance: 0.294 mi., 1551 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : SAN MARCOS HDQTRS/DIVISION II | COUNTY OF SAN DIEGO DPW DIV II | DPW DIV II HEADQUARTERS
1579 OSAGE ST
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, RCRA_SQG] ***(cont.)***

Envirosite ID: 258431
EPA ID: N/R

LUST REG 9 - CA ***(cont.)***

Disadvantaged Community :	N/R
Latitude :	33.148398
Longitude :	-117.197651
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-11

Contacts Summary

Global ID :	T0607302282
Contact Name :	JAMES CLAY
Contact Type :	Local Agency Caseworker
Organization Name :	SAN DIEGO COUNTY LOP
Address :	P.O. Box 129261
City :	San Diego
Phone Number :	N/R
Email :	james.clay@sdcounty.ca.gov

Regulatory Activities

Date :	2004-11-23
Global ID :	T0607302282
Action Type :	ENFORCEMENT
Action :	Closure/No Further Action Letter

Date :	1997-08-01
Global ID :	T0607302282
Action Type :	ENFORCEMENT
Action :	Notice of Responsibility

Date :	1997-07-09
Global ID :	T0607302282
Action Type :	Other
Action :	Leak Discovery

Date :	1997-07-09
Global ID :	T0607302282
Action Type :	Other
Action :	Leak Began

Date :	1997-07-09
Global ID :	T0607302282
Action Type :	Other
Action :	Leak Stopped

Map Id: 105
Direction: SSW
Distance: 0.294 mi., 1551 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : SAN MARCOS HDQTRS/DIVISION II | COUNTY OF SAN DIEGO DPW DIV II | DPW DIV II HEADQUARTERS
1579 OSAGE ST
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, RCRA_SQG] ***(cont.)***

Envirosite ID: 258431
EPA ID: N/R

LUST REG 9 - CA ***(cont.)***

Date :	1997-07-09
Global ID :	T0607302282
Action Type :	Other
Action :	Leak Reported

Status History

Status Date :	2004-11-23
Global ID :	T0607302282
Status :	Completed - Case Closed

Status Date :	1997-07-09
Global ID :	T0607302282
Status :	Open - Case Begin Date

RCRA_SQG

Facility Name :	DPW DIV II HEADQUARTERS
Facility Address :	1579 OSAGE ST, SAN MARCOS, CA 92069
County :	SAN DIEGO
Date Form Received by Agency :	2012-08-27
EPA ID :	CAR000228247
Mailing Address :	5510 OVERLAND AVE STE 410, SAN DIEGO, CA 92123
Contact :	ERIC JONES
Contact Address :	5510 OVERLAND AVE STE 410, SAN DIEGO, CA 92123
Contact Country :	US
Contact Telephone :	858-694-3880
Contact Email :	ERIC.JONES@SDCOUNTY.CA.GOV
EPA Region :	09
Land Type :	County
Source Type :	Notification
Classification :	Small Quantity Generator
Description :	Handlers that generate more than 100 and less than 1000 kilograms of hazardous waste during any calendar month and accumulate less than 6000 kg of hazardous waste at any time; or generate 100 kg or less of hazardous waste during any calendar month, and accumulate more than 1000 kg of hazardous waste at any time.
Last Date in Agency List :	2022-01-25

Owner/Operator Summary

Owner/Operator Name :	CNTY OF SAN DIEGO PUBLIC WORKS
Owner/Operator Address :	5510 OVERLAND AVE STE 410, SAN DIEGO, CA 92123

Map Id: 105
Direction: SSW
Distance: 0.294 mi., 1551 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : SAN MARCOS HDQTRS/DIVISION II | COUNTY OF SAN DIEGO DPW DIV II | DPW DIV II HEADQUARTERS
1579 OSAGE ST
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, RCRA_SQG] ***(cont.)***

Envirosite ID: 258431
EPA ID: N/R

RCRA_SQG ***(cont.)***

Owner/Operator Country :	US
Owner/Operator Telephone :	N/R
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	County
Owner/Operator Type :	Owner
Owner/Operator Start Date :	1960-01-01
Owner/Operator End Date :	N/R

Owner/Operator Name :	DPW
Owner/Operator Address :	N/R
Owner/Operator Country :	US
Owner/Operator Telephone :	N/R
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	County
Owner/Operator Type :	Operator
Owner/Operator Start Date :	1960-01-01
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Hazardous Waste Summary

Waste Code / Name :	181 - Other inorganic solid waste D008 - LEAD

Map Id: 105
Direction: SSW
Distance: 0.294 mi., 1551 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : SAN MARCOS HDQTRS/DIVISION II | COUNTY OF SAN DIEGO DPW DIV II | DPW DIV II HEADQUARTERS
1579 OSAGE ST
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, RCRA_SQG] ***(cont.)***

Envirosite ID: 258431
EPA ID: N/R

RCRA_SQG ***(cont.)***

Notices of Violations Summary
Regulation Violated : N

Map Id: N106
Direction: ESE
Distance: 0.369 mi., 1948 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : PIONEER MILLS | 1X PIONEER MILLS
1329 W MISSION RD | 1329 WEST MISSION ROAD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST HAZNET - CA, HWG - CA, LUST REG 9 - CA]

Envirosite ID: 258147
EPA ID: N/R

CALEPA SITES - CA

Facility Name : PIONEER MILLS
Facility Address : 1329 W MISSION RD, SAN MARCOS, 920691311

Site ID : 195573
EI ID : T0607300032
EI Description : Leaking Underground Storage Tank Cleanup Site
Latitude : 33.148857
Longitude : -117.190059
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-01-07

CASE LIST_SAN DIEGO COUNTY - CA

Facility Name : PIONEER MILLS
Facility Address : 1329 W MISSION RD, SAN MARCOS, CA 920691311
County : San Diego

Site Details
Status Date : 1993-02-12
Status : Completed - Case Closed
Begin Date : 1988-06-28
Global ID : T0607300032
Site History : N/R
RB Case Number : 9UT1010
Potential Media Affected : N/R

Map Id: N106
Direction: ESE
Distance: 0.369 mi., 1948 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : PIONEER MILLS | 1X PIONEER MILLS
1329 W MISSION RD | 1329 WEST MISSION ROAD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST HAZNET - CA, HWG - CA, LUST REG 9 - CA] ***(cont.)***

Envirosite ID: 258147
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Potential Contaminants of Concern :	N/R
Local Agency :	N/R
Local Case Number :	H02919-001
Lead Agency :	SAN DIEGO COUNTY LOP
File Location :	Local Agency
CUF Case :	YES
Caseworker :	N/R
Case Type :	LUST Cleanup Site
How Discovered :	N/R
How Discovered Description :	N/R
Stop Method :	N/R
Stop Description :	N/R
Calwater Watershed Name :	Carlsbad - San Marcos - Richland (904.52)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)
Disadvantaged Community :	N/R
Latitude :	33.148857
Longitude :	-117.19006
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-09

Contacts Summary

Global ID :	T0607300032
Contact Name :	N/R
Contact Type :	N/R
Organization Name :	N/R
Address :	N/R
City :	N/R
Phone Number :	N/R
Email :	N/R

Regulatory Activities

Date :	1993-02-12
Global ID :	T0607300032
Action Type :	ENFORCEMENT
Action :	Closure/No Further Action Letter

Date :	1988-07-12
Global ID :	T0607300032
Action Type :	ENFORCEMENT
Action :	Notice of Responsibility

Status History

Status Date :	1993-02-12
Global ID :	T0607300032

Map Id: N106
Direction: ESE
Distance: 0.369 mi., 1948 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : PIONEER MILLS | 1X PIONEER MILLS
1329 W MISSION RD | 1329 WEST MISSION ROAD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST HAZNET - CA, HWG - CA, LUST REG 9 - CA] ***(cont.)***

Envirosite ID: 258147
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Status :	Completed - Case Closed
Status Date :	1988-06-28
Global ID :	T0607300032
Status :	Open - Case Begin Date

EPA LUST

Facility Name :	PIONEER MILLS
Facility Address :	1329 W MISSION RD, SAN MARCOS, California 920691311
County :	N/R
Facility ID :	N/R
LUST ID :	CAT0607300032
Reported Date :	N/R
Status :	No Further Action
Substance :	N/R
Closed With Residual Contamination (Tribal Only):	N/R
NFA_Letter (Tribal Only) :	N/R
Tribe (Tribal Only) :	N/R
EPA Region :	9
Estimated Population within 1500ft :	360
Estimated Private Domestic Wells within 1500ft:	0
Within Source Water Protection Area (SPA):	No
SPA Public Water System and Facility ID:	N/R
SPA Water Type :	N/R
SPA Facility Type :	N/R
SPA HUC12 :	N/R
Within Groundwater Wellhead Protection Area (WHPA):	No
WHPA Public Water System and Facility ID:	N/R
WHPA Water Type :	N/R
WHPA Facility Type :	N/R
WHPA HUC12 :	N/R
Within Estimated 100-year Floodplain:	No
Latitude :	33.148460000000000
Longitude :	-117.189260000000004
Last Date in Agency List :	2022-01-04

FRS

Facility Name :	PIONEER MILLS
Facility Address :	1329 W MISSION RD, SAN MARCOS, CA 920691311
County :	SAN DIEGO

Map Id: N106
Direction: ESE
Distance: 0.369 mi., 1948 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : PIONEER MILLS | 1X PIONEER MILLS
1329 W MISSION RD | 1329 WEST MISSION ROAD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST HAZNET - CA, HWG - CA, LUST REG 9 - CA] ***(cont.)***

Envirosite ID: 258147
EPA ID: N/R

FRS ***(cont.)***

Site Details

Registry ID :	110066636554
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Source Description

Source Description :

The California Environmental Protection Agency (CalEPA) has recently implemented a new data warehouse system (nSite). This data warehouse combines and merges facility and site information from five different systems managed within CalEPA. The five systems are: California Environmental Reporting System (CERS), EnviroStor, GeoTracker, California Integrated Water Quality System (CIWQS), and Toxic Release Inventory (TRI).

FRS Environmental Interest

Source and System ID :	CA-ENVIROVIEW - 195573

HAZMAT_SAN DIEGO COUNTY - CA

Facility Name :	PIONEER MILLS
Facility Address :	1329 W MISSION RD, SAN MARCOS, CA 92069
Date :	2002-05-04
Record ID :	DEH2002-HUPFP-102919
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23

HAZNET - CA

Facility Name :	1X PIONEER MILLS
Facility Address :	1329 WEST MISSION ROAD, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAC000097237
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R

Map Id: N106
Direction: ESE
Distance: 0.369 mi., 1948 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : PIONEER MILLS | 1X PIONEER MILLS
1329 W MISSION RD | 1329 WEST MISSION ROAD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST HAZNET - CA, HWG - CA, LUST REG 9 - CA] ***(cont.)***

Envirosite ID: 258147
EPA ID: N/R

HAZNET - CA ***(cont.)***

Facility Mailing Address :	P.O. BOX 218, SAN MARCOS, CA 920690000
Latitude :	33.14842648
Longitude :	-117.18917370
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HIST HAZNET - CA

Facility Name :	1X PIONEER MILLS
Facility Address :	1329 WEST MISSION ROAD, SAN MARCOS, 92069
ID Number :	CAC000097237
Last Date in Agency List :	2014-11-17

HWG - CA

Facility Name :	1X PIONEER MILLS
Facility Address :	1329 WEST MISSION ROAD, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAC000097237
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	P.O. BOX 218, SAN MARCOS, CA 920690000
Owner Name :	UNDERGROUND TANK REMOVAL
Owner Address :	N/A
Operator Name :	WARREN KRUM, PRES.
Operator Address :	N/A
Latitude :	33.148695
Longitude :	-117.189502

LUST REG 9 - CA

Facility Name :	PIONEER MILLS
Facility Address :	1329 W MISSION RD, SAN MARCOS, CA 920691311
County :	San Diego

Site Details

Status Date :	1993-02-12
Status :	Completed - Case Closed
Begin Date :	1988-06-28
Global ID :	T0607300032
Region :	REGION 9
Site History :	N/R
RB Case Number :	9UT1010

Map Id: N106
Direction: ESE
Distance: 0.369 mi., 1948 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : PIONEER MILLS | 1X PIONEER MILLS
1329 W MISSION RD | 1329 WEST MISSION ROAD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST HAZNET - CA, HWG - CA, LUST REG 9 - CA] ***(cont.)***

Envirosite ID: 258147
EPA ID: N/R

LUST REG 9 - CA ***(cont.)***

Potential Media Affected :	N/R
Potential Contaminants of Concern :	N/R
Local Agency :	N/R
Local Case Number :	H02919-001
Lead Agency :	SAN DIEGO COUNTY LOP
File Location :	Local Agency
CUF Case :	YES
Caseworker :	N/R
Case Type :	LUST Cleanup Site
How Discovered :	N/R
How Discovered Description :	N/R
Stop Method :	N/R
Stop Description :	N/R
Calwater Watershed Name :	Carlsbad - San Marcos - Richland (904.52)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)
Disadvantaged Community :	N/R
Latitude :	33.148857
Longitude :	-117.19006
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-11

Contacts Summary

Global ID :	T0607300032
Contact Name :	N/R
Contact Type :	N/R
Organization Name :	N/R
Address :	N/R
City :	N/R
Phone Number :	N/R
Email :	N/R

Regulatory Activities

Date :	1993-02-12
Global ID :	T0607300032
Action Type :	ENFORCEMENT
Action :	Closure/No Further Action Letter

Date :	1988-07-12
Global ID :	T0607300032
Action Type :	ENFORCEMENT
Action :	Notice of Responsibility

Map Id: N106
Direction: ESE
Distance: 0.369 mi., 1948 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : PIONEER MILLS | 1X PIONEER MILLS
1329 W MISSION RD | 1329 WEST MISSION ROAD
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST HAZNET - CA, HWG - CA, LUST REG 9 - CA] ***(cont.)***

Envirosite ID: 258147
EPA ID: N/R

LUST REG 9 - CA ***(cont.)***

Status History

Status Date :	1993-02-12
Global ID :	T0607300032
Status :	Completed - Case Closed
Status Date :	1988-06-28
Global ID :	T0607300032
Status :	Open - Case Begin Date

Map Id: O107
Direction: SE
Distance: 0.392 mi., 2069 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : EDCO WASTE & RECYCLING SERVICE | 1X SOLID WASTE SVC | EDCO CONSTRUCTION DEMOLOTION INERT RECYCLING FACILITY
224 S LAS POSAS RD | 224 LAS POSAS ROAD
SAN MARCOS | San Marcos, CA

Database(s) : [CASE LIST_SAN DIEGO COUNTY - CA, CHMIRS - CA, DEBRIS EPA SWRCY, EPA LUST, HAZNET - CA, HWG - CA, LF_SAN DIEGO COUNTY - CA, LUST REG 9 - CA, SLIC REG 9 - CA]

Envirosite ID: 303817
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA

Facility Name :	EDCO WASTE & RECYCLING SERVICE
Facility Address :	224 S LAS POSAS RD, SAN MARCOS, CA 920691423
County :	San Diego

Site Details

Status Date :	1992-09-16
Status :	Completed - Case Closed
Begin Date :	1991-12-18
Global ID :	T0608184522
Site History :	N/R
RB Case Number :	N/R
Potential Media Affected :	N/R
Potential Contaminants of Concern :	N/R
Local Agency :	N/R
Local Case Number :	H10646-002
Lead Agency :	SAN DIEGO COUNTY LOP

Map Id: O107
Direction: SE
Distance: 0.392 mi., 2069 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : EDCO WASTE & RECYCLING SERVICE | 1X SOLID WASTE SVC | EDCO CONSTRUCTION DEMOLOTION INERT RECYCLING FACILITY
224 S LAS POSAS RD | 224 LAS POSAS ROAD
SAN MARCOS | San Marcos, CA

Database(s) : [CASE LIST_SAN DIEGO COUNTY - CA, CHMIRS - CA, DEBRIS EPA SWRCY, EPA LUST, HAZNET - CA, HWG - CA, LF_SAN DIEGO COUNTY - CA, LUST REG 9 - CA, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 303817
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

File Location :	Local Agency
CUF Case :	NO
Caseworker :	N/R
Case Type :	Cleanup Program Site
How Discovered :	N/R
How Discovered Description :	N/R
Stop Method :	N/R
Stop Description :	N/R
Calwater Watershed Name :	Carlsbad - San Marcos - Richland (904.52)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)
Disadvantaged Community :	N/R
Latitude :	33.141628
Longitude :	-117.193864
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-09

Contacts Summary

Global ID :	T0608184522
Contact Name :	N/R
Contact Type :	N/R
Organization Name :	N/R
Address :	N/R
City :	N/R
Phone Number :	N/R
Email :	N/R

Regulatory Activities

Date :	N/R
Global ID :	T0608184522
Action Type :	N/R
Action :	N/R

Status History

Status Date :	1992-09-16
Global ID :	T0608184522
Status :	Completed - Case Closed

Status Date :	1991-12-18
Global ID :	T0608184522
Status :	Open - Case Begin Date

Map Id: O107
Direction: SE
Distance: 0.392 mi., 2069 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : EDCO WASTE & RECYCLING SERVICE | 1X SOLID WASTE SVC | EDCO CONSTRUCTION DEMOLOTION INERT RECYCLING FACILITY
224 S LAS POSAS RD | 224 LAS POSAS ROAD
SAN MARCOS | San Marcos, CA

Database(s) : [CASE LIST_SAN DIEGO COUNTY - CA, CHMIRS - CA, DEBRIS EPA SWRCY, EPA LUST, HAZNET - CA, HWG - CA, LF_SAN DIEGO COUNTY - CA, LUST REG 9 - CA, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 303817
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Site Details

Status Date :	1998-02-11
Status :	Completed - Case Closed
Begin Date :	1992-09-09
Global ID :	T0607301051
Site History :	N/R
RB Case Number :	9UT2285
Potential Media Affected :	Aquifer used for drinking water supply
Potential Contaminants of Concern :	Waste Oil / Motor / Hydraulic / Lubricating
Local Agency :	N/R
Local Case Number :	H10646-003
Lead Agency :	SAN DIEGO COUNTY LOP
File Location :	Local Agency
CUF Case :	YES
Caseworker :	N/R
Case Type :	LUST Cleanup Site
How Discovered :	N/R
How Discovered Description :	N/R
Stop Method :	N/R
Stop Description :	N/R
Calwater Watershed Name :	Carlsbad - San Marcos - Richland (904.52)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)
Disadvantaged Community :	N/R
Latitude :	33.141628
Longitude :	-117.193864
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-09

Contacts Summary

Global ID :	T0607301051
Contact Name :	N/R
Contact Type :	N/R
Organization Name :	N/R
Address :	N/R
City :	N/R
Phone Number :	N/R
Email :	N/R

Regulatory Activities

Date :	1998-01-16
Global ID :	T0607301051
Action Type :	ENFORCEMENT
Action :	Closure/No Further Action Letter - #H10646-003

Map Id: O107
Direction: SE
Distance: 0.392 mi., 2069 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : EDCO WASTE & RECYCLING SERVICE | 1X SOLID WASTE SVC | EDCO CONSTRUCTION DEMOLOTION INERT RECYCLING FACILITY
224 S LAS POSAS RD | 224 LAS POSAS ROAD
SAN MARCOS | San Marcos, CA

Database(s) : [CASE LIST_SAN DIEGO COUNTY - CA, CHMIRS - CA, DEBRIS EPA SWRCY, EPA LUST, HAZNET - CA, HWG - CA, LF_SAN DIEGO COUNTY - CA, LUST REG 9 - CA, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 303817
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Date : 1992-09-28
Global ID : T0607301051
Action Type : ENFORCEMENT
Action : Notice of Responsibility

Date : 1992-09-09
Global ID : T0607301051
Action Type : Other
Action : Leak Began

Date : 1992-09-09
Global ID : T0607301051
Action Type : Other
Action : Leak Reported

Date : 1992-09-09
Global ID : T0607301051
Action Type : Other
Action : Leak Stopped

Date : 1992-09-09
Global ID : T0607301051
Action Type : Other
Action : Leak Discovery

Status History
Status Date : 1998-02-11
Global ID : T0607301051
Status : Completed - Case Closed

Status Date : 1992-09-09
Global ID : T0607301051
Status : Open - Case Begin Date

Site Details
Status Date : 2009-01-21
Status : Completed - Case Closed
Begin Date : 1998-09-09
Global ID : T0607302493

Map Id: O107
Direction: SE
Distance: 0.392 mi., 2069 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : EDCO WASTE & RECYCLING SERVICE | 1X SOLID WASTE SVC | EDCO CONSTRUCTION DEMOLOTION INERT RECYCLING FACILITY
224 S LAS POSAS RD | 224 LAS POSAS ROAD
SAN MARCOS | San Marcos, CA

Database(s) : [CASE LIST_SAN DIEGO COUNTY - CA, CHMIRS - CA, DEBRIS EPA SWRCY, EPA LUST, HAZNET - CA, HWG - CA, LF_SAN DIEGO COUNTY - CA, LUST REG 9 - CA, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 303817
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Site History :	N/R
RB Case Number :	9UT3726
Potential Media Affected :	Aquifer used for drinking water supply
Potential Contaminants of Concern :	Diesel
Local Agency :	N/R
Local Case Number :	H10646-004
Lead Agency :	SAN DIEGO COUNTY LOP
File Location :	Local Agency
CUF Case :	NO
Caseworker :	N/R
Case Type :	LUST Cleanup Site
How Discovered :	N/R
How Discovered Description :	N/R
Stop Method :	Other Means
Stop Description :	OTHER MEANS
Calwater Watershed Name :	Carlsbad - San Marcos - Richland (904.52)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)
Disadvantaged Community :	N/R
Latitude :	33.14199
Longitude :	-117.194659
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-09

Contacts Summary

Global ID :	T0607302493
Contact Name :	N/R
Contact Type :	N/R
Organization Name :	N/R
Address :	N/R
City :	N/R
Phone Number :	N/R
Email :	N/R

Regulatory Activities

Date :	2008-12-24
Global ID :	T0607302493
Action Type :	ENFORCEMENT
Action :	Closure/No Further Action Letter

Date :	2008-10-01
Global ID :	T0607302493
Action Type :	ENFORCEMENT
Action :	Notification - Public Notice of ROD/RAP/CAP

Map Id: O107
Direction: SE
Distance: 0.392 mi., 2069 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : EDCO WASTE & RECYCLING SERVICE | 1X SOLID WASTE SVC | EDCO CONSTRUCTION DEMOLOTION INERT RECYCLING FACILITY
224 S LAS POSAS RD | 224 LAS POSAS ROAD
SAN MARCOS | San Marcos, CA

Database(s) : [CASE LIST_SAN DIEGO COUNTY - CA, CHMIRS - CA, DEBRIS EPA SWRCY, EPA LUST, HAZNET - CA, HWG - CA, LF_SAN DIEGO COUNTY - CA, LUST REG 9 - CA, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 303817
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Date : 1998-09-30
Global ID : T0607302493
Action Type : ENFORCEMENT
Action : Notice of Responsibility

Date : 1998-09-09
Global ID : T0607302493
Action Type : Other
Action : Leak Began

Date : 1998-09-09
Global ID : T0607302493
Action Type : Other
Action : Leak Discovery

Date : 1998-09-09
Global ID : T0607302493
Action Type : Other
Action : Leak Reported

Date : 1998-09-09
Global ID : T0607302493
Action Type : Other
Action : Leak Stopped

Status History

Status Date : 2009-01-21
Global ID : T0607302493
Status : Completed - Case Closed

Status Date : 1999-01-01
Global ID : T0607302493
Status : Open - Remediation

Status Date : 1998-09-09
Global ID : T0607302493
Status : Open - Case Begin Date

Map Id: O107
Direction: SE
Distance: 0.392 mi., 2069 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : EDCO WASTE & RECYCLING SERVICE | 1X SOLID WASTE SVC | EDCO CONSTRUCTION DEMOLOTION INERT RECYCLING FACILITY
224 S LAS POSAS RD | 224 LAS POSAS ROAD
SAN MARCOS | San Marcos, CA

Database(s) : [CASE LIST_SAN DIEGO COUNTY - CA, CHMIRS - CA, DEBRIS EPA SWRCY, EPA LUST, HAZNET - CA, HWG - CA, LF_SAN DIEGO COUNTY - CA, LUST REG 9 - CA, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 303817
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Site Details

Status Date :	1998-02-11
Status :	Completed - Case Closed
Begin Date :	1989-05-18
Global ID :	T0607300258
Site History :	N/R
RB Case Number :	9UT1425
Potential Media Affected :	Aquifer used for drinking water supply
Potential Contaminants of Concern :	Waste Oil / Motor / Hydraulic / Lubricating
Local Agency :	N/R
Local Case Number :	H10646-001
Lead Agency :	SAN DIEGO COUNTY LOP
File Location :	Local Agency
CUF Case :	NO
Caseworker :	N/R
Case Type :	LUST Cleanup Site
How Discovered :	N/R
How Discovered Description :	N/R
Stop Method :	N/R
Stop Description :	N/R
Calwater Watershed Name :	Carlsbad - San Marcos - Richland (904.52)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)
Disadvantaged Community :	N/R
Latitude :	33.141628
Longitude :	-117.193864
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-09

Contacts Summary

Global ID :	T0607300258
Contact Name :	N/R
Contact Type :	N/R
Organization Name :	N/R
Address :	N/R
City :	N/R
Phone Number :	N/R
Email :	N/R

Regulatory Activities

Date :	1998-02-11
Global ID :	T0607300258
Action Type :	ENFORCEMENT
Action :	Closure/No Further Action Letter

Map Id: O107
Direction: SE
Distance: 0.392 mi., 2069 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : EDCO WASTE & RECYCLING SERVICE | 1X SOLID WASTE SVC | EDCO CONSTRUCTION DEMOLOTION INERT RECYCLING FACILITY
224 S LAS POSAS RD | 224 LAS POSAS ROAD
SAN MARCOS | San Marcos, CA

Database(s) : [CASE LIST_SAN DIEGO COUNTY - CA, CHMIRS - CA, DEBRIS EPA SWRCY, EPA LUST, HAZNET - CA, HWG - CA, LF_SAN DIEGO COUNTY - CA, LUST REG 9 - CA, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 303817
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Date : 1998-01-16
Global ID : T0607300258
Action Type : ENFORCEMENT
Action : Closure/No Further Action Letter - #H10646-001

Date : 1989-05-22
Global ID : T0607300258
Action Type : ENFORCEMENT
Action : Notice of Responsibility

Date : 1989-05-18
Global ID : T0607300258
Action Type : Other
Action : Leak Reported

Date : 1989-05-18
Global ID : T0607300258
Action Type : Other
Action : Leak Discovery

Date : 1989-05-18
Global ID : T0607300258
Action Type : Other
Action : Leak Stopped

Date : 1989-05-18
Global ID : T0607300258
Action Type : Other
Action : Leak Began

Status History

Status Date : 1998-02-11
Global ID : T0607300258
Status : Completed - Case Closed

Status Date : 1989-05-18
Global ID : T0607300258
Status : Open - Case Begin Date

Map Id: O107
Direction: SE
Distance: 0.392 mi., 2069 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : EDCO WASTE & RECYCLING SERVICE | 1X SOLID WASTE SVC | EDCO CONSTRUCTION DEMOLOTION INERT RECYCLING FACILITY
224 S LAS POSAS RD | 224 LAS POSAS ROAD
SAN MARCOS | San Marcos, CA

Database(s) : [CASE LIST_SAN DIEGO COUNTY - CA, CHMIRS - CA, DEBRIS EPA SWRCY, EPA LUST, HAZNET - CA, HWG - CA, LF_SAN DIEGO COUNTY - CA, LUST REG 9 - CA, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 303817
EPA ID: N/R

CHMIRS - CA

Facility Address :	224 Las Posas Road, San Marcos
County :	San Diego County
Notified Date :	2019-12-16 14:31:00
Spill Representative :	City of San Marcos
Control Number :	19-8024
Substance 1 :	Fluid, hydraulic
Quantity 1 :	400
Measure 1 :	Gal(s)
Type 1 :	PETROLEUM
Pipeline 1 :	No
Vessel 1 (300 Tons) :	No
Substance 2 :	Foam, fire suppression
Quantity 2 :	15,000
Measure 2 :	Gal(s)
Type 2 :	CHEMICAL
Pipeline 2 :	No
Vessel 2 (300 Tons) :	No
Substance 3 :	N/R
Quantity 3 :	N/R
Measure 3 :	N/R
Type 3 :	N/R
Pipeline 3 :	No
Vessel 3 (300 Tons) :	No

Description :

Historical Report Four parked garbage trucks caught fire at a waste and recycling service center. The San Marcos Fire Department responded to the site. The incident resulted in less than 200 gallons of hydraulic fluid being released from the vehicles. During the fire fighting efforts, personnel dispensed an estimated 15,000 gallons of fire suppression foam. An undetermined amount of the mixed material entered a storm drain that leads to a dry channel. The fire was extinguished and no injuries were reported. The cause of the fire is under investigation. The cleanup was completed by the business owner. ***Historical Report***

Contained :	Stopped,Not contained
Water? :	Yes
Water Way :	Channel (dry)
Drinking Water Impacted :	No
Known Impact :	Unknown
Incident Date :	2019-11-30
Time :	03:40:00
Spill Site :	Merchant/Business
Site :	Channel (dry)
Cause :	Unknown
Other Causes :	N/R
Injuries (Y/N) :	No
Injuries Number :	N/R

Map Id: O107
Direction: SE
Distance: 0.392 mi., 2069 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : EDCO WASTE & RECYCLING SERVICE | 1X SOLID WASTE SVC | EDCO CONSTRUCTION DEMOLOTION INERT RECYCLING FACILITY
224 S LAS POSAS RD | 224 LAS POSAS ROAD
SAN MARCOS | San Marcos, CA

Database(s) : [CASE LIST_SAN DIEGO COUNTY - CA, CHMIRS - CA, DEBRIS EPA SWRCY, EPA LUST, HAZNET - CA, HWG - CA, LF_SAN DIEGO COUNTY - CA, LUST REG 9 - CA, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 303817
EPA ID: N/R

CHMIRS - CA ***(cont.)***

Fatal (Y/N) :	No
Fatal Number :	N/R
Evacs (Y/N) :	No
Evacs Number :	N/R
Cleanup :	Reporting Party
Admin Agency :	San Diego County Health Services Department
Last Date in Agency List :	2020-01-30

DEBRIS EPA SWRCY

Facility Name :	EDCO CDI Recycling
Facility Address :	224 Las Posas Rd, San Marcos, CA 92078
Phone :	760-744-2700
Region :	9
Recovery :	Yes
Landfill :	No
C D :	No
Composting :	No
Demolition :	No
Electronic :	No
HHW :	No
Metals :	No
Tires :	No
Transfer Station :	Yes
Vehicles :	No
LF C D :	No
LF HW :	No
LF MSW :	No
Latitude :	33.140723
Longitude :	-117.192809
Last Date in Agency List :	2022-02-02

EPA LUST

Facility Name :	EDCO WASTE & RECYCLING SERVICE
Facility Address :	224 S LAS POSAS RD, SAN MARCOS, California 920691423
County :	N/R
Facility ID :	N/R
LUST ID :	CAT0607302493
Reported Date :	N/R
Status :	No Further Action
Substance :	N/R
Closed With Residual Contamination (Tribal Only):	N/R

Map Id: O107
Direction: SE
Distance: 0.392 mi., 2069 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : EDCO WASTE & RECYCLING SERVICE | 1X SOLID WASTE SVC | EDCO CONSTRUCTION DEMOLOTION INERT RECYCLING FACILITY
224 S LAS POSAS RD | 224 LAS POSAS ROAD
SAN MARCOS | San Marcos, CA

Database(s) : [CASE LIST_SAN DIEGO COUNTY - CA, CHMIRS - CA, DEBRIS EPA SWRCY, EPA LUST, HAZNET - CA, HWG - CA, LF_SAN DIEGO COUNTY - CA, LUST REG 9 - CA, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 303817
EPA ID: N/R

EPA LUST ***(cont.)***

NFA_Letter (Tribal Only) :	N/R
Tribe (Tribal Only) :	N/R
EPA Region :	9
Estimated Population within 1500ft :	17
Estimated Private Domestic Wells within 1500ft:	0
Within Source Water Protection Area (SPA):	No
SPA Public Water System and Facility ID:	N/R
SPA Water Type :	N/R
SPA Facility Type :	N/R
SPA HUC12 :	N/R
Within Groundwater Wellhead Protection Area (WHPA):	No
WHPA Public Water System and Facility ID:	N/R
WHPA Water Type :	N/R
WHPA Facility Type :	N/R
WHPA HUC12 :	N/R
Within Estimated 100-year Floodplain:	No
Latitude :	33.142200000000003
Longitude :	-117.192089999998998
Last Date in Agency List :	2022-01-04

Facility ID :	N/R
LUST ID :	CAT0607300258
Reported Date :	N/R
Status :	No Further Action
Substance :	N/R
Closed With Residual Contamination (Tribal Only):	N/R
NFA_Letter (Tribal Only) :	N/R
Tribe (Tribal Only) :	N/R
EPA Region :	9
Estimated Population within 1500ft :	17
Estimated Private Domestic Wells within 1500ft:	0
Within Source Water Protection Area (SPA):	No
SPA Public Water System and Facility ID:	N/R
SPA Water Type :	N/R
SPA Facility Type :	N/R
SPA HUC12 :	N/R
Within Groundwater Wellhead Protection Area (WHPA):	No
WHPA Public Water System and Facility ID:	N/R

Map Id: O107
Direction: SE
Distance: 0.392 mi., 2069 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : EDCO WASTE & RECYCLING SERVICE | 1X SOLID WASTE SVC | EDCO CONSTRUCTION DEMOLOTION INERT RECYCLING FACILITY
224 S LAS POSAS RD | 224 LAS POSAS ROAD
SAN MARCOS | San Marcos, CA

Database(s) : [CASE LIST_SAN DIEGO COUNTY - CA, CHMIRS - CA, DEBRIS EPA SWRCY, EPA LUST, HAZNET - CA, HWG - CA, LF_SAN DIEGO COUNTY - CA, LUST REG 9 - CA, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 303817
EPA ID: N/R

EPA LUST ***(cont.)***

WHPA Water Type :	N/R
WHPA Facility Type :	N/R
WHPA HUC12 :	N/R
Within Estimated 100-year Floodplain:	No
Latitude :	33.142200000000003
Longitude :	-117.192089999998998
Last Date in Agency List :	2022-01-04
Facility ID :	N/R
LUST ID :	CAT0607301051
Reported Date :	N/R
Status :	No Further Action
Substance :	N/R
Closed With Residual Contamination (Tribal Only):	N/R
NFA_Letter (Tribal Only) :	N/R
Tribe (Tribal Only) :	N/R
EPA Region :	9
Estimated Population within 1500ft :	17
Estimated Private Domestic Wells within 1500ft:	0
Within Source Water Protection Area (SPA):	No
SPA Public Water System and Facility ID:	N/R
SPA Water Type :	N/R
SPA Facility Type :	N/R
SPA HUC12 :	N/R
Within Groundwater Wellhead Protection Area (WHPA):	No
WHPA Public Water System and Facility ID:	N/R
WHPA Water Type :	N/R
WHPA Facility Type :	N/R
WHPA HUC12 :	N/R
Within Estimated 100-year Floodplain:	No
Latitude :	33.142200000000003
Longitude :	-117.192089999998998
Last Date in Agency List :	2022-01-04

HAZNET - CA

Facility Name :	1X SOLID WASTE SVC
Facility Address :	224 S LAS POSAS RD, SAN MARCOS, CA 92069
County :	SAN DIEGO

Map Id: O107
Direction: SE
Distance: 0.392 mi., 2069 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : EDCO WASTE & RECYCLING SERVICE | 1X SOLID WASTE SVC | EDCO CONSTRUCTION DEMOLOTION INERT RECYCLING FACILITY
224 S LAS POSAS RD | 224 LAS POSAS ROAD
SAN MARCOS | San Marcos, CA

Database(s) : [CASE LIST_SAN DIEGO COUNTY - CA, CHMIRS - CA, DEBRIS EPA SWRCY, EPA LUST, HAZNET - CA, HWG - CA, LF_SAN DIEGO COUNTY - CA, LUST REG 9 - CA, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 303817
EPA ID: N/R

HAZNET - CA ***(cont.)***

Site Details

Generator EPA ID :	CAC000815264
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	P.O. BOX 6907, SAN MARCOS, CA 920790000
Latitude :	33.14219712
Longitude :	-117.19208863
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HWG - CA

Facility Name :	1X SOLID WASTE SVC
Facility Address :	224 S LAS POSAS RD, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAC000815264
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	P.O. BOX 6907, SAN MARCOS, CA 920790000
Owner Name :	SOLID WASTE SVC
Owner Address :	N/A
Operator Name :	JOHN FRASER/MANAGER
Operator Address :	N/A
Latitude :	33.142238
Longitude :	-117.192025

LF_SAN DIEGO COUNTY - CA

Facility Name :	EDCO CONSTRUCTION DEMOLOTION INERT RECYCLING FACILITY
Facility Address :	224 LAS POSAS ROAD, SAN MARCOS
Est Number :	DEH2004-CLEA-186315
SWIS Number :	37-AA-0953
Type of Operation :	CDI PROCESSING
Operation Status :	ACTIVE
Inspection Frequency :	MONTHLY
Activity Code :	J17
Insp Code :	N/R
Permit Fees :	N/R

Map Id: O107
Direction: SE
Distance: 0.392 mi., 2069 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : EDCO WASTE & RECYCLING SERVICE | 1X SOLID WASTE SVC | EDCO CONSTRUCTION DEMOLOTION INERT RECYCLING FACILITY
224 S LAS POSAS RD | 224 LAS POSAS ROAD
SAN MARCOS | San Marcos, CA

Database(s) : [CASE LIST_SAN DIEGO COUNTY - CA, CHMIRS - CA, DEBRIS EPA SWRCY, EPA LUST, HAZNET - CA, HWG - CA, LF_SAN DIEGO COUNTY - CA, LUST REG 9 - CA, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 303817
EPA ID: N/R

LF_SAN DIEGO COUNTY - CA ***(cont.)***

Owner :	FEDERAL BOULEVARD PROPERTIES
Operator :	EDCO WASTE AND RECYCLING INC
Permit Tier :	REGISTRATION
Latitude :	33.14166
Longitude :	-117.19386
Last Date in Agency List :	2021-01-29

LUST REG 9 - CA

Facility Name :	EDCO WASTE & RECYCLING SERVICE
Facility Address :	224 S LAS POSAS RD, SAN MARCOS, CA 920691423
County :	San Diego

Site Details

Status Date :	1998-02-11
Status :	Completed - Case Closed
Begin Date :	1992-09-09
Global ID :	T0607301051
Region :	REGION 9
Site History :	N/R
RB Case Number :	9UT2285
Potential Media Affected :	Aquifer used for drinking water supply
Potential Contaminants of Concern :	Waste Oil / Motor / Hydraulic / Lubricating
Local Agency :	N/R
Local Case Number :	H10646-003
Lead Agency :	SAN DIEGO COUNTY LOP
File Location :	Local Agency
CUF Case :	YES
Caseworker :	N/R
Case Type :	LUST Cleanup Site
How Discovered :	N/R
How Discovered Description :	N/R
Stop Method :	N/R
Stop Description :	N/R
Calwater Watershed Name :	Carlsbad - San Marcos - Richland (904.52)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)
Disadvantaged Community :	N/R
Latitude :	33.141628
Longitude :	-117.193864
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-11

Map Id: O107
Direction: SE
Distance: 0.392 mi., 2069 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : EDCO WASTE & RECYCLING SERVICE | 1X SOLID WASTE SVC | EDCO CONSTRUCTION DEMOLOTION INERT RECYCLING FACILITY
224 S LAS POSAS RD | 224 LAS POSAS ROAD
SAN MARCOS | San Marcos, CA

Database(s) : [CASE LIST_SAN DIEGO COUNTY - CA, CHMIRS - CA, DEBRIS EPA SWRCY, EPA LUST, HAZNET - CA, HWG - CA, LF_SAN DIEGO COUNTY - CA, LUST REG 9 - CA, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 303817
EPA ID: N/R

LUST REG 9 - CA ***(cont.)***

Contacts Summary

Global ID :	T0607301051
Contact Name :	N/R
Contact Type :	N/R
Organization Name :	N/R
Address :	N/R
City :	N/R
Phone Number :	N/R
Email :	N/R

Regulatory Activities

Date :	1998-01-16
Global ID :	T0607301051
Action Type :	ENFORCEMENT
Action :	Closure/No Further Action Letter - #H10646-003

Date :	1992-09-28
Global ID :	T0607301051
Action Type :	ENFORCEMENT
Action :	Notice of Responsibility

Date :	1992-09-09
Global ID :	T0607301051
Action Type :	Other
Action :	Leak Began

Date :	1992-09-09
Global ID :	T0607301051
Action Type :	Other
Action :	Leak Reported

Date :	1992-09-09
Global ID :	T0607301051
Action Type :	Other
Action :	Leak Stopped

Date :	1992-09-09
Global ID :	T0607301051
Action Type :	Other
Action :	Leak Discovery

Map Id: O107
Direction: SE
Distance: 0.392 mi., 2069 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : EDCO WASTE & RECYCLING SERVICE | 1X SOLID WASTE SVC | EDCO CONSTRUCTION DEMOLOTION INERT RECYCLING FACILITY
224 S LAS POSAS RD | 224 LAS POSAS ROAD
SAN MARCOS | San Marcos, CA

Database(s) : [CASE LIST_SAN DIEGO COUNTY - CA, CHMIRS - CA, DEBRIS EPA SWRCY, EPA LUST, HAZNET - CA, HWG - CA, LF_SAN DIEGO COUNTY - CA, LUST REG 9 - CA, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 303817
EPA ID: N/R

LUST REG 9 - CA ***(cont.)***

Status History

Status Date :	1998-02-11
Global ID :	T0607301051
Status :	Completed - Case Closed
Status Date :	1992-09-09
Global ID :	T0607301051
Status :	Open - Case Begin Date

Site Details

Status Date :	2009-01-21
Status :	Completed - Case Closed
Begin Date :	1998-09-09
Global ID :	T0607302493
Region :	REGION 9
Site History :	N/R
RB Case Number :	9UT3726
Potential Media Affected :	Aquifer used for drinking water supply
Potential Contaminants of Concern :	Diesel
Local Agency :	N/R
Local Case Number :	H10646-004
Lead Agency :	SAN DIEGO COUNTY LOP
File Location :	Local Agency
CUF Case :	NO
Caseworker :	N/R
Case Type :	LUST Cleanup Site
How Discovered :	N/R
How Discovered Description :	N/R
Stop Method :	Other Means
Stop Description :	OTHER MEANS
Calwater Watershed Name :	Carlsbad - San Marcos - Richland (904.52)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)
Disadvantaged Community :	N/R
Latitude :	33.14199
Longitude :	-117.194659
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-11

Contacts Summary

Global ID :	T0607302493
Contact Name :	N/R
Contact Type :	N/R
Organization Name :	N/R

Map Id: O107
Direction: SE
Distance: 0.392 mi., 2069 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : EDCO WASTE & RECYCLING SERVICE | 1X SOLID WASTE SVC | EDCO CONSTRUCTION DEMOLOTION INERT RECYCLING FACILITY
224 S LAS POSAS RD | 224 LAS POSAS ROAD
SAN MARCOS | San Marcos, CA

Database(s) : [CASE LIST_SAN DIEGO COUNTY - CA, CHMIRS - CA, DEBRIS EPA SWRCY, EPA LUST, HAZNET - CA, HWG - CA, LF_SAN DIEGO COUNTY - CA, LUST REG 9 - CA, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 303817
EPA ID: N/R

LUST REG 9 - CA ***(cont.)***

Address :	N/R
City :	N/R
Phone Number :	N/R
Email :	N/R

Regulatory Activities

Date :	2008-12-24
Global ID :	T0607302493
Action Type :	ENFORCEMENT
Action :	Closure/No Further Action Letter
Date :	2008-10-01
Global ID :	T0607302493
Action Type :	ENFORCEMENT
Action :	Notification - Public Notice of ROD/RAP/CAP
Date :	1998-09-30
Global ID :	T0607302493
Action Type :	ENFORCEMENT
Action :	Notice of Responsibility
Date :	1998-09-09
Global ID :	T0607302493
Action Type :	Other
Action :	Leak Began
Date :	1998-09-09
Global ID :	T0607302493
Action Type :	Other
Action :	Leak Discovery
Date :	1998-09-09
Global ID :	T0607302493
Action Type :	Other
Action :	Leak Reported
Date :	1998-09-09
Global ID :	T0607302493
Action Type :	Other
Action :	Leak Stopped

Map Id: O107
Direction: SE
Distance: 0.392 mi., 2069 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : EDCO WASTE & RECYCLING SERVICE | 1X SOLID WASTE SVC | EDCO CONSTRUCTION DEMOLOTION INERT RECYCLING FACILITY
224 S LAS POSAS RD | 224 LAS POSAS ROAD
SAN MARCOS | San Marcos, CA

Database(s) : [CASE LIST_SAN DIEGO COUNTY - CA, CHMIRS - CA, DEBRIS EPA SWRCY, EPA LUST, HAZNET - CA, HWG - CA, LF_SAN DIEGO COUNTY - CA, LUST REG 9 - CA, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 303817
EPA ID: N/R

LUST REG 9 - CA ***(cont.)***

Status History

Status Date :	2009-01-21
Global ID :	T0607302493
Status :	Completed - Case Closed
Status Date :	1999-01-01
Global ID :	T0607302493
Status :	Open - Remediation
Status Date :	1998-09-09
Global ID :	T0607302493
Status :	Open - Case Begin Date

Site Details

Status Date :	1998-02-11
Status :	Completed - Case Closed
Begin Date :	1989-05-18
Global ID :	T0607300258
Region :	REGION 9
Site History :	N/R
RB Case Number :	9UT1425
Potential Media Affected :	Aquifer used for drinking water supply
Potential Contaminants of Concern :	Waste Oil / Motor / Hydraulic / Lubricating
Local Agency :	N/R
Local Case Number :	H10646-001
Lead Agency :	SAN DIEGO COUNTY LOP
File Location :	Local Agency
CUF Case :	NO
Caseworker :	N/R
Case Type :	LUST Cleanup Site
How Discovered :	N/R
How Discovered Description :	N/R
Stop Method :	N/R
Stop Description :	N/R
Calwater Watershed Name :	Carlsbad - San Marcos - Richland (904.52)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)
Disadvantaged Community :	N/R
Latitude :	33.141628
Longitude :	-117.193864
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-11

Map Id: O107
Direction: SE
Distance: 0.392 mi., 2069 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : EDCO WASTE & RECYCLING SERVICE | 1X SOLID WASTE SVC | EDCO CONSTRUCTION DEMOLOTION INERT RECYCLING FACILITY
224 S LAS POSAS RD | 224 LAS POSAS ROAD
SAN MARCOS | San Marcos, CA

Database(s) : [CASE LIST_SAN DIEGO COUNTY - CA, CHMIRS - CA, DEBRIS EPA SWRCY, EPA LUST, HAZNET - CA, HWG - CA, LF_SAN DIEGO COUNTY - CA, LUST REG 9 - CA, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 303817
EPA ID: N/R

LUST REG 9 - CA ***(cont.)***

Contacts Summary

Global ID :	T0607300258
Contact Name :	N/R
Contact Type :	N/R
Organization Name :	N/R
Address :	N/R
City :	N/R
Phone Number :	N/R
Email :	N/R

Regulatory Activities

Date :	1998-02-11
Global ID :	T0607300258
Action Type :	ENFORCEMENT
Action :	Closure/No Further Action Letter
Date :	1998-01-16
Global ID :	T0607300258
Action Type :	ENFORCEMENT
Action :	Closure/No Further Action Letter - #H10646-001
Date :	1989-05-22
Global ID :	T0607300258
Action Type :	ENFORCEMENT
Action :	Notice of Responsibility
Date :	1989-05-18
Global ID :	T0607300258
Action Type :	Other
Action :	Leak Reported
Date :	1989-05-18
Global ID :	T0607300258
Action Type :	Other
Action :	Leak Discovery
Date :	1989-05-18
Global ID :	T0607300258
Action Type :	Other
Action :	Leak Stopped

Map Id: O107
Direction: SE
Distance: 0.392 mi., 2069 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : EDCO WASTE & RECYCLING SERVICE | 1X SOLID WASTE SVC | EDCO CONSTRUCTION DEMOLOTION INERT RECYCLING FACILITY
224 S LAS POSAS RD | 224 LAS POSAS ROAD
SAN MARCOS | San Marcos, CA

Database(s) : [CASE LIST_SAN DIEGO COUNTY - CA, CHMIRS - CA, DEBRIS EPA SWRCY, EPA LUST, HAZNET - CA, HWG - CA, LF_SAN DIEGO COUNTY - CA, LUST REG 9 - CA, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 303817
EPA ID: N/R

LUST REG 9 - CA ***(cont.)***

Date :	1989-05-18
Global ID :	T0607300258
Action Type :	Other
Action :	Leak Began

Status History

Status Date :	1998-02-11
Global ID :	T0607300258
Status :	Completed - Case Closed

Status Date :	1989-05-18
Global ID :	T0607300258
Status :	Open - Case Begin Date

SLIC REG 9 - CA

Facility Name :	EDCO WASTE & RECYCLING SERVICE
Facility Address :	224 S LAS POSAS RD, SAN MARCOS, CA 920691423
County :	San Diego

Site Details

Status Date :	1992-09-16
Status :	Completed - Case Closed
Begin Date :	1991-12-18
Global ID :	T0608184522
Region :	REGION 9
Site History :	N/R
RB Case Number :	N/R
Potential Media Affected :	N/R
Potential Contaminants of Concern :	N/R
Local Agency :	N/R
Local Case Number :	H10646-002
Lead Agency :	SAN DIEGO COUNTY LOP
File Location :	Local Agency
CUF Case :	NO
Caseworker :	N/R
Case Type :	Cleanup Program Site
How Discovered :	N/R
How Discovered Description :	N/R
Stop Method :	N/R
Stop Description :	N/R
Calwater Watershed Name :	Carlsbad - San Marcos - Richland (904.52)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)

Map Id: O107
Direction: SE
Distance: 0.392 mi., 2069 ft.
Elevation: 571 ft.
Relative: Lower

Site Name : EDCO WASTE & RECYCLING SERVICE | 1X SOLID WASTE SVC | EDCO CONSTRUCTION DEMOLOTION INERT RECYCLING FACILITY
224 S LAS POSAS RD | 224 LAS POSAS ROAD
SAN MARCOS | San Marcos, CA

Database(s) : [CASE LIST_SAN DIEGO COUNTY - CA, CHMIRS - CA, DEBRIS EPA SWRCY, EPA LUST, HAZNET - CA, HWG - CA, LF_SAN DIEGO COUNTY - CA, LUST REG 9 - CA, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 303817
EPA ID: N/R

SLIC REG 9 - CA ***(cont.)***

Disadvantaged Community :	N/R
Latitude :	33.141628
Longitude :	-117.193864
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-11

Contacts Summary

Global ID :	T0608184522
Contact Name :	N/R
Contact Type :	N/R
Organization Name :	N/R
Address :	N/R
City :	N/R
Phone Number :	N/R
Email :	N/R

Regulatory Activities

Date :	N/R
Global ID :	T0608184522
Action Type :	N/R
Action :	N/R

Status History

Status Date :	1992-09-16
Global ID :	T0608184522
Status :	Completed - Case Closed

Status Date :	1991-12-18
Global ID :	T0608184522
Status :	Open - Case Begin Date

Map Id: 108
Direction: SW
Distance: 0.419 mi., 2213 ft.
Elevation: 591 ft.
Relative: Higher

Site Name : AUTOZONE #5723
195 RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA

Database(s) : [ECHO, FRS, SWRCY - CA]

Envirosite ID: 44661466
EPA ID: N/R

ECHO

Facility Name :	AUTOZONE #5723
Facility Address :	195 RANCHO SANTA FE RD, SAN MARCOS, CA 92078
County :	SAN DIEGO
Last Inspection Date :	N/R
Registry ID :	110017959360
FIPS Code :	06073
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	_____
Collection Method :	ADDRESS MATCHING-HOUSE NUMBER
Reference Point :	CENTER OF A FACILITY OR STATION
Accuracy Meters :	30

Derived Tribes :

San Pasqual Band of Diegueno Mission Indians of California - 12.7 mile(s), Pala Band of Mission Indians - 13.6 mile (s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 14.4 mile(s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 16.6 mile(s), Pauma Band of Luiseno Mission Indians of the Pauma & Yuima Reservation, California - 17.2 mile(s), La Jolla Band of Luiseno Indians, California - 17.5 mile(s), Pechanga Band of Luiseno Mission Indians of the Pechanga Reservation, California - 20.8 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 22.7 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 23 mile(s), Mesa Grande Band of Diegueno Mission Indians of the Mesa Grande Reservation, California - 23.5 mile(s)

Derived HUC :	18070303
Derived WBD :	180703030503
Derived STCTY FIPS :	06073
Derived Zip :	92078
Derived CD113 :	50
Derived CB2010 :	060730200291006
MYRTK Universe :	NNN
NPDES IDs :	N/R
CWA Permit Types :	N/R
CWA Compliance Tracking :	N/R
CWA NAICS :	N/R
CWA SICS :	N/R
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R

Map Id: 108
Direction: SW
Distance: 0.419 mi., 2213 ft.
Elevation: 591 ft.
Relative: Higher

Site Name : AUTOZONE #5723
195 RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA

Database(s) : [ECHO, FRS, SWRCY - CA] ***(cont.)***

Envirosite ID: 44661466
EPA ID: N/R

ECHO ***(cont.)***

CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	N/R
CWA Current Compliance Status :	N/R
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	N/R
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	N/R
Facility NAICS :	45299 - All Other General Merchandise Stores
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	Y
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	N
SDWIS Flag :	N
RCRA Flag :	Y
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	Y
NAA Flag :	Y
Latitude :	33.14644
Longitude :	-117.20008
Last Date in Agency List :	2022-01-17

FRS

Facility Name :	AUTOZONE #5723
Facility Address :	195 RANCHO SANTA FE RD, SAN MARCOS, CA 92078-2501
County :	SAN DIEGO

Site Details

Registry ID :	110017959360
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Source Description

Map Id: 108
Direction: SW
Distance: 0.419 mi., 2213 ft.
Elevation: 591 ft.
Relative: Higher

Site Name : AUTOZONE #5723
195 RANCHO SANTA FE RD
SAN MARCOS | San Marcos, CA

Database(s) : [ECHO, FRS, SWRCY - CA] ***(cont.)***

Envirosite ID: 44661466
EPA ID: N/R

FRS ***(cont.)***

Source Description : The California Environmental Reporting System (CERS) is a statewide web-based user and information exchange system to support over 140,000 regulated businesses and over 130 local agencies in electronically collecting and reporting significant hazardous materials, hazardous waste and compliance and enforcement data as mandated by California law. Under oversight by Cal/EPA, certified local governing agencies (Unified Program Agencies - UPAs) consolidate, coordinate and provide consistent regulatory activities for six state and federal environmental programs.
The California Environmental Protection Agency (CalEPA) has recently implemented a new data warehouse system (nSite). This data warehouse combines and merges facility and site information from five different systems managed within CalEPA. The five systems are: California Environmental Reporting System (CERS), EnviroStor, GeoTracker, California Integrated Water Quality System (CIWQS), and Toxic Release Inventory (TRI).

Source Description : RCRAInfo is EPA's comprehensive information system that supports the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984 through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA. RCRAInfo also supports generation of the National Hazardous Waste Biennial Report. All generators and treatment, storage, and disposal facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years to support creation of the Biennial Report.
The UORS is managed by the California Waste Management Board (CIWMB). The CIWMB helps communities establish and promote convenient collection opportunities for used oil and used oil filters.

FRS Environmental Interest
Source and System ID : CA-CERS - 10140023
CA-ENVIROVIEW - 96582
CERTIFICATION APPLICATION - 37-C-04919
RCRAINFO - CAL000148027

SWRCY - CA

Facility Name : AutoZone #5723
Facility Address : 195 Rancho Santa Fe Rd, San Marcos, 92078
County : N/R

Site Details
ID Number : N/R
Activity Categories : N/R
Activities : N/R
Phone Number : (760) 752-1734
Type : UsedOil
Last Date in Agency List : 2022-02-16

Map Id: O109
Direction: SE
Distance: 0.419 mi., 2213 ft.
Elevation: 562 ft.
Relative: Lower

Site Name : TORREY CHEMICAL CO | GR ENTERPRISE INC
217 LAS POSAS RD
SAN MARCOS, CA

Database(s) : [CERCLIS NFRAP, ENVIROSTOR - CA, FRS, FTTS INSP, HIST CORTESE - CA, SEMS_8R_ARCHIVED SITES]

Envirosite ID: 222767
EPA ID: N/R

CERCLIS NFRAP

Facility Name :	TORREY CHEMICAL CO
Facility Address :	217 LAS POSAS RD, SAN MARCOS, CA 92069
County :	SAN DIEGO
Site ID :	0902600
Epa ID :	CAD982360430
Short Name :	TORREY CHEMICAL CO
Congressional District :	43
IFMS ID :	N/R
SMSA Number :	7320
USGC Hydro Unit :	18070303
Federal Facility :	N
DMNSN Number :	N/R
Site Orphan Flag :	N
RCRA ID :	N/R
USGS Quadrangle :	N/R
Site Init by Prog :	N/R
NFRAP Flag :	NFA
Parent ID :	N/R
RST Code :	N/R
EPA Region :	09
Classification :	N/R
Site Settings Code :	N/R
NPL Status :	Not on the NPL
DMNSN Unit Code :	N/R
RBRAC Code :	N/R
RResp Fed Agency Code :	N/R
Non NPL Status :	NFRAP-Site does not qualify for the NPL based on existing information
Non NPL Status Date :	1991-03-19
Site Fips Code :	06073
CC Concurrence Date :	N/R
CC Concurrence FY :	N/R
Alias EPA ID :	N/R
Site FUDS Flag :	N/R

CERCLIS Site Contact Name(s)

Contact ID :	13003854
Contact Title :	Site Assessment Manager (SAM)
Contact ID :	13003858
Contact Title :	Site Assessment Manager (SAM)
Contact ID :	13004003
Contact Title :	Site Assessment Manager (SAM)
Alias Comments :	N/R
Site Description :	N/R

Map Id: O109
Direction: SE
Distance: 0.419 mi., 2213 ft.
Elevation: 562 ft.
Relative: Lower

Site Name : TORREY CHEMICAL CO | GR ENTERPRISE INC
217 LAS POSAS RD
SAN MARCOS, CA

Database(s) : [CERCLIS NFRAP, ENVIROSTOR - CA, FRS, FTTS INSP, HIST CORTESE - CA, SEMS_8R_ARCHIVED SITES] ***(cont.)***

Envirosite ID: 222767
EPA ID: N/R

CERCLIS NFRAP ***(cont.)***

CERCLIS Assessment History

Action Code :	001
Action :	PRELIMINARY ASSESSMENT
Date Started :	N/R
Date Completed :	1991-03-19
Priority Level :	1
Operational Unit :	00
Primary Responsibility :	EPA Fund-Financed
Planning Status :	N/R
Urgency Indicator :	N/R
Action Anomaly :	N/R

Action Code :	001
Action :	DISCOVERY
Date Started :	N/R
Date Completed :	1987-11-01
Priority Level :	1
Operational Unit :	00
Primary Responsibility :	State, Fund Financed
Planning Status :	N/R
Urgency Indicator :	N/R
Action Anomaly :	N/R

Action Code :	001
Action :	ARCHIVE SITE
Date Started :	N/R
Date Completed :	1991-03-19
Priority Level :	1
Operational Unit :	00
Primary Responsibility :	EPA In-House
Planning Status :	N/R
Urgency Indicator :	N/R
Action Anomaly :	N/R

ENVIROSTOR - CA

Facility Name :	TORREY CHEMICAL CO.
Facility Address :	217 LAS POSAS ROAD, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Cleanup Date :	1995-08-21
Cleanup Status :	Refer: Other Agency
Site Type :	Historical
Site Type Detailed :	* Historical
Acreage :	N/R
APN :	NONE SPECIFIED
National Priorities List :	NO
Regulatory Agencies Involved :	N/R
Lead Agency :	N/R

Map Id: O109
Direction: SE
Distance: 0.419 mi., 2213 ft.
Elevation: 562 ft.
Relative: Lower

Site Name : TORREY CHEMICAL CO | GR ENTERPRISE INC
217 LAS POSAS RD
SAN MARCOS, CA

Database(s) : [CERCLIS NFRAP, ENVIROSTOR - CA, FRS, FTTS INSP, HIST CORTESE - CA, SEMS_8R_ARCHIVED SITES] ***(cont.)***

Envirosite ID: 222767
EPA ID: N/R

ENVIROSTOR - CA ***(cont.)***

Project Manager :	N/R
Supervisor :	* Mmonroy
Office :	Cleanup Cypress
Envirostor ID :	37510137
Site Code :	N/R
Assembly :	75
Senate :	38
Congressional District :	50
Special Program :	N/R
Past Uses :	NONE SPECIFIED
Potential COC :	* HALOGENATED SOLVENTS; * CONTAMINATED SOIL; * UNSPECIFIED ACID SOLUTION; * OXYGENATED SOLVENTS
Confirmed COC :	N/R
Potential Media Affected :	N/R
Restricted Use :	NO
Site Management Req :	N/R
Funding :	N/R
Latitude :	33.146944
Longitude :	-117.188889
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-14

Alias Details

Alias :	37510137
Alias Type :	Envirostor ID Number

Completed Activities

Completed Date :	1994-10-25
Area Name :	PROJECT WIDE
Sub Area Name :	N/R
Document Type :	Site Screening
Comments :	CalSites Validation Program confirms NFA for DTSC.
Completed Date :	1991-08-13
Area Name :	PROJECT WIDE
Sub Area Name :	N/R
Document Type :	Site Screening

Comments :

PA Report was reviewed by Region 4 staff. The site is located at 217 Las Posas R. between Mission Rd. & Hwy 78 in San Marcos. The area is industrial, but Palomar College is north of Mission Rd. Site includes 4,000 sf bldg., 2 small storage sheds, outdoor drum storage area, and abandoned above ground storage tanks (550 gal.). Chemical company is still operating repackaging and storing various chemical products (Algi-gon pool treatment etc.). No sampling result were considered in EPA's PA. Staff recommends PEARM to de- termine if there is a problem DTSC should address.

Map Id: O109
Direction: SE
Distance: 0.419 mi., 2213 ft.
Elevation: 562 ft.
Relative: Lower

Site Name : TORREY CHEMICAL CO | GR ENTERPRISE INC
217 LAS POSAS RD
SAN MARCOS, CA

Database(s) : [CERCLIS NFRAP, ENVIROSTOR - CA, FRS, FTTS INSP, HIST CORTESE - CA, SEMS_8R_ARCHIVED SITES] ***(cont.)***

Envirosite ID: 222767
EPA ID: N/R

ENVIROSTOR - CA ***(cont.)***

Completed Date :	1987-06-20
Area Name :	PROJECT WIDE
Sub Area Name :	N/R
Document Type :	Site Screening
Comments :	SITE SCREENING DONE

Completed Date :	1983-05-11
Area Name :	PROJECT WIDE
Sub Area Name :	N/R
Document Type :	* Discovery
Comments :	FACILITY IDENTIFIED VIA DRIVEBY

Future Activities

Area Name :	N/R
Sub Area Name :	N/R
Document Type :	N/R
Due Date :	N/R

Scheduled Activites

Due Date :	N/R
Revised Date :	N/R
Area Name :	N/R
Sub Area Name :	N/R
Document Type :	N/R

FRS

Facility Name :	GR ENTERPRISE INC
Facility Address :	217 LAS POSAS RD, SAN MARCOS, CA 92069-1422
County :	SAN DIEGO

Site Details

Registry ID :	110011650123
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Source Description

Source Description :

NCDB supports implementation of the Federal Insecticide, Fungicide, and Rodenticide Act (FIFRA) and the Toxic Substances Control Act (TSCA). The system tracks inspections in regions and states with cooperative agreements, enforcement actions, and settlements.

Map Id: O109
Direction: SE
Distance: 0.419 mi., 2213 ft.
Elevation: 562 ft.
Relative: Lower

Site Name : TORREY CHEMICAL CO | GR ENTERPRISE INC
217 LAS POSAS RD
SAN MARCOS, CA

Database(s) : [CERCLIS NFRAP, ENVIROSTOR - CA, FRS, FTTS INSP, HIST CORTESE - CA, SEMS_8R_ARCHIVED SITES] ***(cont.)***

Envirosite ID: 222767
EPA ID: N/R

FRS ***(cont.)***

FRS Environmental Interest

Source and System ID :	NCDB - C09#FIFRA-09-94-164 NCDB - I09#19930112F2718 3

FTTS INSP

Inspection Date :	1993-01-12
Inspection Number :	19930112F2718 3
Inspection Name :	OL
Investigation Type :	SPR
Reason :	FCG
Facility :	PD
Action :	N
Legislation :	F
Region :	09

HIST CORTESE - CA

Facility Name :	TORREY CHEMICAL CO.
Facility Address :	217 LAS POSAS ROAD, SAN MARCOS, 92069
County :	SAN DIEGO
Status Date :	1995-08-21
Status :	REFER: OTHER AGENCY
Envirostor ID :	37510137
Program Type :	HISTORICAL
Site Code :	N/R
CalEnviroScreen Score :	56-60%
Latitude :	33.146944
Longitude :	-117.188889
Last Date in Agency List :	2022-02-04

SEMS_8R_ARCHIVED SITES

Facility Name :	TORREY CHEMICAL CO
Facility Address :	217 LAS POSAS RD, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Site ID :	0902600
EPA ID :	CAD982360430
Region :	09
Congressional District :	43
Federal Facility :	N
Federal Facility Docket :	N
NPL Status :	Not on the NPL
Non NPL Status :	NFRAP-Site does not qualify for the NPL based on existing information
FIPS Code :	06073
Superfund Alternative Agreement :	N
Last Date in Agency List :	2022-02-21

Map Id: O109
Direction: SE
Distance: 0.419 mi., 2213 ft.
Elevation: 562 ft.
Relative: Lower

Site Name : TORREY CHEMICAL CO | GR ENTERPRISE INC
217 LAS POSAS RD
SAN MARCOS, CA

Database(s) : [CERCLIS NFRAP, ENVIROSTOR - CA, FRS, FTTS INSP, HIST CORTESE - CA, SEMS_8R_ARCHIVED SITES] ***(cont.)***

Envirosite ID: 222767
EPA ID: N/R

SEMS_8R_ARCHIVED SITES ***(cont.)***

Additional Information

Start Date :	1987-11-01
Finish Date :	1987-11-01
OU :	00
Action Code :	DS
Action Name :	DISCVRY
Sequence :	1
Quality :	N/R
Current Action Lead :	St Perf

Start Date :	N/R
Finish Date :	1991-03-19
OU :	00
Action Code :	PA
Action Name :	PA
Sequence :	1
Quality :	N
Current Action Lead :	EPA Perf

Start Date :	N/R
Finish Date :	1991-03-19
OU :	00
Action Code :	VS
Action Name :	ARCH SITE
Sequence :	1
Quality :	N/R
Current Action Lead :	EPA Perf In-Hse

Map Id: N110
Direction: ESE
Distance: 0.421 mi., 2223 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : LAS POSAS VENTURE, INC | SAN MARCOS GAS | EXXONMOBIL OIL CORPORATION #12452
1290 W MISSION RD
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_LQG, RCRA_NONGEN, UST - CA]

Envirosite ID: 241207
EPA ID: N/R

BRS

Facility Name :	EXXONMOBIL OIL CORP.

Map Id: N110
Direction: ESE
Distance: 0.421 mi., 2223 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : LAS POSAS VENTURE, INC | SAN MARCOS GAS | EXXONMOBIL OIL CORPORATION #12452
1290 W MISSION RD
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_LQG, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 241207
EPA ID: N/R

BRS ***(cont.)***

Facility Address :	1290 W MISSION RD, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Date Form Received by Agency :	2002-02-28
EPA ID :	CAL000098361
Mailing Address :	12265 WEST BAYAUD AVE., LAKEWOOD, CO 80228
Contact :	JOHN HOOVER
Contact Address :	N/R
Contact Country :	US
Contact Telephone :	800-253-8054
Contact Email :	N/R
EPA Region :	09
Land Type :	Private
Source Type :	Annual/Biennial Report
Classification :	Large Quantity Generator

Description :

Handlers that generate 1,000 kg or more of hazardous waste during any calendar month; or generate more than 1 kg of acutely hazardous waste during any calendar month; or generate more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generate 1 kg or less of acutely hazardous waste during any calendar month, and accumulate more than 1 kg of acutely hazardous waste at any time; or generate 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulated more than 100 kg of that material at any time.

Last Date in Agency List :	2022-01-25

Owner/Operator Summary

Owner/Operator Name :	EXXONMOBIL OIL CORP.
Owner/Operator Address :	N/R
Owner/Operator Country :	US
Owner/Operator Telephone :	N/R
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Private
Owner/Operator Type :	Owner
Owner/Operator Start Date :	2002-05-31
Owner/Operator End Date :	N/R

Map Id: N110
Direction: ESE
Distance: 0.421 mi., 2223 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : LAS POSAS VENTURE, INC | SAN MARCOS GAS | EXXONMOBIL OIL CORPORATION #12452
1290 W MISSION RD
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_LQG, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 241207
EPA ID: N/R

BRS ***(cont.)***

Waste Activity Monitoring

Report Cycle :	2001
Hazardous Waste Page Number :	1
Hazardous Waste Sub-Page Number :	1
BR Form :	GM
Waste Description :	WASTE FLAMMABLE LIQUID, N.O.S
Primary NAICS :	44711 - Gasoline Stations with Convenience Stores
Source Code :	G14 - Removal of tank sludge, sediments, or slag (periodic sludge or residual removal from storage tanks including internal scrubbing or cleaning)
Form Code :	W205 - Oil-water emulsion or mixture (fluid but not sludge)
Management Method :	N/R
Generation Tons :	3.74465
Managed Tons :	0
Shipped Tons :	3.74465
Received Tons :	0
Receiver ID :	CAD028409019
Receiver State :	CA
Shipper ID :	CAL000098361
Shipper State :	CA
Waste Minimization :	N/R
Waste Code List :	D001
Waste Code Group :	D001 - IGNITABLE WASTE
Waste Generation Type :	N/R

CALEPA SITES - CA

Facility Name :	LAS POSAS VENTURE, INC
Facility Address :	1290 W MISSION RD, SAN MARCOS, 92069
Site ID :	396300
EI ID :	10376581
EI Description :	Chemical Storage Facilities
Latitude :	33.148560
Longitude :	-117.188225
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07
Site ID :	396300
EI ID :	10376581
EI Description :	Hazardous Waste Generator
Latitude :	33.148560
Longitude :	-117.188225
Agency Hyperlink :	Click here for hyperlink provided by the agency.

Map Id: N110
Direction: ESE
Distance: 0.421 mi., 2223 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : LAS POSAS VENTURE, INC | SAN MARCOS GAS | EXXONMOBIL OIL CORPORATION #12452
1290 W MISSION RD
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_LQG, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 241207
EPA ID: N/R

CALEPA SITES - CA ***(cont.)***

Last Date in Agency List : 2022-01-07

Site ID : 396300
EI ID : 10376581
EI Description : Underground Storage Tank
Latitude : 33.148560
Longitude : -117.188225
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-01-07

Facility Name : SAN MARCOS GAS
Facility Address : 1290 W MISSION RD, SAN MARCOS, 92069

Site ID : 214270
EI ID : T0607383730
EI Description : Leaking Underground Storage Tank Cleanup Site
Latitude : 33.148608
Longitude : -117.188192
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-01-07

CASE LIST_SAN DIEGO COUNTY - CA

Facility Name : SAN MARCOS GAS
Facility Address : 1290 W MISSION RD, SAN MARCOS, CA 92069
County : San Diego

Site Details
Status Date : 2013-07-15
Status : Completed - Case Closed
Begin Date : 2003-03-18
Global ID : T0607383730
Site History : Refer to "Site Maps/Documents" tab for Closure Letter/Summary
RB Case Number : N/R
Potential Media Affected : Soil

Potential Contaminants of Concern : Diesel, Ethylbenzene, Gasoline, MTBE / TBA / Other Fuel Oxygenates, Toluene, Xylene

Local Agency : SAN DIEGO COUNTY LOP
Local Case Number : H25233-001
Lead Agency : SAN DIEGO COUNTY LOP
File Location : Local Agency

Map Id: N110
Direction: ESE
Distance: 0.421 mi., 2223 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : LAS POSAS VENTURE, INC | SAN MARCOS GAS | EXXONMOBIL OIL CORPORATION #12452
1290 W MISSION RD
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_LQG, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 241207
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

CUF Case :	NO
Caseworker :	TVS
Case Type :	LUST Cleanup Site
How Discovered :	UST System Modification
How Discovered Description :	Piping upgrade
Stop Method :	Replace product piping
Stop Description :	REPLACE PRODUCT PIPING
Calwater Watershed Name :	Carlsbad - San Marcos - Richland (904.52)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)
Disadvantaged Community :	N/R
Latitude :	33.148608
Longitude :	-117.188192
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-09

Contacts Summary

Global ID :	T0607383730
Contact Name :	TONY SAWYER
Contact Type :	Local Agency Caseworker
Organization Name :	SAN DIEGO COUNTY LOP
Address :	P.O. Box 129261
City :	San Diego
Phone Number :	N/R
Email :	tony.sawyer@sdcounty.ca.gov

Regulatory Activities

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Date :	2013-07-15
Global ID :	T0607383730
Action Type :	ENFORCEMENT
Action :	Closure/No Further Action Letter

Date :	2012-01-20
Global ID :	T0607383730
Action Type :	ENFORCEMENT
Action :	Notification - Preclosure

Map Id: N110
Direction: ESE
Distance: 0.421 mi., 2223 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : LAS POSAS VENTURE, INC | SAN MARCOS GAS | EXXONMOBIL OIL CORPORATION #12452
1290 W MISSION RD
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_LQG, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 241207
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Date :	2011-05-10
Global ID :	T0607383730
Action Type :	ENFORCEMENT
Action :	Warning Letter

Date :	2010-05-21
Global ID :	T0607383730
Action Type :	ENFORCEMENT
Action :	Letter - Notice

Date :	2009-07-09
Global ID :	T0607383730
Action Type :	ENFORCEMENT
Action :	Letter - Notice

Date :	2006-12-05
Global ID :	T0607383730
Action Type :	RESPONSE
Action :	Preliminary Site Assessment Report - Regulator Responded

Date :	2003-04-15
Global ID :	T0607383730
Action Type :	ENFORCEMENT
Action :	Notice of Responsibility

Date :	2003-04-03
Global ID :	T0607383730
Action Type :	Other
Action :	Leak Reported

Date :	2003-03-18
Global ID :	T0607383730
Action Type :	Other
Action :	Leak Discovery

Date :	2003-03-18
Global ID :	T0607383730
Action Type :	Other
Action :	Leak Stopped

Map Id: N110
Direction: ESE
Distance: 0.421 mi., 2223 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : LAS POSAS VENTURE, INC | SAN MARCOS GAS | EXXONMOBIL OIL CORPORATION #12452
1290 W MISSION RD
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_LQG, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 241207
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Status History

Status Date :	2013-07-15
Global ID :	T0607383730
Status :	Completed - Case Closed
Status Date :	2013-06-01
Global ID :	T0607383730
Status :	Open - Eligible for Closure
Status Date :	2003-04-15
Global ID :	T0607383730
Status :	Open - Site Assessment
Status Date :	2003-03-18
Global ID :	T0607383730
Status :	Open - Case Begin Date

ECHO

Facility Name :	EXXONMOBIL OIL CORPORATION #12452
Facility Address :	1290 W MISSION ROAD, SAN MARCOS, CA 92069
County :	SAN DIEGO
Last Inspection Date :	N/R
Registry ID :	110041969493
FIPS Code :	N/R
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	_____
Collection Method :	Zip Code Centroid
Reference Point :	N/R
Accuracy Meters :	10000

Map Id: N110
Direction: ESE
Distance: 0.421 mi., 2223 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : LAS POSAS VENTURE, INC | SAN MARCOS GAS | EXXONMOBIL OIL CORPORATION #12452
1290 W MISSION RD
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_LQG, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 241207
EPA ID: N/R

ECHO ***(cont.)***

Derived Tribes :	N/R
Derived HUC :	N/R
Derived WBD :	N/R
Derived STCTY FIPS :	N/R
Derived Zip :	N/R
Derived CD113 :	N/R
Derived CB2010 :	N/R
MYRTK Universe :	NNY
NPDES IDs :	N/R
CWA Permit Types :	N/R
CWA Compliance Tracking :	N/R
CWA NAICS :	N/R
CWA SICS :	N/R
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	N/R
CWA Current Compliance Status :	N/R
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	N/R
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	N/R
Facility NAICS :	44711 - Gasoline Stations with Convenience Stores
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	N/R
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	N
SDWIS Flag :	N
RCRA Flag :	Y

Map Id: N110
Direction: ESE
Distance: 0.421 mi., 2223 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : LAS POSAS VENTURE, INC | SAN MARCOS GAS | EXXONMOBIL OIL CORPORATION #12452
1290 W MISSION RD
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_LQG, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 241207
EPA ID: N/R

ECHO ***(cont.)***

TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	Y
NAA Flag :	N
Latitude :	33.194075
Longitude :	-117.16177
Last Date in Agency List :	2022-01-17
Facility Name :	EXXONMOBIL OIL CORPORATION #12452
Facility Address :	1290 W MISSION ROAD, SAN MARCOS, CA 92069-0000
County :	SAN DIEGO
Last Inspection Date :	N/R
Registry ID :	N/R
FIPS Code :	N/R
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	_____
Collection Method :	Zip Code Centroid
Reference Point :	N/R
Accuracy Meters :	10000
Derived Tribes :	N/R
Derived HUC :	N/R
Derived WBD :	N/R
Derived STCTY FIPS :	N/R
Derived Zip :	N/R
Derived CD113 :	N/R
Derived CB2010 :	N/R
MYRTK Universe :	NNN
NPDES IDs :	N/R
CWA Permit Types :	N/R
CWA Compliance Tracking :	N/R
CWA NAICS :	N/R

Map Id: N110
Direction: ESE
Distance: 0.421 mi., 2223 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : LAS POSAS VENTURE, INC | SAN MARCOS GAS | EXXONMOBIL OIL CORPORATION #12452
1290 W MISSION RD
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_LQG, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 241207
EPA ID: N/R

ECHO ***(cont.)***

CWA SICS :	N/R
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	N/R
CWA Current Compliance Status :	N/R
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	N/R
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	N/R
Facility NAICS :	44711 - Gasoline Stations with Convenience Stores
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	N/R
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	N
SDWIS Flag :	N
RCRA Flag :	Y
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	Y
NAA Flag :	N/R
Latitude :	33.194075
Longitude :	-117.16177
Last Date in Agency List :	2019-07-15

Facility Name :	LAS POSAS VENTURE INC
Facility Address :	1290 W MISSION RD, SAN MARCOS, CA 92069

Map Id: N110
Direction: ESE
Distance: 0.421 mi., 2223 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : LAS POSAS VENTURE, INC | SAN MARCOS GAS | EXXONMOBIL OIL CORPORATION #12452
1290 W MISSION RD
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_LQG, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 241207
EPA ID: N/R

ECHO ***(cont.)***

County :	SAN DIEGO
Last Inspection Date :	N/R
Registry ID :	110055736351
FIPS Code :	06073
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	_____
Collection Method :	ADDRESS MATCHING-HOUSE NUMBER
Reference Point :	CENTER OF A FACILITY OR STATION
Accuracy Meters :	30

Derived Tribes :

San Pasqual Band of Diegueno Mission Indians of California - 12 mile(s), Pala Band of Mission Indians - 13.1 mile(s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 13.7 mile(s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 15.9 mile(s), Pauma Band of Luiseno Mission Indians of the Pauma & Yuima Reservation, California - 16.7 mile(s), La Jolla Band of Luiseno Indians, California - 16.8 mile(s), Pechanga Band of Luiseno Mission Indians of the Pechanga Reservation, California - 20.4 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 22.2 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 22.6 mile(s), Mesa Grande Band of Diegueno Mission Indians of the Mesa Grande Reservation, California - 22.8 mile(s)

Derived HUC :	18070303
Derived WBD :	180703030503
Derived STCTY FIPS :	06073
Derived Zip :	92069
Derived CD113 :	50
Derived CB2010 :	060730200211011
MYRTK Universe :	NNN
NPDES IDs :	N/R
CWA Permit Types :	N/R
CWA Compliance Tracking :	N/R
CWA NAICS :	N/R

Map Id: N110
Direction: ESE
Distance: 0.421 mi., 2223 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : LAS POSAS VENTURE, INC | SAN MARCOS GAS | EXXONMOBIL OIL CORPORATION #12452
1290 W MISSION RD
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_LQG, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 241207
EPA ID: N/R

ECHO ***(cont.)***

CWA SICS :	N/R
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	N/R
CWA Current Compliance Status :	N/R
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	N/R
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	N/R
Facility NAICS :	44719 - Other Gasoline Stations
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	Y
Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	N
SDWIS Flag :	N
RCRA Flag :	Y
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	Y
NAA Flag :	Y
Latitude :	33.14856
Longitude :	-117.18822
Last Date in Agency List :	2022-01-17

EPA LUST

Facility Name :	SAN MARCOS GAS

Map Id: N110
Direction: ESE
Distance: 0.421 mi., 2223 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : LAS POSAS VENTURE, INC | SAN MARCOS GAS | EXXONMOBIL OIL CORPORATION #12452
1290 W MISSION RD
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_LQG, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 241207
EPA ID: N/R

EPA LUST ***(cont.)***

Facility Address :	1290 W MISSION RD, SAN MARCOS, California 92069
County :	N/R
Facility ID :	N/R
LUST ID :	CAT0607383730
Reported Date :	N/R
Status :	No Further Action
Substance :	N/R
Closed With Residual Contamination (Tribal Only):	N/R
NFA_Letter (Tribal Only) :	N/R
Tribe (Tribal Only) :	N/R
EPA Region :	9
Estimated Population within 1500ft :	331
Estimated Private Domestic Wells within 1500ft:	0
Within Source Water Protection Area (SPA):	No
SPA Public Water System and Facility ID:	N/R
SPA Water Type :	N/R
SPA Facility Type :	N/R
SPA HUC12 :	N/R
Within Groundwater Wellhead Protection Area (WHPA):	No
WHPA Public Water System and Facility ID:	N/R
WHPA Water Type :	N/R
WHPA Facility Type :	N/R
WHPA HUC12 :	N/R
Within Estimated 100-year Floodplain:	No
Latitude :	33.148249999999898
Longitude :	-117.188370000000006
Last Date in Agency List :	2022-01-04

EPA UST

Facility Name :	LAS POSAS VENTURE, INC
Facility Address :	1290 W MISSION RD, SAN MARCOS, California 92069
County :	N/R
Facility ID :	CA10376581
Facility Status :	Open UST(s)
Open USTs :	4
Closed USTs :	N/R
Temporarily Out of Service USTs :	N/R
Date of Last Inspection :	N/R

Map Id: N110
Direction: ESE
Distance: 0.421 mi., 2223 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : LAS POSAS VENTURE, INC | SAN MARCOS GAS | EXXONMOBIL OIL CORPORATION #12452
1290 W MISSION RD
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_LQG, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 241207
EPA ID: N/R

EPA UST ***(cont.)***

EPA Region :	9
Tribe :	N/R
Facility ID 2 :	N/R
Latitude :	33.148535011870997
Longitude :	-117.188203016849002
Last Date in Agency List :	2021-12-27

Tank Details

Tank ID :	CA10376581-001_A Stand-alone Tank_1
Tank Status :	Open
Installation Date :	1991-01-01
Removal Date :	N/R
Capacity :	10000
Substances :	Regular Unleaded
Tank Wall Type :	Double Wall

Tank ID :	CA10376581-002_A Stand-alone Tank_1
Tank Status :	Open
Installation Date :	1991-01-01
Removal Date :	N/R
Capacity :	10000
Substances :	Diesel
Tank Wall Type :	Double Wall

Tank ID :	CA10376581-003_A Stand-alone Tank_1
Tank Status :	Open
Installation Date :	1991-01-01
Removal Date :	N/R
Capacity :	10000
Substances :	Regular Unleaded
Tank Wall Type :	Double Wall

Tank ID :	CA10376581-004_A Stand-alone Tank_1
Tank Status :	Open
Installation Date :	1991-01-01
Removal Date :	N/R
Capacity :	10000
Substances :	Premium Unleaded
Tank Wall Type :	Double Wall

FID UST - CA

Facility Name :	LAS POSAS VENTURE, INC

Map Id: N110
Direction: ESE
Distance: 0.421 mi., 2223 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : LAS POSAS VENTURE, INC | SAN MARCOS GAS | EXXONMOBIL OIL CORPORATION #12452
1290 W MISSION RD
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_LQG, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 241207
EPA ID: N/R

FID UST - CA ***(cont.)***

Facility Address : 1290 W MISSION RD, SAN MARCOS, 92069
County : San Diego

Facility ID : 37-000-215691
CERSID : 10376581
Permitting Agency : San Diego County Department of Environmental Health
Latitude : 33.14856
Longitude : -117.18822
Last Date in Agency List : 2022-03-14

Facility Name : MOBIL OIL CORPORATION
Facility Address : 1290 W MISSION RD, SAN MARCOS, 92069
County : San Diego

Facility ID : H25233
CERSID : N/R
Permitting Agency : SAN DIEGO COUNTY
Latitude : 33.149909
Longitude : -117.186877
Last Date in Agency List : 2018-05-14

FRS

Facility Name : EXXONMOBIL OIL CORPORATION #12452
Facility Address : 1290 W MISSION ROAD, SAN MARCOS, CA 92069-0000
County : SAN DIEGO

Site Details

Registry ID : 110041969493
FRS Facility URL : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-02-17

Source Description

Source Description :

All generators and treatment, storage, and disposal (TSD) facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years. The data collected is used to create the National Biennial Resource Conservation and Recovery Act (RCRA) Hazardous Waste Report. This data is processed within the RCRA Information (RCRAInfo) database.

Map Id: N110
Direction: ESE
Distance: 0.421 mi., 2223 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : LAS POSAS VENTURE, INC | SAN MARCOS GAS | EXXONMOBIL OIL CORPORATION #12452
1290 W MISSION RD
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_LQG, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 241207
EPA ID: N/R

FRS ***(cont.)***

Source Description :

RCRAInfo is EPA's comprehensive information system that supports the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984 through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA. RCRAInfo also supports generation of the National Hazardous Waste Biennial Report. All generators and treatment, storage, and disposal facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years to support creation of the Biennial Report.

FRS Environmental Interest

Source and System ID :	RCRAINFO - CAL000098361
Facility Name :	LAS POSAS VENTURE INC
Facility Address :	1290 W MISSION RD, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Registry ID :	110055736351
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Source Description

Source Description :

The California Environmental Reporting System (CERS) is a statewide web-based user and information exchange system to support over 140,000 regulated businesses and over 130 local agencies in electronically collecting and reporting significant hazardous materials, hazardous waste and compliance and enforcement data as mandated by California law. Under oversight by Cal/EPA, certified local governing agencies (Unified Program Agencies - UPAs) consolidate, coordinate and provide consistent regulatory activities for six state and federal environmental programs.
The California Environmental Protection Agency (CalEPA) has recently implemented a new data warehouse system (nSite). This data warehouse combines and merges facility and site information from five different systems managed within CalEPA. The five systems are: California Environmental Reporting System (CERS), EnviroStor, GeoTracker, California Integrated Water Quality System (CIWQS), and Toxic Release Inventory (TRI).

Map Id: N110
Direction: ESE
Distance: 0.421 mi., 2223 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : LAS POSAS VENTURE, INC | SAN MARCOS GAS | EXXONMOBIL OIL CORPORATION #12452
1290 W MISSION RD
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_LQG, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 241207
EPA ID: N/R

FRS ***(cont.)***

Source Description :

RCRAInfo is EPA's comprehensive information system that supports the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984 through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA. RCRAInfo also supports generation of the National Hazardous Waste Biennial Report. All generators and treatment, storage, and disposal facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years to support creation of the Biennial Report.

FRS Environmental Interest

Source and System ID :	CA-CERS - 10376581 CA-ENVIROVIEW - 129781 RCRAINFO - CAL000375415

HAZMAT_SAN DIEGO COUNTY - CA

Facility Name :	LAS POSAS VENTURE, INC
Facility Address :	1290 W MISSION RD, SAN MARCOS, CA 92069
Date :	2011-10-31
Record ID :	DEH2011-HUPFP-215691
Record Type :	Unified Program Facility Permit
Status :	Permit Renewed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23
Facility Name :	MOBIL OIL CORPORATION #18-HLE
Facility Address :	1290 W MISSION RD, SAN MARCOS, CA 92069
Date :	2002-05-04
Record ID :	DEH2002-HUPFP-125233
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23
Facility Name :	SAN MARCOS GAS
Facility Address :	1290 W MISSION RD, SAN MARCOS, CA 92069

Map Id: N110
Direction: ESE
Distance: 0.421 mi., 2223 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : LAS POSAS VENTURE, INC | SAN MARCOS GAS | EXXONMOBIL OIL CORPORATION #12452
1290 W MISSION RD
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_LQG, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 241207
EPA ID: N/R

HAZMAT_SAN DIEGO COUNTY - CA ***(cont.)***

Date :	2003-01-24
Record ID :	DEH2003-HUPFP-201278
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	Pay Fees Due
Short Notes :	N/R
Last Date in Agency List :	2015-11-23

HAZNET - CA

Facility Name :	EXXONMOBIL OIL CORPORATION #12452
Facility Address :	1290 W MISSION ROAD, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000098361
Active :	Active
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	800 E WASHINGTON ST, WEST CHESTER, PA 193804542
Latitude :	33.14809186
Longitude :	-117.18776640
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :

2002: 352 - Other organic solids, 0.02 tons to CAD080014079
2002: 223 - Unspecified oil-containing waste, 2.10161 tons to CAD028409019
2001: 223 - Unspecified oil-containing waste, 0.075 tons to
2001: 223 - Unspecified oil-containing waste, 3.7186 tons to CAD028409019
2000: 134 - Aqueous solution with total organic residues less than 10 percent, 0.1344 tons to CAD028409019
2000: 223 - Unspecified oil-containing waste, 0.0417 tons to CAD028409019
2000: 241 - Tank bottom waste, 0.417 tons to CAD028409019
2000: 223 - Unspecified oil-containing waste, 3.3844 tons to CAD028409019
2000: 181 - Other inorganic solid waste, 0.01 tons to CAD044429835

Map Id: N110
Direction: ESE
Distance: 0.421 mi., 2223 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : LAS POSAS VENTURE, INC | SAN MARCOS GAS | EXXONMOBIL OIL CORPORATION #12452
1290 W MISSION RD
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_LQG, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 241207
EPA ID: N/R

HAZNET - CA ***(cont.)***

2000: 134 - Aqueous solution with total organic residues less than 10 percent, 0.042 tons to CAT080013352
2000: N/R - Blank or unknown, 0 tons to CAD028409019
1999: 181 - Other inorganic solid waste, 0.025 tons to CAD050806850
1999: 223 - Unspecified oil-containing waste, 1.2785 tons to CAD028409019
1998: 134 - Aqueous solution with total organic residues less than 10 percent, 1.1424 tons to CAD028409019
1998: 223 - Unspecified oil-containing waste, 0.9674 tons to CAD028409019
1998: 221 - Waste oil and mixed oil, 0.1064 tons to CAD028409019
1998: 133 - Aqueous solution with total organic residues 10 percent or more, 1.9182 tons to CAD028409019
1997: 134 - Aqueous solution with total organic residues less than 10 percent, 0.2898 tons to CAD028409019
1996: 134 - Aqueous solution with total organic residues less than 10 percent, 0.8442 tons to CAD028409019
1996: 352 - Other organic solids, 0.05 tons to CAT080022148
1996: 241 - Tank bottom waste, 0.7464 tons to CAT080013352
1995: 134 - Aqueous solution with total organic residues less than 10 percent, 0.2898 tons to CAD028409019
1994: 134 - Aqueous solution with total organic residues less than 10 percent, 0.672 tons to CAD028409019

Facility Name :	LAS POSAS VENTURE INC
Facility Address :	1290 W MISSION RD, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000375415
Active :	Active
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	5505 CANCHA DE GOLF, RANCHO SANTA FE, CA 920910000
Latitude :	33.14853900
Longitude :	-117.18820350
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Map Id: N110
Direction: ESE
Distance: 0.421 mi., 2223 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : LAS POSAS VENTURE, INC | SAN MARCOS GAS | EXXONMOBIL OIL CORPORATION #12452
1290 W MISSION RD
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_LQG, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 241207
EPA ID: N/R

HAZNET - CA ***(cont.)***

Waste Generator Details
State Waste :
2019: 491 - Unspecified sludge waste, 0.04170 tons to CAD097030993
2019: 223 - Unspecified oil-containing waste, 1.10922 tons to CAT080013352
2019: 352 - Other organic solids, 0.15000 tons to AZR000510065
2019: 352 - Other organic solids, 0.15000 tons to CAD008252405
2017: 135 - Unspecified aqueous solution, 0.63 tons to CAT080013352
2017: 352 - Other organic solids, 0.125 tons to CAD008252405
2016: 135 - Unspecified aqueous solution, 0.189 tons to CAT080013352
2016: 352 - Other organic solids, 0.025 tons to CAD008252405
2016: 343 - Unspecified organic liquid mixture, 0.068 tons to CAT080013352
2015: 343 - Unspecified organic liquid mixture, 0.051 tons to CAT080013352
2015: 135 - Unspecified aqueous solution, 0.084 tons to CAT080013352
2015: 352 - Other organic solids, 0.025 tons to CAD008252405
2013: 135 - Unspecified aqueous solution, 0.462 tons to CAT080013352

Facility Name : SAN MARCOS GAS
Facility Address : 1290 W MISSION RD, SAN MARCOS, CA 92069
County : SAN DIEGO

Site Details
Generator EPA ID : CAL000269947
Active : Inactive
Category : STATE
Facility Types : N/R
Type : PERMANENT
Contact Name : N/R
Contact Phone : N/R
Facility Mailing Address : 1290 W MISSION RD, SAN MARCOS, CA 920690000
Latitude : 33.14809186
Longitude : -117.18776640
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2021-07-08

Waste Generator Details
State Waste :
2011: 241 - Tank bottom waste, 2.085 tons to CAT080013352
2006: 134 - Aqueous solution with total organic residues less than 10 percent, 6.3 tons to AZR000035915
2004: 213 - Hydrocarbon solvents (benzene, hexane, Stoddard, Etc.), 0.0375 tons to KYD053348108
2003: 135 - Unspecified aqueous solution, 0.84 tons to CAT080013352

Map Id: N110
Direction: ESE
Distance: 0.421 mi., 2223 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : LAS POSAS VENTURE, INC | SAN MARCOS GAS | EXXONMOBIL OIL CORPORATION #12452
1290 W MISSION RD
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_LQG, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 241207
EPA ID: N/R

HAZNET - CA ***(cont.)***

2003: 352 - Other organic solids, 0.0015 tons to CAT080033681

HWG - CA

Facility Name :	EXXONMOBIL OIL CORPORATION #12452
Facility Address :	1290 W MISSION ROAD, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAL000098361
Status :	Active
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	800 E WASHINGTON ST, WEST CHESTER, PA 193804542
Owner Name :	EXXONMOBIL OIL CORPORATION
Owner Address :	5959 LAS COLINAS BOULEVARD, IRVING, TX 750394202
Operator Name :	DONNA HYMES
Operator Address :	800 E. WASHINGTON STREET, WEST CHESTER, PA 19380
Latitude :	33.148266
Longitude :	-117.188714

Facility Name :	LAS POSAS VENTURE INC
Facility Address :	1290 W MISSION RD, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAL000375415
Status :	Active
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	5505 CANCHA DE GOLF, RANCHO SANTA FE, CA 920910000
Owner Name :	LAS POSAS VENTURE, INC
Owner Address :	5505 CANCHA DE GOLF, RANCHO SANTA FE, CA 920910000
Operator Name :	ANTHONY NESHCHERET
Operator Address :	1290 W MISSION RD., SAN MARCOS, CA 92069
Latitude :	33.14855
Longitude :	-117.18822

Facility Name :	SAN MARCOS GAS
Facility Address :	1290 W MISSION RD, SAN MARCOS, CA 92069
County :	SAN DIEGO

Map Id: N110
Direction: ESE
Distance: 0.421 mi., 2223 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : LAS POSAS VENTURE, INC | SAN MARCOS GAS | EXXONMOBIL OIL CORPORATION #12452
1290 W MISSION RD
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_LQG, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 241207
EPA ID: N/R

HWG - CA ***(cont.)***

EPA ID :	CAL000269947
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	1290 W MISSION RD, SAN MARCOS, CA 920690000
Owner Name :	HARMS & NAPIER INC
Owner Address :	1290 W MISSION RD, SAN MARCOS, CA 920690000
Operator Name :	BRAD NAPIER
Operator Address :	1290 W MISSION RD, SAN MARCOS, CA 920690000
Latitude :	33.148608
Longitude :	-117.188192

LUST REG 9 - CA

Facility Name :	SAN MARCOS GAS
Facility Address :	1290 W MISSION RD, SAN MARCOS, CA 92069
County :	San Diego

Site Details

Status Date :	2013-07-15
Status :	Completed - Case Closed
Begin Date :	2003-03-18
Global ID :	T0607383730
Region :	REGION 9
Site History :	Refer to "Site Maps/Documents" tab for Closure Letter/Summary
RB Case Number :	N/R
Potential Media Affected :	Soil
Potential Contaminants of Concern :	Diesel, Ethylbenzene, Gasoline, MTBE / TBA / Other Fuel Oxygenates, Toluene, Xylene
Local Agency :	SAN DIEGO COUNTY LOP
Local Case Number :	H25233-001
Lead Agency :	SAN DIEGO COUNTY LOP
File Location :	Local Agency
CUF Case :	NO
Caseworker :	TVS
Case Type :	LUST Cleanup Site
How Discovered :	UST System Modification
How Discovered Description :	Piping upgrade
Stop Method :	Replace product piping
Stop Description :	REPLACE PRODUCT PIPING
Calwater Watershed Name :	Carlsbad - San Marcos - Richland (904.52)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)
Disadvantaged Community :	N/R

Map Id: N110
Direction: ESE
Distance: 0.421 mi., 2223 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : LAS POSAS VENTURE, INC | SAN MARCOS GAS | EXXONMOBIL OIL CORPORATION #12452
1290 W MISSION RD
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_LQG, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 241207
EPA ID: N/R

LUST REG 9 - CA ***(cont.)***

Latitude :	33.148608
Longitude :	-117.188192
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-11

Contacts Summary

Global ID :	T0607383730
Contact Name :	TONY SAWYER
Contact Type :	Local Agency Caseworker
Organization Name :	SAN DIEGO COUNTY LOP
Address :	P.O. Box 129261
City :	San Diego
Phone Number :	N/R
Email :	tony.sawyer@sdcounty.ca.gov

Regulatory Activities

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Date :	2013-07-15
Global ID :	T0607383730
Action Type :	ENFORCEMENT
Action :	Closure/No Further Action Letter

Date :	2012-01-20
Global ID :	T0607383730
Action Type :	ENFORCEMENT
Action :	Notification - Preclosure

Date :	2011-05-10
Global ID :	T0607383730
Action Type :	ENFORCEMENT
Action :	Warning Letter

Date :	2010-05-21
Global ID :	T0607383730
Action Type :	ENFORCEMENT
Action :	Letter - Notice

Map Id: N110
Direction: ESE
Distance: 0.421 mi., 2223 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : LAS POSAS VENTURE, INC | SAN MARCOS GAS | EXXONMOBIL OIL CORPORATION #12452
1290 W MISSION RD
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_LQG, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 241207
EPA ID: N/R

LUST REG 9 - CA ***(cont.)***

Date : 2009-07-09
Global ID : T0607383730
Action Type : ENFORCEMENT
Action : Letter - Notice

Date : 2006-12-05
Global ID : T0607383730
Action Type : RESPONSE
Action : Preliminary Site Assessment Report - Regulator Responded

Date : 2003-04-15
Global ID : T0607383730
Action Type : ENFORCEMENT
Action : Notice of Responsibility

Date : 2003-04-03
Global ID : T0607383730
Action Type : Other
Action : Leak Reported

Date : 2003-03-18
Global ID : T0607383730
Action Type : Other
Action : Leak Discovery

Date : 2003-03-18
Global ID : T0607383730
Action Type : Other
Action : Leak Stopped

Status History
Status Date : 2013-07-15
Global ID : T0607383730
Status : Completed - Case Closed

Status Date : 2013-06-01
Global ID : T0607383730
Status : Open - Eligible for Closure

Map Id: N110
Direction: ESE
Distance: 0.421 mi., 2223 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : LAS POSAS VENTURE, INC | SAN MARCOS GAS | EXXONMOBIL OIL CORPORATION #12452
1290 W MISSION RD
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_LQG, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 241207
EPA ID: N/R

LUST REG 9 - CA ***(cont.)***

Status Date :	2003-04-15
Global ID :	T0607383730
Status :	Open - Site Assessment

Status Date :	2003-03-18
Global ID :	T0607383730
Status :	Open - Case Begin Date

MANIFEST EPA

Manifest Details

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Manifest Number :	020802530JJK
Shipped Date :	2020-01-07
Updated Date :	2020-02-03
Received Date :	2020-01-17
Status :	Signed
Generator ID :	CAL000375415
Generator Name :	LAS POSAS VENTURE INC
Generator Address :	1290 W MISSION RD, SAN MARCOS, CA 92069-1416
Generator Mailing :	5505 CANCHA DE GOLF, RANCHO SANTA FE, CA 92091-0000
Generator Contact :	N/R
Destination ID :	CAD008252405
Destination Name :	PACIFIC RESOURCE RECOVERY SERVICES INC
Destination Mailing :	3150 EAST PICO BLVD CA90023 CA037US 3150, LOS ANGELES, CA 90023
Destination Address :	3150 EAST PICO BLVD, LOS ANGELES, CA 90023-0000
Destination Contact :	N/R
Submission Type :	DataImage5Copy
Origin Type :	Web
Manifest Residue :	N
Rejection :	N
Last Date in Agency List :	2022-01-14

Waste Details

Waste Line Number :	1
Is DOT Hazardous :	Y
DOT ID Number :	UN1325
DOT Information :	UN1325, WASTE FLAMMABLE SOLID, ORGANIC, N.O.S., (GASOLINE/DIESEL), 4.1, PGII
Non Waste Description :	N/R
Quantity :	90 Pounds

Map Id: N110
Direction: ESE
Distance: 0.421 mi., 2223 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : LAS POSAS VENTURE, INC | SAN MARCOS GAS | EXXONMOBIL OIL CORPORATION #12452
1290 W MISSION RD
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_LQG, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 241207
EPA ID: N/R

MANIFEST EPA ***(cont.)***

Quantity Tons, Acute, Non-Acute :	0.045, 0, 0.045
Quantity Kg, Acute, Non-Acute :	0, 40.816353
Management Method :	H141 - STORAGE, BULKING AND/OR TRANSFER OFF SITE
Is EPA Waste :	Y
Federal Code :	D001, D018
State Code :	CA - 352

Manifest Details

Manifest Number :	020802533JJK
Shipped Date :	2020-01-07
Updated Date :	2020-01-29
Received Date :	2020-01-15
Status :	Signed
Generator ID :	CAL000375415
Generator Name :	LAS POSAS VENTURE INC
Generator Address :	1290 W MISSION RD, SAN MARCOS, CA 92069
Generator Mailing :	1290 W MISSION RD, SAN MARCOS, CA 92069
Generator Contact :	N/R
Destination ID :	CAT080013352
Destination Name :	WORLD OIL RECYCLING
Destination Mailing :	2000 N. ALAMEDA STREET CA90222 CA037US 2000, COMPTON, CA 90222
Destination Address :	2000 N. ALAMEDA STREET, COMPTON, CA 90222-0000
Destination Contact :	N/R
Submission Type :	DataImage5Copy
Origin Type :	Service
Manifest Residue :	N
Rejection :	N
Last Date in Agency List :	2022-01-14

Waste Details

Waste Line Number :	1
Is DOT Hazardous :	Y
DOT ID Number :	UN1203
DOT Information :	UN1203, Waste Gasoline, 3, PG II
Non Waste Description :	N/R
Quantity :	30 Gallons
Quantity Tons, Acute, Non-Acute :	0.12510425, 0, 0.12510425
Quantity Kg, Acute, Non-Acute :	0, 113.47331
Management Method :	H039 - OTHER RECOVERY OR RECLAMATION FOR REUSE
Is EPA Waste :	Y
Federal Code :	D001, D018
State Code :	CA - 343

Map Id: N110
Direction: ESE
Distance: 0.421 mi., 2223 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : LAS POSAS VENTURE, INC | SAN MARCOS GAS | EXXONMOBIL OIL CORPORATION #12452
1290 W MISSION RD
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_LQG, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 241207
EPA ID: N/R

MANIFEST EPA ***(cont.)***

Manifest Details

Manifest Number :	019180903JJK
Shipped Date :	2019-10-09
Updated Date :	2019-11-04
Received Date :	2019-10-11
Status :	Signed
Generator ID :	CAL000375415
Generator Name :	LAS POSAS VENTURE INC
Generator Address :	1290 W MISSION RD, SAN MARCOS, CA 92069-1416
Generator Mailing :	1290 W MISSION RD, SAN MARCOS, CA 92069-1416
Generator Contact :	N/R
Destination ID :	CAT080013352
Destination Name :	WORLD OIL RECYCLING
Destination Mailing :	2000 2000 N. ALAMEDA STREET CA90222 CA037US 2000, COMPTON, CA 90222
Destination Address :	2000 2000 N. ALAMEDA STREET, COMPTON, CA 90222-0000
Destination Contact :	N/R
Submission Type :	DataImage5Copy
Origin Type :	Service
Manifest Residue :	N
Rejection :	N
Last Date in Agency List :	2022-01-14

Waste Details

Waste Line Number :	1
Is DOT Hazardous :	N
DOT ID Number :	N/R
DOT Information :	N/R
Non Waste Description :	Non-RCRA hazardous waste, liquid (oily water)
Quantity :	216 Gallons
Quantity Tons, Acute, Non-Acute :	0.90075064, 0, 0.90075064
Quantity Kg, Acute, Non-Acute :	0, 817.0079
Management Method :	H039 - OTHER RECOVERY OR RECLAMATION FOR REUSE
Is EPA Waste :	N
Federal Code :	N/R
State Code :	CA - 223

Manifest Details

Manifest Number :	019463280JJK
Shipped Date :	2019-09-18
Updated Date :	2019-11-15
Received Date :	2019-09-19
Status :	Signed
Generator ID :	CAL000375415

Map Id: N110
Direction: ESE
Distance: 0.421 mi., 2223 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : LAS POSAS VENTURE, INC | SAN MARCOS GAS | EXXONMOBIL OIL CORPORATION #12452
1290 W MISSION RD
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_LQG, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 241207
EPA ID: N/R

MANIFEST EPA ***(cont.)***

Generator Name :	LAS POSAS VENTURE INC
Generator Address :	1290 W MISSION RD, SAN MARCOS, CA 92069-1416
Generator Mailing :	5505 CANCHA DE GOLF, RANCHO SANTA FE, CA 92091-0000
Generator Contact :	N/R
Destination ID :	AZR000510065
Destination Name :	US FUEL OIL, LLC
Destination Mailing :	8987 W OLIVE AVE STE 117-27, PEORIA, AZ 85345-9125
Destination Address :	3125 W DOME ROCK RD SPC 300, QUARTZSITE, AZ 85346
Destination Contact :	N/R
Submission Type :	DataImage5Copy
Origin Type :	Web
Manifest Residue :	N
Rejection :	N
Last Date in Agency List :	2022-01-14

Waste Details

Waste Line Number :	1
Is DOT Hazardous :	N
DOT ID Number :	N/R
DOT Information :	N/R
Non Waste Description :	NON-RCRA HAZARDOUS WASTE SOLID (SAND BLAST GRIT)
Quantity :	300 Pounds
Quantity Tons, Acute, Non-Acute :	0.15, 0, 0.15
Quantity Kg, Acute, Non-Acute :	0, 136.0545
Management Method :	H141 - STORAGE, BULKING AND/OR TRANSFER OFF SITE
Is EPA Waste :	N
Federal Code :	N/R
State Code :	CA - 352

Manifest Details

Manifest Number :	018182522JJK
Shipped Date :	2019-06-06
Updated Date :	2019-12-12
Received Date :	2019-06-14
Status :	Signed
Generator ID :	CAL000375415
Generator Name :	LAS POSAS VENTURE INC
Generator Address :	1290 W MISSION RD, SAN MARCOS, CA 92069-1416
Generator Mailing :	5505 CANCHA DE GOLF, RANCHO SANTA FE, CA 92091-0000
Generator Contact :	N/R
Destination ID :	CAD008252405
Destination Name :	PACIFIC RESOURCE RECOVERY SERVICES INC
Destination Mailing :	3150 EAST PICO BLVD CA90023 CA037US 3150, LOS ANGELES, CA 90023
Destination Address :	3150 EAST PICO BLVD, LOS ANGELES, CA 90023-0000

Map Id: N110
Direction: ESE
Distance: 0.421 mi., 2223 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : LAS POSAS VENTURE, INC | SAN MARCOS GAS | EXXONMOBIL OIL CORPORATION #12452
1290 W MISSION RD
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_LQG, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 241207
EPA ID: N/R

MANIFEST EPA ***(cont.)***

Destination Contact :	N/R
Submission Type :	DataImage5Copy
Origin Type :	Web
Manifest Residue :	N
Rejection :	N
Last Date in Agency List :	2022-01-14

Waste Details

Waste Line Number :	1
Is DOT Hazardous :	Y
DOT ID Number :	UN1325
DOT Information :	UN1325, WASTE FLAMMABLE SOLID, ORGANIC NOS, (GASOLINE/DIESEL), 4.1, PGII
Non Waste Description :	N/R
Quantity :	300 Pounds
Quantity Tons, Acute, Non-Acute :	0.15, 0, 0.15
Quantity Kg, Acute, Non-Acute :	0, 136.0545
Management Method :	H141 - STORAGE, BULKING AND/OR TRANSFER OFF SITE
Is EPA Waste :	Y
Federal Code :	D001, D018
State Code :	CA - 352

RCRA_LQG

Facility Name :	EXXONMOBIL OIL CORP.
Facility Address :	1290 W MISSION RD, SAN MARCOS, CA 92069
County :	SAN DIEGO
Date Form Received by Agency :	2002-02-28
EPA ID :	CAL000098361
Mailing Address :	12265 WEST BAYAUD AVE., LAKEWOOD, CO 80228
Contact :	JOHN HOOVER
Contact Address :	N/R
Contact Country :	US
Contact Telephone :	800-253-8054
Contact Email :	N/R
EPA Region :	09
Land Type :	Private
Source Type :	Annual/Biennial Report
Classification :	Large Quantity Generator

Map Id: N110
Direction: ESE
Distance: 0.421 mi., 2223 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : LAS POSAS VENTURE, INC | SAN MARCOS GAS | EXXONMOBIL OIL CORPORATION #12452
1290 W MISSION RD
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_LQG, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 241207
EPA ID: N/R

RCRA_LQG ***(cont.)***

Description :

Handlers that generate 1,000 kg or more of hazardous waste during any calendar month; or generate more than 1 kg of acutely hazardous waste during any calendar month; or generate more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generate 1 kg or less of acutely hazardous waste during any calendar month, and accumulate more than 1 kg of acutely hazardous waste at any time; or generate 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulated more than 100 kg of that material at any time.

Last Date in Agency List : 2022-01-25

Owner/Operator Summary

Owner/Operator Name :	EXXONMOBIL OIL CORP.
Owner/Operator Address :	N/R
Owner/Operator Country :	US
Owner/Operator Telephone :	N/R
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Private
Owner/Operator Type :	Owner
Owner/Operator Start Date :	2002-05-31
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Map Id: N110
Direction: ESE
Distance: 0.421 mi., 2223 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : LAS POSAS VENTURE, INC | SAN MARCOS GAS | EXXONMOBIL OIL CORPORATION #12452
1290 W MISSION RD
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_LQG, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 241207
EPA ID: N/R

RCRA_LQG ***(cont.)***

Hazardous Waste Summary

Waste Code / Name :	223 - Unspecified oil-containing waste D001 - IGNITABLE WASTE

Notices of Violations Summary

Regulation Violated :	N

RCRA_NONGEN

Facility Name :	LAS POSAS VENTURE INC
Facility Address :	1290 W MISSION RD, SAN MARCOS, CA 92069-1416
County :	SAN DIEGO
Date Form Received by Agency :	2012-06-19
EPA ID :	CAL000375415
Mailing Address :	5505 CANCHA DE GOLF, RANCHO SANTA FE, CA 92091-0000
Contact :	PHILIP MOORE
Contact Address :	1290 W MISSION RD., SAN MARCOS, CA 92069
Contact Country :	N/R
Contact Telephone :	760-224-2890
Contact Email :	INFO@RELYENVIRONMENTAL.COM
EPA Region :	09
Land Type :	Not Reported
Source Type :	Implementer
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2022-01-26

Owner/Operator Summary

Owner/Operator Name :	LAS POSAS VENTURE, INC
Owner/Operator Address :	5505 CANCHA DE GOLF, RANCHO SANTA FE, CA 92091-0000
Owner/Operator Country :	N/R
Owner/Operator Telephone :	858-755-0216
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R
Owner/Operator Name :	PHILIP MOORE
Owner/Operator Address :	1290 W MISSION RD., SAN MARCOS, CA 92069

Map Id: N110
Direction: ESE
Distance: 0.421 mi., 2223 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : LAS POSAS VENTURE, INC | SAN MARCOS GAS | EXXONMOBIL OIL CORPORATION #12452
1290 W MISSION RD
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_LQG, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 241207
EPA ID: N/R

RCRA_NONGEN ***(cont.)***

Owner/Operator Country :	N/R
Owner/Operator Telephone :	760-224-2890
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Notices of Violations Summary

Regulation Violated :	N

UST - CA

Facility Name :	LAS POSAS VENTURE, INC
Facility Address :	1290 W MISSION RD, SAN MARCOS, 92069
County :	San Diego
Facility ID :	37-000-215691
CERS ID :	10376581
Permitting Agency :	San Diego County Department of Environmental Health
Latitude :	33.14856
Longitude :	-117.18822
Last Date in Agency List :	2022-03-07

Map Id: N110
Direction: ESE
Distance: 0.421 mi., 2223 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : LAS POSAS VENTURE, INC | SAN MARCOS GAS | EXXONMOBIL OIL CORPORATION #12452
1290 W MISSION RD
SAN MARCOS, CA

Database(s) : [BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ECHO, EPA LUST, EPA UST, FID UST - CA, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, LUST REG 9 - CA, MANIFEST EPA, RCRA_LQG, RCRA_NONGEN, UST - CA] ***(cont.)***

Envirosite ID: 241207
EPA ID: N/R

UST - CA ***(cont.)***

Facility Name :	MOBIL OIL CORPORATION
Facility Address :	1290 W MISSION RD, SAN MARCOS, 92069
County :	San Diego
Facility ID :	H25233
CERS ID :	N/R
Permitting Agency :	SAN DIEGO COUNTY
Latitude :	33.149909
Longitude :	-117.186877
Last Date in Agency List :	2017-01-13

Map Id: 111
Direction: SE
Distance: 0.426 mi., 2248 ft.
Elevation: 555 ft.
Relative: Lower

Site Name : BAJA PACIFIC | TIAGO INC | SINGH GROUP INC DBA BAJA PACIFIC
1308 DECANSO AVE | 1308 DESCANSO AVE
SAN MARCOS | San Marcos, CA 92069

Database(s) : [ECHO, FRS, HAULERS - CA, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, HWT - CA, RCRA_NONGEN]

Envirosite ID: 279722
EPA ID: CAL000294570

ECHO

Facility Name :	BAJA PACIFIC
Facility Address :	1308 DECANSO AVE, SAN MARCOS, CA 92069
County :	SAN DIEGO
Last Inspection Date :	N/R
Registry ID :	110070457129
FIPS Code :	N/R
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	N/R
Informal Count :	0
Last Informal Action Date :	N/R
Formal Action Count :	0
Last Formal Action Date :	N/R
Total Penalties :	0
Penalty Count :	N/R

Map Id: 111
Direction: SE
Distance: 0.426 mi., 2248 ft.
Elevation: 555 ft.
Relative: Lower

Site Name : BAJA PACIFIC | TIAGO INC | SINGH GROUP INC DBA BAJA PACIFIC
1308 DECANSO AVE | 1308 DESCANSO AVE
SAN MARCOS | San Marcos, CA 92069

Database(s) : [ECHO, FRS, HAULERS - CA, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, HWT - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 279722
EPA ID: CAL000294570

ECHO ***(cont.)***

Last Penalty Date :	N/R
Last Penalty Amount :	N/R
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	_____
Collection Method :	Zip Code Centroid
Reference Point :	N/R
Accuracy Meters :	10000
Derived Tribes :	N/R
Derived HUC :	N/R
Derived WBD :	N/R
Derived STCTY FIPS :	N/R
Derived Zip :	N/R
Derived CD113 :	N/R
Derived CB2010 :	N/R
MYRTK Universe :	NNN
NPDES IDs :	N/R
CWA Permit Types :	N/R
CWA Compliance Tracking :	N/R
CWA NAICS :	N/R
CWA SICS :	N/R
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	N/R
CWA Current Compliance Status :	N/R
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	N/R
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	N/R
Facility NAICS :	48423 - Specialized Freight (except Used Goods) Trucking, Long-Distance
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	N/R
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	N/R
Facility Last Informal Act EPA Date :	N/R
Facility Last Informal Act State Date:	N/R
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	N/R

Map Id: 111
Direction: SE
Distance: 0.426 mi., 2248 ft.
Elevation: 555 ft.
Relative: Lower

Site Name : BAJA PACIFIC | TIAGO INC | SINGH GROUP INC DBA BAJA PACIFIC
1308 DECANSO AVE | 1308 DESCANSO AVE
SAN MARCOS | San Marcos, CA 92069

Database(s) : [ECHO, FRS, HAULERS - CA, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, HWT - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 279722
EPA ID: CAL000294570

ECHO ***(cont.)***

Chesapeak Bay Flag :	N/R
AIR Flag :	N
NPDES Flag :	N
SDWIS Flag :	N
RCRA Flag :	Y
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	Y
NAA Flag :	N
Latitude :	33.194075
Longitude :	-117.16177
Last Date in Agency List :	2022-01-17

FRS

Facility Name :	BAJA PACIFIC
Facility Address :	1308 DECANSO AVE, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Registry ID :	110070457129
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Source Description

Source Description :

RCRAInfo is EPA's comprehensive information system that supports the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984 through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA. RCRAInfo also supports generation of the National Hazardous Waste Biennial Report. All generators and treatment, storage, and disposal facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years to support creation of the Biennial Report.

FRS Environmental Interest

Source and System ID :	RCRAINFO - CAL000294570

HAULERS - CA

Facility Name :	Singh Group Inc.
Facility Address :	1308 Descanso Avenue, San Marcos, CA 92069
County :	N/R

Map Id: 111
Direction: SE
Distance: 0.426 mi., 2248 ft.
Elevation: 555 ft.
Relative: Lower

Site Name : BAJA PACIFIC | TIAGO INC | SINGH GROUP INC DBA BAJA PACIFIC
1308 DECANSO AVE | 1308 DESCANSO AVE
SAN MARCOS | San Marcos, CA 92069

Database(s) : [ECHO, FRS, HAULERS - CA, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, HWT - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 279722
EPA ID: CAL000294570

HAULERS - CA ***(cont.)***

Site Details

Site Number :	1926717
Site Type :	Hauler Main Site
Site Status :	Active
Contact :	Adolf Singh
Phone :	(760) 213-5462
Current Status :	N/R
End Use :	N/R
Generator :	Small Quantity
Accepting Tires from Public :	No
Last Date in Agency List :	2022-01-20

Additional Details

Current Hauler Status :	N/R
Primary Contact Person :	N/R
Primary Mailing Address :	N/R
Primary Mailing Phone Number :	N/R
Website :	N/R

Permit/Authority Details

Regulatory Status Last Changed/Issued On:	N/R
Current Site Regulatory Status :	N/R
Maximum Number of Tires Permitted :	N/R
Business Types :	N/R

HAZMAT_SAN DIEGO COUNTY - CA

Facility Name :	SINGH GROUP, INC
Facility Address :	1308 DESCANSO AVE, SAN MARCOS, CA 92069
Date :	2011-03-03
Record ID :	DEH2011-HUPFP-214216
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23
Facility Name :	TIAGO INC
Facility Address :	1308 DESCANSO AVE, SAN MARCOS, CA 92069
Date :	2002-05-04
Record ID :	DEH2002-HUPFP-106201

Map Id: 111
Direction: SE
Distance: 0.426 mi., 2248 ft.
Elevation: 555 ft.
Relative: Lower

Site Name : BAJA PACIFIC | TIAGO INC | SINGH GROUP INC DBA BAJA PACIFIC
1308 DECANSO AVE | 1308 DESCANSO AVE
SAN MARCOS | San Marcos, CA 92069

Database(s) : [ECHO, FRS, HAULERS - CA, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, HWT - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 279722
EPA ID: CAL000294570

HAZMAT_SAN DIEGO COUNTY - CA ***(cont.)***

Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23

HAZNET - CA

Facility Name :	SINGH GROUP INC DBA BAJA PACIFIC
Facility Address :	1308 DECANSO AVE, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000294570
Active :	Active
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	1308 DECANSO AVE, SAN MARCOS, CA 92069
Latitude :	33.14605386
Longitude :	-117.19046763
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Facility Name :	TIAGO INC
Facility Address :	1308 DESCANSO AVE, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAL000214886
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	120 N PACIFIC ST STE L4, SAN MARCOS, CA 920691269
Latitude :	33.14605386
Longitude :	-117.19046763
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Map Id: 111
Direction: SE
Distance: 0.426 mi., 2248 ft.
Elevation: 555 ft.
Relative: Lower

Site Name : BAJA PACIFIC | TIAGO INC | SINGH GROUP INC DBA BAJA PACIFIC
1308 DECANSO AVE | 1308 DESCANSO AVE
SAN MARCOS | San Marcos, CA 92069

Database(s) : [ECHO, FRS, HAULERS - CA, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, HWT - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 279722
EPA ID: CAL000294570

HAZNET - CA ***(cont.)***

Waste Generator Details
State Waste : 2010: 343 - Unspecified organic liquid mixture, 0.187 tons to CAT080013352
2010: 352 - Other organic solids, 0.55 tons to CAD097030993
2007: 352 - Other organic solids, 0.15 tons to CAD097030993
1999: 611 - Contaminated soil from site clean-up, 0.4 tons to CAD982444481

HWG - CA

Facility Name : SINGH GROUP INC DBA BAJA PACIFIC
Facility Address : 1308 DECANSO AVE, SAN MARCOS, CA 92069
County : SAN DIEGO

EPA ID : CAL000294570
Status : Active
Category : STATE
Type : PERMANENT
Facility Type : N/R
Mailing Address : 1308 DECANSO AVE, SAN MARCOS, CA 92069
Owner Name : SINGH GROUP INC./ADOLF SINGH
Owner Address : 1308 DECANSO AVE, SAN MARCOS, CA 92069
Operator Name : ADOLF SINGH/PRES
Operator Address : 1308 DECANSO AVE, SAN MARCOS, CA 92069
Latitude : 33.20126
Longitude : -117.33696

Facility Name : TIAGO INC
Facility Address : 1308 DESCANSO AVE, SAN MARCOS, CA 92069
County : SAN DIEGO

EPA ID : CAL000214886
Status : Inactive
Category : STATE
Type : PERMANENT
Facility Type : N/R
Mailing Address : 120 N PACIFIC ST STE L4, SAN MARCOS, CA 920691269
Owner Name : TIAGO INC
Owner Address : 1308 DESCANSO AVE, SAN MARCOS, CA 920690000
Operator Name : CAROL DILORETO/ADMIN
Operator Address : 1308 DESCANSO AVE, SAN MARCOS, CA 920690000
Latitude : 33.14627
Longitude : -117.1904

HWT - CA

Facility Name : BAJA PACIFIC
Facility Address : 1308 DESCANSO AVE, SAN MARCOS, CA 92069

Map Id: 111
Direction: SE
Distance: 0.426 mi., 2248 ft.
Elevation: 555 ft.
Relative: Lower

Site Name : BAJA PACIFIC | TIAGO INC | SINGH GROUP INC DBA BAJA PACIFIC
1308 DECANSO AVE | 1308 DESCANSO AVE
SAN MARCOS | San Marcos, CA 92069

Database(s) : [ECHO, FRS, HAULERS - CA, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, HWT - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 279722
EPA ID: CAL000294570

HWT - CA ***(cont.)***

County :	SAN DIEGO
Expiration Date :	2022-02-28
Registration Number :	4695
Last Date in Agency List :	2022-02-04

RCRA_NONGEN

Facility Name :	BAJA PACIFIC
Facility Address :	1308 DECANSO AVE, SAN MARCOS, CA 92069
County :	SAN DIEGO
Date Form Received by Agency :	2005-05-25
EPA ID :	CAL000294570
Mailing Address :	1308 DECANSO AVE, SAN MARCOS, CA 92069
Contact :	ADOLF SINGH/PRES
Contact Address :	1308 DECANSO AVE, SAN MARCOS, CA 92069
Contact Country :	N/R
Contact Telephone :	760-213-5462
Contact Email :	ADOLF@SGIWEBSITE.COM
EPA Region :	09
Land Type :	Not Reported
Source Type :	Implementer
Classification :	Not a generator, verified
Description :	Not a generator, verified
Last Date in Agency List :	2022-01-26

Owner/Operator Summary

Owner/Operator Name :	ADOLF SINGH/PRES
Owner/Operator Address :	1308 DECANSO AVE, SAN MARCOS, CA 92069
Owner/Operator Country :	N/R
Owner/Operator Telephone :	760-213-5462
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type
Owner/Operator Type :	Operator
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R
Owner/Operator Name :	SINGH GROUP INC./ADOLF SINGH
Owner/Operator Address :	1308 DECANSO AVE, SAN MARCOS, CA 92069
Owner/Operator Country :	N/R
Owner/Operator Telephone :	760-213-5462
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Other land type

Map Id: 111
Direction: SE
Distance: 0.426 mi., 2248 ft.
Elevation: 555 ft.
Relative: Lower

Site Name : BAJA PACIFIC | TIAGO INC | SINGH GROUP INC DBA BAJA PACIFIC
1308 DECANSO AVE | 1308 DESCANSO AVE
SAN MARCOS | San Marcos, CA 92069

Database(s) : [ECHO, FRS, HAULERS - CA, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, HWT - CA, RCRA_NONGEN] ***(cont.)***

Envirosite ID: 279722
EPA ID: CAL000294570

RCRA_NONGEN ***(cont.)***

Owner/Operator Type :	Owner
Owner/Operator Start Date :	N/R
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	Y
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Notices of Violations Summary

Regulation Violated :	N

Map Id: 112
Direction: NW
Distance: 0.445 mi., 2349 ft.
Elevation: 497 ft.
Relative: Lower

Site Name : GOURMET LIQUOR 100944 | EZ SERVE 100944 | RESTRUCTURE PETROLEUM MARKETING SRVS
2966 S SANTA FE AVE
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, EPA LUST, FRS, HAZNET - CA, HWG - CA, LUST REG 9 - CA]

Envirosite ID: 257430
EPA ID: CAL000310461

CALEPA SITES - CA

Facility Name :	GOURMET LIQUOR 100944
Facility Address :	2966 S SANTA FE AV, SAN MARCOS, 920696049

Map Id: 112
Direction: NW
Distance: 0.445 mi., 2349 ft.
Elevation: 497 ft.
Relative: Lower

Site Name : GOURMET LIQUOR 100944 | EZ SERVE 100944 | RESTRUCTURE PETROLEUM MARKETING SRVS
2966 S SANTA FE AVE
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, EPA LUST, FRS, HAZNET - CA, HWG - CA, LUST REG 9 - CA] ***(cont.)***

Envirosite ID: 257430
EPA ID: CAL000310461

CALEPA SITES - CA ***(cont.)***

Site ID :	256890
EI ID :	T0607300358
EI Description :	Leaking Underground Storage Tank Cleanup Site
Latitude :	33.157319
Longitude :	-117.200388
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07

CASE LIST_SAN DIEGO COUNTY - CA

Facility Name :	GOURMET LIQUOR 100944
Facility Address :	2966 S SANTA FE AV, SAN MARCOS, CA 920696049
County :	San Diego

Site Details

Status Date :	2017-11-01
Status :	Completed - Case Closed
Begin Date :	1986-04-25
Global ID :	T0607300358

Site History :

An unauthorized release case was opened for the site after routine tank testing in April 1986 indicated that leaks were occurring from an 8,000-gallon (also reported as 6,000 gallons) gasoline underground storage tank (UST). The UST and a second 10,000-gallon gasoline UST were removed from a common excavation on July 18, 1986. Numerous holes were present in both USTs, and free product was observed in the excavation. Laboratory analysis of the soil sample collected in the UST excavation showed a total extractable hydrocarbons concentration of 661 milligrams per kilogram (mg/kg). On January 30, 1996, a 15,000-gallon compartmentalized (7,500 gallon/7,500 gallons) UST was removed from the site. Soil staining and strong petroleum odors were observed, but no holes were noted in the tank. There are currently no USTs or dispenser islands on the property, and a commercial business occupies the building. Between August 1986 and April 2016, thirty-two groundwater monitoring wells were installed onsite and offsite to delineate the extent of contamination. Groundwater beneath the site has been designated as beneficial for municipal, agricultural, and industrial uses. The primary contaminants of concern identified in soil and groundwater include benzene, toluene, ethylbenzene, and xylenes (BTEX), methyl tertiary butyl ether (MTBE), and total petroleum hydrocarbons in the gasoline range (TPH-g). In 2001, approximately 1,519.37 tons of petroleum hydrocarbon-impacted soil were excavated and transported offsite to a licensed disposal facility. The excavated areas included the former fuel dispenser island and UST locations. Excavation base and sidewall soil samples were collected, and the consultant concluded that the majority of the TPH-g impacted soil had been removed. In 2011, a vapor risk assessment was conducted to evaluate whether the migration of petroleum hydrocarbon vapors is a potential health risk to the on-site building occupants. BTEX, naphthalene, and fuel oxygenates were not detected, and no significant risks were identified based on commercial use of the property. No groundwater production wells or sensitive receptors were identified within a 2500-foot radius of the site in a 2011 sensitive receptor survey. A December 2016 Corrective Action Plan (CAP) and a March 2017 CAP Addendum were prepared. The groundwater cleanup goals identified in the CAP were the California maximum contaminant levels (MCLs) for drinking water. The maximum benzene concentration reported in the most recent sampling event was 2,000 micrograms per liter (g/l) in a monitoring well located near the center of the plume. The consultant estimates that the timeline for dissolved benzene to reach its MCL of 1 g/l is approximately 60 years. Free product was previously observed in several wells, with a maximum thickness of 6.59 feet. There has been no documented free product reported at the site since 2001. The consultant concludes that the dissolved plume

Map Id: 112
Direction: NW
Distance: 0.445 mi., 2349 ft.
Elevation: 497 ft.
Relative: Lower

Site Name : GOURMET LIQUOR 100944 | EZ SERVE 100944 | RESTRUCTURE PETROLEUM MARKETING SRVS
2966 S SANTA FE AVE
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, EPA LUST, FRS, HAZNET - CA, HWG - CA, LUST REG 9 - CA] ***(cont.)***

Envirosite ID: 257430
EPA ID: CAL000310461

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

beneath the site is stable and decreasing via natural attenuation, and recommends case closure under the State Water Resources Control BoardÆs Low-Threat UST Case Closure Policy (LTCP). A 60-day public notification period was completed to allow public review and comments on the CAP/CAP Addendum and DEHÆs intent to close the case. No comments were received. The nineteen remaining groundwater monitoring wells and two extraction wells associated with the site will be destroyed under permit number DEH2017-LMWP-003155.

RB Case Number :	9UT154
Potential Media Affected :	Aquifer used for drinking water supply
Potential Contaminants of Concern :	Gasoline
Local Agency :	SAN DIEGO COUNTY LOP
Local Case Number :	H20986-001
Lead Agency :	SAN DIEGO COUNTY LOP
File Location :	Local Agency
CUF Case :	YES
Caseworker :	TS
Case Type :	LUST Cleanup Site
How Discovered :	UST System Modification
How Discovered Description :	N/R
Stop Method :	Close and Replace Tank
Stop Description :	CLOSE AND REPLACE TANK
Calwater Watershed Name :	Carlsbad - Agua Hedionda - Buena (904.32)
DWR Groundwater Subbasin Name :	N/R
Disadvantaged Community :	N/R
Latitude :	33.157319
Longitude :	-117.200388
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-09

Contacts Summary

Global ID :	T0607300358
Contact Name :	TERESA SHERMAN
Contact Type :	Local Agency Caseworker
Organization Name :	SAN DIEGO COUNTY LOP
Address :	P.O. Box 129261
City :	San Diego
Phone Number :	N/R
Email :	teresa.sherman@sdcounty.ca.gov

Regulatory Activities

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Date :	2017-11-01
Global ID :	T0607300358
Action Type :	ENFORCEMENT

Map Id: 112
Direction: NW
Distance: 0.445 mi., 2349 ft.
Elevation: 497 ft.
Relative: Lower

Site Name : GOURMET LIQUOR 100944 | EZ SERVE 100944 | RESTRUCTURE PETROLEUM MARKETING SRVS
2966 S SANTA FE AVE
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, EPA LUST, FRS, HAZNET - CA, HWG - CA, LUST REG 9 - CA] ***(cont.)***

Envirosite ID: 257430
EPA ID: CAL000310461

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Action :	Closure/No Further Action Letter
Date :	2017-10-19
Global ID :	T0607300358
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other
Date :	2017-09-07
Global ID :	T0607300358
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other
Date :	2017-08-23
Global ID :	T0607300358
Action Type :	RESPONSE
Action :	Other Report / Document - Regulator Responded
Date :	2017-03-21
Global ID :	T0607300358
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other
Date :	2017-03-06
Global ID :	T0607300358
Action Type :	RESPONSE
Action :	Corrective Action Plan / Remedial Action Plan - Addendum - Regulator Responded
Date :	2017-01-27
Global ID :	T0607300358
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other
Date :	2016-12-21
Global ID :	T0607300358
Action Type :	RESPONSE
Action :	Corrective Action Plan / Remedial Action Plan - Regulator Responded
Date :	2016-12-21
Global ID :	T0607300358
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other

Map Id: 112
Direction: NW
Distance: 0.445 mi., 2349 ft.
Elevation: 497 ft.
Relative: Lower

Site Name : GOURMET LIQUOR 100944 | EZ SERVE 100944 | RESTRUCTURE PETROLEUM MARKETING SRVS
2966 S SANTA FE AVE
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, EPA LUST, FRS, HAZNET - CA, HWG - CA, LUST REG 9 - CA] ***(cont.)***

Envirosite ID: 257430
EPA ID: CAL000310461

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Date :	2016-12-20
Global ID :	T0607300358
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other

Status History

Status Date :	2017-11-01
Global ID :	T0607300358
Status :	Completed - Case Closed
Status Date :	2017-10-19
Global ID :	T0607300358
Status :	Open - Eligible for Closure
Status Date :	2008-01-08
Global ID :	T0607300358
Status :	Open - Verification Monitoring
Status Date :	1986-04-25
Global ID :	T0607300358
Status :	Open - Case Begin Date

EPA LUST

Facility Name :	GOURMET LIQUOR 100944
Facility Address :	2966 S SANTA FE AV, SAN MARCOS, California 920696049
County :	N/R
Facility ID :	N/R
LUST ID :	CAT0607300358
Reported Date :	N/R
Status :	No Further Action
Substance :	N/R
Closed With Residual Contamination (Tribal Only):	N/R
NFA_Letter (Tribal Only) :	N/R
Tribe (Tribal Only) :	N/R
EPA Region :	9
Estimated Population within 1500ft :	2881
Estimated Private Domestic Wells within 1500ft:	0
Within Source Water Protection Area (SPA):	No
SPA Public Water System and Facility ID:	N/R
SPA Water Type :	N/R

Map Id: 112
Direction: NW
Distance: 0.445 mi., 2349 ft.
Elevation: 497 ft.
Relative: Lower

Site Name : GOURMET LIQUOR 100944 | EZ SERVE 100944 | RESTRUCTURE PETROLEUM MARKETING SRVS
2966 S SANTA FE AVE
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, EPA LUST, FRS, HAZNET - CA, HWG - CA, LUST REG 9 - CA] ***(cont.)***

Envirosite ID: 257430
EPA ID: CAL000310461

EPA LUST ***(cont.)***

SPA Facility Type :	N/R
SPA HUC12 :	N/R
Within Groundwater Wellhead Protection Area (WHPA):	No
WHPA Public Water System and Facility ID:	N/R
WHPA Water Type :	N/R
WHPA Facility Type :	N/R
WHPA HUC12 :	N/R
Within Estimated 100-year Floodplain:	No
Latitude :	33.157119999999900
Longitude :	-117.200609999999003
Last Date in Agency List :	2022-01-04

FRS

Facility Name :	GOURMET LIQUOR 100944
Facility Address :	2966 S SANTA FE AV, SAN MARCOS, CA 920696049
County :	SAN DIEGO

Site Details

Registry ID :	110066529518
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Source Description

Source Description :

The California Environmental Protection Agency (CalEPA) has recently implemented a new data warehouse system (nSite). This data warehouse combines and merges facility and site information from five different systems managed within CalEPA. The five systems are: California Environmental Reporting System (CERS), EnviroStor, GeoTracker, California Integrated Water Quality System (CIWQS), and Toxic Release Inventory (TRI).

FRS Environmental Interest

Source and System ID :	CA-ENVIROVIEW - 256890

HAZNET - CA

Facility Name :	EZ SERVE 100944
Facility Address :	2966 S SANTA FE AVE, SAN MARCOS, CA 92069
County :	SAN DIEGO

Map Id: 112
Direction: NW
Distance: 0.445 mi., 2349 ft.
Elevation: 497 ft.
Relative: Lower

Site Name : GOURMET LIQUOR 100944 | EZ SERVE 100944 | RESTRUCTURE PETROLEUM MARKETING SRVS
2966 S SANTA FE AVE
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, EPA LUST, FRS, HAZNET - CA, HWG - CA, LUST REG 9 - CA] ***(cont.)***

Envirosite ID: 257430
EPA ID: CAL000310461

HAZNET - CA ***(cont.)***

Site Details

Generator EPA ID :	CAL000310461
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	27141 ALISO CREEK RD STE 270, ALISO VIEJO, CA 92656
Latitude :	33.15716524
Longitude :	-117.20058493
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08
Facility Name :	RESTRUCTURE PETROLEUM MARKETING SRVS
Facility Address :	2966 S SANTA FE AVE, SAN MARCOS, CA 92101
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAC002201289
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	205 S HOOVER BLVD #101, TAMPLA, FL 336090000
Latitude :	33.15716524
Longitude :	-117.20058493
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	1999: 135 - Unspecified aqueous solution, 0.231 tons to CAD028409019
Facility Name :	RESTRUCTURE PETROLEUM MARKETING SVCS
Facility Address :	2966 S SANTA FE AVE, SAN MARCOS, CA 92101
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAC002483295
Active :	Inactive
Category :	STATE

Map Id: 112
Direction: NW
Distance: 0.445 mi., 2349 ft.
Elevation: 497 ft.
Relative: Lower

Site Name : GOURMET LIQUOR 100944 | EZ SERVE 100944 | RESTRUCTURE PETROLEUM MARKETING SRVS
2966 S SANTA FE AVE
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, EPA LUST, FRS, HAZNET - CA, HWG - CA, LUST REG 9 - CA] ***(cont.)***

Envirosite ID: 257430
EPA ID: CAL000310461

HAZNET - CA ***(cont.)***

Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	205 HOOVER BLVD STE 101, TAMPA, FL 336070000
Latitude :	33.15716524
Longitude :	-117.20058493
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

HWG - CA

Facility Name :	EZ SERVE 100944
Facility Address :	2966 S SANTA FE AVE, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAL000310461
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	27141 ALISO CREEK RD STE 270, ALISO VIEJO, CA 92656
Owner Name :	RESTRUCTURE PETROLEUM MKTG SERV INC
Owner Address :	205 S HOOVER BLVD, TAMPA, FL 336093500
Operator Name :	SHEILA ROGAN
Operator Address :	27141 ALISO CREEK RD STE 270, ALISO VIEJO, CA 92656
Latitude :	33.157092
Longitude :	-117.200771

Facility Name :	RESTRUCTURE PETROLEUM MARKETING SRVS
Facility Address :	2966 S SANTA FE AVE, SAN MARCOS, CA 92101
County :	SAN DIEGO
EPA ID :	CAC002201289
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	205 S HOOVER BLVD #101, TAMPLA, FL 336090000
Owner Name :	RESTRUCTURE PETROLEUM MKTG SRV
Owner Address :	205 S HOOVER BLVD #101, TAMPLA, FL 336090000
Operator Name :	HEIDE BAUER
Operator Address :	205 S HOOVER BLVD #101, TAMPLA, FL 336090000
Latitude :	34.191513
Longitude :	-118.229282

Map Id: 112
Direction: NW
Distance: 0.445 mi., 2349 ft.
Elevation: 497 ft.
Relative: Lower

Site Name : GOURMET LIQUOR 100944 | EZ SERVE 100944 | RESTRUCTURE PETROLEUM MARKETING SRVS
2966 S SANTA FE AVE
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, EPA LUST, FRS, HAZNET - CA, HWG - CA, LUST REG 9 - CA] ***(cont.)***

Envirosite ID: 257430
EPA ID: CAL000310461

HWG - CA ***(cont.)***

Facility Name :	RESTRUCTURE PETROLEUM MARKETING SVCS
Facility Address :	2966 S SANTA FE AVE, SAN MARCOS, CA 92101
County :	SAN DIEGO
EPA ID :	CAC002483295
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	205 HOOVER BLVD STE 101, TAMPA, FL 336070000
Owner Name :	RESTRUCTURE PETROLEUM MARKETIN
Owner Address :	205 HOOVER BLVD STE 101, TAMPA, FL 336070000
Operator Name :	SCOTT FLETCHER/BELSHIRE
Operator Address :	25422 TRABUCO RD STE 105-269, LAKE FOREST, CA 926300000
Latitude :	34.191513
Longitude :	-118.229282

LUST REG 9 - CA

Facility Name :	GOURMET LIQUOR 100944
Facility Address :	2966 S SANTA FE AV, SAN MARCOS, CA 920696049
County :	San Diego

Site Details

Status Date :	2017-11-01
Status :	Completed - Case Closed
Begin Date :	1986-04-25
Global ID :	T0607300358
Region :	REGION 9

Site History :

An unauthorized release case was opened for the site after routine tank testing in April 1986 indicated that leaks were occurring from an 8,000-gallon (also reported as 6,000 gallons) gasoline underground storage tank (UST). The UST and a second 10,000-gallon gasoline UST were removed from a common excavation on July 18, 1986. Numerous holes were present in both USTs, and free product was observed in the excavation. Laboratory analysis of the soil sample collected in the UST excavation showed a total extractable hydrocarbons concentration of 661 milligrams per kilogram (mg/kg). On January 30, 1996, a 15,000-gallon compartmentalized (7,500 gallon/7,500 gallons) UST was removed from the site. Soil staining and strong petroleum odors were observed, but no holes were noted in the tank. There are currently no USTs or dispenser islands on the property, and a commercial business occupies the building. Between August 1986 and April 2016, thirty-two groundwater monitoring wells were installed onsite and offsite to delineate the extent of contamination. Groundwater beneath the site has been designated as beneficial for municipal, agricultural, and industrial uses. The primary contaminants of concern identified in soil and groundwater include benzene, toluene, ethylbenzene, and xylenes (BTEX), methyl tertiary butyl ether (MTBE), and total petroleum hydrocarbons in the gasoline range (TPH-g). In 2001, approximately 1,519.37 tons of petroleum hydrocarbon-impacted soil were excavated and transported offsite to a licensed disposal facility. The excavated areas included the former fuel dispenser island and UST locations. Excavation base and sidewall soil samples were collected, and the consultant concluded that the majority of the TPH-g impacted soil

Map Id: 112
Direction: NW
Distance: 0.445 mi., 2349 ft.
Elevation: 497 ft.
Relative: Lower

Site Name : GOURMET LIQUOR 100944 | EZ SERVE 100944 | RESTRUCTURE PETROLEUM MARKETING SRVS
2966 S SANTA FE AVE
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, EPA LUST, FRS, HAZNET - CA, HWG - CA, LUST REG 9 - CA] ***(cont.)***

Envirosite ID: 257430
EPA ID: CAL000310461

LUST REG 9 - CA ***(cont.)***

had been removed. In 2011, a vapor risk assessment was conducted to evaluate whether the migration of petroleum hydrocarbon vapors is a potential health risk to the on-site building occupants. BTEX, naphthalene, and fuel oxygenates were not detected, and no significant risks were identified based on commercial use of the property. No groundwater production wells or sensitive receptors were identified within a 2500-foot radius of the site in a 2011 sensitive receptor survey. A December 2016 Corrective Action Plan (CAP) and a March 2017 CAP Addendum were prepared. The groundwater cleanup goals identified in the CAP were the California maximum contaminant levels (MCLs) for drinking water. The maximum benzene concentration reported in the most recent sampling event was 2,000 micrograms per liter (g/l) in a monitoring well located near the center of the plume. The consultant estimates that the timeline for dissolved benzene to reach its MCL of 1 g/l is approximately 60 years. Free product was previously observed in several wells, with a maximum thickness of 6.59 feet. There has been no documented free product reported at the site since 2001. The consultant concludes that the dissolved plume beneath the site is stable and decreasing via natural attenuation, and recommends case closure under the State Water Resources Control BoardÆs Low-Threat UST Case Closure Policy (LTCP). A 60-day public notification period was completed to allow public review and comments on the CAP/CAP Addendum and DEHÆs intent to close the case. No comments were received. The nineteen remaining groundwater monitoring wells and two extraction wells associated with the site will be destroyed under permit number DEH2017-LMWP-003155.

RB Case Number :	9UT154
Potential Media Affected :	Aquifer used for drinking water supply
Potential Contaminants of Concern :	Gasoline
Local Agency :	SAN DIEGO COUNTY LOP
Local Case Number :	H20986-001
Lead Agency :	SAN DIEGO COUNTY LOP
File Location :	Local Agency
CUF Case :	YES
Caseworker :	TS
Case Type :	LUST Cleanup Site
How Discovered :	UST System Modification
How Discovered Description :	N/R
Stop Method :	Close and Replace Tank
Stop Description :	CLOSE AND REPLACE TANK
Calwater Watershed Name :	Carlsbad - Agua Hedionda - Buena (904.32)
DWR Groundwater Subbasin Name :	N/R
Disadvantaged Community :	N/R
Latitude :	33.157319
Longitude :	-117.200388
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-11

Contacts Summary

Global ID :	T0607300358
Contact Name :	TERESA SHERMAN
Contact Type :	Local Agency Caseworker
Organization Name :	SAN DIEGO COUNTY LOP
Address :	P.O. Box 129261
City :	San Diego
Phone Number :	N/R
Email :	teresa.sherman@sdcounty.ca.gov

Map Id: 112
Direction: NW
Distance: 0.445 mi., 2349 ft.
Elevation: 497 ft.
Relative: Lower

Site Name : GOURMET LIQUOR 100944 | EZ SERVE 100944 | RESTRUCTURE PETROLEUM MARKETING SRVS
2966 S SANTA FE AVE
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, EPA LUST, FRS, HAZNET - CA, HWG - CA, LUST REG 9 - CA] ***(cont.)***

Envirosite ID: 257430
EPA ID: CAL000310461

LUST REG 9 - CA ***(cont.)***

Regulatory Activities

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Date :	2017-11-01
Global ID :	T0607300358
Action Type :	ENFORCEMENT
Action :	Closure/No Further Action Letter

Date :	2017-10-19
Global ID :	T0607300358
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other

Date :	2017-09-07
Global ID :	T0607300358
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other

Date :	2017-08-23
Global ID :	T0607300358
Action Type :	RESPONSE
Action :	Other Report / Document - Regulator Responded

Date :	2017-03-21
Global ID :	T0607300358
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other

Date :	2017-03-06
Global ID :	T0607300358
Action Type :	RESPONSE
Action :	Corrective Action Plan / Remedial Action Plan - Addendum - Regulator Responded

Date :	2017-01-27
Global ID :	T0607300358
Action Type :	ENFORCEMENT
Action :	Technical Correspondence / Assistance / Other

Map Id: 112
Direction: NW
Distance: 0.445 mi., 2349 ft.
Elevation: 497 ft.
Relative: Lower

Site Name : GOURMET LIQUOR 100944 | EZ SERVE 100944 | RESTRUCTURE PETROLEUM MARKETING SRVS
2966 S SANTA FE AVE
SAN MARCOS, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, EPA LUST, FRS, HAZNET - CA, HWG - CA, LUST REG 9 - CA] ***(cont.)***

Envirosite ID: 257430
EPA ID: CAL000310461

LUST REG 9 - CA ***(cont.)***

Date : 2016-12-21
Global ID : T0607300358
Action Type : RESPONSE
Action : Corrective Action Plan / Remedial Action Plan - Regulator Responded

Date : 2016-12-21
Global ID : T0607300358
Action Type : ENFORCEMENT
Action : Technical Correspondence / Assistance / Other

Date : 2016-12-20
Global ID : T0607300358
Action Type : ENFORCEMENT
Action : Technical Correspondence / Assistance / Other

Status History

Status Date : 2017-11-01
Global ID : T0607300358
Status : Completed - Case Closed

Status Date : 2017-10-19
Global ID : T0607300358
Status : Open - Eligible for Closure

Status Date : 2008-01-08
Global ID : T0607300358
Status : Open - Verification Monitoring

Status Date : 1986-04-25
Global ID : T0607300358
Status : Open - Case Begin Date

Map Id: O113
Direction: SE
Distance: 0.452 mi., 2387 ft.
Elevation: 558 ft.
Relative: Lower

Site Name : COCA COLA ENTERPISES
LAS POSAS/ARMORLITE | NONE LAS POSAS/ARMORLITE
SAN MARCOS, CA 92069

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, FRS, SLIC REG 9 - CA]

Envirosite ID: 342625
EPA ID: N/R

CALEPA SITES - CA

Facility Name :	COCA COLA ENTERPISES
Facility Address :	NONE LAS POSAS/ARMORLITE, SAN MARCOS, 92069
Site ID :	232487
EI ID :	T0608184290
EI Description :	Cleanup Program Site
Latitude :	33.146262
Longitude :	-117.189507
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07

CASE LIST_SAN DIEGO COUNTY - CA

Facility Name :	COCA COLA ENTERPISES
Facility Address :	None LAS POSAS/ARMORLITE, SAN MARCOS, CA 92069
County :	San Diego

Site Details

Status Date :	1997-07-31
Status :	Completed - Case Closed
Begin Date :	1996-11-01
Global ID :	T0608184290
Site History :	N/R
RB Case Number :	N/R
Potential Media Affected :	Aquifer used for drinking water supply
Potential Contaminants of Concern :	* Chlorinated Hydrocarbons
Local Agency :	N/R
Local Case Number :	H36816-001
Lead Agency :	SAN DIEGO COUNTY LOP
File Location :	Local Agency
CUF Case :	NO
Caseworker :	N/R
Case Type :	Cleanup Program Site
How Discovered :	N/R
How Discovered Description :	N/R
Stop Method :	N/R
Stop Description :	N/R
Calwater Watershed Name :	Carlsbad - San Marcos - Richland (904.52)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)
Disadvantaged Community :	N/R
Latitude :	33.146262
Longitude :	-117.189508
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-09

Contacts Summary

Global ID :	T0608184290
Contact Name :	N/R
Contact Type :	N/R

Map Id: O113
Direction: SE
Distance: 0.452 mi., 2387 ft.
Elevation: 558 ft.
Relative: Lower

Site Name : COCA COLA ENTERPISES
LAS POSAS/ARMORLITE | NONE LAS POSAS/ARMORLITE
SAN MARCOS, CA 92069

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, FRS, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 342625
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Organization Name : N/R
Address : N/R
City : N/R
Phone Number : N/R
Email : N/R

Regulatory Activities

Date : 1997-07-25
Global ID : T0608184290
Action Type : ENFORCEMENT
Action : Closure/No Further Action Letter

Date : 1997-07-18
Global ID : T0608184290
Action Type : ENFORCEMENT
Action : Closure/No Further Action Letter - #H36816-001

Date : 1996-11-01
Global ID : T0608184290
Action Type : Other
Action : Leak Reported

Status History

Status Date : 1997-07-31
Global ID : T0608184290
Status : Completed - Case Closed

Status Date : 1996-11-01
Global ID : T0608184290
Status : Open - Case Begin Date

FRS

Facility Name : COCA COLA ENTERPISES
Facility Address : NONE LAS POSAS/ARMORLITE, SAN MARCOS, CA 92069
County : SAN DIEGO COUNTY

Site Details

Registry ID : 110066329832
FRS Facility URL : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-02-17

Map Id: O113
Direction: SE
Distance: 0.452 mi., 2387 ft.
Elevation: 558 ft.
Relative: Lower

Site Name : COCA COLA ENTERPISES
LAS POSAS/ARMORLITE | NONE LAS POSAS/ARMORLITE
SAN MARCOS, CA 92069

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, FRS, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 342625
EPA ID: N/R

FRS ***(cont.)***

Source Description

Source Description :

The California Environmental Protection Agency (CalEPA) has recently implemented a new data warehouse system (nSite). This data warehouse combines and merges facility and site information from five different systems managed within CalEPA. The five systems are: California Environmental Reporting System (CERS), EnviroStor, GeoTracker, California Integrated Water Quality System (CIWQS), and Toxic Release Inventory (TRI).

FRS Environmental Interest

Source and System ID :	CA-ENVIROVIEW - 232487

SLIC REG 9 - CA

Facility Name :	COCA COLA ENTERPISES
Facility Address :	None LAS POSAS/ARMORLITE, SAN MARCOS, CA 92069
County :	San Diego

Site Details

Status Date :	1997-07-31
Status :	Completed - Case Closed
Begin Date :	1996-11-01
Global ID :	T0608184290
Region :	REGION 9
Site History :	N/R
RB Case Number :	N/R
Potential Media Affected :	Aquifer used for drinking water supply
Potential Contaminants of Concern :	* Chlorinated Hydrocarbons
Local Agency :	N/R
Local Case Number :	H36816-001
Lead Agency :	SAN DIEGO COUNTY LOP
File Location :	Local Agency
CUF Case :	NO
Caseworker :	N/R
Case Type :	Cleanup Program Site
How Discovered :	N/R
How Discovered Description :	N/R
Stop Method :	N/R
Stop Description :	N/R
Calwater Watershed Name :	Carlsbad - San Marcos - Richland (904.52)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)
Disadvantaged Community :	N/R
Latitude :	33.146262
Longitude :	-117.189508
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-11

Map Id: O113
Direction: SE
Distance: 0.452 mi., 2387 ft.
Elevation: 558 ft.
Relative: Lower

Site Name : COCA COLA ENTERPISES
LAS POSAS/ARMORLITE | NONE LAS POSAS/ARMORLITE
SAN MARCOS, CA 92069

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, FRS, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 342625
EPA ID: N/R

SLIC REG 9 - CA ***(cont.)***

Contacts Summary

Global ID :	T0608184290
Contact Name :	N/R
Contact Type :	N/R
Organization Name :	N/R
Address :	N/R
City :	N/R
Phone Number :	N/R
Email :	N/R

Regulatory Activities

Date :	1997-07-25
Global ID :	T0608184290
Action Type :	ENFORCEMENT
Action :	Closure/No Further Action Letter

Date :	1997-07-18
Global ID :	T0608184290
Action Type :	ENFORCEMENT
Action :	Closure/No Further Action Letter - #H36816-001

Date :	1996-11-01
Global ID :	T0608184290
Action Type :	Other
Action :	Leak Reported

Status History

Status Date :	1997-07-31
Global ID :	T0608184290
Status :	Completed - Case Closed

Status Date :	1996-11-01
Global ID :	T0608184290
Status :	Open - Case Begin Date

Map Id: 114
Direction: SSE
Distance: 0.486 mi., 2566 ft.
Elevation: 550 ft.
Relative: Lower

Site Name : CITY SAN MARCOS BUILDING & SAFETY | CCC POOL SERVICES, INC.
120 LAS POSAS RD | 120 N LAS POSAS RD
SAN MARCOS | San Marcos, CA 92069

Database(s) : [HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, RMP]

Envirosite ID: 531878
EPA ID: CAC002412007

HAZMAT_SAN DIEGO COUNTY - CA

Facility Name :	CCC POOL SERVICES, INC.
Facility Address :	120 N LAS POSAS RD, SAN MARCOS, CA 92069
Date :	2002-05-04
Record ID :	DEH2002-HUPFP-103858
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23

HAZNET - CA

Facility Name :	CITY SAN MARCOS BUILDING & SAFETY
Facility Address :	120 LAS POSAS RD, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAC002412007
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	1 CIVIC CENTER DR, SAN MARCOS, CA 920690000
Latitude :	33.14486533
Longitude :	-117.19083739
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

State Waste :	2001: 135 - Unspecified aqueous solution, 6.3 tons to CAT080033681

HWG - CA

Facility Name :	CITY SAN MARCOS BUILDING & SAFETY
Facility Address :	120 LAS POSAS RD, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAC002412007
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	1 CIVIC CENTER DR, SAN MARCOS, CA 920690000
Owner Name :	CITY SAN MARCOS
Owner Address :	1 CIVIC CENTER DR, SAN MARCOS, CA 920690000
Operator Name :	CARL BLAISDELL

Map Id: 114
Direction: SSE
Distance: 0.486 mi., 2566 ft.
Elevation: 550 ft.
Relative: Lower

Site Name : CITY SAN MARCOS BUILDING & SAFETY | CCC POOL SERVICES, INC.
120 LAS POSAS RD | 120 N LAS POSAS RD
SAN MARCOS | San Marcos, CA 92069

Database(s) : [HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, RMP] ***(cont.)***

Envirosite ID: 531878
EPA ID: CAC002412007

HWG - CA ***(cont.)***

Operator Address :	1 CIVIC CENTER DR, SAN MARCOS, CA 920690000
Latitude :	33.144301
Longitude :	-117.190956

RMP

Facility Name :	CCC Pool Services, Inc.
Facility Address :	120-N Las Posas Rd., San Marcos, CA 92069
Facility ID :	17927
Facility County FIPS :	06073
LEPC :	Region VI LEPC
Facility URL :	N/R
Facility Phone Number :	N/R
Facility Email Address :	MGNADT@MSN.COM
Facility DUNS :	0
Parent Company Name :	N/R
Company 2 Name :	N/R
Company DUNS :	0
Company 2 DUNS :	0
Operator Name :	Myron A. Gnadt
Operator Address :	120-B Las Posas Rd., San Marcos, CA 92069-1420
Operator Address 2 :	N/R
Operator Phone :	7607367665
Emergency Contact Name :	Myron A. Gnadt/ Rena Gnadt
Emergency Contact Title :	President/ Secretary-Treasurer
Emergency Contact Phone :	7604380569
Phone 24 :	7604380569
Emergency Contact Ext PIN :	N/R
Emergency Contact Email :	N/R
No Accidents :	True
Foreign State Prov :	N/R
Foreign Zip Code :	N/R
Foreign Country :	N/R
FTE :	11
Other EPA Facility ID :	61616
EPA Facility ID :	100000099822
OSHA PSM :	True
EPCRA 302 :	True
CAA Title V :	False
Clear Air Op Permit ID :	N/R
Safety Inspection Date :	1998-05-01
Safety Inspection by :	San Diego Health Dept.
OSHA Ranking :	False
Predictive Filing Flag :	False
Submission Type :	C
CBI Flag :	False
Completion Check Date :	1999-10-12
Receipt Date :	1999-10-04
Graphics Indicator :	False
Attachments Indicator :	False
Certification Received Flag :	True
Submission Method :	Commercial Software Vendor
CBI Substantiation Flag :	False

Map Id: 114
Direction: SSE
Distance: 0.486 mi., 2566 ft.
Elevation: 550 ft.
Relative: Lower

Site Name : CITY SAN MARCOS BUILDING & SAFETY | CCC POOL SERVICES, INC.
120 LAS POSAS RD | 120 N LAS POSAS RD
SAN MARCOS | San Marcos, CA 92069

Database(s) : [HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, RMP] ***(cont.)***

Envirosite ID: 531878
EPA ID: CAC002412007

RMP ***(cont.)***

Electronic Waiver Received Flag :	False
Postmark Date :	1999-10-01
De Registration Date :	2005-06-28
De Registration Effective Date :	2001-10-11
Anniversary Date :	2004-06-19
Error Report Date :	N/R
CBI Unsanitized Version Flag :	False
Version Number :	1.1.7
Facility Latitude :	33.146278
Facility Longitude :	-117.192889
Valid Latitude Longitude Flag :	True
FRS Description :	PLANT ENTRANCE (GENERAL)
FRS Method :	ADDRESS MATCHING-HOUSE NUMBER
Horizontal Accuracy Measure :	N/R
Horizontal Reference Datum Code :	N/R
Source Map Scale Number :	N/R
Last Date in Agency List :	2022-01-05

Process Details

Process ID :	25289
Process Facility ID :	17927
Process Description :	N/R

Chemical Details

Chemical Name :	Chlorine
Chemical ID :	62
Quantity :	8000
Chemical Name :	Public OCA Chemical
Chemical ID :	0
Quantity :	0

RMP Summary

RMP Contact Name :	Myron A. Gnadt
RMP Title :	President
RMP Description :	N/R
RMP Complete Flag :	True

Accident History

Facility ID :	17927
Accident Date :	N/R
Accident Time :	N/R
Accident Release Duration :	N/R
Release Event :	N/R
Release Source :	N/R
Other Release Source :	N/R

Map Id: 114
Direction: SSE
Distance: 0.486 mi., 2566 ft.
Elevation: 550 ft.
Relative: Lower

Site Name : CITY SAN MARCOS BUILDING & SAFETY | CCC POOL SERVICES, INC.
120 LAS POSAS RD | 120 N LAS POSAS RD
SAN MARCOS | San Marcos, CA 92069

Database(s) : [HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, RMP] ***(cont.)***

Envirosite ID: 531878
EPA ID: CAC002412007

RMP ***(cont.)***

Onsite Property Damage :	N/R
Offsite Property Damage :	N/R
Envir Damage :	N/R
Envir Damage-Other :	N/R
Initiating Event :	N/R
Cause Equipment Failure :	N/R
Cause-Other :	N/R
Offsite Responders Notify :	N/R
CBI Flag :	N/R
Accident History ID :	N/R

Facility ID :	8030
Facility County FIPS :	06073
LEPC :	N/R
Facility URL :	N/R
Facility Phone Number :	N/R
Facility Email Address :	MGNADT@MSN.COM
Facility DUNS :	0
Parent Company Name :	N/R
Company 2 Name :	N/R
Company DUNS :	0
Company 2 DUNS :	0
Operator Name :	Myron A. Gnadt
Operator Address :	120-N Las Posas Rd., San Marcos, CA 92069
Operator Address 2 :	N/R
Operator Phone :	7607367665
Emergency Contact Name :	Myron A. Gnadt & Rena Gnadt
Emergency Contact Title :	President, Sec./Treasure
Emergency Contact Phone :	7604380569
Phone 24 :	7604380569
Emergency Contact Ext PIN :	N/R
Emergency Contact Email :	N/R
No Accidents :	True
Foreign State Prov :	N/R
Foreign Zip Code :	N/R
Foreign Country :	N/R
FTE :	11
Other EPA Facility ID :	61616
EPA Facility ID :	100000099822
OSHA PSM :	True
EPCRA 302 :	True
CAA Title V :	False
Clear Air Op Permit ID :	N/R
Safety Inspection Date :	1998-05-01
Safety Inspection by :	San Diego Health Dept.
OSHA Ranking :	False
Predictive Filing Flag :	False
Submission Type :	F
CBI Flag :	False
Completion Check Date :	1999-07-07
Receipt Date :	1999-06-21
Graphics Indicator :	False
Attachments Indicator :	False
Certification Received Flag :	False

Map Id: 114
Direction: SSE
Distance: 0.486 mi., 2566 ft.
Elevation: 550 ft.
Relative: Lower

Site Name : CITY SAN MARCOS BUILDING & SAFETY | CCC POOL SERVICES, INC.
120 LAS POSAS RD | 120 N LAS POSAS RD
SAN MARCOS | San Marcos, CA 92069

Database(s) : [HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, RMP] ***(cont.)***

Envirosite ID: 531878
EPA ID: CAC002412007

RMP ***(cont.)***

Submission Method :	RMP*Submit
CBI Substantiation Flag :	False
Electronic Waiver Received Flag :	False
Postmark Date :	1999-06-19
De Registration Date :	2005-06-28
De Registration Effective Date :	2001-10-11
Anniversary Date :	2004-06-19
Error Report Date :	1999-07-07
CBI Unsanitized Version Flag :	False
Version Number :	1.1.7
Facility Latitude :	33.145194
Facility Longitude :	117.190722
Valid Latitude Longitude Flag :	False
FRS Description :	PLANT ENTRANCE (GENERAL)
FRS Method :	ADDRESS MATCHING-HOUSE NUMBER
Horizontal Accuracy Measure :	N/R
Horizontal Reference Datum Code :	N/R
Source Map Scale Number :	N/R
Last Date in Agency List :	2022-01-05

Process Details

Process ID :	9651
Process Facility ID :	8030
Process Description :	Repacking & Distrubution

Chemical Details

Chemical Name :	Chlorine
Chemical ID :	62
Quantity :	10000
Chemical Name :	Public OCA Chemical
Chemical ID :	0
Quantity :	0

RMP Summary

RMP Contact Name :	Myron A. Gnadt
RMP Title :	President
RMP Description :	N/R
RMP Complete Flag :	False

Accident History

Facility ID :	8030
Accident Date :	N/R
Accident Time :	N/R
Accident Release Duration :	N/R
Release Event :	N/R

Map Id: 114
Direction: SSE
Distance: 0.486 mi., 2566 ft.
Elevation: 550 ft.
Relative: Lower

Site Name : CITY SAN MARCOS BUILDING & SAFETY | CCC POOL SERVICES, INC.
120 LAS POSAS RD | 120 N LAS POSAS RD
SAN MARCOS | San Marcos, CA 92069

Database(s) : [HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HWG - CA, RMP] ***(cont.)***

Envirosite ID: 531878
EPA ID: CAC002412007

RMP ***(cont.)***

Release Source :	N/R
Other Release Source :	N/R
Onsite Property Damage :	N/R
Offsite Property Damage :	N/R
Envir Damage :	N/R
Envir Damage-Other :	N/R
Initiating Event :	N/R
Cause Equipment Failure :	N/R
Cause-Other :	N/R
Offsite Responders Notify :	N/R
CBI Flag :	N/R
Accident History ID :	N/R

Map Id: 115
Direction: NNW
Distance: 0.544 mi., 2875 ft.
Elevation: 600 ft.
Relative: Higher

Site Name : RANCHO SANTA LUNA SCHOOL | RANCHO SANTA LUNA SC
SANTA LUNA HILLS
SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, ENVIROSTOR - CA, SCH - CA]

Envirosite ID: 272272
EPA ID: N/R

CALEPA SITES - CA

Facility Name :	RANCHO SANTA LUNA SC
Facility Address :	SANTA LUNA HILLS, SAN MARCOS, 92069
Site ID :	371563
EI ID :	37010030
EI Description :	School Investigation
Latitude :	33.160100
Longitude :	-117.197700
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07

ENVIROSTOR - CA

Facility Name :	RANCHO SANTA LUNA SCHOOL
Facility Address :	Santa Luna Hills, San Marcos, CA 92069
County :	SAN DIEGO

Site Details

Cleanup Date :	2002-05-25
Cleanup Status :	No Action Required
Site Type :	School Investigation
Site Type Detailed :	School
Acreage :	16

Map Id: 115
Direction: NNW
Distance: 0.544 mi., 2875 ft.
Elevation: 600 ft.
Relative: Higher

Site Name : RANCHO SANTA LUNA SCHOOL |
RANCHO SANTA LUNA SC
SANTA LUNA HILLS
SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, ENVIROSTOR - CA, SCH - CA] ***(cont.)***

Envirosite ID: 272272
EPA ID: N/R

ENVIROSTOR - CA ***(cont.)***

APN :	NONE SPECIFIED
National Priorities List :	NO
Regulatory Agencies Involved :	* DTSC
Lead Agency :	* DTSC
Project Manager :	Angela Garcia
Supervisor :	Shahir Haddad
Office :	Southern California Schools & Brownfields Outreach
Envirostor ID :	37010030
Site Code :	404349
Assembly :	75
Senate :	38
Congressional District :	50
Special Program :	N/R
Past Uses :	AGRICULTURAL - ROW CROPS
Potential COC :	No Contaminants found
Confirmed COC :	N/R
Potential Media Affected :	No Media Affected
Restricted Use :	NO
Site Management Req :	N/R
Funding :	School District
Latitude :	33.1601
Longitude :	-117.1977
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-14

Alias Details

Alias :	37010030
Alias Type :	Envirostor ID Number
Alias :	404349
Alias Type :	Project Code (Site Code)
Alias :	RANCHO SANTA LUNA SCHOOL
Alias Type :	Alternate Name
Alias :	SAN MARCOS UNIFIED SCHOOL DISTRICT
Alias Type :	Alternate Name
Alias :	SAN MARCOS USD-RANCHO SANTALINA SCL SITE
Alias Type :	Alternate Name

Completed Activities

Completed Date :	2002-06-25
Area Name :	PROJECT WIDE
Sub Area Name :	N/R
Document Type :	Cost Recovery Closeout Memo
Comments :	N/R

Map Id: 115
Direction: NNW
Distance: 0.544 mi., 2875 ft.
Elevation: 600 ft.
Relative: Higher

Site Name : RANCHO SANTA LUNA SCHOOL | RANCHO SANTA LUNA SC
SANTA LUNA HILLS
SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, ENVIROSTOR - CA, SCH - CA] ***(cont.)***

Envirosite ID: 272272
EPA ID: N/R

ENVIROSTOR - CA ***(cont.)***

Completed Date :	2002-05-29
Area Name :	PROJECT WIDE
Sub Area Name :	N/R
Document Type :	Phase 1
Comments :	N/R

Completed Date :	2002-05-23
Area Name :	PROJECT WIDE
Sub Area Name :	N/R
Document Type :	Site Inspections/Visit (Non LUR)
Comments :	N/R

Future Activities

Area Name :	N/R
Sub Area Name :	N/R
Document Type :	N/R
Due Date :	N/R

Scheduled Activites

Due Date :	N/R
Revised Date :	N/R
Area Name :	N/R
Sub Area Name :	N/R
Document Type :	N/R

SCH - CA

Facility Name :	RANCHO SANTA LUNA SCHOOL
Facility Address :	SANTA LUNA HILLS, SAN MARCOS, 92069
County :	SAN DIEGO
Status Date :	2002-05-25
Status :	NO ACTION REQUIRED
Envirostor ID :	37010030
School District :	SAN MARCOS UNIFIED
Program Type :	SCHOOL INVESTIGATION
Site Code :	404349
CalEnviroScreen Score :	31-35%
Latitude :	33.1601
Longitude :	-117.1977
Last Date in Agency List :	2022-02-02

Map Id: 116
Direction: N
Distance: 0.702 mi., 3708 ft.
Elevation: N/R
Relative: N/R

Site Name : N/R
33.686331, -116.858686
CA

Database(s) : [HIGH FIRE - CA]

Envirosite ID: 24267674
EPA ID: N/R

HIGH FIRE - CA

State Responsibility Areas :	Yes
Haz Code :	3
Haz Class :	Very High

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA]

Envirosite ID: 256168
EPA ID: N/R

AFS

Facility Name :	SIGNET ARMORLITE
Facility Address :	1001 ARMORLITE DR, SAN MARCOS, CA 92069
County :	San Diego

Facility Summary

Program System ID :	CASDS0000607300058
Facility Registry ID :	110000478689
EPA Region :	EPA Region 9 - AZ, CA, HI, NV, AS, GU
SIC :	3851 - OPHTHALMIC GOODS
NAICS :	326199 - All Other Plastics Product Manufacturing
Facility Type :	Privately Owned Facility
Air Pollutant Class :	Minor Emissions
Air Operating Status :	Operating
Current High Priority Violation (HPV):	No Violation Identified
Local Control Region Name :	San Diego County Air Pollution Control District (Grantee)
Last Date in Agency List :	2022-02-08

Air Pollutant Details

Program System ID :	CASDS0000607300058
Pollutant :	TOTAL HYDROCARBONS
Substance Registry Services ID (SRS):	966481
Chemical Abstract Service Number :	308067530
Air Pollutant Class :	Minor Emissions

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

AFS ***(cont.)***

Program System ID :	CASDS0000607300058
Pollutant :	Carbon monoxide
Substance Registry Services ID (SRS):	65052
Chemical Abstract Service Number :	630080
Air Pollutant Class :	Minor Emissions

Program System ID :	CASDS0000607300058
Pollutant :	TOTAL PARTICULATE MATTER
Substance Registry Services ID (SRS):	1647643
Chemical Abstract Service Number :	N/R
Air Pollutant Class :	Minor Emissions

Program System ID :	CASDS0000607300058
Pollutant :	Sulfur dioxide
Substance Registry Services ID (SRS):	150367
Chemical Abstract Service Number :	7446095
Air Pollutant Class :	Minor Emissions

Program System ID :	CASDS0000607300058
Pollutant :	FACIL
Substance Registry Services ID (SRS):	N/R
Chemical Abstract Service Number :	N/R
Air Pollutant Class :	Minor Emissions

Program System ID :	CASDS0000607300058
Pollutant :	ADMIN
Substance Registry Services ID (SRS):	N/R
Chemical Abstract Service Number :	N/R
Air Pollutant Class :	Minor Emissions

Program System ID :	CASDS0000607300058
Pollutant :	VOLATILE ORGANIC COMPOUNDS (VOCS)
Substance Registry Services ID (SRS):	761346
Chemical Abstract Service Number :	N/R
Air Pollutant Class :	Minor Emissions

Program System ID :	CASDS0000607300058
Pollutant :	NITROGEN OXIDES NO2
Substance Registry Services ID (SRS):	167924
Chemical Abstract Service Number :	10102440

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

AFS ***(cont.)***

Air Pollutant Class : Minor Emissions

Air Violation History Details

HPV Day Zero Date :	1993-03-08
HPV Resolved Date :	1994-06-28
Program System ID :	CASDS0000607300058
Activity ID :	3400409804
Agency Type :	Local
State Code :	CA
Air Local Control Region Code (LCON):	SDS
Comp Determination UID :	CASDSA0000060730005800026
Enforcement Response Policy :	High Priority Violation
Program :	State Implementation Plan for National Primary and Secondary Ambient Air Quality Standards
Pollutant :	Carbon monoxide NITROGEN OXIDES NO2 VOLATILE ORGANIC COMPOUNDS (VOCS)
Earliest Determination Date of Federally Reportable Violation (FRV):	N/R

BRS

Facility Name :	SIGNET ARMORLITE, INC.
Facility Address :	1001 ARMORLITE DRIVE, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Date Form Received by Agency :	2012-02-29
EPA ID :	CAD008362634
Mailing Address :	1001 ARMORLITE DRIVE, SAN MARCOS, CA 92069
Contact :	JOHN T HINGEY
Contact Address :	1001 ARMORLITE DRIVE, SAN MARCOS, CA 92069
Contact Country :	US
Contact Telephone :	760-744-4000
Contact Email :	JHINGEY@SIGNETARMOLITE.COM
EPA Region :	09
Land Type :	Private
Source Type :	Annual/Biennial Report updated with Notification
Classification :	Large Quantity Generator

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

BRS ***(cont.)***

Description :

Handlers that generate 1,000 kg or more of hazardous waste during any calendar month; or generate more than 1 kg of acutely hazardous waste during any calendar month; or generate more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generate 1 kg or less of acutely hazardous waste during any calendar month, and accumulate more than 1 kg of acutely hazardous waste at any time; or generate 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulated more than 100 kg of that material at any time.

Last Date in Agency List : 2022-01-25

Owner/Operator Summary

Owner/Operator Name :	EDA HOLDINGS CO, INC.
Owner/Operator Address :	135555 N STEMMONS FREEWAY, DALLAS, TX 75234
Owner/Operator Country :	N/R
Owner/Operator Telephone :	760-744-4000
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Private
Owner/Operator Type :	Operator
Owner/Operator Start Date :	2010-04-01
Owner/Operator End Date :	N/R

Owner/Operator Name :	EDA HOLDINGS CO, INC.
Owner/Operator Address :	135555 N STEMMONS FREEWAY, DALLAS, TX 75234
Owner/Operator Country :	N/R
Owner/Operator Telephone :	760-744-4000
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Private
Owner/Operator Type :	Owner
Owner/Operator Start Date :	2010-04-01
Owner/Operator End Date :	N/R

Waste Activity Monitoring

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

BRS ***(cont.)***

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Report Cycle :	2011
Hazardous Waste Page Number :	1
Hazardous Waste Sub-Page Number :	1
BR Form :	GM
Waste Description :	SOLVENT CONTAMINATED WIPES FROM INSPECTION & CLEANING PROCESS
Primary NAICS :	326199 - All Other Plastics Product Manufacturing
Source Code :	G01 - Dip, flush or spray rinsing (using solvents to clean or prepare parts or assemblies for further processing - i.e. painting or assembly)
Form Code :	W409 - Other organic solids (specify in comments)
Management Method :	H141 - The site receiving this waste stored/bulked and transferred the waste with no treatment or recovery (H010-H129), fuel blending (H061), or disposal (H131-H135) at that receiving site.
Generation Tons :	2.175
Managed Tons :	0
Shipped Tons :	2.175
Received Tons :	0
Receiver ID :	CAD008252405
Receiver State :	CA
Shipper ID :	CAD008362634
Shipper State :	CA
Waste Minimization :	Y - Waste minimization was implemented and was successful in reducing quantity and/or toxicity (please detail reasons in the Comments section)
Waste Code List :	D001, F003
Waste Code Group :	F003 - THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCL
Waste Generation Type :	N/R
Report Cycle :	2011
Hazardous Waste Page Number :	10
Hazardous Waste Sub-Page Number :	1

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

BRS ***(cont.)***

BR Form :	GM
Waste Description :	LABPACK ELEMENTAL MERCURY
Primary NAICS :	326199 - All Other Plastics Product Manufacturing
Source Code :	G11 - Discarding off-specification, out-of-date, and/or unused chemicals or products
Form Code :	W001 - Lab packs from any source not containing acute hazardous waste
Management Method :	H141 - The site receiving this waste stored/bulked and transferred the waste with no treatment or recovery (H010-H129), fuel blending (H061), or disposal (H131-H135) at that receiving site.
Generation Tons :	0.016
Managed Tons :	0
Shipped Tons :	0.016
Received Tons :	0
Receiver ID :	AZD049318009
Receiver State :	AZ
Shipper ID :	CAD008362634
Shipper State :	CA
Waste Minimization :	X - No waste minimization efforts were implemented for this waste
Waste Code List :	D009, U151
Waste Code Group :	U151 - MERCURY
Waste Generation Type :	N/R
Report Cycle :	2011
Hazardous Waste Page Number :	11
Hazardous Waste Sub-Page Number :	1
BR Form :	GM
Waste Description :	LAB PACK-POTASSIUM NITRATE SALTS
Primary NAICS :	326199 - All Other Plastics Product Manufacturing
Source Code :	G07 - Product and by-product processing (direct flow of wastes from chemical manufacturing or processing, etc.)
Form Code :	W409 - Other organic solids (specify in comments)
Management Method :	H141 - The site receiving this waste stored/bulked and transferred the waste with no treatment or recovery (H010-H129), fuel blending (H061), or disposal (H131-H135) at that receiving site.
Generation Tons :	0.4455
Managed Tons :	0
Shipped Tons :	0.4455

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

BRS ***(cont.)***

Received Tons :	0
Receiver ID :	UTD981552177
Receiver State :	UT
Shipper ID :	CAD008362634
Shipper State :	CA
Waste Minimization :	X - No waste minimization efforts were implemented for this waste
Waste Code List :	D001
Waste Code Group :	D001 - IGNITABLE WASTE
Waste Generation Type :	N/R
Report Cycle :	2011
Hazardous Waste Page Number :	12
Hazardous Waste Sub-Page Number :	1
BR Form :	GM
Waste Description :	LAB PACK-GENERATED FOR PRODUCTION SHUT-DOWN AT THE FACILITY, SENT OFFSITE TO BE COMBINED WITH OTHER SIMILAR WASTES
Primary NAICS :	326199 - All Other Plastics Product Manufacturing
Source Code :	G11 - Discarding off-specification, out-of-date, and/or unused chemicals or products
Form Code :	W001 - Lab packs from any source not containing acute hazardous waste
Management Method :	H141 - The site receiving this waste stored/bulked and transferred the waste with no treatment or recovery (H010-H129), fuel blending (H061), or disposal (H131-H135) at that receiving site.
Generation Tons :	0.4155
Managed Tons :	0
Shipped Tons :	0.4155
Received Tons :	0
Receiver ID :	CAD008302903
Receiver State :	CA
Shipper ID :	CAD008362634
Shipper State :	CA
Waste Minimization :	X - No waste minimization efforts were implemented for this waste
Waste Code List :	D001, D003
Waste Code Group :	ICR - D001-D003 combinations only
Waste Generation Type :	N/R
Report Cycle :	2011
Hazardous Waste Page Number :	2

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

BRS ***(cont.)***

Hazardous Waste Sub-Page Number :	1
BR Form :	GM
Waste Description :	CORROSIVE, SPENT STRIPPING SOLUTION FORM PARTS CLEANING PROCESS CONTAINING POTASSIUM HYDROXIDE.
Primary NAICS :	326199 - All Other Plastics Product Manufacturing
Source Code :	G02 - Stripping and acid or caustic cleaning (using caustics to remove coatings or layers from parts or assemblies)
Form Code :	W110 - Caustic aqueous waste without cyanides (pH >12.5)
Management Method :	H039 - Other recovery or reclamation for reuse including acid regeneration, organics recovery, etc. (specify in comments)
Generation Tons :	22.1972547
Managed Tons :	0
Shipped Tons :	22.1972547
Received Tons :	0
Receiver ID :	CAT080013352
Receiver State :	CA
Shipper ID :	CAD008362634
Shipper State :	CA
Waste Minimization :	Y - Waste minimization was implemented and was successful in reducing quantity and/or toxicity (please detail reasons in the Comments section)
Waste Code List :	D002
Waste Code Group :	D002 - CORROSIVE WASTE
Waste Generation Type :	N/R
Report Cycle :	2011
Hazardous Waste Page Number :	3
Hazardous Waste Sub-Page Number :	1
BR Form :	GM
Waste Description :	SOLVENT LADDEN SOLIDS
Primary NAICS :	326199 - All Other Plastics Product Manufacturing
Source Code :	G06 - Painting and coating (manufacturing, building, or maintenance)
Form Code :	W406 - Dried paint (paint chips, filters, air filters, other)

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

BRS ***(cont.)***

Management Method :	H141 - The site receiving this waste stored/bulked and transferred the waste with no treatment or recovery (H010-H129), fuel blending (H061), or disposal (H131-H135) at that receiving site.
Generation Tons :	1.1
Managed Tons :	0
Shipped Tons :	1.1
Received Tons :	0
Receiver ID :	CAD008252405
Receiver State :	CA
Shipper ID :	CAD008362634
Shipper State :	CA
Waste Minimization :	Y - Waste minimization was implemented and was successful in reducing quantity and/or toxicity (please detail reasons in the Comments section)
Waste Code List :	D001
Waste Code Group :	D001 - IGNITABLE WASTE
Waste Generation Type :	N/R
Report Cycle :	2011
Hazardous Waste Page Number :	4
Hazardous Waste Sub-Page Number :	1
BR Form :	GM
Waste Description :	SPENT SOLVENTS
Primary NAICS :	326199 - All Other Plastics Product Manufacturing
Source Code :	G06 - Painting and coating (manufacturing, building, or maintenance)
Form Code :	W203 - Concentrated non-halogenated (e.g., non-chlorinated) solvent
Management Method :	H141 - The site receiving this waste stored/bulked and transferred the waste with no treatment or recovery (H010-H129), fuel blending (H061), or disposal (H131-H135) at that receiving site.
Generation Tons :	3.3501139
Managed Tons :	0
Shipped Tons :	3.3501139
Received Tons :	0
Receiver ID :	CAD008252405
Receiver State :	CA
Shipper ID :	CAD008362634
Shipper State :	CA
Waste Minimization :	X - No waste minimization efforts were implemented for this waste
Waste Code List :	D001, F003

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

BRS ***(cont.)***

Waste Code Group :	F003 - THE FOLLOWING SPENT NONHALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCL
Waste Generation Type :	N/R
Report Cycle :	2011
Hazardous Waste Page Number :	5
Hazardous Waste Sub-Page Number :	1
BR Form :	GM
Waste Description :	LAB PACKS GENERATED FROM PRODUCTION SHUT-DOWN AT THE FACILITY. ALL SENT OUT DIRECTLY TO INCINERATION FACILITY.
Primary NAICS :	326199 - All Other Plastics Product Manufacturing
Source Code :	G11 - Discarding off-specification, out-of-date, and/or unused chemicals or products
Form Code :	W001 - Lab packs from any source not containing acute hazardous waste
Management Method :	H040 - Incineration - thermal destruction other than use as a fuel (includes any preparation prior to burning)
Generation Tons :	0.0605
Managed Tons :	0
Shipped Tons :	0.0605
Received Tons :	0
Receiver ID :	ARD069748192
Receiver State :	AR
Shipper ID :	CAD008362634
Shipper State :	CA
Waste Minimization :	X - No waste minimization efforts were implemented for this waste
Waste Code List :	D001, D002, D003, D007, D011, D035, U002, U007, U080, U112, U154, U220, U236
Waste Code Group :	UMIX - U mixtures
Waste Generation Type :	N/R
Report Cycle :	2011
Hazardous Waste Page Number :	5
Hazardous Waste Sub-Page Number :	2
BR Form :	GM

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

BRS ***(cont.)***

Waste Description :	LAB PACKS GENERATED FROM PRODUCTION SHUT-DOWN AT THE FACILITY. ALL SENT OUT DIRECTLY TO INCINERATION FACILITY.
Primary NAICS :	326199 - All Other Plastics Product Manufacturing
Source Code :	G11 - Discarding off-specification, out-of-date, and/or unused chemicals or products
Form Code :	W001 - Lab packs from any source not containing acute hazardous waste
Management Method :	H040 - Incineration - thermal destruction other than use as a fuel (includes any preparation prior to burning)
Generation Tons :	4.097
Managed Tons :	0
Shipped Tons :	4.097
Received Tons :	0
Receiver ID :	UTD981552177
Receiver State :	UT
Shipper ID :	CAD008362634
Shipper State :	CA
Waste Minimization :	X - No waste minimization efforts were implemented for this waste
Waste Code List :	D001, D002, D003, D007, D011, D035, U002, U007, U080, U112, U154, U220, U236
Waste Code Group :	UMIX - U mixtures
Waste Generation Type :	N/R
Report Cycle :	2011
Hazardous Waste Page Number :	6
Hazardous Waste Sub-Page Number :	1
BR Form :	GM
Waste Description :	ACETONE AND ACETONITRILE SOLUTION
Primary NAICS :	326199 - All Other Plastics Product Manufacturing
Source Code :	G09 - Other production or service-related processes from which the waste is a direct outflow or result (specify in comments)
Form Code :	W219 - Other organic liquid (specify in comments)
Management Method :	H040 - Incineration - thermal destruction other than use as a fuel (includes any preparation prior to burning)
Generation Tons :	0.021
Managed Tons :	0
Shipped Tons :	0.021

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

BRS ***(cont.)***

Received Tons :	0
Receiver ID :	UTD981552177
Receiver State :	UT
Shipper ID :	CAD008362634
Shipper State :	CA
Waste Minimization :	X - No waste minimization efforts were implemented for this waste
Waste Code List :	D001
Waste Code Group :	D001 - IGNITABLE WASTE
Waste Generation Type :	N/R

CALEPA SITES - CA

Facility Name :	ARMORLITE INC
Facility Address :	1001 ARMORLITE DR, SAN MARCOS, 920691431
Site ID :	207455
EI ID :	T0607302793
EI Description :	Leaking Underground Storage Tank Cleanup Site
Latitude :	33.144460
Longitude :	-117.185845
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07
Facility Name :	MILANO HOLDINGS INC. (FORMER SIGNET ARMORLITE, INC.)
Facility Address :	1001 ARMORLITE DRIVE, SAN MARCOS, 92069
Site ID :	209533
EI ID :	SL209154190
EI Description :	Cleanup Program Site
Latitude :	33.144127
Longitude :	-117.185867
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07
Facility Name :	PROPOSED DAVIA VILLAGE
Facility Address :	1001 ARMORLITE DRIVE, SAN MARCOS, 92069
Site ID :	212080
EI ID :	T10000003706
EI Description :	Cleanup Program Site
Latitude :	33.144343

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

CALEPA SITES - CA ***(cont.)***

Longitude :	-117.186355
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07
Facility Name :	SIGNET ARMORLITE
Facility Address :	1001 ARMORLITE DR., SAN MARCOS, 920691431
Site ID :	494325
EI ID :	110000478689
EI Description :	US EPA Air Emission Inventory System (EIS)
Latitude :	33.144830
Longitude :	-117.184170
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07
Facility Name :	SIGNET ARMORLITE INC
Facility Address :	1001 ARMORLITE DR, SAN MARCOS, 920690000
Site ID :	203292
EI ID :	CAD008362634
EI Description :	Hazardous Waste
Latitude :	33.144906
Longitude :	-117.184376
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07
Site ID :	203292
EI ID :	80001570
EI Description :	Corrective Action
Latitude :	33.144906
Longitude :	-117.184376
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07

CASE LIST_SAN DIEGO COUNTY - CA

Facility Name :	ARMORLITE INC
Facility Address :	1001 ARMORLITE DR, SAN MARCOS, CA 920691431
County :	San Diego

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Site Details

Status Date :	1986-09-22
Status :	Completed - Case Closed
Begin Date :	1986-08-22
Global ID :	T0607302793
Site History :	N/R
RB Case Number :	9UT493
Potential Media Affected :	Soil
Potential Contaminants of Concern :	Diesel
Local Agency :	SAN DIEGO COUNTY LOP
Local Case Number :	H02662-001
Lead Agency :	SAN DIEGO COUNTY LOP
File Location :	Local Agency
CUF Case :	NO
Caseworker :	KH
Case Type :	LUST Cleanup Site
How Discovered :	N/R
How Discovered Description :	N/R
Stop Method :	N/R
Stop Description :	N/R
Calwater Watershed Name :	Carlsbad - San Marcos - Richland (904.52)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)
Disadvantaged Community :	N/R
Latitude :	33.14446
Longitude :	-117.185846
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-09

Contacts Summary

Global ID :	T0607302793
Contact Name :	KEVIN HEATON
Contact Type :	Local Agency Caseworker
Organization Name :	SAN DIEGO COUNTY LOP
Address :	P.O. Box 129261
City :	San Diego
Phone Number :	N/R
Email :	kevin.heaton@sdcounty.ca.gov

Regulatory Activities

Date :	1986-08-26
Global ID :	T0607302793
Action Type :	Other

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Action : Leak Discovery

Date : 1986-08-26
Global ID : T0607302793
Action Type : Other
Action : Leak Began

Date : 1986-08-22
Global ID : T0607302793
Action Type : Other
Action : Leak Reported

Status History

Status Date : 1986-09-22
Global ID : T0607302793
Status : Completed - Case Closed

Status Date : 1986-08-22
Global ID : T0607302793
Status : Open - Case Begin Date

Facility Name : Milano Holdings Inc. (Former SIGNET ARMORLITE, INC.)
Facility Address : 1001 ARMORLITE DRIVE, SAN MARCOS, CA 92069
County : San Diego

Site Details

Status Date : 2014-01-31
Status : Completed - Case Closed
Begin Date : 1986-08-22
Global ID : SL209154190

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Site History :

The Facility is approximately 11.8 acres in size and contains buildings associated with the manufacture, marketing, and distribution of optical lenses. Site assessment activities have been conducted at the Facility since the early 1990s. Investigations revealed the presence of VOCs, including methylene chloride, in soil and groundwater at the Facility. Signet has undertaken four remedial actions at the Facility, as well as subsequent investigation activities to assess the adequacy of the remedial actions. Active remediation has included operation of a multiphase extraction system (MPE system) from 1995 to 1998 to remove subsurface VOCs from source areas at the Facility. Additionally, three targeted source removal actions have been conducted at the Facility since 1986. Remedial activities have included removal and disposal of contaminated soil and addition of soil amendments to facilitate in-situ degradation. In late 2009, an interim remedial measure to extract VOCs from deep groundwater was evaluated, and the findings of this evaluation are incorporated into the CAP.

RB Case Number :	2091500
Potential Media Affected :	Aquifer used for drinking water supply
Potential Contaminants of Concern :	1,1,1-Trichloroethane (TCA), Acetone, Benzene, Other Chlorinated Hydrocarbons, Tetrachloroethylene (PCE), Trichloroethylene (TCE), Freon, Diesel, Gasoline
Local Agency :	N/R
Local Case Number :	H02662-001
Lead Agency :	SAN DIEGO RWQCB (REGION 9)
File Location :	Regional Board
CUF Case :	NO
Caseworker :	N/R
Case Type :	Cleanup Program Site
How Discovered :	Visual
How Discovered Description :	N/R
Stop Method :	Close and Remove Tank
Stop Description :	N/R
Calwater Watershed Name :	Carlsbad - San Marcos - Richland (904.52)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)
Disadvantaged Community :	Severely Disadvantaged Community
Latitude :	33.144127
Longitude :	-117.185867
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-09

Contacts Summary

Global ID :	SL209154190
Contact Name :	N/R
Contact Type :	N/R
Organization Name :	N/R

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Address :	N/R
City :	N/R
Phone Number :	N/R
Email :	N/R

Regulatory Activities

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Date :	2018-06-11
Global ID :	SL209154190
Action Type :	ENFORCEMENT
Action :	Closure Summary

Date :	2014-06-30
Global ID :	SL209154190
Action Type :	ENFORCEMENT
Action :	Deed Restriction / Land Use Restriction / Covenant - #2014-0270414

Date :	2014-01-31
Global ID :	SL209154190
Action Type :	ENFORCEMENT
Action :	Closure/No Further Action Letter

Date :	2013-07-27
Global ID :	SL209154190
Action Type :	ENFORCEMENT
Action :	Annual Estimation Letter

Date :	2012-07-31
Global ID :	SL209154190
Action Type :	ENFORCEMENT
Action :	Cost Recovery Agreement / N. of Reimbursement

Date :	2012-04-02
Global ID :	SL209154190
Action Type :	ENFORCEMENT

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Action : Technical Correspondence / Assistance / Other

Date : 2012-02-03
Global ID : SL209154190
Action Type : RESPONSE
Action : Correspondence

Date : 2011-12-01
Global ID : SL209154190
Action Type : ENFORCEMENT
Action : Technical Correspondence / Assistance / Other

Date : 2011-03-03
Global ID : SL209154190
Action Type : ENFORCEMENT
Action : Technical Correspondence / Assistance / Other

Date : 2011-03-01
Global ID : SL209154190
Action Type : RESPONSE
Action : Monitoring Report - Annually - Regulator Responded

Status History

Status Date : 2014-01-31
Global ID : SL209154190
Status : Completed - Case Closed

Status Date : 2013-08-07
Global ID : SL209154190
Status : Open - Eligible for Closure

Status Date : 2006-03-30
Global ID : SL209154190
Status : Open - Site Assessment

Status Date : 2003-05-22
Global ID : SL209154190

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Status : Open - Remediation

Status Date : 2003-03-01
Global ID : SL209154190
Status : Open - Remediation

Status Date : 1986-08-22
Global ID : SL209154190
Status : Open - Case Begin Date

Facility Name : Proposed Davia Village
Facility Address : 1001 Armorlite Drive, San Marcos, CA 92069
County : San Diego

Site Details

Status Date : 2016-05-03
Status : Completed - Case Closed
Begin Date : 1986-08-01
Global ID : T10000003706

Site History : This case is for a planned redevleopment of the former Signet Armorlite Site. For historical information regarding the site please review the Geotracker file for Milano Holdings, Inc. (former Signet Armorlite), Geotracker ID SL209154190.

RB Case Number : 4090003
Potential Media Affected : Indoor Air, Other Groundwater (uses other than drinking water), Soil

Potential Contaminants of Concern : 1,1,1-Trichloroethane (TCA), Acetone, Other Chlorinated Hydrocarbons, Tetrachloroethylene (PCE), Trichloroethylene (TCE), Freon, Benzene, Diesel, Gasoline

Local Agency : N/R
Local Case Number : N/R
Lead Agency : SAN DIEGO RWQCB (REGION 9)
File Location : All Files are on GeoTracker or in the Local Agency Database
CUF Case : NO
Caseworker : SAM
Case Type : Cleanup Program Site
How Discovered : N/R
How Discovered Description : N/R

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Stop Method :	N/R
Stop Description :	N/R
Calwater Watershed Name :	Carlsbad - San Marcos - Richland (904.52)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)
Disadvantaged Community :	Severely Disadvantaged Community
Latitude :	33.144343
Longitude :	-117.186356
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-09

Contacts Summary

Global ID :	T10000003706
Contact Name :	SARAH A. MEARON
Contact Type :	Regional Board Caseworker
Organization Name :	SAN DIEGO RWQCB (REGION 9)
Address :	2375 NORTHSIDE DRIVE, SUITE 100
City :	SAN DIEGO
Phone Number :	6195213363
Email :	sarah.mearon@waterboards.ca.gov

Regulatory Activities

Date :	2017-09-05
Global ID :	T10000003706
Action Type :	RESPONSE
Action :	Other Report / Document

Date :	2017-06-26
Global ID :	T10000003706
Action Type :	ENFORCEMENT
Action :	Annual Estimation Letter

Date :	2016-06-17
Global ID :	T10000003706
Action Type :	ENFORCEMENT
Action :	Annual Estimation Letter

Date :	2016-02-12
Global ID :	T10000003706
Action Type :	ENFORCEMENT

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Action : Deed Restriction / LUC Monitoring Report

Date : 2015-06-22
Global ID : T10000003706
Action Type : ENFORCEMENT
Action : Annual Estimation Letter

Date : 2015-06-11
Global ID : T10000003706
Action Type : RESPONSE
Action : Technical Memos - Regulator Responded

Date : 2015-04-21
Global ID : T10000003706
Action Type : RESPONSE
Action : Technical Memos - Regulator Responded

Date : 2014-06-30
Global ID : T10000003706
Action Type : ENFORCEMENT
Action : Deed Restriction / Land Use Restriction / Covenant - #2014-0270414

Date : 2014-06-30
Global ID : T10000003706
Action Type : ENFORCEMENT
Action : Annual Estimation Letter

Date : 2014-01-31
Global ID : T10000003706
Action Type : ENFORCEMENT
Action : Closure/No Further Action Letter

Status History
Status Date : 2016-05-03
Global ID : T10000003706
Status : Completed - Case Closed

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Status Date :	2015-04-15
Global ID :	T10000003706
Status :	Open - Reopen Case
Status Date :	2015-04-15
Global ID :	T10000003706
Status :	Open - Eligible for Closure
Status Date :	2015-04-15
Global ID :	T10000003706
Status :	Open - Inactive
Status Date :	2014-01-31
Global ID :	T10000003706
Status :	Completed - Case Closed
Status Date :	2013-10-15
Global ID :	T10000003706
Status :	Open - Eligible for Closure
Status Date :	2012-05-11
Global ID :	T10000003706
Status :	Open - Assessment & Interim Remedial Action
Status Date :	1986-08-01
Global ID :	T10000003706
Status :	Open - Case Begin Date

CIWQS - CA

Facility Name :	SIGNET ARMORLITE
Facility Address :	1001 ARMORLITE DR, SAN MARCOS, CA 92069
County :	SAN DIEGO
Place ID :	257031
Agency Name :	SIGNET ARMORLITE
Last Date in Agency List :	2021-12-30

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

CIWQS - CA ***(cont.)***

Facility Name :	SIGNET ARMORLITE INC
Facility Address :	1001 ARMORLITE DR, SAN MARCOS, CA 92069
County :	SAN DIEGO
Place ID :	S257030
Agency Name :	SIGNET ARMORLITE ESSILOR LABS OF AMERICA
Last Date in Agency List :	2021-12-30

CIWQS 2 - CA

Facility Name :	Signet Armorlite
Facility Address :	1001 Armorlite Dr, San Marcos, 92069
County :	San Diego
Facility ID :	257031
WDID :	N/R
Facility Type :	All other facilities
Region :	9
Place Type :	Facility
Place Subtype :	N/R
Ageny Name :	N/R
Agency Type :	N/R
Number of Agencies :	N/R
Status Date :	N/R
Status :	N/R
Status Enrollee :	N/R
Individual/General :	N/R
Fee Code :	N/R
Staff Assigned :	N/R
Number of Staff Assigned :	N/R
Supervisor :	N/R
Number of Supervisor :	N/R
Number of Amendments :	0
Number of Reg Measures :	N/R
Baseline Flow :	N/R
Population (MS4)/Acres :	N/R
Reclamation :	N/R
CAFO Type :	N/R
CAFO Subtype :	N/R
CAFO Population :	N/R
Onsite :	N/R
Quality Assurance :	N/R
RCRA Flag :	N/R
Total MMP Violations Number :	0

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

CIWQS 2 - CA ***(cont.)***

Total Number of Violations :	2
Total Number of Inspections :	0
Date of Most Recent Completed Inspection:	N/R
Date of Most Recent Received Report :	N/R
Total Number of Final (A+H) Enforcement Actions:	2
Most Recent Effective Date of Enf Action (A+H):	2000-01-27
Program :	SLIC
Program Category :	TANKS
Number of Programs :	N/R
Complexity :	N/R
Pretreatment :	N/R
Facility Waste Type :	N/R
Reg Measure ID :	N/R
Reg Measure Type :	N/R
Reg Measure Title :	N/R
Reg Measure Description :	N/R
SIC 1 :	-
SIC 2 :	-
SIC 3 :	-
Latitude :	33.146831
Longitude :	-117.189715
Last Date in Agency List :	2022-01-18

CORRACTS

Facility Name :	SIGNET ARMORLITE, INC.
Facility Address :	1001 ARMORLITE DRIVE, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAD008362634
EPA Region :	09
Last Date in Agency List :	2022-01-25
HNAICS Code :	326199 - ALL OTHER PLASTICS PRODUCT MANUFACTURING 339115 - OPHTHALMIC GOODS MANUFACTURING
Area Name :	ENTIRE FACILITY
Actual Date :	2018-06-11
Action :	REMEDY CONSTRUCTION-REMEDY CONSTRUCTED
Original Schedule Date :	2018-06-11

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

CORRACTS ***(cont.)***

Schedule End Date : N/R

Area Name : ENTIRE FACILITY
Actual Date : 2018-06-11
Action : RELEASE TO GW CONTROLLED DETERMINATION-YES, APPLICABLE AS OF THIS DATE
Original Schedule Date : 2018-07-16
Schedule End Date : N/R

Area Name : ENTIRE FACILITY
Actual Date : 1997-12-15
Action : HUMAN EXPOSURES CONTROLLED DETERMINATION-YES, APPLICABLE AS OF THIS DATE
Original Schedule Date : 1997-12-15
Schedule End Date : N/R

Area Name : N/R
Actual Date : 1997-12-15
Action : RELEASE TO GW CONTROLLED DETERMINATION-FACILITY DOES NOT MEET DEFINITION
Original Schedule Date : N/R
Schedule End Date : N/R

Area Name : N/R
Actual Date : 1997-12-15
Action : REFERRED TO A NON-RCRA AUTHORITY
Original Schedule Date : N/R
Schedule End Date : N/R

Area Name : ENTIRE FACILITY
Actual Date : 1997-12-15
Action : RELEASE TO GW CONTROLLED DETERMINATION-FACILITY DOES NOT MEET DEFINITION
Original Schedule Date : 1997-12-15
Schedule End Date : N/R

Area Name : N/R
Actual Date : 1997-12-15
Action : HUMAN EXPOSURES CONTROLLED DETERMINATION-YES, APPLICABLE AS OF THIS DATE

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

CORRACTS ***(cont.)***

Original Schedule Date : N/R
Schedule End Date : N/R

Area Name : ENTIRE FACILITY
Actual Date : 1996-01-01

Action : STABILIZATION/INTERIM MEASURES DECISION-PRIMARY MEAS IS SOURCE REMOVL &/OR TRT

Original Schedule Date : N/R
Schedule End Date : N/R

Area Name : ENTIRE FACILITY
Actual Date : 1996-01-01
Action : STABILIZATION/INTERIM MEASURES DECISION-GROUNDWATER EXTRACTION & TREATMENT
Original Schedule Date : N/R
Schedule End Date : N/R

Area Name : N/R
Actual Date : 1992-01-31
Action : STABILIZATION MEASURES EVALUATION-FACILITY NOT AMENABLE TO STABILIZATION
Original Schedule Date : N/R
Schedule End Date : N/R

Area Name : N/R
Actual Date : 1992-01-15
Action : CA PRIORITIZATION-LOW CA PRIORITY
Original Schedule Date : N/R
Schedule End Date : N/R

Area Name : N/R
Actual Date : 1991-08-08
Action : CA PRIORITIZATION-LOW CA PRIORITY
Original Schedule Date : N/R
Schedule End Date : N/R

Area Name : N/R
Actual Date : 1991-08-08

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

CORRACTS ***(cont.)***

Action :	PA OR CERCLA INSPECTION
Original Schedule Date :	N/R
Schedule End Date :	N/R
Area Name :	N/R
Actual Date :	1991-08-08
Action :	RFA COMPLETED-ASSESSMENT WAS A RFA
Original Schedule Date :	N/R
Schedule End Date :	N/R
Area Name :	N/R
Actual Date :	1991-08-08
Action :	LEAD AGENCY DETERMINATION
Original Schedule Date :	N/R
Schedule End Date :	N/R

CORRECTIVE ACTIONS_2020

Facility Name :	SIGNET ARMORLITE, INC.
Facility Address :	1001 ARMORLITE DRIVE, SAN MARCOS, CA 92069
EPA ID :	CAD008362634
Region :	9
Remedy Construction :	N/R
Federal Facility :	N/R
CA725 :	YE
CA750 :	N/R
CA550 :	N/R
CA900 :	N/R

DEED - CA

Facility Name :	MILANO HOLDINGS INC. (FORMER SIGNET ARMORLITE, INC.)
Facility Address :	1001 ARMORLITE DRIVE, SAN MARCOS, 92069
County :	SAN DIEGO
Date Recorded :	2014-06-30
Global ID :	SL209154190
Status :	COMPLETED - CASE CLOSED
Site Type :	SLIC
Lead Agency :	SAN DIEGO RWQCB (REGION 9)
Covenant Uploaded? :	Y

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

DEED - CA ***(cont.)***

APN(s) :	N/R
Link To Deed Restriction :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-31
Facility Name :	PROPOSED DAVIA VILLAGE
Facility Address :	1001 ARMORLITE DRIVE, SAN MARCOS, 92069
County :	SAN DIEGO
Date Recorded :	2014-06-30
Global ID :	T10000003706
Status :	COMPLETED - CASE CLOSED
Site Type :	SLIC
Lead Agency :	SAN DIEGO RWQCB (REGION 9)
Covenant Uploaded? :	Y
APN(s) :	N/R
Link To Deed Restriction :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-31

DOCKET

Facility Name :	SIGNET ARMORLITE
Facility Address :	1001 ARMORLITE DR, SAN MARCOS, CA 92069

Standard Industrial Classification(SIC) Summary

Enforcement Action Name :	SIGNET ARMORLITE
Registry ID :	110000478689
Primary SIC :	3851 - OPHTHALMIC GOODS
Primary NAICS :	326199 - All Other Plastics Product Manufacturing
Last Date in Agency List :	2018-12-17
Enforcement Action Case Number :	N/R
Activity ID :	N/R
Final Ordr Iss/Final Order Enter Date:	N/R
Final Order Name :	N/R
Settlement FRS ICIS Facility ID :	N/R
Final Order FRS Name :	N/R

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

DOCKET ***(cont.)***

SEP Category :	N/R
SEP Description :	N/R

Complaint Summary

Respondent/Defendant Name :	N/R
Named in Complaint :	N/R
Named in Final Order :	N/R

Pollutant Summary

Pollutants (SRS) :	N/R

Violation and Enforcement Action Summary

Court Docket Number :	N/R
Complaint/Proposed Order Actual Date:	N/R
Final Order Issued Actual Date :	N/R
Admin EA Closed Actual Date :	1994-03-21
Enforcement Action Name :	SIGNET ARMORLITE 060730005800027
Enforcement Action Resolution :	N/R
Violation Type :	N/R
Statute Code :	CAA
Law Section Code :	OTHER
Law Section Description :	Violations not covered elsewhere

Violation Penalties and Compliance Summary

Compliance Action Cost :	N/R
EPA Penalty Assessed Amount :	N/R
Cost Recovery Required :	N/R
Cost of SEP :	N/R
Cost of Complying Actions :	N/R

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

DOCKET ***(cont.)***

Standard Industrial Classification(SIC) Summary

Enforcement Action Name :	SIGNET ARMORLITE
Registry ID :	110000478689
Primary SIC :	3851 - OPHTHALMIC GOODS
Primary NAICS :	326199 - All Other Plastics Product Manufacturing
Last Date in Agency List :	2019-02-25
Enforcement Action Case Number :	CASDSA0000060730005800029
Activity ID :	3400498190
Final Ordr Iss/Final Order Enter Date:	1994-03-28
Final Order Name :	SIGNET ARMORLITE 060730005800029
Settlement FRS ICIS Facility ID :	3400192680
Final Order FRS Name :	SIGNET ARMORLITE
SEP Category :	N/R
SEP Description :	N/R

Complaint Summary

Respondent/Defendant Name :	N/R
Named in Complaint :	N/R
Named in Final Order :	N/R

Pollutant Summary

Pollutants (SRS) :	N/R

Violation and Enforcement Action Summary

Court Docket Number :	N/R
Complaint/Proposed Order Actual Date:	N/R
Final Order Issued Actual Date :	1994-03-28
Admin EA Closed Actual Date :	N/R
Enforcement Action Name :	N/R
Enforcement Action Resolution :	N/R

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

DOCKET ***(cont.)***

Violation Type :	N/R
Statute Code :	CAA
Law Section Code :	OTHER
Law Section Description :	Violations not covered elsewhere

Violation Penalties and Compliance Summary

Compliance Action Cost :	0
EPA Penalty Assessed Amount :	0
Cost Recovery Required :	N/R
Cost of SEP :	0
Cost of Complying Actions :	N/R

ECHO

Facility Name :	SIGNET ARMORLITE
Facility Address :	1001 ARMORLITE DR., SAN MARCOS, CA 92069
County :	SAN DIEGO
Last Inspection Date :	2006-10-27
Registry ID :	110000478689
FIPS Code :	06073
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	4853
Informal Count :	0
Last Informal Action Date :	1994-03-21
Formal Action Count :	0
Last Formal Action Date :	1994-03-28
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	1994-03-28
Last Penalty Amount :	800
QTRS IN NC :	0
Programs IN SNC :	0
Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	_____
Collection Method :	ADDRESS MATCHING-HOUSE NUMBER
Reference Point :	ENTRANCE POINT OF A FACILITY OR STATION
Accuracy Meters :	50

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

ECHO ***(cont.)***

Derived Tribes :

San Pasqual Band of Diegueno Mission Indians of California - 11.8 mile(s), Pala Band of Mission Indians - 13.2 mile (s), Rincon Band of Luiseno Mission Indians of the Rincon Reservation, California - 13.6 mile(s), Rincon Band of Luiseno Mission Indians of the Rincon Reservation, California - 15.8 mile(s), Pauma Band of Luiseno Mission Indians of the Pauma & Yuima Reservation, California - 16.7 mile(s), La Jolla Band of Luiseno Indians, California - 16.7 mile (s), Pechanga Band of Luiseno Mission Indians of the Pechanga Reservation, California - 20.6 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 21.9 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 22.2 mile(s), Mesa Grande Band of Diegueno Mission Indians of the Mesa Grande Reservation, California - 22.6 mile(s)

Derived HUC :	18070303
Derived WBD :	180703030503
Derived STCTY FIPS :	06073
Derived Zip :	92069
Derived CD113 :	50
Derived CB2010 :	060730200292001
MYRTK Universe :	NNY
NPDES IDs :	N/R
CWA Permit Types :	N/R
CWA Compliance Tracking :	N/R
CWA NAICS :	N/R
CWA SICS :	N/R
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	N/R
CWA Current Compliance Status :	N/R
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	N/R
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.
Facility SIC :	3851
Facility NAICS :	326199 - All Other Plastics Product Manufacturing, 339113 - Surgical Appliance and Supplies Manufacturing
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	2006-10-27

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

ECHO ***(cont.)***

Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	1994-03-28
Facility Last Informal Act EPA Date :	1988-07-05
Facility Last Informal Act State Date:	1994-03-21
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	Y
Chesapeak Bay Flag :	N/R
AIR Flag :	Y
NPDES Flag :	N
SDWIS Flag :	N
RCRA Flag :	Y
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	Y
NAA Flag :	Y
Latitude :	33.14483
Longitude :	-117.18417
Last Date in Agency List :	2020-02-10

Facility Name :	SIGNET ARMORLITE INC
Facility Address :	1001 ARMORLITE DR., SAN MARCOS, CA 92069
County :	SAN DIEGO

Last Inspection Date :	2009-02-12
Registry ID :	110000478689
FIPS Code :	06073
EPA Region :	09
Inspection Count :	0
Last Inspection Days :	4693
Informal Count :	0
Last Informal Action Date :	1994-03-21
Formal Action Count :	0
Last Formal Action Date :	1994-03-28
Total Penalties :	0
Penalty Count :	N/R
Last Penalty Date :	1994-03-28
Last Penalty Amount :	800
QTRS IN NC :	0

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

ECHO ***(cont.)***

Programs IN SNC :	0
Current Compliance Status :	No Violation Identified
Three-Year Compliance Status :	_____
Collection Method :	ADDRESS MATCHING-HOUSE NUMBER
Reference Point :	ENTRANCE POINT OF A FACILITY OR STATION
Accuracy Meters :	50

Derived Tribes :

San Pasqual Band of Diegueno Mission Indians of California - 11.8 mile(s), Pala Band of Mission Indians - 13.2 mile (s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 13.6 mile(s), Rincon Band of Luiseno Mission Indians of Rincon Reservation, California - 15.8 mile(s), Pauma Band of Luiseno Mission Indians of the Pauma & Yuima Reservation, California - 16.7 mile(s), La Jolla Band of Luiseno Indians, California - 16.7 mile(s), Pechanga Band of Luiseno Mission Indians of the Pechanga Reservation, California - 20.6 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 21.9 mile(s), Capitan Grande Band of Diegueno Mission Indians of California: Barona Group of Capitan Grande Band of Mission Indians of the Barona Reservation, California - 22.2 mile(s), Mesa Grande Band of Diegueno Mission Indians of the Mesa Grande Reservation, California - 22.6 mile(s)

Derived HUC :	18070303
Derived WBD :	180703030503
Derived STCTY FIPS :	06073
Derived Zip :	92069
Derived CD113 :	50
Derived CB2010 :	060730200292001
MYRTK Universe :	NNY
NPDES IDs :	N/R
CWA Permit Types :	N/R
CWA Compliance Tracking :	N/R
CWA NAICS :	N/R
CWA SICS :	N/R
CWA Inspection Count :	N/R
CWA Last Inspection Days :	N/R
CWA Informal Count :	N/R
CWA Formal Action Count :	N/R
CWA Last Formal Action Date :	N/R
CWA Penalties :	N/R
CWA Last Penalty Date :	N/R
CWA Last Penalty Amount :	N/R
CWA Quarters IN NC :	N/R
CWA Current Compliance Status :	N/R
CWA Current SNC Flag :	N
CWA 13 Quarters Compliance Status :	N/R
CWA 13 Quarters Effluent Exceedances:	N/R
CWA Three-Year QNCR Codes :	N/R
DFR URL :	Click here for hyperlink provided by the agency.

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

ECHO ***(cont.)***

Facility SIC :	3851
Facility NAICS :	326199 - All Other Plastics Product Manufacturing, 339113 - Surgical Appliance and Supplies Manufacturing
Facility Last Inspection EPA Date :	N/R
Facility Last Inspection State Date :	2009-02-12
Facility Last Formal Act EPA Date :	N/R
Facility Last Formal Act State Date :	1994-03-28
Facility Last Informal Act EPA Date :	1988-07-05
Facility Last Informal Act State Date:	1994-03-21
Facility Federal Agency :	N/R
TRI Reporter :	N/R
Facility Imp Water Flag :	N/R
Current SNC Flag :	N
Indian County Flag :	N
Federal Flag :	N/R
US Mexico Border Flag :	Y
Chesapeak Bay Flag :	N/R
AIR Flag :	Y
NPDES Flag :	N
SDWIS Flag :	N
RCRA Flag :	Y
TRI Flag :	N
GHG Flag :	N
Major Flag :	N/R
Active Flag :	Y
NAA Flag :	Y
Latitude :	33.14483
Longitude :	-117.18417
Last Date in Agency List :	2022-01-17

ENVIROSTOR - CA

Facility Name :	SIGNET ARMORLITE INC
Facility Address :	1001 ARMORLITE DR, SAN MARCOS, CA 920690000
County :	SAN DIEGO

Site Details

Cleanup Date :	2012-08-29
Cleanup Status :	Refer: RWQCB
Site Type :	Corrective Action
Site Type Detailed :	Corrective Action
Acreage :	0

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

ENVIROSTOR - CA ***(cont.)***

APN :	NONE SPECIFIED
National Priorities List :	NO
Regulatory Agencies Involved :	RWQCB 9 - San Diego
Lead Agency :	RWQCB 9 - San Diego
Project Manager :	N/R
Supervisor :	* Unknown
Office :	Cleanup Cypress
Envirostor ID :	80001570
Site Code :	400252
Assembly :	75
Senate :	38
Congressional District :	50
Special Program :	N/R
Past Uses :	NONE SPECIFIED
Potential COC :	N/R
Confirmed COC :	N/R
Potential Media Affected :	N/R
Restricted Use :	NO
Site Management Req :	N/R
Funding :	N/R
Latitude :	33.145548
Longitude :	-117.185379
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-14

Alias Details

Alias :	110000478689
Alias Type :	EPA (FRS #)
Alias :	400252
Alias Type :	Project Code (Site Code)
Alias :	80001570
Alias Type :	Envirostor ID Number
Alias :	CAD008362634
Alias Type :	EPA Identification Number

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

ENVIROSTOR - CA ***(cont.)***

Completed Activities

Completed Date :	2018-06-11
Area Name :	PROJECT WIDE
Sub Area Name :	N/R
Document Type :	Remedy Construction Complete
Comments :	N/R

Completed Date :	2018-06-11
Area Name :	PROJECT WIDE
Sub Area Name :	N/R
Document Type :	Groundwater Migration Controlled
Comments :	N/R

Completed Date :	1997-12-15
Area Name :	PROJECT WIDE
Sub Area Name :	N/R
Document Type :	Groundwater Migration Controlled
Comments :	N/R

Completed Date :	1997-12-15
Area Name :	PROJECT WIDE
Sub Area Name :	N/R
Document Type :	Human Exposure Controlled
Comments :	N/R

Completed Date :	1996-01-01
Area Name :	PROJECT WIDE
Sub Area Name :	N/R
Document Type :	Interim Measures Workplan
Comments :	N/R

Completed Date :	1995-04-10
Area Name :	PROJECT WIDE
Sub Area Name :	N/R
Document Type :	Consent Order
Comments :	N/R

Completed Date :	1992-01-31
Area Name :	PROJECT WIDE
Sub Area Name :	N/R

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

ENVIROSTOR - CA ***(cont.)***

Document Type : Interim Measures Questionnaire
Comments : N/R

Completed Date : 1991-08-08
Area Name : PROJECT WIDE
Sub Area Name : N/R
Document Type : RCRA Facility Assessment Report
Comments : N/R

Completed Date : 1991-08-08
Area Name : PROJECT WIDE
Sub Area Name : N/R
Document Type : Preliminary Assessment Report
Comments : N/R

Future Activities
Area Name : N/R
Sub Area Name : N/R
Document Type : N/R
Due Date : N/R

Scheduled Activites
Due Date : N/R
Revised Date : N/R
Area Name : N/R
Sub Area Name : N/R
Document Type : N/R

EPA LUST

Facility Name : ARMORLITE INC
Facility Address : 1001 ARMORLITE DR, SAN MARCOS, California 920691431
County : N/R

Facility ID : N/R
LUST ID : CAT0607302793
Reported Date : N/R
Status : No Further Action
Substance : N/R

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

EPA LUST ***(cont.)***

Closed With Residual Contamination (Tribal Only):	N/R
NFA_Letter (Tribal Only) :	N/R
Tribe (Tribal Only) :	N/R
EPA Region :	9
Estimated Population within 1500ft :	233
Estimated Private Domestic Wells within 1500ft:	1
Within Source Water Protection Area (SPA):	No
SPA Public Water System and Facility ID:	N/R
SPA Water Type :	N/R
SPA Facility Type :	N/R
SPA HUC12 :	N/R
Within Groundwater Wellhead Protection Area (WHPA):	No
WHPA Public Water System and Facility ID:	N/R
WHPA Water Type :	N/R
WHPA Facility Type :	N/R
WHPA HUC12 :	N/R
Within Estimated 100-year Floodplain:	No
Latitude :	33.144779999999898
Longitude :	-117.184259999999000
Last Date in Agency List :	2022-01-04

FRS

Facility Name :	ARMORLITE INC
Facility Address :	1001 ARMORLITE DR, SAN MARCOS, CA 920691431
County :	SAN DIEGO

Site Details

Registry ID :	110065494049
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Source Description

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

FRS ***(cont.)***

Source Description :

The California Environmental Protection Agency (CalEPA) has recently implemented a new data warehouse system (nSite). This data warehouse combines and merges facility and site information from five different systems managed within CalEPA. The five systems are: California Environmental Reporting System (CERS), EnviroStor, GeoTracker, California Integrated Water Quality System (CIWQS), and Toxic Release Inventory (TRI).

FRS Environmental Interest

Source and System ID :	CA-ENVIROVIEW - 207455
Facility Name :	MILANO HOLDINGS INC. (FORMER SIGNET ARMORLITENA INC.)
Facility Address :	1001 ARMORLITE DRIVE, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Registry ID :	110066604400
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Source Description

Source Description :

The California Environmental Protection Agency (CalEPA) has recently implemented a new data warehouse system (nSite). This data warehouse combines and merges facility and site information from five different systems managed within CalEPA. The five systems are: California Environmental Reporting System (CERS), EnviroStor, GeoTracker, California Integrated Water Quality System (CIWQS), and Toxic Release Inventory (TRI).

FRS Environmental Interest

Source and System ID :	CA-ENVIROVIEW - 209533
Facility Name :	PROPOSED DAVIA VILLAGE
Facility Address :	1001 ARMORLITE DRIVE, SAN MARCOS, CA 92069
County :	SAN DIEGO

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

FRS ***(cont.)***

Site Details
Registry ID : 110066552867
FRS Facility URL : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-02-17

Source Description

Source Description :

The California Environmental Protection Agency (CalEPA) has recently implemented a new data warehouse system (nSite). This data warehouse combines and merges facility and site information from five different systems managed within CalEPA. The five systems are: California Environmental Reporting System (CERS), EnviroStor, GeoTracker, California Integrated Water Quality System (CIWQS), and Toxic Release Inventory (TRI).

FRS Environmental Interest
Source and System ID : CA-ENVIROVIEW - 212080

Facility Name : SIGNET ARMORLITE
Facility Address : 1001 ARMORLITE DR., SAN MARCOS, CA 920691431
County : SAN DIEGO

Site Details
Registry ID : 110000478689
FRS Facility URL : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2020-08-31

Source Description
Source Description : AIR contains compliance and permit data for stationary sources of air pollution regulated by the EPA, State, and Local air pollution agencies. AFS contains compliance and permit data for stationary sources of air pollution regulated by the EPA, State, and Local air pollution agencies. All generators and treatment, storage, and disposal (TSD) facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years. The data collected is used to create the National Biennial Resource Conservation and Recovery Act (RCRA) Hazardous Waste Report. This data is processed within the RCRA Information (RCRAInfo) database.

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

FRS ***(cont.)***

Source Description : The Emission Inventory System (EIS) maintains an inventory of large stationary sources and voluntarily-reported smaller sources of air point pollution emitters. It contains information about facility sites and their physical location, emission units, emission processes, release points, control approaches, and regulations. Facility inventory data are kept separate from the emissions data and have stable identifiers to improve continuity from year to year and to help identify duplicate or missing facilities.
HWTS-DATAMART provides California with information on hazardous waste shipments for generators, transporters, and treatment, storage, and disposal facilities.

Source Description :

RCRAInfo is EPA's comprehensive information system that supports the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984 through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA. RCRAInfo also supports generation of the National Hazardous Waste Biennial Report. All generators and treatment, storage, and disposal facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years to support creation of the Biennial Report.

FRS Environmental Interest

Source and System ID : AIRS/AFS - 0607300058
EIS - 2432411
HWTS-DATAMART - CAD008362634
ICIS - CASDS0000607300058
RCRAINFO - CAD008362634

Facility Name : SIGNET ARMORLITE INC
Facility Address : 1001 ARMORLITE DR., SAN MARCOS, CA 920691431
County : SAN DIEGO

Site Details

Registry ID : 110000478689
FRS Facility URL : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-02-17

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

FRS ***(cont.)***

Source Description

Source Description : AIR contains compliance and permit data for stationary sources of air pollution regulated by the EPA, State, and Local air pollution agencies. AFS contains compliance and permit data for stationary sources of air pollution regulated by the EPA, State, and Local air pollution agencies. All generators and treatment, storage, and disposal (TSD) facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years. The data collected is used to create the National Biennial Resource Conservation and Recovery Act (RCRA) Hazardous Waste Report. This data is processed within the RCRA Information (RCRAInfo) database.

Source Description : The Emission Inventory System (EIS) maintains an inventory of large stationary sources and voluntarily-reported smaller sources of air point pollution emitters. It contains information about facility sites and their physical location, emission units, emission processes, release points, control approaches, and regulations. Facility inventory data are kept separate from the emissions data and have stable identifiers to improve continuity from year to year and to help identify duplicate or missing facilities.
HWTS-DATAMART provides California with information on hazardous waste shipments for generators, transporters, and treatment, storage, and disposal facilities.

Source Description :

RCRAInfo is EPA’s comprehensive information system that supports the Resource Conservation and Recovery Act (RCRA) of 1976 and the Hazardous and Solid Waste Amendments (HSWA) of 1984 through the tracking of events and activities related to facilities that generate, transport, and treat, store, or dispose of hazardous waste. RCRAInfo allows RCRA program staff to track the notification, permit, compliance, and corrective action activities required under RCRA. RCRAInfo also supports generation of the National Hazardous Waste Biennial Report. All generators and treatment, storage, and disposal facilities who handle hazardous waste are required to report to the EPA Administrator at least once every two years to support creation of the Biennial Report.

FRS Environmental Interest

Source and System ID : AIRS/AFS - 0607300058
EIS - 2432411
HWTS-DATAMART - CAD008362634
ICIS - CASDS0000607300058
RCRAINFO - CAD008362634

HAZMAT_SAN DIEGO COUNTY - CA

Facility Name : ARMORLITE INC
Facility Address : 1001 ARMORLITE DR, SAN MARCOS, CA 92069

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

HAZMAT_SAN DIEGO COUNTY - CA ***(cont.)***

Date :	2002-05-04
Record ID :	DEH2002-HUPFP-102662
Record Type :	Unified Program Facility Permit
Status :	Completed
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23
Facility Name :	SIGNET ARMORLITE, INC
Facility Address :	1001 ARMORLITE DR, SAN MARCOS, CA 92069
Date :	2010-12-15
Record ID :	DEH2010-HUPFP-213233
Record Type :	Unified Program Facility Permit
Status :	Permit Suspended
Action :	N/R
Short Notes :	N/R
Last Date in Agency List :	2015-11-23

HAZNET - CA

Facility Name :	MILANO HOLDING INC.
Facility Address :	1001 ARMORLITE DR, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAC002717415
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	TEMPORARY
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	130 BIRMINGHAM DRIVE, SAN MARCOS, CA 92069
Latitude :	33.14479050
Longitude :	-117.18425677
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

HAZNET - CA ***(cont.)***

Waste Generator Details

State Waste : 2013: 151 - Asbestos containing waste, 0.4 tons to AZC950823111

Facility Name : SIGNET ARMORLITE INC
Facility Address : 1001 ARMORLITE DR, SAN MARCOS, CA 92069
County : SAN DIEGO

Site Details

Generator EPA ID : CAD008362634
Active : Inactive
Category : FEDERAL
Facility Types : N/R
Type : PERMANENT
Contact Name : N/R
Contact Phone : N/R
Facility Mailing Address : 1001 ARMORLITE DR, SAN MARCOS, CA 920691431
Latitude : 33.14479050
Longitude : -117.18425677
Agency Hyperlink : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2021-07-08

Waste Generator Details

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

State Waste :
2013: 214 - Unspecified solvent mixture, 0.005 tons to CAD008252405
2013: 212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.), tons to CAD008252405
2013: 223 - Unspecified oil-containing waste, 0.2502 tons to CAD028409019
2013: 181 - Other inorganic solid waste, 0.002 tons to IN0000351387
2013: 122 - Alkaline solution without metals pH >= 12.5, 1.8348 tons to CAT080013352
2013: 181 - Other inorganic solid waste, 0.155 tons to AZR000501510
2013: 141 - Off-specification, aged or surplus inorganics, 0.00417 tons to CAD028409019
2013: 352 - Other organic solids, 0.231 tons to CAD008252405
2013: 223 - Unspecified oil-containing waste, 0.18765 tons to CAT080013352

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

HAZNET - CA ***(cont.)***

2013: 331 - Off-specification, aged or surplus organics, 0.105 tons to TXD055141378
2013: 181 - Other inorganic solid waste, 101.136 tons to AZD983481813
2013: 135 - Unspecified aqueous solution, 0.21 tons to AZR000501510
2013: 331 - Off-specification, aged or surplus organics, 0.033 tons to CAD028409019
2013: 141 - Off-specification, aged or surplus inorganics, 0.00417 tons to CAD097030993
2013: 221 - Waste oil and mixed oil, 0.266 tons to CAT080013352
2013: 223 - Unspecified oil-containing waste, 0.09 tons to CAD044429835
2013: 343 - Unspecified organic liquid mixture, 0.65 tons to TXD055141378
2013: 551 - Laboratory waste chemicals, 0.0725 tons to TXD055141378
2013: 134 - Aqueous solution with total organic residues less than 10 percent, 0.21 tons to CAD044429835
2013: 214 - Unspecified solvent mixture, 0.108 tons to CAD028409019
2012: 135 - Unspecified aqueous solution, 0.63 tons to CAD982444481
2012: 343 - Unspecified organic liquid mixture, 0.4415 tons to UTD981552177
2012: 181 - Other inorganic solid waste, 0.192 tons to CAD982444481
2012: 223 - Unspecified oil-containing waste, 0.6672 tons to CAT080013352
2012: 181 - Other inorganic solid waste, 337.12 tons to AZD983481813
2012: N/R - Blank or unknown, 67.424 tons to AZD983481813
2012: 122 - Alkaline solution without metals pH >= 12.5, 6.7554 tons to CAT080013352
2012: 741 - Liquids with halogenated organic compounds >= 1,000 Mg./L, 0.2365 tons to UTD981552177
2012: 331 - Off-specification, aged or surplus organics, 0.112 tons to UTD981552177
2012: 352 - Other organic solids, 1.6305 tons to CAD008252405

HIST AFS 2

Facility Name :	SIGNET ARMORLITE
Facility Address :	1001 ARMORLITE DR, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

PEPA :	110000478689
Region :	09
STTE :	06
County Code :	073

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

HIST AFS 2 ***(cont.)***

PCDS :	00058
DB Number :	N/R
AQCR :	029
SIC Code :	3851
NIC Code :	326199
DCS :	3
DCL :	B
Government :	0
CMSC :	N/R
HP1F :	N/R
Last Date in Agency List :	2015-01-14

Air Pollutant Data

Region :	09
STTE :	06
County Code :	073
PCDS :	00058
APC :	0
PLAP :	ADMIN
DCAP :	3
DCLP :	B
DATT :	N/R

Region :	09
STTE :	06
County Code :	073
PCDS :	00058
APC :	0
PLAP :	HC
DCAP :	3
DCLP :	B
DATT :	N

Region :	09
STTE :	06
County Code :	073
PCDS :	00058
APC :	0
PLAP :	NO2
DCAP :	3
DCLP :	B
DATT :	A

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

HIST AFS 2 ***(cont.)***

Region :	09
STTE :	06
County Code :	073
PCDS :	00058
APC :	V
PLAP :	FACIL
DCAP :	3
DCLP :	B
DATT :	N/R

Region :	09
STTE :	06
County Code :	073
PCDS :	00058
APC :	0
PLAP :	SO2
DCAP :	3
DCLP :	B
DATT :	A

Region :	09
STTE :	06
County Code :	073
PCDS :	00058
APC :	0
PLAP :	PT
DCAP :	3
DCLP :	B
DATT :	N

Region :	09
STTE :	06
County Code :	073
PCDS :	00058
APC :	0
PLAP :	VOC
DCAP :	3
DCLP :	B
DATT :	V

Region :	09
STTE :	06

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

HIST AFS 2 ***(cont.)***

County Code :	073
PCDS :	00058
APC :	0
PLAP :	CO
DCAP :	3
DCLP :	B
DATT :	A

Historical Quarterly Status 12

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Region :	09
STTE :	06
County Code :	073
PCDS :	00058
SCH :	3
HDT :	1204
APH :	V

Region :	09
STTE :	06
County Code :	073
PCDS :	00058
SCH :	3
HDT :	1203
APH :	V

Region :	09
STTE :	06
County Code :	073
PCDS :	00058
SCH :	3
HDT :	1403
APH :	0

Region :	09
STTE :	06
County Code :	073

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

HIST AFS 2 ***(cont.)***

PCDS :	00058
SCH :	3
HDT :	1303
APH :	V
Region :	09
STTE :	06
County Code :	073
PCDS :	00058
SCH :	3
HDT :	1203
APH :	0
Region :	09
STTE :	06
County Code :	073
PCDS :	00058
SCH :	3
HDT :	1303
APH :	0
Region :	09
STTE :	06
County Code :	073
PCDS :	00058
SCH :	3
HDT :	1104
APH :	V
Region :	09
STTE :	06
County Code :	073
PCDS :	00058
SCH :	3
HDT :	1304
APH :	0
Region :	09
STTE :	06
County Code :	073
PCDS :	00058

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

HIST AFS 2 ***(cont.)***

SCH :	3
HDT :	1201
APH :	0
Region :	09
STTE :	06
County Code :	073
PCDS :	00058
SCH :	3
HDT :	1304
APH :	V

Non a Sources - Actions

Region :	09
STTE :	06
County Code :	073
PCDS :	00058
PEPA :	110000478689
APC :	V
ANT :	5C
DTA :	980121
PAM :	000000000
Region :	09
STTE :	06
County Code :	073
PCDS :	00058
PEPA :	110000478689
APC :	0
ANT :	FS
DTA :	030122
PAM :	N/R
Region :	09
STTE :	06
County Code :	073
PCDS :	00058
PEPA :	110000478689
APC :	0
ANT :	5C
DTA :	000330

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

HIST AFS 2 ***(cont.)***

PAM :	000000000
Region :	09
STTE :	06
County Code :	073
PCDS :	00058
PEPA :	110000478689
APC :	V
ANT :	CC
DTA :	020506
PAM :	N/R
Region :	09
STTE :	06
County Code :	073
PCDS :	00058
PEPA :	110000478689
APC :	V
ANT :	FS
DTA :	040120
PAM :	N/R
Region :	09
STTE :	06
County Code :	073
PCDS :	00058
PEPA :	110000478689
APC :	V
ANT :	FS
DTA :	050708
PAM :	N/R
Region :	09
STTE :	06
County Code :	073
PCDS :	00058
PEPA :	110000478689
APC :	0
ANT :	5C
DTA :	990127
PAM :	000000000

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

HIST AFS 2 ***(cont.)***

Region :	09
STTE :	06
County Code :	073
PCDS :	00058
PEPA :	110000478689
APC :	V
ANT :	SR
DTA :	030422
PAM :	N/R

Region :	09
STTE :	06
County Code :	073
PCDS :	00058
PEPA :	110000478689
APC :	V
ANT :	ER
DTA :	040707
PAM :	N/R

Region :	09
STTE :	06
County Code :	073
PCDS :	00058
PEPA :	110000478689
APC :	0
ANT :	FS
DTA :	070612
PAM :	N/R

Permit Events

Region :	09
STTE :	06
County Code :	073
PCDS :	00058
PAPN :	960096
PATY :	IF
PADL :	*PERMIT AUTHORITY ISSUES FINAL PERMIT
PACN :	001
PDEA :	20001125

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

HWG - CA

Facility Name :	MILANO HOLDING INC.
Facility Address :	1001 ARMORLITE DR, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAC002717415
Status :	Inactive
Category :	STATE
Type :	TEMPORARY
Facility Type :	N/R
Mailing Address :	130 BIRMINGHAM DRIVE, SAN MARCOS, CA 92069
Owner Name :	MILANO HOLDING INC.
Owner Address :	130 BIRMINGHAM DRIVE, SAN MARCOS, CA 92069
Operator Name :	ADAM STANFORD
Operator Address :	130 BIRMINGHAM DRIVE, SAN MARCOS, CA 92069
Latitude :	33.14484
Longitude :	-117.184356

Facility Name :	SIGNET ARMORLITE INC
Facility Address :	1001 ARMORLITE DR, SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAD008362634
Status :	Inactive
Category :	FEDERAL
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	1001 ARMORLITE DR, SAN MARCOS, CA 920691431
Owner Name :	EOA HOLDING CO INC
Owner Address :	13555 N STEMMONS FWY, DALLAS, TX 752340000
Operator Name :	PRASHANT SANTAN
Operator Address :	130 BINGHAM DR, SAN MARCOS, CA 920691402
Latitude :	33.14688
Longitude :	-117.18979

HWP - CA

Facility Name :	SIGNET ARMORLITE INC
Facility Address :	1001 ARMORLITE DR, SAN MARCOS, CA 920690000
County :	SAN DIEGO

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

HWP - CA ***(cont.)***

Site Details

EPA ID :	CAD008362634
Site Code :	400252
Facility Type :	Historical - Non-Operating
Status :	CLOSED
Team :	N/R
Facility Size :	N/R
Project Manager :	N/R
Assembly District :	75
Senate District :	38
Public Information Officer :	N/R
Public Participation Specialist :	N/R
Latitude :	33.145548
Longitude :	-117.185379
Last Date in Agency List :	2022-02-07
Alias :	110000478689
Alias Type :	FRS
Alias :	400252
Alias Type :	Project Code (Site Code)

Completed Activities Details

Completed Date :	1991-06-20
Unit Names :	N/R
Event Description :	New Operating Permit - FINAL PERMIT - WITHDRAWAL REQUEST ACKNOWLEDGED
Completed Date :	1989-12-07
Unit Names :	N/R
Event Description :	New Operating Permit - FINAL PERMIT - WITHDRAWAL REQUEST RECEIVED
Completed Date :	1989-11-29
Unit Names :	N/R
Event Description :	New Operating Permit - APPLICATION PART A RECEIVED

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

HWP - CA ***(cont.)***

Undergoing Closure Details

Completed Date :	1992-06-30
Unit Names :	CONTAIN1, OTHRTRT1
Event Description :	Closure Final - ISSUE CLOSURE VERIFICATION
Completed Date :	1992-06-18
Unit Names :	CONTAIN1, OTHRTRT1
Event Description :	Closure Final - RECEIVE CLOSURE CERTIFICATION

Maintenance Information

Received Date :	N/R
Title :	N/R
Document Type :	N/R

LUST REG 9 - CA

Facility Name :	ARMORLITE INC
Facility Address :	1001 ARMORLITE DR, SAN MARCOS, CA 920691431
County :	San Diego

Site Details

Status Date :	1986-09-22
Status :	Completed - Case Closed
Begin Date :	1986-08-22
Global ID :	T0607302793
Region :	REGION 9
Site History :	N/R
RB Case Number :	9UT493
Potential Media Affected :	Soil
Potential Contaminants of Concern :	Diesel
Local Agency :	SAN DIEGO COUNTY LOP
Local Case Number :	H02662-001
Lead Agency :	SAN DIEGO COUNTY LOP
File Location :	Local Agency
CUF Case :	NO
Caseworker :	KH
Case Type :	LUST Cleanup Site
How Discovered :	N/R
How Discovered Description :	N/R
Stop Method :	N/R
Stop Description :	N/R

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

LUST REG 9 - CA ***(cont.)***

Calwater Watershed Name :	Carlsbad - San Marcos - Richland (904.52)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)
Disadvantaged Community :	N/R
Latitude :	33.14446
Longitude :	-117.185846
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-11

Contacts Summary

Global ID :	T0607302793
Contact Name :	KEVIN HEATON
Contact Type :	Local Agency Caseworker
Organization Name :	SAN DIEGO COUNTY LOP
Address :	P.O. Box 129261
City :	San Diego
Phone Number :	N/R
Email :	kevin.heaton@sdcounty.ca.gov

Regulatory Activities

Date :	1986-08-26
Global ID :	T0607302793
Action Type :	Other
Action :	Leak Discovery

Date :	1986-08-26
Global ID :	T0607302793
Action Type :	Other
Action :	Leak Began

Date :	1986-08-22
Global ID :	T0607302793
Action Type :	Other
Action :	Leak Reported

Status History

Status Date :	1986-09-22
Global ID :	T0607302793
Status :	Completed - Case Closed

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

LUST REG 9 - CA ***(cont.)***

Status Date :	1986-08-22
Global ID :	T0607302793
Status :	Open - Case Begin Date

NPDES - CA

Facility Name :	Signet Armorlite Inc
Facility Address :	1001 Armorlite Dr, San Marcos, 92069
County :	San Diego
Effective Date :	1992-03-27
Adoption Date :	N/R
Expiration Date :	N/R
Termination Date :	2013-03-31
Order Number :	97-03-DWQ
NPDES Number :	CAS000001
WDID :	9 37I001658
RM Status :	Terminated
Reg Meas ID :	218190
Reg Meas Type :	Enrollee
Program :	Industrial
Facility Place ID :	N/R
Region Code :	9
Discharger ID :	0
Discharger :	Signet Armorlite Essilor Labs of America
Discharger Address :	PO Box 961389, El Paso, Texas 79996
Last Date in Agency List :	2016-01-05

PRP-CORP

Facility Name :	SIGNET ARMORLITE, INC.
Facility Address :	1001 ARMORLITE DRIVE, SAN MARCOS, CA 92069
Actual Date :	2013-02-02
Date Type :	SETTLEMENT DATE
EPA ID :	CAD020748125
Site Name :	CASMALIA RESOURCES
NPL Status Description :	Currently on the Final NPL
Non NPL Status Short Name :	N/R
Action Name :	ADM ORDR
Action Type Seq :	AC-14
Region Code :	09
Last Date in Agency List :	2022-03-08

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

PRP-CORP ***(cont.)***

Actual Date :	2017-03-31
Date Type :	SETTLEMENT DATE
EPA ID :	CAD042245001
Site Name :	OMEGA CHEMICAL CORPORATION
NPL Status Description :	Currently on the Final NPL
Non NPL Status Short Name :	N/R
Action Name :	C DECREE
Action Type Seq :	CD-10
Region Code :	09
Last Date in Agency List :	2022-03-08

Actual Date :	2010-10-07
Date Type :	SETTLEMENT DATE
EPA ID :	CAD042245001
Site Name :	OMEGA CHEMICAL CORPORATION
NPL Status Description :	Currently on the Final NPL
Non NPL Status Short Name :	N/R
Action Name :	C DECREE
Action Type Seq :	CD-6
Region Code :	09
Last Date in Agency List :	2022-03-08

Actual Date :	2009-11-09
Date Type :	SETTLEMENT DATE
EPA ID :	CAD042245001
Site Name :	OMEGA CHEMICAL CORPORATION
NPL Status Description :	Currently on the Final NPL
Non NPL Status Short Name :	N/R
Action Name :	ADM ORDR
Action Type Seq :	AC-3
Region Code :	09
Last Date in Agency List :	2022-03-08

Actual Date :	2001-02-28
Date Type :	SETTLEMENT DATE
EPA ID :	CAD042245001
Site Name :	OMEGA CHEMICAL CORPORATION
NPL Status Description :	Currently on the Final NPL
Non NPL Status Short Name :	N/R
Action Name :	C DECREE
Action Type Seq :	CD-2
Region Code :	09
Last Date in Agency List :	2022-03-08

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

PRP-CORP ***(cont.)***

Actual Date :	1995-05-09
Date Type :	SETTLEMENT DATE
EPA ID :	CAD042245001
Site Name :	OMEGA CHEMICAL CORPORATION
NPL Status Description :	Currently on the Final NPL
Non NPL Status Short Name :	N/R
Action Name :	UNL ORDR
Action Type Seq :	UA-1
Region Code :	09
Last Date in Agency List :	2022-03-08

RCRA_LQG

Facility Name :	SIGNET ARMORLITE, INC.
Facility Address :	1001 ARMORLITE DRIVE, SAN MARCOS, CA 92069
County :	SAN DIEGO
Date Form Received by Agency :	2012-02-29
EPA ID :	CAD008362634
Mailing Address :	1001 ARMORLITE DRIVE, SAN MARCOS, CA 92069
Contact :	JOHN T HINGEY
Contact Address :	1001 ARMORLITE DRIVE, SAN MARCOS, CA 92069
Contact Country :	US
Contact Telephone :	760-744-4000
Contact Email :	JHINGEY@SIGNETARMOLITE.COM
EPA Region :	09
Land Type :	Private
Source Type :	Annual/Biennial Report updated with Notification
Classification :	Large Quantity Generator

Description :

Handlers that generate 1,000 kg or more of hazardous waste during any calendar month; or generate more than 1 kg of acutely hazardous waste during any calendar month; or generate more than 100 kg of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month; or generate 1 kg or less of acutely hazardous waste during any calendar month, and accumulate more than 1 kg of acutely hazardous waste at any time; or generate 100 kg or less of any residue or contaminated soil, waste or other debris resulting from the cleanup of a spill, into or on any land or water, of acutely hazardous waste during any calendar month, and accumulated more than 100 kg of that material at any time.

Last Date in Agency List : 2022-01-25

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

RCRA_LQG ***(cont.)***

Owner/Operator Summary

Owner/Operator Name :	EDA HOLDINGS CO, INC.
Owner/Operator Address :	135555 N STEMMONS FREEWAY, DALLAS, TX 75234
Owner/Operator Country :	N/R
Owner/Operator Telephone :	760-744-4000
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Private
Owner/Operator Type :	Operator
Owner/Operator Start Date :	2010-04-01
Owner/Operator End Date :	N/R

Owner/Operator Name :	EDA HOLDINGS CO, INC.
Owner/Operator Address :	135555 N STEMMONS FREEWAY, DALLAS, TX 75234
Owner/Operator Country :	N/R
Owner/Operator Telephone :	760-744-4000
Owner/Operator Email :	N/R
Owner/Operator Fax :	N/R
Legal Status :	Private
Owner/Operator Type :	Owner
Owner/Operator Start Date :	2010-04-01
Owner/Operator End Date :	N/R

Handler Activities Summary

U.S. Importer of Hazardous Waste :	N
Mixed Waste (Haz. and Radioactive) :	N
Recycler of Hazardous Waste :	N
Transporter of Hazardous Waste :	N
Treater, Storer or Disposer of HW :	N
Underground Injection Activity :	N
On-site Burner Exemption :	N
Furnace Exemption :	N
Used Oil Fuel Burner :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Used Oil Transfer Facility :	N
Used Oil Transporter :	N

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

RCRA_LQG ***(cont.)***

Historical Generators

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Date Form Received by Agency :	2010-02-01
Facility Name :	SIGNET ARMORLITE, INC.
Classification :	Large Quantity Generator
Date Form Received by Agency :	2008-06-16
Facility Name :	SIGNET ARMORLITE, INC.
Classification :	Large Quantity Generator
Date Form Received by Agency :	2004-03-10
Facility Name :	SIGNET ARMORLITE, INC.
Classification :	Large Quantity Generator
Date Form Received by Agency :	2004-03-10
Facility Name :	SIGNET ARMORLITE, INC.
Classification :	Small Quantity Generator
Date Form Received by Agency :	2002-02-27
Facility Name :	SIGNET ARMORLITE INC.
Classification :	Large Quantity Generator
Date Form Received by Agency :	2000-10-12
Facility Name :	SIGNET ARMORLITE
Classification :	Large Quantity Generator
Date Form Received by Agency :	1999-03-04
Facility Name :	SIGNET ARMORLITE, INC.
Classification :	Large Quantity Generator
Date Form Received by Agency :	1996-09-01
Facility Name :	SIGNET ARMORLITE INC
Classification :	Large Quantity Generator

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

RCRA_LQG ***(cont.)***

Date Form Received by Agency : 1996-02-26
Facility Name : SIGNET ARMORLITE, INC.
Classification : Large Quantity Generator

Date Form Received by Agency : 1994-03-09
Facility Name : SIGNET ARMORLITE INC
Classification : Large Quantity Generator

Hazardous Waste Summary
Waste Code / Name :
122 - Alkaline solution without metals (pH > 12.5)
135 - Unspecified aqueous solution
181 - Other inorganic solid waste
212 - Oxygenated solvents (acetone, butanol, ethyl acetate, etc.)
331 - Off-specification, aged, or surplus organics
352 - Other organic solids
551 - Laboratory waste chemicals
791 - Liquids with pH < 2
D001 - IGNITABLE WASTE
D002 - CORROSIVE WASTE

Corrective Action Summary
Date / Status / CA Event Description:
2018-06-11 (Active) CA550RC - REMEDY CONSTRUCTION-REMEDY CONSTRUCTED
2018-06-11 (Active) CA750YE - RELEASE TO GW CONTROLLED DETERMINATION-YES, APPLICABLE AS OF THIS DATE
1997-12-15 (Active) CA725YE - HUMAN EXPOSURES CONTROLLED DETERMINATION-YES, APPLICABLE AS OF THIS DATE
1997-12-15 (Active) CA750NO - RELEASE TO GW CONTROLLED DETERMINATION-FACILITY DOES NOT MEET DEFINITION
1997-12-15 (Inactive) CA210 - REFERRED TO A NON-RCRA AUTHORITY
1996-01-01 (Active) CA600SR - STABILIZATION/INTERIM MEASURES DECISION-PRIMARY MEAS IS SOURCE REMOVL &/OR TRT
1996-01-01 (Active) CA600GW - STABILIZATION/INTERIM MEASURES DECISION-GROUNDWATER EXTRACTION & TREATMENT
1992-01-31 (Active) CA225NR - STABILIZATION MEASURES EVALUATION-FACILITY NOT AMENABLE TO STABILIZATION
1992-01-15 (Active) CA075LO - CA PRIORITIZATION-LOW CA PRIORITY
1991-08-08 (Active) CA075LO - CA PRIORITIZATION-LOW CA PRIORITY

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

RCRA_LQG ***(cont.)***

Notices of Violations Summary

Date of Violation :	2003-09-08
Date Achieved Compliance :	2005-10-27
Regulation Violated :	Y
Area of Violation :	Generators - General
Enforcement Action :	N/R
Enforcement Action Date :	N/R
Enf. Disposition Status :	N/R
Enf. Disp. Status Date :	N/R
Violation Lead Agency :	State
Enforcement Lead Agency :	N/R
Proposed Penalty Amount :	N/R
Final Penalty Amount :	N/R
Paid Penalty Amount :	N/R

Date of Violation :	1993-07-22
Date Achieved Compliance :	1998-07-22
Regulation Violated :	Y
Area of Violation :	Generators - General
Enforcement Action :	N/R
Enforcement Action Date :	N/R
Enf. Disposition Status :	N/R
Enf. Disp. Status Date :	N/R
Violation Lead Agency :	State
Enforcement Lead Agency :	N/R
Proposed Penalty Amount :	N/R
Final Penalty Amount :	N/R
Paid Penalty Amount :	N/R

Date of Violation :	1992-03-13
Date Achieved Compliance :	1992-09-10
Regulation Violated :	Y
Area of Violation :	TSD - General
Enforcement Action :	N/R
Enforcement Action Date :	N/R
Enf. Disposition Status :	N/R
Enf. Disp. Status Date :	N/R
Violation Lead Agency :	State
Enforcement Lead Agency :	N/R
Proposed Penalty Amount :	N/R
Final Penalty Amount :	N/R
Paid Penalty Amount :	N/R

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

RCRA_LQG ***(cont.)***

Date of Violation :	1992-03-13
Date Achieved Compliance :	1992-09-10
Regulation Violated :	Y
Area of Violation :	TSD - Closure/Post-Closure
Enforcement Action :	N/R
Enforcement Action Date :	N/R
Enf. Disposition Status :	N/R
Enf. Disp. Status Date :	N/R
Violation Lead Agency :	State
Enforcement Lead Agency :	N/R
Proposed Penalty Amount :	N/R
Final Penalty Amount :	N/R
Paid Penalty Amount :	N/R

Date of Violation :	1992-03-13
Date Achieved Compliance :	1992-09-10
Regulation Violated :	Y
Area of Violation :	Generators - General
Enforcement Action :	N/R
Enforcement Action Date :	N/R
Enf. Disposition Status :	N/R
Enf. Disp. Status Date :	N/R
Violation Lead Agency :	State
Enforcement Lead Agency :	N/R
Proposed Penalty Amount :	N/R
Final Penalty Amount :	N/R
Paid Penalty Amount :	N/R

Date of Violation :	1991-03-07
Date Achieved Compliance :	1992-03-13
Regulation Violated :	Y
Area of Violation :	Generators - General
Enforcement Action :	N/R
Enforcement Action Date :	N/R
Enf. Disposition Status :	N/R
Enf. Disp. Status Date :	N/R
Violation Lead Agency :	State
Enforcement Lead Agency :	N/R
Proposed Penalty Amount :	N/R
Final Penalty Amount :	N/R
Paid Penalty Amount :	N/R

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

RCRA_LQG ***(cont.)***

Date of Violation :	1990-01-17
Date Achieved Compliance :	1991-03-07
Regulation Violated :	Y
Area of Violation :	Generators - General
Enforcement Action :	N/R
Enforcement Action Date :	N/R
Enf. Disposition Status :	N/R
Enf. Disp. Status Date :	N/R
Violation Lead Agency :	State
Enforcement Lead Agency :	N/R
Proposed Penalty Amount :	N/R
Final Penalty Amount :	N/R
Paid Penalty Amount :	N/R

Date of Violation :	1988-01-26
Date Achieved Compliance :	1989-04-26
Regulation Violated :	Y
Area of Violation :	TSD - Financial Requirements
Enforcement Action :	INITIAL 3008(A) COMPLIANCE
Enforcement Action Date :	1989-02-01
Enf. Disposition Status :	N/R
Enf. Disp. Status Date :	N/R
Violation Lead Agency :	State
Enforcement Lead Agency :	State
Proposed Penalty Amount :	30000
Final Penalty Amount :	30000
Paid Penalty Amount :	N/R

Date of Violation :	1988-01-26
Date Achieved Compliance :	1989-04-26
Regulation Violated :	Y
Area of Violation :	TSD - Financial Requirements
Enforcement Action :	WRITTEN INFORMAL
Enforcement Action Date :	1988-02-24
Enf. Disposition Status :	N/R
Enf. Disp. Status Date :	N/R
Violation Lead Agency :	State
Enforcement Lead Agency :	State
Proposed Penalty Amount :	N/R
Final Penalty Amount :	N/R
Paid Penalty Amount :	N/R

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

RCRA_LQG ***(cont.)***

Date of Violation :	1988-01-21
Date Achieved Compliance :	1988-07-25
Regulation Violated :	Y
Area of Violation :	LDR - General
Enforcement Action :	WRITTEN INFORMAL
Enforcement Action Date :	1988-07-05
Enf. Disposition Status :	N/R
Enf. Disp. Status Date :	N/R
Violation Lead Agency :	State
Enforcement Lead Agency :	EPA
Proposed Penalty Amount :	N/R
Final Penalty Amount :	N/R
Paid Penalty Amount :	N/R

Evaluation Action Summary

Evaluation Date :	2006-10-27
Evaluation :	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of Violation :	N/R
Date Achieved Compliance :	N/R
Evaluation Lead Agency :	Local

Evaluation Date :	2005-10-27
Evaluation :	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of Violation :	N/R
Date Achieved Compliance :	N/R
Evaluation Lead Agency :	Local

Evaluation Date :	2003-09-08
Evaluation :	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of Violation :	Generators - General
Date Achieved Compliance :	2005-10-27
Evaluation Lead Agency :	State Contractor/Grantee

Evaluation Date :	1993-07-22
Evaluation :	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of Violation :	Generators - General
Date Achieved Compliance :	1998-07-22
Evaluation Lead Agency :	State Contractor/Grantee

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

RCRA_LQG ***(cont.)***

Evaluation Date :	1992-04-21
Evaluation :	FINANCIAL RECORD REVIEW
Area of Violation :	N/R
Date Achieved Compliance :	N/R
Evaluation Lead Agency :	State

Evaluation Date :	1992-03-13
Evaluation :	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of Violation :	TSD - General
Date Achieved Compliance :	1992-09-10
Evaluation Lead Agency :	State

Evaluation Date :	1992-03-13
Evaluation :	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of Violation :	TSD - Closure/Post-Closure
Date Achieved Compliance :	1992-09-10
Evaluation Lead Agency :	State

Evaluation Date :	1992-03-13
Evaluation :	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of Violation :	Generators - General
Date Achieved Compliance :	1992-09-10
Evaluation Lead Agency :	State

Evaluation Date :	1991-03-07
Evaluation :	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of Violation :	Generators - General
Date Achieved Compliance :	1992-03-13
Evaluation Lead Agency :	State Contractor/Grantee

Evaluation Date :	1990-01-17
Evaluation :	COMPLIANCE EVALUATION INSPECTION ON-SITE
Area of Violation :	Generators - General
Date Achieved Compliance :	1991-03-07
Evaluation Lead Agency :	State Contractor/Grantee

RCRA_TSDF

Facility Name :	SIGNET ARMORLITE, INC.
Facility Address :	1001 ARMORLITE DRIVE, SAN MARCOS, CA 92069
County :	SAN DIEGO

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

RCRA_TSDF ***(cont.)***

Site Details

EPA Handler ID :	CAD008362634
Receive Date :	2012-02-29
Handler Date of Last Change :	2012-11-06
Activity Location :	CA
Mailing Address :	1001 ARMORLITE DRIVE, SAN MARCOS, CA 92069
Mailing Country :	US
Contact Name :	JOHN T HINGEY
Contact Title :	V.P. OF MANUFACTURING
Contact Email Address :	JHINGEY@SIGNETARMOLITE.COM
Contact Address :	1001 ARMORLITE DRIVE, SAN MARCOS, CA 92069
Contact Telephone Number and Extension:	760-744-4000
Contact Facsimile Number :	760-471-6255
Region :	09
Land Type :	Private
Source Type :	Annual/Biennial Report updated with Notification
Sequence Number :	2
Non-Notifier :	N/R
Biennial Report Cycle :	2011
Federal Facility Indicator :	Not a Federal Facility
Accessibility :	N/R
NAICS Codes :	326199
Active Site Indicator :	Handler Activities, Corrective Action Activities
Last Date in Agency List :	2022-01-25

Owner/Operator Summary

Owner Name :	EDA HOLDINGS CO, INC.
Owner Type :	Private
Owner/Operator Sequence Number :	1
Operator Name :	EDA HOLDINGS CO, INC.
Operator Type :	Private

Handler Activities Summary

Commercial TSD Indicator :	N
Operating TSDF Universe :	No
Treatment, Storage, and Disposal Type:	Storage, Treatment
Full Enforcement Universe :	No
Permit Renewals Workload Universe :	No
Permit Workload Universe :	No
Permit Progress Universe :	Storage, Treatment
Post-Closure Workload Universe :	No

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

RCRA_TSDF ***(cont.)***

Closure Workload Universe :	No
TSDFs Potentially Subject to Corrective Action Under 3004 (u)/(v) Universe:	N
TSDFs Only Subject to Corrective Action Under Discretionary Authorities Universe:	Y
Active Site Federally-Regulated Treatment, Storage, and Disposal Facility:	No
Active Site Converter Treatment, Storage, and Disposal Facility:	No
Active Site State-Regulated Treatment, Storage, and Disposal Facility:	No
In a Handler Universe :	Y
In a Universe :	Y
Federal Generator Status Universe :	Large Quantity Generator
Short-Term Generator Activity :	N
Importer Activity :	N
Mixed Waste Generator :	N
Federal Waste Generator Code Owner :	HQ
Federal Waste Generator Code :	1
Federal Waste Generator Description :	Large Quantity Generator
State Waste Generator Code Owner :	CA
State Waste Generator Code :	1
Transporter Activity :	N
Transfer Facility Activity :	N
Recycler Activity with Storage :	N
Small Quantity On-site Burner Exemption:	N
Smelting, Melting, and Refining Furnace Exemption:	N
Underground Injection Control :	N
Off-site Waste Receipt :	N
Universal Waste Indicator :	N
Universal Waste Destination Facility:	N
Federal Universal Waste :	N
Used Oil Transporter :	N
Used Oil Transfer Facility :	N
Used Oil Processor :	N
Used Oil Refiner :	N
Used Oil Fuel Burner :	N
Used Oil Fuel Marketer to Burner :	N
Used Oil Specification Marketer :	N
Active Site State-Regulated Handler :	---
Corrective Action Workload Universe :	Y
Subject to Corrective Action Universe:	Y

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

RCRA_TSDF ***(cont.)***

Non-TSDFs Where RCRA Corrective Action Has Been Imposed Universe:	N
Corrective Action Priority Ranking :	No NCAPS ranking
Environmental Control Indicator :	N
Institutional Control Indicator :	N
Human Exposure Controls Indicator :	Yes
Groundwater Controls Indicator :	Yes
Significant Non-Complier Universe :	N
Unaddressed Significant Non-Complier Universe:	N
Addressed Significant Non-Complier Universe:	N
Significant Non-Complier With a Compliance Schedule Universe:	N
Financial Assurance Required :	-----
Public Notes :	N/R
Recognized Trader - Importer :	N
Recognized Trader - Exporter :	N
Importer of Spent Lead Acid Batteries:	N
Exporter of Spent Lead Acid Batteries:	N
Recycler Activity without Storage :	N/R
Manifest Broker :	N/R
Subpart P :	N

SLIC REG 9 - CA

Facility Name :	Milano Holdings Inc. (Former SIGNET ARMORLITE, INC.)
Facility Address :	1001 ARMORLITE DRIVE, SAN MARCOS, CA 92069
County :	San Diego

Site Details

Status Date :	2014-01-31
Status :	Completed - Case Closed
Begin Date :	1986-08-22
Global ID :	SL209154190
Region :	REGION 9

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

SLIC REG 9 - CA ***(cont.)***

Site History :

The Facility is approximately 11.8 acres in size and contains buildings associated with the manufacture, marketing, and distribution of optical lenses. Site assessment activities have been conducted at the Facility since the early 1990s. Investigations revealed the presence of VOCs, including methylene chloride, in soil and groundwater at the Facility. Signet has undertaken four remedial actions at the Facility, as well as subsequent investigation activities to assess the adequacy of the remedial actions. Active remediation has included operation of a multiphase extraction system (MPE system) from 1995 to 1998 to remove subsurface VOCs from source areas at the Facility. Additionally, three targeted source removal actions have been conducted at the Facility since 1986. Remedial activities have included removal and disposal of contaminated soil and addition of soil amendments to facilitate in-situ degradation. In late 2009, an interim remedial measure to extract VOCs from deep groundwater was evaluated, and the findings of this evaluation are incorporated into the CAP.

RB Case Number :	2091500
Potential Media Affected :	Aquifer used for drinking water supply
Potential Contaminants of Concern :	1,1,1-Trichloroethane (TCA), Acetone, Benzene, Other Chlorinated Hydrocarbons, Tetrachloroethylene (PCE), Trichloroethylene (TCE), Freon, Diesel, Gasoline
Local Agency :	N/R
Local Case Number :	H02662-001
Lead Agency :	SAN DIEGO RWQCB (REGION 9)
File Location :	Regional Board
CUF Case :	NO
Caseworker :	N/R
Case Type :	Cleanup Program Site
How Discovered :	Visual
How Discovered Description :	N/R
Stop Method :	Close and Remove Tank
Stop Description :	N/R
Calwater Watershed Name :	Carlsbad - San Marcos - Richland (904.52)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)
Disadvantaged Community :	Severely Disadvantaged Community
Latitude :	33.144127
Longitude :	-117.185867
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-11

Contacts Summary

Global ID :	SL209154190
Contact Name :	N/R
Contact Type :	N/R
Organization Name :	N/R

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

SLIC REG 9 - CA ***(cont.)***

Address :	N/R
City :	N/R
Phone Number :	N/R
Email :	N/R

Regulatory Activities

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

Date :	2018-06-11
Global ID :	SL209154190
Action Type :	ENFORCEMENT
Action :	Closure Summary

Date :	2014-06-30
Global ID :	SL209154190
Action Type :	ENFORCEMENT
Action :	Deed Restriction / Land Use Restriction / Covenant - #2014-0270414

Date :	2014-01-31
Global ID :	SL209154190
Action Type :	ENFORCEMENT
Action :	Closure/No Further Action Letter

Date :	2013-07-27
Global ID :	SL209154190
Action Type :	ENFORCEMENT
Action :	Annual Estimation Letter

Date :	2012-07-31
Global ID :	SL209154190
Action Type :	ENFORCEMENT
Action :	Cost Recovery Agreement / N. of Reimbursement

Date :	2012-04-02
Global ID :	SL209154190
Action Type :	ENFORCEMENT

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

SLIC REG 9 - CA ***(cont.)***

Action : Technical Correspondence / Assistance / Other

Date : 2012-02-03
Global ID : SL209154190
Action Type : RESPONSE
Action : Correspondence

Date : 2011-12-01
Global ID : SL209154190
Action Type : ENFORCEMENT
Action : Technical Correspondence / Assistance / Other

Date : 2011-03-03
Global ID : SL209154190
Action Type : ENFORCEMENT
Action : Technical Correspondence / Assistance / Other

Date : 2011-03-01
Global ID : SL209154190
Action Type : RESPONSE
Action : Monitoring Report - Annually - Regulator Responded

Status History

Status Date : 2014-01-31
Global ID : SL209154190
Status : Completed - Case Closed

Status Date : 2013-08-07
Global ID : SL209154190
Status : Open - Eligible for Closure

Status Date : 2006-03-30
Global ID : SL209154190
Status : Open - Site Assessment

Status Date : 2003-05-22
Global ID : SL209154190

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

SLIC REG 9 - CA ***(cont.)***

Status : Open - Remediation

Status Date : 2003-03-01
Global ID : SL209154190
Status : Open - Remediation

Status Date : 1986-08-22
Global ID : SL209154190
Status : Open - Case Begin Date

Facility Name : Proposed Davia Village
Facility Address : 1001 Armorlite Drive, San Marcos, CA 92069
County : San Diego

Site Details

Status Date : 2016-05-03
Status : Completed - Case Closed
Begin Date : 1986-08-01
Global ID : T10000003706
Region : REGION 9

Site History : This case is for a planned redevleopment of the former Signet Armorlite Site. For historical information regarding the site please review the Geotracker file for Milano Holdings, Inc. (former Signet Armorlite), Geotracker ID SL209154190.

RB Case Number : 4090003
Potential Media Affected : Indoor Air, Other Groundwater (uses other than drinking water), Soil

Potential Contaminants of Concern : 1,1,1-Trichloroethane (TCA), Acetone, Other Chlorinated Hydrocarbons, Tetrachloroethylene (PCE), Trichloroethylene (TCE), Freon, Benzene, Diesel, Gasoline

Local Agency : N/R
Local Case Number : N/R
Lead Agency : SAN DIEGO RWQCB (REGION 9)
File Location : All Files are on GeoTracker or in the Local Agency Database
CUF Case : NO
Caseworker : SAM
Case Type : Cleanup Program Site
How Discovered : N/R

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

SLIC REG 9 - CA ***(cont.)***

How Discovered Description :	N/R
Stop Method :	N/R
Stop Description :	N/R
Calwater Watershed Name :	Carlsbad - San Marcos - Richland (904.52)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)
Disadvantaged Community :	Severely Disadvantaged Community
Latitude :	33.144343
Longitude :	-117.186356
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-11

Contacts Summary

Global ID :	T10000003706
Contact Name :	SARAH A. MEARON
Contact Type :	Regional Board Caseworker
Organization Name :	SAN DIEGO RWQCB (REGION 9)
Address :	2375 NORTHSIDE DRIVE, SUITE 100
City :	SAN DIEGO
Phone Number :	6195213363
Email :	sarah.mearon@waterboards.ca.gov

Regulatory Activities

Date :	2017-09-05
Global ID :	T10000003706
Action Type :	RESPONSE
Action :	Other Report / Document
Date :	2017-06-26
Global ID :	T10000003706
Action Type :	ENFORCEMENT
Action :	Annual Estimation Letter
Date :	2016-06-17
Global ID :	T10000003706
Action Type :	ENFORCEMENT
Action :	Annual Estimation Letter
Date :	2016-02-12
Global ID :	T10000003706

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

SLIC REG 9 - CA ***(cont.)***

Action Type : ENFORCEMENT
Action : Deed Restriction / LUC Monitoring Report

Date : 2015-06-22
Global ID : T10000003706
Action Type : ENFORCEMENT
Action : Annual Estimation Letter

Date : 2015-06-11
Global ID : T10000003706
Action Type : RESPONSE
Action : Technical Memos - Regulator Responded

Date : 2015-04-21
Global ID : T10000003706
Action Type : RESPONSE
Action : Technical Memos - Regulator Responded

Date : 2014-06-30
Global ID : T10000003706
Action Type : ENFORCEMENT
Action : Deed Restriction / Land Use Restriction / Covenant - #2014-0270414

Date : 2014-06-30
Global ID : T10000003706
Action Type : ENFORCEMENT
Action : Annual Estimation Letter

Date : 2014-01-31
Global ID : T10000003706
Action Type : ENFORCEMENT
Action : Closure/No Further Action Letter

Status History
Status Date : 2016-05-03
Global ID : T10000003706
Status : Completed - Case Closed

Map Id: 117
Direction: ESE
Distance: 0.746 mi., 3940 ft.
Elevation: 556 ft.
Relative: Lower

Site Name : SIGNET ARMORLITE INC | ARMORLITE INC | PROPOSED DAVIA VILLAGE
1001 ARMORLITE DR
SAN MARCOS | San Marcos, CA

Database(s) : [AFS, BRS, CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, CIWQS - CA, CIWQS 2 - CA, CORRACTS, CORRECTIVE ACTIONS_2020, DEED - CA, DOCKET, ECHO, ENVIROSTOR - CA, EPA LUST, FRS, HAZMAT_SAN DIEGO COUNTY - CA, HAZNET - CA, HIST AFS 2, HWG - CA, HWP - CA, LUST REG 9 - CA, NPDES - CA, PRP-CORP, RCRA_LQG, RCRA_TSDF, SLIC REG 9 - CA] ***(cont.)***

Envirosite ID: 256168
EPA ID: N/R

SLIC REG 9 - CA ***(cont.)***

Status Date :	2015-04-15
Global ID :	T10000003706
Status :	Open - Reopen Case
Status Date :	2015-04-15
Global ID :	T10000003706
Status :	Open - Eligible for Closure
Status Date :	2015-04-15
Global ID :	T10000003706
Status :	Open - Inactive
Status Date :	2014-01-31
Global ID :	T10000003706
Status :	Completed - Case Closed
Status Date :	2013-10-15
Global ID :	T10000003706
Status :	Open - Eligible for Closure
Status Date :	2012-05-11
Global ID :	T10000003706
Status :	Open - Assessment & Interim Remedial Action
Status Date :	1986-08-01
Global ID :	T10000003706
Status :	Open - Case Begin Date

Map Id: 118
Direction: SSW
Distance: 0.796 mi., 4201 ft.
Elevation: 549 ft.
Relative: Lower

Site Name : NAPP SYSTEMS * | NAPP SYSTEMS, INC. | MACDERMID PRINTING SOLUTIONS 360 PACIFIC ST S | 360 S. PACIFIC STREET | 360 SOUTH PACIFIC STREET SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ENVIROSTOR - CA, EPA LUST, FRS, LUST REG 9 - CA, PRP-CORP]

Envirosite ID: 44661476
EPA ID: N/R

CALEPA SITES - CA

Facility Name :	NAPP SYSTEMS *
Facility Address :	360 PACIFIC ST S, SAN MARCOS, 92069
Site ID :	240786
EI ID :	T0607302457
EI Description :	Leaking Underground Storage Tank Cleanup Site
Latitude :	33.139844
Longitude :	-117.198367
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07

CASE LIST_SAN DIEGO COUNTY - CA

Facility Name :	NAPP SYSTEMS *
Facility Address :	360 PACIFIC ST S, SAN MARCOS, CA 92069
County :	San Diego

Site Details

Status Date :	1996-02-29
Status :	Completed - Case Closed
Begin Date :	1985-01-18
Global ID :	T0607302457
Site History :	N/R
RB Case Number :	9UT369
Potential Media Affected :	Aquifer used for drinking water supply
Potential Contaminants of Concern :	* Solvents
Local Agency :	N/R
Local Case Number :	H06217-001
Lead Agency :	SAN DIEGO RWQCB (REGION 9)
File Location :	N/R
CUF Case :	NO
Caseworker :	VRR
Case Type :	LUST Cleanup Site
How Discovered :	Other Means
How Discovered Description :	N/R
Stop Method :	N/R
Stop Description :	N/R
Calwater Watershed Name :	Carlsbad - San Marcos - Richland (904.52)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)
Disadvantaged Community :	N/R
Latitude :	33.139844
Longitude :	-117.198368
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-09

Map Id: 118
Direction: SSW
Distance: 0.796 mi., 4201 ft.
Elevation: 549 ft.
Relative: Lower

Site Name : NAPP SYSTEMS * | NAPP SYSTEMS, INC. | MACDERMID PRINTING SOLUTIONS 360 PACIFIC ST S | 360 S. PACIFIC STREET | 360 SOUTH PACIFIC STREET SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ENVIROSTOR - CA, EPA LUST, FRS, LUST REG 9 - CA, PRP-CORP] ***(cont.)***

Envirosite ID: 44661476
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Contacts Summary

Global ID :	T0607302457
Contact Name :	VICENTE R. RODRIGUEZ
Contact Type :	Regional Board Caseworker
Organization Name :	SAN DIEGO RWQCB (REGION 9)
Address :	2375 NORTHSIDE DRIVE, SUITE 100
City :	SAN DIEGO
Phone Number :	6195213966
Email :	vicente.rodriguez@waterboards.ca.gov

Regulatory Activities

Date :	1985-07-19
Global ID :	T0607302457
Action Type :	ENFORCEMENT
Action :	* Historical Enforcement
Date :	1985-01-22
Global ID :	T0607302457
Action Type :	Other
Action :	Leak Discovery
Date :	1985-01-22
Global ID :	T0607302457
Action Type :	Other
Action :	Leak Reported
Date :	1985-01-18
Global ID :	T0607302457
Action Type :	Other
Action :	Leak Stopped

Status History

Status Date :	1996-02-29
Global ID :	T0607302457
Status :	Completed - Case Closed
Status Date :	1987-11-16
Global ID :	T0607302457
Status :	Open - Remediation
Status Date :	1985-01-18
Global ID :	T0607302457

Map Id: 118
Direction: SSW
Distance: 0.796 mi., 4201 ft.
Elevation: 549 ft.
Relative: Lower

Site Name : NAPP SYSTEMS * | NAPP SYSTEMS, INC. | MACDERMID PRINTING SOLUTIONS 360 PACIFIC ST S | 360 S. PACIFIC STREET | 360 SOUTH PACIFIC STREET SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ENVIROSTOR - CA, EPA LUST, FRS, LUST REG 9 - CA, PRP-CORP] ***(cont.)***

Envirosite ID: 44661476
EPA ID: N/R

CASE LIST_SAN DIEGO COUNTY - CA ***(cont.)***

Status :	Open - Case Begin Date

ENVIROSTOR - CA

Facility Name :	Napp Systems, Inc.
Facility Address :	360 S. Pacific Street, San Marcos, CA 92069
County :	SAN DIEGO

Site Details

Cleanup Date :	N/R
Cleanup Status :	Inactive - Needs Evaluation
Site Type :	Tiered Permit
Site Type Detailed :	Tiered Permit
Acreage :	N/R
APN :	NONE SPECIFIED
National Priorities List :	NO
Regulatory Agencies Involved :	N/R
Lead Agency :	N/R
Project Manager :	N/R
Supervisor :	N/R
Office :	Cleanup Cypress
Envirostor ID :	71002510
Site Code :	N/R
Assembly :	75
Senate :	38
Congressional District :	50
Special Program :	N/R
Past Uses :	NONE SPECIFIED
Potential COC :	N/R
Confirmed COC :	N/R
Potential Media Affected :	N/R
Restricted Use :	NO
Site Management Req :	N/R
Funding :	N/R
Latitude :	33.139844
Longitude :	-117.198368
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-14

Alias Details

Alias :	71002510
Alias Type :	Envirostor ID Number
Alias :	CAD063237341
Alias Type :	EPA Identification Number

Map Id: 118
Direction: SSW
Distance: 0.796 mi., 4201 ft.
Elevation: 549 ft.
Relative: Lower

Site Name : NAPP SYSTEMS * | NAPP SYSTEMS, INC. | MACDERMID PRINTING SOLUTIONS 360 PACIFIC ST S | 360 S. PACIFIC STREET | 360 SOUTH PACIFIC STREET SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ENVIROSTOR - CA, EPA LUST, FRS, LUST REG 9 - CA, PRP-CORP] ***(cont.)***

Envirosite ID: 44661476
EPA ID: N/R

ENVIROSTOR - CA ***(cont.)***

Completed Activities

Completed Date :	N/R
Area Name :	N/R
Sub Area Name :	N/R
Document Type :	N/R
Comments :	N/R

Future Activities

Area Name :	N/R
Sub Area Name :	N/R
Document Type :	N/R
Due Date :	N/R

Scheduled Activites

Due Date :	N/R
Revised Date :	N/R
Area Name :	N/R
Sub Area Name :	N/R
Document Type :	N/R

EPA LUST

Facility Name :	NAPP SYSTEMS *
Facility Address :	360 PACIFIC ST S, SAN MARCOS, California 92069
County :	N/R
Facility ID :	N/R
LUST ID :	CAT0607302457
Reported Date :	N/R
Status :	No Further Action
Substance :	N/R
Closed With Residual Contamination (Tribal Only):	N/R
NFA_Letter (Tribal Only) :	N/R
Tribe (Tribal Only) :	N/R
EPA Region :	9
Estimated Population within 1500ft :	277
Estimated Private Domestic Wells within 1500ft:	0
Within Source Water Protection Area (SPA):	No
SPA Public Water System and Facility ID:	N/R
SPA Water Type :	N/R
SPA Facility Type :	N/R
SPA HUC12 :	N/R

Map Id: 118
Direction: SSW
Distance: 0.796 mi., 4201 ft.
Elevation: 549 ft.
Relative: Lower

Site Name : NAPP SYSTEMS * | NAPP SYSTEMS, INC. | MACDERMID PRINTING SOLUTIONS 360 PACIFIC ST S | 360 S. PACIFIC STREET | 360 SOUTH PACIFIC STREET SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ENVIROSTOR - CA, EPA LUST, FRS, LUST REG 9 - CA, PRP-CORP] ***(cont.)***

Envirosite ID: 44661476
EPA ID: N/R

EPA LUST ***(cont.)***

Within Groundwater Wellhead Protection Area (WHPA):	No
WHPA Public Water System and Facility ID:	N/R
WHPA Water Type :	N/R
WHPA Facility Type :	N/R
WHPA HUC12 :	N/R
Within Estimated 100-year Floodplain:	No
Latitude :	33.139859999999899
Longitude :	-117.198380000000000
Last Date in Agency List :	2022-01-04

FRS

Facility Name :	MACDERMID PRINTING SOLUTIONS
Facility Address :	360 SOUTH PACIFIC STREET, SAN MARCOS, CA 92078
County :	SAN DIEGO

Site Details

Registry ID :	110002413567
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2015-01-20

Source Description

Source Description :

HWTS-DATAMART provides California with information on hazardous waste shipments for generators, transporters, and treatment, storage, and disposal facilities.
The NPDES module of the Compliance Information System (ICIS) tracks surface water permits issued under the Clean Water Act. Under NPDES, all facilities that discharge pollutants from any point source into waters of the United States are required to obtain a permit. The permit will likely contain limits on what can be discharged, impose monitoring and reporting requirements, and include other provisions to ensure that the discharge does not adversely affect water quality.
TRIS is a publicly available EPA database reported annually by certain covered industry groups, as well as federal facilities. It contains information about more than 650 toxic chemicals that are being used, manufactured, treated, transported, or released into the environment, and includes information about waste management and pollution prevention activities.

FRS Environmental Interest

Source and System ID :

HWTS-DATAMART - CAD063237341
ICIS - CAP000087
TRI REPORTING FORM - 92069NPPSY360SO

Map Id: 118
Direction: SSW
Distance: 0.796 mi., 4201 ft.
Elevation: 549 ft.
Relative: Lower

Site Name : NAPP SYSTEMS * | NAPP SYSTEMS, INC. | MACDERMID PRINTING SOLUTIONS 360 PACIFIC ST S | 360 S. PACIFIC STREET | 360 SOUTH PACIFIC STREET SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ENVIROSTOR - CA, EPA LUST, FRS, LUST REG 9 - CA, PRP-CORP] ***(cont.)***

Envirosite ID: 44661476
EPA ID: N/R

FRS ***(cont.)***

Facility Name : NAPP SYSTEMS, INC.
Facility Address : 360 S. PACIFIC STREET, SAN MARCOS, CA 92069
County : SAN DIEGO

Site Details
Registry ID : 110060806631
FRS Facility URL : Click here for hyperlink provided by the agency.
Last Date in Agency List : 2022-02-17

Source Description

Source Description :

The California Environmental Protection Agency (CalEPA) has recently implemented a new data warehouse system (nSite). This data warehouse combines and merges facility and site information from five different systems managed within CalEPA. The five systems are: California Environmental Reporting System (CERS), EnviroStor, GeoTracker, California Integrated Water Quality System (CIWQS), and Toxic Release Inventory (TRI).

FRS Environmental Interest
Source and System ID : CA-ENVIROVIEW - 240786

LUST REG 9 - CA

Facility Name : NAPP SYSTEMS *
Facility Address : 360 PACIFIC ST S, SAN MARCOS, CA 92069
County : San Diego

Site Details
Status Date : 1996-02-29
Status : Completed - Case Closed
Begin Date : 1985-01-18
Global ID : T0607302457
Region : REGION 9
Site History : N/R
RB Case Number : 9UT369
Potential Media Affected : Aquifer used for drinking water supply
Potential Contaminants of Concern : * Solvents
Local Agency : N/R
Local Case Number : H06217-001
Lead Agency : SAN DIEGO RWQCB (REGION 9)
File Location : N/R
CUF Case : NO
Caseworker : VRR

Map Id: 118
Direction: SSW
Distance: 0.796 mi., 4201 ft.
Elevation: 549 ft.
Relative: Lower

Site Name : NAPP SYSTEMS * | NAPP SYSTEMS, INC. | MACDERMID PRINTING SOLUTIONS 360 PACIFIC ST S | 360 S. PACIFIC STREET | 360 SOUTH PACIFIC STREET SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ENVIROSTOR - CA, EPA LUST, FRS, LUST REG 9 - CA, PRP-CORP] ***(cont.)***

Envirosite ID: 44661476
EPA ID: N/R

LUST REG 9 - CA ***(cont.)***

Case Type :	LUST Cleanup Site
How Discovered :	Other Means
How Discovered Description :	N/R
Stop Method :	N/R
Stop Description :	N/R
Calwater Watershed Name :	Carlsbad - San Marcos - Richland (904.52)
DWR Groundwater Subbasin Name :	San Marcos Area (9-032)
Disadvantaged Community :	N/R
Latitude :	33.139844
Longitude :	-117.198368
Agency URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-11

Contacts Summary

Global ID :	T0607302457
Contact Name :	VICENTE R. RODRIGUEZ
Contact Type :	Regional Board Caseworker
Organization Name :	SAN DIEGO RWQCB (REGION 9)
Address :	2375 NORTHSIDE DRIVE, SUITE 100
City :	SAN DIEGO
Phone Number :	6195213966
Email :	vicente.rodriguez@waterboards.ca.gov

Regulatory Activities

Date :	1985-07-19
Global ID :	T0607302457
Action Type :	ENFORCEMENT
Action :	* Historical Enforcement

Date :	1985-01-22
Global ID :	T0607302457
Action Type :	Other
Action :	Leak Discovery

Date :	1985-01-22
Global ID :	T0607302457
Action Type :	Other
Action :	Leak Reported

Date :	1985-01-18
Global ID :	T0607302457
Action Type :	Other
Action :	Leak Stopped

Map Id: 118
Direction: SSW
Distance: 0.796 mi., 4201 ft.
Elevation: 549 ft.
Relative: Lower

Site Name : NAPP SYSTEMS * | NAPP SYSTEMS, INC. | MACDERMID PRINTING SOLUTIONS 360 PACIFIC ST S | 360 S. PACIFIC STREET | 360 SOUTH PACIFIC STREET SAN MARCOS | San Marcos, CA

Database(s) : [CALEPA SITES - CA, CASE LIST_SAN DIEGO COUNTY - CA, ENVIROSTOR - CA, EPA LUST, FRS, LUST REG 9 - CA, PRP-CORP] ***(cont.)***

Envirosite ID: 44661476
EPA ID: N/R

LUST REG 9 - CA ***(cont.)***

Status History

Status Date :	1996-02-29
Global ID :	T0607302457
Status :	Completed - Case Closed
Status Date :	1987-11-16
Global ID :	T0607302457
Status :	Open - Remediation
Status Date :	1985-01-18
Global ID :	T0607302457
Status :	Open - Case Begin Date

PRP-CORP

Facility Name :	NAPP SYSTEMS
Facility Address :	360 S. PACIFIC ST., SAN MARCOS, CA 92069
Actual Date :	1985-10-09
Date Type :	SETTLEMENT DATE
EPA ID :	OHD074727793
Site Name :	CHEM-DYNE
NPL Status Description :	Currently on the Final NPL
Non NPL Status Short Name :	N/R
Action Name :	C DECREE
Action Type Seq :	CD-1
Region Code :	05
Last Date in Agency List :	2022-03-08
Actual Date :	1982-03-26
Date Type :	GENERAL NOTICE
EPA ID :	OHD074727793
Site Name :	CHEM-DYNE
NPL Status Description :	Currently on the Final NPL
Non NPL Status Short Name :	N/R
Action Name :	Not Ltrs
Action Type Seq :	NJ-1
Region Code :	05
Last Date in Agency List :	2022-03-08

Map Id: 119
Direction: NW
Distance: 0.845 mi., 4461 ft.
Elevation: N/R
Relative: N/R

Site Name : N/R
33.190584, -117.21929
CA
Database(s) : [HIGH FIRE - CA]

Envirosite ID: 24267082
EPA ID: N/R

HIGH FIRE - CA

State Responsibility Areas :	Yes
Haz Code :	1
Haz Class :	Moderate

Map Id: 120
Direction: NNW
Distance: 0.963 mi., 5086 ft.
Elevation: N/R
Relative: N/R

Site Name : N/R
33.202447, -117.208458
CA
Database(s) : [HIGH FIRE - CA]

Envirosite ID: 24267096
EPA ID: N/R

HIGH FIRE - CA

State Responsibility Areas :	Yes
Haz Code :	2
Haz Class :	High

Map Id: 121
Direction: SE
Distance: 0.964 mi., 5088 ft.
Elevation: 544 ft.
Relative: Lower

Site Name : HUES METAL FINISHING INC | RMP METAL FINISHING
977 LINDA VISTA DR
SAN MARCOS | San Marcos, CA 92069
Database(s) : [CALEPA SITES - CA, ENVIROSTOR - CA, FRS, HAZNET - CA, HWG - CA]

Envirosite ID: 270931
EPA ID: N/R

CALEPA SITES - CA

Facility Name :	RMP METAL FINISHING
Facility Address :	977 LINDA VISTA DR, SAN MARCOS, 92069
Site ID :	400796
EI ID :	10375831
EI Description :	Chemical Storage Facilities
Latitude :	33.138980
Longitude :	-117.185650
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-07
Site ID :	400796
EI ID :	10375831
EI Description :	Hazardous Waste Generator
Latitude :	33.138980
Longitude :	-117.185650
Agency Hyperlink :	Click here for hyperlink provided by the agency.

Map Id: 121
Direction: SE
Distance: 0.964 mi., 5088 ft.
Elevation: 544 ft.
Relative: Lower

Site Name : HUES METAL FINISHING INC | RMP METAL FINISHING
977 LINDA VISTA DR
SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, ENVIROSTOR - CA, FRS, HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 270931
EPA ID: N/R

CALEPA SITES - CA ***(cont.)***

Last Date in Agency List :	2022-01-07

ENVIROSTOR - CA

Facility Name :	Hues Metal Finishing, Inc.
Facility Address :	977 Linda Vista Drive, San Marcos, CA 92069
County :	SAN DIEGO

Site Details

Cleanup Date :	N/R
Cleanup Status :	Inactive - Needs Evaluation
Site Type :	Tiered Permit
Site Type Detailed :	Tiered Permit
Acreage :	N/R
APN :	NONE SPECIFIED
National Priorities List :	NO
Regulatory Agencies Involved :	N/R
Lead Agency :	N/R
Project Manager :	N/R
Supervisor :	N/R
Office :	Cleanup Cypress
Envirostor ID :	71002362
Site Code :	N/R
Assembly :	75
Senate :	38
Congressional District :	50
Special Program :	N/R
Past Uses :	NONE SPECIFIED
Potential COC :	N/R
Confirmed COC :	N/R
Potential Media Affected :	N/R
Restricted Use :	NO
Site Management Req :	N/R
Funding :	N/R
Latitude :	33.13898
Longitude :	-117.185657
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-01-14

Alias Details

Alias :	71002362
Alias Type :	Envirostor ID Number
Alias :	CAD039769583
Alias Type :	EPA Identification Number

Map Id: 121
Direction: SE
Distance: 0.964 mi., 5088 ft.
Elevation: 544 ft.
Relative: Lower

Site Name : HUES METAL FINISHING INC | RMP METAL FINISHING
977 LINDA VISTA DR
SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, ENVIROSTOR - CA, FRS, HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 270931
EPA ID: N/R

ENVIROSTOR - CA ***(cont.)***

Completed Activities

Completed Date :	N/R
Area Name :	N/R
Sub Area Name :	N/R
Document Type :	N/R
Comments :	N/R

Future Activities

Area Name :	N/R
Sub Area Name :	N/R
Document Type :	N/R
Due Date :	N/R

Scheduled Activites

Due Date :	N/R
Revised Date :	N/R
Area Name :	N/R
Sub Area Name :	N/R
Document Type :	N/R

FRS

Facility Name :	RMP METAL FINISHING
Facility Address :	977 LINDA VISTA DR, SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Registry ID :	110066540639
FRS Facility URL :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2022-02-17

Source Description

Source Description :

The California Environmental Protection Agency (CalEPA) has recently implemented a new data warehouse system (nSite). This data warehouse combines and merges facility and site information from five different systems managed within CalEPA. The five systems are: California Environmental Reporting System (CERS), EnviroStor, GeoTracker, California Integrated Water Quality System (CIWQS), and Toxic Release Inventory (TRI).

FRS Environmental Interest

Source and System ID :	CA-ENVIROVIEW - 123451

Map Id: 121
Direction: SE
Distance: 0.964 mi., 5088 ft.
Elevation: 544 ft.
Relative: Lower

Site Name : HUES METAL FINISHING INC | RMP METAL FINISHING
977 LINDA VISTA DR
SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, ENVIROSTOR - CA, FRS, HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 270931
EPA ID: N/R

HAZNET - CA

Facility Name :	HUES METAL FINISHING INC
Facility Address :	977 LINDA VISTA DR., SAN MARCOS, CA 92069
County :	SAN DIEGO

Site Details

Generator EPA ID :	CAD039769583
Active :	Inactive
Category :	STATE
Facility Types :	N/R
Type :	PERMANENT
Contact Name :	N/R
Contact Phone :	N/R
Facility Mailing Address :	977 LINDA VISTA DR, SAN MARCOS, CA 920780000
Latitude :	33.13931126
Longitude :	-117.18577820
Agency Hyperlink :	Click here for hyperlink provided by the agency.
Last Date in Agency List :	2021-07-08

Waste Generator Details

Details for this site have been truncated due to the large number of available details for this site within this dataset. For the complete details for this site, contact your Envirosite account representative for a complimentary site report containing all of the details available.

State Waste :

2015: 181 - Other inorganic solid waste, 0.0675 tons to AZR000501510
2015: 241 - Tank bottom waste, 0.5838 tons to CAL000170578
2015: 171 - Metal sludge (see 121), 6.8805 tons to NVT330010000
2015: 331 - Off-specification, aged or surplus organics, 0.726 tons to CAD008252405
2015: 792 - Liquids with pH <= 2 with metals, 0.01668 tons to CAD008488025
2015: 135 - Unspecified aqueous solution, 1.155 tons to AZR000501510
2015: 723 - Liquids with chromium (VI) >= 500 Mg./L, 0.4587 tons to NVT330010000
2015: 122 - Alkaline solution without metals pH >= 12.5, 0.00417 tons to CAD008488025
2015: 291 - Latex waste, 0.22935 tons to AZR000501510
2015: 181 - Other inorganic solid waste, 0.005 tons to NVT330010000
2014: 331 - Off-specification, aged or surplus organics, 0.1815 tons to CAD008252405
2014: 214 - Unspecified solvent mixture, 0.792 tons to CAD008252405
2014: 135 - Unspecified aqueous solution, 1.617 tons to AZR000501510
2014: 171 - Metal sludge (see 121), 0.22935 tons to NVT330010000
2013: 135 - Unspecified aqueous solution, 1.386 tons to AZR000501510
2013: 214 - Unspecified solvent mixture, 0.396 tons to CAD008252405
2013: 171 - Metal sludge (see 121), 0.4587 tons to NVT330010000
2012: 135 - Unspecified aqueous solution, 0.21 tons to AZR000501510
2012: 171 - Metal sludge (see 121), 0.22935 tons to NVT330010000
2012: 331 - Off-specification, aged or surplus organics, 0.099 tons to CAD008252405
2012: 214 - Unspecified solvent mixture, 0.396 tons to CAD008252405

Map Id: 121
Direction: SE
Distance: 0.964 mi., 5088 ft.
Elevation: 544 ft.
Relative: Lower

Site Name : HUES METAL FINISHING INC | RMP METAL FINISHING
977 LINDA VISTA DR
SAN MARCOS | San Marcos, CA 92069

Database(s) : [CALEPA SITES - CA, ENVIROSTOR - CA, FRS, HAZNET - CA, HWG - CA] ***(cont.)***

Envirosite ID: 270931
EPA ID: N/R

HAZNET - CA ***(cont.)***

2011: 135 - Unspecified aqueous solution, 0.735 tons to ARZ000501510
2011: 171 - Metal sludge (see 121), 0.617 tons to NVT330010000
2011: 331 - Off-specification, aged or surplus organics, 0.475 tons to CAD008252405
2011: 181 - Other inorganic solid waste, 0.015 tons to AZR000501510
2009: 171 - Metal sludge (see 121), 0.4 tons to NVT330010000
2009: 135 - Unspecified aqueous solution, 0.945 tons to ARZ000501510
2009: 331 - Off-specification, aged or surplus organics, 0.035 tons to CAD008252405
2008: 171 - Metal sludge (see 121), 0.4 tons to NVT330010000
2008: 252 - Other still bottom waste, 0.125 tons to TXD077603371

HWG - CA

Facility Name :	HUES METAL FINISHING INC
Facility Address :	977 LINDA VISTA DR., SAN MARCOS, CA 92069
County :	SAN DIEGO
EPA ID :	CAD039769583
Status :	Inactive
Category :	STATE
Type :	PERMANENT
Facility Type :	N/R
Mailing Address :	977 LINDA VISTA DR, SAN MARCOS, CA 920780000
Owner Name :	HUES METAL FINISHING, INC.
Owner Address :	977 LINDA VISTA DRIVE, SAN MARCOS, CA 920780000
Operator Name :	DOLOUR WORMALD/OWNER
Operator Address :	977 LINDA VISTA DR, SAN MARCOS, CA 920780000
Latitude :	33.139383
Longitude :	-117.185707

ENVIROSITE ID	NAME	ADDRESS	CITY	ZIP	DATABASE(S)
40680121	2174 Vons A Safeway Compa...	671 S RANCHO SANTA FE RD,...			HAZMAT_SAN DIEGO C...
40680072	5 M MAINTENANCE SERVICES	1404 DESCANSO AVE, SAN MA...			HAZMAT_SAN DIEGO C...
40679673	COLINAS CONTRACTORS	1990 S SANTA FE AVE, SUIT...			HAZMAT_SAN DIEGO C...
32615409	COUNTY OF SAN DIEGO - VEC...	126 PACIFIC ST			HAZMAT_SAN DIEGO C...
8986859	Gregory Canyon Landfill	State Route 76, SW of Pal...			LF_SAN DIEGO COUNT...
8986883	Jacumba Burnsite II	Jacumba Street SW of Lake...			LF_SAN DIEGO COUNT...
40680264	Javier Mobile and Auto Re...	2514 S SANTA FE AVE, SUIT...			HAZMAT_SAN DIEGO C...
40680187	Luna's Auto Shop	1828 S SANTA FE AVE, VIST...			HAZMAT_SAN DIEGO C...
7383261	MEADOWLARK WASTE WATER RE...	2310 RANCHO SANTA FE RD	SAN MARCOS	92069	HAZNET - CA, HWG - CA
44374060	PARK REVOCABLE FAMILY TRU...	225, 235, 245 N RANCHO SA...	SAN MARCOS	92069	ECHO, FRS, HWG - CA,...

FEDERAL RCRA NON-CORRACTS TSD FACILITIES LIST

ARCHIVED RCRA TSDF: Resource Conservation and Recovery Act hazardous waste transportation storage disposal and treatment facilities

Agency Version Date: 12/30/2021
Agency Update Frequency: Quarterly
Planned Next Contact: 03/28/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 215-814-2469
Most Recent Contact: 12/30/2021

RCRA_TSDF: Resource Conservation and Recovery Act hazardous waste transportation storage disposal and treatment facilities

Agency Version Date: 12/30/2021
Agency Update Frequency: Quarterly
Planned Next Contact: 03/28/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 215-814-2469
Most Recent Contact: 12/30/2021

FEDERAL, STATE, AND TRIBAL REGISTERED STORAGE TANK LISTS

AST PBS: Bulk petroleum terminals with a total bulk storage capacity of 50,000 barrels or more.

Agency Version Date: 02/22/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 05/20/2022
Agency: Department of Homeland Security
Agency Contact: 202-853-5361
Most Recent Contact: 02/22/2022

EPA UST: Facilities listed in the EPA UST Finder database

Agency Version Date: 11/19/2021
Agency Update Frequency: Quarterly
Planned Next Contact: 05/12/2022
Agency: EPA
Agency Contact: (202) 566-1667
Most Recent Contact: 02/15/2022

FEMA UST: FEMA underground storage tank listing

Agency Version Date: 10/08/2021
Agency Update Frequency: Varies
Planned Next Contact: 04/01/2022
Agency: FEMA
Agency Contact: 202-212-5283
Most Recent Contact: 01/04/2022

HIST INDIAN UST R6: Historical Underground Storage Tanks on Indian Land in EPA Region 6

Agency Version Date: 12/03/2021
Agency Update Frequency: Semi Annually
Planned Next Contact: 05/27/2022
Agency: U.S. Environmental Protection Agency Region 6
Agency Contact: 855-246-3642
Most Recent Contact: 03/01/2022

HIST INDIAN UST R7: Historical Underground Storage Tanks on Indian Land in EPA Region 7

Agency Version Date: 08/10/2021
Agency Update Frequency: Quarterly
Planned Next Contact: 05/12/2022
Agency: U.S. Environmental Protection Agency Region 7
Agency Contact: 855-246-3642
Most Recent Contact: 02/15/2022

INDIAN UST R1: Underground Storage Tanks on Indian Land in EPA Region 1

Agency Version Date: 01/18/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/15/2022
Agency: U.S. Environmental Protection Agency Region 1
Agency Contact: 855-246-3642
Most Recent Contact: 10/18/2021

INDIAN UST R10: Underground Storage Tanks on Indian Land in EPA Region 10

Agency Version Date: 02/14/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 05/12/2022
Agency: U.S. Environmental Protection Agency Region 10
Agency Contact: 855-246-3642
Most Recent Contact: 02/14/2022

FEDERAL, STATE, AND TRIBAL REGISTERED STORAGE TANK LISTS (cont.)

INDIAN UST R2: Underground Storage Tanks on Indian Land in EPA Region 2

Agency Version Date: 12/07/2016
Agency Update Frequency: Quarterly
Planned Next Contact: 04/19/2022
Agency: U.S. Environmental Protection Agency Region 2
Agency Contact: 855-246-3642
Most Recent Contact: 01/21/2022

INDIAN UST R4: Underground Storage Tanks on Indian Land in EPA Region 4

Agency Version Date: 02/14/2022
Agency Update Frequency: Semi Annually
Planned Next Contact: 05/12/2022
Agency: U.S. Environmental Protection Agency Region 4
Agency Contact: 855-246-3642
Most Recent Contact: 02/14/2022

INDIAN UST R5: Underground Storage Tanks on Indian Land in EPA Region 5

Agency Version Date: 01/31/2022
Agency Update Frequency: Varies
Planned Next Contact: 04/28/2022
Agency: U.S. Environmental Protection Agency Region 5
Agency Contact: 855-246-3642
Most Recent Contact: 01/31/2022

INDIAN UST R6: Underground Storage Tanks on Indian Land in EPA Region 6

Agency Version Date: 03/01/2022
Agency Update Frequency: Semi Annually
Planned Next Contact: 05/27/2022
Agency: U.S. Environmental Protection Agency Region 6
Agency Contact: 855-246-3642
Most Recent Contact: 03/01/2022

INDIAN UST R7: Underground Storage Tanks on Indian Land in EPA Region 7

Agency Version Date: 01/31/2022
Agency Update Frequency: Varies
Planned Next Contact: 04/28/2022
Agency: U.S. Environmental Protection Agency Region 7
Agency Contact: 855-246-3642
Most Recent Contact: 01/31/2022

INDIAN UST R8: Underground Storage Tanks on Indian Land in EPA Region 8

Agency Version Date: 01/17/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/14/2022
Agency: U.S. Environmental Protection Agency Region 8
Agency Contact: 855-246-3642
Most Recent Contact: 01/17/2022

INDIAN UST R9: Underground Storage Tanks on Indian Land in EPA Region 9

Agency Version Date: 01/17/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/14/2022
Agency: U.S. Environmental Protection Agency Region 9
Agency Contact: 855-246-3642
Most Recent Contact: 01/17/2022

AST - CA: Listing of tank facilities that are subject to the California Aboveground Petroleum Storage Act

Agency Version Date: 10/04/2021
Agency Update Frequency: No update
Planned Next Contact: 03/28/2022
Agency: California Environmental Protection Agency Unified Program Section
Agency Contact: 916-327-5092
Most Recent Contact: 12/29/2021

AST_KERN COUNTY - CA: Kern County aboveground storage tank sites

Agency Version Date: 12/17/2021
Agency Update Frequency: Quarterly
Planned Next Contact: 06/13/2022
Agency: Kern County Environment Health Division
Agency Contact: 661-862-8774
Most Recent Contact: 03/15/2022

AST_ORANGE COUNTY - CA: Orange county aboveground storage tanks

Agency Version Date: 02/22/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 05/20/2022
Agency: Orange County Health Care Agency
Agency Contact: 714-433-6000
Most Recent Contact: 02/22/2022

FEDERAL, STATE, AND TRIBAL REGISTERED STORAGE TANK LISTS (cont.)

AST_PLACER COUNTY - CA: Placer county aboveground storage tank sites

Agency Version Date: 01/25/2022
Agency Update Frequency: Semi Annually
Planned Next Contact: 04/20/2022
Agency: Placer County Environmental Health
Agency Contact: 530-745-2350
Most Recent Contact: 01/25/2022

AST_YOLO COUNTY - CA: Yolo county above ground storage tank sites listing

Agency Version Date: 01/31/2022
Agency Update Frequency: Annually
Planned Next Contact: 04/27/2022
Agency: Yolo County Environmental Health
Agency Contact: 530-666-8646
Most Recent Contact: 01/31/2022

CLOSED UST_VENTURA COUNTY - CA: Ventura County closed underground storage tank site listing

Agency Version Date: 02/01/2022
Agency Update Frequency: Varies
Planned Next Contact: 04/29/2022
Agency: Environmental Health Division
Agency Contact: 805-654-2815
Most Recent Contact: 02/01/2022

FID UST - CA: The State Water Resource Control Board's Facility Inventory Database underground storage tank locations listing

Agency Version Date: 03/10/2022
Agency Update Frequency: Varies
Planned Next Contact: 06/06/2022
Agency: California Environmental Protection Agency
Agency Contact: 916-341-5791
Most Recent Contact: 03/10/2022

HIST AST - CA: Historical listing of tank facilities that are subject to the California Aboveground Petroleum Storage Act

Agency Version Date: 07/19/2019
Agency Update Frequency: Quarterly
Planned Next Contact: 04/06/2022
Agency: California Environmental Protection Agency Unified Program Section
Agency Contact: 916-327-5092
Most Recent Contact: 01/10/2022

HIST UST - CA: Historical UST listing

Agency Version Date: 09/24/2021
Agency Update Frequency: Varies
Planned Next Contact: 06/16/2022
Agency: State Water Resources Control Board
Agency Contact: 916-341-5791
Most Recent Contact: 03/21/2022

HIST UST_EL SEGUNDO CITY - CA: List of City of El Segundo Underground Storage Tanks that are no longer in current agency list.

Agency Version Date: 01/29/2018
Agency Update Frequency: Annually
Planned Next Contact: 03/23/2022
Agency: City of El Segundo Fire Department
Agency Contact: 310-524-2242
Most Recent Contact: 12/27/2021

HIST UST_KERN COUNTY - CA: List of Kern County underground storage tank records that is no longer in current agency list.

Agency Version Date: 11/28/2018
Agency Update Frequency: Annually
Planned Next Contact: 05/31/2022
Agency: Kern County Environment Health Division
Agency Contact: 661-862-8774
Most Recent Contact: 03/04/2022

HIST UST_SUTTER COUNTY - CA: List of Sutter County Underground Storage Tank records that are no longer in current agency list.

Agency Version Date: 10/22/2018
Agency Update Frequency: Annually
Planned Next Contact: 04/06/2022
Agency: Sutter County Department of Agriculture
Agency Contact: 530-822-7400
Most Recent Contact: 01/10/2022

FEDERAL, STATE, AND TRIBAL REGISTERED STORAGE TANK LISTS (cont.)

TANKS_CONTRA COSTA COUNTY - CA: Listing of aboveground storage tanks in Contra Costa County

Agency Version Date: 11/10/2021
Agency Update Frequency: Varies
Planned Next Contact: 05/03/2022
Agency: Contra Costa Health Services Department
Agency Contact: 925-335-3200
Most Recent Contact: 02/04/2022

UST - CA: Listing of active underground storage tank facilities

Agency Version Date: 03/03/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 05/30/2022
Agency: CA Gov geotracker state water resources control board
Agency Contact: N/R
Most Recent Contact: 03/03/2022

UST_ALAMEDA COUNTY - CA: Alameda County Underground Storage Tank sites

Agency Version Date: 03/03/2022
Agency Update Frequency: Varies
Planned Next Contact: 05/30/2022
Agency: CA Gov geotracker state water resources control board
Agency Contact: 916-341-5791
Most Recent Contact: 03/03/2022

UST_CITY OF LONG BEACH - CA: City of Long Beach underground storage tank sites

Agency Version Date: 06/29/2021
Agency Update Frequency: Quarterly
Planned Next Contact: 05/06/2022
Agency: City of Long Beach Fire Department
Agency Contact: 562-570-6782
Most Recent Contact: 02/08/2022

UST_CITY OF TORRANCE - CA: City of Torrance underground storage tank sites

Agency Version Date: 05/07/2021
Agency Update Frequency: Quarterly
Planned Next Contact: 04/22/2022
Agency: City of Torrance Fire Department
Agency Contact: 310-618-2872
Most Recent Contact: 01/25/2022

UST_EL SEGUNDO CITY - CA: City of El Segundo Underground Storage Tanks

Agency Version Date: 01/29/2018
Agency Update Frequency: Annually
Planned Next Contact: 03/31/2022
Agency: City of El Segundo Fire Department
Agency Contact: 310-524-2242
Most Recent Contact: 01/04/2022

UST_KERN COUNTY - CA: Kern County underground storage tank sites

Agency Version Date: 12/17/2021
Agency Update Frequency: Quarterly
Planned Next Contact: 06/13/2022
Agency: Kern County Environment Health Division
Agency Contact: 661-862-8774
Most Recent Contact: 03/15/2022

UST_MARIN COUNTY - CA: Marin county underground storage tank sites

Agency Version Date: 08/04/2018
Agency Update Frequency: Semi Annually
Planned Next Contact: 05/02/2022
Agency: Marin County Department of Public Works
Agency Contact: 415-473-5051
Most Recent Contact: 02/04/2022

UST_MENDOCINO COUNTY - CA: A listing of underground storage tank locations in Mendocino County

Agency Version Date: 03/03/2022
Agency Update Frequency: Varies
Planned Next Contact: 05/30/2022
Agency: CA Gov geotracker state water resources control board
Agency Contact: 916-341-5791
Most Recent Contact: 03/03/2022

UST_NAPA COUNTY - CA: Underground storage tank sites located in Napa county.

Agency Version Date: 03/03/2022
Agency Update Frequency: Varies
Planned Next Contact: 05/30/2022
Agency: CA Gov geotracker state water resources control board
Agency Contact: 916-341-5791
Most Recent Contact: 03/03/2022

FEDERAL, STATE, AND TRIBAL REGISTERED STORAGE TANK LISTS (cont.)

UST_ORANGE COUNTY - CA: Orange county underground storage tanks

Agency Version Date: 02/11/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 05/10/2022
Agency: Orange County Health Care Agency
Agency Contact: 714-433-6000
Most Recent Contact: 02/11/2022

UST_PLACER COUNTY - CA: Placer county underground storage tank sites

Agency Version Date: 01/25/2022
Agency Update Frequency: Semi Annually
Planned Next Contact: 04/20/2022
Agency: Placer County Environmental Health
Agency Contact: 530-745-2350
Most Recent Contact: 01/25/2022

UST_RIVERSIDE COUNTY - CA: Riverside county underground storage tank sites

Agency Version Date: 03/03/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 05/30/2022
Agency: CA Gov geotracker state water resources control board
Agency Contact: N/R
Most Recent Contact: 03/03/2022

UST_SAN FRANCISCO COUNTY - CA: San Francisco county Underground storage tank sites listing

Agency Version Date: 02/25/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 05/23/2022
Agency: San Francisco Department of Public Health
Agency Contact: N/R
Most Recent Contact: 02/25/2022

UST_SAN JOAQUIN COUNTY - CA: San Joaquin County Underground storage tank sites listing

Agency Version Date: 03/03/2022
Agency Update Frequency: Semi Annually
Planned Next Contact: 05/30/2022
Agency: CA Gov geotracker state water resources control board
Agency Contact: 916-341-5791
Most Recent Contact: 03/03/2022

UST_SOLANO COUNTY - CA: Solano county underground storage tank listing

Agency Version Date: 03/03/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 05/30/2022
Agency: CA Gov geotracker state water resources control board
Agency Contact: N/R
Most Recent Contact: 03/03/2022

UST_SUTTER COUNTY - CA: Sutter county underground storage tank listing

Agency Version Date: 01/21/2022
Agency Update Frequency: Semi Annually
Planned Next Contact: 04/19/2022
Agency: Sutter County Department of Agriculture
Agency Contact: 530-822-7400
Most Recent Contact: 01/21/2022

UST_YOLO COUNTY - CA: Yolo county underground storage tank sites listing

Agency Version Date: 11/09/2021
Agency Update Frequency: Annually
Planned Next Contact: 05/02/2022
Agency: Yolo County Environmental Health
Agency Contact: 530-666-8646
Most Recent Contact: 02/04/2022

FEDERAL CERCLIS LIST

CERCLIS NFRAP: The CERCLIS sites with No Further Remedial Action Planned from the CERCLIS program database. The Environmental Protection Agency decommissioned the CERCLIS data in 2014. The last update was November 12, 2013.

Agency Version Date: 01/28/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/26/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 800-424-9346
Most Recent Contact: 01/28/2022

FEDERAL CERCLIS LIST (cont.)

CERCLIS-HIST: The CERCLIS program database contains information on the assessment and remediation of federal hazardous waste sites. The Environmental Protection Agency decommissioned the CERCLIS data in 2014. The last update was November 12, 2013.

Agency Version Date: 01/28/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/26/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 800-424-9346
Most Recent Contact: 01/28/2022

EPA SAA: Listing of Sites with Superfund Alternative Approach Agreements.

Agency Version Date: 11/01/2021
Agency Update Frequency: Quarterly
Planned Next Contact: 04/25/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 800-424-9346
Most Recent Contact: 01/27/2022

FEDERAL FACILITY: Sites where Federal Facilities Restoration and Reuse Office (FFRRO) arranged cleanup for Base Closure and Property Transfer at Federal Facilities

Agency Version Date: 01/28/2022
Agency Update Frequency: Varies
Planned Next Contact: 04/26/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 703-603-8712
Most Recent Contact: 01/28/2022

SEMS_8R_ACTIVE SITES: The Active Site Inventory Report displays site and location information at active SEMS sites. An active site is one at which site assessment, removal, remedial, enforcement, cost recovery, or oversight activities are being planned or conducted. NPL sites include latitude and longitude information. For non-NPL sites, a brief site status is provided.

Agency Version Date: 01/28/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/26/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 703-603-8867
Most Recent Contact: 01/28/2022

SEMS_8R_ARCHIVED SITES: The Archived Site Inventory displays site and location information at sites archived from SEMS. An archived site is one at which EPA has determined that assessment has been completed and no further remedial action is planned under the Superfund program at this time.

Agency Version Date: 01/28/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/26/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 703-603-8867
Most Recent Contact: 01/28/2022

FEDERAL RCRA CORRACTS FACILITIES LIST

CORRACTS: List of facilities where Resource Conservation and Recovery Act Corrective Action Program used to investigate and remediate hazardous releases

Agency Version Date: 12/30/2021
Agency Update Frequency: Quarterly
Planned Next Contact: 03/28/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 202-566-1667
Most Recent Contact: 12/30/2021

HIST CORRACTS 2: List of facilities where Resource Conservation and Recovery Act Corrective Action Program used to investigate and remediate hazardous releases that are no longer in current agency list.

Agency Version Date: 10/12/2018
Agency Update Frequency: Annually
Planned Next Contact: 05/23/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 202-566-1667
Most Recent Contact: 02/24/2022

FEDERAL DELISTED NPL SITE LIST

DELISTED NPL: National Priority List of sites that were delisted and no longer require action

Agency Version Date: 01/28/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/26/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 703-603-8867
Most Recent Contact: 01/28/2022

FEDERAL DELISTED NPL SITE LIST (cont.)

DELISTED PROPOSED NPL: Sites that have been delisted from the proposed National Priority List

Agency Version Date: 01/28/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/26/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 703-603-8867
Most Recent Contact: 01/28/2022

SEMS_DELETED NPL: All Deleted National Priority List Sties

Agency Version Date: 01/28/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/26/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 703-603-8867
Most Recent Contact: 01/28/2022

FEDERAL LANDFILL AND/OR SOLID WASTE DISPOSAL SITE LISTS

EPA LF MOP: Sites in the EPA Landfill Methane Outreach Program

Agency Version Date: 12/29/2021
Agency Update Frequency: Quarterly
Planned Next Contact: 03/25/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 703-603-8867
Most Recent Contact: 12/29/2021

FEDERAL, STATE, AND TRIBAL LEAKING STORAGE TANK LISTS

EPA LUST: Releases listed in the EPA UST Finder database

Agency Version Date: 11/19/2021
Agency Update Frequency: Quarterly
Planned Next Contact: 05/12/2022
Agency: EPA
Agency Contact: (202) 566-1667
Most Recent Contact: 02/15/2022

HIST INDIAN LUST R4: Historical Leaking Underground Storage Tanks on Indian Land in EPA Region 4

Agency Version Date: 08/23/2021
Agency Update Frequency: Quarterly
Planned Next Contact: 05/12/2022
Agency: U.S. Environmental Protection Agency Region 4
Agency Contact: 855-246-3642
Most Recent Contact: 02/15/2022

HIST INDIAN LUST R8: Historical Leaking Underground Storage Tanks on Indian Land in EPA Region 8

Agency Version Date: 08/16/2021
Agency Update Frequency: Quarterly
Planned Next Contact: 05/04/2022
Agency: U.S. Environmental Protection Agency Region 8
Agency Contact: 855-246-3642
Most Recent Contact: 02/07/2022

INDIAN LUST R1: Leaking Underground Storage Tanks on Indian Land in EPA Region 1

Agency Version Date: 10/21/2021
Agency Update Frequency: Quarterly
Planned Next Contact: 04/15/2022
Agency: U.S. Environmental Protection Agency Region 1
Agency Contact: 855-246-3642
Most Recent Contact: 01/18/2022

INDIAN LUST R10: Leaking Underground Storage Tanks on Indian Land in EPA Region 10

Agency Version Date: 02/14/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 05/12/2022
Agency: U.S. Environmental Protection Agency Region 10
Agency Contact: 855-246-3642
Most Recent Contact: 02/14/2022

INDIAN LUST R2: Leaking Underground Storage Tanks on Indian Land in EPA Region 2

Agency Version Date: 12/07/2016
Agency Update Frequency: Quarterly
Planned Next Contact: 04/19/2022
Agency: U.S. Environmental Protection Agency Region 2
Agency Contact: 855-246-3642
Most Recent Contact: 01/21/2022

FEDERAL, STATE, AND TRIBAL LEAKING STORAGE TANK LISTS (cont.)

INDIAN LUST R4: Leaking Underground Storage Tanks on Indian Land in EPA Region 4

Agency Version Date: 02/14/2022
Agency Update Frequency: Semi Annually
Planned Next Contact: 05/12/2022
Agency: U.S. Environmental Protection Agency Region 4
Agency Contact: 855-246-3642
Most Recent Contact: 02/14/2022

INDIAN LUST R5: Leaking Underground Storage Tanks on Indian Land in EPA Region 5

Agency Version Date: 01/31/2022
Agency Update Frequency: Varies
Planned Next Contact: 04/28/2022
Agency: U.S. Environmental Protection Agency Region 5
Agency Contact: 855-246-3642
Most Recent Contact: 01/31/2022

INDIAN LUST R6: Leaking Underground Storage Tanks on Indian Land in EPA Region 6

Agency Version Date: 02/03/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 05/02/2022
Agency: U.S. Environmental Protection Agency Region 6
Agency Contact: 855-246-3642
Most Recent Contact: 02/03/2022

INDIAN LUST R7: Leaking Underground Storage Tanks on Indian Land in EPA Region 7

Agency Version Date: 08/10/2021
Agency Update Frequency: Varies
Planned Next Contact: 04/28/2022
Agency: U.S. Environmental Protection Agency Region 7
Agency Contact: 855-246-3642
Most Recent Contact: 01/31/2022

INDIAN LUST R8: Leaking Underground Storage Tanks on Indian Land in EPA Region 8

Agency Version Date: 02/04/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 05/03/2022
Agency: U.S. Environmental Protection Agency Region 8
Agency Contact: 855-246-3642
Most Recent Contact: 02/04/2022

INDIAN LUST R9: Leaking Underground Storage Tanks on Indian Land in EPA Region 9

Agency Version Date: 01/17/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/14/2022
Agency: U.S. Environmental Protection Agency Region 9
Agency Contact: 855-246-3642
Most Recent Contact: 01/17/2022

HIST LUST_SONOMA COUNTY - CA: List of Sonoma County leaking underground storage tank sites that is no longer in current agency list.

Agency Version Date: 08/23/2018
Agency Update Frequency: Annually
Planned Next Contact: 03/31/2022
Agency: CA Gov geotracker state water resources control board
Agency Contact: 916-341-5791
Most Recent Contact: 01/04/2022

LUFT_ALAMEDA COUNTY - CA: Listing of Alameda County leaking underground fuel tank sites

Agency Version Date: 11/18/2018
Agency Update Frequency: No Longer Maintained
Planned Next Contact: 05/16/2022
Agency: Alameda County Environmental Health Services
Agency Contact: 510-567-6721
Most Recent Contact: 02/17/2022

LUST ORANGE COUNTY - CA: Orange county leaking underground storage tanks

Agency Version Date: 07/29/2021
Agency Update Frequency: Quarterly
Planned Next Contact: 04/18/2022
Agency: Orange County Health Care Agency
Agency Contact: 714-433-6000
Most Recent Contact: 01/19/2022

FEDERAL, STATE, AND TRIBAL LEAKING STORAGE TANK LISTS (cont.)

LUST REG 1 - CA: Leaking underground storage tanks in Region 1: Del Norte Glenn Humboldt Lake Marin Mendocino Modoc Siskiyou Sonoma andTrinity counties.

Agency Version Date: 01/25/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/22/2022
Agency: State Water Resources Control Board
Agency Contact: 916-341-5791
Most Recent Contact: 01/25/2022

LUST REG 2 - CA: Leaking underground storage tanks in Region 2: Alameda Contra Costa San Francisco Santa Clara (north of Morgan Hill) San Mateo Marin Sonoma Napa Solano counties

Agency Version Date: 01/25/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/22/2022
Agency: State Water Resources Control Board
Agency Contact: 916-341-5791
Most Recent Contact: 01/25/2022

LUST REG 3 - CA: Leaking underground storage tanks in Region 3: Santa Clara (south of Morgan Hill) San Mateo (southern part) Santa Cruz SanBenito Monterey Kern (some parts) San Luis Obispo Santa Barbara Ventura(northern part) counties

Agency Version Date: 01/25/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/22/2022
Agency: State Water Resources Control Board
Agency Contact: 916-341-5791
Most Recent Contact: 01/25/2022

LUST REG 4 - CA: Leaking underground storage tanks in Region 4: Los Angeles Ventura counties (Small parts of Kern and Santa Barbara counties).

Agency Version Date: 01/25/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/22/2022
Agency: State Water Resources Control Board
Agency Contact: 916-341-5791
Most Recent Contact: 01/25/2022

LUST REG 5 - CA: Leaking underground storage tanks in Region 5: Modoc Shasta Lassen Plumas Butte Glen Colusa Lake Sutter Yuba Sierra Nevada Placer Yolo Napa (Northeast) Solano (West) Sacramento El Dorado Amador Calaveras San Joaquin Contra Costa (East) Stanislaus Toulumne Merced Mariposa Madera Kings Fresno Tulare Kern (Very small portions of San Benito and SanLuis Obispo) counties

Agency Version Date: 01/25/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/22/2022
Agency: State Water Resources Control Board
Agency Contact: 916-341-5791
Most Recent Contact: 01/25/2022

LUST REG 6 - CA: Leaking underground storage tanks in Region 6: Modoc (East) Lassen (East side and Eagle Lake) Sierra Nevada Placer El Dorado Alpine Mono Inyo Kern (East) San Bernardino Los Angeles (Northeast corner) counties

Agency Version Date: 01/25/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/22/2022
Agency: State Water Resources Control Board
Agency Contact: 916-341-5791
Most Recent Contact: 01/25/2022

LUST REG 7 - CA: Leaking underground storage tanks in Region 7: Imperial San Bernardino Riverside and San Diego counties.

Agency Version Date: 01/25/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/22/2022
Agency: State Water Resources Control Board
Agency Contact: 916-341-5791
Most Recent Contact: 01/25/2022

LUST REG 8 - CA: Leaking underground storage tanks in Region 8: Orange Riverside San Bernardino counties.

Agency Version Date: 01/25/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/22/2022
Agency: State Water Resources Control Board
Agency Contact: 916-341-5791
Most Recent Contact: 01/25/2022

FEDERAL, STATE, AND TRIBAL LEAKING STORAGE TANK LISTS (cont.)

LUST REG 9 - CA: Leaking underground storage tanks in Region 9: San Diego Imperial Riverside counties.

Agency Version Date: 01/25/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/22/2022
Agency: State Water Resources Control Board
Agency Contact: 916-341-5791
Most Recent Contact: 01/25/2022

LUST_HAZMAT_YOLO COUNTY - CA: Yolo county leaking underground storage tank sites listing

Agency Version Date: 01/21/2022
Agency Update Frequency: Varies
Planned Next Contact: 04/19/2022
Agency: Yolo County Environmental Health
Agency Contact: 530-666-8646
Most Recent Contact: 01/21/2022

LUST_KERN COUNTY - CA: Kern County leaking underground tank sites

Agency Version Date: 01/21/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/19/2022
Agency: CA Gov geotracker state water resources control bo
Agency Contact: 916-341-5791
Most Recent Contact: 01/21/2022

LUST_RIVERSIDE COUNTY - CA: Riverside county leaking underground storage tank sites

Agency Version Date: 01/21/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/19/2022
Agency: CA Gov geotracker state water resources control board
Agency Contact: 916-341-5791
Most Recent Contact: 01/21/2022

LUST_SAN FRANCISCO COUNTY - CA: A listing of leaking underground storage tank sites located in San Francisco county.

Agency Version Date: 01/21/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/19/2022
Agency: CA Gov geotracker state water resources control board
Agency Contact: 916-341-5791
Most Recent Contact: 01/21/2022

LUST_SAN MATEO COUNTY - CA: San Mateo county leaking underground storage tank listing

Agency Version Date: 01/21/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/19/2022
Agency: CA Gov geotracker state water resources control board
Agency Contact: 916-341-5791
Most Recent Contact: 01/21/2022

LUST_SOLANO COUNTY - CA: Solano county leaking underground storage tank listing

Agency Version Date: 01/21/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/19/2022
Agency: CA Gov geotracker state water resources control board
Agency Contact: 916-341-5791
Most Recent Contact: 01/21/2022

LUST_SONOMA COUNTY - CA: Sonoma county leaking underground storage tank sites listing

Agency Version Date: 01/21/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/19/2022
Agency: CA Gov geotracker state water resources control board
Agency Contact: 916-341-5791
Most Recent Contact: 01/21/2022

LUST_SUTTER COUNTY - CA: Sutter County Leaking Underground Storage Tanks

Agency Version Date: 01/21/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/19/2022
Agency: CA Gov geotracker state water resources control board
Agency Contact: 916-341-5791
Most Recent Contact: 01/21/2022

LUST_VENTURA COUNTY - CA: Ventura County leaking underground storage tank site listing

Agency Version Date: 01/21/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/19/2022
Agency: CA Gov geotracker state water resources control boa
Agency Contact: 916-341-5791
Most Recent Contact: 01/21/2022

FEDERAL, STATE, AND TRIBAL LEAKING STORAGE TANK LISTS (cont.)

SLIC REG 1 - CA: List of Region 1 sites from GeoTracker Site Cleanup Program (formerly known as SLIC) database.

Agency Version Date: 01/25/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/22/2022
Agency: State Water Resources Control Board
Agency Contact: 916-341-5791
Most Recent Contact: 01/25/2022

SLIC REG 2 - CA: List of Region 2 sites from GeoTracker Site Cleanup Program (formerly known as SLIC) database.

Agency Version Date: 01/25/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/22/2022
Agency: State Water Resources Control Board
Agency Contact: 916-341-5791
Most Recent Contact: 01/25/2022

SLIC REG 3 - CA: List of Region 3 sites from GeoTracker Site Cleanup Program (formerly known as SLIC) database.

Agency Version Date: 01/25/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/22/2022
Agency: State Water Resources Control Board
Agency Contact: 916-341-5791
Most Recent Contact: 01/25/2022

SLIC REG 4 - CA: List of Region 4 sites from GeoTracker Site Cleanup Program (formerly known as SLIC) database.

Agency Version Date: 01/25/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/22/2022
Agency: State Water Resources Control Board
Agency Contact: 916-341-5791
Most Recent Contact: 01/25/2022

SLIC REG 5 - CA: List of Region 5 sites from GeoTracker Site Cleanup Program (formerly known as SLIC) database.

Agency Version Date: 01/25/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/22/2022
Agency: State Water Resources Control Board
Agency Contact: 916-341-5791
Most Recent Contact: 01/25/2022

SLIC REG 6 - CA: List of Region 6 sites from GeoTracker Site Cleanup Program (formerly known as SLIC) database that is no longer in current agency list.

Agency Version Date: 01/25/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/22/2022
Agency: State Water Resources Control Board
Agency Contact: 916-341-5791
Most Recent Contact: 01/25/2022

SLIC REG 7 - CA: List of Region 7 sites from GeoTracker Site Cleanup Program (formerly known as SLIC) database.

Agency Version Date: 01/25/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/22/2022
Agency: State Water Resources Control Board
Agency Contact: 916-341-5791
Most Recent Contact: 01/25/2022

SLIC REG 8 - CA: List of Region 8 sites from GeoTracker Site Cleanup Program (formerly known as SLIC) database.

Agency Version Date: 01/25/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/22/2022
Agency: State Water Resources Control Board
Agency Contact: 916-341-5791
Most Recent Contact: 01/25/2022

SLIC REG 9 - CA: List of Region 9 sites from GeoTracker Site Cleanup Program (formerly known as SLIC) database that is no longer in current agency list.

Agency Version Date: 01/25/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/22/2022
Agency: State Water Resources Control Board
Agency Contact: 916-341-5791
Most Recent Contact: 01/25/2022

FEDERAL, STATE, AND TRIBAL LEAKING STORAGE TANK LISTS (cont.)

SLIC_ALAMEDA COUNTY - CA: Listing of spills leaks investigation & cleanup sites

Agency Version Date: 01/16/2019
Agency Update Frequency: Quarterly
Planned Next Contact: 05/02/2022
Agency: Alameda County Environmental Health Services
Agency Contact: 510-567-6721
Most Recent Contact: 02/03/2022

FEDERAL ERNS LIST

ERNS: Emergency Response Notification System records of reported spills

Agency Version Date: 01/21/2022
Agency Update Frequency: Annually
Planned Next Contact: 04/19/2022
Agency: National Response Center United States Coast Guard
Agency Contact: N/R
Most Recent Contact: 01/21/2022

FEDERAL INSTITUTIONAL CONTROLS / ENGINEERING CONTROLS REGISTRIES

FED E C: Federal listing of remediation sites with engineering controls

Agency Version Date: 02/22/2022
Agency Update Frequency: Varies
Planned Next Contact: 05/20/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 800-424-9346
Most Recent Contact: 02/22/2022

FED I C: Federal listing of remediation sites with institutional controls

Agency Version Date: 02/22/2022
Agency Update Frequency: Varies
Planned Next Contact: 05/20/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 800-424-9346
Most Recent Contact: 02/22/2022

RCRA IC_EC: Sites with institutional or engineering controls related to Resource Conservation and Recovery Act

Agency Version Date: 02/04/2022
Agency Update Frequency: Varies
Planned Next Contact: 05/03/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 215-814-2469
Most Recent Contact: 02/04/2022

FEDERAL RCRA GENERATORS LIST

HIST RCRA_CESQG: List of Resource Conservation and Recovery Act licensed conditionally exempt small quantity generators that are no longer in current agency list.

Agency Version Date: 10/12/2018
Agency Update Frequency: Annually
Planned Next Contact: 05/23/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 215-814-2469
Most Recent Contact: 02/24/2022

HIST RCRA_LQG: List of Resource Conservation and Recovery Act licensed large quantity generators that are no longer in current agency list.

Agency Version Date: 10/12/2018
Agency Update Frequency: Annually
Planned Next Contact: 05/23/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 215-814-2469
Most Recent Contact: 02/24/2022

HIST RCRA_NONGEN: List of Resource Conservation and Recovery Act licensed non-generators that are no longer in current agency list.

Agency Version Date: 10/12/2018
Agency Update Frequency: Annually
Planned Next Contact: 05/23/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 215-814-2469
Most Recent Contact: 02/24/2022

FEDERAL RCRA GENERATORS LIST (cont.)

HIST RCRA_SQG: List of Resource Conservation and Recovery Act licensed small quantity generators that are no longer in current agency list.

Agency Version Date: 10/12/2018
Agency Update Frequency: Annually
Planned Next Contact: 05/23/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 215-814-2469
Most Recent Contact: 02/24/2022

RCRA_LQG: Resource Conservation and Recovery Act listing of licensed large quantity generators

Agency Version Date: 12/30/2021
Agency Update Frequency: Quarterly
Planned Next Contact: 03/28/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 215-814-2469
Most Recent Contact: 12/30/2021

RCRA_NONGEN: Resource Conservation and Recovery Act listing of licensed non-generators

Agency Version Date: 12/30/2021
Agency Update Frequency: Varies
Planned Next Contact: 03/28/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 215-814-2469
Most Recent Contact: 12/30/2021

RCRA_SQG: Resource Conservation and Recovery Act listing of licensed small quantity generators

Agency Version Date: 12/30/2021
Agency Update Frequency: Quarterly
Planned Next Contact: 03/28/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 215-814-2469
Most Recent Contact: 12/30/2021

RCRA_VSQG: Resource Conservation and Recovery Act listing of licensed very small quantity generators.

Agency Version Date: 12/30/2021
Agency Update Frequency: Varies
Planned Next Contact: 03/28/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 215-814-2469
Most Recent Contact: 12/30/2021

FEDERAL NPL SITE LIST

NPL: List of priority contaminated sites among identified releases or threatened releases of hazardous substances pollutants or contaminants nationally

Agency Version Date: 01/28/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/26/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 703-603-8867
Most Recent Contact: 01/28/2022

NPL EPA R1 GIS: Geospatial data for the Environmental Protection Agency Region 1 National Priority List subject to environmental regulation

Agency Version Date: 01/28/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/26/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 202-566-2132
Most Recent Contact: 01/28/2022

NPL EPA R3 GIS: Geospatial data for the Environmental Protection Agency Region 3 National Priority List subject to environmental regulation

Agency Version Date: 01/28/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/26/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 202-566-2132
Most Recent Contact: 01/28/2022

NPL EPA R6 GIS: Geospatial data for the Environmental Protection Agency Region 6 National Priority List subject to environmental regulation

Agency Version Date: 01/28/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/26/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 202-566-2132
Most Recent Contact: 01/28/2022

FEDERAL NPL SITE LIST (cont.)

NPL EPA R8 GIS: Geospatial data for the Environmental Protection Agency Region 8 National Priority List subject to environmental regulation

Agency Version Date: 01/28/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/26/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 202-566-2132
Most Recent Contact: 01/28/2022

NPL EPA R9 GIS: Geospatial data for the Environmental Protection Agency Region 9 National Priority List subject to environmental regulation

Agency Version Date: 01/28/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/26/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 202-566-2132
Most Recent Contact: 01/28/2022

PART NPL: Sites that are a part of an National Priority List site referred to as the parent site

Agency Version Date: 01/28/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/26/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 703-603-8867
Most Recent Contact: 01/28/2022

PROPOSED NPL: Sites that have been proposed for the National Priority List

Agency Version Date: 01/28/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/26/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 703-603-8867
Most Recent Contact: 01/28/2022

SEMS_FINAL NPL: All Included National Priority List Sites

Agency Version Date: 01/28/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/26/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 703-603-8867
Most Recent Contact: 01/28/2022

SEMS_PROPOSED NPL: All Proposed National Priority List Sites

Agency Version Date: 01/28/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/26/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 703-603-8867
Most Recent Contact: 01/28/2022

STATE- AND TRIBAL - EQUIVALENT CERCLIS

ENVIROSTOR - CA: Department of Toxic Substances Controls

Agency Version Date: 12/23/2021
Agency Update Frequency: Quarterly
Planned Next Contact: 06/16/2022
Agency: Department of Toxic Substances Control
Agency Contact: 916-327-1077
Most Recent Contact: 03/21/2022

HIST TOXIC PITS - CA: Listing of Toxic Pit Cleanup Act sites that are no longer in current agency list.

Agency Version Date: 10/12/2018
Agency Update Frequency: Quarterly
Planned Next Contact: 04/06/2022
Agency: State Water Resources Control Board
Agency Contact: 916-341-5810
Most Recent Contact: 01/10/2022

OIL & GAS CLEANUP - CA: List of SWRCB Oil & Gas Cleanup Sites from GeoTracker Site Cleanup Program database.

Agency Version Date: 01/25/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/22/2022
Agency: California Regional Water Quality Control Board
Agency Contact: 916-341-5791
Most Recent Contact: 01/25/2022

STATE- AND TRIBAL - EQUIVALENT CERCLIS (cont.)

SWRCB CLEANUP - CA: List of SWRCB Cleanups from Geotracker including CAF, Sampling Points, and Projects.

Agency Version Date: 01/25/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/22/2022
Agency: California Regional Water Quality Control Board
Agency Contact: 916-341-5791
Most Recent Contact: 01/25/2022

SWRCB NON_CASE - CA: List of SWRCB Non-Case sites from GeoTracker Site Cleanup Program database.

Agency Version Date: 01/25/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/22/2022
Agency: California Regional Water Quality Control Board
Agency Contact: 916-341-5791
Most Recent Contact: 01/25/2022

TOXIC PITS - CA: Listing of Toxic Pit Cleanup Act sites

Agency Version Date: 01/10/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/06/2022
Agency: State Water Resources Control Board
Agency Contact: 916-341-5810
Most Recent Contact: 01/10/2022

STATE- AND TRIBAL - EQUIVALENT NPL

HIST RESPONSE - CA: List of state response sites with confirmed releases and potential high risk that are no longer in current agency list.

Agency Version Date: 10/19/2017
Agency Update Frequency: Annually
Planned Next Contact: 05/12/2022
Agency: Department of Toxic Substances Control
Agency Contact: 916-327-1077
Most Recent Contact: 02/15/2022

RESPONSE - CA: State response sites with confirmed releases and potential high risk

Agency Version Date: 12/23/2021
Agency Update Frequency: Annually
Planned Next Contact: 06/16/2022
Agency: Department of Toxic Substances Control
Agency Contact: 916-327-1077
Most Recent Contact: 03/21/2022

STATE AND TRIBAL LANDFILL AND/OR SOLID WASTE DISPOSAL SITE LISTS

HIST SWF/LF - CA: List of Solid Waste Information System's solid waste facilities and landfills that is no longer in current agency list.

Agency Version Date: 03/05/2018
Agency Update Frequency: Annually
Planned Next Contact: 05/09/2022
Agency: Department of Resources Recycling and Recovery
Agency Contact: 916-341-6066
Most Recent Contact: 02/10/2022

SWF/LF - CA: Solid Waste Information System's facility listing of solid waste facilities and landfills

Agency Version Date: 03/10/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 06/06/2022
Agency: Department of Resources Recycling and Recovery
Agency Contact: 916-341-6066
Most Recent Contact: 03/10/2022

STATE RCRA GENERATORS LIST

HWG - CA: Hazardous waste generator listing

Agency Version Date: 12/22/2021
Agency Update Frequency: Quarterly
Planned Next Contact: 06/14/2022
Agency: Department of Toxic Substances Control
Agency Contact: N/R
Most Recent Contact: 03/18/2022

STATE RCRA GENERATORS LIST (cont.)

HWG_YOLO COUNTY - CA: Listing of permitted hazardous waste generators

Agency Version Date: 01/21/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/19/2022
Agency: Yolo County Environmental Health
Agency Contact: 530-666-8646
Most Recent Contact: 01/21/2022

STATE AND TRIBAL BROWNFIELD SITES

TRIBAL BROWNFIELDS: Tribal brownfield remediation site listing

Agency Version Date: 02/10/2017
Agency Update Frequency: No Longer Maintained
Planned Next Contact: 06/10/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 855-246-3642
Most Recent Contact: 03/16/2022

STATE AND TRIBAL VOLUNTARY CLEANUP SITES

VCP - CA: Voluntary Cleanup Program remediation sites listing

Agency Version Date: 12/23/2021
Agency Update Frequency: Quarterly
Planned Next Contact: 06/16/2022
Agency: Department of Toxic Substances Control
Agency Contact: 916-322-2861
Most Recent Contact: 03/21/2022

LOCAL BROWNFIELD LISTS

BROWNFIELDS-ACRES: EPA Brownfields Assessment, Cleanup and Redevelopment Exchange System.

Agency Version Date: 09/17/2021
Agency Update Frequency: Quarterly
Planned Next Contact: 06/06/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 855-246-3642
Most Recent Contact: 03/10/2022

FED BROWNFIELDS: Federal brownfield remediation sites

Agency Version Date: 01/24/2022
Agency Update Frequency: Semi Annually
Planned Next Contact: 04/21/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 855-246-3642
Most Recent Contact: 01/24/2022

LOCAL LISTS OF HAZARDOUS WASTE / CONTAMINATED SITES

FED CDL: The U.S. Department of Justice listing of clandestine drug lab locations

Agency Version Date: 01/12/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/11/2022
Agency: U.S. Department of Justice
Agency Contact: 202-307-7610
Most Recent Contact: 01/12/2022

US HIST CDL: The U.S. Department of Justice historical listing of clandestine drug lab locations

Agency Version Date: 08/05/2019
Agency Update Frequency: Quarterly
Planned Next Contact: 05/16/2022
Agency: U.S. Department of Justice
Agency Contact: 202-307-7610
Most Recent Contact: 02/16/2022

CALARP_KERN COUNTY - CA: Kern County hazardous material permitted facilities

Agency Version Date: 02/24/2022
Agency Update Frequency: Varies
Planned Next Contact: 05/23/2022
Agency: County of Kern Public Health Services Department
Agency Contact: 661-862-8740
Most Recent Contact: 02/24/2022

LOCAL LISTS OF HAZARDOUS WASTE / CONTAMINATED SITES (cont.)

CASE LIST_SAN DIEGO COUNTY - CA: San Diego county listing of hazardous chemical releases

Agency Version Date: 01/25/2022
Agency Update Frequency: Varies
Planned Next Contact: 04/22/2022
Agency: County of San Diego Department of Environmental Health
Agency Contact: 619-338-2259
Most Recent Contact: 01/25/2022

CDL - CA: Listing of Meth and clandestine drug labs maintained by the Department of Toxic Substances Control

Agency Version Date: 07/30/2020
Agency Update Frequency: Varies
Planned Next Contact: 04/05/2022
Agency: Department of Toxic Substances Control
Agency Contact: 916-322-2861
Most Recent Contact: 01/07/2022

CORRECTIVE ACTION_RIVERSIDE COUNTY - CA: Riverside county corrective action sites list

Agency Version Date: 11/15/2017
Agency Update Frequency: No Longer Maintained
Planned Next Contact: 06/09/2022
Agency: Riverside County Environmental Health
Agency Contact: 888-722-4234
Most Recent Contact: 03/15/2022

CS_NAPA COUNTY - CA: Napa county listing of Contaminated sites

Agency Version Date: 01/28/2022
Agency Update Frequency: Varies
Planned Next Contact: 04/26/2022
Agency: Napa County Department of Environmental Management
Agency Contact: 707-253-4471
Most Recent Contact: 01/28/2022

CS_PLACER COUNTY - CA: Placer county cleanup sites listing

Agency Version Date: 01/25/2022
Agency Update Frequency: Semi Annually
Planned Next Contact: 04/20/2022
Agency: Placer County Environmental Health
Agency Contact: 530-745-2350
Most Recent Contact: 01/25/2022

SCH - CA: Listing of possible hazardous material contamination sites on existing school properties

Agency Version Date: 01/25/2022
Agency Update Frequency: Varies
Planned Next Contact: 04/22/2022
Agency: Department of Toxic Substances Control
Agency Contact: 916-322-2861
Most Recent Contact: 01/25/2022

SITE LIST_CONTRA COSTA COUNTY - CA: Listing of underground tank hazardous waste generator and business plan sites in Contra Costa County

Agency Version Date: 11/10/2021
Agency Update Frequency: Varies
Planned Next Contact: 05/03/2022
Agency: Contra Costa Health Services Department
Agency Contact: 925-335-3200
Most Recent Contact: 02/04/2022

TOXIC SITE_SACRAMENTO COUNTY - CA: Sacramento County listing of historical sites where unauthorized releases of potentially hazardous materials have occurred

Agency Version Date: 08/24/2021
Agency Update Frequency: No Longer Maintained
Planned Next Contact: 05/12/2022
Agency: Sacramento County Environmental Management
Agency Contact: 916-875-8550
Most Recent Contact: 02/15/2022

RECORDS OF EMERGENCY RELEASE REPORTS

HMIRS (DOT): Hazardous Material spills reported by the Department of Transportation

Agency Version Date: 12/22/2021
Agency Update Frequency: Varies
Planned Next Contact: 06/14/2022
Agency: U.S. Department of Transportation
Agency Contact: (202) 366-4996
Most Recent Contact: 03/18/2022

RECORDS OF EMERGENCY RELEASE REPORTS (cont.)

CHMIRS - CA: California Hazardous Material Incident Reporting System's reported accidental hazardous material incidents releases or spills

Agency Version Date: 01/11/2022
Agency Update Frequency: Varies
Planned Next Contact: 04/08/2022
Agency: California Emergency Management Agency
Agency Contact: 916-845-8275
Most Recent Contact: 01/11/2022

HIST CHMIRS - CA: California Hazardous Material Incident Reporting System's reported accidental hazardous material incidents releases or spills

Agency Version Date: 04/06/2017
Agency Update Frequency: Quarterly
Planned Next Contact: 05/09/2022
Agency: California Emergency Management Agency
Agency Contact: 916-845-8275
Most Recent Contact: 02/09/2022

INDUSTRIAL CLEANUP_ORANGE COUNTY - CA: Petroleum and non-petroleum industrial spills

Agency Version Date: 02/23/2022
Agency Update Frequency: Annually
Planned Next Contact: 05/23/2022
Agency: Orange County Health Care Agency
Agency Contact: 714-433-6000
Most Recent Contact: 02/23/2022

SML_LOS ANGELES COUNTY - CA: Listing of all Emergency Response session spills

Agency Version Date: 07/12/2017
Agency Update Frequency: Quarterly
Planned Next Contact: 04/22/2022
Agency: Los Angeles Department of Public Health
Agency Contact: 323-890-7808
Most Recent Contact: 01/26/2022

LOCAL LAND RECORDS

LIENS 2: Comprehensive Environmental Response Compensation and Liability Act sites with liens

Agency Version Date: 05/11/2017
Agency Update Frequency: No Longer Maintained
Planned Next Contact: 06/13/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 800-424-9346
Most Recent Contact: 03/16/2022

DEED - CA: The Department of Toxic Substances Control's listing of property locations with Deed restrictions

Agency Version Date: 01/27/2022
Agency Update Frequency: Semi Annually
Planned Next Contact: 04/25/2022
Agency: Department of Toxic Substances Control
Agency Contact: 916-341-5791
Most Recent Contact: 01/27/2022

HIST LIENS - CA: The Department of Toxic Substances Control's listing of property locations with environmental liens that is no longer in current agency list.

Agency Version Date: 12/04/2018
Agency Update Frequency: Annually
Planned Next Contact: 05/06/2022
Agency: Department of Toxic Substances Control
Agency Contact: 916-322-2861
Most Recent Contact: 02/08/2022

LIENS - CA: The Department of Toxic Substances Control's listing of property locations with environmental liens

Agency Version Date: 03/09/2022
Agency Update Frequency: Varies
Planned Next Contact: 06/06/2022
Agency: Department of Toxic Substances Control
Agency Contact: 916-322-2861
Most Recent Contact: 03/09/2022

LOCAL LISTS OF LANDFILL / SOLID WASTE DISPOSAL SITES

HIST INDIAN ODI R8: List of Region 8 Indian land open dump inventory sites maintained within the STARS program that is no longer in current agency list.

Agency Version Date: 11/12/2018
Agency Update Frequency: Annually
Planned Next Contact: 04/07/2022
Agency: Indian Health Service
Agency Contact: 855-246-3642
Most Recent Contact: 01/11/2022

INDIAN ODI R8: Region 8 Indian land open dump inventory sites maintained within the STARS program

Agency Version Date: 01/28/2022
Agency Update Frequency: Varies
Planned Next Contact: 04/26/2022
Agency: Indian Health Service
Agency Contact: 855-246-3642
Most Recent Contact: 01/28/2022

ODI: Open dump inventory sites

Agency Version Date: 10/03/2017
Agency Update Frequency: No Update
Planned Next Contact: 05/10/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 855-246-3642
Most Recent Contact: 02/11/2022

TRIBAL ODI: Indian land open dump inventory for all regions

Agency Version Date: 02/21/2022
Agency Update Frequency: Varies
Planned Next Contact: 05/19/2022
Agency: Indian Health Service
Agency Contact: 301-443-3593
Most Recent Contact: 02/21/2022

HAULERS - CA: Waste Tire Manifest Program Hauler Registration listing

Agency Version Date: 12/29/2021
Agency Update Frequency: Varies
Planned Next Contact: 03/25/2022
Agency: California Department of Resources Recycling and Recovery (CalRecycle)
Agency Contact: 916-341-6066
Most Recent Contact: 12/29/2021

LF_SAN DIEGO COUNTY - CA: San Diego county landfill listing

Agency Version Date: 01/25/2022
Agency Update Frequency: Varies
Planned Next Contact: 04/22/2022
Agency: County of San Diego Department of Environmental Health
Agency Contact: 858-694-2801
Most Recent Contact: 01/25/2022

SWF_LOS ANGELES COUNTY - CA: Listing of Los Angeles County solid waste facilities

Agency Version Date: 02/23/2022
Agency Update Frequency: Varies
Planned Next Contact: 05/20/2022
Agency: LA County Department of Public Works
Agency Contact: 800-320-1771
Most Recent Contact: 02/23/2022

SWRCY - CA: Listing of facilities which perform recycled material processing activities

Agency Version Date: 02/15/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 05/12/2022
Agency: California Department of Resources Recycling and Recovery (CalRecycle)
Agency Contact: 916-341-6066
Most Recent Contact: 02/15/2022

OTHER ASCERTAINABLE RECORDS

AFS: Air Facility Systems Quarterly Extract

Agency Version Date: 01/31/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/28/2022
Agency: Environmental Protection Agency
Agency Contact: (202) 566-1667
Most Recent Contact: 01/31/2022

OTHER ASCERTAINABLE RECORDS (cont.)

ALT FUELING: Alternative Fueling Stations by fuel type.

Agency Version Date: 12/29/2021
Agency Update Frequency: Quarterly
Planned Next Contact: 03/25/2022
Agency: U.S. Department of Energy
Agency Contact: N/R
Most Recent Contact: 12/29/2021

BRS: Reporting of hazardous waste generation and management from large quantity generators

Agency Version Date: 12/30/2021
Agency Update Frequency: Biennial
Planned Next Contact: 03/28/2022
Agency: Environmental Protection Agency
Agency Contact: (202) 566-1667
Most Recent Contact: 12/30/2021

CDC HAZDAT: The Agency for Toxic Substances and Disease Registry's Hazardous Substance Release/Health Effects Database.

Agency Version Date: 01/28/2022
Agency Update Frequency: Varies
Planned Next Contact: 04/26/2022
Agency: Agency for Toxic Substances and Disease Registry
Agency Contact: 770-488-6399
Most Recent Contact: 01/28/2022

COAL ASH DOE: List of existing and planned generators with 1 megawatt or greater of combined capacity that are utilizing coal ash impoundments.

Agency Version Date: 09/29/2021
Agency Update Frequency: Varies
Planned Next Contact: 03/22/2022
Agency: Department of Energy
Agency Contact: (202) 586-8800
Most Recent Contact: 12/24/2021

COAL ASH EPA: Coal Combustion Residues Surface Impoundments List

Agency Version Date: 02/18/2021
Agency Update Frequency: Varies
Planned Next Contact: 04/29/2022
Agency: Environmental Protection Agency
Agency Contact: (202) 566-1667
Most Recent Contact: 02/01/2022

COAL GAS: Manufactured Gas Plant locations

Agency Version Date: 01/07/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/05/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 855-246-3642
Most Recent Contact: 01/07/2022

COLLEGES: List of major Universities & Colleges

Agency Version Date: 02/08/2022
Agency Update Frequency: Varies
Planned Next Contact: 04/15/2022
Agency: DHS Homeland Infrastructure Foundation
Agency Contact: N/R
Most Recent Contact: 01/18/2022

COLLEGES 2: List of Universities & Colleges

Agency Version Date: 02/08/2022
Agency Update Frequency: Varies
Planned Next Contact: 04/18/2022
Agency: DHS Homeland Infrastructure Foundation
Agency Contact: N/R
Most Recent Contact: 01/19/2022

CONSENT (DECREES): Legal decisions regarding responsibility for Superfund locations

Agency Version Date: 01/28/2022
Agency Update Frequency: Varies
Planned Next Contact: 04/26/2022
Agency: Environmental Protection Agency
Agency Contact: (800) 424-9346
Most Recent Contact: 01/28/2022

OTHER ASCERTAINABLE RECORDS (cont.)

CORRECTIVE ACTIONS_2020: In 2009 the EPA created the 2020 Corrective Action Baseline list of contaminated or potentially contaminated sites with a cleanup goal to complete 95% by the year 2020. The names on the list indicate the facility owners who may or may not have caused the contamination.

Agency Version Date: 12/21/2018
Agency Update Frequency: No Longer Maintained
Planned Next Contact: 04/19/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: N/R
Most Recent Contact: 01/21/2022

DEBRIS EPA LF: EPA list of designated landfill facilities for the safe disposal of disaster debris.

Agency Version Date: 01/14/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/12/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 855-246-3642
Most Recent Contact: 01/14/2022

DEBRIS EPA SWRCY: EPA list of facilities for the safe recovery, recycling, and disposal of disaster debris.

Agency Version Date: 01/14/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/12/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 855-246-3642
Most Recent Contact: 01/14/2022

DOD: Department of Defense sites from the Protected Areas Database (PAD-US)

Agency Version Date: 01/28/2022
Agency Update Frequency: Varies
Planned Next Contact: 04/26/2022
Agency: United States Geologic Survey (USGS)
Agency Contact: 1-888-275-8747
Most Recent Contact: 01/28/2022

DOT OPS: Incident Data Report

Agency Version Date: 02/14/2022
Agency Update Frequency: Varies
Planned Next Contact: 05/12/2022
Agency: U.S. Department of Transportation
Agency Contact: (202) 366-4996
Most Recent Contact: 02/14/2022

ECHO: ECHO is EPA Enforcement and Compliance History Online website to search for facilities in your community to assess their compliance with environmental regulations related to CAA, CWA, RCRA, & SDWA.

Agency Version Date: 12/24/2021
Agency Update Frequency: Quarterly
Planned Next Contact: 03/22/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 202-566-1667
Most Recent Contact: 12/24/2021

ENOI: The Electronic Notice of Intent (eNOI) database contains construction sites and industrial facilities that submit permit requests to EPA for Construction General Permits (CGP) and Multi-Sector General Permits (MSGP).

Agency Version Date: 03/19/2021
Agency Update Frequency: Quarterly
Planned Next Contact: 06/02/2022
Agency: Environmental Protection Agency
Agency Contact: (202) 566-1667
Most Recent Contact: 03/08/2022

EPA FUELS: List of companies and facilities registered to participate in EPA Fuel Programs under Title 40 CFR Part 80.

Agency Version Date: 02/04/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 05/03/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: (202) 564-2307
Most Recent Contact: 02/04/2022

EPA OSC: Listing of oil spills and hazardous substance release sites requiring EPA On-Site Coordinators.

Agency Version Date: 09/24/2021
Agency Update Frequency: Quarterly
Planned Next Contact: 06/13/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: (202) 564-2307
Most Recent Contact: 03/17/2022

OTHER ASCERTAINABLE RECORDS (cont.)

EPA WATCH: The EPA Watch List was used to facilitate dialogue between EPA, state and local environmental agencies on enforcement matters relating to facilities with alleged violations identified as either significant or high priority. EPA maintained the lists from 2011 - 2013.

Agency Version Date: 02/09/2018
Agency Update Frequency: No Longer Maintained
Planned Next Contact: 06/13/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: (202) 564-2307
Most Recent Contact: 03/16/2022

FA HWF: Hazardous Waste Facilities with Financial Assurance

Agency Version Date: 01/06/2022
Agency Update Frequency: Varies
Planned Next Contact: 04/04/2022
Agency: Environmental Protection Agency
Agency Contact: (800) 424-9346
Most Recent Contact: 01/06/2022

FEDLAND: Federal Lands from the Protected Areas Database (PAD-US)

Agency Version Date: 01/28/2022
Agency Update Frequency: Varies
Planned Next Contact: 04/26/2022
Agency: United States Geologic Survey (USGS)
Agency Contact: 1-888-275-8747
Most Recent Contact: 01/28/2022

FRS: Facility Registry Systems

Agency Version Date: 02/09/2022
Agency Update Frequency: Varies
Planned Next Contact: 05/06/2022
Agency: Environmental Protection Agency
Agency Contact: (202) 566-1667
Most Recent Contact: 02/09/2022

FTTS: Tracking of administrative and enforcement activities related to FIFRA/TSCA

Agency Version Date: 04/06/2013
Agency Update Frequency: No Longer Maintained
Planned Next Contact: 04/01/2022
Agency: Environmental Protection Agency
Agency Contact: (202) 564-2280
Most Recent Contact: 01/05/2022

FTTS INSP: Tracking of inspections related to FIFRA/TSCA

Agency Version Date: 05/08/2017
Agency Update Frequency: No Longer Maintained
Planned Next Contact: 03/25/2022
Agency: Environmental Protection Agency
Agency Contact: (202) 564-2280
Most Recent Contact: 12/30/2021

FUDS: Defense sites that require cleanup

Agency Version Date: 02/07/2022
Agency Update Frequency: Varies
Planned Next Contact: 05/05/2022
Agency: US Army Corps of Engineering
Agency Contact: (202) 761-0011
Most Recent Contact: 02/07/2022

HIST AFS: List of Air Facility Systems Quarterly Extract that are no longer in current agency list.

Agency Version Date: 06/14/2019
Agency Update Frequency: Quarterly
Planned Next Contact: 06/10/2022
Agency: Environmental Protection Agency
Agency Contact: (202) 566-1667
Most Recent Contact: 03/16/2022

HIST AFS 2: List of Air Facility Systems Quarterly Extract that are no longer in current agency list.

Agency Version Date: 11/26/2018
Agency Update Frequency: Quarterly
Planned Next Contact: 04/14/2022
Agency: Environmental Protection Agency
Agency Contact: (202) 566-1667
Most Recent Contact: 01/18/2022

OTHER ASCERTAINABLE RECORDS (cont.)

HIST DOD: Department of Defense historical sites

Agency Version Date: 01/28/2022
Agency Update Frequency: No Longer Maintained
Planned Next Contact: 04/26/2022
Agency: Environmental Protection Agency
Agency Contact: (800) 424-9346
Most Recent Contact: 01/28/2022

HIST LEAD_SMELTER: List of former lead smelter sites that is no longer in current agency list.

Agency Version Date: 12/12/2018
Agency Update Frequency: Annually
Planned Next Contact: 04/01/2022
Agency: Environmental Protection Agency
Agency Contact: (202) 566-1667
Most Recent Contact: 01/05/2022

HIST MLTS: List of sites in possession/use of radioactive materials regulated by NRC that is no longer in current agency list.

Agency Version Date: 07/13/2016
Agency Update Frequency: Annually
Planned Next Contact: 04/11/2022
Agency: Nuclear Regulatory Commission
Agency Contact: (800) 397-4209
Most Recent Contact: 01/12/2022

HIST PCB TRANS: List of PCB Disposal Facilities that are no longer in current agency list.

Agency Version Date: 01/18/2018
Agency Update Frequency: No Update
Planned Next Contact: 05/03/2022
Agency: Environmental Protection Agency
Agency Contact: (703) 308-8404
Most Recent Contact: 02/04/2022

HIST PCS ENF: List of permitted facilities to discharge wastewater (Federal equivalent to NPDES) that are no longer in current agency list.

Agency Version Date: 12/08/2018
Agency Update Frequency: Annually
Planned Next Contact: 05/17/2022
Agency: Environmental Protection Agency
Agency Contact: (202) 564-6582
Most Recent Contact: 02/18/2022

HIST PCS FACILITY: List of Permitted facilities to discharge wastewater (Federal equivalent to NPDES) that are no longer in current agency list.

Agency Version Date: 12/18/2018
Agency Update Frequency: Annually
Planned Next Contact: 05/17/2022
Agency: Environmental Protection Agency
Agency Contact: (202) 564-6582
Most Recent Contact: 02/18/2022

HIST SSTS: List of tracking of facilities who produce pesticides and their quantity that are no longer in current agency list.

Agency Version Date: 02/13/2019
Agency Update Frequency: Annually
Planned Next Contact: 05/06/2022
Agency: Environmental Protection Agency
Agency Contact: (202) 566-1667
Most Recent Contact: 02/08/2022

HOSPITALS: List of major Hospitals

Agency Version Date: 02/08/2022
Agency Update Frequency: Varies
Planned Next Contact: 04/15/2022
Agency: DHS Homeland Infrastructure Foundation
Agency Contact: N/R
Most Recent Contact: 01/18/2022

HWC DOCKET: Listing of Federal facilities which are managing or have managed hazardous waste; or have had a release of hazardous waste.

Agency Version Date: 11/09/2021
Agency Update Frequency: Quarterly
Planned Next Contact: 05/03/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: (202) 564-2307
Most Recent Contact: 02/03/2022

OTHER ASCERTAINABLE RECORDS (cont.)

ICIS: Comprised of all Federal Administrative and Judicial enforcement information [intended to replace PCS] by tracking enforcement and compliance information (also contains what used to be known as FFTS)

Agency Version Date: 12/28/2021
Agency Update Frequency: Varies
Planned Next Contact: 03/25/2022
Agency: Environmental Protection Agency
Agency Contact: (202) 566-1667
Most Recent Contact: 12/28/2021

INACTIVE PCS: Inactive Permitted facilities to discharge wastewater

Agency Version Date: 12/28/2021
Agency Update Frequency: Varies
Planned Next Contact: 03/25/2022
Agency: Environmental Protection Agency
Agency Contact: (202) 564-6582
Most Recent Contact: 12/28/2021

INDIAN RESERVATION: American Indian Lands from the Protected Areas Database (PAD-US)

Agency Version Date: 01/28/2022
Agency Update Frequency: Varies
Planned Next Contact: 04/26/2022
Agency: United States Geologic Survey (USGS)
Agency Contact: 1-888-275-8747
Most Recent Contact: 01/28/2022

LUCIS: Land Use Control Information Systems

Agency Version Date: 12/21/2021
Agency Update Frequency: Quarterly
Planned Next Contact: 06/16/2022
Agency: Department of the Navy: BRAC PMO
Agency Contact: (619) 532-0900
Most Recent Contact: 03/18/2022

LUCIS 2: Land Use Control Information Systems

Agency Version Date: 01/17/2018
Agency Update Frequency: No Longer Maintained
Planned Next Contact: 05/03/2022
Agency: Department of the Navy: BRAC PMO
Agency Contact: (619) 532-0900
Most Recent Contact: 02/04/2022

MANIFEST EPA: EPA Hazardous Waste Electronic Manifest System (e-Manifest)

Agency Version Date: 11/12/2021
Agency Update Frequency: Quarterly
Planned Next Contact: 05/06/2022
Agency: Environmental Protection Agency
Agency Contact: (202) 566-1667
Most Recent Contact: 02/08/2022

MINE OPERATIONS: Mine plants and operations for commodities monitored by the National Minerals Information Center of the USGS

Agency Version Date: 02/11/2022
Agency Update Frequency: Varies
Planned Next Contact: 05/10/2022
Agency: USGS Mineral Resources Program
Agency Contact: (703) 648-5953
Most Recent Contact: 02/11/2022

MINES: Mines Master Index Files

Agency Version Date: 12/29/2021
Agency Update Frequency: Varies
Planned Next Contact: 03/28/2022
Agency: Department of Labor
Agency Contact: (202) 693-9400
Most Recent Contact: 12/29/2021

MINES USGS: Listing of all active mines and mineral plants in 2003

Agency Version Date: 02/11/2022
Agency Update Frequency: Varies
Planned Next Contact: 05/10/2022
Agency: USGS Mineral Resources Program
Agency Contact: (703) 648-5953
Most Recent Contact: 02/11/2022

OTHER ASCERTAINABLE RECORDS (cont.)

MLTS: Sites in possession/use of radioactive materials regulated by NRC

Agency Version Date: 01/21/2022
Agency Update Frequency: Varies
Planned Next Contact: 04/19/2022
Agency: Nuclear Regulatory Commission
Agency Contact: (800) 397-4209
Most Recent Contact: 01/21/2022

NPL AOC: Areas of Concern related to NPL remediation sites

Agency Version Date: 01/28/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/26/2022
Agency: Environmental Protection Agency
Agency Contact: N/R
Most Recent Contact: 01/28/2022

NPL LIENS: National Priority List of sites with Liens

Agency Version Date: 01/28/2022
Agency Update Frequency: Varies
Planned Next Contact: 04/26/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 703-603-8867
Most Recent Contact: 01/28/2022

NURSING HOMES: List of Nursing Homes

Agency Version Date: 01/14/2022
Agency Update Frequency: Varies
Planned Next Contact: 04/12/2022
Agency: DHS Homeland Infrastructure Foundation
Agency Contact: N/R
Most Recent Contact: 01/14/2022

OSHA: OSHA's listing of inspections violations and fatality information

Agency Version Date: 12/27/2021
Agency Update Frequency: Varies
Planned Next Contact: 03/24/2022
Agency: Occupational Safety & Health Administration
Agency Contact: 800-321-6742
Most Recent Contact: 12/27/2021

PADS: Listing of generators transporters commercial store/ brokers and disposers of PCB

Agency Version Date: 01/28/2022
Agency Update Frequency: Varies
Planned Next Contact: 04/26/2022
Agency: Environmental Protection Agency
Agency Contact: (703) 308-8404
Most Recent Contact: 01/28/2022

PCB TRANSFORMER: Disposal and Storage of Polychlorinated Biphenyl (PCB) Waste

Agency Version Date: 02/11/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 05/10/2022
Agency: Environmental Protection Agency
Agency Contact: (703) 308-8404
Most Recent Contact: 02/11/2022

PCS ENF: Permitted facilities to discharge wastewater (Federal equivalent to NPDES)

Agency Version Date: 12/28/2021
Agency Update Frequency: Varies
Planned Next Contact: 03/25/2022
Agency: Environmental Protection Agency
Agency Contact: (202) 564-6582
Most Recent Contact: 12/28/2021

PCS FACILITY: Permitted facilities to discharge wastewater (Federal equivalent to NPDES)

Agency Version Date: 12/28/2021
Agency Update Frequency: Varies
Planned Next Contact: 03/25/2022
Agency: Environmental Protection Agency
Agency Contact: (202) 564-6582
Most Recent Contact: 12/28/2021

PFAS NPL: List of NPL sites with PFAS or PFOA contamination

Agency Version Date: 01/05/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/01/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 703-603-8867
Most Recent Contact: 01/05/2022

OTHER ASCERTAINABLE RECORDS (cont.)

PFAS TRIS: List of TRIS sites where PFAS or PFOA are used/manufactured/ treated/ transported/released.

Agency Version Date: 12/28/2021
Agency Update Frequency: Varies
Planned Next Contact: 03/25/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: (202) 566-1667
Most Recent Contact: 12/28/2021

PFAS UCMR3: List of PWS wells sampled for Unregulated Contaminant Monitoring Rule (UCMR)

Agency Version Date: 03/08/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 06/02/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 703-603-8867
Most Recent Contact: 03/08/2022

RAATS: Listing of major violators with enforcement actions issued under RCRA. Includes administrative and civil actions filed by the EPA. This dataset is no longer maintained.

Agency Version Date: 09/23/2019
Agency Update Frequency: Varies
Planned Next Contact: 04/18/2022
Agency: Environmental Protection Agency
Agency Contact: (202) 566-1667
Most Recent Contact: 01/20/2022

RADINFO: EPA regulated facilities with radiation and radioactive materials

Agency Version Date: 08/01/2019
Agency Update Frequency: Varies
Planned Next Contact: 04/06/2022
Agency: Environmental Protection Agency
Agency Contact: (202) 566-1667
Most Recent Contact: 01/10/2022

RMP: Facilities producing/handling/ process/ distribute/ store specific chemicals report plans required by the Clean Air Act

Agency Version Date: 01/04/2022
Agency Update Frequency: Monthly
Planned Next Contact: 04/01/2022
Agency: Environmental Protection Agency
Agency Contact: (202) 564-2534
Most Recent Contact: 01/04/2022

ROD: Permanent remedy at an NPL site

Agency Version Date: 01/28/2022
Agency Update Frequency: Varies
Planned Next Contact: 04/26/2022
Agency: Environmental Protection Agency
Agency Contact: (800) 424-9346
Most Recent Contact: 01/28/2022

SCHOOLS PRIVATE: List of Private Schools

Agency Version Date: 02/08/2022
Agency Update Frequency: Varies
Planned Next Contact: 04/15/2022
Agency: DHS Homeland Infrastructure Foundation
Agency Contact: N/R
Most Recent Contact: 01/18/2022

SCHOOLS PUBLIC: List of Public Schools

Agency Version Date: 02/08/2022
Agency Update Frequency: Varies
Planned Next Contact: 04/15/2022
Agency: DHS Homeland Infrastructure Foundation
Agency Contact: N/R
Most Recent Contact: 01/18/2022

SCRD DRYCLEANERS: State Coalition for Remediation of Drycleaners

Agency Version Date: 09/09/2021
Agency Update Frequency: No Update
Planned Next Contact: 05/27/2022
Agency: Environmental Protection Agency
Agency Contact: (202) 566-1667
Most Recent Contact: 03/02/2022

OTHER ASCERTAINABLE RECORDS (cont.)

SEMS_SMELTER: This report includes sites that have smelting-related, or potentially smelting-related, indicators in the SEMS database. The report includes information on the site location as well as contaminants of concern.

Agency Version Date: 01/28/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/26/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 703-603-8867
Most Recent Contact: 01/28/2022

SSTS: Tracking of facilities who produce pesticides and their quantity

Agency Version Date: 12/10/2021
Agency Update Frequency: Annually
Planned Next Contact: 06/02/2022
Agency: Environmental Protection Agency
Agency Contact: (202) 566-1667
Most Recent Contact: 03/08/2022

STORMWATER: Permitted storm water sites

Agency Version Date: 12/21/2021
Agency Update Frequency: Varies
Planned Next Contact: 06/14/2022
Agency: Environmental Protection Agency
Agency Contact: (202) 566-1667
Most Recent Contact: 03/18/2022

TOSCA-PLANT: Plants controlled by the Toxic Substance Control Act

Agency Version Date: 12/16/2021
Agency Update Frequency: Varies
Planned Next Contact: 06/09/2022
Agency: Environmental Protection Agency
Agency Contact: (202) 566-1667
Most Recent Contact: 03/14/2022

TRIS: Information regarding toxic chemicals that are being used/manufactured/ treated/ transported/released into the environment

Agency Version Date: 12/28/2021
Agency Update Frequency: Varies
Planned Next Contact: 03/25/2022
Agency: Environmental Protection Agency
Agency Contact: (202) 566-1667
Most Recent Contact: 12/28/2021

UMTRA: Uranium Recovery Sites

Agency Version Date: 07/08/2021
Agency Update Frequency: Varies
Planned Next Contact: 03/25/2022
Agency: United States Nuclear Regulatory Commission
Agency Contact: (301) 415-8200
Most Recent Contact: 12/29/2021

VAPOR: EPA Vapor Intrusion Database

Agency Version Date: 03/19/2021
Agency Update Frequency: Varies
Planned Next Contact: 06/03/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 855-246-3642
Most Recent Contact: 03/08/2022

AOC_SAN GABRIEL VALLEY - CA: San Gabriel Valley Superfund sites

Agency Version Date: 01/28/2022
Agency Update Frequency: Varies
Planned Next Contact: 04/26/2022
Agency: U.S. Environmental Protection Agency
Agency Contact: 415-972-3181
Most Recent Contact: 01/28/2022

BOND EXPENDITURE PLAN - CA: Hazardous Substance Cleanup Bond Act of 1984 Article 7.5 of Health and Safety Code 25385 listing of orphan sites

Agency Version Date: 12/23/2021
Agency Update Frequency: Quarterly
Planned Next Contact: 06/16/2022
Agency: Department of Toxic Substance Control
Agency Contact: 916-322-2861
Most Recent Contact: 03/21/2022

OTHER ASCERTAINABLE RECORDS (cont.)

BP HW OUT_VENTURA COUNTY - CA: Ventura County Business Plan Hazardous Waste Producers and Operating Underground Tanks

Agency Version Date: 02/08/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 05/06/2022
Agency: Ventura County Environmental Health Division
Agency Contact: 805-654-2815
Most Recent Contact: 02/08/2022

BUSINESS INVENTORY_SAN MATEO COUNTY - CA: San Mateo County listing of underground storage tanks, hazardous materials, business plans, and hazardous waste generators

Agency Version Date: 01/05/2022
Agency Update Frequency: Annually
Planned Next Contact: 04/04/2022
Agency: San Mateo County Environmental Health Services Division
Agency Contact: 650-372-6200
Most Recent Contact: 01/05/2022

CALEPA SITES - CA: CalEPA Regulated Sites from the Certified Unified Program Agencies (CUPA).

Agency Version Date: 12/31/2021
Agency Update Frequency: Quarterly
Planned Next Contact: 03/29/2022
Agency: California Environmental Protection Agency Unified Program Section
Agency Contact: 916-327-5092
Most Recent Contact: 12/31/2021

CIWQS - CA: California Integrated Water Quality System database facilities listing which includes owner information, violations, inspections, and other regulatory matters

Agency Version Date: 12/21/2021
Agency Update Frequency: Varies
Planned Next Contact: 06/14/2022
Agency: CA State Water Resources Control Board
Agency Contact: 916-341-5791
Most Recent Contact: 03/18/2022

CIWQS 2 - CA: California Integrated Water Quality System database facilities listing which includer owner information violations inspections and other regulatory matters

Agency Version Date: 01/10/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/06/2022
Agency: CA State Water Resources Control Board
Agency Contact: 916-341-5791
Most Recent Contact: 01/10/2022

CORTESE - CA: Compliance document used in providing information about the location of hazardous material release sites utilized by the state local agencies and developers

Agency Version Date: 12/23/2021
Agency Update Frequency: Quarterly
Planned Next Contact: 06/16/2022
Agency: Department of Toxic Substance Control
Agency Contact: 916-322-2861
Most Recent Contact: 03/21/2022

CUPA_BUTTE COUNTY - CA: Listing of the Butte County Certified Unified Program Agency`s hazardous material program sites

Agency Version Date: 03/19/2018
Agency Update Frequency: No Longer Maintained
Planned Next Contact: 05/23/2022
Agency: Butte County Environmental Health
Agency Contact: 530.538.7281
Most Recent Contact: 02/23/2022

CUPA_FRESNO COUNTY - CA: Listing of the Fresno County Certified Unified Program Agency's hazardous material program sites

Agency Version Date: 12/29/2021
Agency Update Frequency: Quarterly
Planned Next Contact: 03/25/2022
Agency: Fresno County Department of Public Health
Agency Contact: 559-600-3271
Most Recent Contact: 12/29/2021

CUPA_PLACER COUNTY - CA: Listing of the Placer County Certified Unified Program Agency's hazardous material program sites

Agency Version Date: 01/25/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/20/2022
Agency: Placer County Environmental Health
Agency Contact: 530-745-2350
Most Recent Contact: 01/25/2022

OTHER ASCERTAINABLE RECORDS (cont.)

DAYCARE - CA: List of daycare locations

Agency Version Date: 01/18/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/15/2022
Agency: California Department of Social Services
Agency Contact: 916-651-6040
Most Recent Contact: 01/18/2022

DRYCLEANERS - CA: Listing of drycleaning facilities

Agency Version Date: 09/09/2014
Agency Update Frequency: Quarterly
Planned Next Contact: 06/14/2022
Agency: California EPA Air Resources Board
Agency Contact: 916-324-3013
Most Recent Contact: 03/18/2022

DRYCLEANERS_AMADOR COUNTY - CA: Listing of drycleaning facilities in Amador County

Agency Version Date: 11/02/2016
Agency Update Frequency: Varies
Planned Next Contact: 06/03/2022
Agency: Amador County APCD
Agency Contact: (209) 223-6439
Most Recent Contact: 03/08/2022

DRYCLEANERS_ANTELOPE VALLEY - CA: Listing of drycleaning facilities in Antelope Valley

Agency Version Date: 02/11/2022
Agency Update Frequency: Varies
Planned Next Contact: 05/09/2022
Agency: Antelope Valley AQMD
Agency Contact: 661-723-8070
Most Recent Contact: 02/11/2022

DRYCLEANERS_BAY AREA - CA: Listing of drycleaning facilities in Bay Area

Agency Version Date: 07/01/2021
Agency Update Frequency: Quarterly
Planned Next Contact: 06/15/2022
Agency: Bay Area AQMD
Agency Contact: 415-749-4784
Most Recent Contact: 03/17/2022

DRYCLEANERS_BUTTE COUNTY - CA: Listing of drycleaning facilities in Butte County

Agency Version Date: 12/11/2019
Agency Update Frequency: Semi Annually
Planned Next Contact: 04/20/2022
Agency: Butte County AQMD
Agency Contact: 530-332-9400 ext. 107
Most Recent Contact: 01/24/2022

DRYCLEANERS_CALAVERAS COUNTY - CA: Listing of drycleaning facilities in Calaveras County

Agency Version Date: 11/19/2015
Agency Update Frequency: Varies
Planned Next Contact: 04/18/2022
Agency: Calaveras County APCD
Agency Contact: 209-754-6504
Most Recent Contact: 01/20/2022

DRYCLEANERS_COLUSA COUNTY - CA: Listing of drycleaning facilities in Colusa County

Agency Version Date: 09/08/2014
Agency Update Frequency: Quarterly
Planned Next Contact: 04/21/2022
Agency: Colusa County APCD
Agency Contact: 530-458-0590
Most Recent Contact: 01/25/2022

DRYCLEANERS_EASTERN KERN COUNTY - CA: Listing of drycleaning facilities in Eastern Kern County

Agency Version Date: 10/29/2021
Agency Update Frequency: Varies
Planned Next Contact: 04/21/2022
Agency: Eastern Kern County APCD
Agency Contact: 661-862-5250
Most Recent Contact: 01/25/2022

DRYCLEANERS_EL DORADO COUNTY - CA: Listing of drycleaning facilities in El Dorado County

Agency Version Date: 03/18/2016
Agency Update Frequency: Varies
Planned Next Contact: 04/21/2022
Agency: El Dorado County AQMD
Agency Contact: 530-621-7503
Most Recent Contact: 01/25/2022

OTHER ASCERTAINABLE RECORDS (cont.)

DRYCLEANERS_FEATHER RIVER - CA: Listing of drycleaning facilities in Feather River

Agency Version Date: 09/24/2021
Agency Update Frequency: Varies
Planned Next Contact: 06/14/2022
Agency: Feather River AQMD
Agency Contact: 530-634-7659 ext. 205
Most Recent Contact: 03/16/2022

DRYCLEANERS_GLENN COUNTY - CA: Listing of drycleaning facilities in Glenn County

Agency Version Date: 10/29/2018
Agency Update Frequency: Varies
Planned Next Contact: 05/09/2022
Agency: Glenn County APCD
Agency Contact: 530-934-6500
Most Recent Contact: 02/11/2022

DRYCLEANERS_GREAT BASIN UNIFIED - CA: Listing of drycleaning facilities in the Great Basin Unified region

Agency Version Date: 09/09/2014
Agency Update Frequency: Varies
Planned Next Contact: 04/01/2022
Agency: Great Basin Unified APCD
Agency Contact: 760-872-8211 ext. 228
Most Recent Contact: 01/04/2022

DRYCLEANERS_IMPERIAL COUNTY - CA: Listing of drycleaning facilities in Imperial County

Agency Version Date: 10/29/2021
Agency Update Frequency: Annually
Planned Next Contact: 04/21/2022
Agency: Imperial County APCD
Agency Contact: 760-482-4606
Most Recent Contact: 01/25/2022

DRYCLEANERS_LAKE COUNTY - CA: Listing of drycleaning facilities in Lake County

Agency Version Date: 03/29/2016
Agency Update Frequency: Varies
Planned Next Contact: 04/18/2022
Agency: Lake County AQMD
Agency Contact: 707-263-7000
Most Recent Contact: 01/20/2022

DRYCLEANERS_LASSEN COUNTY - CA: Listing of drycleaning facilities in Lassen County

Agency Version Date: 05/16/2013
Agency Update Frequency: Varies
Planned Next Contact: 05/06/2022
Agency: Lassen County APCD
Agency Contact: 530-257-1045
Most Recent Contact: 02/08/2022

DRYCLEANERS_MENDOCINO COUNTY - CA: Listing of drycleaning facilities in Mendocino County

Agency Version Date: 08/24/2016
Agency Update Frequency: Varies
Planned Next Contact: 04/13/2022
Agency: Mendocino County AQMD
Agency Contact: 707-463-4354
Most Recent Contact: 01/17/2022

DRYCLEANERS_MOJAVE DESERT - CA: Listing of drycleaning facilities in the Mojave Desert region

Agency Version Date: 02/11/2022
Agency Update Frequency: Varies
Planned Next Contact: 05/09/2022
Agency: Mojave Desert AQMD
Agency Contact: 661-723-8070
Most Recent Contact: 02/11/2022

DRYCLEANERS_MONTEREY BAY - CA: Listing of drycleaning facilities in the Monterey Bay region

Agency Version Date: 03/08/2022
Agency Update Frequency: Varies
Planned Next Contact: 06/06/2022
Agency: Monterey Bay Unified APCD
Agency Contact: 831-647-9418 ext.240
Most Recent Contact: 03/08/2022

DRYCLEANERS_NORTH COAST UNIFIED - CA: Listing of drycleaning facilities in the North Coast region

Agency Version Date: 12/29/2021
Agency Update Frequency: Varies
Planned Next Contact: 03/25/2022
Agency: North Coast Unified AQMD
Agency Contact: 707-443-3093 ext. 111
Most Recent Contact: 12/29/2021

OTHER ASCERTAINABLE RECORDS (cont.)

DRYCLEANERS_NORTHERN SIERRA - CA: Listing of drycleaning facilities in the Northern Sierra region

Agency Version Date: 09/08/2014
Agency Update Frequency: No Update
Planned Next Contact: 05/30/2022
Agency: Northern Sierra AQMD
Agency Contact: 530-274-9360 ext. 106
Most Recent Contact: 03/03/2022

DRYCLEANERS_NORTHERN SONOMA COUNTY - CA: Listing of drycleaning facilities in Northern Sonoma County

Agency Version Date: 06/01/2018
Agency Update Frequency: Varies
Planned Next Contact: 05/09/2022
Agency: Northern Sonoma County APCD
Agency Contact: 707-433-5911
Most Recent Contact: 02/11/2022

DRYCLEANERS_PLACER COUNTY - CA: Listing of drycleaning facilities in Placer County

Agency Version Date: 05/02/2018
Agency Update Frequency: Quarterly
Planned Next Contact: 05/18/2022
Agency: Placer County APCD
Agency Contact: 530-745-2324
Most Recent Contact: 02/21/2022

DRYCLEANERS_SACRAMENTO COUNTY - CA: Listing of drycleaning facilities in Sacramento County

Agency Version Date: 03/08/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 06/06/2022
Agency: Sacramento Metro AQMD
Agency Contact: 916-874-4817
Most Recent Contact: 03/08/2022

DRYCLEANERS_SAN DIEGO COUNTY - CA: Listing of drycleaning facilities in San Diego County

Agency Version Date: 05/20/2019
Agency Update Frequency: Varies
Planned Next Contact: 05/09/2022
Agency: San Diego County APCD
Agency Contact: 858-586-2618
Most Recent Contact: 02/11/2022

DRYCLEANERS_SAN JOAQUIN VALLEY - CA: Listing of drycleaning facilities in the San Joaquin Valley

Agency Version Date: 02/04/2022
Agency Update Frequency: Varies
Planned Next Contact: 04/29/2022
Agency: San Joaquin Valley APCD
Agency Contact: 559-230-5936
Most Recent Contact: 02/03/2022

DRYCLEANERS_SAN LUIS OBISPO - CA: Listing of drycleaning facilities in the San Luis Obispo region

Agency Version Date: 02/15/2022
Agency Update Frequency: Varies
Planned Next Contact: 05/13/2022
Agency: San Luis Obispo County APCD
Agency Contact: 805-781-5912
Most Recent Contact: 02/15/2022

DRYCLEANERS_SANTA BARBARA COUNTY - CA: Listing of drycleaning facilities in Santa Barbara County

Agency Version Date: 08/20/2021
Agency Update Frequency: Varies
Planned Next Contact: 05/09/2022
Agency: Santa Barbara County APCD
Agency Contact: 805-961-8867
Most Recent Contact: 02/09/2022

DRYCLEANERS_SHASTA COUNTY - CA: Listing of drycleaning facilities in Shasta County

Agency Version Date: 02/12/2021
Agency Update Frequency: Varies
Planned Next Contact: 04/21/2022
Agency: Shasta County AQMD
Agency Contact: 530-225-5674
Most Recent Contact: 01/25/2022

DRYCLEANERS_SISKIYOU COUNTY - CA: Listing of drycleaning facilities in Siskiyou County

Agency Version Date: 09/08/2014
Agency Update Frequency: Varies
Planned Next Contact: 04/11/2022
Agency: Siskiyou County APCD
Agency Contact: N/R
Most Recent Contact: 01/13/2022

OTHER ASCERTAINABLE RECORDS (cont.)

DRYCLEANERS_SOUTH COAST - CA: Listing of drycleaning facilities in the South Coast region

Agency Version Date: 02/18/2022
Agency Update Frequency: Varies
Planned Next Contact: 05/16/2022
Agency: South Coast AQMD
Agency Contact: 909-396-2000
Most Recent Contact: 02/18/2022

DRYCLEANERS_TEHAMA COUNTY - CA: Listing of drycleaning facilities in Tehama County

Agency Version Date: 02/25/2022
Agency Update Frequency: Varies
Planned Next Contact: 05/23/2022
Agency: Tehama County APCD
Agency Contact: 530-527-3717 ext.100
Most Recent Contact: 02/25/2022

DRYCLEANERS_TUOLUMNE COUNTY - CA: Listing of drycleaning facilities in Tuolumne County

Agency Version Date: 09/21/2020
Agency Update Frequency: Varies
Planned Next Contact: 05/30/2022
Agency: Tuolumne County APCD
Agency Contact: 209-533-6678
Most Recent Contact: 03/03/2022

DRYCLEANERS_VENTURA COUNTY - CA: Listing of drycleaning facilities in Ventura County

Agency Version Date: 01/25/2022
Agency Update Frequency: Varies
Planned Next Contact: 04/21/2022
Agency: Ventura County APCD
Agency Contact: 805-645-1405
Most Recent Contact: 01/25/2022

DRYCLEANERS_YOLO-SOLANO COUNTIES - CA: Listing of drycleaning facilities in Yolo and Solano Counties

Agency Version Date: 02/15/2022
Agency Update Frequency: Varies
Planned Next Contact: 05/13/2022
Agency: Yolo-Solano AQMD
Agency Contact: 530-757-3664
Most Recent Contact: 02/15/2022

EMI - CA: An estimation of air pollution for a listing of air permitted facilities

Agency Version Date: 03/08/2022
Agency Update Frequency: Varies
Planned Next Contact: 06/02/2022
Agency: California Air Resources Board
Agency Contact: 916-327-6251
Most Recent Contact: 03/08/2022

FA - CA: Listing of the Department of Toxic Substance Control's Financial Assurance report sites and facilities

Agency Version Date: 10/26/2021
Agency Update Frequency: Varies
Planned Next Contact: 04/19/2022
Agency: Department of Toxic Substance Control
Agency Contact: 916-322-2861
Most Recent Contact: 01/21/2022

FA 2 - CA: Financial Assurance Information for solid waste facilities

Agency Version Date: 01/13/2022
Agency Update Frequency: Varies
Planned Next Contact: 04/11/2022
Agency: Department of Environment & Natural Resources
Agency Contact: 916-341-6066
Most Recent Contact: 01/13/2022

FIRE AREAS - CA: The multi-agency statewide database of fire perimeters.

Agency Version Date: 01/06/2022
Agency Update Frequency: No Update
Planned Next Contact: 04/04/2022
Agency: California Department of Forestry and Fire Protection
Agency Contact: 916-445-4302
Most Recent Contact: 01/06/2022

GCC_SANTA CLARA VALLEY - CA: Santa Clara Valley groundwater contamination cleanups listing

Agency Version Date: 02/23/2022
Agency Update Frequency: Varies
Planned Next Contact: 05/23/2022
Agency: CA State Water Resources Control Board
Agency Contact: 916-341-5791
Most Recent Contact: 02/23/2022

OTHER ASCERTAINABLE RECORDS (cont.)

HAZMAT INCIDENT_CONTRA COSTA COUNTY - CA: Listing of hazardous material incident sites since 1993 in Contra Costa County

Agency Version Date: 08/13/2021
Agency Update Frequency: Varies
Planned Next Contact: 05/02/2022
Agency: Contra Costa Health Services Department
Agency Contact: 925-335-3200
Most Recent Contact: 02/04/2022

HAZMAT_CITY OF SAN JOSE - CA: City of San Jose hazardous material facilities listing

Agency Version Date: 01/05/2021
Agency Update Frequency: Quarterly
Planned Next Contact: 06/15/2022
Agency: Santa Clara County Department of Environmental Health
Agency Contact: 408-918-1951
Most Recent Contact: 03/17/2022

HAZMAT_SACRAMENTO COUNTY - CA: Sacramento county hazardous material facilities listing

Agency Version Date: 08/20/2021
Agency Update Frequency: Quarterly
Planned Next Contact: 05/09/2022
Agency: Sacramento County Environmental Management
Agency Contact: 916-875-8550
Most Recent Contact: 02/09/2022

HAZMAT_SAN BERNARDINO COUNTY - CA: San Bernardino county listing of hazardous material permitted facilities

Agency Version Date: 02/04/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/29/2022
Agency: San Bernardino County Fire Department Hazardous Materials Division
Agency Contact: 909-386-8419
Most Recent Contact: 02/03/2022

HAZMAT_SAN DIEGO COUNTY - CA: San Diego county listing of hazardous material permitted facilities

Agency Version Date: 02/03/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 05/03/2022
Agency: Hazardous Materials Management Division
Agency Contact: 858-505-6700
Most Recent Contact: 02/03/2022

HAZMAT_SANTA CLARA COUNTY - CA: Santa Clara county hazardous material facilities listing

Agency Version Date: 02/15/2022
Agency Update Frequency: Annually
Planned Next Contact: 05/13/2022
Agency: Santa Clara Department of Environmental Health
Agency Contact: 408-918-3428
Most Recent Contact: 02/15/2022

HAZNET - CA: Listing of hazardous waste manifests from when hazardous waste is transported from generators to permitted recycling treatment storage or disposal facilities by registered hazardous waste transporters

Agency Version Date: 04/05/2021
Agency Update Frequency: Annually
Planned Next Contact: 06/14/2022
Agency: California Environmental Protection Agency
Agency Contact: 916-341-5791
Most Recent Contact: 03/18/2022

HAZWASTE_ORANGE COUNTY - CA: Orange County hazardous waste facilities

Agency Version Date: 02/08/2022
Agency Update Frequency: Annually
Planned Next Contact: 05/06/2022
Agency: Orange County Health Care Agency
Agency Contact: 714-433-6000
Most Recent Contact: 02/08/2022

HIGH FIRE - CA: Fire hazard severity zones mapped as areas of significant fire hazards on the basis of fuels terrain weather and other factors

Agency Version Date: 03/22/2021
Agency Update Frequency: No update
Planned Next Contact: 06/01/2022
Agency: California Department of Forestry and Fire Protection
Agency Contact: 916-445-4302
Most Recent Contact: 03/07/2022

OTHER ASCERTAINABLE RECORDS (cont.)

HIST CORTESE - CA: The historical compliance document used in providing information about the location of hazardous material release sites utilized by the state local agencies and developers

Agency Version Date: 02/03/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 05/02/2022
Agency: Department of Toxic Substance Control
Agency Contact: 916-322-2861
Most Recent Contact: 02/03/2022

HIST HAZNET - CA: List of hazardous waste manifests from when hazardous waste is transported from generators to permitted recycling treatment storage or disposal facilities by registered hazardous waste transporters that are no longer in current agency list.

Agency Version Date: 10/10/2018
Agency Update Frequency: Annually
Planned Next Contact: 05/17/2022
Agency: California Environmental Protection Agency
Agency Contact: 916-341-5791
Most Recent Contact: 02/18/2022

HIST HMS_LOS ANGELES COUNTY - CA: List of Los Angeles county industrial waste and underground storage tank sites that are no longer in current agency list.

Agency Version Date: 09/15/2018
Agency Update Frequency: Annually
Planned Next Contact: 06/13/2022
Agency: County of Los Angeles Department of Public Works
Agency Contact: 626-458-3518
Most Recent Contact: 03/16/2022

HIST HWP - CA: List of the Department of Toxic Substance Control's hazardous waste transporters and corrective action that are no longer in current agency list.

Agency Version Date: 01/18/2019
Agency Update Frequency: Annually
Planned Next Contact: 04/21/2022
Agency: Department of Toxic Substance Control
Agency Contact: 916-322-2861
Most Recent Contact: 01/25/2022

HIST LDS - CA: List of areas of land on or in which hazardous waste is placed or the largest area in which there is significant likelihood of mixing hazardous waste constituents in the same area that are no longer in current agency list.

Agency Version Date: 05/20/2018
Agency Update Frequency: Annually
Planned Next Contact: 05/23/2022
Agency: State Water Qualilty Control Board
Agency Contact: 916-341-5791
Most Recent Contact: 02/24/2022

HIST MCS - CA: List of the State Water Resources Control Boards investigation and remediation of water quality issues at military facilities that is no longer in current agency list.

Agency Version Date: 09/24/2018
Agency Update Frequency: No Longer Maintained
Planned Next Contact: 06/10/2022
Agency: State Water Resources Control Board
Agency Contact: 916-341-5791
Most Recent Contact: 03/16/2022

HIST NFA - CA: Historical No further action cleanup sites listing

Agency Version Date: 02/21/2019
Agency Update Frequency: Quarterly
Planned Next Contact: 05/09/2022
Agency: Department of Toxic Substances Control
Agency Contact: 916-322-2861
Most Recent Contact: 02/10/2022

HMS_LOS ANGELES COUNTY - CA: Listing of Los Angeles county industrial waste and underground storage tank sites

Agency Version Date: 12/21/2021
Agency Update Frequency: Monthly
Planned Next Contact: 06/13/2022
Agency: County of Los Angeles Department of Public Works
Agency Contact: 626-458-3518
Most Recent Contact: 03/15/2022

OTHER ASCERTAINABLE RECORDS (cont.)

HWM COMMERCIAL FACILITIES - CA: Listing of all commercial hazardous waste permitted off-site transfer recycling treatment storage and disposal facilities

Agency Version Date: 01/20/2022
Agency Update Frequency: Varies
Planned Next Contact: 04/18/2022
Agency: Department of Toxic Substance Control
Agency Contact: 916-322-5308
Most Recent Contact: 01/20/2022

HWP - CA: Facility listing of the Department of Toxic Substance Control's hazardous waste transporters and corrective action

Agency Version Date: 01/28/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/26/2022
Agency: Department of Toxic Substance Control
Agency Contact: 916-322-2861
Most Recent Contact: 01/28/2022

HWT - CA: Listing of registered hazardous waste transporters

Agency Version Date: 02/01/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/29/2022
Agency: Department of Toxic Substance Control
Agency Contact: 916-322-2861
Most Recent Contact: 02/01/2022

LDS - CA: List of Land Disposal Cleanup Sites from Geotracker

Agency Version Date: 01/25/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/22/2022
Agency: State Water Resources Control Board
Agency Contact: 916-341-5791
Most Recent Contact: 01/25/2022

LOP_SANTA CLARA COUNTY - CA: Santa Clara county leaking underground storage tank sites

Agency Version Date: 07/21/2017
Agency Update Frequency: No Longer Maintained
Planned Next Contact: 04/18/2022
Agency: Department of Environmental Health
Agency Contact: 408-280-6479
Most Recent Contact: 01/20/2022

MCS - CA: List of Military Cleanup Sites from Geotracker

Agency Version Date: 01/25/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/22/2022
Agency: State Water Resources Control Board
Agency Contact: 916-341-5791
Most Recent Contact: 01/25/2022

MWMP - CA: Listing of treatment and transfer stations that properly handle and dispose of medical waste that are permitted and inspected by the Medical Waste Management Program

Agency Version Date: 01/28/2022
Agency Update Frequency: Varies
Planned Next Contact: 04/26/2022
Agency: California-Health Human Services Department of Public Health
Agency Contact: 916-449-5661
Most Recent Contact: 01/28/2022

MWMP 2 - CA: Listing of facilities that generate permitted medical waste and are inspected by the Medical Waste Management Program

Agency Version Date: 01/13/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/11/2022
Agency: California-Health Human Services Department of Public Health
Agency Contact: 916-449-5661
Most Recent Contact: 01/13/2022

NFA - CA: No further action cleanup sites listing

Agency Version Date: 12/23/2021
Agency Update Frequency: Quarterly
Planned Next Contact: 06/16/2022
Agency: Department of Toxic Substances Control
Agency Contact: 916-322-2861
Most Recent Contact: 03/21/2022

OTHER ASCERTAINABLE RECORDS (cont.)

NFE - CA: Unconfirmed contaminated properties listing

Agency Version Date: 12/22/2021
Agency Update Frequency: Quarterly
Planned Next Contact: 06/14/2022
Agency: Department of Toxic Substances Control
Agency Contact: 916-322-2861
Most Recent Contact: 03/18/2022

NPDES - CA: Listing of facilities with wastewater and NPDES permits including stormwater

Agency Version Date: 02/24/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 05/23/2022
Agency: State Water Resources Control Board
Agency Contact: 916-341-5810
Most Recent Contact: 02/24/2022

PERCHLORATE 2 - CA: Listing of contaminated sites where the primary known chemical is perchlorate

Agency Version Date: 12/21/2021
Agency Update Frequency: Quarterly
Planned Next Contact: 06/14/2022
Agency: Department of Toxic Substances Control
Agency Contact: 916-322-2861
Most Recent Contact: 03/18/2022

PFAS - CA: List of PFAS sites and areas of interest

Agency Version Date: 01/07/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/05/2022
Agency: California State Water Resources Control Board
Agency Contact: N/R
Most Recent Contact: 01/07/2022

PFAS DOD - CA: List of DoD facilities conducting PFAS investigations

Agency Version Date: 01/07/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/05/2022
Agency: California State Water Resources Control Board
Agency Contact: N/R
Most Recent Contact: 01/07/2022

PFAS GAMA - CA: PFOS & PFAS GAMA Well Sampling program

Agency Version Date: 01/03/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/01/2022
Agency: California State Water Resources Control Board
Agency Contact: N/R
Most Recent Contact: 01/03/2022

PROPOSITION 65 - CA: Listing of Proposition 65 enforcement reporting notice sites in accordance with "The Safe Drinking Water and Toxic Enforcement Act of 1986"

Agency Version Date: 06/11/2021
Agency Update Frequency: No update
Planned Next Contact: 05/27/2022
Agency: State of California Department of JusticeOffice of the Attorney General
Agency Contact: 510-873-6321
Most Recent Contact: 03/01/2022

RFR - CA: State Water Resources Control Board Regulated Facility Report database listing which includes program agency type and their permit status

Agency Version Date: 03/03/2022
Agency Update Frequency: Varies
Planned Next Contact: 05/30/2022
Agency: CA State Water Resources Control Board
Agency Contact: 916-341-5810
Most Recent Contact: 03/03/2022

SITES INVENTORY_VENTURA COUNTY - CA: Listing of Ventura County inventory of closed illegal abandoned and inactive sites

Agency Version Date: 05/14/2021
Agency Update Frequency: Annually
Planned Next Contact: 04/29/2022
Agency: Environmental Health Division
Agency Contact: 805-654-2815
Most Recent Contact: 02/01/2022

OTHER ASCERTAINABLE RECORDS (cont.)

SMU_SANTA BARBARA COUNTY - CA: Site Mitigation Unit site assessment and corrective actions at properties in Santa Barbara County

Agency Version Date: 12/31/2021
Agency Update Frequency: Varies
Planned Next Contact: 03/29/2022
Agency: Santa Barbara County APCD
Agency Contact: (805) 681-4900
Most Recent Contact: 12/31/2021

SWAT - CA: The SWAT Reports Summary Data and the Waste Management Unit Database were published by State Water Resources Control Board staff and the Regional Water Quality Control Boards for tracking and inventory of waste management units.

Agency Version Date: 08/08/2015
Agency Update Frequency: No Longer Maintained
Planned Next Contact: 05/16/2022
Agency: Department of Ecology
Agency Contact: 916-322-2861
Most Recent Contact: 02/17/2022

VCCP_VENTURA COUNTY - CA: Listing of Ventura County cleanup program sites

Agency Version Date: 11/04/2021
Agency Update Frequency: Annually
Planned Next Contact: 04/27/2022
Agency: Environmental Health Division
Agency Contact: 805-654-2815
Most Recent Contact: 01/31/2022

WDS - CA: Listing of waste discharge system reporting facilities

Agency Version Date: 01/18/2022
Agency Update Frequency: Quarterly
Planned Next Contact: 04/15/2022
Agency: State Water Resources Control Board
Agency Contact: 916-341-5810
Most Recent Contact: 01/18/2022

WILDLANDS - CA: The Wildlands Conservancy listing of preserves in California

Agency Version Date: 11/18/2021
Agency Update Frequency: Varies
Planned Next Contact: 05/12/2022
Agency: The Wildlands Conservancy
Agency Contact: 909-797-8507
Most Recent Contact: 02/14/2022

WIP - CA: Listing of Well Investigation Program cases in the San Gabriel and San Fernando Valley area

Agency Version Date: 07/01/2009
Agency Update Frequency: Varies
Planned Next Contact: 05/06/2022
Agency: Los Angeles Water Quality Control Board
Agency Contact: 916-341-5810
Most Recent Contact: 02/08/2022

OTHER

SEISMIC - CA: Earthquake Zones of Required Investigation. Shows the location of both Seismic Hazard Zones and Earthquake Fault Zones

Agency Version Date: 04/30/2021
Agency Update Frequency: Varies
Planned Next Contact: 04/15/2022
Agency: State of California Department of Conservation
Agency Contact: 916-324-7299
Most Recent Contact: 01/18/2022

SUBJECT PROPERTY ADDRESS:

Vacant Property
Northeast Side of Capalina Rd.
San Marcos, CA 92069

SUBJECT PROPERTY COORDINATES:

Latitude(North):	33.151670 - 33°9'6"
Longitude(West):	-117.195125 - -117°11'42.5"
Universal Transverse Mercator:	Zone 11N
UTM X (Meters):	481803.45
UTM Y (Meters):	3668118.20

ELEVATION:

Elevation:	587 ft. above sea level

USGS TOPOGRAPHIC MAP:

Subject Property Map:	33117-B2 San Marcos, CA
Most Recent Revision:	2018

GEOHYDROLOGY DATA:

SUBJECT PROPERTY TOPOGRAPHY:

Topographic Gradient: East

DFIRM FLOOD ZONE:

	DFIRM Flood
Subject Property County:	Electronic Data:
SAN DIEGO	Yes - refer to the PROPERTY PROXIMITY MAP and AREA MAP
Flood Plain Panel at Subject Property:	06073C0789H (Eff. date 5/16/2012)
Additional Panels in search area:	06073C0787H (Eff. date 5/16/2012) 06073C0793G (Eff. date 5/16/2012) 06073C0791G (Eff. date 5/16/2012)

FEMA FLOOD ZONE:

	FEMA Flood
Subject Property County:	Electronic Data:
SAN DIEGO	No available data.
Flood Plain Panel at Subject Property:	No available data
Additional Panels in search area:	No available data

NATIONAL WETLAND INVENTORY:

	NWI Electronic
NWI Quad at Subject Property:	Data Coverage:
San Marcos	Yes - refer to the Geological Findings Map

LITHOSTRATIGRAPHIC INFORMATION:

ROCK STRATIGRAPHIC UNIT:		GEOLOGIC AGE IDENTIFICATION
Era:	Mesozoic	Category: 62 lMze Lower Mesozoic eugeosynclinal
System:	Jurassic-Triassic	
Series:	Lower Mesozoic eugeosynclinal	
Code:	lMze	

SURROUNDING ELEVATION PROFILES:





SUBJECT NAME: Vacant Property
ADDRESS: Northeast Side of Capalina Rd., San Marcos, C...
LAT/LONG: 33.151670 / -117.195125

PREPARED FOR: The Phase One Group
ORDER #: 69131
REPORT DATE: March 21, 2022



Subject Property — SSURGO — STATSGO

SOIL COMPOSITION IN GENERAL AREA OF SUBJECT PROPERTY:

Agency source: Soil Conservation Service, US Department of Agriculture

SOIL MAP ID 1	SSURGO
USDA Soil Name	Auld,Series
USDA Soil Texture	Clay
Hydrologic Soil Group	C
Soil Drainage Class	Well drained
Hydric Classification	0
Corrosion Potential - Uncoated Steel	High

Layer	Depth (inches)	Soil Texture	AASHTO Group	Unified Soil Description	Saturated Hydraulic Conductivity micro m/sec	Soil Reaction pH
1	0-137	Clay	Silt-Clay materials (more than 35% passing No. 200), clayey soils. Reference: This is a classification of soil material for highway and airfield construction (Procedure M 145-73 in Am. Assoc. of State Highway and Transportation Officials, 1984.	FINE-GRAINED SOILS, Silts and clays (liquid limit is 50% or more), Fat Clay. Reference: This is a classification of soil material designed for general construction purposes. It is dependent on the particle size distribution of the <75 mm, the liquid limit, and the plasticity index and on whether the soil material is high in organic matter (ASTM test D 2487, in ASTM, 1984).	0.42-1.4	6.6-8.4
2	137-150		No data	No data	0-0	0-0

SOIL MAP ID 2	SSURGO
USDA Soil Name	Escondido,Series
USDA Soil Texture	Very fine sandy loam
Hydrologic Soil Group	C
Soil Drainage Class	Well drained
Hydric Classification	0
Corrosion Potential - Uncoated Steel	Low

Layer	Depth (inches)	Soil Texture	AASHTO Group	Unified Soil Description	Saturated Hydraulic Conductivity micro m/sec	Soil Reaction pH
1	0-20	Very fine sandy loam	Silt-Clay materials (more than 35% passing NO. 200), silty soils. Reference: This is a classification of soil material for highway and airfield	FINE-GRAINED SOILS, Silts and clays, (liquid limit is less than 50%), Silt. Reference: This is a classification of soil material designed for general construction	4-14	6.1-7.3

Layer	Depth (inches)	Soil Texture	AASHTO Group	Unified Soil Description	Saturated Hydraulic Conductivity micro m/sec	Soil Reaction pH
1	0-20	Very fine sandy loam	construction (Procedure M 145-73 in Am. Assoc. of State Highway and Transportation Officials, 1984.	purposes. It is dependent on the particle size distribution of the <75 mm, the liquid limit, and the plasticity index and on whether the soil material is high in organic matter (ASTM test D 2487, in ASTM, 1984).	4-14	6.1-7.3
2	20-86	Silt loam	Silt-Clay materials (more than 35% passing NO. 200), silty soils. Reference: This is a classification of soil material for highway and airfield construction (Procedure M 145-73 in Am. Assoc. of State Highway and Transportation Officials, 1984.	FINE-GRAINED SOILS, Silts and clays, (liquid limit is less than 50%), Silt. Reference: This is a classification of soil material designed for general construction purposes. It is dependent on the particle size distribution of the <75 mm, the liquid limit, and the plasticity index and on whether the soil material is high in organic matter (ASTM test D 2487, in ASTM, 1984).	4-14	6.1-7.3
3	86-97		No data	No data	0-0	0-0

SOIL MAP ID 3 **SSURGO**

USDA Soil Name	Diablo,Series
USDA Soil Texture	Clay
Hydrologic Soil Group	D
Soil Drainage Class	Well drained
Hydric Classification	0
Corrosion Potential - Uncoated Steel	High

Layer	Depth (inches)	Soil Texture	AASHTO Group	Unified Soil Description	Saturated Hydraulic Conductivity micro m/sec	Soil Reaction pH
1	0-38	Clay	Silt-Clay materials (more than 35% passing No. 200), clayey soils. Reference: This is a classification of soil material for highway and airfield construction (Procedure M 145-73 in Am. Assoc. of State Highway and Transportation Officials, 1984.	FINE-GRAINED SOILS, Silts and clays (liquid limit is 50% or more), Fat Clay. Reference: This is a classification of soil material designed for general construction purposes. It is dependent on the particle size distribution of the <75 mm, the liquid limit, and the plasticity index and on whether the soil	0.42-1.4	6.6-7.8

Layer	Depth (inches)	Soil Texture	AASHTO Group	Unified Soil Description	Saturated Hydraulic Conductivity micro m/sec	Soil Reaction pH
1	0-38	Clay	Silt-Clay materials (more than 35% passing No. 200), clayey soils. Reference: This is a classification of soil material for highway and airfield construction (Procedure M 145-73 in Am. Assoc. of State Highway and Transportation Officials, 1984.	material is high in organic matter (ASTM test D 2487, in ASTM, 1984).	0.42-1.4	6.6-7.8
2	38-81	Clay	Silt-Clay materials (more than 35% passing No. 200), clayey soils. Reference: This is a classification of soil material for highway and airfield construction (Procedure M 145-73 in Am. Assoc. of State Highway and Transportation Officials, 1984.	FINE-GRAINED SOILS, Silts and clays (liquid limit is 50% or more), Fat Clay. Reference: This is a classification of soil material designed for general construction purposes. It is dependent on the particle size distribution of the <75 mm, the liquid limit, and the plasticity index and on whether the soil material is high in organic matter (ASTM test D 2487, in ASTM, 1984).	0.42-1.4	6.6-7.8
3	81-91		No data	No data	0-0	0-0

SOIL MAP ID 4 **SSURGO**

USDA Soil Name	Diablo,Series
USDA Soil Texture	Clay
Hydrologic Soil Group	C
Soil Drainage Class	Well drained
Hydric Classification	0
Corrosion Potential - Uncoated Steel	High

Layer	Depth (inches)	Soil Texture	AASHTO Group	Unified Soil Description	Saturated Hydraulic Conductivity micro m/sec	Soil Reaction pH
1	0-38	Clay	Reference: This is a classification of soil material for highway and airfield construction (Procedure M 145-73 in Am. Assoc. of State Highway and Transportation Officials, 1984.	FINE-GRAINED SOILS, Silts and clays (liquid limit is 50% or more), Fat Clay. Reference: This is a classification of soil material designed for general construction purposes. It is dependent on the particle size	0.42-1.41	6.4-8.4

Layer	Depth (inches)	Soil Texture	AASHTO Group	Unified Soil Description	Saturated Hydraulic Conductivity micro m/sec	Soil Reaction pH
1	0-38	Clay	Reference: This is a classification of soil material for highway and airfield construction (Procedure M 145-73 in Am. Assoc. of State Highway and Transportation Officials, 1984.	distribution of the <75 mm, the liquid limit, and the plasticity index and on whether the soil material is high in organic matter (ASTM test D 2487, in ASTM, 1984).	0.42-1.41	6.4-8.4
2	38-71	Clay	Reference: This is a classification of soil material for highway and airfield construction (Procedure M 145-73 in Am. Assoc. of State Highway and Transportation Officials, 1984.	FINE-GRAINED SOILS, Silts and clays (liquid limit is 50% or more), Fat Clay. Reference: This is a classification of soil material designed for general construction purposes. It is dependent on the particle size distribution of the <75 mm, the liquid limit, and the plasticity index and on whether the soil material is high in organic matter (ASTM test D 2487, in ASTM, 1984).	0.42-1.41	6.4-8.4
3	71-101	Clay loam	Reference: This is a classification of soil material for highway and airfield construction (Procedure M 145-73 in Am. Assoc. of State Highway and Transportation Officials, 1984.	FINE-GRAINED SOILS, Silts and clays (liquid limit is less than 50%), Lean Clay. Reference: This is a classification of soil material designed for general construction purposes. It is dependent on the particle size distribution of the <75 mm, the liquid limit, and the plasticity index and on whether the soil material is high in organic matter (ASTM test D 2487, in ASTM, 1984).	0.42-1.41	7.4-8.4
4	101-200		No data	No data	0-0	0-0

SOIL MAP ID 5	**SSURGO**
USDA Soil Name	Diablo,Series
USDA Soil Texture	Clay
Hydrologic Soil Group	D
Soil Drainage Class	Well drained
Hydric Classification	0
Corrosion Potential - Uncoated Steel	High

Layer	Depth (inches)	Soil Texture	AASHTO Group	Unified Soil Description	Saturated Hydraulic Conductivity micro m/sec	Soil Reaction pH
1	0-38	Clay	Silt-Clay materials (more than 35% passing No. 200), clayey soils. Reference: This is a classification of soil material for highway and airfield construction (Procedure M 145-73 in Am. Assoc. of State Highway and Transportation Officials, 1984.	FINE-GRAINED SOILS, Silts and clays (liquid limit is 50% or more), Fat Clay. Reference: This is a classification of soil material designed for general construction purposes. It is dependent on the particle size distribution of the <75 mm, the liquid limit, and the plasticity index and on whether the soil material is high in organic matter (ASTM test D 2487, in ASTM, 1984).	0.42-1.4	6.6-7.8
2	38-81	Clay	Silt-Clay materials (more than 35% passing No. 200), clayey soils. Reference: This is a classification of soil material for highway and airfield construction (Procedure M 145-73 in Am. Assoc. of State Highway and Transportation Officials, 1984.	FINE-GRAINED SOILS, Silts and clays (liquid limit is 50% or more), Fat Clay. Reference: This is a classification of soil material designed for general construction purposes. It is dependent on the particle size distribution of the <75 mm, the liquid limit, and the plasticity index and on whether the soil material is high in organic matter (ASTM test D 2487, in ASTM, 1984).	0.42-1.4	6.6-7.8
3	81-91		No data	No data	0-0	0-0

SOIL MAP ID 6 **SSURGO**

USDA Soil Name	Placentia,Series
USDA Soil Texture	Sandy loam
Hydrologic Soil Group	C
Soil Drainage Class	Well drained
Hydric Classification	1
Corrosion Potential - Uncoated Steel	High

Layer	Depth (inches)	Soil Texture	AASHTO Group	Unified Soil Description	Saturated Hydraulic Conductivity micro m/sec	Soil Reaction pH
1	0-10	Sandy loam	Silt-Clay materials (more than 35% passing NO. 200), silty soils. Reference: This is a classification of soil material for highway and airfield construction (Procedure M 145-73 in Am. Assoc. of State Highway and Transportation Officials, 1984.	COARSE-GRAINED SOILS, Sands, sands with fines, Clayey Sand. Reference: This is a classification of soil material designed for general construction purposes. It is dependent on the particle size distribution of the <75 mm, the liquid limit, and the plasticity index and on whether the soil material is high in organic matter (ASTM test D 2487, in ASTM, 1984).	4.2-14	5.6-6
2	10-33	Sandy loam	Silt-Clay materials (more than 35% passing NO. 200), silty soils. Reference: This is a classification of soil material for highway and airfield construction (Procedure M 145-73 in Am. Assoc. of State Highway and Transportation Officials, 1984.	COARSE-GRAINED SOILS, Sands, sands with fines, Clayey Sand. Reference: This is a classification of soil material designed for general construction purposes. It is dependent on the particle size distribution of the <75 mm, the liquid limit, and the plasticity index and on whether the soil material is high in organic matter (ASTM test D 2487, in ASTM, 1984).	4.2-14	6.1-6.5
3	33-53	Sandy clay	Reference: This is a classification of soil material for highway and airfield construction (Procedure M 145-73 in Am. Assoc. of State Highway and Transportation Officials, 1984.	COARSE-GRAINED SOILS, Sands, sands with fines, Clayey Sand. Reference: This is a classification of soil material designed for general construction purposes. It is dependent on the particle size distribution of the <75 mm, the liquid limit, and the plasticity index and on whether the soil material is high in organic matter (ASTM test D 2487, in ASTM, 1984).	0.4-4.2	7.9-8.4
4	53-86	Sandy clay	Reference: This is a classification of soil material for highway and airfield construction (Procedure M 145-73 in Am. Assoc. of State Highway and Transportation Officials, 1984.	COARSE-GRAINED SOILS, Sands, sands with fines, Clayey Sand. Reference: This is a classification of soil material designed for general construction purposes. It is dependent on the particle size distribution of the <75	0.4-4.2	7.9-8.4

Layer	Depth (inches)	Soil Texture	AASHTO Group	Unified Soil Description	Saturated Hydraulic Conductivity micro m/sec	Soil Reaction pH
4	53-86	Sandy clay	Reference: This is a classification of soil material for highway and airfield construction (Procedure M 145-73 in Am. Assoc. of State Highway and Transportation Officials, 1984.	mm, the liquid limit, and the plasticity index and on whether the soil material is high in organic matter (ASTM test D 2487, in ASTM, 1984).	0.4-4.2	7.9-8.4
5	86-135	Sandy clay loam	Silt-Clay materials (more than 35% passing No. 200) clayey soils. Reference: This is a classification of soil material for highway and airfield construction (Procedure M 145-73 in Am. Assoc. of State Highway and Transportation Officials, 1984.	COARSE-GRAINED SOILS, Sands, sands with fines, Clayey Sand. Reference: This is a classification of soil material designed for general construction purposes. It is dependent on the particle size distribution of the <75 mm, the liquid limit, and the plasticity index and on whether the soil material is high in organic matter (ASTM test D 2487, in ASTM, 1984).	1.4-14	7.9-8.4
6	135-160	Sandy clay loam	Silt-Clay materials (more than 35% passing No. 200) clayey soils. Reference: This is a classification of soil material for highway and airfield construction (Procedure M 145-73 in Am. Assoc. of State Highway and Transportation Officials, 1984.	COARSE-GRAINED SOILS, Sands, sands with fines, Clayey Sand. Reference: This is a classification of soil material designed for general construction purposes. It is dependent on the particle size distribution of the <75 mm, the liquid limit, and the plasticity index and on whether the soil material is high in organic matter (ASTM test D 2487, in ASTM, 1984).	1.4-14	7.9-8.4

SOIL MAP ID 7	**SSURGO**
USDA Soil Name	Las Flores,Series
USDA Soil Texture	Loamy fine sand
Hydrologic Soil Group	D
Soil Drainage Class	Moderately well drained
Hydric Classification	2
Corrosion Potential - Uncoated Steel	Moderate

Layer	Depth (inches)	Soil Texture	AASHTO Group	Unified Soil Description	Saturated Hydraulic Conductivity micro m/sec	Soil Reaction pH
1	0-51	Loamy fine sand	Granular materials (35% or less passing No. 200), silty or clayey gravel and sand. Reference: This is a classification of soil material for highway and airfield construction (Procedure M 145-73 in Am. Assoc. of State Highway and Transportation Officials, 1984.	COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand. Reference: This is a classification of soil material designed for general construction purposes. It is dependent on the particle size distribution of the <75 mm, the liquid limit, and the plasticity index and on whether the soil material is high in organic matter (ASTM test D 2487, in ASTM, 1984).	14-42	5.6-6.5
2	51-76	Sandy clay	Silt-Clay materials (more than 35% passing No. 200), clayey soils. Reference: This is a classification of soil material for highway and airfield construction (Procedure M 145-73 in Am. Assoc. of State Highway and Transportation Officials, 1984.	FINE-GRAINED SOILS, Silts and clays (liquid limit is 50% or more), Fat Clay. Reference: This is a classification of soil material designed for general construction purposes. It is dependent on the particle size distribution of the <75 mm, the liquid limit, and the plasticity index and on whether the soil material is high in organic matter (ASTM test D 2487, in ASTM, 1984).	0.01-0.42	6.1-7.3
3	76-102	Sandy clay	Silt-Clay materials (more than 35% passing No. 200), clayey soils. Reference: This is a classification of soil material for highway and airfield construction (Procedure M 145-73 in Am. Assoc. of State Highway and Transportation Officials, 1984.	FINE-GRAINED SOILS, Silts and clays (liquid limit is 50% or more), Fat Clay. Reference: This is a classification of soil material designed for general construction purposes. It is dependent on the particle size distribution of the <75 mm, the liquid limit, and the plasticity index and on whether the soil material is high in organic matter (ASTM test D 2487, in ASTM, 1984).	0.01-0.42	6.6-7.3
4	102-122	Loamy coarse sand	Granular materials (35% or less passing No. 200 sieve), silty or clayey gravel and sand. Reference: This is a classification of soil material for highway and airfield construction (Procedure M 145-73 in Am. Assoc. of State Highway and	COARSE-GRAINED SOILS, Sands, Sands with fines, Silty Sand. Reference: This is a classification of soil material designed for general construction purposes. It is dependent on the particle size distribution of the <75 mm, the liquid limit, and the plasticity index and	42-141	6.6-7.3

Layer	Depth (inches)	Soil Texture	AASHTO Group	Unified Soil Description	Saturated Hydraulic Conductivity micro m/sec	Soil Reaction pH
4	102-122	Loamy coarse sand	Transportation Officials, 1984.	on whether the soil material is high in organic matter (ASTM test D 2487, in ASTM, 1984).	42-141	6.6-7.3
5	122-132		No data	No data	0-0	0-0

SOIL MAP ID 8 **SSURGO**

USDA Soil Name	Auld,Series
USDA Soil Texture	Clay
Hydrologic Soil Group	C
Soil Drainage Class	Well drained
Hydric Classification	0
Corrosion Potential - Uncoated Steel	High

Layer	Depth (inches)	Soil Texture	AASHTO Group	Unified Soil Description	Saturated Hydraulic Conductivity micro m/sec	Soil Reaction pH
1	0-137	Clay	Silt-Clay materials (more than 35% passing No. 200), clayey soils. Reference: This is a classification of soil material for highway and airfield construction (Procedure M 145-73 in Am. Assoc. of State Highway and Transportation Officials, 1984.	FINE-GRAINED SOILS, Silts and clays (liquid limit is 50% or more), Fat Clay. Reference: This is a classification of soil material designed for general construction purposes. It is dependent on the particle size distribution of the <75 mm, the liquid limit, and the plasticity index and on whether the soil material is high in organic matter (ASTM test D 2487, in ASTM, 1984).	0.42-1.4	6.6-8.4
2	137-150		No data	No data	0-0	0-0

SOIL MAP ID 9	SSURGO
USDA Soil Name	Huerhuero,Series
USDA Soil Texture	Loam
Hydrologic Soil Group	D
Soil Drainage Class	Moderately well drained
Hydric Classification	2
Corrosion Potential - Uncoated Steel	High

Layer	Depth (inches)	Soil Texture	AASHTO Group	Unified Soil Description	Saturated Hydraulic Conductivity micro m/sec	Soil Reaction pH
1	0-30	Loam	Silt-Clay materials (more than 35% passing NO. 200), silty soils. Reference: This is a classification of soil material for highway and airfield construction (Procedure M 145-73 in Am. Assoc. of State Highway and Transportation Officials, 1984.	Reference: This is a classification of soil material designed for general construction purposes. It is dependent on the particle size distribution of the <75 mm, the liquid limit, and the plasticity index and on whether the soil material is high in organic matter (ASTM test D 2487, in ASTM, 1984).	4-14	5.1-6
2	30-140	Clay loam	Silt-Clay materials (more than 35% passing No. 200), clayey soils. Reference: This is a classification of soil material for highway and airfield construction (Procedure M 145-73 in Am. Assoc. of State Highway and Transportation Officials, 1984.	FINE-GRAINED SOILS, Silts and clays (liquid limit is 50% or more), Fat Clay. Reference: This is a classification of soil material designed for general construction purposes. It is dependent on the particle size distribution of the <75 mm, the liquid limit, and the plasticity index and on whether the soil material is high in organic matter (ASTM test D 2487, in ASTM, 1984).	0.01-0.42	7.4-8.4
3	140-183	Sandy loam	Granular materials (35% or less passing No. 200), silty or clayey gravel and sand. Reference: This is a classification of soil material for highway and airfield construction (Procedure M 145-73 in Am. Assoc. of State Highway and Transportation Officials, 1984.	Reference: This is a classification of soil material designed for general construction purposes. It is dependent on the particle size distribution of the <75 mm, the liquid limit, and the plasticity index and on whether the soil material is high in organic matter (ASTM test D 2487, in ASTM, 1984).	1.4-4	7.4-8.4

SOIL MAP ID 10	SSURGO
USDA Soil Name	Auld,Series
USDA Soil Texture	Clay
Hydrologic Soil Group	D
Soil Drainage Class	Well drained
Hydric Classification	0
Corrosion Potential - Uncoated Steel	High

Layer	Depth (inches)	Soil Texture	AASHTO Group	Unified Soil Description	Saturated Hydraulic Conductivity micro m/sec	Soil Reaction pH
1	0-76	Clay	Silt-Clay materials (more than 35% passing No. 200), clayey soils. Reference: This is a classification of soil material for highway and airfield construction (Procedure M 145-73 in Am. Assoc. of State Highway and Transportation Officials, 1984.	FINE-GRAINED SOILS, Silts and clays (liquid limit is 50% or more), Fat Clay. Reference: This is a classification of soil material designed for general construction purposes. It is dependent on the particle size distribution of the <75 mm, the liquid limit, and the plasticity index and on whether the soil material is high in organic matter (ASTM test D 2487, in ASTM, 1984).	0.42-1.4	6.6-8.4
2	76-150		No data	No data	0-0	0-0

SOIL MAP ID 11	SSURGO
USDA Soil Name	Huerhuero,Series
USDA Soil Texture	Loam
Hydrologic Soil Group	D
Soil Drainage Class	Moderately well drained
Hydric Classification	2
Corrosion Potential - Uncoated Steel	High

Layer	Depth (inches)	Soil Texture	AASHTO Group	Unified Soil Description	Saturated Hydraulic Conductivity micro m/sec	Soil Reaction pH
1	0-30	Loam	Silt-Clay materials (more than 35% passing NO. 200), silty soils. Reference: This is a classification of soil material for highway and airfield construction (Procedure M 145-73 in Am. Assoc. of State Highway and Transportation Officials,	Reference: This is a classification of soil material designed for general construction purposes. It is dependent on the particle size distribution of the <75 mm, the liquid limit, and the plasticity index and on whether the soil material is high in	4-14	5.1-6

Layer	Depth (inches)	Soil Texture	AASHTO Group	Unified Soil Description	Saturated Hydraulic Conductivity micro m/sec	Soil Reaction pH
1	0-30	Loam	1984.	organic matter (ASTM test D 2487, in ASTM, 1984).	4-14	5.1-6
2	30-140	Clay loam	Silt-Clay materials (more than 35% passing No. 200), clayey soils. Reference: This is a classification of soil material for highway and airfield construction (Procedure M 145-73 in Am. Assoc. of State Highway and Transportation Officials, 1984.	FINE-GRAINED SOILS, Silts and clays (liquid limit is 50% or more), Fat Clay. Reference: This is a classification of soil material designed for general construction purposes. It is dependent on the particle size distribution of the <75 mm, the liquid limit, and the plasticity index and on whether the soil material is high in organic matter (ASTM test D 2487, in ASTM, 1984).	0.01-0.42	7.4-8.4
3	140-183	Sandy loam	Granular materials (35% or less passing No. 200), silty or clayey gravel and sand. Reference: This is a classification of soil material for highway and airfield construction (Procedure M 145-73 in Am. Assoc. of State Highway and Transportation Officials, 1984.	Reference: This is a classification of soil material designed for general construction purposes. It is dependent on the particle size distribution of the <75 mm, the liquid limit, and the plasticity index and on whether the soil material is high in organic matter (ASTM test D 2487, in ASTM, 1984).	1.4-4	7.4-8.4

SOIL MAP ID A	STATSGO
USDA Soil Name	Antioch,Series
USDA Soil Texture	Loam
Hydrologic Soil Group	D
Soil Drainage Class	Moderately well drained
Hydric Classification	0
Corrosion Potential - Uncoated Steel	High

Layer	Depth (inches)	Soil Texture	AASHTO Group	Unified Soil Description	Saturated Hydraulic Conductivity micro m/sec	Soil Reaction pH
1	0-19	Loam	No data	No data	4.2343-14.1143	5.1-7.3
2	19-60	No data	No data	No data	0-0.4234	5.6-8.4
3	60-81	Sandy loam	No data	No data	1.4114-4.2343	7.4-8.4

SOIL MAP ID B **STATSGO**

USDA Soil Name	Ramona,Series
USDA Soil Texture	Sandy loam
Hydrologic Soil Group	B
Soil Drainage Class	Well drained
Hydric Classification	0
Corrosion Potential - Uncoated Steel	Moderate

Layer	Depth (inches)	Soil Texture	AASHTO Group	Unified Soil Description	Saturated Hydraulic Conductivity micro m/sec	Soil Reaction pH
1	0-14	Sandy loam	No data	No data	4.2343-14.1143	5.6-7.3
2	14-23	No data	No data	No data	4.2343-14.1143	6.1-7.3
3	23-29	No data	No data	No data	4.2343-14.1143	6.1-7.3
4	29-68	No data	No data	No data	1.4114-4.2343	6.1-7.3
5	68-73	No data	No data	No data	1.4114-4.2343	6.6-8.4

SOIL MAP ID C **STATSGO**

USDA Soil Name	Exchequer,Series
USDA Soil Texture	Silt loam
Hydrologic Soil Group	D
Soil Drainage Class	Well drained
Hydric Classification	0
Corrosion Potential - Uncoated Steel	Moderate

Layer	Depth (inches)	Soil Texture	AASHTO Group	Unified Soil Description	Saturated Hydraulic Conductivity micro m/sec	Soil Reaction pH
1	0-10	Silt loam	No data	No data	4.2343-14.1143	5.6-6.5
2	10-14		No data	No data	No data	No data

WATER AGENCY DATA:

WATER AGENCY SEARCH DISTANCES:

DATABASE:	SEARCH DISTANCE (MILES):
NWIS	1.000
OIL & GAS WELLS - CA	1.000
PWS	1.000
WELLS - GAMA - CA	0.000

DISTANCE TO NEAREST:	DISTANCE:
NWIS	N/A
OIL & GAS WELLS - CA	0.226 mi / 1193 ft
PWS	N/A
WELLS - GAMA - CA	N/A

FEDERAL WATER AGENCY DATA SUMMARY:

MAP ID:	WELL ID:	LOCATION FROM SP:
No Wells Found	N/R	N/R

Note: PWS System location is not always the same as well location.

STATE/LOCAL WATER AGENCY DATA SUMMARY:

MAP ID:	WELL ID:	LOCATION FROM SP:
1	0407300014	1/8 - 1/4 Mile S

SUBJECT NAME: Vacant Property
ADDRESS: Northeast Side of Capalina Rd., San Marcos, C...
LAT/LONG: 33.151670 / -117.195125

PREPARED FOR: The Phase One Group
ORDER #: 69131
REPORT DATE: March 21, 2022



- Subject Property
- Geological Site
- Basins (No Data)
- NWI
- DAMS (No Data)
- NWIS (No Data)
- Fire Areas
- Oil & Gas Wells

Map Id: 1
Direction: S
Distance: 0.226 mi., 1193 ft.
Elevation: 574 ft.
Relative: Lower

Site Name : 0407300014
33.147854, -117.195709
CA

Database(s) : [OIL & GAS WELLS - CA]

Envirosite ID: 9904529
EPA ID: N/R

OIL & GAS WELLS - CA

Spud Date :	N/R
API Number :	0407300014
Well Status :	Idle
Well Type :	Oil & Gas
Operator Code :	02065
Operator Name :	Davenport Oil & Gas Development Co.
Lease Name :	Lease by Davenport Oil & Gas Development Co.
Field Name :	Any Field
Area Name :	Any Area
District :	Southern
County :	San Diego
Section/Township/Range :	SEC 09, TWP 12S, RNG 03W
Base Meridian :	San Bernardino
GIS Source :	hud
Confidential Well :	No
Directionallly Drilled :	No
Latitude :	33.147854
Longitude :	-117.195709
Last Date in Agency List :	2021-12-21

Map Id: 2
Direction: WSW
Distance: 0.718 mi., 3790 ft.
Elevation: 670 ft.
Relative: Higher

Site Name : UTILITY POLE
33.148806, -117.207822
SAN MARCOS, CA

Database(s) : [DIGITAL OBSTACLE]

Envirosite ID: 906887
EPA ID: N/R

DIGITAL OBSTACLE

Date of Action :	2018-01-30
Action :	Add
FAA Study Number :	2014AWP05262OE
OBS Number :	06-151184
Obstacle Type :	UTILITY POLE
City Name :	SAN MARCOS
State Identifier :	CA
Country Identifier :	USA
Type of Lighting :	None
Verification Status :	Unverified
Quantity :	1
Mark Indicator :	None
Above Ground Level Height (Feet) :	00053
Above Mean Sea Level Height (Feet) :	00720
Horizontal Accuracy :	+-250'
Vertical Accuracy :	+-50'
Latitude :	33 08 55.70N
Longitude :	117 12 28.16W

Map Id: 3
Direction: SE
Distance: 0.819 mi., 4322 ft.
Elevation: 546 ft.
Relative: Lower

Site Name : UTILITY POLE
33.141167, -117.187025
SAN MARCOS, CA

Database(s) : [DIGITAL OBSTACLE]

Envirosite ID: 903599
EPA ID: N/R

DIGITAL OBSTACLE

Date of Action :	2018-01-30
Action :	Add
FAA Study Number :	2016AWP04945OE
OBS Number :	06-164971
Obstacle Type :	UTILITY POLE
City Name :	SAN MARCOS
State Identifier :	CA
Country Identifier :	USA
Type of Lighting :	None
Verification Status :	Unverified
Quantity :	1
Mark Indicator :	None
Above Ground Level Height (Feet) :	00043
Above Mean Sea Level Height (Feet) :	00587
Horizontal Accuracy :	+-250'
Vertical Accuracy :	+-50'
Latitude :	33 08 28.20N
Longitude :	117 11 13.29W

Map Id: 4
Direction: WSW
Distance: 0.917 mi., 4842 ft.
Elevation: 657 ft.
Relative: Higher

Site Name : UTILITY POLE
33.146419, -117.2105
SAN DIEGO, CA

Database(s) : [DIGITAL OBSTACLE]

Envirosite ID: 44657922
EPA ID: N/R

DIGITAL OBSTACLE

Date of Action :	2021-10-19
Action :	Add
FAA Study Number :	2020AWP01465OE
OBS Number :	06-241099
Obstacle Type :	UTILITY POLE
City Name :	SAN DIEGO
State Identifier :	CA
Country Identifier :	USA
Type of Lighting :	None
Verification Status :	Unverified
Quantity :	1
Mark Indicator :	None
Above Ground Level Height (Feet) :	00043
Above Mean Sea Level Height (Feet) :	00699
Horizontal Accuracy :	+-250'
Vertical Accuracy :	+-50'
Latitude :	33 08 47.11N
Longitude :	117 12 37.80W

RADON DATA:

STATE SOURCE: CA

Radon Test Results:

Zip:	Total Sites:	Cnt >=4 pCi/L:	Pct >= 4 pCi/L:	Max Result (pCi/L):
92069	34	2	5.882	7.2

FEDERAL AREA RADON INFORMATION FOR: 92069

NUMBER OF SAMPLE SITES: 3

Area:	Average Activity:	% <4 pCi/L:	% 4-20 pCi/L:	% >20 pCi/L:
first floor	0.8333 pCi/L	100%	0%	0%

FEDERAL EPA RADON ZONE FOR SAN DIEGO COUNTY: Zone = 3

Note: Zone 1 indoor average level > 4 pCI/L

: Zone 2 indoor average level > = 2 pCI/L and <= 4 pCI/L

: Zone 3 indoor average < 2 pCI/L

HIST PWS ENF
Historical Public Water Supply locations with Enforcement Violations
Environmental Protection Agency
(800) 426-4791
List of Safe Drinking Water Information Systems (SDWIS) with enforcement violations that are no longer in current agency list.

NWIS
National Water Information Systems
United States Geological Society
(703) 648-5953
Information on all water resources for the United States. This database contains all current and historical data for the nation.

PWS
Public Water Supply
Environmental Protection Agency
(800) 426-4791
Safe drinking water information Systems

PWS ENF
Public Water Supply locations with Enforcement Violations
Environmental Protection Agency
(800) 426-4791
Safe drinking water information Systems with enforcememnt violations

WELLS - GAMA - CA
California Groundwater Ambient Monitoring Assessment
State Water Resources Control Board
916-341-5791
Brings together datasets from California state agencies including: Public Health Water Resources and Pesticide Regulation as well as from the US Geological Survey Lawrence Livermore National Laboratory and the Water Boards. It shows results for untreated raw water in different types of wells for naturally-occurring and man-made chemicals.

FLOOD Q3
Flood data
Environmental Protection Agency
(202) 566-1667
Q3 Flood Data

HYDROLOGIC UNIT
Hydrologic Unit Maps
USGS
The United States Geological Survey created a hierarchical system of hydrologic units originally called regions, sub-regions, accounting units, and cataloging units. Each unit was assigned a unique Hydrologic Unit Code (HUC). As first implemented the system had 21 regions, 221 subregions, 378 accounting units, and 2,264 cataloging units. Over time the system was changed and expanded. As of 2010 there are six levels in the hierarchy, represented by hydrologic unit codes from 2 to 12 digits long, called regions, subregions, basins, subbasins, watersheds, and subwatersheds. The table below describes the system's hydrologic unit levels and their characteristics, along with example names and codes.

WETLANDS NWI
National Wetland Inventory
U.S. Fish and Wildlife Service
(703) 358-2171
Wetland Inventory for the United States

SSURGO
Detailed Soil Data Map
Natural Resources Conservation Service: U.S. Department of Agriculture
(202) 690-4985
Detailed Soil Data Map

STATSGO & MUI
General Soil Data Map
Natural Resources Conservation Service: U.S. Department of Agriculture
(202) 690-4985
General Soil Data Map

USGS GEOLOGIC AGE
USGS Digital Data Series DDS
Natural Resources Conservation Service: U.S. Department of Agriculture
(202) 690-4985
USGS Digital Data Series DDS: Geologic Age and Rock Stratigraphic Unit

DAMS - CA
California Dam Inundation Maps
Department of Water Resources
916-845-8275
Dam inundation maps show the maximum extent of damage of a flood wave from a dam failure

OIL & GAS WELLS - CA
Oil and Gas Well Data
State of California Department of Conservation
916-327-1042
Oil and gas well locations and detail for all 6 districts

RADON
National Radon Database
U.S. Environmental Protection Agency
215-814-2469
A study of the EPA/State Residential Radon Survey and the National Residential Radon Survey.

RADON - CA
Radon tested locations in California
California Department of Health Services
(916) 449-5674
A table of long term and short term indoor radon measurments

RADON EPA
RADON EPA
U.S. Environmental Protection Agency
215-814-2469
EPA list of Radon zones

AIRPORT FACILITIES
Airport landing facilities
Federal Aviation Administration
(866) 835-5322
Airport landing facilities

BASINS
Better Assessment Science Integrating point & Non-point Sources
U.S. Environmental Protection Agency
855-246-3642
Integrated geographical information system national watershed data and environmental assessment known as Better Assessment Science Integrating point & Non-point Sources

DIGITAL OBSTACLE
Obstacles of interest to aviation users
Federal Aviation Administration
855-379-6518
The Digital Obstacle File describes all known obstacles of interest to aviation users in the U.S. with limited coverage of the Pacific the Caribbean Canada and Mexico. The obstacles are assigned unique numerical identifiers; accuracy codes and listed in order of ascending latitude within each state or area by FAA Region.

EPICENTERS
National Geographical Data Center
National Geographical Data Center
303-497-6826
List of recent and historic earthquakes and information.

FLOOD DFIRM
National Flood Hazard Layer Database
Federal Emergency Management Agency
The National Flood Hazard Layer Database (NFHL) is a computer database that contains the flood hazard map information from FEMAs Flood Map Modernization program. These map data are from Digital Flood Insurance Rate Map (DFIRM) databases and Letters of Map Revision.

APPENDIX D

Other Pertinent Data

PARCELQUEST



© 2015 ParcelQuest www.parcelquest.com (888) 217-8999

PARCELQUEST
LIST 1
DETAIL

1 Property Address: CAPALINA RD SAN MARCOS CA 92069

Ownership

County:	**SAN DIEGO, CA**
Assessor:	**ERNIE DRONENBURG, ASSESSOR**
Parcel # (APN):	**219-115-33-00**
Parcel Status:	**ACTIVE**
Owner Name:	**SABA FAMILY TRUST 07-24-18**
Mailing Address:	**41309 AVENIDA BIONA TEMECULA CA 92591**
Legal Description:	**PM02003 PAR 2*(EX ST)**

Assessment

Total Value:	**$1,721,000**	Use Code:	**20**	Use Type:	**VACANT**
Land Value:	**$1,721,000**	Tax Rate Area:	**013-151**	County Zoning:	**6**
Impr Value:		Year Assd:	**2021**	Census Tract:	
Other Value:		Property Tax:		Price/SqFt:	
% Improved:	**0%**	Delinquent Yr:			
Exempt Amt:		HO Exempt:	**N**		

Sale History

	Sale 1	Sale 2	Sale 3	Transfer
Document Date:				**08/02/2019**
Document Number:				**0321344**
Document Type:				
Transfer Amount:				
Seller (Grantor):				

Property Characteristics

Bedrooms:		Fireplace:		Units:	
Baths (Full):		A/C:		Stories:	
Baths (Half):		Heating:		Quality:	
Total Rooms:		Pool:		Building Class:	
Bldg/Liv Area:		Park Type:		Condition:	
Lot Acres:	**2.510**	Spaces:		Site Influence:	
Lot SqFt:	**109,335**	Garage SqFt:		Timber Preserve:	
Year Built:				Ag Preserve:	
Effective Year:					



A	R=50	78.58
B	S61°08'20"W	11.77
C	R=10	7.86
D	N16°06'53"E	18.10
E	R=10	7.86
F	R=307	43.13
G	N20°51'38"W	36.35
H	R=293	41.16
I	N28°54'34"W	20.36
J	N23°38'11"E	35.27
K	S61°19'13"E	116.10
L	S28°42'22"W	3.00
M	R=1288.38	73.51
N	S28°02'E	17.91
O	R=1570.69	123.61
P	N28°54'34"W	9.83
Q	N73°53'07"W	35.34
R	N61°08'20"E	3.22
S	R=50	77.90
T	R=1542.69	88.52
U	S23°40'38"W	33.48
V	S28°39'22"W	113.52

CHANGES

BLK	OLD	NEW	YR	CUT	
115	9,23-26	27-30	74	2930	
113	7,8,9	45	77	1214	
113	35,36	46	77	3658	
113	40	TAX DEED	77	5896	
114	10	S/W & B/C CHG	78	5502	
113	13-15 & ACCESS RTS	SAME	78	5667	
113	13-15	47	79	6546	
115	8	SAME & WID	79	3505	
114	22	ST OP	80	3965	
113	23-26	48	81	2621	
113	29,37 & 39-41,46	49	85	2458	
114	23	ST CLSD	SAME	88	3591
115	18-20 & 22	SAME & ST CLSD	92	5516	
115	18-22	31	94	1324	
113	47	50 & 51	94	1595	
114	PICKUP	24	03	1914	
114	6 & 24	217-PG 65	03	154	
114	18	25	04	2023	
115	31	32		CANC	
115	28	33 & ST OP	05	1322	CANC
114	19	26 & ST OP	05	1178	CANC
114	15	POR 050-60	05	1820	
114	23	27 & ST OP	05	1896	CANC
115	29	34 & ST OP	06	1406	CANC
115	27	35 & ST OP	06	1418	CANC
114	27	SAME & ST OP	06	4761	
114	20	SAME & ST OP	07	4611	
114	25-27	28-33	08	1022	
114	20 & 29-33	34-36	08	1902	

National Flood Hazard Layer FIRMette

FEMA



Basemap: USGS National Map: Orthoimagery: Data refreshed October, 2020

Legend

SEE FIS REPORT FOR DETAILED LEGEND AND INDEX MAP FOR FIRM PANEL LAYOUT

SPECIAL FLOOD HAZARD AREAS
- Without Base Flood Elevation (BFE) *Zone A, V, A99*
- With BFE or Depth *Zone AE, AO, AH, VE, AR*
- Regulatory Floodway

OTHER AREAS OF FLOOD HAZARD
- 0.2% Annual Chance Flood Hazard, Areas of 1% annual chance flood with average depth less than one foot or with drainage areas of less than one square mile *Zone X*
- Future Conditions 1% Annual Chance Flood Hazard *Zone X*
- Area with Reduced Flood Risk due to Levee. See Notes. *Zone X*
- Area with Flood Risk due to Levee *Zone D*

OTHER AREAS
- NO SCREEN Area of Minimal Flood Hazard *Zone X*
- Effective LOMRs
- Area of Undetermined Flood Hazard *Zone D*

GENERAL STRUCTURES
- Channel, Culvert, or Storm Sewer
- Levee, Dike, or Floodwall

OTHER FEATURES
- 20.2 / 17.5 Cross Sections with 1% Annual Chance / Water Surface Elevation
- Coastal Transect
- Base Flood Elevation Line (BFE)
- Limit of Study
- Jurisdiction Boundary
- Coastal Transect Baseline
- Profile Baseline
- Hydrographic Feature

MAP PANELS
- Digital Data Available
- No Digital Data Available
- Unmapped

N

The pin displayed on the map is an approximate point selected by the user and does not represent an authoritative property location.

This map complies with FEMA's standards for the use of digital flood maps if it is not void as described below. The basemap shown complies with FEMA's basemap accuracy standards

The flood hazard information is derived directly from the authoritative NFHL web services provided by FEMA. This map was exported on 3/28/2022 at 10:05 PM and does not reflect changes or amendments subsequent to this date and time. The NFHL and effective information may change or become superseded by new data over time.

This map image is void if the one or more of the following map elements do not appear: basemap imagery, flood zone labels, legend, scale bar, map creation date, community identifiers, FIRM panel number, and FIRM effective date. Map images for unmapped and unmodernized areas cannot be used for regulatory purposes.

APPENDIX E

Qualifications

Mark E. Smith
Environmental Professional
President, The Phase One Group LLC

PROFESSIONAL EDUCATION

University of California, Riverside (UCR), Riverside, CA, B.S. Environmental Science, 1994

CERTIFICATIONS/QUALIFICATIONS

- AHERA Asbestos Inspector
- 40-Hour OSHA HAZWOPER Training
- Certified Technical Writer

SELECTED EXPERIENCE

Mr. Smith has more than 25 years of experience in Phase 1 Environmental Site Assessments (Phase 1 ESAs) and Real Estate Transaction Screens of residential multifamily, commercial, retail, fueling facilities, agricultural and industrial properties throughout the United States for a wide range of financial clients, attorneys and real estate companies.

Mr. Smith has conducted over 2,300 environmental due diligence projects since 1994.

For a national environmental consulting firm, Mr. Smith served as a Senior Project Manager, where he supervised Phase I Environmental Site Assessments on various industrial, commercial, institutional and residential properties. Assessments included limited and comprehensive surveys for asbestos, lead-based paint, lead-in-drinking water and radon gas emissions. He also managed subsurface investigations to determine the presence of contamination in soil and groundwater, prepared and reviewed written reports in formats prescribed by various fiduciary institutions and performed peer reviews on environmental site assessments completed by other environmental firms. He was responsible for review of final reports and QA/QC.

In May 2007, Mr. Smith resigned from the national environmental consulting firm to start Smithmark LLC as an environmental subcontractor to provide Phase 1 ESA report services to existing national, regional and local environmental/engineering firms in need of report services for overflow projects unable to be covered by in-house staff. In February 2016, Mr. Smith dissolved Smithmark LLC and formed The Phase One Group LLC to provide Phase 1 ESA report services to property purchasers, brokers, investors and lenders.

PROFESSIONAL AFFILIATIONS:

- Association of Environmental Professionals, Los Angeles County Chapter, Member

RELEVANT PROJECT EXPERIENCE:

- **Embassy Suites – Glendale, California**

  Performed ESA of a 272-room Embassy Suites hotel facility in Glendale, California.

- **Limoneira Company – Santa Paula, California**

  Performed several ESAs of Limoneira Company corporate headquarters and numerous multi-acre orchards owned and operated by Limoneira Company.

- **Royal Truck Body – Paramount, California**

  Performed ESA of Royal Truck Body, a heavy industrial facility who manufactures truck service bodies. Facility comprised of over 300,000 square feet of manufacturing and assembly space.

- **Bank Branches – Pacific Northwest**

  Performed ESAs of over 20 bank branches throughout Oregon and Washington. ESAs were completed within a four-week period.

- **North DeKalb Mall – Decatur, Georgia**

  Performed ESA of the North DeKalb Mall, a regional shopping mall in Decatur, Georgia.

- **Various Properties – Hawaii**

  Performed ESAs of commercial, retail and residential properties on the islands of Oahu and Kauai, Hawaii.